

# JAZZ HILL HOMES 924 - 1304 The Paseo Boulevard Kansas City, Missouri

Architectural/Historic Inventory Submitted for Eligibility Assessment for potential listing as a National Register District

Submitted By:
Brenda R. Spencer
10150 Onaga Road
Wamego, Kansas 66547
785/456-9857
for Pioneer Group, Inc.
Topeka, Kansas

#### **BIBLIOGRAPHY**

30)

31) 32)

33)

1)	1975 Drawings by William Johnson, 424 Law Building, KC, MO, for the Housing Development Corporation and Information Center (for the 1975-76 HUD
0)	remodeling).
2)	1995 Ariel Photo, Planning Department, City of Kansas City, Missouri.
3)	Atlas of Kansas City, MQ and Environs. Kansas City: Tuttle-Ayers-Woodward, Co. Surveyors and City Planners, 1925.
4)	Atlas of Kansas City, USA and Vicinity. Kansas City: Tuttle and Pike, 1907.
5)	Becker, Linda F. "Focus on Dr. Generous L. Henderson Residence." <u>Historic Kansas City</u> <u>Foundation Gazette</u> . November/December, 1984.
6)	Becker, Linda F. and Cydney E. Millstein. "Colonnaded Kansas City Apartment Buildings
	(Phase 1) A Study," Kansas City, Missouri: Landmarks Commission, City
	Development Department, May, 1990.
7)	Building Permits, City Archives, 2 <sup>nd</sup> Floor Oak Tower Building, Kansas City, Missouri.
8)	Ford, Susan Jezak. "Ernest O. Brostrom Biography," Kansas City Public Library: Special
O,	Collections.
9)	Hoye's Kansas City Blue Book and Club Directory. Kansas City: Hoye's Directory
<b>.</b> ,	Company, Compilers, Printers, and Bindery, 1900, 1901, 1902, 1903, 1904,
	1905, 1906, 1907, 1908, 1909, 1913, 1914, 1917.
10)	"Images of Kansas City" Photograph Display, Kansas City Public Library.
11)	Inland Architect and News Record, May, 1906.
12	Inland Architect and News Record, June, 1906.
13)	Jackson County, Missouri Tax Assessment Records, 1999.
14)	Kansas City Illustrated, 1901, 1902, and 1907.
15)	Kansas City Star, 12 March, 1977.
16)	Kansas City Times, 18 May, 1968.
17)	Kansas City Times, 17 April, 1971.
18)	Kansas City Times, 26 February, 1972.
19)	Kansas City Times, 13 April, 1974.
20)	Kansas City Times, 29 June, 1974.
21)	Kansas City Times, 11 January, 1975.
22)	Kansas City Times, 28 April, 1978.
23)	Landmarks Commission, City of Kansas City, Missouri, card file. City Hall, Kansas City,
	Missouri.
24)	Lee, Janice, David Boutros, Charlotte R. White, and Deon Wolfenbarger ed. Legacy of
	Design An Historical Survey of the Kansas City Missouri Parks and Boulevards
	System, 1893-1940. Kansas City, Missouri: Kansas City Center for Design
	Education and Research in cooperation with the Western Historical Manuscript
	Collection-Kansas City, 1995.
25)	Parkview Homes (Current Property Owner) Marketing Packet, date unknown
26)	Pen and Sunlight Sketches of Greater Kansas City, 1911.
27)	Piland, Sherry. "Kansas City Architects: Owen and Payson," <u>Historic Kansas City</u>
	Foundation Gazette, Vol.8, January/February, 1984, p.6.
28)	Ray, Mrs. Sam. Postcard collection. Kansas City Library: Special Collections.
	[Postcards and local history articles were published in the Kansas City Times in
001	the 1970s].
29)	Sanborn Insurance Maps, Kansas City, Missouri. New York: Sanborn Map Company, 1896, 1909, 1940.

Wilson, William H. <u>The City Beautiful Movement</u>. Baltimore: The John Hopkins University Press, 1994.

USGS Quad Map: Kansas City, Missouri and Kansas. c.1983.

Water Permits, 5th Floor, City Hall, Kansas City, Missouri.

University of Missouri Press, 1964

Sandy, Wilda. "Kessler Biography." Kansas City Public Library: Special Collections.

Wilson, William H. The City Beautiful Movement in Kansas City. Columbia, MO:







#10 1116 PASEO 1/00 Interior stairway




#9 1116 PASEO 1/00 Window detail (north elevation)












#6 1116 PASEO 1/00 Window detail (east elevation)

1116 PASEO South (side) elevation

1/00



#2 1116 PASEO 1/00 South (side) elevation from SE corner of building




#1 1116 PASEO 1/00 East (front) elevation



**Photographs** 

Full frontal and side view; located at 11th and Paseo.



#13

1106 PASEO
Date of photo unknown
Source: Images of Kansas City
Display, Kansas City Library

### MISSOURI HISTORIC PRESERVATION PROGRAM

•		4. PRESENT LOCAL NAME	E(S) OR DESIG	NATION(S)	
		Parkview Homes, T		• •	
2-COUNTY		5. OTHER NAME(S)	·····	······································	
Jackson Jackson					
3-LOCATION OF NEGATIVES	· · · · · · · · · · · · · · · · · · ·	<u> </u>	**************************************		
& SPECIFIC LEGAL LOCATION	16 THEMATIC	CATEGORY		28. NO. OF STORIES	
TOWNSHIP 49 RANGE 33 SECTION 4			-	4-1/2	
IFCITY OR TOWN, STREET ADDRESS	17. DATE(S) OR	PERIOD		29. BASEMENT YES (X) NO ( ) full	
1116 The Paseo Boulevard	circa 1905		30. FOUNDATION MATERIAL ashlar coursed stone-east		
7. CITY OR TOWN IF RURAL, VICINITY	IS. STYLE OR DESIGN		3). WALL CONSTRUCTION		
Kansas City		Neo-Classical w/ Prairie influences		brick	
8. DESCRIPTION OF LOCATION	19. ARCHITECT	OR ENGINEER		32. ROOF TYPE AND MATERIAL flat - membrane	
South 39 feet of Lot 10 and all of Lots		Sunderland		33. NO. OF BAYS	
11 & 12; Block 2, Gates & Kendall's	20. CONTRACTO	OR OR BUILDER		FRONT 3 SIDE 3	
Second Addition See Attached Map	unknown			34. WALL TREATMENT	
	21 OPERINAL II	SE IF APPARENT		running bond brick	
9. COORDINATES UTM	Apartment	·	ł	35. PLAN SKAPE rectangular - short facade	
LAT LONG	22. PRESENT US	<del></del>		36. CHANGES ADDITION()	
	Apartment			(EXPLAIN:IN: ALTERED (X) NO. 42) MOVED ( )	
10. SITE() STRUCTURE() BUILDING(0) OBJECT()					
SSEEDING(X) CONCES(1)	23. OWNERSHIP	PUBLIC() PRIVATE(X)		37. CONDITION DITERIOR fair	
II. ON NATIONAL YES ( ) REGISTER? NO ( )				EXTERIOR good	
REGISTER? NO()		ME AND ADDRESS es, L.P. c/o Pioneer Gro	un Inc	38. PRESERVATION YES()	
12 ISTT YES()	<b>a</b>	as Ave. Topeka, KS 666		UNDERWAY? NO(X)	
ELIGIBLE NO()	25. OPEN TO PU	BLIC YES()		39. ENDANGERED? YES (X)	
IJ. PART OF ESTAB. YES()	NO (X)			RY WHATE NO()	
HIST. DISTRICT NO (X)	26 LOCAL CON	TACT PERSON OR ORGANIZ	ZATION	vacant, blighted area, lack of maintenance  40. VISIBLE FROM YES (X)	
14. DISTRICT YES (>>	*Ross Freeman, Pioneer Group, Inc.785/232-1122		1	40. VISIBLE FROM YES (X) PUBLIC ROAD NO()	
POTENTIAL NO()		27. OTHER SURVEYS IN WHICH INCLUDED		C. SITTANIAN MANAGAMAN	
	27. OTHER SURVETS EN WINCH INCLUDED			41. DISTANCE FROM AND FRONTAGE ON ROAD	
15. NAME OF ESTABLISHED DISTRICT					
	ES	ank a central entrance o	on the first fl	FRONTAGE ON ROAD	
42. FURTHER DESCRIPTION OF IMPORTANT FEATUR The primary facade has two full-height project porches are characterized by stone bands, pec	ES ing porches that fl limented parapet v	valls, and ribbons of dou	ıble-hung wi	oor. The ndows.	
42. FURTHER DESCRIPTION OF IMPORTANT FEATUR The primary facade has two full-height project	ES ing porches that fl limented parapet v ary facade have st	valls, and ribbons of dou one sills and stone flat a	uble-hung wi arched lintels	oor. The indows.	
42. FURTHER DESCRIPTION OF IMPORTANT FEATUR The primary facade has two full-height project porches are characterized by stone bands, pec The windows in the recessed area of the prim- keystones. The windows on the other facade	ES ing porches that fl limented parapet v ary facade have st	valls, and ribbons of dou one sills and stone flat a	uble-hung wi arched lintels	oor. The ndows.	
42. FURTHER DESCRIPTION OF IMPORTANT FEATUR The primary facade has two full-height project porches are characterized by stone bands, pec The windows in the recessed area of the prim- keystones. The windows on the other facade  43. HISTORY AND SIGNIFICANCE This apartment building is directly associated	ing porches that fillimented parapet vary facade have standard intels a	valls, and ribbons of dou one sills and stone flat a ind sills with the exception	uble-hung wi arched lintels ion of four w develop the I	oor. The indows. Is with vindows blighted	
42. FURTHER DESCRIPTION OF IMPORTANT FEATUR The primary facade has two full-height project porches are characterized by stone bands, pec The windows in the recessed area of the prim- keystones. The windows on the other facade  43. HISTORY AND SIGNIFICANCE This apartment building is directly associated of property along The Paseo Boulevard between	ing porches that fillimented parapet vary facade have standard facade have standard facade have flat lintels a with the historically 9th Street and 14th	valls, and ribbons of dou one sills and stone flat a and sills with the exception y significant effort to red Street through the cons	uble-hung wi arched lintels ion of four w develop the l struction of e	oor. The indows. Is with vindows blighted	
42. FURTHER DESCRIPTION OF IMPORTANT FEATUR The primary facade has two full-height project porches are characterized by stone bands, pec The windows in the recessed area of the prim- keystones. The windows on the other facade  43. HISTORY AND SIGNIFICANCE This apartment building is directly associated	ing porches that fillimented parapet vary facade have standard facade have standard facade have flat lintels a with the historically 9th Street and 14th	valls, and ribbons of dou one sills and stone flat a and sills with the exception y significant effort to red Street through the cons	uble-hung wi arched lintels ion of four w develop the l struction of e	oor. The indows. Is with vindows blighted	
42. FURTHER DESCRIPTION OF IMPORTANT FEATUR The primary facade has two full-height project porches are characterized by stone bands, pec The windows in the recessed area of the prim keystones. The windows on the other facade:  43. HISTORY AND SIGNIFICANCE This apartment building is directly associated to property along The Paseo Boulevard between apartment housing in the years 1901 through A 1905 water permit identifies a Mr. Kendall a	ing porches that fillimented parapet vary facade have standard facade have standard facade have flat lintels a with the historically 9th Street and 14th 1913. See historical the owner of the	valls, and ribbons of dou one sills and stone flat a and sills with the exception y significant effort to red Street through the cons c context for the propose e property. The New En	able-hung wind arched lintels ion of four was develop the lastruction of each district.	oor. The indows. Swith vindows blighted elite BE PROVIDED ment building was designed by Edwards &	
42. FURTHER DESCRIPTION OF IMPORTANT FEATUR The primary facade has two full-height project porches are characterized by stone bands, pec The windows in the recessed area of the prim keystones. The windows on the other facade  43. HISTORY AND SIGNIFICANCE This apartment building is directly associated of property along The Paseo Boulevard between apartment housing in the years 1901 through A 1905 water permit identifies a Mr. Kendall a Sunderland circa 1906. Around the same time	ing porches that flatimented parapet vary facade have standard flat lintels at with the historically 9th Street and 14th 1913. See historicals the owner of the parameters & Sundards & Sun	valls, and ribbons of dou one sills and stone flat a and sills with the exception y significant effort to red Street through the cons c context for the propose e property. The New En- derland were also respon	able-hung wi arched lintels ion of four w develop the l struction of e ed district.	oor. The indows. Swith vindows blighted elite BE PROVIDED was designed by Edwards & design of The Maples Apartments at	
42. FURTHER DESCRIPTION OF IMPORTANT FEATUR The primary facade has two full-height project porches are characterized by stone bands, pec The windows in the recessed area of the prim keystones. The windows on the other facade:  43. HISTORY AND SIGNIFICANCE This apartment building is directly associated to property along The Paseo Boulevard between apartment housing in the years 1901 through A 1905 water permit identifies a Mr. Kendall a	ing porches that flatimented parapet vary facade have standard flat lintels at with the historically 9th Street and 14th 1913. See historicals the owner of the parameters & Sundards & Sun	valls, and ribbons of dou one sills and stone flat a and sills with the exception y significant effort to red Street through the cons c context for the propose e property. The New En- derland were also respon	able-hung wi arched lintels ion of four w develop the l struction of e ed district.	oor. The indows. Swith vindows blighted elite BE PROVIDED was designed by Edwards & design of The Maples Apartments at	
42. FURTHER DESCRIPTION OF IMPORTANT FEATUR The primary facade has two full-height project porches are characterized by stone bands, pec The windows in the recessed area of the prim- keystones. The windows on the other facade:  43. HISTORY AND SIGNIFICANCE This apartment building is directly associated or property along The Paseo Boulevard between apartment housing in the years 1901 through A 1905 water permit identifies a Mr. Kendall a Sunderland circa 1906. Around the same time 1401 East 10th Street. Both buildings were for	ing porches that fillimented parapet vary facade have standard facade have standard facade have flat lintels and the standard facade have flat lintels and the standard facade have flat lintels and the standard facade have flat lintels for the standard facade have standard for the standard facade have flat lintels and standard facade have stand	valls, and ribbons of dou one sills and stone flat a and sills with the exception y significant effort to red Street through the cons c context for the propose e property. The New En- derland were also respon	able-hung wi arched lintels ion of four w develop the l struction of e ed district.	oor. The indows. Swith vindows blighted elite BE PROVIDED was designed by Edwards & design of The Maples Apartments at	
42. FURTHER DESCRIPTION OF IMPORTANT FEATUR The primary facade has two full-height project porches are characterized by stone bands, pec The windows in the recessed area of the prim- keystones. The windows on the other facade:  43. HISTORY AND SIGNIFICANCE This apartment building is directly associated or property along The Paseo Boulevard between apartment housing in the years 1901 through A 1905 water permit identifies a Mr. Kendall a Sunderland circa 1906. Around the same time 1401 East 10th Street. Both buildings were for  44. DESCRIPTION OF ENVIRONMENT AND OUTBUILD The primary facade faces The Paseo. The ad	ing porches that fillimented parapet vary facade have standard facade have standard facade have standard facade have flat lintels and standard facade have flat lintels and standard facade have standard facade have standard facade have standard facade have flat facade have standard facade have flat facade have flat flat flat flat flat flat flat flat	valls, and ribbons of dou one sills and stone flat a and sills with the excepti- y significant effort to red Street through the cons c context for the proposi- e property. The New En- derland were also respon- architect and News Reco	able-hung wind arched lintels ion of four was develop the lastruction of each district.  Ingland Apartics and in May are in May are in May are in the lastruction of	oor. The indows. Swith vindows blighted elite ment building was designed by Edwards & e design of The Maples Apartments at ind June of 1906, respectively.	
42. FURTHER DESCRIPTION OF IMPORTANT FEATUR The primary facade has two full-height project porches are characterized by stone bands, pec The windows in the recessed area of the prim keystones. The windows on the other facade  43. HISTORY AND SIGNIFICANCE This apartment building is directly associated or property along The Paseo Boulevard between apartment housing in the years 1901 through A 1905 water permit identifies a Mr. Kendall a Sunderland circa 1906. Around the same time 1401 East 10th Street. Both buildings were for	ing porches that fillimented parapet vary facade have standard facade have standard facade have standard facade have flat lintels and standard facade have flat lintels and standard facade have standard facade have standard facade have standard facade have flat facade have standard facade have flat facade have flat flat flat flat flat flat flat flat	valls, and ribbons of dou one sills and stone flat a and sills with the excepti- y significant effort to red Street through the cons c context for the proposi- e property. The New En- derland were also respon- architect and News Reco	able-hung wind arched lintels ion of four was develop the lastruction of each district.  Ingland Aparticus for the last line and in May and lintels. The	oor. The indows. Swith vindows blighted elite BE PROVIDED blighted elite Bedsign of The Maples Apartments at ind June of 1906, respectively.	
42. FURTHER DESCRIPTION OF IMPORTANT FEATUR The primary facade has two full-height project porches are characterized by stone bands, pec The windows in the recessed area of the prim keystones. The windows on the other facade  43. HISTORY AND SIGNIFICANCE This apartment building is directly associated or property along The Paseo Boulevard between a partment housing in the years 1901 through A 1905 water permit identifies a Mr. Kendall a Sunderland circa 1906. Around the same time 1401 East 10th Street. Both buildings were for  44. DESCRIPTION OF ENVIRONMENT AND OUTBUILD The primary facade faces The Paseo. The ad stone retaining wall with a central flight of co	ing porches that fillimented parapet vary facade have standard facade have standard facade have flat lintels and standard facade have flat lintels and standard facade fac	valls, and ribbons of dou one sills and stone flat a and sills with the excepti- y significant effort to red Street through the cons c context for the propose e property. The New En- derland were also respon- cribitect and News Reco	develop the lastruction of each district.  Ingland Aparticustible for the bord in May are anti-lots. The	oor. The indows. Swith windows blighted elite ment building was designed by Edwards & edesign of The Maples Apartments at ind June of 1906, respectively.	
42. FURTHER DESCRIPTION OF IMPORTANT FEATUR The primary facade has two full-height project porches are characterized by stone bands, pec The windows in the recessed area of the prim keystones. The windows on the other facade: 43. HISTORY AND SIGNIFICANCE This apartment building is directly associated of property along The Paseo Boulevard between apartment housing in the years 1901 through A 1905 water permit identifies a Mr. Kendall as Sunderland circa 1906. Around the same time 1401 East 10th Street. Both buildings were for 44. DESCRIPTION OF ENVIRONMENT AND OUTBUILD. The primary facade faces The Paseo. The ad stone retaining wall with a central flight of co	ing porches that fluimented parapet wary facade have start and 14th 1913. See historically street and 14th 1913. See historical see the owner of the eatured in Inland Approximately 1915.	valls, and ribbons of dou one sills and stone flat a and sills with the exception y significant effort to red Street through the consic context for the proposi e property. The New Enderland were also respon inchitect and News Reco	develop the I struction of court with the struction of the structure of the struc	oor. The indows. BE PROVIDED blighted elite ment building was designed by Edwards & e design of The Maples Apartments at ind June of 1906, respectively.	
42. PURTHER DESCRIPTION OF IMPORTANT FEATUR The primary facade has two full-height project porches are characterized by stone bands, pec The windows in the recessed area of the prim keystones. The windows on the other facade:  43. HISTORY AND SIGNIFICANCE This apartment building is directly associated of property along The Paseo Boulevard between apartment housing in the years 1901 through A 1905 water permit identifies a Mr. Kendall at Sunderland circa 1906. Around the same time 1401 East 10th Street. Both buildings were for 44. DESCRIPTION OF ENVIRONMENT AND OUTBUILD The primary facade faces The Paseo. The ad stone retaining wall with a central flight of co	ing porches that fillimented parapet vary facade have standard facade have standard facade have flat lintels and standard facade have flat lintels and standard facade have flat lintels and standard facade have flat lintels for the flat lintels for the flat lintels	valls, and ribbons of dou one sills and stone flat a and sills with the exception y significant effort to red Street through the consist c context for the proposi e property. The New Enderland were also respond architect and News Reconstruction and south are vacal e main entrance.	develop the I struction of four was develop the I struction of each district.  Ingland Aparticus of the prod in May are struction. The Brends  47. ORGANE	oor. The indows. So with vindows blighted elite ment building was designed by Edwards & edesign of The Maples Apartments at ind June of 1906, respectively.  The raised lawn at the east is surrounded by a EDBY a R. Spencer (785) 456-9857	
42. FURTHER DESCRIPTION OF IMPORTANT FEATUR The primary facade has two full-height project porches are characterized by stone bands, pec The windows in the recessed area of the prim- keystones. The windows on the other facade  43. HISTORY AND SIGNIFICANCE This apartment building is directly associated or property along The Paseo Boulevard between a partment housing in the years 1901 through A 1905 water permit identifies a Mr. Kendall a Sunderland circa 1906. Around the same time 1401 East 10th Street. Both buildings were for 44. DESCRIPTION OF ENVIRONMENT AND OUTBUILD The primary facade faces The Paseo. The ad stone retaining wall with a central flight of co  45. SOURCE OF INFORMATION Water permit a sources: 1, 3, RETURN THIS FORM WHEN COMPLETED TO: 6	ing porches that fillimented parapet vary facade have stary facade have stary facade have stary facade have flat lintels and stary facade have flat lintels and stary facade have flat lintels and stary flat flat flat flat flat flat flat flat	valls, and ribbons of dou one sills and stone flat a and sills with the exception y significant effort to red Street through the consist c context for the proposi e property. The New Enderland were also respond architect and News Reconstruction and south are vacal e main entrance.	develop the lastruction of four was develop the lastruction of ceed district.  In a sible for the bord in May are last lots. The Brends  47. ORGANT for Jaz	oor. The indows. Swith vindows BE PROVIDED blighted elite Belite	
42. FURTHER DESCRIPTION OF IMPORTANT FEATUR The primary facade has two full-height project porches are characterized by stone bands, pec The windows in the recessed area of the prim keystones. The windows on the other facade  43. HISTORY AND SIGNIFICANCE This apartment building is directly associated or property along The Paseo Boulevard between a partment housing in the years 1901 through A 1905 water permit identifies a Mr. Kendall a Sunderland circa 1906. Around the same time 1401 East 10th Street. Both buildings were for 44. DESCRIPTION OF ENVIRONMENT AND OUTBUILD. The primary facade faces The Paseo. The ad stone retaining wall with a central flight of co  45. SOURCE OF INFORMATION Water permit a sources: 1, 3, RETURN THIS FORM WHEN COMPLETED TO: 6	ing porches that fillimented parapet vary facade have standard facade have standard facade have flat lintels and standard facade have flat lintels and standard facade have flat lintels and standard facade have flat lintels for the flat lintels for the flat lintels	valls, and ribbons of dou one sills and stone flat a and sills with the exception y significant effort to red Street through the consic context for the proposi e property. The New Enderland were also respondered and News Reco context and News Reco controller and south are vacal e main entrance.  Bibliography, 9, 31, & 32.  3C PRESERVATION	develop the lastruction of four was develop the lastruction of ceed district.  In a sible for the bord in May are last lots. The Brends  47. ORGANT for Jaz	oor. The indows. So with vindows blighted elite ment building was designed by Edwards & edesign of The Maples Apartments at ind June of 1906, respectively.  The raised lawn at the east is surrounded by a EDBY a R. Spencer (785) 456-9857	

#### 1116 PASEO - CONTINUATION SHEET

#### 42. FURTHER DESCRIPTION OF IMPORTANT FEATURES - Continued

on each of the north and south facades, which have projecting shallow wooden hip-roofs and stone sills. The historic windows were replaced in 1975. The rear porches were removed, openings were closed, and a steel fire escape was installed on the rear facade in 1975. The interior was remodeled in 1975, but the wooden stairs are extant. The windows openings on lower levels of this vacant building are currently boarded up.











#10 1106 PASEO 1/00 Interior stairway





1106 PASEO West (rear) elevation South (side) elevation from SW corner of building

1/00



1106 PASEO Porch/entry detail (East elevation) 1/00



1/00

(East elevation)






#1 1106 PASEO 1/00 East (front) elevation



#2 1106 PASEO 1/00 North (side) elevation from NE corner of building



#13 1100 PASEO
1975 Source: 1975 Drawings
for HUD remodeling
William Johnson, Architect

## MISSOURI HISTORIC PRESERVATION PROGRAM

1.NO.		PRESENT LOCAL NAME(3) OR DESIGNATION(S)     Parkview Homes, The Vaydick		
2-COUNTY Jackson		5. OTHER NAME(S) The McMahan Apartments		
1-LOCATION OF NEGATIVES				
6 SPECIFIC LEGAL LOCATION TOWNSHIP 49 RANGE 33 SECTION 4	16. THEMATIC	CATEGORY	28. NO. OF STORIES 3-1/2	
IPCITY OR TOWN, STREET ADDRESS	17 DATE(S) OR	PERIOD	29. BASEMENT YES (X) NO() full	
1106 The Paseo Boulevard	17. DATE(S) OR PERIOD 1913		30. FOUNDATION MATERIAL natural faced, semi coursed, squared stone	
CITY OR TOWN IF RURAL, VICINITY	IS. STYLE OR DESIGN		3). WALL CONSTRUCTION	
Kansas City	Neo-Class	sical Colonnaded Apartm	nent Bidg.  32. ROOF TYPE AND MATERIAL	
L DESCRIPTION OF LOCATION	19. ARCHITECT		flat - membrane	
South 39 feet of Lot 9 and the north 11 feet of Lot 10; Block 2, Gates &	E.O. Bros	trom	33. NO. OF BAYS FRONT 3 SIDE 6	
Kendall's Second Addition		OR OR BUILDER		
See Attached Map	C.H. Lewi		14. WALL TREATMENT uniquely bonded brick	
COORDINATES UTM	21. ORIGINAL I	JSE, IF APPARENT	35. PLAN SHAPE	
LAT	Apartmen	ts	rectangular - short facade  36. CHANGES ADDITION()	
LONG	22. PRESENT U	SE	(EXPLAIN IN ALTERED (X)	
10. SITE() STRUCTURE()	Apartmen	its	NO. 42) MOVED ( )	
BUILDING (x) OBJECT ( )	23. OWNERSHI	P PUBLIC() PRIVATE(X)	37. CONDITION	
1. ON NATIONAL YES()		WALLE	INTERIOR fair EXTERIOR good	
REGISTER? NO(')	24. OWNER'S NAME AND ADDRESS			
2 isit yes() ELIGIBLE NO()	1200 S. Kans	nes, L.P. c/o Pioneer Gr sas Ave. Topeka, KS 66		
IJ. PART OF ESTAB. YES() HIST. DISTRICT NO (X)	25. OPEN TO PU	JBLIC YES ( ) NO (X)	39. ENDANGERED? YES (X) BY WHAT? NO ( ) vacant, blighted area, lack of maintenance	
14. DISTRICT YES ○○	1	NTACT PERSON OR ORGAN	TO THE PARTY OF TH	
POTENTIAL NO()	*Ross Freeman, Pioneer Group, Inc.785/232-1122			
15. NAME OF ESTABLISHED DISTRICT	27. OTHER SUR	iveys in which include	41. DISTANCE FROM AND FRONTAGE ON ROAD	
42. FURTHER DESCRIPTION OF IMPORTANT FRATUR This apartment building is an excellent example width porch has four wooden ionic columns w modified in 1975. The original porch railings a ashlar stone trim at the window sills, column bear frame addition with stucco finish. The int 43. HISTORY AND SIGNIFICANCE  This colonnaded apartment building is directly the blighted property along The Paseo Bouleva of elite apartment housing in the years 1901 the	ith a substantial vand double-hung wases, and at the erior was remode associated with the double between 9th St	vood and metal cornice vindows were also replated bowed first floor porchibled in 1975, but the wolfer historically significant and 14th Street through	that was slightly aced in 1975. There is knee walls. There is a coden stairs are extant.  It effort to redevelop ough the construction	
Brostrom was identified as a designer of the T	hree-story, colum Brostrom was influ	n-over-pier apartment bi	I. McMahan. Ernest O. Brostrom was the architect. Mr. uilding (a sub-type of the colonnaded apartment style of architecture and the work of Chicago architect,	
The primary facade faces The Paseo. The adj vacant lot. The lawn at the east entrance is s	acent lot to the n			
45. SOURCE OF INFORMATION Building Permit	#10000-1913; S	ee Bibliography,	46. PREPARED BY Brenda R. Spencer (785) 456-9857	
sources: 1, 6,	7, 8, 10, 13, 29,	31, & 32.	47. ORGANIZATION	
RETURN THIS FORM WHEN COMPLETED TO : C	OFFICE OF HISTOR	UC PRESERVATION	for Jazz Hill Homes, L.P. c/o Pioneer Group, Inc.	
T . COMMON	JEFFERSON CITY,	MO 65102	rebruary 2000	
SEPARATE SHEET(S) TO THIS FORM	PHL 573-751-785		49. REVISION DATE(S)	



**LEGGEN** 





#9 1100 PASEO
1/00 Tile at building entrance
east elevation








#8 1100 PASEO
1/00 West (rear) elevation
South (side) elevation
from SW corner of building



#5 1100 PASEO 1/00 Porch detail (east elevation)



#6 1100 PASEO 1/00 Porch detail north (side) elevation





1100 PASEO North (side) elevation from NE corner of building 1/00



#1 1100 PASEO 1/00 East (front) elevation



#2 1100 PASEO 1/00 South (side) elevation from SE corner of building

#### 1100 PASEO - CONTINUATION SHEET


#### 42. FURTHER DESCRIPTION OF IMPORTANT FEATURES - Continued

pediments, egg-and-dart molding, brackets and garlands caps the entire building on the east and north facades and partially wraps around the south side. There are ashlar quoins on the east and north facades. Ashlar stone window enframement is typical on the east facade and upper story windows. The entrance doors on the east and north are enframed by ashlar columns and pediments. The west end of the north facade has two projecting bays that were originally open porches but were filled in partially with brick and partially with windows in the 1975 HUD project. Historic tile flooring at the entrance and original wood stairways are extant although the 1975 HUD project included substantial remodeling of the interior.

#### 44. DESCRIPTION OF ENVIRONMENT AND OUTBUILDINGS - Continued

The north entrance, which abuts the sidewalk, is protected by a recently installed steel gate.







1000 PASEO
Date of postcards unknown
Source: Parkview Homes'
(current property owner)
marketing packet

PARKVIEW HOTEL - 1000 PASEO - KANSAS CITY, MISSOURI

# MISSOURI HISTORIC PRESERVATION PROGRAM

		PRESENT LOCAL NAME(S) OR DESIGNATION(S)     Parkview Homes, The Virginia			
2-COUNTY Jackson	5. OTHER NAME(S)				
3-LOCATION OF NEGATIVES					
SPECIFIC LEGAL LOCATION TOWNSHIP 49 RANGE 33 SECTION 4	16. THEMATIC CATEGORY	28. NO. OF STORIES 4-1/2			
FCITY OR TOWN, STREET ADDRESS	17. DATE(S) OR PERIOD	29. BASEMENT YES (X) NO ( ) full + partial sub basement (east end)			
1100 The Paseo Boulevard	1911	30. FOUNDATION MATERIAL coursed ashlar cut stone-north & east			
7. CITY OR TOWN IF RURAL, VICINITY	18. STYLE OR DESIGN	31. WALL CONSTRUCTION			
Kansas City	Neo-Classical Colonnaded Apartment B	Bidg. 32. ROOF TYPE AND MATERIAL			
DESCRIPTION OF LOCATION	19. ARCHITECT OR ENGINEER	flat - membrane			
Lot 8 and the north 11 feet of Lot 9;	Owen & Payson	33. NO. OF BAYS FRONT 3 SIDE 3			
Block 2, Gates & Kendall's Second Addition	20. CONTRACTOR OR BUILDER				
See Attached Map	J. W. McKamey	14. WALL TREATMENT running bond brick			
9. COORDINATES UTM	21. ORIGINAL USE, IF APPARENT	35. PLAN SHAPE			
LAT	Apartments	rectangular - short facade  36. CHANGES ADDITION()			
LONG	22. PRESENT USE	(EXPLAIN IN ALTERED (X)			
IO. SITE() STRUCTURE()	Apartments	NO. 42) MOVED ( )			
BUILDING (☆ OBJECT()	23. OWNERSHIP PUBLIC ( ) PRIVATE (X)	37. CONDITION			
II. ON NATIONAL YES()		INTERIOR fair EXTERIOR good			
REGISTER? NO(')	24. OWNER'S NAME AND ADDRESS				
2 is it yes ( ) Eligible NO( )	Jazz Hill Homes, L.P. c/o Pioneer Group, I 1200 S. Kansas Ave. Topeka, KS 66612-				
13. PART OF ESTAB. YES() HIST. DISTRICT NO (X)	25. OPEN TO PUBLIC YES ( ) NO (x)	39. ENDANGERED? YES(X) BY WHAT? NO() vacant, blighted area, lack of maintenance			
14. DISTRICT YES (X)	26. LOCAL CONTACT PERSON OR ORGANIZATIO	I W. Tibibob i Nom			
POTENTIAL NO()	*Ross Freeman, Pioneer Group, Inc.785/232-1	122 PUBLIC ROAD NO()			
15. NAME OF ESTABLISHED DISTRICT	27. OTHER SURVEYS IN WHICH INCLUDED	41. DISTANCE FROM AND FRONTAGE ON ROAD			
columns on the upper level. The porch has a railings on the porch were replaced in 1975. alternating raised and recessed bands. The u	RES  porch with brick columns on the lower levels an substantial intermediate cornice and a cornice at the base of the building (first floor) is a dark bripper walls are red brick. A pressed metal cornice.	at the top. The ick with			
The east facade has a full-height colonnaded columns on the upper level. The porch has a railings on the porch were replaced in 1975. alternating raised and recessed bands. The understanding raised and recessed bands. The understanding raised apartment building is directly blighted property along The Paseo Boulevard I	porch with brick columns on the lower levels an substantial intermediate cornice and a cornice a The base of the building (first floor) is a dark bri	at the top. The ick with ice with  BE PROWIDED  ort to redevelop the construction of			
The east facade has a full-height colonnaded columns on the upper level. The porch has a railings on the porch were replaced in 1975. alternating raised and recessed bands. The upper level. HISTORY AND SIGNIFICANCE  This colonnaded apartment building is directly blighted property along The Paseo Boulevard is elite apartment housing in the years 1901 through the transfer of the 1911 Building Permit identifies W. A. Pat Charles Payson and Albert Owen formed an a of schools, commercial buildings, residences,	porch with brick columns on the lower levels an substantial intermediate cornice and a cornice at the base of the building (first floor) is a dark bripper walls are red brick. A pressed metal cornice associated with the historically significant effortiet between 9th Street and 14th Street through the cough 1913. See Historic Context of proposed coret as the property owner. The building was determined the substantial of the couple of the substantial of the couple of the coup	at the top. The ick with ice with BE PROVIDED out to redevelop the construction of district.  esigned by Owen & Payson, Architects. In 1908 lesigned a variety of buildings, including a number y is active support of professional architectural			
The east facade has a full-height colonnaded columns on the upper level. The porch has a railings on the porch were replaced in 1975. alternating raised and recessed bands. The upper level.  43. HISTORY AND SIGNIFICANCE  This colonnaded apartment building is directly blighted property along The Paseo Boulevard is elite apartment housing in the years 1901 through the property along The Paseo Boulevard is elite apartment housing in the years 1901 through the property along The Paseo Boulevard is elite apartment housing in the years 1901 through the property along the years 1901 through the property along the propert	porch with brick columns on the lower levels an substantial intermediate cornice and a cornice at the base of the building (first floor) is a dark bripper walls are red brick. A pressed metal cornice associated with the historically significant effort between 9th Street and 14th Street through the cough 1913. See Historic Context of proposed context as the property owner. The building was described the property owner. The building was described and distinctive apartments. Part of their legacy Kansas City Architectural Club founded in 1901 DINGS secondary facade faces 11th Street. The adjaced Paseo is a non-contributing structure. The law	at the top. The ick with ice with BE PROVIDED ort to redevelop the construction of district.  esigned by Owen & Payson, Architects. In 1908 lesigned a variety of buildings, including a number y is active support of professional architectural			
The east facade has a full-height colonnaded columns on the upper level. The porch has a railings on the porch were replaced in 1975. alternating raised and recessed bands. The upper level. History and significance  43. History and significance This colonnaded apartment building is directly blighted property along The Paseo Boulevard is elite apartment housing in the years 1901 through the second s	porch with brick columns on the lower levels an substantial intermediate cornice and a cornice at the base of the building (first floor) is a dark bripper walls are red brick. A pressed metal cornice associated with the historically significant effort between 9th Street and 14th Street through the cough 1913. See Historic Context of proposed cornicet as the property owner. The building was described the property owner. The building was described and distinctive apartments. Part of their legacy Kansas City Architectural Club founded in 1901 DINGS secondary facade faces 11th Street. The adjaced Paseo is a non-contributing structure. The law	at the top. The ick with ice with BE PROVIDED ort to redevelop the construction of district.  esigned by Owen & Payson, Architects. In 1908 lesigned a variety of buildings, including a number y is active support of professional architectural 1 and the Kansas City Chapter of the AIA.  ent lot to the south is occupied by an apartment with at the east entrance is surrounded by a recently PREPARED BY  Brenda R. Spencer (785) 456-9857			
The east facade has a full-height colonnaded columns on the upper level. The porch has a railings on the porch were replaced in 1975. alternating raised and recessed bands. The upper level.  13. HISTORY AND SIGNIFICANCE  This colonnaded apartment building is directly blighted property along The Paseo Boulevard I elite apartment housing in the years 1901 through the second secon	porch with brick columns on the lower levels an substantial intermediate cornice and a cornice at the base of the building (first floor) is a dark bripper walls are red brick. A pressed metal cornice associated with the historically significant effort between 9th Street and 14th Street through the cough 1913. See Historic Context of proposed cornicet as the property owner. The building was detected as the property owner. The building was detected as the property owner. The building was detected as the property owner. Part of their legacy Kansas City Architectural Club founded in 1901 and distinctive apartments. Part of their legacy Kansas City Architectural Club founded in 1901 binds secondary facade faces 11th Street. The adjace of Paseo is a non-contributing structure. The law	est the top. The lick with lice with BE PROVIDED of the construction of district.  The esting of the e			
The east facade has a full-height colonnaded columns on the upper level. The porch has a railings on the porch were replaced in 1975. alternating raised and recessed bands. The upper level.  43. HISTORY AND SIGNIFICANCE  This colonnaded apartment building is directly blighted property along The Paseo Boulevard I elite apartment housing in the years 1901 through the second secon	porch with brick columns on the lower levels an substantial intermediate cornice and a cornice at the base of the building (first floor) is a dark bripper walls are red brick. A pressed metal cornice associated with the historically significant effort between 9th Street and 14th Street through the cough 1913. See Historic Context of proposed cornicet as the property owner. The building was detected as the property owner. The building was detected as the property owner. The building was detected as the property owner. Part of their legacy Kansas City Architectural Club founded in 1901 and distinctive apartments. Part of their legacy Kansas City Architectural Club founded in 1901 binds secondary facade faces 11th Street. The adjace of Paseo is a non-contributing structure. The law	at the top. The lick with BE PROVIDED out to redevelop the construction of district.  Sesigned by Owen & Payson, Architects. In 1908 designed a variety of buildings, including a number by is active support of professional architectural 1 and the Kansas City Chapter of the AIA.  Sent lot to the south is occupied by an apartment with at the east entrance is surrounded by a recently PREPARED BY  Brenda R. Spencer (785) 456-9857  ORGANIZATION			

1/00 "Typical" Interior corridor




















#9 1000 PASEO 1/00 Apartment Interior under remodeling due to fire note tile floor



#10 1000 PASEO 1/00 Building entry (east elevation)










1000 PASEO South east corner of building 1/00



1000 PASEO Porch detail (east elevation) 1/00







1000 PASEO East (front) elevation 1/00



1/00



"THE MAPLES" APARTMENT BUILDING, KANSAS CITY, MO.

EDWARDS & SUNDERLAND, ARCHITECTS.

### MISSOURI HISTORIC PRESERVATION PROGRAM

I.NO.		4. PRESENT LOCAL NAM			
	9. OTHER NAME(\$) Alameda Hotel, Parkview Hotel; Dr. McCleary's Parkview Hotel & Sanitarium				
Jackson Jackson					
LOCATION OF NEGATIVES	····		<del>,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,</del>		
SPECIFIC LEGAL LOCATION	IL THEMATIC	CATEGORY		28. NO. OF STORIES 5-1/2	
TOWNSHIP 49 RANGE 33 SECTION 4 IF CITY OR TOWN, STREET ADDRESS			}		
1000 The Paseo Boulevard	17. DATE(S) OR 1912	17. DATE(S) OR PERIOD 1912		29. BASEMENT YES (X) NO ( ) full  30. FOUNDATION MATERIAL natural faced, random coursed stone	
CITY OR TOWN IF RURAL, VICINITY		18. STYLE OR DESIGN Neo-Classical Colonnaded Building with Prairie influenced details		31. WALL CONSTRUCTION brick	
Kansas City				32. ROOF TYPE AND MATERIAL	
DESCRIPTION OF LOCATION		19. ARCHITECT OR ENGINEER  G. R. Sloep		flat - membrane  33. NO. OF BAYS	
Lots 7 thru 10, Block B, Pratts Addition		G. B. Sloan		FRONT 5 SIDE 1	
See Attached Map		20. CONTRACTOR OR BUILDER Walter M. Davis		34. WALL TREATMENT running bond brick	
COORDINATES UTM	21. ORIGINAL U	JSE, IF APPARENT	1	35. PLAN SHAPE	
LAT	Hotel	·······		'U' 36. CHANGES ADDITION()	
LONG	22. PRESENT U	SE	· · · · · · · · · · · · · · · · · · ·	(EXPLAIN IN ALTERED (X)	
SITE() STRUCTURE()	Apartmen			NO. 42) MOVED ( )	
BUILDING (X) OBJECT ( )  ON NATIONAL YES ( )	23. OWNERSHI	P PUBLIC ( ) PRIVATE (X)		37. CONDITION INTERIOR fair	
REGISTER? NO(')	24. OWNER'S N	24. OWNER'S NAME AND ADDRESS  Jazz Hill Homes, L.P. c/o Pioneer Group, Inc.* 1200 S. Kansas Ave. Topeka, KS 66612-1331		EXTERIOR good	
ISIT YES() ELIGIBLE NO()				38. PRESERVATION YES ( ) UNDERWAY7 NO (X)	
PART OF ESTAB. YES() HIST. DISTRICT NO (X)	25. OPEN TO PU	TBLIC YES ( ) NO (X)		39. ENDANGERED? YES (◊)  BY WHAT? NO()  blighted area, lack of maintenance	
	26. LOCAL CON	26. LOCAL CONTACT PERSON OR ORGANIZATION		40. VISIBLE FROM YES (X) PUBLIC ROAD NO()	
POTENTIAL NO()	*Ross Freeman	*Ross Freeman, Pioneer Group, Inc.785/232-1122			
NAME OF ESTABLISHED DISTRICT	27. OTHER SUR	EVEYS IN WHICH INCLUDED		41. DISTANCE FROM AND FRONTAGE ON ROAD	
2. FURTHER DESCRIPTION OF IMPORTANT FEATURE four-story porch has been modified slightlabs. The porch sets atop a dark brick base ap the porch projection and the top of the kinee double-hung windows. On the north file. HISTORY AND SIGNIFICANCE This colonnaded hotel building, constructed buildings constructed along The Paseo Boule	tly with the replace with ashlar stone building. On the east acade the first floor	banding. Projecting pres st facade, the windows a windows are either sing turally compatible with the	sed-metal c are grouped le double-hu he apartmer	errnices in sets of ung BE PROVIDED	
of 1901 and 1913. See historic context for A 1912 building permit identifies Walter M. builder of other apartment buildings in the arolf the "Alameda" Hotel. Two historic postolates unknown.	proposed district.  Davis as the owner ea including 930, 1	of the property at the tir 300, and 1304 Paseo.	me of constr A 1913 buil	ruction. Mr. Davis was also the owner/ ding permit identifies rebuilding fire damag	
4. DESCRIPTION OF ENVIRONMENT AND OUTBUT The primary facade faces The Paseo and the parking lot. North of the intersection of 10th several feet above the level of the sidewalk	e secondary facade h and Paseo, there	is an apartment building		nce on the east side of the building is raise	
S. SOURCE OF INFORMATION Building Permit	s 10605-1912, 543	345-1913; See	Brend 47. ORGAN	Ia R. Spencer (785) 456-9857	
ETURN THIS FORM WHEN COMPLETED TO			lazz Hill Homes, L.P. c/o Pioneer Group, Inc		
ADDITIONAL SPACE IS NEEDED, ATTACH	PO BOX 176	MO 65102	44. DATE	February 2000	
	JEFFERSON CITY, MO 65102			EVISION DATE(S)	

PHL 573-751-7858

SEPARATE SHEET(S) TO THIS FORM

#### 1000 PASEO - CONTINUATION SHEET

#### 42. FURTHER DESCRIPTION OF IMPORTANT FEATURES - Continued

windows or are grouped in sets of four double-hung windows. On all of the other facades the windows are either single or paired double-hung windows with exception of the first floor windows, which are in groups of three. The upper floor windows are enframed with ashlar stone blocks and all windows have ashlar stone sills. On the north facade there are two projecting bays, which occur at the second through fourth floors, with three windows in each bay. Pressed metal cornices cap each projecting bay. There are ashlar stone bands below the second floor windows and the upper floor windows. The stone foundation wall is coated with stucco on the north facade. There is historic floor tile extant in some parts of the interior. The windows and doors were replaced and the interior was remodeled during a HUD project in 1975. A 1937 building permit notes interior remodeling. According to a building permit, rear and front porches were added in 1953.


#### 44. DESCRIPTION OF ENVIRONMENT AND OUTBUILDINGS - Continued

south ends of the first floor porch to access the main entrance.

1401 E. 10th STREET Existing terrazzo/tile in apartment (possible former fireplace hearth)

#12









#9 1401 E. 10th STREET

#10 1401 E. 10th STREET 1/00 Replacement window exterior view

1401 E. 10th STREET Interior terrazzo stairway

1/00






#5 1401 E. 10th STREET 1/00 Porch and cornice detail (North elevation)



#6 1401 E. 10th STREET 1/00 East (side) elevation from NE corner of building










#2 1401 E. 10th STREET 1/00 South (rear) elevation

#1 1401 E. 10th STREET 1/00 North (front) elevation. & West (side) elevation from NW corner of building

### 1401 E. 10th STREET - CONTINUATION SHEET

#### 42. FURTHER DESCRIPTION OF IMPORTANT FEATURES - Continued

windows were replaced, a few windows on the secondary facades were filled with masonry, and the interior was remodeled during a HUD project in 1975.



#13 930 PASEO 1902 Source: <u>Kansas City Illustrated</u>

# MISSOURI HISTORIC PRESERVATION PROGRAM

I.NO.	4. PRESENT LOCAL NAME(S) OR DESIGNATION(S) Parkview Homes, The August					
2-COUNTY Jackson		5. OTHER NAME(S) The Maples Apartments				
LOCATION OF NEGATIVES			· · · · · · · · · · · · · · · · · · ·			
SPECIFIC LEGAL LOCATION TOWNSHIP 49 RANGE 33 SECTION 4	16 THEMATIC CA	ATEGORY		28. NO. OF STORIES 4-1/2		
IFCITY OR TOWN, STREET ADDRESS	17 DATE(S) OF S	17 hartman agricon		29. BASEMENT YES() NO() full + partial sub-basement (east side)		
1401 East 10th Street	circa 1906	17. DATE(S) OR PERIOD circa 1906		30. FOUNDATION MATERIAL natural faced, random coursed stone		
CITY OR TOWN IF RURAL, VICINITY	18. STYLE OR DESIGN Neo-Classical Colonnaded Apartment Building w/ Prairie Influences			31. WALL CONSTRUCTION brick		
Kansas City	Apartment Bui	iding w/ Frame initiden	1003	32. ROOF TYPE AND MATERIAL		
DESCRIPTION OF LOCATION		19. ARCHITECT OR ENGINEER		flat - membrane		
Lot 1, Block B, Pratts Addition	Edwards &	Sunderland	· · · · · · · · · · · · · · · · · · ·	33. NO. OF BAYS FRONT 5 SIDE 1		
See Attached Map	20. CONTRACTO	R OR BUILDER				
·	unknown	unknown		34. WALL TREATMENT Flemish bond red brick w/ dark klinkers		
COORDINATES UTM	21. ORIGINAL US	e, if apparent	-	35. PLAN SHAPE		
COORDINATES UTM LAT	Apartments			rectangular - long facade  36. CHANGES ADDITION()		
LONG	22. PRESENT USE	22. PRESENT USE Apartments		(EXPLAIN IN ALTERED (X) NO. 42) MOVED ( )		
SITE() STRUCTURE()	Apartments					
BUILDING(X) OBJECT()	23. OWNERSHIP	PUBLIC ( ) PRIVATE (X)		37. CONDITION INTERIOR fair		
ON NATIONAL YES()		(MINIEW)		EXTERIOR GOOD		
REGISTER? NO()	24. OWNER'S NAME AND ADDRESS		he micerniti more week			
ISIT YES() ELIGIBLE NO()						
PART OF ESTAB. YES() HIST. DISTRICT NO (X)	NO (x) BY WHAT? NO (					
DISTRICT YES (X)	26. LOCAL CONTACT PERSON OR ORGANIZATION		IZATION	40. VISIBLE FROM YES (X)		
POTENTIAL NO()	*Ross Freeman, F	*Ross Freeman, Pioneer Group, Inc.785/232-1122		PUBLIC ROAD NO()		
- NAME OF ESTABLISHED DISTRICT	27. OTHER SURVEYS IN WHICH INCLUDED		41. DISTANCE FROM AND PRONTAGE ON ROAD			
2. FURTHER DESCRIPTION OF IMPORTANT FEATUR. The three-story porches have modified lonic conrackets. A cornice projects from the exterior ypically have stone sills. The upper story win extant terrazzo and tile flooring and stairs at the	olumns. There is a wall at between the down have stone line.	e third and fourth stor ntels (flat arches with	ies. The wi keystones.)	ndows There is		
1. HISTORY AND SIGNIFICANCE This colonnaded apartment building is directly the blighted property along The Paseo Bouleva of elite apartment housing in the years 1901 to	associated with the	historically significant et and 14 <sup>th</sup> Street thro	t effort to re	edevelop		
The Maple's Apartment Building was designed same time, Edwards & Sunderland were respo Paseo. Both buildings were featured in Inland	nsible for the desig	n of the New England	Apartments	at 1116		
<ol> <li>DESCRIPTION OF ENVIRONMENT AND OUTBUILD The primary facade faces 10<sup>th</sup> Street and the lot to the east contains an apartment building.</li> </ol>	secondary facade fi		s located on	the adjacent lot to the south.		
			46. PREPARED BY			
See Bibliography Sources: 1 7 12 13 29	21 and 22		Brenda R. Spencer (785) 456-9857			
See Bibliography, sources: 1, 7, 12, 13, 29,				47. ORGANIZATION		
LETURN THIS FORM WHEN COMPLETED TO: OFFICE OF HISTORIC PRESERV/ PO BOX 176			for Jazz Hill Homes, L.P. c/o Pioneer Group, Inc.			
and the second s			48. DATE February 2000			
UDABATE CUTTOWN MA MICH.				49. REVISION DATE(S)		

PHL 573-751-7858

SEPARATE SHEET(S) TO THIS FORM


930 PASEO "Typical" Apartment Interior

#12












#10 930 PASEO 1/00 2nd floor interior stairway



1/00





930 PASEO Porch doorway (2nd level) 1/00

930 PASEO Entry detail (east elevation) 1/00 







#1 930 PASEO 1/00 East (front) elevation



#2 930 PASEO 1/00 North (side) elevation from NW corner of building

#### 930 PASEO - CONTINUATION SHEET

#### 42. FURTHER DESCRIPTION OF IMPORTANT FEATURES - Continued

"quoins" and porch columns are white glazed brick. The porch columns have ornamental terra cotta details at the top. The window surrounds on the second, third and fourth floors are ashlar stone. The main entrance on the east facade is an entablature on columns. The east door is surrounded by elaborate cut stone. The interior wood stairway is intact. A 1917 building permit notes that sleeping porches were added over the stairs. The porch railings, porch steps, doors, and windows were replaced, a rear fire escape was added, and the interior was remodeled during a HUD project in 1975.

#### 44. DESCRIPTION OF ENVIRONMENT AND OUTBUILDINGS - Continued

with Neo-Classical detailing adjacent to the sidewalk.



## MISSOURI HISTORIC PRESERVATION PROGRAM

1.NO.	4. PRESENT LOCAL NAME(S) OR DESIGNATION(S) Parkview Homes, The Maryland				
2-COUNTY Jackson		5. OTHER NAME(S)			
3-LOCATION OF NEGATIVES			· · · · · · · · · · · · · · · · · · ·		
6 SPECIFIC LEGAL LOCATION 16 TOWNSHIP 49 RANGE 33 SECTION 4		CATEGORY		28. NO. OF STORIES 4-1/2	
IF CITY OR TOWN, STREET ADDRESS	LT DATEM OF PRIOR			29. BASEMENT YES (X) NO ( ) full	
930 The Paseo Boulevard	17. DATE(S) OR PERIOD  1901		Ì	30. FOUNDATION MATERIAL coursed, ashlar stone	
CITY OR TOWN IF RURAL, VICINITY	18. STYLE OR DESIGN			3). WALL CONSTRUCTION brick	
Kansas City	Neo-Classical			32. ROOF TYPE AND MATERIAL	
DESCRIPTION OF LOCATION 19. ARCHI		T OR ENGINEER		flat - membrane  33. NO. OF BAYS FRONT 3; 5 w/ porches SIDE 6	
(Southern Section) Lots 11 Thru 14 of	unknown				
Block A, Pratts Addition (924, 928, and 930 Paseo are combined in one legal	20. CONTRACTOR OR BUILDER unknown				
description). See Attached Map				34. WALL TREATMENT running bond brick	
P. COORDINATES UTM	21. ORIGINAL I	use, if apparent		35. PLAN SHAPE rectangular - short facade 36. CHANGES ADDITION()	
COORDINATES UT:M	Apartmen	its			
LONG	22. PRESENT U	ISE		(EXPLAIN IN ALTERED (X)	
0. SITE() STRUCTURE()	Apartments			NO. 42) MOVED ( )	
BUILDING (X) OBJECT()	23. OWNERSHI	23. OWNERSHIP PUBLIC ( ) PRIVATE (X)		37. CONDITION	
1. ON NATIONAL YES()	1			INTERIOR fair EXTERIOR good	
REGISTER? NO()				EXTERIOR GOOD	
2 isit yes() Eligible NO()	Jazz Hill Homes, L.P. c/o Pioneer Group, Inc.* 1200 S. Kansas Ave. Topeka, KS 66612-1331  25. OPEN TO FUBLIC  YES()  NO(X)			38. PRESERVATION YES() UNDERWAY? NO(X)  39. ENDANGERED? YES(X) BY WHAT? NO() blighted area, lack of maintenance	
13. PART OF ESTAB. YES() HIST. DISTRICT NO (X)					
14 Manual Carlo	26. LOCAL CONTACT PERSON OR ORGANIZATION *Ross Freeman, Pioneer Group, Inc.785/232-1122 27. OTHER SURVEYS IN WHICH INCLUDED		ZATION	40. VISIBLE FROM YES (X)	
POTENTIAL NO()				PUBLIC ROAD NO()	
15. NAME OF ESTABLISHED DISTRICT			41. DISTANCE FROM AND FRONTAGE ON ROAD		
42. FURTHER DESCRIPTION OF IMPORTANT FEATURI The first floor exterior material is tan brick that is a stone band between the brick of the first fl stone banding below the fourth floor windows. projecting cornice is pressed metal with ornam 43. HISTORY AND SIGNIFICANCE This apartment building is directly associated w property along The Paseo Boulevard between 9	is banded and door and the red to There is glazed entation that including with the historical	brick of the upper floors. white brick below the coudes dentils, brackets, a	There is accornice. The and lion head	dditional  Is. The  BE PROVIDED	
apartment housing in the years 1901 through 1 A 1901 water permit identifies Walter M. Davis of the Alameda/Parkview Hotel at 1000 Paseo	1913. See Histori s as owner of the	ic Context for the propose property. Mr. Davis wa	sed district. as also own	er/builder	
1304 Paseo.  4. DESCRIPTION OF ENVIRONMENT AND OUTBUILD The primary facade faces The Paseo and the s South of the intersection of 10th and Paseo, t feet above the level of the sidewalk and there	INGS econdary facade here is an apartm	faces 10 <sup>th</sup> Street. The a	adjacent lots	s to the north contain apartment buildings. nd south side of the building is raised several	
45. SOURCE OF INFORMATION Water Permit #1817, 1901; See E		Bibliography,	Brenda R. Spencer (785) 456-9857		
sources: 1, 7, 9 RETURN THIS FORM WHEN COMPLETED TO : C	9, 13, 14, 29, 30 DEFICE OF HISTO	·	47. ORGANIZATION for Jazz Hill Homes, L.P. c/o Pioneer Group, Inc		
P	O BOX 176	4.	44 DATE February 2000		
	EFFERSON CITY	, MO 65102			
EPARATE SHEET(S) TO THIS FORM PH. 573-751-7858			49. REVISION DATE(S)		

POLY-VO



TOWNSHIP 49 RANGE 33 SECTION 4  IFCITY OR TOWN, STREET ADDRESS  928 The Paseo Boulevard  7. CITY OR TOWN  Kansas City  8. DESCRIPTION OF LOCATION  (Center Section) Lots 11 Thru 14 of Block A, Pratts Addition (924, 928, and 930 Paseo are combined in one legal description). See Attached Map  9. COORDINATES  LAT  LONG  10. SITE() STRUCTURE() BUILDING(X) OBJECT()  11. ON NATIONAL YES() REGISTER? NO()  12. ISIT YES() ELIGIBLE NO()  13. PART OF ESTAB. YES() HIST. DISTRICT NO(X)  14. DISTRICT YES(X) POTENTIAL NO()  15. PARS FROM PROSEN FOR STRUCTURE  16. SITE() STRUCTURE() 22. PRES  24. OWN 25. OPEN  16. PART OF ESTAB. YES() HIST. DISTRICT NO(X)  26. LOC.  *Ross From Proceedings of the Process	S. OTHER NAME(S) The Ellsworth  MATIC CATEGORY  E(S) OR PERIOD a 1906  E OR DESIGN  connaded Apartment Building  HITECT OR ENGINEER  nown  TRACTOR OR BUILDER  nown  TNAL USE, IF APPARENT  rtments  ENT USE  rtments  ERSHIP  PUBLIC ( )  PRIVATE (X)	28. NO. OF STORIES 3-1/2  29. BASEMENT YES (X) NO ( ) full  30. FOUNDATION MATERIAL natural faced, coursed, rubble stone  31. WALL CONSTRUCTION brick  32. ROOF TYPE AND MATERIAL flat - membrane  33. NO. OF BAYS FRONT 3 SIDE 1  34. WALL TREATMENT running bond brick (painted)  35. PLAN SHAPE rectangular - short facade  36. CHANGES ADDITION ( ) (EXPLAIN IN ALTERED (X) NO. 42) MOVED ( )
4 SPECIFIC LEGAL LOCATION TOWNSHIP 49 RANGE 33 SECTION 4 IF CITY OR TOWN, STREET ADDRESS  928 The Paseo Boulevard  7. CITY OR TOWN Kansas City  8. DESCRIPTION OF LOCATION (Center Section) Lots 11 Thru 14 of Block A, Pratts Addition (924, 928, and 930 Paseo are combined in one legal description). See Attached Map  9. COORDINATES UTM LAT LONG  10. SITE() STRUCTURE() BUILDING(X) OBJECT()  21. ORK Apa 22. PRES Apa 23. OWN  11. ON NATIONAL YES() REGISTER? NO()  12. ISIT YES() ELIGIBLE NO()  13. PART OF ESTAB. YES() HIST. DISTRICT NO(X)  14. DISTRICT YES(X) POTENTIAL NO()  15. NAME OF ESTABLISHED DISTRICT	E(S) OR PERIOD a 1906 E OR DESIGN connaded Apartment Building HITECT OR ENGINEER mown FRACTOR OR BUILDER mown INAL USE, IF APPARENT rtments ENT USE ertments FRSHIP PUBLIC ( )	29. BASEMENT YES (X) NO() full  30. FOUNDATION MATERIAL natural faced, coursed, rubble stone  31. WALL CONSTRUCTION brick  32. ROOF TYPE AND MATERIAL flat - membrane  33. NO. OF BAYS FRONT 3 SIDE 1  34. WALL TREATMENT running bond brick (painted)  35. FLAN SIAPE rectangular - short facade  36. CHANGES ADDITION () (EXPLAIN IN ALTERED (X) NO. 42) MOVED ()
TOWNSHIP 49 RANGE 33 SECTION 4 IF CITY OR TOWN, STREET ADDRESS  928 The Paseo Boulevard  7. CITY OR TOWN  FRURAL, VICINITY  Kansas City  19. ARC  (Center Section) Lots 11 Thru 14 of Block A, Pratts Addition (924, 928, and 930 Paseo are combined in one legal description). See Attached Map  20. CON  Unk  11. OR COORDINATES  LAT  LONG  12. SITE() STRUCTURE()  BUILDING(X) OBJECT()  13. PART OF ESTAB. YES() HIST. DISTRICT  NO()  14. DISTRICT  YES(X) POTENTIAL  NO()  15. NAME OF ESTABLISHED DISTRICT	E(S) OR PERIOD a 1906 E OR DESIGN connaded Apartment Building HITECT OR ENGINEER mown FRACTOR OR BUILDER mown INAL USE, IF APPARENT rtments ENT USE ertments FRSHIP PUBLIC ( )	29. BASEMENT YES (X) NO() full  30. FOUNDATION MATERIAL natural faced, coursed, rubble stone  31. WALL CONSTRUCTION brick  32. ROOF TYPE AND MATERIAL flat - membrane  33. NO. OF BAYS FRONT 3 SIDE 1  34. WALL TREATMENT running bond brick (painted)  35. FLAN SIAPE rectangular - short facade  36. CHANGES ADDITION () (EXPLAIN IN ALTERED (X) NO. 42) MOVED ()
(Center Section) Lots 11 Thru 14 of Block A, Pratts Addition (924, 928, and 930 Paseo are combined in one legal description). See Attached Map  9. COORDINATES LAT LONG  10. SITE() STRUCTURE() BUILDING(X) OBJECT()  11. ON NATIONAL YES() REGISTER? NO()  12. ISIT YES() ELIGIBLE NO()  13. PART OF ESTAB. YES() HIST. DISTRICT NO(X)  14. DISTRICT YES(X) POTENTIAL NO()  15. NAME OF ESTABLISHED DISTRICT  16. Unit 14 OWN 21. ORN 22. PRES 22. PRES 23. OWN 24. OWN 25. OPER 25. OPER 27. OTH	TRACTOR OR BUILDER TOWN  INAL USE, IF APPARENT  THENT USE  ENT USE  THENT OF THE PUBLIC ( )	33. NO. OF BAYS FRONT 3 SIDE 1  34. WALL TREATMENT running bond brick (painted)  35. FLAN SHAPE rectangular - short facade  36. CHANGES ADDITION ( ) (EXPLAIN IN ALTERED (X) NO. 42) MOVED ( )  37. CONDITION
LAT LONG  22. PRES Aps	ENT USE rtments ERSHIP PUBLIC ( )	36. CHANGES ADDITION ( ) (EXPLAIN IN ALTERED (X) NO. 42) MOVED ( )
REGISTER? NO()  12. ISIT YES() ELIGIBLE NO()  13. PART OF ESTAB. YES() HIST. DISTRICT NO()  14. DISTRICT YES() POTENTIAL NO()  15. NAME OF ESTABLISHED DISTRICT  16. NAME OF ESTABLISHED DISTRICT  17. OTH	- ·	
25. OPER  13. PART OF ESTAB. YES ( ) HIST. DESTRICT NO (X)  14. DISTRICT YES (X) POTENTIAL NO ( )  15. NAME OF ESTABLISHED DISTRICT  25. OPER  26. LOC. *Ross Fr.  27. OTH	ER'S NAME AND ADDRESS II Homes, L.P. c/o Pioneer Group, Inc. I. Kansas Ave. Topeka, KS 66612-133	
POTENTIAL NO()  15. NAME OF ESTABLISHED DISTRICT  17. OTH	TO PUBLIC YES ( ) NO (X) AL CONTACT PERSON OR ORGANIZATION	39. ENDANGERED? YES (X) BY WHAT? NO() vacant, blighted area, lack of maintenance 40. VISIBLE FROM YES (X)
42. FURTHER DESCRIPTION OF IMPORTANT FRATURES	eman, Pioneer Group, Inc.785/232-1122 SR SURVEYS IN WHICH INCLUDED	PUBLIC ROAD NO()  41. DISTANCE FROM AND FRONTAGE ON ROAD
alternating bands (quoins) of white glazed brick and red brick of white glazed brick. The historic doors, sidelights, transporch railings, front steps, and windows were replaced, a remodeled during a HUD project in 1975.  43. HISTORY AND SIGNIFICANCE  This colonnaded apartment building is directly associated the blighted property along The Paseo Boulevard between of elite apartment housing in the years 1901 through 191	ick. The three-story porch has full-hei om windows, and interior stairway are rear fire escape was added, and the inwith the historically significant effort to 9th Street and 14th Street through the	ght columns intention was BE PROVIDED  oredevelop construction
44. DESCRIPTION OF ENVIRONMENT AND OUTBUILDINGS The property faces The Paseo. Adjacent lots to the north several feet above the level of the sidewalk and there is a foundation wall, near the sidewalk.	natural-faced and coursed limestone	s. The lawn at the front of the building is raised retaining wall, which matches the stone

several feet above the level of the sidewalk and there is a natural-faced and coursed limestone retaining wall, which matches the stone foundation wall, near the sidewalk.

45. SOURCE OF INFORMATION
See Bibliography, sources: 1, 7, 9, 13, 29, 31, and 32.

RETURN THIS FORM WHEN COMPLETED TO: OFFICE OF HISTORIC PRESERVATION
PO BOX 176

IF ADDITIONAL SPACE IS NEEDED, ATTACH
SEPARATE SHEET(S) TO THIS FORM
PH. 573-751-7858

IF APPLICATION PLANTAGE IS NEEDED, ATTACH
SEPARATE SHEET(S) TO THIS FORM
PH. 573-751-7858



928 PASEO East (front) elevation 1/00



928 PASEO North (side) elevation from NE corner of building



928 PASEO Porch detail (east elevation) 1/00



928 PASEO
West (rear) elevation and south (side) elevation from sw corner of building 1/00





928 PASEO Porch detail (east elevation)

1/00

928 PASEO Transom at east entry





928 PASEO 2nd floor interior stairway

1/00







#11 928 PASEO 1/00 "Typical" Interior Corridor



#12 928 PASEO 1/00 "Typical" Apartment Interior

924 PASEO "Typical" Apartment Interior

#12







#9 924 PASEO 1/00 Interior view replacement windows #10 924 PASEO 1/00 "Typical" Interior Corridor

924 PASEO West (rear) elevation

1/00







#5 924 PASEO 1/00 Porch detail (east elevation)



#6 924 PASEO 1/00 South (side) elevation-west end

924 PASEO Exterior view of replacement windows (on porch)


1/00







924 PASEO East (front) elevation 1/00



924 PASEO North (side) elevation from NE corner of building 1/00

<b>MISSOURI</b>	HISTORI	C PRESER	VATION	<b>PROGRAM</b>
ARCHITECTURA	L/HISTORIC IN	VENTORY FORM	<b>1</b>	

1.10.		PRESENT LOCAL NAME(S) OR DESIGNATION(S)     Parkview Homes, The Kessler Building			
3-LOCATION OF NEGATIVES					
& SPECIFIC LEGAL LOCATION	16 THEMATIC	CATEGORY		28. NO. OF STORIES	
TOWNSHIP 49 RANGE 33 SECTION 4 IF CITY OR TOWN, STREET ADDRESS		CATEGORY		2-1/2 29. BASEMENT YES(X) NO( )	
924 The Paseo Boulevard	17. DATE(S) OR PERIOD between 1896-1909		F	partial  30. FOUNDATION MATERIAL natural faced, coursed, rubble stone	
7. CITY OR TOWN IF RURAL, VICINITY	18. STYLE OR DESIGN Colonnaded Apt. Bidg. —			31. WALL CONSTRUCTION brick	
Ransas City  8. DESCRIPTION OF LOCATION	Queen Anne w/ Neo Classical modifications  19. ARCHITECT OR ENGINEER		ations	32. ROOF TYPE AND MATERIAL flat - membrane	
(Northern Section) Lots 11 Thru 14 of Block A, Pratts Addition (924, 928, and	unknown	<u> </u>		33. NO. OF BAYS FRONT 2; 3 on porch SIDE 4	
930 Paseo are combined in one legal description). See Attached Map	20. CONTRACTO	or or builder	ŀ	14. WALL TREATMENT running bond red brick	
9. COORDINATES UTM	: <b>i</b>	SE, IF APPARENT		35. PLAN SHAPE rectangular - short facade  36. CHANGES ADDITION (X)	
LAT LONG	Apartment	<del></del>			
	22. PRESENT US Apartmen		ı	(EXPLAIN: IN: ALTERED (X) NO. 42) MOVED ( )	
10. SITE() STRUCTURE()  BUILDING (>) OBJECT()	23. OWNERSHI	23. OWNERSHIP PUBLIC( )		37. CONDITION INTERIOR good EXTERIOR good	
11. ON NATIONAL YES() REGISTER? NO()	24. OWNER'S NAME AND ADDRESS  Jazz Hill Homes, L.P. c/o Pioneer Group, Inc.* 1200 S. Kansas Ave. Topeka, KS 66612-1331				
12. ISIT YES() ELIGIBLE NO()			38. PRESERVATION YES() UNDERWAY? NO(X)		
13. PART OF ESTAB. YES()	25. OPEN TO PUBLIC YES ( ) NO (X)  26. LOCAL CONTACT PERSON OR ORGANIZATION *Ross Freeman, Pioneer Group, Inc.785/232-1122  27. OTHER SURVEYS IN WHICH INCLUDED			39. ENDANGERED? YES (X) BY WHAT? NO()	
HIST. DISTRICT NO (X)			IZATION	blighted area, lack of maintenance  40. VISIBLE FROM YES (X)	
14. DISTRICT YES CO POTENTIAL NO()			ł	PUBLIC ROAD NO()  41. DISTANCE FROM AND FRONTAGE ON ROAD	
15. NAME OF ESTABLISHED DISTRICT			D		
42. FURTHER DESCRIPTION OF IMPORTANT FRATUR. The upper facade is ornamented with brick cornot part of the original construction but was ac existing porch replaced a smaller porch located porch railings and floor, front steps, windows, during a HUD project in 1975.  43. HISTORY AND SIGNIFICANCE  This colonnaded apartment building is directly redevelop the blighted property along The Pase through the construction of elite apartment hot for proposed district.	Ided along with a lin the void of the and doors were reassociated with the Boulevard betw	rear addition between 1e 'L' on the SE corner of eplaced and the interior ne historically significant veen 9th Street and 14th	1925 - 1940. If the building was remode  at effort to Street	The PHOTO MUST	
44. DESCRIPTION OF ENVIRONMENT AND OUTBUILD The property faces The Paseo. The half-block The lawn at the front of the building is raised retaining wall, which matches the stone found.	k to the north of t several feet above	the level of the sidewa	alk and there 46. PREPAR	is a natural-faced and coursed limestone ED BY	
45. SOURCE OF INFORMATION See Bibliography, sources: 1, 3, 7, 9, 13, 29	45. SOURCE OF INFORMATION See Bibliography, sources: 1, 3, 7, 9, 13, 29, 31, and 32.		Brenda R. Spencer (785) 456-9857  47. ORGANIZATION		
LETURN THIS FORM WHEN COMPLETED TO: OFFICE OF HISTORIC PRESERVATION PO BOX 176		for Jazz Hill Homes, L.P. c/o Pioneer Group, Inc.			
			48. DATE February 2000		
SEPARATE SHEET(S) TO THIS FORM	PHL 573-751-7858		49. REVISION DATE(S)		

### **Images of Kansas City**

Photographs Postcards Maps Biographies Exhibits

**Photographs** 

Central Methodist Church, 11th and Paseo, full frontal and side view.



Location:

Churches--Methodist #6

Negative Number: V-626-6


Dimensions: 8x10

Identifier Number: 10001716

#22

CONTEXT Date unknown Images of Kansas City Kansas City Library
The church has been demolished

**Photograph Collection Home** 



The old 11-foot-long Spanish cannon, cast in Seville, Spain, in 1865 from 6,500 pounds of bronze, with the crest of Spain inscribed near the breech and the words "Sancho El Bravo" inscribed near the muzzle, was a gift from the United States government to the Kansas City Board of Park Commissioners Aug. 22,

The cannon had been captured by the U.S. Navy the year before during the Spanish-American war, in the battle of Santiago. For years, every evening at sunset, it had been fired in a ceremony in Santiago.


After its presentation to Kansas City several locations were suggested for its placement: 15th and the Paseo, Gladstone Boulevard near Scarritt Point, 12th and the Paseo, and 9th and the Paseo. It was placed at 12th and the Paseo, as shown on the old post card, at the north end of the colorful sunken flower gardens and was pointed south. The fashionable Paseo had just been completed as far south as 17th.

The cannon still stands at the location today. All the apartments shown in the picture, some of Kansas City's finest at the time, have been razed within the last few years.

Kansas City Times June 29, 1974

1899.

Date unknown
Mrs. Sam Ray's Postcard Collection
Kansas City Library, Special Collections
Note: Apartments on the East side of
The Paseo were demolished through
Urban Renewal.



The 3-story mansion of Dr. Generous L. Henderson at 1016 Paseo, built before the turn of the century of cut stone and glazed brick with terra cotta ornamentation, still stands today, and is still protected by the spikes of a tall wrought-iron fence.

Dr. Henderson is listed at the Paseo address in city directories as early as 1900. (His former home was in the Mulkey Square district.)

The Paseo residence is pictured on the old post card beyond the pergola or colonnade between the Paseo roadways.

At the rear of the Henderson place was the stone barn and carriage house, large enough for several horses and vehicles.

The Neo-Palladian style home was designed by Rudolph Markgras. Notable in the interior are the pastel shaded ceilings of the drawing room and parlor, which are still in good condition. They are described by James Ryan, a curator of the Kansas City Museum, as "tinted ornamental plasterwork in Louis XV style, featuring a scallop shell and white blossoms." The same design is carried out on the front of the fireplace.

The monumental mahogany staircase, with classical balustrade, leads up from the entrance hall and features a "musician's gallery" in the bay window at the first landing.

Isadore Chinn of Higginsville, Mo., present owner, rents out rooms in the once fashionable mansion.

Kansas City Times April 13, 1974 A spring scene is shown on this 1910 post card of the pergola on the Paseo.


A high-seated motor car and a horse and buggy are the only traffic on the fashionable boulevard.

Minutes of a park board meeting of Aug. 24, 1898, show the city engineer was instructed to have "foundation for peers for arbor or pergola built between 10th Street and 11th Street in the Paseo."

After advertisements were circulated for bids for material and labor "to be performed in the execution and completion of terra cotta cut stone and timber pergola," a contract was awarded George W. Goodlander, Aug. 2, 1899. Sidewalks, trees, vines and other plantings completed the project.

In 1971, almost 80 years later, the park board built a new overhead trellis in concrete, using the old wood beams as forms. They also replaced broken or damaged sidewalks and steps. This spring new plants and vines will be planted to complete the restoration of the early day landmark.

Kansas City Times April 28, 1978



The New York apartments at the northwest corner of 12th and the Paseo, shown at the right side of the post card, served a quality clientele early in this century, and the sturdy building with the rounded façade and eight tall Ionic columns became a landmark.

This apartment house was one of the four pictured in Emery-Bird-Thayer's 24-page 1908 brochure extolling the beauty spots and accomplishments of Kansas City at the time. (Other apartments pictured were the Elsmere, the Eleanor and the Maryland.)

In the foreground are the carefully landscaped sunken gardens of the park board, their pride, as was all of the Paseo, Kansas City's finest and longest of the boulevard system.

The church dome seen in the background, is that of the newly finished central Methodist Church at 11th and the Paseo. It seated 2,500 persons and was one of the largest and best-equipped in the city.

Today fire and age show their scars on the aristocratic old New York apartment house. Only two of the stately pillars remain in place and they are cracked, unpainted and without a roof above them.

Other old homes and apartments directly east across the street on Paseo have been razed as part of the 12th and Vine urban renewal project which extends from the Paseo east to Woodland, and from 9th to 12th.

The post card was printed in color by Paul Eskenasay, 107 W. 9th, Kansas City.

Kansas City Times February 26, 1972

18 CONTEXT

Date unknown
Mrs. Sam Ray's Postcard Collection
Kansas City Library, Special Collections
Note: the New York Apartments have
since been demolished



Sunken flower gardens, an old Spanish cannon, the Central Methodist South Church (in background) and two fine apartment buildings are pictured on the triple post card panorama showing the Paseo at the turn of the century.

The Circle apartment (left center), built in 1905 and the New York (with tall columns), 1906, are still standing.

The apartments are typical of those built in Kansas City at this time with large open porches.

John W. McKecknie, well-known Kansas City architect of the period, in an interview May 16, 1900, discussing Kansas City apartments, commented: "The porches of necessity are a dominating feature of the modern flat in this climate."

Recently the Paseo roadway between 11th and 13th was relocated so that the sharp turn at the vine-covered retaining wall at 12th could be eliminated.

New sidewalks, curbs, traffic lights and traffic islands have been installed. The cannon was moved 50 feet east and the old sunken gardens were leveled and regraded for new landscaping.

Kansas City Times January 11, 1975

#### **#17 CONTEXT**

Date unknown Mrs. Sam Ray's Postcard Collection Kansas City Library, Special Collections Note: the New York Apartments have since been demolished








#13 CONTEXT
1/00 1100 block of Paseo with
The Terrace in foreground
1116, 1106 & 1100 Paseo
in background

#14 CONTEXT
1/00 1200 block of Paseo
Fitzsimons Memorial at 11th
1200, 1116, 1106, 1100
Paseo (L to R in background)

CONTEXT

1/00/1









#9 CONTEXT
1/00 900 block of Paseo from
Women's Leadership Fountain
930, 928, & 924 Paseo in
background



#10 CONTEXT
1/00 August R. Meyer Memorial
at 10th & Paseo
930, 928, & 924 Paseo in
background





CONTEXT 13th & Paseo (SW corner) 1304 and 1300 Paseo (L to R)

1/00



#5 CONTEXT 1/00 1100 Block of Paseo 1106 and 1100 Paseo (L to R)



#6 CONTEXT 1/00 1100 Block of Paseo 1116 Paseo (foreground)





#10 1304 PASEO 1/00 "Typical" Apartment interior

#9 1304 PASEO 1/00 "Typical" Apartment interior 





1304 PASEO Cornice detail (East elevation) 1/00




#6 1304 PASEO 1/00 Porch/entry detail (east elevation)

1304 PASEO West (rear) elevation

1/00







#1 1304 PASEO 1/00 East (front) elevation 

#2 1300 PASEO 1/00 South (side) elevation from SE corner of building

### **Images of Kansas City**

Photographs Postcards Maps Biographies Exhibits

**Photographs** 

Cars in procession moving southward along the Paseo at 14th. 1923 Harding visible.



### Location:

Parades--Presidential--Harding #3

Negative Number: V-2316

Dimensions: 8x10

Identifier Number: 10005521

### **Related Subjects:**

Presidential Parade
Paseo
14th Street

#13 1300 PASEO

1923 Images of Kansas City Kansas City Public Library

**Photograph Collection Home** 

# MISSOURI HISTORIC PRESERVATION PROGRAM

ARCHITECTURAL/HISTORIC INV	ENTURY FO	· · · · · · · · · · · · · · · · · · ·				
I'NO'		PRESENT LOCAL NAME(S) OR DESKINATION(S)     Parkview Homes, The Lovett				
2-COUNTY Jackson		5. OTHER NAME(S) The Missouri Apartments				
3-LOCATION OF NEGATIVES	•					
& SPECIFIC LEGAL LOCATION 16 THEN		CATEGORY	28. NO. OF STORIES 3-1/2			
TOWNSHIP 49 RANGE 33 SECTION 4 IF CITY OR TOWN, STREET ADDRESS			29. BASEMENT YES (X) NO()			
1304-06 The Paseo Boulevard	17. DATE(S) OF	R PERIOD	full 30. FOUNDATION MATERIAL			
7. CITY OR TOWN IF RURAL, VICINITY	IS. STYLE OR	VERN	natural faced, random coursed stone			
Kansas City		sical Colonnaded Apartn				
1. DESCRIPTION OF LOCATION	19. ARCHITEC	T OR ENGINEER	32. ROOF TYPE AND MATERIAL flat - membrane			
ast 109.75 feet of Lot 17, South 10 feet of /est 27 feet of Lot 17, East 109.75 feet of Lot	unknown		33. NO. OF BAYS FRONT 3 SIDE 3			
8; Block 2, Munford & Francher's Addition.		OR OR BUILDER				
1300-02 & 1304-06 Paseo are combined in one egal description. See Attached Map.	Walter M.	. Davis	34. WALL TREATMENT running bond brick			
9. COORDINATES UTM		USE, IF APPARENT	35. PLAN SHAPE rectangular - short facade			
LAT LONG	Apartmen	<del></del>	36. CHANGES ADDITION()			
	22. PRESENT U	•	(EXPLAIN IN ALTERED (X) NO. 42) MOVED ( )			
16. SITE() STRUCTURE() BUILDING() OBJECT()	23. OWNERSHI	·	37. CONDITION			
II. ON NATIONAL YES()	-	PRIVATE (X)	INTERIOR fair - good			
REGISTER? NO()	24. OWNER'S N	AME AND ADDRESS	EXTERIOR good			
12. ISTT YES() ELIGIBLE NO()		nes, L.P. c/o Pioneer Gr sas Ave. Topeka, KS 66				
13. PART OF ESTAB. YES() HIST. DISTRICT NO (X)	25. OPEN TO PO	UBLIC YES() NO(X)	39. ENDANGERED? YES (★) BY WHAT? NO() blighted area, lack of maintenance			
***	26. LOCAL COL	NTACT PERSON OR ORGAN	ization 40. Visible from Yes (x)			
POTENTIAL NO()	*Ross Freeman	, Pioneer Group, Inc.785/	/232-1122 PUBLIC ROAD NO()			
15. NAME OF ESTABLISHED DISTRICT	27. OTHER SUI	rveys in which include	41. DISTANCE FROM AND FRONTAGE ON ROAD			
42. FURTHER DESCRIPTION OF IMPORTANT FEATURE. The central bay of the east facade is a full-he projecting cornices. The original wooden porcedes. There are four glazed brick (white) pil in alternating courses of buff brick and white	ight projecting por ch railings were rep asters at the east	placed with metal in 197 facade. The brick at the	75 to meet life-safety e first floor is banded			
43. HISTORY AND SIGNIFICANCE This colonnaded apartment building is directly blighted property along The Paseo Boulevard elite apartment housing in the years 1901 thr	between 9 <sup>th</sup> Street ough 1913. See h	t and 14 <sup>th</sup> Street through historic context for the p	h the construction of proposed district.			
			Commission records identify Walter Davis also as the tments at 930 Paseo in 1901 and the Alameda/Parkview			
44. DESCRIPTION OF ENVIRONMENT AND OUTBUIL The primary facade faces The Paseo. There is south are occupied by single-family residence	s a small lawn bet		he sidewalk on the east side. The adjacent lots to the an apartment building.			
			46. PREPARED BY			
45. SOURCE OF INFORMATION Water Permit sources: 1, 7,	#18420-1901; Sec 9, 13, 27, 29, 31		Brenda R. Spencer (785) 456-9857  47. ORGANIZATION			
RETURN THIS FORM WHEN COMPLETED TO:	OFFICE OF HISTO		for Jazz Hill Homes, L.P. c/o Pioneer Group, Inc.			
IF ADDITIONAL SPACE IS NEEDED, ATTACH	PO BOX 176 JEFFERSON CITY	MO 65102	48. DATE February 2000			
SEPARATE SHEET(S) TO THIS FORM	PH. 573-751-785		49: REVISION DATE(S)			

### 1304 PASEO - CONTINUATION SHEET


### 42. FURTHER DESCRIPTION OF IMPORTANT FEATURES - Continued

brick cornice at the top of the east facade. Ashlar stone window sills are present on all of the double-hung windows. The second story windows on the east facade have flat ashlar lintels. The building was converted from six to twelve apartments in 1944 (Building Permit #15745-A). A 1957 building permit notes the addition of the front fire escape. The doors and windows were replaced and a fire escape was installed at the rear of the building in 1975. The interior was remodeled in 1975, but the wooden stairway and several door surrounds are extant.

1300 PASEO "Typical" interior door/surround

#12







1300 PASEO 2nd level porch entry from porch 1/00



1300 PASEO 2nd level porch entry from interior #10








1/00

1300 PASEO Detail east elevation 1/00







North (side) elevation & West (rear) elevation from NW corner of building

1/00



1300 PASEO East (front) elevation 1/00



1300 PASEO South (side) elevation from SE corner of building 1/00

# MISSOURI HISTORIC PRESERVATION PROGRAM

ARCHITECTURAL/HISTORIC INVI	ENTORY FO	)RM		<u>.</u>		
LNO.		PRESENT LOCAL NAME(S) OR DESIGNATION(S)     Parkview Homes, The Thomas				
2-COUNTY Jackson	5. OTHER NAME(S)  The Maine Apartments and The Missouri Apartments (along w/ 1304 Paseo)					
3-LOCATION OF NEGATIVES						
& SPECIFIC LEGAL LOCATION	4			VO OR STORMS		
TOWNSHIP 49 RANGE 33 SECTION 4 IF CITY OR TOWN, STREET ADDRESS	IN THEMATIC	14. THEMATIC CATEGORY		NO. OF STORIES 3-1/2  BASEMENT YES (X) NO()		
1300-02 The Paseo Boulevard	17. DATE(S) OR 1901	PERIOD	30.	full  FOUNDATION MATERIAL stural faced, coursed rubble stone		
7. CITY OR TOWN IF RURAL, VICINITY Kansas City	18. STYLE OR DESIGN Neo-Classical Colonnaded Apartment Bldg.			WALL CONSTRUCTION brick		
				ROOF TYPE AND MATERIAL		
* DESCRIPTION OF LOCATION ast 109.75 feet of Lot 17, South 10 feet of Vest 27 feet of Lot 17, East 109.75 feet of Lot	unknown	19. ARCHITECT OR ENGINEER unknown		flat - membrane NO. OF BAYS		
8; Block 2, Munford & Francher's Addition.	20. CONTRACT	OR OR BUILDER		FRONT 3 SIDE 4		
1300-02 & 1304-06 Paseo are combined in one gal description. See Attached Map.	Walter M.	Walter M. Davis		WALL TREATMENT Flemish bond brick		
	21. ORIGINAL I	USE, IF APPARENT		PLAN SHAPE		
9. COORDINATES UTM	Apartmen	ts	<u> </u>	rectangular - short facade  CHANGES ADDITION()		
LONG	22. PRESENT U	SE	36.	(EXPLAIN IN ALTERED (X)		
10. SITE() STRUCTURE()	Apartmer	nts		NO. 42) MOVED ( )		
BUILDING (O OBJECT()  11. ON NATIONAL YES()	23. OWNERSHI	PUBLIC() PRIVATE(X)	-37.	CONDITION good		
REGISTER? NO()	24. OWNER'S NAME AND ADDRESS			EXTERIOR fair-good		
12 ISIT YES( ) ELIGIBLE NO( )		nes, L.P. c/o Pioneer Gr sas Ave. Topeka, KS 66		PRESERVATION YES() UNDERWAY? NO(X)		
13. PART OF ESTAB. YES() HIST. DISTRICT: NO (X)	25. OPEN TO PO	JBLIC YES() NO(X)	39.	ENDANGERED? YES(X) BY WHAT? NO() blighted area, lack of maintenance		
14. DISTRICT YES (X)	26. LOCAL CONTACT PERSON OR ORGANIZATION		ZATION 40.	VISIBLE FROM YES (X)		
POTENTIAL NO()	*Ross Freeman	*Ross Freeman, Pioneer Group, Inc.785/232-1122		PUBLIC ROAD NO()		
15. NAME OF ESTABLISHED DISTRICT	27. OTHER SURVEYS IN WHICH INCLUDED			41. DISTANCE FROM AND FRONTAGE ON ROAD		
	<u> </u>	·				
42. FURTHER DESCRIPTION OF IMPORTANT FEATURE The central bay of the east facade is a full-heigl with projecting cornices. The original wooden p safety codes. There are four glazed brick (whit corbelled to resemble quoins at the building cor 43. HISTORY AND SIGNIFICANCE	ht projecting por- orch railings wei e) pilasters at th ners. There is a	re replaced with metal in e east facade. The brick projecting wooden corn	1975 to meet like at the first floo- ice on the east a	ife- r is and BE PROVIDED		
This colonnaded apartment building is directly a blighted property along The Paseo Boulevard be elite apartment housing in the years 1901 throu A 1901 water permit identifies Walter M. Davis builder of 1300 and 1304 Paseo. Mr. Davis we Hotel at 1000 Paseo in 1912. This apartment I Hoye's Kansas City Blue Book and Club Directo together as The Missouri Apartments.	etween 9 <sup>th</sup> Street ugh 1913. See he as as owner of the as also owner of building was ider	and 14 <sup>th</sup> Street through historic context for the p property. Landmarks ( the Maryland Apartmen hitified as The Maine Apa	n the construction roposed district. Commission reconts at 930 Paseon artments on the	rds identify Walter Davis also as the in 1901 and the Alameda/Parkview 1901 water permit and in the 1905		
44. DESCRIPTION OF ENVIRONMENT AND OUTBUELD The primary facade faces The Paseo. The sec sidewalk on the east side. The north facade al occupied by an apartment building.	ondary facade or			t are vacant. The adjacent lot south is		
45. SOURCE OF INFORMATION Water Permit 18420-1901; See Bibliography, sources: 1, 4, 7, 9, 13, 23, 29, 31, & 32.			Brenda R. Spencer (785) 456-9857 47. ORGANIZATION			
RETURN THIS FORM WHEN COMPLETED TO: OFFICE OF HISTORIC PRESERVATION			for Jazz Hill Homes, L.P. c/o Pioneer Group, Inc.			
TP 4 COMMON A STATE OF THE STAT	D BOX:176 EFFERSON CTTY,	.MO 65102	49. DATE February 2000			
SEPARATE SHEET(S) TO THIS FORM	PHL 573-751-785		49. REVISION DATE(S)			

### 1300 PASEO - CONTINUATION SHEETS

### 42. FURTHER DESCRIPTION OF IMPORTANT FEATURES - Continued


north sides of the parapet wall. Ashlar stone window sills and flat arch lintels with keystones ornament the windows on the east and north facades. Ashlar sills are present on all other double-hung windows. The building was converted from six to twelve apartments in 1944 (Building Permit #15744A). The doors and windows were replaced and a fire escape was installed at the rear of the building in 1975. The interior was remodeled in 1975, but the original stairway with newels and railings and several door surrounds are extant.



## 1200 PASEO (The Circle Apts)

#13

Date unknown
Mrs. Sam Ray's Postcard Collection
Kansas City Library, Special Collections
Note: the New York Apartments have
since been demolished



#14 1200 PASEO 1975 Source: 1975 Drawings for HUD remodeling William Johnson, Architect

1200 PASEO Sub-basement

#12









#10 1200 PASEO 1/00 Interior stairway

#9 1200 PASEO 1/00 "Typical" apartment interior

1200 PASEO "Typical" interior corridor


1/00







#5 1200 PASEO 1/00 South (side) elevation from SE corner



#6 1200 PASEO 1/00 North (side) elevation from NW corner of building



1200 PASEO West (rear) elevation


1/00



#1 1200 PASEO 1/00 East (front) elevation



#2 1200 PASEO 1/00 Northeast elevation from NE corner of building





THE NEW ENGLAND APARTMENT HOUSE, KANSAS CITY, MO. EDWARDS & SUNDERLAND, ARCHITECTS.

#13 1906 1116 PASEO Source: Inland Architect and News Record, May, 1906

## MISSOURI HISTORIC PRESERVATION PROGRAM

ARCHITECTURAL/HISTORIC INVEN
------------------------------

RCHITECTURAL/HISTORIC INVI	SIVIORI I C	4. PRESENT LOCAL NAM				
2-COUNTY Jackson	Parkview Homes, The Cameron  5. OTHER NAME(S)  The Circle Apartments					
1-LOCATION OF NEGATIVES	·		······································			
4 SPECIFIC LEGAL LOCATION TOWNSHIP 49 RANGE 33 SECTION 4	16 THEMATIC	14 THEMATIC CATEGORY		28. NO, OF STORIES 4-1/2		
FCITY OR TOWN, STREET ADDRESS	17. DATE(S) OR PERIOD		·	29. BASEMENT YES (A NO ( ) full + partial sub-basement (south end)		
1200 The Paseo Boulevard	circa 190	_		30. FOUNDATION MATERIAL ashlar coursed stone-east/north		
CITY OR TOWN IF RURAL, VICINITY  Kansas City	is. STYLE OR I	DESION sical Colonnaded Apartm	nent Bldg.	3). WALL CONSTRUCTION brick		
DESCRIPTION OF LOCATION	19. ARCHITECT	FOR ENGINEER		32. ROOF TYPE AND MATERIAL flat - membrane		
Lots 11, 12 & 13, except that part in The Paseo; Block 2, East Dundee	unknown			33. NO. OF BAYS FRONT 4 SIDE 2		
See Attached Map	20. CONTRACT unknown	20. CONTRACTOR OR BUILDER unknown		34. WALL TREATMENT		
	21. ORIGINAL I	JSE, IF APPARENT	***********	running bond brick 35. PLAN SHAPE		
COORDINATES UTM	Apartmen	ts		rectangular - long facade 36. CHANGES ADDITION ( )		
LONG	22. PRESENT U	SE		(EXPLAIN IN ALTERED (X)		
O. SITE() STRUCTURE()	Apartmen	Apartments		NO. 42) MOVED ( )		
BUILDING (x) OBJECT ( )  1. ON NATIONAL YES ( )	23. OWNERSHI	PUBLIC() PRIVATE(X)		37. CONDITION INTERIOR fair - poor		
1. ON NATIONAL YES() REGISTER? NO()	24. OWNER'S NAME AND ADDRESS		EXTERIOR fair			
LEST YES()		nes, L.P.  c/o Pioneer Gr sas Ave. Topeka, KS 66		38. PRESERVATION YES() UNDERWAY7 NO(X)		
ELIGIBLE NO()	25. OPEN TO PU	JBLIC YES()		19. ENDANGERED? YES (X)		
J. Part of Estab. Yes ( ) Hist. District NO (X)	NO (x)			BY WHAT? NO() blighted area, lack of maintenance		
4. DISTRICT YES (0) POTENTIAL NO ( )	1	NTACT PERSON OR ORGAN , Pioneer Group, Inc.785/	40. VISIBLE FROM YES (X) PUBLIC ROAD NO()			
POTENTIAL NO()  5. NAME OF ESTABLISHED DISTRICT		VEYS IN WHICH INCLUDE		41. DISTANCE FROM AND FRONTAGE ON ROAD		
				PROFINGE OF KOAD		
42. FURTHER DESCRIPTION OF IMPORTANT FEATURE This apartment building is a unique crescent sh and one on the north facade. The porches wer wooden porch columns and railings were replace the first floor on the east facade and the substa	ape. There are t e modified in 19 ced with metal or	75 to meet life-safety con the east facade. The	odes. The omasonry col	riginal PHOTO MUST		
This colonnaded apartment building is directly a blighted property along The Paseo Boulevard be elite apartment housing in the years 1901 through	etween 9 <sup>th</sup> Street	and 14 <sup>th</sup> Street through	h the constr	uction of		
The Circle Apartments are first listed in the Citrand the Landmarks Commission card file puts trecognized buildings remaining in this area. It northeast corner of 12th and Paseo and demoli	he date of consti was frequently pi	ruction at 1907. The Coctured alongside the we	ircle Apartm ell known Ne	ent building is one of the most widely w York Apartments (located on the		
4. DESCRIPTION OF ENVIRONMENT AND OUTBUILD The primary facade faces The Paseo. The sec the building. The lots between this apartment	ondary facade or	n the north faces 12 <sup>th</sup> Si Street to the south are	treet. There vacant. The	e lot north of 12 <sup>th</sup> Street is vacant.		
S. SOURCE OF INFORMATION				da R. Spencer (785) 456-9857		
See Bibliography, sources: 1, 3, 4, 9, 13, 21,	23, 28, 29, 31, a	VI. OKCA		NIZATION		
LETURN THIS FORM WHEN COMPLETED TO: O	FFICE OF HISTO			for Jazz Hill Homes, L.P. c/o Pioneer Group, Inc.		
				February 2000		

JEFFERSON CTTY, MO 65102

PHL 573-751-7858

49. REVISION DATE(S)

IF ADDITIONAL SPACE IS NEEDED, ATTACH


SEPARATE SHEET(S) TO THIS FORM

### 1200 PASEO - CONTINUATION SHEET


### 42. FURTHER DESCRIPTION OF IMPORTANT FEATURES - Continued

facade is intact with the exception of replacement metal railings. Ashlar stone banding, cornices, quoins, window sills, window lintels and window enframement contribute to the architectural character of the east, south, and north facades. Fire escapes were installed at the rear of the building in 1975. The doors and windows were replaced in 1975. The interior was remodeled in 1975, but ceramic tile at the entrance and wooden stairs are extant.





1/00





#1 CONTEXT 1/00 10th & Paseo (NW corner) 930, 928 & 924 Paseo (L to R)



#2 CONTEXT 1/00 10th & Paseo (SW Corner) 1000 Paseo (foreground) 1401 E. 10th Street