
Columbia, Missouri 65201 STORI INVENTORY JA-AS-005-435 4. Present Name(s) 20-GBD-1 20-C CBD- N 14 Folger Coffee Company 2. County --Jackson 5. Other Name(s) 3 Location of Negatives K. C. CBD#7 Boss Manufacturing Company Building Landmarks Commission 6 Specific Location 16. Thematic Category 28. No. of Stories Architecture/Economics 29. Basement? Yes X ackson 700 May Street/701 Broadway 17. Date(s) or Period No I 1917 30. Foundation Material If Rural, Township & Vicinity 18. Style or Design Reinforced Concrete Kansas City, Missouri 64105 Commercial/Tapestry Brick 31. Wall Construction 8. Site Plan with North Arrow 19. Architect or Engineer Masonry and Rein. Conc N WEST J. C. Sunderland 32. Roof Type & Material 20. Contractor or Builder Flat: Tar & Gravel BROADWAY 33. No. of Bays Front 21. Original Use, if apparent Side Present Name(s) 34. Wall Treatment Industrial 22. Present Use Tapestry Br. over Br. Commercial/Industrial 35. Plan Shape Rectangular 23 Ownership Public 11 36. Changes Addition X: Private KI (Explain Altered 1 in #42) Moved i 24. Owner's Name & Address, if known J. A. Folger & Company, 37. Condition Interior P. O. Box Box 599, 9. Coordinates UTM Lat. Cincinnati, Ohio 45201 Excellent Exterior Long 25. Open to Yes K 38. Preservation Yes X Public? Restricted No II Underway? Site ! : Structure | No i Building K Object 11 26. Local Contact Person or Organization 39. Endangered? Yes By What? 11. On National YesXX Yes X No K Landmarks Commission Eligible? Register? No !! No 27. Other Surveys in Which Included Yes K 3. Part of Estab. Yes II District 40. Visible Irom Yes K Hist. Dist.? No K Potent'l? No: Public Road? (None) No 11 15. Name of Established District 41. Distance from and Frontage on Road 15' 8th Street Wholesale District 80' along Broadway 12. Further Description of Important Features The main facade faces West 7th Street. The main entrance is located along Broadway. A se-Boss condary recessed is located at the extreme east bay of the north bay. The fenestration consists of multi-light vent windows, outlined Photo Manufacturing by brick frames. The street facades are divided in to bays by engaged piers and spandrels. The parapet is stepped and topped by stone coping. Windows along the first story of the facade are one-over-one light double sash. No visible alterations, Grain Elevator addition. 13. History and Significance The building was erected in 1917, by Mrs. Emma Meyer for the Boss Manufacturing Company. The company was the largest cotton glove factory west of New York City. The building is a major commercial design by local architect J. C. Sunderland. 4. Description of Environment and Outbuildings The building is located in the Wholesale District in the Central Busniess District of Kansas City. To the south, east & west are other commercial & industrial buildings. To the north is a surface parking lot. 5 Sources of Information Building Permit No. 12195, Building Permits Office, 46. Prepared by 18th Fl. City Hall, 414 E. 12th Street, Kansas City, Mo. 64106 Ed Miszczuk 47. Organization K. C. Kansas City (Missouri) Star, April 8, 1917 Kansas City (Missouri) Star December 23, 1917 Landmarks Commission Western Contractor, Vol. 31 No. 850, April 11, 1917 p. 21 48. Date 49. Revision Date(s) Western Contractor, Vol. 31 No. 852 p.19, April 25, 1917 9/77

State Historical Survey and Planning Office, 909 University Avenue, Suite 215.



Landmarks Commission
Date 49 Revision Date(s)

48. Date 9/ 77



9/77

State Historical Survey and Planning Office, 909 University Avenue, Suite 215,



Office of Historic Preservation, P.O. Box 176, Jefferson City, Missouri 65101 HISTORIC INVENTORY JA-AS-005-438 4 Present Name(s) No 11-A M & G Auto Care 0126 2 County Jackson 3 Lucation of Negatives CBD# 32-20 Oner Garage Landmarks Commission 28 No of Stores 16 Themalic Calegory Jackson 6 Specific Location 29. Basement? 601 McGee No X. 17 Date(s) or Period (309 East 6th Street) 1940 30. Foundation Material H Rural, Township & Vicinity 18 Style or Design 7 City or Town 31. Wall Construction Kansas City, Missouri 19 Architect or Engineer concrete block 68 Site Plan with North Arrow 32. Roof Type & Material East 67 Street flat; tar/gravel [ 20 Contractor or Builder 33. No. of Bays Front Side 21. Original Use, if apparent DOE Present Name(s) garage; filling station 34 Wall Treatment concrete block 65 Present Use McGee 35. Plan Shape rectangular garage Public 11 Private XX 36 Changes Addition . 23 Ownership (Explain Attered i (309 m 842) Moved i 24 Owner's Name & Address. el known 37 Condition Interior East Cuprdinates Exterior pood Lung 25 Open to Yes 11 38 Preservation 6 Public? No II Underway? No iX Structure ! . Sile: Object 11 Building X 26 Local Contact Person or Organization Endangered? Yes II S By What? No IX Landmarks Commission Yes I I 11 On National Yes .. treet) Eliqible? No XI Register? No .X 27. Other Surveys in Which Included Yes. 14 District Yes : 13 Part of Estab Visible from Yes .X HIST DIST ? No 'Y Potent'1? No XI Public Road? No . : Distance from and 15 Name of Established District Frontage on Road 27 feet on E. 6th St. 42 Further Description of Important Features This simple structure features plate Other Names glass windows at the northwest corner. Garage entrances are located on the north and west facades. 43 MINIORY and Symmicance -- The original owner of this building was Anthony Totero, who ran the Oner Garage. The building is currently used as a wash-and-wax garage. 44 Description of Environment and Outbuildings The Intercity Freeway is to the north of this building. A commercial building is to the south. A vacant lot is to the east and to the west is a surfaced drive and work area. 45 Sources of Information 46. Prepared by Sherry Piland WP# 5064 47. Organization Kansas City Times, Aug. 29, 1980, p. 1 Landmarks Commission 8/29/8049 Revision Dele(s)





Office of Historic Preservation, P.O. Box 176. Jefferson City, Missouri 65101 HISTORIC INVENTORY JA-AS-005-439 4 Present Name(s) 11-C 0127 Superior Screw Products County Other Name's) Jackson Location of Negatives CBD #32-18 Elk Garage 16 Themalic Calegory 28 No of Stories Specific Location Jackson 030 29. Basement? 605 McGee (604 Oak) No : 17 Date(s) or Period 30. Foundation Material 1925 concrete 16 Style or Design H Rural, Township & Vicinity 7 City or Town 31. Wall Construction Re Kansas City, Missouri reinforced concrete 19 Architect or Engineer Site Plan with North Arrow PR 32. Roof Type & Material T John Marra bowstring; composition 20 Contractor or Builder 33. No. of Bays Patti-Moore Cons Front 21. Original Use, If apparent 605 McGee (604 34 Wall Treatment parking garage Jak 22 Present Use hrick 35. Plan Shape rectangular commercial 36 Changes Public 1 1 Addition 23 Ownership Altered : Private IJ (Explain m 842) Moved . 24. Owner's Name & Address, Other d known Condition Interior MTU Curdinales good Exterior Lat Yes M Preservation Lung 25 Open to Underway? No X. Public? Structure ! . Sale Object 11 Endangered? Yes II Local Contact Person or Organization Building X By What? No K. Landmarks Commission Yes X 1 On National Yes .. Eligible? No 11 27 Other Surveys in Which included Register? Yes X Visible from Yes X Part of Estab Yes 14 District Public Road? No . : No 'X Potent'l? No II MIST DIST ? Distance from and 5 Name of Established District Frontage on Road feet on McGee 2 Further Description of Important Features This building extends through the block, providing frontage on both Oak and McGee Streets. Street facade has a garage entrance at its north end. Both floors are fenestrated with rectangular multi-paned, windows. The stepped parapet wall has a stone coping. The McGee Street facade has garage entrances at each end. Multi-paned windows fenestrate the 2nd floor and a parapet identical to the Oak Street facade tops the building. The original owner of this building was Albert DeMayo, who also 13 History and Significance operated a drug store from the building. It was probably named the Elk Garage because of its close proximity to the Elk Club at the northwest corner of 7th and Grand. Description of Environment and Outbuildings Surface parking lots are located to the north and east of this building. Commercial buildings are located to the north and west. A small commercial building on the north abuts the mid-portion of this building. 46. Prepared by 5 Sources of Information WP #44807 Sherry Piland 47. Organization BP #14146 (1) Landmarks Commission


48. Date

1/29/81

49 Revision Dele(s)



State Historical Survey and Planning Office, 909 University Avenue, Suite 215,





ISTORIC INVENT JA-AS-005-441 I. No 4. Present Name(s) 28-D 709-11 McGee 28 0129 2. County 5. Other Name(s) Jackson Location of Negatives CBD # 12-17 Admiral Hotel Landmarks Commission 6 Specific Location 16. Thematic Category 28. No. of Stories 29. Basement? Jackson Yes ! 709-11 McGee 17. Date(s) or Period c. 1885; c. 1905 30. Foundation Material 7. City or Town . If Rural, Township & Vicinity 18. Style or Design rubble stone 4/ 69 31. Wall Construction Kansas City, Missouri B. Site Plan with North Arrow 19. Architect or Engineer masonry 32. Roof Type & Material 20. Contractor or Builder varied 33. No. of Bays Front 3 21. Original Use, if apparent Side 709-11 Present Name(s) 010 residential 34. Wall Treatment 22. Present Use brick 35. Plan Shape irregular vacant McGee 23 Ownership Addition : Public 1! 36. Changes Private XI (Explain Altered IX in #42) 24. Owner's Name & Address. Moved i if known 37. Condition Interior 9. Coordinates f at Exterior poor Long 25. Open to 38. Preservation Yes I i Yes : Public? No IXX Site ! : Underway? Structure | Building IX Object 11 26. Local Contact Person or Organization 39. Endangered? Yes IX By What? future 11. On National Yesli 12 Is It Yes : X Landmarks Commission No I : demolition and/or redevelopment Eligible? Register? No IX No :: 27. Other Surveys in Which Included 13. Part of Estab. Yes ! ! Yes IX 14. District 40. Visible from Yes !X Hist. Dist.? No IX Potent'1? No : Public Road? No 11 15. Name of Established District 41. Distance from and 44 ft. Frontage on Road on McGee 42. Further Description of Important Features A 3-story commercial building has been attached to the front of a residence. The truncated hip roof of the residence is covered with composition roofing. Double hung sash windows set in arched openings are visible in the residence. Asbetos siding covers the 1st floor of the commercial addition. A garage door indicated on this facade. The upper 2 floors each contain 3 sash windows with stone sills and lintels. 43. History and Significance A 3 story commercial addition was attached to the residence By 1917 it was known as the Admiral Hotel. 44. Description of Environment and Outbuildings Surface parking lots are located to the south and west of this building. To the north and east are small commercial buildings. 45 Sources of Information 46. Prepared by Sherry Piland WP # 31069 47. Organization Landmarks Commission 48. Date 49. Revision Date(s) 1/29/81

State Historical 'urvey and Planning Office, 909 University Avenue, Suite 215.

Columbia, Missouri 65201



49 Revision Dole(s)

48. Date

1/29/8

Kansas City Star, Oct. 19, 1930

Vansas City Star, Aug. 19, 1973

KC Journal Post, Aug. 18, 1929, p. 4C



Columbia, Missouri 65201 HISTORICANVENTORY JA-AS-005-443 4. Present Name(s) 1. No. 61-F Apcoa Parking Garage 2. County 5. Other Name(s) Jackson 3 Location of Negatives CBD# 19-6 Empire Garage Building 0131 Landmarks Commission 6 Specific Location 16. Thematic Category 28. No. of Stories 29. Basement? Yes IX Jackson 17 Date(s) or Period 904-10 McGee No I 1925 30. Foundation Material 7. City or Town . If Rural, Township & Vicinity 18. Style or Design 31. Wall Construction Kansas City, Missouri modified tapestry brick reinforced concrete B. Site Plan with North Arrow 19. Architect or Engineer 32. Roof Type & Material PR 20. Contractor or Builder flat; tar/gravel 33. No. of Bays B.L. Hoffman Company Front Side 21. Original Use, if apparent 02 Present Apcoa parking garage 34. Wall Treatment 22. Present Use brick 35. Plan Shape rectangular parking garage Parking Public !! 23 Ownership 36. Changes Addition :: Private XI (Explain Altered I in #421 Moved i 24. Owner's Name & Address, if known 37. Condition Ga Interior UTM 9. Coordinates fair Exterior Lat. Long 25. Open to Yes Ki 38. Preservation Yes i Public? No I Underway? No ix 10. Structure | Site ! : Building IX Object ! I 39. Endangered? Yes IX 26. Local Contact Person or Organization By What? future demolition and/or redevelopment No I : Yes :X 11. On National Yes I i 12 Is It Landmarks Commission Eligible? Register? No IX No !! 27. Other Surveys in Which Included Yes IX 3. Part of Estab. Yes ! ! 14 District 40. Visible from Yes !X No IX Potent'l? No : . Public Road? Hist. Dist.? No ! : 41. Distance from and 15. Name of Established District Frontage on Road 96 feet on McGee 12. Further Description of Important Features -- Garage entrance doors are located on olther the first floor. A stone string course runs above the first floor 90 windows. The second and third floors are fenestrated by groups of multi-paned, hinged windows. Another stone string course runs above Photo the third floor windows. Above this is a stepped parapet roof with Garage stone coping. Building 13. History and Significance One of several parking garages constructed in the downtown area in the 1920's. 14. Description of Environment and Outbuildings -- A vacant lot is located to the north of this building. Another parking facility is located to the south. Commercial buildings are located to the east and west. 5 Sources of Information 46. Prepared by Sherry Piland WP# 81007 47. Organization BP# 14282 Landmarks Commission Kansas City Journal, Dec. 20, 1925, p. 10 48. Date 49. Revision Date(s) Western Contractor, Jan. 14, 1925, p. 40 and May 27, 1925, p. 32 11/7/80

State Historical Survey and Planning Office, 909 University Avenue, Suite 215



| 1. No.61-G  | 4. Pre                  | seni Name(s)  | JA-AS-005-46                                | -                     |
|---|-------------------------|---|---|-----------------------|
|   |                         | leral Reserve Bank Addition and Garage                                    |   | 6 N                   |
| 2. County   |                         | her Name(s)   |   | 1-6                   |
| 3 Location of Negatives Landmarks Commis                            | CBD# 19-7               | Not entered   |   |                       |
| 6 Specific Location   | 3 1011                  | 16. Thematic Category   | 28. No. of Stories 4                        | -                     |
| 912 McGee   |                         |   | 29. Basement? Yes XX                        | 2. Co<br>Ja           |
|   |                         | 17. Date(s) or Period   | No 1 .                                      | Jacks                 |
|   |                         | 1966  | 30. Foundation Material                     | ckson                 |
| 7. City or Town If Rural, Township & Vicinity Kansas City, Missouri |                         | 18. Style or Design   | concrete 31. Wall Construction              | 2                     |
| 8. Site Plan with North Arrow                                       |                         | 19. Architect or Engineer   | - St. Wall Construction                     |                       |
|   |                         | Kivett and Myers  | 32. Roof Type & Material                    | 4. Present<br>Federal |
|   |                         | 20. Contractor or Builder   | flat: tar/gravel                            |                       |
|   |                         | 21. Original Use, if apparent   | 33. No. of Bays<br>Front 7 Side             |                       |
|   |                         | commercial  | 34. Wall Treatment                          | Pre                   |
|   |                         | 22. Present Use   | marble                                      | 'a l                  |
|   |                         | commercial  | 35. Plan Shape rectangular                  | 24                    |
| mº Gee  |                         | 23 Ownership Public XX Private  | 36. Changes Addition :: (Explain Altered !! | Reser                 |
| $\nearrow \longrightarrow$  |                         | 24. Owner's Name & Address,   | in #42) Moved                               | erve                  |
| _   |                         | if known  | 37. Condition                               |                       |
| 9. Coordinates UTM  |                         |   | Interior                                    | Bank                  |
| Lut.<br>Long.   |                         | 25. Open to Yes XX  | Exterior good                               |                       |
| 10. Site!: Structure!   |                         | 25. Open to Yes XX Public? No 11  | 38. Preservation Yes : Underway? No :X      | Addition              |
| Building Xi Object 11   |                         | 26. Local Contact Person or Organization                                  | 39. Endangered? Yes I                       | iti                   |
| 11. On National Yes Li  | 12 Is It Yes :          | Landmarks Commission  | By What? No IX                              | ion                   |
| Register? No IX   | Eligible? NoXX          | 27. Other Surveys in Which Included                                       |   | 20                    |
| 3. Part of Estab. Yes 11 14. District Yes XX Potent'1? No 1.        |                         |   | 40. Visible from Yes !X Public Road? No ! : | Ga                    |
| 15. Name of Established District                                    |                         |   | 41. Distance from and                       | Garag                 |
|   |                         |   | Frontage on Road                            | je                    |
|   |                         | be feede of this building is som  | 240 feet on McGee                           | _                     |
|   |                         | he facade of this building is com-<br>cal slit windows of dark gray solar |   | 5.                    |
|   |                         | the second floor level. The   |   | 1                     |
| building is connec  | cted to the Feder       | al Reserve Bank on the west by an   | Photo                                       | 2.                    |
|   |                         | are underground, servicing various  | 5   | i.ame(s               |
|   |                         | vels are above ground. Garage en-<br>de. The grill work of the first      |   | £.                    |
|   |                         | e with that of the bank structure.  |   |                       |
|   |                         | Building was razed to make way for  | this addition to the                        |                       |
| Federal Reserve   |                         | •   |   |                       |
|   |                         |   |   |                       |
|   |                         |   |   |                       |
|   |                         |   |   |                       |
| 4. Description of Environn  | ment and Outbuildings _ | -Commercial buildings are located t                                       | to the north, south, and                    |                       |
| east of this struc  | cture. To the we        | st is the Federal Reserve Bank.   |   |                       |
|   |                         |   |   |                       |
| 5 Sources of Information  |                         |   | 46 Prepared his                             |                       |
| WP# 15833   |                         |   | 46. Prepared by Sherry Piland               |                       |
|   | r, Jan. 9, 1966,        | p. 14F  | 47. Organization                            |                       |
| Kansas City Star  | r, June 26, 1966        |   | Landmarks Commission                        |                       |
| Kansas City Star  | r, Nov. 2, 1964         |   | 48. Date 49. Revision Date(s) 3/19/80       |                       |
|   |                         |   | 137 1 97 811                                |                       |



Office of Historic Preservation, P.O. Box 176, Jefferson City, Missouri 65101 HISTORIC INVENTORY JA-AS-005-445 4 Present Name(s) 78-G J. Boutross Company; Hagers Liquors & Gifts; Allright Auto 5 Other Name(s) Jackson 3 Lucation of Negatives CBD#15-19, entired Mutual Auto Parks, Inc. Landmarks Commission 15-18 16 Thematic Category 28 No of Stories 6 Specific Location 29. Basement? Yes !! Date(s) or Period 1000-08 McGee 1959 30. Foundation Material 18 Style or Design Il Rural, Township & Vicinity concrete 7 City or Town 31. Wall Construction Kansas City, Missouri 19 Architect or Engineer reinforced concrete & Site Plan with North Arrow 32. Roof Type & Material Sam Callahan (engineer) 20 Contractor or Builder flat; tar/gravel S. Patti Construction Co. 33. No. of Bays Front Side 21. Original Use, if apparent 10 th St. Present Name(s) 34. Wall Treatment commercial & parking garage 22 Present Use brick; concrete 35. Plan Shape rectangular commercial & parking garage 23 Ownership Public 1 36. Changes Addition mº Gee Private IX Altered : (Explain in #42) Moved i 24. Owner's Name & Address. if known Condition Interior UTM & Curidinales Exterior good 25. Open to Yes IX Preservation Yes . Public? No I I Underway? No i X Structure 1 . Sile Building X Object | | 26 Local Contact Person or Organization Endangered? Yes II By What? No IX 11 On National 12 Is II Yes ! ! Landmarks Commission Yes . Eligible? No IX Register? No . X 27. Other Surveys in Which Included 13 Part of Estab Yes District Yes IX Visible from Yes X Potent'l? No I I No 1 X Public Road? HIST DIST ? No : 41. Distance from and 15 Name of Established District Frontage on Road 145 ft. on McGee 42 Further Description of Important Features -- A simple retail store with large display windows occupies the corner site. To the south and west Other Names is a multilevel parking facility that was constructed at the same time. Entrances to the parking facility are from McGee and from Photo East 10th Street. The parking area contains space for 200 cars. 43 History and Significance -- In 1923 Harry A. Rubins and Clyde Storms leased a lot for their first parking facility. By 1959 this venture had grown to 22 downtown units that could handle 10,000 cars per day. Mutual Auto Parks, Inc. was part of Parking System, Inc. with Harry Rubins as President. 44 Description of Environment and Outbuildings -- Commercial buildings are located to the south, east, and west of this structure. The Federal Reserve parking facility is located to the

45 Sources of Information BP# 18918

north.

2 County

Lung

WP# 3421 Kansas City Star, Sept. 27, 1959

46. Prepared by Sherry Piland 47. Organization Landmarks Commission 48. Date 49 Revision Dala(s)

8/6/80

## J.H.BOUTROSS.CO. DRAPERIES CURTAINS LINENS BEDSPREADS



Columbia, Missouri 65201 JA-AS-005-447 4. Present Name(s) 1. No 79-B Gordon Rogers Company 2. County 5. Other Name(s) Jackson 1005-1007 McGer Street Buildir Location of Negatives CBD# 19-8 Landmarks Commission 6 Specific Location 16. Thematic Category 28. No. of Stories Jackson 29. Basement? Yes I County 17 Date(s) or Period No i 1005-07 McGee 1913 alt 30. Foundation Material 18 Style or Design 7. City or Town . If Rural, Township & Vicinity 31. Wall Construction Kansas City, Missouri B. Site Plan with North Arrow 19. Architect or Engineer reinforced concrete Shepard, Farrar, and Wiser 32. Roof Type & Material flat; tar/gravel F4 20. Contractor or Builder 33. No. of Bays Alex Kingman Front Side 1005-07 21. Original Use, if apparent 3 commercial O- A 34. Wall Treatment 22. Present Use brick 35. Plan Shape rectangular commercial Addition : : 23 Ownership Public 1 ! 36 Changes Private XI (Explain in #42) Moved 24. Owner's Name & Address. if known 37. Condition Interior 9. Coordinates good Exterior Lat. Long 25. Open to Yes Xi 38. Preservation Yes . Public? No 11 Underway? No iX Structure | 10. Site! Building IX Object ! I 39. Endangered? Yes IX 26. Local Contact Person or Organization By What? future No I : 11. On National 12 15 11 Yes : X Yes ! ! Landmarks Commission demolition and/or redevelopment Eligible? Register? No IX No :: 27. Other Surveys in Which Included Yes : X 13. Part of Estab. Yes ! ! District 40. Visible from Yes : X Potent'l? No: Hist. Dist.? No IX Public Road? 41. Distance from and 15. Name of Established District Frontage on Road 48 feet on McGee 42. Further Description of Important Features .- The terra cotta facing and projecting terra cotta cornice was removed in an attempt at modernization in 1959. Leon Maslan was the architect for this project, in which the fixed windows were added to the second floor and the facade was Photo covered with granite panels. 13. History and Significance -- Various commercial firms have occupied this building, originally constructed for K.C. businessman, Clarence E. Gould. 14. Description of Environment and Outbuildings -- Surface parking lots are located to the north and east of this building. A parking garage is located to the west and a commerical building to the south. 5 Sources of Information 46. Prepared by Sherry Piland WP# 5136 47. Organization BP# 10920 and #61761A Landmarks Commission Western Contractor, Dec. 18, 1912, p. 25 48. Date 49. Revision Date(s) 8/1/80

State Historical Survey and Planning Office, 909 University Avenue, Suite 215,



TORIC INVENTORY JA-AS-005-4418 4. Present Name(s) I. No 79-C Dibble Building - name 2. County 5. Other Name(s) Jackson Location of Negatives CBD# 19-9 Vogue Fabrics Landmarks Commission 16. Thematic Calegory 28. No. of Stories 6 Specific Location 030 29. Basement? Yes IX Jackson 17. Date(s) or Period No I 1009-13 McGee 30. Foundation Material 1917 reinforced concrete 7. City or Town . If Rural, Township & Vicinity 18. Style or Design 69 31. Wall Construction Kansas City, Missouri Tapestry Brick B. Site Plan with North Arrow 19. Architect or Engineer 32. Roof Type & Material S. E. Edwards roof; tar/gravel F+ 20. Contractor or Builder Martin Carroll Construction Co. 33. No. of Bays Front Side 21. Original Use, if apparent Present Namels commercial ORE ibble 34. Wall Treatment paca 22. Present Use brick AW 35. Plan Shaperectangular commercial Buildi 23 Ownership Public I ! 36. Changes Addition : Private XI (Explain Altered 1 ' in #421 Moved i 24. Owner's Name & Address, if known 37. Condition Interior UTM 9. Coordinates Exterior fair Lat Long 25. Open to Yes Xi Preservation Yes :: No :X Public? No II Underway? Structure I Site ! : Building IX Object ! I 26. Local Contact Person or Organization 39. Endangered? Yes IX By What? future No 1: Yes :X Landmarks Commission 11. On National 12 Is It Yes II demolition and/or redevelopment Eligible? Register? No IX No : ! 27. Other Surveys in Which Included 13 Part of Estab. Yes !! 14 District Yes IX 40. Visible from Yes ! X No IX Hist. Dist.? Potent'l? No: Public Road? No II 41. Distance from and 15. Name of Established District Frontage on Road 96 feet on McGee 42. Further Description of Important Features -- Brick piers, outlined in stone, divide the facade into 5 bays. Five stops are at street level where display windows are topped with vertical transom lights. Each bay of the top 3 floors contains a triple double hung sash window. Stone ornament forms a flush pediment above the 4th floor windows and a decorative treatment of the parapet wall. 43. History and Significance -- In 1916, veteran Kansas City physician Dr. LeRoy Dibble, deeded vacant land on McGee to Iowa's Grinnel College. His wife, Dr. Martha Dibble, was an 1867 graduate of the school. He had previously planned to leave his estate to Kansas City, but became disgusted with civic affairs and what he perceived as a "lack of public spirit." The gift of Grinnel was for the purpose of establishing free scholarships. Grinnel College erected the building the following year, naming it for the Doctors Dibble. Numerous commercial (continued on second sheet) 14. Description of Environment and Outbuildings -- Commercial buildings are located to the north, south, east and west of this structure 46. Prepared by 5 Sources of Information Sherry Piland BP# 12034 47. Organization Western Contractor, Jan. 24, 1917, p. 18 Landmarks Commission Kansas City Star, June 18, 1944 48. Date 49. Revision Date(s) Kansas City Times, Jan. 4, 1916 3/27/80

State Historical Survey and Planning Office, 909 University Avenue, Suite 215.

Columbia, Missouri 65201

HISTORIC INVENTORY--page 2
Dibble Building

43. firms have utilized the building. For many years it housed Dr. John Brock's optical plant. Later it was used by affiliated laboratories in the manufacturing of toilet preparations.



1/15/81

State Historica' Survey and Planning Office, 909 "siversity Avenue, Suite 215,



State Historical Survey and Planning Office, 909 University Avenue, Suite 215, Columbia, Missouri 65201 STORIC INVENTORY JA-AS-005-450 4. Present Name(s) I. No 79-D Trailways Bus Terminal 2. County 5/Other Name(s) 1 amo Jackson Burnap-Meyer Building; Methodist Publishing House; 3 Location of Negatives CBD# 19-10 Landmarks Commission #34-8 Continental Trailways 16. Thematic Category 28. No. of Stories 7+mezzanine 6 Specific Location 030 29. Basement? Yes IX 17. Date(s) or Period 1023 McGee No I 196 30. Foundation Material 1924-25 concrete . If Rural, Township & Vicinity Style or Design 7. City or Town 31. Wall Construction Kansas City, Missouri Art Deco reinforced concrete B. Site Plan with North Arrow 19. Architect or Engineer Frederick McIlvain 32. Roof Type & Material flat; tar & gravel 20. Contractor or Builder 33. No. of Bays Trailways Front 3 Side 6 21. Original Use, if apparent Present Namers 34. Wall Treatment commercial 22 Present Use make brick 30 AW 35. Plan Shape rectangular bus terminal Bus Public 11 36. Changes 23 Ownership Addition X Private XX (Explain Altered L in #421 Moved i 24. Owner's Name & Address, ermina if known 37. Condition Interior 9. Coordinates Exterior poop Lat. Long 25. Open to Yes XX Preservation Yes . Public? No 11 Underway? No iy Site ! : Structure I Building Ki Object ! ! 39. Endangered? 26. Local Contact Person or Organization Yes I No IX By What? Yes :X 11. On National Yes I i Landmarks Commission Eligible? No 1 Register? No IX! 27. Other Surveys in Which Included Yes X Yes :X 13. Part of Estab. Yes ! ! 14. District 40. Visible from Potent'1? Hist. Dist.? No NI No : Public Road? No I I Distance from and 15. Name of Established District Frontage on Road 50 feet on McGee 42. Further Description of Important Features -- The verticality of this building is stressed by the slightly projecting piers that break the facade thodist Publishing into three bays. This is further emphasized by the set back at the seventh floor level. The upper floors are trimmed with terra cotta isame(E, hoto ornamentation. The building contains 44,000 square feet. In 1979 a rectangular package express building was added to the south of the bus loading area (architect, Leon Maslan; builder, Drexel Nobel). Burnap-Meyer 43. History and Significance -- The Burnap Company was established in Kansas City in 1878 and became one of the largest stationery and office supply houses in the U.S. When the firm moved from 104 West 10th Street to this building in 1925 it became known as Burnap-Meyers, Inc. During the House; Second World War the building was used as a military canteen and dormitory, operated by the Salvation Army. In 1945 the building was acquired by the Methodist Publishing House. Building; continued on second sheet) 44. Description of Environment and Outbuildings A surface parking lot is located to the south and east Continental of this building. To the west is a parking garage. A commercial building is located to the north. 15 Sources of Information 46. Prepared by WP# 77731 Sherry Piland Trailways Kansas City Star, July 6, 1960 47. Organization Landmarks Commission Kansas City Star, March 2, 1964 48. Date 49. Revision Date(s) Kansas City Journal Post, Feb. 22, 1925 3/21/80 Kansas City Star, Feb. 9, 1926 BP #00825

- 43. In 1960 the building was purchased by Continental Central Realty. In 1961 the Union Bus Depot to the south of the building was razed and plans were announced for the construction of a 30 story building on the site. By 1964 it was decided that conditions did not warrant the construction of the new building. Instead the ground to the south became a surface parking lot and a bus loading area was attached to the south of the building. Leon Maslan served as architect for this project. The building won second place in the Business District League's awards for outstanding new downtown structures erected in 1925.
- 42. (cont'd) pilasters. The back portion of the building has a flat roof, interrupted by sawtooth projections containing ventilator windows.







Columbia, Missouri 65201 HISTORIC INVENTORY JA-AS-005-451 4. Present Name(s) 1. No. 95-F National Garage 2. County 5. Other Name(s) Jackson Location of Negatives CBD# 17-1 Parking Systems, Inc. Garage Landmarks Commission 28. No. of Stories 6. Specific Location 16. Thematic Category Jackson 030 29. Basement? Yes IX 17. Date(s) or Period No I 1100-10 McGee 1930 30. Foundation Material 18. Style or Design 7. City or Town . If Rural, Township & Vicinity concrete Art Deco Kansas City, Missouri 31. Wall Construction B. Site Plan with North Arrow 19. Architect or Engineer reinforced concrete East 11th St. PR 32. Roof Type & Material F+ George McIntyre 20. Contractor or Builder flat; tar and gravel S. Patti Construction Co. 33. No. of Bays Front Side 8 21. Original Use, if apparent Present Name(s) National Garage garage 34. Wall Treatment 22. Present Use brick; terra cotta 35. Plan Shape rectangular garage 36. Changes 23 Ownership Public 1! Addition : Private NI (Explain Altered I Moved i in #42) 24. Owner's Name & Address, if known 37. Condition Interior 9. Coordinates UTM Exterior fair Lal. Long 25. Open to Yes Ki Preservation Yes . Public? No II Underway? No iX Site ! : Structure | Building IXI Object 11 26. Local Contact Person or Organization 39. Endangered? Yes IX By What? future No I : Landmarks Commission 11. On National Yesli 12 Is It Yes :X demolition and/or redevelopment Eligible? No I ! Register? No IX 27. Other Surveys in Which Included Yes IX 13. Part of Estab. Yes !! 14. District 40. Visible from Yes !X Hist. Dist.? No IXI Potent'l? No : Public Road? No ! : 41. Distance from and 15. Name of Established District Frontage on Road 156 feet on McGee 42. Further Description of Important Features -- The garage entrance is centrally located on McGee Street. Unadorned brick piers separate the structure 30 into irregular bays and stress the verticality of the building. The building is fenestrated by one-over-one light, double hung sash win-Photo dows. In the northern three bays of the east facade these windows are in strips of three. Each bay along the remainder of the east facade and along the north facade features two separate windows. (continued on second sheet) 43. History and Significance -- The Kupper Hotel was razed to make room for this 1,000 car garage. upper floors and two floors below street level are utilized for parking. Store fronts along the first floor have been used for a variety of commercial concerns. This building was constructed as an auxiliary for the Professional Building, completed the previous year. buildings were connected by an underground passage. The building was constructed by (cont.) 44. Description of Environment and Outbuildings -- Commercial buildings surround this structure. 45 Sources of Information 46. Prepared by Kansas City Star, Sept. 27, 1959. BP# 15582 Sherry Piland Kansas City Star, Sept. 15, 1929, p. 1D. WP# 28285 47. Organization Landmarks Commission Kansas City Times, September 11, 1929 48. Date 49. Revision Date(s) Kansas City Journal Post, July 6, 1930, p. 4C 3/20/80 Kansas City Journal Post, June 29, 1930, p. 7A

State Historical Survey and Planning Office, 909 University Avenue, Suite 215,

HISTORIC INVENTORY - (cont.)
National Garage
Page 2

1/00-10 McG-ee-K.C.

- 42. Terra Cotta is used for decorative purposes. Along a string course between the 1st and 2nd floors, a repeating curvilinear curve is used. Lintels above the second floor windows feature a Sullivanesque motif. The parapet wall utilizes zig-zag and rectilinear ornamentation.
- 43. Parking Systems, Inc. and was considered a "daring venture" to undertake during the Depression years.



JA-AS-005-452 4. Present Name(s) 1. No 96-A Southwestern Bell Telephone Co. - Phone Center Store 2. County Jackson 3 Location of Negatives CBD # 19-11 not enleved Landmarks Commission 16. Thematic Category 28. No. of Stories 6 Specific Location Jacksor 29. Basement? Yes X 17. Date(s) or Period 1101 McGee No I 1973 - 7530. Foundation Material . If Rural, Township & Vicinity 18. Style or Design 7. City or Town 31. Wall Construction Kansas City, Missouri modified Brutalism B. Site Plan with North Arrow structural steel 19. Architect or Engineer Kivett and Myers 32. Roof Type & Material 20. Contractor or Builder flat; tar/gravel St. Thomas Construc. Co. 33. No. of Bays Southwestern Front Side 21. Original Use, if apparent 3 Present Namels commercial 34. Wall Treatment 22. Present Use brick 35. Plan Shape commercial 36. Changes 23 Ownership Public !! Addition Private XX E. 11th ST. (Explain Altered I in #42) Moved i Be 24. Owner's Name & Address. if known 37. Condition Interior 9. Coordinates UTM Tel good Exterior Lat. Long Yes XX 25. Open to Preservation ephone Yes Public? No II No ix Underway? Site ! : Structure 1 : Building IX Object ! I 26. Local Contact Person or Organization 39. Endangered? Yes By What? No IX: 11. On National Yes II 12 Is It Yes : Landmarks Commission Company Eligible? No IX Register? No IX 27. Other Surveys in Which Included Yes IX 13. Part of Estab. Yes II District Visible from Yes !X Hist. Dist.? No KI Potent'1? No : Public Road? No 11 41. Distance from and 15. Name of Established District Frontage on Road 132 feet on East 11th 42. Further Description of Important Features The glazed brick surface of this corner building is unadorned. The main entrance is at the north end of the west facade. Five beveled recessions stretch along the 1st floor of the west facade. Each opening contains a fixed window consisting of four panes. Other beveled, recessed windows fenestrate the upper floors at each end of this facade. Another grouping of beveled openings marks the north facade. These recessions are filled with metal panes. 43. History and Significance This building was constructed to house the telephone electronic switching system and to streamline downtown customer service. 14. Description of Environment and Outbuildings A bus terminal is located to the north of this building. Surface parking lots are to the south and east. Commercial buildings are also to the east. To the west is a parking garage 5 Sources of Information 46. Prepared by Kansas City Star, Feb. 6, 1972. WP# 146192 Sherry Piland 47. Organization BP# 90211 Landmarks Commission Kansas City Star, Dec. 12, 1973, p. 2B. 48. Date 49. Revision Date(s) 12/8/80

State Historical Survey and Planning Office, 909 University Avenue, Suite 215,

Columbia, Missouri 65201



|   | Survey and Planning Office, 909 Universit          | ty Avenue, Suite 215,<br>umbia, Missouri 65201              |  |
|---|--|---|--|
|   | NVENTORY   | JA-AS-005- 4:   |  |
| 1. No.<br>95-G  | 4. Present Name(s)                                 |   |  |
|   | Micro Cleaners                                     |   |  |
| R. County Jackson   | 5. Other Name(s)                                   |   |  |
| 3 Location of Negatives CBD #17-2<br>Landmarks Commission                 | 1114-1116 mcG                                      | se Street Building  |  |
| Specific Location   | 16. Thematic Category                              | 28. No. of Stories 3  |  |
| Specific Cocation   | To. Memanic Calegory                               | 29. Basement? Yes IXX                                       |  |
| 1114-16 McGee   | 17. Date(s) or Period 1904                         | 29. Basement? Yes IXX No I.  30. Foundation Material        |  |
| 7. City or Town If Aural, Township &                                      |  |   |  |
| Kansas City, Missouri  B. Site Plan with North Arrow                      | 19. Architect or Engineer                          | 31. Wall Construction SY                                    |  |
| Site Plan with North Arrow  | Louis Curtiss                                      | 32. Roof Type & Material                                    |  |
|   | 20. Contractor or Builder                          | flat; tar & gravel  |  |
|   |  | 33. No. of Bays   |  |
|   | 21. Original Use, if apparent                      | Front 7 Side  |  |
|   | commercial ODE                                     | 34. Wall Treatment  |  |
| 2   | 22. Present Use                                    | brick: glass 30   |  |
|   | Commercial   | 35. Plan Shape rectangular                                  |  |
| N   | 23 Ownership Public I ! Private I X                | 36. Changes Addition : (Explain Altered XX) in #42) Moved : |  |
|   | 24. Owner's Name & Address,.                       |   |  |
|   |  | 37. Condition Interior                                      |  |
| ). Coordinates UTM  |  | Exterior fair   |  |
| Long.   | 25. Open to Yes IX                                 | 38. Preservation Yes  |  |
| 0. Site!; Stru  | cture 1 : Public? No 11                            | Underway? No X  |  |
|   | bject !   26. Local Contact Person or Organization | 39. Endangered? Yes X                                       |  |
| 1. On National Yes I 12 Is It   | Yes X Landmarks Commission                         | By What? future No 1:                                       |  |
| Register? No X! Eligible?   | No i! 27. Other Surveys in Which Included          | demolition and/or redevelopment                             |  |
| 3. Part of Estab. Yes   1   14. District   Hist. Dist.? No XI   Potent'l? | Yes IX   | 40. Visible from Yes !X: Public Road? No 11                 |  |
| 5. Name of Established District   |  | 41. Distance from and                                       |  |
|   |  | Frontage on Road  |  |
| <u> </u>  |  | 38 feet on McGee  |  |
|   | ures The two store fronts on the 1st floor         | Blkv.   |  |
|   | e enameled brick forms the narrow side             | 30  |  |
| walls and cornice of the  | building. The second and third floors              |   |  |
| consist of glass curtain  | walls, fenestrated by rows of 7 windows.           | Photo   |  |
|   |  |   |  |
|   |  |   |  |
|   |  |   |  |
|   | ilding was owned by the architect, Louis           |   |  |
| built another building t  | o the immediate south, where he lived an           | d had his office.   |  |
|   |  |   |  |
|   |  |   |  |
|   |  |   |  |
| 4. Description of Environment and Outbu                                   | oildings Commercial buildings are to the so        |   |  |
| structure. To the north is  | a parking garage, while a surface parking          | g lot is to the west.                                       |  |
|   |  |   |  |
|   |  |   |  |
| 5 Sources of Information  |  | 46. Prepared by   |  |
| WP #11998   |  | Sherry Piland   |  |
|   |  | 47. Organization  |  |
|   |  | Landmarks Commission  |  |
|   |  | 48. Date 49. Revision Date(s) 2/4/81                        |  |
|   |  | 14/4/01   |  |



State Historical Survey and Planning Office, 909 University Avenue, Suite 215, Columbia, Missouri 65201 ISTORIC INVENTO 4. Present Name(s) 1. No. 95-H Royal Blueprint Company 2. County 5. Other Name(s) Jackson 3. Location of Negatives Kansas City The Louis Curtiss Studio Building (89 153-4 Landmarks Commission 28. No. of Stories 16. Thematic Category 6. Specific Location 1118-1120 McGee Street Architecture/Engineering 29. Basement? Yes !X 17. Date(s) or Period No I 1908 - 1909 30. Foundation Material 18. Style or Design Twentieth poured concrete If Rural, Township & Vicinity 7. City or Town 31. Wall Construction concretie century commerical Kansas City, Missouri frame reinforced with 1 19. Architect or Engineer 8. Site Plan with North Arrow Louis S. Curtiss 32. Roof Type & Material flat/ tar and grave) 20. Contractor or Builder 33. No. of Bays Side Front 21. Original Use, if apparent Commercial/residential 34. Wall Treatment 22. Present Use masonry Commercial 35. Plan Shape rectangular Addition :: Altered iX 23. Ownership 36. Changes Public 1 Private XI (Explain in #42) MCGEE STREET Moved 1 24. Owner's Name & Address, if known Albert C. Weyersburg 37. Condition Interior boag Roland Laboratory Inc. UTM 9. Coordinates good Exterior 1118 McGee St. KC. Mo. Lal. Yes X Long. 25. Open to Preservation Yes I Public? Underway? No X restrictive Structure 1 10. Site ! ; Building X Object | | Yes X 39. Endangered? 26. Local Contact Person or Organization By What? No 1: Landmarks Commission Yes ! Yes X 12 Is !! 11. On National possible redevelopmen No I! Eligible? No !! 27. Other Surveys in Which Included Register? 40. Visible from Preliminary Inventory-KC. Yes !X District Yes ! 13. Part of Estab. Yes 11 Public Road? Hist. Dist.? NoXI Potent'1? Landmarks Commission, 41. Distance from and 10ft. 15. Name of Established District Historic Building Preservation Frontage on Road 46 ft. Analysis, Downtown Plan-Land Clearance for Redevelopment of 42. Further Description of Important Features The Louis Curtiss Studio Building is three story, plus full basement, concrete frame, rectangular in plan. The bearing walls on the south, west and north are constructed of concrete frame reinforced with brick and concrete Photo block masonry. The east window wall, the primary facade, is an early, glass curtain wall. The first and second story and the second and third stories are horizontally divided by spandrels ornamented with bands of red and cr am tiles in a 43. History and Significance The Louis Curtiss Studio Building is significant as an early examples. of reinforced concrete and glass curtain wall architecture in the U.S. It is also noteworthy for its partially intact early modern interior design. The street facade stairhall and Curtiss' former office survive with a high degree of original integrity 44. Description of Environment and Outbuildings The building is in a predominantly commercial area. To the south is the Trader's National Bank parking garage. 46. Prepared by 45. Sources of Information Linda F. Becker National Register Form Prepared February 11, 1972 47. Organization Kansas City WP #38403 Landmarks Commission BP #9071 48. Date 49. Revision Date(s) 10-24-79 11/76



47. Organization

48. Date

2/6/81

Landmarks Commission

49. Revision Date(s)

WP #107674

BP #68934

KC Star, Oct. 6, 1957, p. 8D.



11/12/80

Office of Historic Preservation, P.O. Box 176, Jefferson City, Missouri 65101 HISTORIC INVENTORY

| 1 No 4 Pre                                       | sent Namo(s)                            |                              |         |
|--|---|------------------------------|---------|
| 112-J  | 0-18 McGee (219-25 East 12th Stree      | 0138                         | 112     |
| Jackson 5 Oir                                    | er Name(s)                              | at) U1-                      | 7       |
| 3 Location of Negatives CBD# 26-18               | Daltimona Shint Company                 |                              |         |
| Landmarks Commission                             | Baltimore Shirt Company                 |                              |         |
| 6 Specific Location                              | 16 Themalic Calegory                    | 28 No of Stories 2           | N       |
|  |   | 29. Basement? Yes XX         | 40      |
| 1200 - 18 McGee and                              | 17 Date(s) or Period                    | No                           | Jackson |
| 219-25 E. 12th Street                            | 1922                                    | 30. Foundation Material      | ks      |
| 7 City or Town If Rural, Township & Vicinity     | 18 Style or Design                      |                              | on      |
| Kansas City, Missouri                            | Tapestry Brick 60 69                    | 31. Wall Construction PC     |         |
| 8 Site Plan with North Arrow                     | 19. Architect or Engineer               | reinforced concrete          |         |
| Sile Files with Horizon                          | McKecknie & Trask                       | 32. Roof Type & Material     |         |
| $\wedge$   | 20 Contractor or Builder                | flat; tar/gravel             |         |
|  | Mosby-Goodrich Const. Co.               | 33. No. of Bays              |         |
| in in  | 21. Original Use, if apparent           | Front 5 Side 3               | - P     |
|  | commercial ODE                          | 34. Wall Treatment           | 20      |
| 2  | 22 Present Use                          | brick 30                     | 1200-   |
| 2757   | commercial                              | 35. Plan Shape rectangular   | 18 ×    |
| <b>√</b>   | 23 Ownership Public I 1                 | 36. Changes Addition         |         |
|  | Private IX                              | (Explain Altered XX)         | McG.    |
| mcGee_   | 24. Owner's Name & Address,             | in #42) Moved i              | O       |
| III GEE  | if known                                | 37 Condition                 | 0       |
| 9 Coordinates UTM                                |   | Interior                     | 8       |
| Lat  |   | Exterior fair                | 219     |
| Lung   | 25 Open to Yes 1)                       | 38. Preservation Yes         | 1       |
| 10 Site: Structure (                             | Public? No I I                          | Underway? No X               | 25      |
| Building X Object 11                             | 26 Local Contact Person or Organization | 39. Endangered? Yes          | [T]     |
| 11 On National Yes . 12 Is II Yes IX             | Landmarks Commission                    | By What? No X                |         |
| Register? No . X Eligible? No i i                | 27. Other Surveys in Which included     |                              | 12      |
| Hist Dist ? No x Potent'!? No 1                  |   | 40 Visible from Yes X        | th      |
| ^1   |   | Public Road? No ::           | St      |
| 15 Name of Established District                  |   | Frontage on Road             | *       |
|  |   | 132 feet on McGee            |         |
| 42 Euribar Danasialum of Important Englished     |   | 132. Teet on Micdee          | -       |
| 42 Further Description of Important Features The | 1st floor of this corner building       | other.                       | 5       |
| has undergone various alterations                | . The entrance to the 2nd floor i       | s 62 39                      | 3       |
| located on the McGee Street facad                | e. A simple terra cotta string co       | ourse runs                   | =       |
| below the 2nd floor windows. Rai                 | sed soldier courses of brick form       | panels Photo                 | Name(s) |
| around the double hung, sash wind                | ows with transoms. Cross-shaped t       | cerra cotta                  | 2       |
| decoration marks each bay. A sim                 | ple terra cotta band course and co      | pping                        | 5       |
|  | ate the building. The south and w       |                              |         |
| 43 Harris and Suppliered With Stucco.            |   |                              |         |
| This building                                    | was originally owned by J. North M      | Mehorney, Vice-President     |         |
| of the Mehorney-North Furniture                  | Company. It was leased to the Ba        | altimore Shirt Company.      |         |
| Various tenants have occupied t                  | he building over the years.             |                              |         |
|  |   |                              |         |
|  |   |                              |         |
| 44 Description of Environment and Outbuildings   | Surface parking lots are located t      | to the west and south        |         |
| of this building To the north                    | is a bank parking facility. The H       | Kansas City Public           |         |
| Library is to the east.                          | is a sam parking facility. The f        | tansas city rabite           |         |
| biblary is to the east.                          |   |                              |         |
| 45 Seurces at Information                        | <del></del>                             | AS General                   |         |
| 45 Sources of Information BP # 12984             | 46. Prepared by                         |                              |         |
| WP#'s 3025, 3029, 3030                           |   | Sherry Piland                |         |
| Western Contractor, Nov. 23, 192                 | 47. Organization Landmarks Commission   |                              |         |
|  | CAMPAN TOWNSHIP AND AND ADDRESS.        | 48. Date 49 Revision Date(s) |         |
|  |   | 1 PER   42 UEA1210U PA16(2)  |         |



Office of Historic Preservation, P.O. Box 176, Jefferson City, Missouri 65101 HISTORIC INVENTORY JA-AS-005-457 4 Present Name(s) 0139 112-K Gepford, Sears, Hughes, Matula of Counsel Lewis E. Pierce 2 County 5 Other Name(s) Jackson LaVeine Building 3 Lucation of Negatives CBD# 26-17 222 McGee Street Bulding Landmarks Commission 28 No of Stories 16 Themalic Category Specific Location 29. Basement? Jackson 17 Date(s) or Period 1222 McGee c. 1906 30. Foundation Material caused rubble 4 18 Style or Design 7 City or Town Il Rural, Township & Vicinity 31. Wall Construction Kansas City, Missouri masonry UD 19. Architect or Engineer & Site Plan with North Arrow 32. Roof Type & Material 20 Contractor or Builder flat; tar/gravel 33. No. of Bays Front Side 21. Original Use, if apparent PAC Present Namel 00 34. Wall Treatment 22 Present Use brick 35. Plan Shape rectangular commercial 23 Ownership Public 11 36. Changes Addition X Private XX (Explain Altered i I Dawold In 8421 24. Owner's Name & Address. if known Condition Interior Cuordinales UTM Exterior fair 25. Open to YesXX 38. Preservation Yes . Public? Underway? No X Structure I. Sile Building X Object 11 Endangered? 26 Local Contact Person or Organization Yes II By What? No IX YesXX Landmarks Commission 11 On National Yes .. 12 Is II Register Eliqible? No II No X 27. Other Surveys in Which included YesXX Visible from Part of Estab Yes : District Yes X Potent'l? Noti Public Road? No X HISI DIST ? No . Distance from and 15 Name of Established District Frontage on Road 25 feet on McGee 42 Further Description of Important Features The windowless north and south walls have been covered with stucco, except for a portion of the rear Other Namels south wall. The main (east) facade is faced with brick. Stone is used for coping across the roof line, banding along the corners, Photo and for cornerstones at each front corner. A large plate glass window fenestrates the facade, with the entrance off center to the south. 43 History and Significance The La Veine family had a residence on this property as early as 1881. It was probably replaced by this commercial building around 1906. A 50 foot rear extension was added in 1921 (architect, J. C. Sunderland). Various commercial firms have used this structure. 44 Description of Environment and Outbuildings -- The Kansas City Public Library is located to the east of this building. To the north, south, and west are surface parking lots.

> 46. Prepared by Sherry Piland

47. Organization

9/24/80

Landmarks Commission 48. Date 49 Revision Date(s)

Lung

45 Sources of, Information

WP# 2003, BP# 73406




Office of Historic Preservation, P.O. Box 176, Jefferson City, Missouri 65101 JA-AS-005-458 HISTORIC INVENTORY 4 Present Name(8) 1 No 128-B Trailways Garage 2 County 5 Other Name(s) other-Missoun Pacific Jackson 3 Lucation of Negatives CBD# 26-16 Regent Garage Landmarks Commission 28. No of Stories 16 Thematic Category 6 Specific Location 29. Basement? Ves I KSOI 17 Date(s) or Period No 1313-31 McGee alt 1995 30. Foundation Material 1926 concrete 18 Style or Design Il Rural, Township & Vicinity City or Town 69 31. Wall Construction Kansas City, Missouri 19. Architect or Engineer steel frame 8 Site Plan with North Arrow 32. Roof Type & Material William R. Boyard 20 Contractor or Builder varied GB Swenson Construction Co. 33. No. of Bays Side 21. Original Use, If apparent 2000 34. Wall Treatment DR parking garage (D) brick 22 Present Use ODE Nen 35. Plan Shape rectangular garage Public 1 36. Changes Addition . 23 Ownership Attered XX Private XX (Explain In 8421 Moved i 24 Owner's Name & Address. MGGeo if known 37. Condition Interior UTM & Coordinates good Exterior Yes :X 38. Preservation Lung 25. Open to Yes 11 Underway? Public? No IXX Structure ! . Sile: Endangered? Yes II Building X' Object 1 i 26 Local Contact Person or Organization By What? No 1X Landmarks Commission Yes XX 12 Is II Yes .. 11 On National Eligible? No 11 27. Other Surveys in Which Included No .X Register? Visible from Yes . X District Yes XX 13 Part of Estab Public Road? No . Potent'l? No I HIST DIST ? No X Distance from and 15 Name of Established District Frontage on Road 248 feet on McGee 42 Further Description of Important Features The central portion of this long building is recessed beneath a tile shed roof. A brick parapet wall projects behind this. Two garage entrance doors are located within this recession. garage door is located on the south wall of the building. Flanking this central recession are store fronts with tile gable roofs with dormers. gable area is of stucco. Most of the glass store fronts have been boarded up. The store fronts on the north end of the building are separated by brick 43 History and Supericance This building was originally constructed as a parking garage, with severa store fronts along the facade housing commercial firms. In 1945 the building was remodeled to serve as the Missouri Pacific Trailways Garage. The Patti Construction firm handled the remodeling. 44 Description of Environment and Outbuildings Surface parking lots are located to the north, east, south of this building. Commercial buildings are to the west and to the east. 45 Sources of Information 46. Prepared by Sherry Piland WP# 81596 47. Organization BP# 14794; 16904A Landmarks Commission 48. Dale 49 Revision Date(s) Western Contractor, Sept. 22, 1926, p. 40.

oc 1926, p. 4D.

1/13/81

HISTORIC INVENTORY
Trailways Garage
Page 2 13.3 3 New L.C.

42. (cont'd) pilasters. The back portion of the building has a flat roof, interrupted by sawtooth projections containing ventilator windows.



HISTORIC INVENTORY JA-AS-005-4 Present Name(s) N127-S Temperature Engineering Corporation County 5 Other Name(s) Jackson Conroy Building; Bour Coffee Company 3 Location of Negatives CBD# 10-9 & Landmarks Commission 16 Themalic Calegory 28 No of Stories 6 Specific Location 29. Basement? Yes ! 17 Date(s) or Period No : 1332-38 McGee 30. Foundation Material 1907 (1950's, additions) 18 Style or Design Il Rural, Township & Vicinity 7 Cily or Town 31. Wall Construction Kansas City, Missouri masonry wo Site Plan with North Arrow 19. Architect or Engineer 32. Roof Type & Material flat; tar/gravel 20 Contractor or Builder 33. No. of Bays Viron Front 21. Original Use, If apparent Present 02 A 34 Wall Treatment commercial 1.1 22 Present Use brick 35. Plan Shape Corporation Namels commercial irregular Public 11 36 Changes 23 Ownership Addition Mª Geo Private IX (Explain Attered m #42) DavoM 24 Owner's Name & Address, of known 37 Condition Interior UTM Condinates Exterior poop Lat Lung Yes MX 38. Preservation 25 Open to Yes . Mo II Underway? No X Public? Structure I Site Object I i 39 Endangered? Yes II Building 26 Local Contact Person or Organization By What? No X Yes i i 12 Is II 11 On National Landmarks Commission Yes Eligible? No IX Register? 27. Other Surveys in Which Included Yes 1% 40 Visible from 14 District 13 Part of Estab Yes Yes X Potent'l? No I I Public Road? No 'V No . HIST DIST ? Distance from and 15 Name of Established District approx Frontage on Road 125 feet on McGee 42 Further Description of important Features The three story building in the center Conroy Onroy Building of this complex has been altered. The display windows of the 1st floor have been filled in and a projecting metal cornice removed. the south is a one story brick addition, with frontage on McGee and East 14th Street. To the north is a loading dock that connects the 3 story building to another one story brick addition. 43 History and Significance The 3-story building was erected c. 1907 and occupied first by the Bour Coffee Company and later by other coffee companies. In the 1950's various alterations were undertaken by the Temperature Engineering Company. 44 Description of Environment and Outbuildings Commercial buildings are to the north, east, and west of this complex. Surface parking lots are also to the west and south. 46. Prepared by 45 Sources of Information Sherry Piland WP# 44449 47. Organization BP #'s 54668; 37438A; 42868 Landmarks Commission 48. Date 49 Revision Dale(s)

Office of Historic Preservation, P.O. Box 176, Jefferson City, Missouri 65101





Office of Historic Preservation, P.O. Box 176, Jefferson City, Missouri 65101 HISTORIC INVENTORY JA-AS-005-460 4 Present Name(s) 1 No 142-A Mobil Downtown Auto Service 2 County 5 Other Name(s) Jackson 3 Lucation of Negatives CBD# 26-15 Downtown Service Station Landmarks Commission 16 Themalic Calegory 28 No of Stories 6 Specific Location 29. Bascinent? Yes ! ! lackso 1401 McGee No X 17 Date(s) or Period 1955 30. Foundation Material 18 Style or Design If Rural, Township & Vicinity 7 City or Town 31. Wall Construction Kansas City, Missouri 19. Architect or Engineer concrete block & Site Plan with North Arrow Harold E. Biggs, engineer 32. Roof Type & Material 20 Contractor or Builder flat: tar/gravel
33. No. of Bays . Present Name(s) Front 3 Side 1401 21. Original Use, if apparent 34. Wall Treatment filling station metal panels 22 Present Use 35. Pian Shape rectangular filling station 23 Ownership Public 11 36. Changes Addition . Private XX M'Gec (Explain Attered i in #42) Moved i 24. Owner's Name & Address. if known Condition Interior Coordinates UTM Exterior good Lal Lung 25 Open to Yes XX Preservation Yes . Public? Underway? No iX Structure 1 . Sile Building X' Object 11 26. Local Contact Person or Organization 39 Endangered? Yes II By What? No IX Landmarks Commission 11 On National 15 11 Yes II Yes No X Eligible? NoXX 27. Other Surveys in Which Included Register? Yes XX 13 Part of Estab District Visible from Yes .X Yes : Potent'l? Public Road? HIST DIST ? No X No . 41. Distance from and 15 Name of Established District Frontage on Road 30 feet on McGee 42 Further Description of important Features The main facade faces north and consists of two garage entrances and an office area. The office Other Name(s) area features large plate glass windows. The building is sheathed with metal panels. 43 HISTORY and Significance -- This is one of the few service stations that ring the downtown area. The original owner was Sam Benati. 44 Description of Environment and Outbuildings Surface parking lots are located to the north, east, and west of this building. A commercial building is to the south. 45 Sources of Information 46. Prepared by WP# 2609 Sherry Piland BP# 18358 47. Organization

Landmarks Commission
48. Date 49 Revision Date(s)

11/12/80



Office of Historic Preservation, P.O. Box 176, Jefferson City, Missouri 65101 HISTORIC INVENTORY JA-AS-005-461 4 Present Name(s) 1 No 142-B 1409 McGee (Stanco Enterprises) 0142 2 County Jackson 5 Other Name(s) 3 Lucation of Negatives CBD# 26-14 Shore & Arnold Auto Repairs Landmarks Commission 16 Themalic Calegory 28 No of Stories 6 Specific Location 29. Basement? Yes XI 17 Date(s) or Period No : 1409 McGee 30. Foundation Material concrete Il Rural, Township & Vicinity 18 Style or Design 7 City or Town 31. Wall Construction Kansas City, Missouri 19. Architect or Engineer H Site Plan with North Arrow A.H. Buckley 32. Roof Type & Material 20 Contractor or Builder bowstring Edelman-Fleming Const. Co. 33. No. of Bays Front 3 Side 21. Original Use, if apparent parking garage 0-34. Wall Treatment 22 Present Use brick 35. Plan Shape rectangular commercial 23 Ownership Public 11 36 Changes Addition Attered X Mº Geo Private IX (Explain in #421 Moved 24 Owner's Name & Address if known Condition Interior UTM Coordinates Exterior dood Lat Land 25. Open to Yes II 38. Preservation Public? No II Underway? No X Sile Structure ! . Object 11 Building X . Yes I 26 Local Contact Person or Organization Endangered? By What? 11 On National Is II Yes IX Landmarks Commission Yes .. Eligible? No II Register? No X 27. Other Surveys in Which Included 13 Part of Estab District Yes IX Yes . Visible from Yes X Potent'l? No I Public Road? HIST DIST ? No . 41. Distance from and 15 Name of Established District Frontage on Road 50 feet on McGee 42 Further Description of Important Features -- Brick piers, With brick laid in a Other herringbone pattern, mark each end of the facade. A garage door is Other Name(s) centrally located, flanked on each side by customer entrance doors. A shaped parapet roof line is trimmed with stone. The original large plate glass windows have been altered, reduced in size, and the opaque glass transoms replaced with board. 43 History and Significance -- This building has been used as a parking garage and as an automobile repair shop. The most recent use of the building has been for storage for the Constable-Hodgins Printing and Lithographing Company. 44 Description of Environment and Outbuildings -- A service station is to the north of this building and a business college to the south. To the east and west are surface parking lots. 45 Sources of Information 46. Prepared by Sherry Piland WP# 4426 47. Organization

Landmarks Commission

49 Revision Date(s)

48. Date

8/6/80

BP# 12052



iversity Avenue, Suite 215,



Office of Historic Preservation, P.O. Box 176, Jefferson City, Missouri 65101 HISTORIC INVENTORY JA-AS-005-463 4 Present Name(s) 142-C Kansas City Business College 2 County Jackson not enteres Location of Negatives CBD# 26-13 Landmarks Commission 16 Thematic Category 28 No of Stories Specific Location 29. Basement? 1415 McGee No : . 17 Date(s) or Period 1966 30. Foundation Material 18 Style or Design If Aural, Township & Vicinity 7 City or Town 31. Wall Construction Kansas City, Missouri concrete block 19. Architect or Engineer M Site Plan with North Arrow 32. Roof Type & Material Robert L. Riley 20 Contractor or Builder flat; tar/gravel Howard Baltis & Son 33. No. of Bays Front Side 21. Original Use, if apparent school 34. Wall Treatment N 22 Present Use brick 35. Plan Shape rectangular school 3 36. Changes 23 Ownership Public 11 Addition Private 1) (Explain Altered : In 842) Moved i 24. Owner's Name & Address. if known 37 Condition Interior UTM Coordinates good Exterior Lat Lung 25 Open to Yes Ki Preservation Public? No II Underway? No X Structure ! . Sile Object 11 Building X 26 Local Contact Person or Organization Endangered? Yes !! By What? No K Landmarks Commission Yes II 11 On National 12 Is II Yes . Eligible? No IX No . X Register? 27 Other Surveys in Which included District Yes X 13 Part of Estab Yes Visible from Yes X No X Potent'1? Noli Public Road? HISI DIST ? No . 41. Distance from and 15 Name of Established District Frontage on Road 49 feet on McGee 42 Further Description of Important Features The entrance, on the west facade, was remodeled in 1980. The entrance is now slightly recessed. Metal Other Name(s) panels, in a grid pattern, are above the entrance. The walls of the building are a light colored brick. Panels of darker brick Photo below the 1st & 2nd story windows are used as an accent. The windows have fixed upper panes, and smaller hinged bottom panes. 43 History and Significance -- The Kansas City Business College was founded in 1896 by C.T. Smith. The School was located at several sites before building this structure. This building was designed to handle 500 students in the 2-year program. In 1970 the school was purchased by CBS-Holt, Inc., a wholly owned subsidiary of the Columbia Broadcasting System. In 1971 the first floor was remodeled to accommodate a new para-medical division of the school. 44 Description of Environment and Outbuildings Vacant land and an interstate connector are to the south of this building. To the north and west are commercial buildings. A surface parking lot is to the east. 45 Sources of Information 46. Prepared by BP #52300 Sherry Piland WP# 18616 47. Organization Kansas City Star, July 15, 1956

Kansas City Star, Jan. 3, 1965

Kansas City Star, Jan. 9, 1966

Kansas City Star. Mar. 7. 1971

Landmarks Commission

49 Revision Date(s)

48. Date

1/19/81



iversity Avenue, Suite 215,

2/25/80

State Historica 'urvey and Planning Office, 909



HISTORIC INVENTORY JA-AS-005-465 4 Present Namo(s) No 28-E 710 Oak 2 County 5 Other Name(s) Jackson 3 Lucation of Negatives CBD# 30-10 Ball Grinding Company name Landmarks Commission 16 Themalic Calegory 28 No of Stories 6 Specific Location 29. Basement? Yes I 710 Oak 17 Date(s) or Period No 1918 30. Foundation Material 18 Style or Design Il Rural, Township & Vicinity 7 City or Town 31. Wall Construction Kansas City, Missouri 19 Architect or Engineer Site Plan with North Arrow Masonry 32. Roof Type & Material PR 20 Contractor or Builder flat; tar/gravel + 33. No. of Bays Front 21. Original Use, if apparent Present Name(s) commercial ADE 34 Wall Treatment 22 Present Use brick 35. Plan Shape rectangular auto parking 36. Changes 23 Ownership Public 11 Addition . Attered IX Private XX (Explain m #42) Moved i 24 Owner's Name & Address, if known 37 Condition Interior UTM Currdinales Exterior fair Lung 25 Open to Yes 11 38. Preservation Yes . Public? Novit Underway? No iX Structure ! . 10 Sile Building X' Object 11 26 Local Contact Person or Organization 39 Endangered? Yes II By What? No IX Yes II Landmarks Commission 11 On National Yes .. 12 15 11 Register? No X Eligible? No XX 27. Other Surveys in Which Included Yes XX 14 District 40 Visible from 13 Part of Estab Yes Yes .X Potent'l? No Ti Public Road? HIST DIST ? No X No . : Distance from and 15 Name of Established District Frontage on Road 59 feet on Oak 42 Further Description of Important Features -- The windows of this building have Itales, been enclosed. Centrally located are an entrance door and a garage Other Name(s) door. Cut stone forms a string course and coping along the roof line Cut stone is also used to form three decorative accents below the roof line. 43 HISTORY and Significance -- The original owner of this building was John I. Glover. It was leased to the Ball Grinding Company. 44 Description of Environment and Outbuildings Commercial buildings are located to the north and west of this structure. To the south and east are surface parking lots. 45 Sources of Information 46. Prepared by Sherry Piland WP# 2327 47. Organization Landmarks Commission 8/25/80 49 Revision Date(s)

Office of Historic Preservation, P.O. Box 176, Jefferson City, Missouri 65101



| 1. No. 29-A  | 4. Present Name(s)   |   |                     |  |
|--|--|---|---------------------|--|
| 2 County Tackson   | Research Downtown Health Care Center   |   |                     |  |
| 3 Location of Negatives CBD#59-14<br>Landmarks Commission of KC                                  | o name(s)  |   | The Linear          |  |
| 6 Specific Location  | 16. Thematic Category  | 28. No. of Stories 3  |                     |  |
| 720 Oak  | 17. Date(s) or Period  | 29. Basement? Yes! No 1.  | Jackson             |  |
| 7 City or Town If Rural, Township & Vicinity Kansas City, Missouri B. Site Plan with North Arrow | 18. Style or Design  | 31. Wall Construction reinforced concrete   | kson                |  |
|  | Bucher & Willis 20. Contractor or Builder  | 32. Roof Type & Malerial flat; tar and gravel                                       | THE PERSON NAMED IN |  |
| Oak Car  | J.E.Dunn 21. Original Use, if apparent   | 33. No. of Bays<br>Front Side   | Name of the least   |  |
|  | Hospital 22 Present Use Hospital   | 34. Wall Treatment brick  | 720                 |  |
| East 83 Street   | 23 Ownership Public !! Private !X  | 35. Plan Shape irregular  36. Changes Addition : (Explain Altered ! in #42) Moved i | Oak                 |  |
| 3 Coordinates UTM  | 24. Owner's Name & Address,<br>if known  | 37. Condition Interior Exterior excellent   |                     |  |
| Long  O. Site!: Structure!   | 25. Open to YesX Public? No 11   | 38. Preservation Yes Underway? No X   | and the same        |  |
| 1. On National Yes i 12 Is It Yes : Register? No XI Eligible? No XI                              | 26. Local Contact Person or Organization  Landmarks Commission of KC 27. Other Surveys in Which Included | 39. Endangered? Yes 1<br>By What? No ½:   |                     |  |
| Part of Estab. Yes!! 14 District Yes! Hist. Dist.? No ⋈ Potent'!? No ⋈                           |  | 40. Visible from Yes X<br>Public Road? No 11  |                     |  |
| 5. Name of Established District  |  | 41. Distance from and<br>Frontage on Road   |                     |  |

sheltered entrance along the north facade. Window treatment is varied: projecting window boxes, horizontantal bonds of windows, and vertical window areas. An open balcony area is at the southeast corner of the building. The building contains 23,690 square feet.

- 43. History and Significance The Downtown Hospital (918 Oak) was purchased by Research Medical Center in 1981 and this building was constructed to replace it. The \$2.5 million structure opened in November, 1982 offering day care for the elderly and emergency treatment, but no surgical facilities or full-time beds. The Center also provided a pharmacy, speech and hearing programs, and rehabilitation and occupational health services.
- 44. Description of Environment and Outbuildings A parking area is to the north. Surface parking lots are to the south and west.

| 45 | Sou | rces | at | Information |
|----|-----|------|----|-------------|
| -  | WP  | #56  | 69 |             |
|    | BP  | #66  | 91 | 8A          |

Kansas City Star, Feb. 1, 1981, p. 48.
 Kansas City Star, Sept. 29, 1982.
 Kansas City Star, September 2, 1981, p. 7C

| 46. Prepar<br>PILANI |     | у                |
|----------------------|-----|------------------|
|                      | ks  | Commission       |
| 48. Date             | 49. | Revision Date(s) |



Office of Historic Preservation, P.O. Box 176, Jefferson City, Missouri 65101 HISTORIC INVENTORY JA-AS-005-467 4 Present Name(s) 63-A Sam's Parking Company 2 County 5 Other Name's) Jackson 3 Lucation of Negatives CBD 40-17 Empire Garage name 0144 Landmarks Commission 16 Themalic Calegory 28 No of Stories & Specific Location 29. Basement? Jackson Yes !! 17 Date(s) or Period No XX 905-11 Oak 1923 30. Foundation Material 7 City or Town H Rural, Township & Vicinity 18 Style or Design 34 brick Tapestry Brick 31. Wall Construction Missouri Kansas City. Sile Plan with North Arrow steel frame 19 Architect or Engineer 9TH ST. Wilkinson & Crans 32. Roof Type & Material 20 Contractor or Builder PIZ flat; composition 33. No. of Bays Wm. Jewell Realty Co Front 5 21. Original Use, If apparent Side Parking garage 00 34 Wall Treatment 22 Present Use brick 35. Plan Shape Parking garage rectangular 23 Ownership 36 Changes Public 1 4 Addition Private LJ (Explain Altered i m 842) Moved . 24 Owner's Name & Address. of Annuan 37 Condition Interior & Cumulnates UTM Exterior poop Lung 25 Open to Yes IX Preservation Yes . Public? Underway? Sile Structure t No X Buildingx Object I i 26 Local Contact Person or Organization 39 Endangered? Yes II 11 On National Yes X By What? Landmarks Commission No X Yes .. 12 Is II Register? NOX Eliqible? No 11 27 Other Surveys in Which Included Yes X 13 Part of Estab Yes . District Visible from Yes X MIST DIST ? Potent'12 Nov No L Public Road? No . : 15 Name of Established District Distance from and Frontage on Road 96 feet on Oak 2 Further Description of Important Feetures On the west facade, the 1st floor has other Other Nameis 3 garage doors. A garage door at the south end of this facade 40 has been filled in with cement blocks. A single door is centrally located, flanked by plate glass windows. Five groups of hinged metal windows are located on both the 2nd and 3rd floors. Above each window group is a soldier course band of brick. Six raised brick panels are above and below the 3 central windows of the 3rd floor. The shaped 4) Mistory and Seguilicance parapet wall has stone coping. One of the early downtown parking garages. Description of Environment and Outbuildings Vacant lots are to the north and west of this building. To the east and south are surface parking lots. 5 Sources of, Information 46. Prepared by WP #1274 Helmer /Piland BP #13527 47. Organization Western Contractor, Feb. 14, 1923, p. 36 Landmarks Commission 48 Date 49 Revision Date(s) 10/22/80



Office of Historic Preservation, P.O. Box 176, Jefferson City, Missouri 65101 HISTORIC INVENTOR JA-AS-005- 468 4 Present Name(s) K.C. Honor Center 2 County 5 Other Nameral Jackson 3 totation of Megalives CBD #40-18 Snyderhof Hotel; Ka-Cee Hotel Landmarks Commission 16 Themalic Calegory 28 No of Stories Specific Location 29 Basement? Yes IX 917-19 Oak 17 Date(s) or Period No : . 1912 30. Foundation Material If Rural, Township & Vicinity 18 Style or Design concrete 7 City or Town 69 31. Wall Construction Kansas City, Missouri Italianate Site Plan with North Arrow 19. Architect or Engineer reinforced concrete Charles M. Willians 32. Roof Type & Material PR 20 Contractor or Builder flat; tar & gravel 33. No. of Bays Front 3 Side 13 21 Original Use, If apparent hotel 34 Wall Treatment 22 Present Use brick 35 Plan Shape rectangular governmental/hotel 23 Ownership Public 1 36. Changes Addition Private ! ! (Explain Attered XX m 842) Moved . 24. Owner's Name & Address. 57. 10TH of known Condition Interior UTM Cuordinales Exterior good Lunu 25 Open to Yes II Preservation Public? kkoM Underway? Structure ! . No X. Sile BuildingX Object 11 26 Local Contact Person or Organization Endangered? Yes II By What? Yes A Landmarks Commission No X 11 On National Yes .. NoX Eligible? No II Register? 27 Other Surveys in Which Included Yes X 13 Part of Estab Yes 14 District Visible from Yes X. HIST DIST ? Nox Potent'l? No I I Public Road? No :: Distance from and 15 Name of Established District Frontage on Road 48 feet on Oak 42 Further Description of important features The first floor, consisting of plate glass windows in the outer bays and a glass door in the central Other Nameis 2 bay has been altered. A simple string course runs beneath the 2nd floor. The 2nd through the 7th floors have single windows with terra cotta surrounds in the outer bays, while the central bay contains triplicate windows with floral terra cotta detailing in the spandrels. A balustrade fronts the central windows of the 7th floor. A string course runs between the 6th & 7th floors. (cohe'd) 43 Mislory and Significance Two pioneer grocers, brothers William P. and David T. Snyder, parlayed their income from a small fruit stand to finance this \$200,000 hotel project. The hotel, originally called the Snyderhof, opened in October, 1913. In 1956 it was purchased by the National Chain Hotel Company and the name changed to Ka-Cee Hotel. Since 1978 the building has been used by the State penal system as housing for prisoners in a work-releas Description of Environment and Outbuildings To the north and east of this building are surface parking lots. The YMCA is to the south and another parking garage is to the west. Kansas City Star, Nov. 25, 1956. 46. Prepared by WP #7017 Helmer/Piland 47. Organization KC Times, Sept. 13, 1979, p. 12B. Landmarks Commission


48. Date

11/7/80

49 Revision Dete(s)

HISTORIC INVENTORY
K.C. Honor Center
Page 2 917-19 Oak, KC JA-A5-005-468

42. (cont'd) The parapet wall has a denticulated cornice with modillions intermittantly spaced between the windows. A polychromy terra cotta cartouche with the initial S is placed at the center of the parapet wall.



State Historical Survey and Planning Office, 909 University Avenue, Suite 215,

Columbia, Missouri 65201



State Historic Survey and Planning Office, 90' Iniversity Avenue, Suite 215, Columbia, Missouri 65201 HISTORIC INVEN JA-AS-005-470 4. Present Name(s) No. Annex 63-C Young Men's Christian Association 2. County Jackson 3 Location of Negatives CBD #40-19 Kansas City Boy's Club; YMCA Annex Landmarks Commission 16. Thematic Category 6. Specific Location 28. No. of Stories ackson 921 Oak St. 29. Basement? Yes IX 17. Date(s) or Period No I 1913 30. Foundation Material stone 7. City or Town . If Rural, Township & Vicinity 18. Style or Design Kansas City, Missouri Renaissance Revival 48 31. Wall Construction 19. Architect or Engineer 8. Site Plan with North Arrow masonry UD Smith, Rea, & Lovitt Roof Type & Material 20. Contractor or Builder flat; composition 33. No. of Bays Geo. L. Brown Front Side 21. Original Use, if apparent social organization 03A 01E 34. Wall Treatment OAK 22. Present Use brick & stone 35. Plan Shape social organization rectangular 36. Changes Addition 1: Public I ! 23. Ownership Private X (Explain Altered D in #42) Moved i 24. Owner's Name & Address, IOTH ST. if known 37. Condition Interior 9. Coordinates UTM Exterior good Long Yes XX 25. Open to Preservation Public? No X Underway? 10. Site ! : Structure 1 Building I Object 11 39. Endangered? Yes I 26. Local Contact Person or Organization No IXX By What? Yes XX 11. On National 12 Is It Yes II Landmarks Commission No It Eligible? No I! Register? 27. Other Surveys in Which Included Yes XX 13. Part of Estab. Yes II 14. District Yes !X Visible from No.J. Potent'l? No T Hist. Dist.? Public Road? No 11 41. Distance from and 15. Name of Established District Frontage on Road 48 feet on Oak 42. Further Description of Important Features This brown/tan brick building has stone other trim. Bands of brick and stone are applied to the 1st floor. At the 0 center of the stone raised basement level is a pedimented doorway. The first floor contains three sets of one-over-one, double hung sash windows Photo with large transoms. A string course runs above the first floor. second through fourth floors are fenestrated with paired, sash windows. The central windows on each floor have stone quoined surrounds and modilliop keystones. A modillion cornice terminates the building. 43. History and Significance This annex to the YMCA was built to provide services for boys aged 10-16, too young for the YMCA program. Owned by the Charles E. Brown Realty Company, it was finally purchased by the YMCA in 1926. At that time, it was used as a dormitory for out-oftown students. 44. Description of Environment and Outbuildings The YMCA Building is to the south. A parking garage is to the east. A hotel building is to the north. To the west is a commercial building. 46. Prepared by 45 Sources of Information WP #20057 BP #10692 Helmer/Piland 47. Organization KC Star, Sept. 21, 1913 Landmarks Commission

48. Date

1/23/81

49. Revision Date(s)

KC Star, Aug 15, 1926, p. 1D.



| No.  | FORIC IN                           | ent Name(s)  |                          | JA-A5-005-4  |
|--|------------------------------------|--|--------------------------|--|
| 62-D   |                                    | Acme Typesetting Company   |                          |  |
| County   |                                    | r Name(s)  |                          |  |
| Jackson<br>Location of Negatives (   | CBD#16-10                          | Hoover Brothers Sc   | chool Supplies           | 0150   |
| Landmarks Commiss  | 10n                                | AND DESCRIPTION OF THE PARTY OF | one outprises            | Control of the Contro |
| Specific Location  |                                    | 16. Thematic Category  |                          | 28. No. of Stories 3  29. Basement? Yes IV   |
| 922 Oak  |                                    | 17 Date(s) or Period   |                          | 29. Basement? Yes IX   |
|  |                                    | 1914 (addition, 1  | 1923)                    | 30. Foundation Material  |
| City or Town - If Rural, Township & Vicinity                               |                                    | . 18 Style or Design   | to E1 10                 |  |
| Kansas City, Mo.<br>Site Plan with North Arrow                             |                                    | classical elemen   | ts 51 69                 | 31. Wall Construction PC   |
| . Site Plan with North Arrow   |                                    | Saylor & Seddon (S   | avlor, 1923)             | reinforced_concrete_<br>32. Roof Type & Material   |
|  | 1                                  | 20 C- 1 - 1  | osling, 1923)            | flat: tar & gravel   |
|  | N                                  | <u>Alexander Kinghorn</u>  |                          | 33. No. of Bays<br>Front 3 Side  |
| *  |                                    | 21. Original Use, if apparent commercial   |                          | 34. Wall Treatment   |
|  |                                    | 22. Present Use  | perch                    | brick 30   |
|  |                                    | commercial   | BA                       | 35. Plan Shape rectangular   |
|  |                                    | 23 Ownership   | Public 1 !<br>Private XX | 36. Changes Addition XX (Explain Altered)  |
|  |                                    | 24. Owner's Name & Addres  |                          | in #42) Moved  |
|  |                                    | if known   |                          | 37. Condition  |
| Coordinates UTM<br>Lat.<br>Long  |                                    |  |                          | Interior,  |
|  |                                    | 25. Open to  | YesXX                    | Exterior Good  38. Preservation Yes  |
| Site 1:  | Structure +                        | Public?  | No                       | 38. Preservation Yes :: Underway? No XX  |
| Building XX  | Object ! !                         | 26. Local Contact Person or  | Organization             | 39. Endangered? Yes XX   |
| On National Yes Li<br>Register? No XX                                      | 12 Is It Yes XX<br>Eligible? No !! |  |                          | By What? Demolition No!:   |
| Part of Estab. Yes II  | 14. District Yes XX                | 27. Other Surveys in Which I   | Included                 | and/or_redevelopment<br>40. Visible from Yes XX  |
| Hist. Dist.? No XX Potent'l? No :  Name of Established District            |                                    |  |                          | Public Road? No 13   |
|  |                                    |  |                          | 41. Distance from and<br>Frontage on Road  |
|  | and the same                       |  |                          | 36 ft. on Oak  |
| Further Description of I   | mportant Features The              | first floor of this  | 3 story brick            | setter /   |
| ommercial buildin  | ig features a cen                  | ter entrance with dis  | play windows             | 62   |
| on each side. An additional entrand  |                                    |  |                          |  |
| second floor is distinguished by Fr<br>onto small balconies with iron rail |                                    |  |                          | Photo  |
|  |                                    | ment windoes fill the  |                          |  |
| hese doors. A bal  | ustraded strong                    | course runs between t  |                          |  |
| History and Cincilicans  | Hooven Protho                      |  | second sheet)            | 1900 by Alvin and Orves  |
|  |                                    |  |                          | nly in kindergarten and  |
| rt supplies, but   | later expanded t                   | o include all areas o  | f educational            | training materials. The  |
|  |                                    | ation from 1914 to 19  | 50. The firm             | is still in business,  |
| ow located at 151  | i baitimore.                       |  | ,                        |  |
| Description of Environm  | _                                  |  |                          |  |
| ommercial buildin  | gs are located to                  | o the north, south, e  | ast, & west.             |  |
|  |                                    |  |                          |  |
| Sources of Information   |                                    |  |                          | 46. Prepared by  |
| ater permit #3928  | 4 Western Co                       | ontractor, March 28,   | 1923, p. 34              | Sherry Piland  |
| wilding permit #1  | 1187 & 76503                       |  |                          | 47. Organization   |
| Western Contractor, Feb. 11, 1914,   |                                    |  |                          | Landmarks Commission   |
| Western Contractor, Jan. 14, 1914,   |                                    |  |                          | 48. Date 49. Revision Date(s)  |
| ansas City Star,   |                                    | K.C. Post, Feb. 21,  | 1914, p. 3               | 4/4/80   |
| ansas City Star,   | Jan 20 1061                        |  |                          |  |

Acme Typesetting Company 922 Oak K.C. Sheet 2.


42. third floor. The third floor, which was added in 1923, is marked by tapestry brick work and double hung sash windows set in terra cotta surrounds.






Columbia, Missouri 65201 HISTORIC INVENTORY JA-AS-005-473 4. Present Name(s) 1. No. 79-G Commercial (vacant) 2. County Other Name(s) Lawrence Hotel; Brown Hotel; Louvain April 3 Location of Negatives CBD# 15-17 Stuppy Florist Supplies Landmarks Commission 16. Thematic Category 6 Specific Location 28. No. of Stories Basement? Yes XX 17. Date(s) or Period No I 1014 Oak ckson 1908 30. Foundation Material rubble stone - If Rural, Township & Vicinity 18. Style or Design 31. Wall Construction Kansas City, Missouri steel frame 8. Site Plan with North Arrow 19. Architect or Engineer Oscar G. Knecht 32. Roof Type & Material 20. Contractor or Builder flat; tar & gravel 33. No. of Bays Side Front 21. Original Use, if apparent Present Name(s) Vacant 34. Wall Treatment Hotel OID 22. Present Use brick 35. Plan Shape Vacant rectangular Public 1 23 Ownership 36. Changes Addition I Private XXX (Explain in #42) Moved 24. Owner's Name & Address... il known 37. Condition Interior poor UTM 9. Coordinates Exterior poor lat Long 25. Open to Yes I i Preservation Yes i Public? No XX No XX Underway? Structure I Site 1: Object | | **Building XIX** 39. Endangered? 26. Local Contact Person or Organization Yes XX By What? Demolition No! Yesxx 11. On National Yesii 12 Is It Landmarks Commission No IXIX Eligible? No 11 Register? 27. Other Surveys in Which Included and/or redevelopment 14. District YesXX 13. Part of Estab. Yes [ ] 40. Visible from Yes XX Public Road? No IXIX Potent'l? No: Hist Dist? No !! 41. Distance from and 15. Name of Established District Frontage on Road 48 ft. on Oak 42. Further Description of Important Features -- This building recently suffered a other major fire and is now vacant and in disrepair. The first floor facade has been variously treated in attempts at modernization. Each of the upper three floors is marked by a stone string course that Hote isame(s, Photo also serves as the window lugsills. The windows also have stone lintels. Lawrence Hotel; tuppy Florist Supply 43. History and Significance -- This hotel building was built by realtor Edward J. Spencer. first known as the Lawrence Hotel; later, the Louvain Hotel; and still later, the Brown Hotel Around 1920 the south portion of the first floor began to see commercial use and for many years was the location of Stuppy's Florist Supplies. 44. Description of Environment and Outbuildings Surface parking lots are located to the north, south and east. A commercial building is located to the west. 45 Sources of Information 46. Prepared by Building permit #8910 Sherry Piland 47. Organization WP# 23460 Landmarks Commission 48. Date 49. Revision Date(s) 3/25/80

State Historical Survey and Planning Office, 909 University Avenue, Suite 215,






State Historical Survey and Planning Office, 909 University Avenue, Suite 215,

HISTORIC INVENTORY
1104 Oak
Page 2

- 43. front 8 feet of the building. The south and west walls of the building were retained while the remainder of the building was rebuilt and leveled to 2 stories in height. Numerous commercial establishments have occupied the building in the ensuing years.
- 42. have been minor alterations to the first floor entrances and windows.





## HISTORIC INVENTORY

JA-AS-005-477

| 1. No.<br>128-A  | 4. Prese                            | Missouri Court of Appeals                                      |  | 128-4 |
|--|-------------------------------------|--|--|-------|
| Jackson  Jocation of Negatives Landmarks Commission of KC                    |                                     | ner Name(s)  |  |       |
| 6 Specific Location  |                                     | 16. Theinatic Category   | 28. No. of Stories 2                         |       |
| 1300 Oak  7 City or Town II Rural, Township & Vicinity Kansas City, Missouri |                                     | 17. Date(s) or Period  | 29. Basement? Yes ! No ! .                   |       |
|  |                                     | 1981-82<br>18 Style or Design                                  | 30. Foundation Material                      |       |
|  |                                     | 31. W  | 31. Wall Construction                        |       |
| B. Site Plan with North Arrow  |                                     | 19. Architect or Engineer                                      | reinforced concrete                          |       |
| East 13" N   |                                     | Abend, Singleton Associates 20. Contractor or Builder          | 32. Roof Type & Material flat; tar & gravel  |       |
|  |                                     | Concordia Project Management Ltd.                              | 33. No. of Bays                              |       |
|  |                                     | 21. Original Use, if apparent                                  | Front Side                                   | H 3   |
|  |                                     | governmental 22 Present Use                                    | 34. Wall Treatment brick                     | 1300  |
|  |                                     | governmental   | 35. Plan Shape irregular                     | 0 2   |
|  |                                     | 23 Ownership Public XI Private I I                             | 36. Changes Addition : (Explain Altered )    | Oak   |
|  |                                     | 24. Owner's Name & Address, if known                           | in #42) Moved : 37. Condition                |       |
| 9. Coordinates UTM   |                                     |  | Interior excellent                           |       |
| Long.  | ructure L                           | 25. Open to Yes Xi No : 1                                      | 38. Preservation Yes : Underway? No X        |       |
| - A  | Object                              | 26. Local Contact Person or Organization                       | 39. Endangered? Yes I<br>By What? No IX      |       |
| 11. On National Yes   12 Is It Register? No IX Eligible?                     | Yes:                                | Landmarks Commission of KC 27. Other Surveys in Which Included | by What.                                     |       |
| 13 Part of Estab. Yes 11 14. District Hist. Dist.? No lxt Potent's           | August Change and African and Sales |  | 40. Visible from Yes X<br>Public Road? No ii |       |
| 15. Name of Established District   |                                     |  | 41. Distance from and<br>Frontage on Road    |       |
| 15. Name of Established District  15. Name of Established District           |                                     | monumentalized entrance of this -                              | 41. Distance from and<br>Frontage on Road    |       |

- 42. Further Description of Important Features The monumentalized entrance of this corner building faces northeast. A glass block barrel vault highlights the entrance area. Wings extending to the south and west from the canted entrance feature slightly recessed semicircular windows that echo the vaults of the entrance. Limestone is used for a narrow string course above the foundation level.
- 43. History and Significance This building, constructed at a cost of \$2.6 million, houses suites for 12 judges, a law libaray, administrative offices, a conference room, and a large, two-story court room. The building was dedicated on December 10, 1982.
- 44. Description of Environment and Outbuildings Surface parking areas are north and west of this building. To the south and east are commercial buildings.
- WP #5566
  Kansas City Star, March 29, 1981, p. 2H.
  Kansas City Star, December 9, 1982, p. 198
  Architecture, May 1984, p. 350
  - 46. Prepared by
    PILAND

    47. Organization
    Landmarks Commission

    48. Date 49. Revision Date(s)
    4/4/84



Office of Historic Preservation, P.O. Box 176, Jefferson City, Missouri 65101 HISTORIC INVENTORY JA-AS-005-478 4 Present Name(s) 1 No 129-A Civic Plaza National Bank 2 County 5 Other Name(s) Jackson 3 Location of Negatives CBD #35-1 Landmarks Commission -Other 0154 Mutual Building; Puritan Building 16. Thematic Category 28. No of Stories 6 Specific Location 29. Basement? Yes II 1301-03 Oak 17 Date(s) or Period No : . 1919 30. Foundation Material 18 Style or Design If Rural, Township & Vicinity concrete 7 City or Town 31. Wall Construction Kansas City, Missouri 64106 19. Architect or Engineer Site Plan with North Arrow reinforced concrete 32. Roof Type & Material 20 Contractor or Builder flat; tar/gravel 33. No. of Bays N Side 3 Front 21. Original Use, if apparent 34. Wall Treatment commercial DOF brick 22 Present Use 35. Plan Shape commercial rectangular 36. Changes 23 Ownership Public I Addition Private VI (Explain Altered : in #42) Moved . E. 13 TST. 24. Owner's Name & Address. of known 37. Condition Interior UTM 9 Coordinates Exterior good Lung 25. Open to 38. Preservation Yes XI Yes : No X Public? Underway? Structure I. Site Building X' Object | | 26. Local Contact Person or Organization 39. Endangered? Yes II By What? No IX Yes XI 12 Is II 11 On National Landmarks Commission Yes .. Eligible? No X No II Register? 27. Other Surveys in Which Included District Yes X 13 Part of Estab Visible from Yes · X Public Road? HIST DIST ? No X Potent'l? No I No . : 41. Distance from and 15 Name of Established District Frontage on Road 49 feet on Oak 42 Further Description of Important Features Entrances are located on both the north and west sides. Large plate glass windows distinguish the first and second floors. The wall area between the windows is faced with ceramic tile. The upper floor windows are placed in Photo pairs and are covered by metal mesh. The building contains 34,000 square feet. 43 History and Significance -- This building was erected by the Merry Investment Company, as was the building to the immediate east (1300 Locust). The principal early tenant was the Mutual Oil Company. In the early 1960's the building was briefly occupied by Puritan Compressed Gas Corporation, a Kansas City firm founded in 1913 that grew to national propor tions. company produced oxygen and medical gases. In 1962 this building (cont. 2nd page) 44 Description of Environment and Outbuildings To the north and south of this building are surface parking lots. To the east and west are commercial buildings. This building is connected above the second floor, across an alley, to the building on the east. 45 Sources of Information 46. Prepared by Sherry Piland WP# 56739 47. Organization BP# 12480 Landmarks Commission Kansas City Star, April 14, 1963 48. Date 49 Revision Date(s)

9/23/80

Kansas City Star, April 9, 1962

43. was selected to house the Civic Plaza National Bank, the first new downtown National bank in 40 years. The site was favored because of its proximity to various governmental buildings. From 1942 to 1948 the building had been used as a headquarters for several federal agencies. In 1948 the building was leased by the Consumer's Cooperative Association, a regional group of manufacturers and wholesalers of petroleum products and farm supplies.



State Historical rivey and Planning Office, 909 I versity Avenue, Suite 215,

HISTORIC INVENTORY
Communication Workers of America Building
Page 2 1316 Oak K.C.

42. (cont'd) was Emil O Bayerl; contractor, H. H. Fox Construction Co. The entrance is centrally located and recessed. Double hung sash windows fenestrate the second floor. Bricks set in a soldier course form a panel above the second floor windows.



Office of Historic Preservation, P.O. Box 176, Jefferson City, Missouri 65101 HISTORIC INVENTORY JA AS-005-480 4 Present Name(s) 130-A Phil Jacobs Building 2 County 5 Other Name's) L.B. Price Mercantile Jackson Building 3 Lucation of Negatives CBD # 18-12 Gray Building; Liberty Building Landmarks Commission 28 No of Stories 16 Themalic Calegory 6 Specific Location Yes IX 29. Basement? ackson 17 Date(s) or Period 1329-35 Oak 30. Foundation Material 1903-04 stone; concrete 40 4 18 Style or Design H Rural, Township & Vicinity 31. Wall Construction (00) Kansas City, Missouri masonry 19 Architect or Engineer & Site Plan with North Arrow 32. Roof Type & Material ++ Shepard and Farrar flat; tar and gravel Contractor or Builder 33. No. of Bays G. Swenson 140 Side Front 5 21. Original Use, If apparent Present Name(s) 1329-35 Oak 5 commercial OFF 34 Wall Treatment 30 brick 22 Present Use 35. Plan Shape rectangular commercia1 36. Changes Addition Public 1 4 23 Ownership Attered D (Explain Private IV oak Moved i m #42) 24. Owner's Name & Address. el known Condition N Interior MTU Currdinales Exterior anod Lal 38. Preservation Yes . Lung 25 Open to Underway? No X Public? Structure ! . Sile 39 Endangered? 26 Local Contact Person or Organization Yes I Object 11 Building X' No X. By What? Landmarks Commission Yes IX 12 15 11 11 On National Yes . Eligible? No 11 27 Other Surveys in Which Included Register? No X Visible from Yes X Yes . District 13 Part of Estab Yes Public Road? Polent'1? No IX No . : MIST DIST ? No X Distance from and 15 Name of Established District Frontage on Road 117 feet on East 14 St 42 Further Description of important Features The building features a recessed entrance, centrally located, on Oak Street. Brick piers divide the facade into 5 bays. Plate glass windows fenestrate the 1st floor. Triple windows are located in the 3 central bays of the upper floors, while paired windows are in the corner bays. 43 History and Significance The building was constructed for the L. B. Price Mercantile Company. Over the years it has housed a variety of tenants including the Gray Advertising Company, the K.C College of Commerce, and the Liberty Starch Company. 44 Description of Environment and Outbuildings The building has frontage on Oak, East 13th Terrace, and East 14th Street. To the north, south, and west are surface parking lots. A small residence and a surface parking lot are to the east. 46. Prepared by Western Contractor, April 8, 1903. 45 Sources of Information Sherry Piland Kansas City Star, July 1, 1945, p. 4D. WP # 24705 47. Organization Landmarks Commission 49 Revision Dele(s) 48. Date

12/12/80



Columbia, Missouri 65201 JA-AS-005- 481 4. Present Name(s) 1. No. 143-A 1401 Oak (vacant) 2. County 5. Other Name(s) Jackson 3 Location of Negatives CBD# 18-13 Downtown 66 Service Station Landmarks Commission 6 Specific Location 16. Thematic Category 28. No. of Stories 29. Basement? Yes I Jackson 17. Date(s) or Period No IX 1401 Oak 30. Foundation Material 1965 7. City or Town . If Rural, Township & Vicinity 18. Style or Design concrete 31. Wall Construction Kansas City, Missouri 64110 8. Site Plan with North Arrow 19. Architect or Engineer 32. Roof Type & Material 20. Contractor or Builder flat: tar/gravel N 33. No. of Bays Herboth Construction Co. Front Side 21. Original Use, if apparent Present Name(s) 34. Wall Treatment filling station 1401 22. Present Use concrete block 35. Plan Shape rectangular vacant 36. Changes 23 Ownership Public I ! Addition : Private XX (Explain Altered I Oak in #42) Moved i 24. Owner's Name & Address. if known 37. Condition Interior UTM Coordinates Exterior fair Lat. Long 25. Open to Yes I i 38. Preservation Yes . Public? No XX Underway? No X 10. Site ! : Structure | Building KI Object ! I 26. Local Contact Person or Organization 39. Endangered? Yes IX By What? future No I i 11. On National Yesli 12 Is It Yes : Landmarks Commission demolition and/or redevelopment Register? Eligible? No IV No N! 27. Other Surveys in Which Included 13. Part of Estab. Yes II 14. District Yes IX Visible from Yes X No : Potent'l? Hist. Dist.? No XI Public Road? No I I 41. Distance from and 15. Name of Established District Frontage on Road 53 feet on Oak 42. Further Description of Important Features -- Triangular shaped roof projections, supported by metal posts, extend from the north and west facades. Chirch indiness Photo 13. History and Significance --Originally a downtown filling station, owned by the Phillips Petroleum Company. 14. Description of Environment and Outbuildings -- Commercial buildings are located to the north, south, and east of this structure. A surface parking lot is to the west. 5 Sources of Information 46. Prepared by Sherry Piland WP# 13119 47. Organization BP# 22107 Landmarks Commission 48. Date 49. Revision Date(s) 6/11/80

State Historical Survey and Planning Office, 909 University Avenue, Suite 215.



Columbia, Missouri 65201 ISTORIC INVENT JA-AS-005-482 4. Present Name(s) I. No. 144-A Southwestern Bell Telephone Building 0151 44 2. County 5. Other Name(s) Jackson 3 Location of Negatives CBD# 18-1 Landmarks Commission Southwestern Bell Telephone Long Distance Bldg. (Toll Bldg.) 16. Thematic Category 6 Specific Location 28. No. of Stories 29. Basement? Yes K 17. Date(s) or Period No I 1425 Oak Street 1930; additions in 1950,1963,1973 30. Foundation Material granite plinth 7. City or Town . If Rural, Township & Vicinity 18. Style or Design Kansas City, Missouri 64106 31. Wall Construction 8. Site Plan with North Arrow steel frame 19. Architect or Engineer Hoit, Price & Barns(1930); Neville, Sharp, Simon 32. Roof Type & Material 20. Contractor or Builder (additions) flat; tar/grave] see #43 33. No. of Bays Southwestern Front Side 21. Original Use, if apparent Present Name commercial 🗢 🗛 34. Wall Treatment 22. Present Use brick 3/ 35. Plan Shape commercial 23 Ownership Public 1! 36. Changes Addition X: Private X X (Explain Altered I Dak Be in #421 Moved i 24. Owner's Name & Address, il known 37. Condition Interior 9. Coordinates UTM Te good Lat. Exterior epho Long 25. Open to Yesli 38. Preservation Yes No X Public? No II Underway? Site ! : Structure 1 : Building XX Object | 1 ne 26. Local Contact Person or Organization 39. Endangered? Yes I By What? No IX: Yes X Landmarks Commission 11. On National Yes I i 12 Is II Bu Eligible? Register? No XX No 1! 27. Other Surveys in Which Included Yes X 13. Part of Estab. Yes ! ! 14. District 40. Visible from d Yes X Hist Dist ? No KX Potent'1? No : Public Road? No L 41. Distance from and 15. Name of Established District Frontage on Road 200 feet on Oak 42. Further Description of Important Features -- In 1950, five floors were added to WS. hes the original 3 story building. The terra cotta of the original build-Bel ing was replaced by brick. Aluminum spandrels separate the windows of this lower section of the building. In 1963 an 8 story east wing was Photo built and joined to the existing structure. In 1973 an 8 story addi-Tel tion brought the building to its present 16 stories. The building sits on a granite plinth. The 1st & 2nd floor windows of the north and ephone west are united by a stone surround with an incise of granite inset. (cortid) 43. History and Significance When the Bell Telephone Company built the original three-story long distance center, they planned for future expansions and projected a final 14 story building. Long The Swenson Construction Co. served as builders for the 1930 building and the 1950 addition; Universal Construction Co. built the 1963 addditon; and the J. E. Dunn Construction Co. built Distance the 1973 addition. 14. Description of Environment and Outbuildings The Crosstown Freeway runs to the south and east of this building. A surface parking lot is to the west. To the north is a surface parking lot, a vacant service station, and a small restaurant. Bldg. 5 Sources of Information 46. Prepared by Kansas City Journal Post, July 6, 1930, p. 4c. Sherry Piland (Tol) Kansas City Star, April 8, 1973 47. Organization WP# 90285 Landmarks Commission 48. Date 49. Revision Date(s) Bldg BP# 24373A Kansas City Star, Jan. 10, 1971 3/18/80

State Historical Survey and Planning Office, 909 University Avenue, Suite 215.

HISTORIC INVENTORY
Southwestern Bell Telephone Building 1425 Oak K.C.
Page 2

42 (cont'd) The main entrance is on the south. The entrance is marked by a rectangular projection the height of the building. Vaulted concrete canopys protect the walkways from the east and west of the entrance.



|   | 5-D                 |
|---|---------------------|
| No of Stories 2   | Jac                 |
| Basement? Yes Ki<br>No : .<br>Foundation Material                           | 2 Courty<br>Jackson |
| Wall Construction   |                     |
| Roof Type & Material flat;<br>yurethane foam spray<br>No. of Bays           | _                   |
| Front Side Wall Treatment Ood, brick  | Barnes              |
| Plan Shape square Changes Addition .  | Barnes Romi         |
| Explain Attered ( Moved ( Condition   | mine                |
| Interior good   | ine Residence       |
| Preservation Yes Underway? No X   | dence               |
| Endangered? Yes II  By What? No W   |                     |
| Visible from Yes X Public Road? No ::                                       |                     |
| Frontage on Road 00 foot frontage   |                     |
|   | 5. Other Nam        |
| Photo   | Namet               |
|   | 5)                  |
| m buildings that<br>assenger shed at<br>Store, Wolferman's<br>t carried the |                     |
| t carried the   |                     |

47. Organization

48. Date

3/80

Landmarks Commission

49 Revision Date(s)

Office of Historic Preservation, P.O. Box 176, Jefferson City, Missouri 65101 HISTORIC INVENTORY TA-45-005-483 4 Present Name(s) 1 No Barnes Romine Residence 2 County 5 Other Name(s) Jackson not Landmarks Commission 16 Themalic Category 28. 6 Specific Location 29. 727 Pennsylvania Avenue 17 Date(s) or Period 1975-77 30. If Rural, Township & Vicinity 18 Style or Design 7 City or Town 31. modern Kansas City, Missouri W 19. Architect or Engineer 8 Sile Plan with North Arrow Shaughnessy Assoc. 32. 20 Contractor or Builder Barnes Romine Downtown Const. Co., Vince Bahm pol 33. 1 21. Original Use, if apparent AVE residence 34. 1 22 Present Use W 35. residence 36. ( 23 Ownership Public 1 Private 1% 24. Owner's Name & Address, if known 37 ( UTM 9 Coordinates Lung 25. Open to Yes II 38. 1 Public? No IX Structure ! 10 Sile Building X Object 11 39. 26. Local Contact Person or Organization 11 On National 12 Is II Yes II Landmarks Commission Yes . No . X Eligible? No IX Register 27. Other Surveys in Which Included District Yes . 13 Part of Estab Yes 40 Potent'l? No IX HISI DIST ? No X 41. 15 Name of Established District 42 Further Description of Important Features -- The main entrance of this structure faces southeast. The building is surrounded by a high fence of hori zontal weathered planks supported by I beams. The exterior of the building is made of diagonal weathered board siding with a brick chimney on the west facade and a large glass wall on the north facade. Roof beams are exposed at the roof edge. The roof is a poly urethane sprayed 2" thick, creating an insulated roof. A wide wooden (continued on second sheet) 43 History and Significance -- This residence was built from material salvaged from were razed for downtown parking lots. Some of these buildings include parking lots. Union Station, Transfer Company Warehouse at 14th & Central, Duff & Repp Store. The residence is on the site of the old Eighth Street tunnel that elevated railway tracks to the Old Union Depot. 44 Description of Environment and Outbuildings -- To the north and south of this residence are vacant lots, to the west is the River Club and river, and to the east is another residence. This structure is located near the boundary to the Quality Hill Historic District in Kansas City's Central Business district. 45 Sources of Information 46. Prepared by Linda F. Becker BP# 20801, Public Works Dept., Kansas City, MO 64106 Kansas City Star, 7/31/77, p. H1-2

HISTORIC INVENTORY - CBD# 1-13 Barnes Romine Residence Page 2

727 Pennsylvania K.C.

42. deck located at the northwest side of the house provides a panoramic view of the Missouri River.



Office of Historic Preservation, P.O. Box 176, Jefferson City, Missouri 65101 HISTORIC INVENTORY JA-A5-005-484 4 Present Namo(s) No 52-B 910 Pennsylvania Apartments County 5 Other Name(s) Jackson 3 Lucation of Negatives CBD# 1-8 Landmarks Commission 16. Thematic Category 28. No of Stories 6 Specific Location 29. Basement? Yes IX 910 Pennsylvania Avenue 17 Date(s) or Period No : . 1957 30. Foundation Material 18 Style or Design If Rural, Township & Vicinity 7 City or Town 31. Wall Construction Kansas City, Missouri glass curtain wall 19. Architect or Engineer Site Plan with North Arrow Kivett, Myers & McCallum 32. Roof Type & Material 20 Contractor or Builder flat Winn-Senter Construction Company 33. No. of Bays Front 12 Side 21. Original Use, if apparent Present Name(s) 34. Wall Treatment apartment enamel 0 glass, brick, steel 22 Present Use Pennsy 35. Plan Shape apartment 23 Ownership Public 11 36. Changes Addition Altered : Private XI (Explain In #421 Moved . 24. Owner's Name & Address, vanla if known 37 Condition Interior UTM 9 Coordinates Exterior good Lat Lung 25 Open to Yes XI 38. Preservation Yes . Public? Underway? No i X Structure ! Sile Object 1 i Building X 26 Local Contact Person or Organization 39. Endangered? Yes II By What? No 1 X 11 On National 12 Is II Yesii Landmarks Commission Yes .. No 1X Eliqible? No .X Register? 27. Other Surveys in Which Included 13 Part of Estab Yes 14. District Yes I Visible from Yes . No . X Hist Dist ? No X Potent'1? No XI Public Road? 41. Distance from and 15 Name of Established District Frontage on Road 42 Further Description of Important Features -- The main facade of this modern structure faces east. The first floor of main facade consists of set Other Name(s back large display windows with piers set a few feet in front that visually support the remaining floors. The main entrance is approached Photo under a metal canopy. The remaining floors consist of metal I-beams, windows and charcoal gray enamel steel, creating a glass curtain wall design. The north/south facades consists of buff brick walls with a two bay wide window treatment as on main facade. 43 History and Significance -- This structure is one of several built as part of the Quality Hill Towers development plan. 44 Description of Environment and Outbuildings -- This structure is located in Kansas City's Central Business district. To the south, west and east are other multi-family dwellings. 45 Sources of Information 46. Prepared by Kansas City Times, June 18, 1957, p. 15 Linda F. Becker Kansas City Star, September 28, 1958 47. Organization Kansas City Star, July 5, 1959, p. 16F Landmarks Commission 48. Date 49 Revision Date(s) 3/80



Columbia, Missouri 65201 HISTORIC INVENTORY JA-AS-005 - 485 1. No. 4. Present Name(s) 53-A Penn Hill Apartments 2. County 5. Other Name(s) Jackson 80 JA 0158 3 Location of Negatives CBD #30-13 Roscoe Apartments - Name Landmarks Commission 6. Specific Location 16. Thematic Category 28. No. of Stories 030 Yes XX 911 Pennsylvania 29. Basement? County Jac 17. Date(s) or Period No I kson 30. Foundation Material 1918 cut stone 70 . If Rural, Township & Vicinity 18. Style or Design City or Town Kansas City, Missouri 31. Wall Construction Classical Revival masonry (1) 8. Site Plan with North Arrow 19. Architect or Engineer 32. Roof Type & Material flat; tar & gravel+7 20. Contractor or Builder Carl B. Vrooman 33. No. of Bays Side 21. Original Use, if apparent produ Front 10 911 Present 34. Wall Treatment apartment 22. Present Use brick Pennsylvania Nam 35. Plan Shape rectangular apartment 23. Ownership Public 1! 36. Changes Addition : Private \*\* (Explain Altered 1: in #42) Moved i 24. Owner's Name & Address, if known 37. Condition Interior 9. Coordinates UTM Lat. Exterior Long 25. Open to Yes I 38. Preservation Yes . No XX Public? No X Underway? 10. Site ! : Structure 1 Building X Object ! ! 26. Local Contact Person or Organization 39. Endangered?future Yes X By What? No II 11. On National 12 Is It Yes X Yes I i Landmarks Commission Eligible? Register? No !! No Ix 27. Other Surveys in Which Included redevelopment 13. Part of Estab. Yes IX Yes II District Yes X 40. Visible from Hist. Dist.? No I Potent'l? No : Public Road? No ! : 41. Distance from and 15. Name of Established District Frontage on Road 40 feet on Pennsylvani 42. Further Description of Important Features The main (west) facade features a 3-Schen story portico, divided into two major divisions by engaged wood columns 40 20 surmounted by a pedimented gable. A cut stone porch with a balustrade carrie brick piers which serve as the bases for the columns extending from the 2nd Photo through the 3rd stories. Smooth stone lintels appear over the doors and window openings. 43. History and Significance The original owner of this apartment building and the identical building to the north was C. M. Roscoe. 44. Description of Environment and Outbuildings An identical building is to the north. An apartment building is also to the west. To the north and east are surface parking lots. 45 Sources of Information 46. Prepared by BP #12308 Piland/Uguccioni WP #737 47. Organization
Landmarks Commission 48. Date 49. Revision Date(s) 1/2/81

State Historical Frvey and Planning Office, 909 Ur versity Avenue, Suite 215,




Columbia, Missouri 65201 HISTORIC INVENTORY JA-AS-605-486 1. No. 53-B Penn Hill Apartments 2 County 5. Other Name(s) Jackson 3 Location of Negatives CBD #30-14 0159 Cresent Apartments Landmarks Commission 28. No. of Stories 16. Thematic Category 6. Specific Location Yes XX 29. Basement? 17. Date(s) or Period No I 915 Pennsylvania 30. Foundation Material 1918 cut stone 40 18. Style or Design 7. City or Town . If Rural, Township & Vicinity 31. Wall Construction Classical revival Kansas City, Missouri masonry WD 19. Architect or Engineer B. Site Plan with North Arrow 32. Roof Type & Material 20. Contractor or Builder flat; tar & gravel PENNSYLUANIA 33. No. of Bays Carl B. Vrooman Front Side 21. Original Use, if apparent prich Present 34. Wall Treatment apartment O/B ms 22. Present Use brick 35. Plan Shape apartment rectangular Public 1 36. Changes Addition :: 23. Ownership Private XX Altered I ! (Explain in #42) Moved i 24. Owner's Name & Address,.. if known 37. Condition Interior UTM 9. Coordinates fair Exterior Lat. Long 25. Open to 38. Preservation Yes I No LX Public? Noxx Underway? Structure 1 Site!: Building XX Object 11 39. Endangered? 26. Local Contact Person or Organization Yes By What? No XX Landmarks Commission YesXX 12 Is It 11. On National Yesli Eligible? No 1 Register? No XX 27. Other Surveys in Which Included Yes XX District YesxiX 40. Visible from 13. Part of Estab. Yes 11 No XX No ! Potent'l? No : Public Road? Hist. Dist.? Distance from and 15. Name of Established District Frontage on Road 40 feet on Pennsylvani 42. Further Description of Important Features The main (west) facade features a 3-story other Curci hamels portico, divided into two major divisions by engaged wood columns surmounted 20 by a pedimented gable. A cut stone porch with a balustrade carrier brick piers which serve as the bases for the columns extending from the 2nd through Photo the 3rd stories. Smooth stone lintels appear over the doors and window openings. 43. History and Significance The original owner of this apartment building and the identical building to the south was C. M. Roscoe. 44. Description of Environment and Outbuildings Surface parking lots are located to the east of this building. An identical building is to the south. An apartment building is to the west. To the south is vacant land. 46. Prepared by 45 Sources of Information WP #109 Piland/Uguccioni BP #12308 47. Organization Landmarks Commission 48. Date 49. Revision Date(s) 1/16/81

State Historica' Survey and Planning Office, 909 University Avenue, Suite 215,



Columbia, Missouri 65201 HISTORIC INVENTORY JA-AS-005-487 1. No. 4. Present Name(s) CBD 70-B Apartment house (1005-07 Pennsylvania Ave.) 2. County 5. Other Name(s) Jackson 780A00079 3 Location of Negatives UD# 14-11 Saxon Flats Landmarks Commission 6 Specific Location 16. Thematic Category 28. No. of Stories <u>Architecture</u> County 29. Basement? YesXX 1005-07 Pennsylvania Ave. 17. Date(s) or Period No I 1900 30. Foundation Material 7. City or Town If Rural, Township & Vicinity Style or Design Rubble Limestone Kansas City, Missouri 64105 Georgian Revival 31. Wall Construction B. Site Plan with North Arrow 19. Architect or Engineer Masonry and Wood George Mathews 32. Roof Type & Material 20. Contractor or Builder Flat:Built-up Asph ENNSYM AUG Leo N. Leslie 33. No. of Bays Front 5 Side 9 21. Original Use, if apparent Present Name(s) 1005-07 Pennsylvania Multi-Family Residential 34. Wall Treatment 22. Present Use Br. Ven. over Com. Br 35. Plan Shape Rectangular Multi-Family Residential 23 Ownership Public 11 36. Changes Addition : **PrivateXX** (Explain Altered I 24. Owner's Name & Address, if known R.G.R. ASSOC., in #42) Moved i 37. Condition 1025 Wyandotte Street Interior 9. Coordinates UTM Kansas City, Missouri 64105 Lat. Excellent Exterior Long 25. Open to YesXX 38. Preservation Yes XX Public? 10. Restricted No II Ave Site ! Structure | Underway? No i **Building XX** Object ! ! 26. Local Contact Person or Organization 39. Endangered? Yes XX Yes XXX 11. On National By What? 12 Is It Yes XX Landmarks Commission No 1: Register? No !! Eligible? No I 27. Other Surveys in Which Included 13. Part of Estab. Yes XX Yes IXX 14. District Visible from Yes XX Hist. Dist.? No II Potent'l? No : Public Road? No 1 (None) 15. Name of Established District 41. Distance from and 10' Frontage on Road Quality Hill Neighborhood 48' along Penn. Ave. 42. Further Description of Important Features The main facade faces west entrance is a single leaf glazed door surmounted by a fanlight transom placed in a semi-circular, cut stone doorframe, within the central bay. The upper two stories of the central bay is a large semi-Photo circular frame containing windows, and stone and brick spandrals. The Flanking bays have single story brick and cut stone piers supporting two story wood porch columns. The fenestration consists of one-overone, double-hung sash windows placed in rectangular openings. 43. History and Significance The Saxon Flats was erected in 1900 by Leo N. Leslie who was a prominent realtor and builder The Saxon is a significent example of one of the earliest known type of colonaded apartment buildings, and indigeous design found especially in Kansas City. 44. Description of Environment and Outbuildings The building is located in the "Quality Hill" Neighborhood in the Central Business District of Downtown Kansas City, Missouri. To the north, east and south are multi-family residential structures vacant lots and surface parking lots. To the west is the Kansas City, Baptist Union. 45 Sources of Information 46. Prepared by Service Permit No. 17297, Water Department, 5th Fl., City Hall, Ed Miszczuk 414 E. 12th St., Kansas City, Missouri 64105. 47. Organization Kansas City (Missouri) Star, November 1, 1930. K.C. Landmarks Comm. Kansas City Architect and Builder, Vol. XV No. 1, January, 1900 and 48. Date 49. Revision Date(s) March 3, 1900, p.13. 2/77

State Historical Survey and Planning Office, 909 "riversity Avenue, Suite 215.



Columbia, Missouri 65201 HISTORIC INVENTORY JA-AS-005-488 4. Present Name(s) I. No. 69-C Downtown Baptist Church 2. County not entere 5. Other Name(s) Jackson CBD #1-6 Pennsylvania Avenue Baptist Church 3 Location of Negatives Landmarks Commission 28. No. of Stories 16. Thematic Category 6. Specific Location 1010 Pennsylvania (603 W 10th St) 29. Basement? Yes KX County No I . 17. Date(s) or Period 30. Foundation Material 1949-50 concrete . If Rural, Township & Vicinity 18. Style or Design 7. City or Town 31. Wall Construction Kansas City, Missouri brick 8. Site Plan with North Arrow 19. Architect or Engineer 32. Roof Type & Material 20. Co....actor or Builder flat; tar & gravel 10 TH ST 33. No. of Bays Side Front 21. Original Use, if apparent Present 34. Wall Treatment church 22. Present Use 35. Plan Shape rectangular Name(s) church 36. Changes Addition 1: Public ! 23 Ownership Private IXX Altered 1 (Explain Moved i in #42) 24. Owner's Name & Address, if known 37. Condition Interior 9. Coordinates UTM Exterior Lat. Long 38. Preservation Yes IXX 25. Open to Yes . No XX No II Underway? Public? Structure 1 10. Site!: 39. Endangered? Building XX Object | | Yes 26. Local Contact Person or Organization No XX By What? Landmarks Commission 12 Is It Yes ! 11. On National Yesli No XX No XX Eligible? Register? 27. Other Surveys in Which Included Yes XX Yes i 40. Visible from 13. Part of Estab. Yes 11 District Public Road? No 11 No XX Potent'1? No Hist. Dist.? 41. Distance from and 15. Name of Established District Frontage on Road 92 ft on Pennsylvania 42. Further Description of Important Features This is the basement for a structure that never materialized The main facade faces east. The glass entrance door is located off center towards the south end of the structure. Soldier courses of brick run above the windows, some of which are separated ed amers, by brick piers. A steeped projection is located above the entrance. A squat projection is local at the north end of the main facade and contains a hipped, asphalt shingled roof 43. History and Significance This church, with a congregation of 85, was organized in 1946. They originally met in the former Kersey Coates residence, which was located on the corner to the north of the present structure. In 1949-50 this basement structure was completed and plans were drawn by Albert Fuller for the church structure. In 1955 a fund raising drive was undertaken, with the congregation now numbering 300, for completion of the church from plans by Kivett and Myers. 44. Description of Environment and Outbuildings This lot sits above grade, with a stone wall running along the street line. To the north, east, and west of this structure are apartment buildings. A residence is to the south. 46. Prepared by BP #27022A Piland WP #423 47. Organization Kansas City Times, Nov. 7, 1949, p. 5. Landmarks Commission 48. Date 49. Revision Date(s) Kansas City Star, March 13, 1949, p. 16D 2/13/81 Kansas City Star, Oct. 29, 1955.

State Historica Survey and Planning Office, 909 University Avenue, Suite 215,



Columbia, Missouri 65201 TORL INVEN JA-AS-005-489 'resent Name(s) 1 No 69-0 CBD douse (1020 Pennsylvania Avenue) 2. County 5 Other Name(s) Jackson 3 Location of Negatives K, C. Carriage House/Stables (1020 Pennsylvania Avenue) Landmarks Commission 16. Thematic Category 6 Specific Location 28. No of Stories 30-1 Architecture 29. Basement? Yes o alcacaon 1020 Pennsylvania Avneue (Rear) 17 Date(s) or Period No :X c.1887-1888 30. Foundation Material 18 Style or Design Il Rural, Township & Vicinity Rubble Limestone Kansas City, Missouri 64105 Queen Anne 31. Wall Construction 8. Site Plan with North Arrow 19 Architect or Engineer Masonry and Wood 32 Roof Type & Material 20. Contractor or Builder Gable; Asph. Comp. 33. No. of Bays Front Side 21. Original Use, if apparent Carrage House/ Stables 34. Wall Treatment 22. Present Use Br. Ven. over Com. 335. Plan Shape Rectangular Single Family Residential 23 Ownership 36 Changes Public I Addition . . Private N Altered ix (Explain in #42) Moved 24. Owner's Name & Address, il known R. G. R. Assoc., 1025 37. Condition Wyandotte Ave. Kansas City, Interior 9 Coordinates UTM Missouri 64105 Exterior Lat Long 25 Open to Yes IX vania Preservation Yes X Public? Restricted No i Underway? S : a Structura No : Object -Building XI 26. Local Contact Person or Organization 39 Endangered? Yes IX By What? Yes X No ! Avenue 11. On National Yes XX 12 15 11 Landmarks Commission Eligible? No Register? 27. Other Surveys in Which Included Future Redevelopment Yes X 13 Part of Estab. Yes XX District 40. Visible from Yes X Hist Dist ? Potent'1? No No Public Road? No: (None) 15. Name of Established District 41. Distance Irom and 100' Frontage on Road Quality Hill Neighborhood app. 30' along alley 42 Further Description of Important Features Main facade faces east. The fenestration consists of one-over-one light double hung sash windows Carriage House/Stables placed in segmental arched openings along the first(ground) story and placed in rectangular openings along the attic level. The attic level contains gable roofed and hipped roof wall dormers. Gable ends are surfaced with fish scale shingles. 43. History and Significance The structure was erected in about 1887 presumably by David Stater, local tailor for his carriage house/stables. 44. Description of Environment and Outbuildings The structure is located in the "Quality Hill" Neighborhood in the Central Business District in downtown Kansas City, Misseuri. To the north, south, east and west are single and multi-family residential structures. 45 Sources of Information Kansas City(Missouri) Journal, January 1. 1888 p. 446 Prepared by Service Permit No. 7227, Water Department, 5th Fl. City, Hall, 414 Ed Miszczuk 47. Organization K. C. e. 12th St. Kansas City, Missouri 64106. Landmarks Congission 48. Date 49 Revision Date(s) 4177

State Historical Survey and Planning Office, 909 University Avenue, Suite 215.



State Historical Survey and Planning Office, State Capitol Building, Room B-25, HISTORIC INVENTORY Jefferson City, Missouri 65101 JA-AS-005-1 No Present Name(s) CBD 70-G Monroe and Lefebvre, Architects, Inc., A.I.A. 2. County Jackson 3 Location of Negatives K.C. (BL Major William Warner Residence 40 Landmarks Commission#14 6. Specific Location 16. Thematic Category 28. No. of Stories 23 Jacks 1021 Pennsylvania Avenue Architecture 29. Basement? Yes M 17. Date(s) or Period No 1 1880 30. Foundation Material 9 Rubble Stone 18. Style or Design City or Town If Rural, Township & Vicinity Kansas City, Mo. 64105 31. Wall Construction Builders Vernacular 8. Sile Plan with North Arrow Masonry and Wood 19. Architect or Engineer 32. Roof Type & Material Unknown 20. Contractor or Builder Mansard; Tab roofing 33. No. of Bays Unknown Side 5 Front 3 21. Original Use, if apparent 34. Wall Treatment Pressed Residence 22. Present Use Orange-red Brick 35. Plan Shape Cross Commercial 23. Ownership Public 36. Changes Addition :: Private XI (Explain Altered M in #42) 24. Owner's Name & Address d Lefebvre Moved i. Le PENNSYLVANIA AVENUE febv 37. Condition Good Architects, Inc., A.I.A. Interior 9 Coordinates UTM 1021 Pennsylvania Avenue Good Lat. Exterior re Long 25. Open to Yes M 38. Preservation Yes x Public? No II Underway? Noli Site ! I Structure 1 i Building N Object 11 26 Local Contact Person or Organization K.C. Landmarks Commission Endangered? Yes X By What? No 1 ; Yes X Yes IX 11. On National 12 Is II Possible Redevelop. Eligible? Noll Register? No .. 27 Other Surveys in Which Included Historic Building Preservation Yes IX 13. Part of Estab. Yes XX 14. District Visible from Yes X Potent'1? Noli Analysis; Land Clearance for Hist Dist ? No 11 Public Road? No 1: Redevelopment, Room 318, 366 15. Name of Established District Distance from and East 12th Street, Kansas City 20 Frontage on Road Quality Hill Neighborhood Missouri, 1973 39' along Penn Ave 42 Further Description of Important Features Main Entrance faces west. Fenestration consists of one-over-one double-hung sash windows. Other Namels windows have pressed stone sills, and pressed stone lintels insized with scrolls linear and circular motifs. On South Faca is dominated by a projecting two story semi-hexagonal protrusion adjoined to a rectangular bay. Major Refurbishing of resid ence occured in 1968 by present owners. Alterations included; 1) Removal of L-shape West Facade porch, 2) Removal of West (cont 43 History and Significance Residence is significance as being a fine example of the type of residencial mansions which lined early Kansas City Streets. Residence, erected in 1880, is sigificant as being the home of Major William Warner. Warner was one of the distinguished personalities of Missouri politics. Warner wascity attorney (1867), circuit attorney (1868), elected Mayor (1870), United States District Attorney for th 44. Description of Environment and Outbuildings Residence is situated in the Quality Hill neighborhood, which is the last remaining portion of downtown Kansas City residential area To the north is a surface parking lot. In the general vicinity, to the east, west, and south is otherQuality Hill residences and structures
45 Sources of Information 46. Prepared by Ed Miszczuk Kansas City (Missouri) Star, April 8, 1928. p.6C 47. Organization K.C. Kansas City (Missouri) Times, December 10, 1972. p.1E Lnadmarks Commission Kansas City (Missouri) Times, October 5, 1916. p.1-2 49. Revision Date(s) 48. Date 2/20/75

HISTORIC INVENTE Y- State Office of Historic \_eservation

Monroe and Lefebvre, Architects, Inc., A.I.A.
(Major William Warner Residence)
Kansas City, Missouri

Page two

42) Further Description of Important Features (cont.)

Facade roof dormer: 3) Removal of paired brackets along roof frieze.
4) Removal of slate shingles originally covering the roof, and removal of lacy iron grillwork encircling ithe mansard roof. 5) the Building originally contained three brick chimneys. 6) Within the interiors, the partitions of othe first floor were changed to create office space.
7) Removal of the second floor bedroom partitions. 8) Kemoval of the original rear (east) facade wood frame porches. 9) In the 1880's, the north-rest corner was extended to the north.

43) History and Significance (cont)

Western District of Missouri (1882-1884). In 1892, Warner was Missouri Republican Gubernatorial nominee. Warner was appointed for a second time U.S. District Attorney (1900-1905). He was elected to the United States House of Representatives (1884-1887). In 1905, Warner was elected to the U.S.Senate serving two terms until 1911.



State Historica Jurvey and Planning Office, 909 niversity Azenue, Suite 215, Columbia, Missouri 65201 HISTORIC INVENT JA-AS-005-491 2 22.73 sent Name(s) 69-M CBD ...artment House (1024 Pennsylvania Ave.) 2 County Other Name(s) Jackson Location of Negatives K. C.C.PDF Apartment House (1024 Pennsylvania Ave.) Landmarks Commission 16. Thematic Category 28 No of Stories 6 Specific Location Architecture 29. Basement? Yes X acks 1024 Pennsylvania Avenue 17. Date(s) or Period 1907; addition 1912 30. Foundation Material on 18 Style or Design Rubble Limestone If Hural, Township & Vicinity Kansas City, Missouri 64105 31. Wall Construction Neo-Classic Revival 8. Site Plan with North Arrow 19. Architect or Engineer Masonry and Wood Horace LaPierre 32. Roof Type & Material 20. Contractor or Builder Flat; tar & gravel 33. No. of Bays Front Side 21. Original Use, if apparent redy 34. Wall Treatment Multi-family Residential 22 Present Use Buff Br. veneers 35. Plan Shape Rectangular Multi-family Residential 36. Changes Addition X Public 11 23 Ownership Private X (Explain Altered I Hou in #42) Moved i 24. Owner's Name & Address, se if known Arnold Garfinkle % R. G. 37. Condition Interior R. Associates, 1025 Wyandotte UTM y Coordinates Exterior Good St. Kansas City, Mo. 64105 Lat. Long 25 Open to Yes X Preservation Yes X Public? No : Underway? No : Sile Structure Restricted Building X Object : i Endangered? 26. Local Contact Person or Organization Yes X By What? No 1: Yes x 12 Is It Landmarks Commission 11. On National YesXX Future Redevelopment Eligible? No Register? Noil 27 Other Surveys in Which Included 13 Part of Estab YesxX Yes X 40. Visible from Yes X 14 District Potent'1? No : Public Road? No 1 4 No Hist. Dist ? (None) Distance from and 15 Name of Established District 10' Frontage on Road 50' along Penn, Ave. Quality Hill Neighborhood 42. Further Description of Important Features Main facade faces east. The east facade is assymetrical in design due to a possible 1912 northeast addition. The first story walls are rusticated. The main entrance is sheltered by a pediment door surround. The fenestration is composed of one-over one light double hung sash windows placed in rectangular openings on the primary facade and placed in segmental arched openings on the secandary facades. 43. History and Significance The structure was erected in 1907 as a four apartment flat by U. S. Routzong. The building is fine example of the work by the local architect, Horace LaPierre. 46. Description of Environment and Outbuildings The Structure is located in the "Quality Hill" Neighborhood in the Central Business District of Downtown Kansas City, Missouri. To the north, south, east and west are single and multi-family residential structures. 8 45 Sources of Information Service Permit No. 877, Water Department, 5th Floor 46 Prepared by Ed Miszc-tik City Hail 414 E. 12th St. Kansas City, Missouri. 64106 47. Organization Building Permits Nos. 52132, 8499, Public Works Department, 18th Fl.

K. C.

43. Date

2/77

Landmarks Comm

49 Revision Date(s)


City Hall, 414 E. 12th St. Kansas City Mo. 64106



JA-AS-605-492 sent Name(s) No 69-L CBD Hotel (1028 Pennsylvania Avenue) County Jackson 5 Other Name(s) Dormicory 3 Location of Negatives K. C. CBD#1 Girls Club (North wing) Landmarks Commission -16. Thematic Category 6 Specific Location 28 No of Stories Architecture 29. Basement? Yes X 1028 Pennsylvania Avenue 17. Date(s) or Period No L 1928 30. Foundation Material Rubble Limestone 7 City or Town If Rural, Township & Vicinity 18. Style or Design 31. Wall Construction Kansas City, Missouri 64105 Spanish Colonial Revival 8 Site Plan with North Arrow 19 Architect or Engineer Masonry and Wood Walter A. Besecke 32. Roof Type & Material 20. Contractor or Builder Flat; tar and gravel J. E. Dunn 33. No. of Bays Front Side 21. Original Use, if apparent Hotel 34. Wall Treatment 22 Present Use Br. Ven & Terra Cotta 35. Plan Shape Rectangular 23 Ownership Public I 36 Changes Addition . Private :X (Explain Altered X in #42) Moved i 24. Owner's Name & Address, PA. AVE. if known Arnold Garfinkle % R. G. 237. Condition R. Associates, 1025 Wyandotte 9 Coordinates St. Kansas City, Missouri 64105 Exterior Excellent Lat Long 25. Open to Yes ! Yes X 38. Preservation Public? No x Underway? Structure No : 5 :-Suiding X Object ... 26. Local Contact Person or Organization 39. Endangered? Yes X No X Landmarks Commission By What? Yes X 11 On National Yes XX 12 15 11 Eliqible? Register? No 1 No 27. Other Surveys in Which Included 14 District Yes X 13 Part of Estab YesXX Visible from Yes X Hist. Dist.? No : Potent'1? No (None) Public Road? No :: Distance from and 15. Name of Established District Frontage on Road Ouality Hill Neighborhood 30' along Penn. St. 42. Further Description of Important Features Main facade faces east. The east facade is dominated by a single story brick veranda porch (presently enclosed). Fenestration consists of six-over-one light double-hung sash windows. The windows along the third story are surmounted by semi-circular terra cotta lintels. Portion of the parapets along the consists of red clay Spanish tiles. Along the south facade is a glass enclosed passageway extending to the Blossom House (1032 Penn. Ave.). The building was erected in 1928 by Philanthropist, William Volker, for 43. History and Significance the Girls Home Association, to serve as the north wing. The Girls Home Association as founded by Volker to serve as a hotel for girls. Description of Environment and Outbuildings The building is located in the "Qualtiy Hill" Neighborhood of the Central Business District of Downtown Kansas City, Missouri. To the north, south, east and west are commercial or residential structures. 3 Sources of Information Brochure entitled, Urban Architects, located in the 46 Prepared by files of the Landmarks Commission office, 1973 Ed Miszczuk Building Permit No. 15322, Public Works Department, 18th Floor, City 47. Organization Hall, 414 E. 12th St. Kansas City, Missouri 64106 K. C. Landmarks Comm. Western Contractor, November 7, 1928, p. 26. 48. Date 49 Revision Date(s) 2/77

State Historical Survey and Planning Office, 909 University Avenue, Suite 215.


Columbia, Missouri 65201



Columbia, Missouri 65201 STORIC INVENT JA-AS-005-493 1. No 4. Present Name(s) CBD 70-H 2. County House (1029 Pennsylvania Ave.) Jackson 5. Other Name(s) 3. Location of Negatives CBD# 14-9 Issac F. Guiwits Residence Landmarks Commission 6. Specific Location 16. Thematic Category 28. No. of Stories Architecture 29. Basement? Yes IXX 1029 Pennsylvania Avenue Date(s) or Period No I 1889 kson 30. Foundation Material 7. City or Town . If Rural, Township & Vicinity 18. Style or Design Rubble Limestone 31. Wall Construction Kansas City, Missouri 64105 "Builder's Vernacular" B. Site Plan with North Arrow 19. Architect or Engineer Masonry and Wood 32. Roof Type & Material 20. Contractor or Builder Gable; slate No. of Bays Side 5 Front 21. Original Use, if apparent Residence 34. Wall Treatment 22. Present Use Face Br. over Com. Br Pennsylvania Apartments 35. Plan Shape Rectangular 23 Ownership Public 11 36. Changes Addition 1: Private XIX (Explain Altered IXX 24. Owner's Name & Address, in #42) Moved i if known Clem W. Fairchild, 37. Condition 900 Walnut St., 3rd Fl. Interior 9. Coordinates UTM Kansas City, Missouri 64106 lat Avenue Exterior Good Long. 25. Open to Yes XX Preservation Yes (X) Public? 10. Site ! : Structure 1 Restricted Underway? No i BuildingXX Object 11 26. Local Contact Person or Organization Endangered? Yes (X) Yes XX 11. On National Yes XX By What? 12 Is It No 1 Landmarks Commission Eligible? Register? No No I! 27. Other Surveys in Which Included Future Redevelopment 13. Part of Estab. Yes XX 14. District Yes XX 40. Visible from Yes !X) Hist. Dist.? No Potent'l? No : (None) Public Road? No 11 15. Name of Established District Distance from and 20' Frontage on Road Quality Hill Neighborhood 23' along Penn. Ave. 42. Further Description of Important Features Main facade faces west. The west facade is dominated by a two story enclosed wood frame and brick porch. The main entrance is composed of a single leaf door with side windows and surmounted by a transom. Fenestration consists of one-over-one light Photo double sash windows placed in rectangular frames within the west and east porches. The fenestration on the secondary facades are composed of one-over-one light double sash windows placed in segmental openings. The roof is broken by hipped roof dormers. 43. History and Significance The building is located in the "Quality Hill" Neighborhood of the Central Business District of Downtown Kansas City, Missouri. To the north, south, east and west are commercial and residential structures. 44. Description of Environment and Outbuildings The building is located in the "Quality Hill" Neighborhood of the Central Business District of Downtown Kansas City, Missouri. To the north, south, east and west are commercial and residential structures. 45 Sources of Information 46. Prepared by Service Permit No. 9631, Water Department, 5th Floor, City Hall, Ed Miszczuk 414 E. 12th St., Kansas City, Missouri 64106. 47. Organization Kansas City Journal, June 5, 1889, p.3. K.C. Landmarks Comm. 48. Date 49. Revision Date(s)

2/77

State Historica Survey and Planning Office, 909 "iversity Avenue, Suite 215,



State Histor: 1 Survey and Planning Office, 7 University Avenue, Suite 215, Columbia, Missouri 65201 HISTORIC INVENTORY JA-AS-005-494 resent Name(s) No CBE 69-K Blossam House 2 County Jackson 5 Other Name(s) 3 Location of Negatives K. C, CBD#1 Mrs. George N. Blossom Residence, Girls Home Association Landmarks Commission 6. Specific Location 16 Thematic Category 28 No of Stories Architecture 29. Basement? Yes X 17 Date(s) or Period No i 1032 Pennsylvania Avenue 1888 30. Foundation Material Rubble Limestone Il Aural, Township & Vicinity 218. Style or Design 7. City or Town 31. Wall Construction Victorian Eclectic Kansas City, Missouri 64105 19 Architect or Engineer Masonry and Wood 8. Site Plan with North Arrow Van Brunt & Howe 32. Roof Type & Material 20. Contractor or Builder Hip; Asph. Comp. 33. No. of Bays Norcross Bros (Worcester, Mass. Front Side 21 Original Use, if apparent 34. Wall Treatment Residence 22. Present Use Br. Ven. over Com 35. Plan Shape Rectangular Commercial 36. Changes Public ! 23 Ownership Addition X Private \*1 (Explain Altered I in #421 Moved : 24. Owner's Name & Address. il known Arnold Garfinkle % R. G. 37. Condition Interior R. Associates, 1025 Wyandotte UTM Coordinates Kansas City, No. 64105 Exterior Excellent Lat Long 25. Open to Yesx Preservation Yes X Public? No: Underway? Restricted No: Site Structura Building X Object Local Contact Person or Organization 39 Endangered? Yesi By What? No K Landmarks Commission Yes X 12 Is II 11 On National Yes X Eligible? Register? No it Other Surveys in Which Included Yes X Historic Building Preservation 14. District Yes X Visible from 13 Part of Estab Yes XI Hist. Dist ? No ! : Potent'1? Public Road? No : : Analysis, prepared by Land Clea 41. Distance from and rance for Redevelopment. 15. Name of Established District 10' Frontage on Road 1973 Quality Hill Neighborhood App. 60' along Penn. The main facade faces east. The east 42. Further Description of Important Features facade is dominated by a single story brick veranda consisting of a brick piers and wood screens. Fenestration consists of one-over-one light double hung sash windows, either grouped singly or in pairsed, or in threes. Terra Cotta panels and cut stone embellish window lintels, lugsills and chimneys. Chimneys are placed assymetrically extending high over the roof line. The roof contains both wall and roof dormers. The building refurbished in 1973. 43. History and Significance The building was erected in 1888 by Mrs. George N. Blossom (Elizabeth Allman), proprietor of the Blossom House Hotel, for her residence. In 1902, philanthropist William Volker purchased the building from the Blossom family. Volker renamed the mansion and the ajoining duplex (612W. 11th St.) into the "Girls Association," a hotel for girls. Volker later donated the complex to the Kansas City, Roman Catholic Diocese. The Blossom was renovated in 1973 by Urban Architects AIA as an office building 44 Description of Environment and Outbuildings The building is located in the "Quality Hill Neighborhood in the Central Business District in Downtown Kansas City, Missouri. The building is adjoined 2 to the north, by a single story passageway, to 1028 Penn. apartment building and to the west by a three story duplex. To the east and south are commercial and residential structures. 45 Prepared by 45 Sources of Information Kansas City(Missouri) Times, April 22, 1888. p.8 Ed Miszczuk Kansas City(Missouri) Star January 30, 1972 p. 1E; Service Permit Organization No. 8337, Water Department, 5th Floor City Hall, 414 E. 12th St., K. C. Landmarks Comm. Kansas City, Missouri 64106; Case, Theo. S. History of KansasCity,

Syracuse, N.Y. D. Mason & co. C. 1888, p.124A

48. Date 49. Revision Date(s)

2/77



State Historical Survey and Planning Office, 909 University Azenue, Suite 215. Columbia, Missouri 65201 TORIC INVENTORY JA-AS-005-495 4. Present Name(s) 1 No CBD Al meda Hotel; 86-D Apartment House (1100 Pennsylvania Ave.) 2 County Jackson 5 Other Name(s) 3 Location of Negatives K. C. COD#2 Double Tounhouse Duplex (1100 Pennsylvania Avenue); Almeda Hotel Landmarks Commission 28. No of Stories Specific Location 16. Thematic Category ) Architecture 29. Basement? Yes IX 1100 Pennsylvania Avenue 17. Date(s) or Period No I KSON 1899; addition 1924 30. Foundation Material Rubble Limestone If Rural, Township & Vicinity 18 Style or Design 7 City or Town 31. Wall Construction Kansas City Missouri 64105 Neo Classic Masonry and Wood 8. Site Plan with North Arrow 19 Architect or Engineer 32. Roof Type & Material Contractor or Builder Hip & Flat; A. C. &T Carl Bliss (addition) 33. No. of Bays Side Front 21. Original Use, if apparent 34. Wall Treatment Duplex 22. Present Use Br. Ven. over Com. 35. Plan Shape H-shape Multi- Family Residential 36. Changes Public I Addition .X 23 Ownership Private Ix (Explain Altered I 7 in #42) Moved i 24. Owner's Name & Address. il known Wayne & Betty Dicker % 37. Condition PA. AVE. Interior Alameda Hotel, 1100 Penn. St. UTM 9 Coordinates Kansas City, Mo. 64105 Exterior Lal Long 25. Open to Yes X 38. Preservation Yes X Restricted Public? No : Underway? Structure 10 Sia 39. Endangered? On ect Building X 25 Local Contact Person or Organization Yesix By What? No !: Landmarks Commission Yes X Yes X Is It 11. On National Future Redevelopment Eliqible? No ! Register? No 27. Other Surveys in Which Included Visible Iron Yes X Yes :X 13 Part of Estab Yes XX 14 District Public Road? No i . Potent'1? Hist. Dist ? No (None) 41. Distance from and 15. Name of Established District 15' Frontage on Road Quality Hill Neighborhood 46' along Penn. St. 42. Further Description of Important Features Main facade faces east. The complex is composed of two separate sections; a two story brick duplex, constructed 1899, and a two story brick addition constructed in 1924. East facade is dominated by a single story hip roof entrance porch Fenestration consists of nine-cver-one double hung sash windows placed in segmental arched openings. The central second story windows are outlined by quoining. Fenestration on the secondary facades of the addition consists of 9-over-one light windows placed in rectangual comanings. 43 History and Significance The structure was erected in 1899 by E. W. Shields, secretary and treasure of the Simonds Grain Co., probably for spectulation. The earleist known resident was Herbert D. Cutler, President of the Cutler & Neilson Paint & Color Co. The structure was enlarged in 1924 and renamed the Almeda Hotel. 44 Description of Environment and Outbuildings The Structure is located in the "Quality Hill" Neighborhood in the Central Business District of downtown Kansas City, Missouri. To the north, south, west and east are multifamily residential and commercial structures. 46. Prepared by 45 Sources of Information Service Permit No. 15472, Water Department, 5th Fl. Ed Miszczuk Vaccac City Missouri 64106. 47. Organization



State Historical Survey and Planning Office, 909 University Avenue, Suite 215, Columbia, Missouri 65201 HISTORIC INVENT JA-AS-005-494 Present Name(s) Nº86-E CBD Loomis Boarding House CBD Apartment House (1104 PennsylvaniaAve.) 2 County Jackson 5. Other Name(s) Location of Negatives K. C. Landmarks Commission (80# 28-3 Alpha Hotel, Imperial Hotel, Lora Flats 6 Specific Location 16. Thematic Category 28. No of Stories Architecture 29. Basement? Yesk 1104 Pennsylvania Avenue Date(s) or Period No I 1886-87 30. Foundation Material Style or Design If Rural, Township & Vicinity Rubble Limestone Kansas City, Missouri 64105 Richardsonian Romanesque 31. Wall Construction 8. Site Plan with North Arrow PA. AVE. 19. Architect or Engineer Masonry 32. Roof Type & Material 20. Contractor or Builder Flat; Tar & Gravel 33. No. of Bays Front 2 Side 21. Original Use, if apparent Boarding House 34. Wall Treatment Br., Cut stone., T. C. 22. Present Use 35. Plan Shape Apartment House Rectangular 23 Ownership Public 11 36. Changes Addition 1: Private 14 (Explain Altered 1 ' in #42) Moved i 24. Owner's Name & Address, if known 37. Condition Jack G. Pittman, 1104 Interior Penn., Ave. Kansas City, Mo. 9 Coordinates UTM Good Exterior Lal. 64105 Long 25. Open to Yes X Preservation Yesx Underway? Public? No i Restricted 5.12 Structura Building x' Object . . 26. Local Contact Person or Organization 39. Endangered? Yesx By What? Landmarks Commission No 1: 11. On National Yes 'X 12 Is It Yes X Eligible? No Register? Nois 27. Other Surveys in Which Included Future Redevelopment District Yes x Historic Building Preservation 13 Part of Estab Yes XI 40. Visible from Yes X Potent'l? Hist. Dist.? No. No : Public Road? No 1: Analysis, Pub. by Land Clearande Distance from and 15. Name of Established District for Redevelopment, Kansas City, 15' Frontage on Road Missouri. 1973 Quality Hill Neighborhood 40' along Penn Ave. 42. Further Description of Important Features The main facade faces east. The facade is dominated by a two bay wide double story projection, consisting of a recessed porch with coursed stone arches supporting the second story. Terra cotta stringcoursing visually separate the first and second of the porch and embellish the roof parapet and porch parapet multi-light double sash windows place Fenestration consists of in rectangular openings on the second and first stories. Cut stone is used for window quoins, lintels, voussoirs and lugsills. Queen Anne sa 43. History and Significance The building was erected in 1886-87 by Mrs. Carrie Deardorff as a boarding house. In later years its been renamed the Alpha, Imperial, and Lora hotels. It acquired its more common name, the Loomis Boarding House from George H. Loomis, first tenant/inthe boarding house. The building is one of the finest examples of Richardsonian Romanesque Style architecture in the city. Description of Environment and Outbuildings The building is located in the "Quality Hill" Neighborhood in the Central Business District of Downtown Kansas City, Mssouri. To the north, south, and east are residential structures. To the west are commercials.structures. ra 45 Sources of Information Kansas City, (Missouri) Journal , January 1, 1888 p.4 46. Prepared by Service Permit No. 5827, Water Department 5th floor, City Hall, 414 Ed Miszczuk 47. Organization E. 12th St. Kansas City, Missouri 64106. Landmarks Comm Hoye's City Directory, Hoye Directory Company, Kansas City, Mo., 48. Date 49 Revision Date(s) Vanne 1886-1910.

2/77




State Historican Survey and Planning Office, 905 University Avenue, Suite 215. Columbia, Missouri 65201 HISTORIC INVENTORY resent Name(s) 1. No CBD 86-F CBD-5 House (1110 Pennsylvania Avenue) 2. County Jackson 5 Other Name(s) W. A. Seeley Residence 3 Location of Negatives K. C. CBO# Landmarks Commission 28-4 16. Thematic Category 6 Specific Location 28 No of Stories 23 Architecture 29. Basement? ackson Yes IX 1110 Pennsylvania Avenue 17. Date(s) or Period No : 1884 30. Foundation Material City or Town If Aural, Township & Vicinity Kansas City, Missouri 64105 Style or Design Rubble Limestone Queen Anne 31. Wall Construction 8. Site Plan with North Arrow 19. Architect or Engineer Masonry and Wood 32. Roof Type & Material PA AVE 20. Contractor or Builder Cable: Asph. comp 33. No. of Bays Front 3 Side 21. Original Use, if apparent 3 House Single family Residence 34. Wall Treatment 22. Present Use Br. Venover Com. Br. 35. Plan Shape Rectangular Multi-family Residential 23 Ownership Public 1 36 Changes Addition . : Private L Altered Ix (Explain 5 in #42) Moved : 24. Owner's Name & Address. if known Mr. & Mrs. Harold W. Alex 37. Condition Interior ander 11138 Walnut, Kansas City UTM 9 Coordinates Exterior Good Lal. Mo. 64114 Long Yes X 25. Open to Preservation Yes X Public? No Underway? Sile Structure No : Restricted Building | X Object 1: 26. Local Contact Person or Organization 39 Endangered? Yesk By What? 11. On National Yes XX 12 Is It Yes X Landmarks Commission Eligible? No : : Register? No 1 27. Other Surveys in Which Included Future Redevelopment Yes x 13. Part of Estab Yes IXX 14 District Visible from Yes X Hist. Dist ? No 11 Potent'1? No : Public Road? No : . (None) 41. Distance from and 15. Name of Established District 15' Frontage on Road Quality Hill Neighborhood 22.5 Feet along Penn 42. Further Description of Important Features The main facade faces east. The east facade has a single leaf door surmounted by a transom placed in the extreme bay of the first story. Fenestration consists of one-overone light double-hung sash windows placed in rectangular openings. Along the attic level is pedimented gable with paired windows and orgamented with strong classical details. The front porch has been removed. Along the north facade is the 12 story projecting bay beginining at the second story. Exterior facades painted blue. 43. History and Significance The building was erected in 1884 by W. A. Seeley, a localcattle dealer, for his residence. The builging is fine example of the Queen Anne style of Architecture in Kansas City. 44 Description of Environment and Outbuildings The building is located in the "Quality Hill" Neighborhood of the Central Business District in Downtown Kansas City, Missouri. To the north, south, and east are either single family or multifamily residential structures. To the west is a single commercial building. 45 Sources of Information Service Permit No. 3930, Water Department, 5th Floor 46 Prepared by Ed Miszczuk City Hall, 414 E. 12th St. Kansas City, Missouri 64106 47. Organization Hoye's City Directory, Hoye Directory Company, Kansas City, Mo. K. C. Landmarks Comm. 1884-85 43. Date 49 Revision Date(s)

2.77



State Historica Burvey and Planning Office, 905 'niversity Azenue, Suite 215. Columbia, Missouri 65201 JA-AS-005-498 Cit sent Name(s) CBD 36-G use (1114 Pennsylvania Avenue) 2. County Jackson 3 Location of Negatives K. C. James Follans Residence, Thomas I. Moore Residence CBO# Landmarks Commission 6 Specific Location 16. Thematic Category 28 No of Stories 28-5 29. Basement? Architecture Yes IX 1114 Pennsylvania Avenue 17. Date(s) or Period No I 30. Foundation Material 1885 7 City or Town If Rural, Township & Vicinity 18 Style or Design Rubble Limestone Kansas City, Missouri 64105 31. Wall Construction Queen Anne 8. Site Plan with North Arrow 19. Architect or Engineer Masonry and Wood 32. Roof Type & Material PA. AVE. 20 Contractor or Builder Hip& Gable: Asph. Comp 33. No. of Bays Front Side 21 Original Use, if apparent 3 Residence 34. Wall Treatment 22. Present Use Face and Common Brick 35. Plan Snape Rectangular Apartments 23 Ownership Public ! ! 36. Changes Addition :: Private x Altered K (Explain in #42) Moved i 24. Owner's Name & Address, if known Arnold Garfinkle % R. G. 37. Condition R. Associates, 1025 Wyandotte Interior UTM 9 Coordinates St. Kansas City, Mo. 64165 Lal. Exterior Good Long Open to Yes X Preservation Yes X Restricted Public? No : Underway? S.15 Structure No : Building Xi Colect : I Local Contact Person or Organization 39 Endangered? Yas X Landmarks Commission Yes IX By What? Yes X 11 On National 12 Is It No 1: Register? No 12 Eligible? No 27. Other Surveys in Which Included Future Redevelopment 13 Part of Estab Yes IX 14. District Yes x Visible from Yes X Hist. Dist.? No : I Potent'1? No : (None) Public Road? No : : 15. Name of Established District Distance from and Frontage on Road 15' Quality Hill Neighborhood 22½ Feet alongPenn AV 42. Further Description of Important Features The main facade faces east. The east facade is dominated by a single story wood frame porch, with turned posts supporting a shed roof. The fenestration consists of one-overlight double hung sash windows placed in rectangular openings, Cn the east facade, the windows are surmounted by a cut limestone lintels with incised patterns. A gable roofwall dormer is surfaced with half timbering. A two story bay is located in along the north facade. The building was erected in 1885 by James Follans, a local conductor 43. History and Significance for his residence. In 1903 the structure was a boarding under the supervisor of E. Minnie Every. いかいろこ 44. Description of Environment and Outbuildings The building is located in the "Quality Hill" Neighborhood in the Central Business District of Downtown Kansas City, Missouri. to the south is vacant lot. To the north and east are single or multi-family residential structures. To the west are commercial structures. 45 Sources of Information Service Permit No. 4117, Water Department, 5th Floor 46 Prepared by City Hall, 414 E 12th St. Kansas City, Missouri 64106 Ed Miszczak 47. Organization Hoye's City Directory, Hoye Directory Company, Kansas City, Mo. K. C. Landmarks Comm 1885,1903 48. Date 49. Revision Date(s) 2/77



State Historical Survey and Planning Office, 909 University Azenue, Suite 215, Columbia, Missouri 65201 HISTORIC INVENTORY JA-AS-605-499 4. Present Name(s) CBD 86-H Apartment House (1120-1122 Pennsylvania Ave.) 2 County Jackson 5. Other Name(s) Hotel Burlington; Location of Negatives K. C.COD+2 Burlington Hotel Landmarks Commission 16. Thematic Category 5 Specific Location 26. No. of Stories Architecture 29. Basement? Yes X Jackson 1120-1122 Pennsylvania Avenue 17. Date(s) or Period 1890 30. Foundation Material Rubble Limestone 18. Style or Design 7 City or Tewn - If Rural, Township & Vicinity Neo- Classic Revival: 31. Wall Construction Kansas City, Mo. 64105 19 Architect or Engineer Masonry and wood 8. Site Plan with North Arrow 32. Roof Type & Malerial PA. AUE 20. Contractor or Builder Flat; tar & gravel 33. No of Bays Front Side 21. Original Use, if apparent 34. Wall Treatment Multi-family Residential 22. Present Use Brick and Brownstone 35. Flan Shape Rectangular Multifamily Residential 23 Ownership Public 1 36 Changes Addition . : Private X (Explain Altered 1 . in #42) Moved: 24. Owner's Name & Address, if known Ann Catron % Dietrich-37. Condition Davis, 1004 Baltimore Ave., Interior 9 Coordinates Kansas City, Mo. 64105 Exterior · Lal. Good .... Long Yes X 25. Open to Preservation Yes X Public? Restricted No: Underway? No : Sile : Structure Budding K' Object : . 26. Local Contact Person or Organization \$39. Endangered? Yes X By What? No 1: Yes X Landmarks Commission 12 15 11 11 On National Yes 'X No Eligible? Register? No ! ! Other Surveys in Which Included Future Redevelopement Yes x 40 Visible from 13 Part of Estab Yes X 14 District Yes X Potent'1? No Public Road? Hist. Dist ? (None) No :: 41. Distance from and 15. Name of Established District 15" Frontage on Road Quality Hill Neighborhood App. 40 ' along Penni 22 Further Description of Important Features Main facade faces east. The east facade is dominated by double story projecting porch /balcony. Stone stringcoursing visually separates each floor level. Main entrances are appa two run concrete staircase. Fenestration consists of one-over-one light, double-hung sash windows placed in rectangular openings on the primary facade and windows are placed in segmental arched openings. 4) History and Significance The structure was erected in 1890 and orginally as a boarding house under the proprietorship of a Mrs. \_\_\_\_ Merrill. Around 1895, the structure was named the Burlington Hotel. 44. Description of Environment and Outbuildings The structure is located in the "Quality Hill" Neighborhood in the Central Business District of downtown Kansas City, Missouri. To the eastand north are single and multi-family residential structures. To the south across 12th St. is modern grocery store. -5 Sources of Information Service Permit No. 3771, Water Department, 5th Fl. 46 Prepared by City, Hall, 414 E. 12th St. Kansas City, Mo. 64106. Ed Miszczuk Hoye's City Directory, City Directory Co. Kansas City, Mo. Years-47. Organization K. C. Landmacks Commission 1890-1901 49. Date 49 Revision Date(s) 4/77



State Historical Survey and Planning Office, 909 University Avenue, Suite 215, Columbia, Missouri 65201


| HIS  |  | CAN INCIDENT STREET, S | JA-AS-005-500  | -           |
|--|--|--|--|-------------|
| 1. 184-B <sub>CBD</sub>  | 4. Pre   | sent Name(s)   |  | 104-B       |
| 2 County   | Hou  | ise (1207 Pennsylvania Avenue)   |  | 100         |
| Jackson  | 5. Oth   | ner Name(s)  |  | CB          |
| 3 Location of Negatives  | T  | lia Conklin Residence; Roland R. Co  | phlip Pogidanos  | CBD-60      |
| Landmarks Commiss  | THE PERSON NAMED IN COLUMN TWO IS NOT THE OWNER. | 16. Thematic Category  | The state of the s | -           |
| 6 Specific Location  | 28-6   | Architecture   | 28. No. of Stories 21.   | L           |
| 1207 Pennsylvania  | a Avenue   | 17 Date(s) or Period .   | No i   | acl         |
|  |  | 1882   | 30. Foundation Material  | kson        |
| 7 City or Town If Rural, Township & Vicinity   |  | 18 Style or Design   | Rubble Limestone   |             |
| Kansas City, Missouri 64105  |  | Queen Anne   | 31, Wall Construction  | i e         |
| 8. Site Plan with North Ar   |  | 19. Architect or Engineer  | Masonry and Wood  32. Roof Type & Material   |             |
| PA. AVE  | Z  | 20. Contractor or Builder  | Gable; Asph. Comp.   | 1           |
| TH. AUC  |  |  | 33. No. of Bays  | 1           |
|  |  | 21. Original Use, if apparent  | Front 3 Side 2   | =           |
|  |  | Single Family Residence  | 34. Wall Treatment   | STU         |
|  |  | 22. Present Use Residential  | Br. Ven. over Com. Br<br>35. Plan Shape Lrshape  | - P         |
|  |  | 23 Ownership Public ! 1  | 36. Changes Addition .:  | 15          |
| 7  |  | Private k  | (Explain Altered I   | 07          |
|  |  | 24. Owner's Name & Address,  | in #42) Moved i.   | P           |
|  |  | if known Nick & W. F. Baccala,   | 37. Condition<br>Interior  | 明           |
| 5 Occidinatio  | итм  | 3118 Karnes Blvd. Kansas City,<br>Missouri 64111   | Exterior Excellent   | sy.         |
| Lat.<br>Long   |  | 25 Open to Yes X   | #38 Preservation YesX  | 45          |
| 10. Site ! .   | Structure I                                      | Public? Restricted No:   | Underway? No:  |             |
| Building Ix  | Object   | 26. Local Contact Person or Organization   | 39. Endangered? Yes X  | P           |
| II. On National Yes X  | 12 Is II Yes X                                   | K. C. Landmarks Commission   | By What? No 1:   | 17          |
| Register? No D   | Eligible? No 1.3                                 | 27. Other Surveys in Which Included  | Future Redevelopment   | H           |
| Hist. Dist.? No  | 14 District Yes X<br>Potent'l? No:               | (None)   | 40. Visible from Yes X Public Road? No 1:  | 2           |
| 15. Name of Established C  | District   |  | 41. Distance from and  | nin.        |
| Quality Hill Neig  | hborhood   |  | Frontage on Road 25'<br>25' along Penn. St.  | Trza:       |
| )  |  |  |  | 3           |
|  |  | e main facade faces west. The west<br>tory, shed roof, word frame porch. T   |  |             |
|  |  | ver-one light double hung sash win   |  | E           |
|  |  | penings. The attic gable of the we   |  | 10          |
| facade is surface  | ed with wood vert                                | ical clapboard.  |  | 3           |
|  |  |  |  | Conk Lin Re |
|  |  |  |  |             |
|  | m  | 1000 h. D. B. M.M.   | <u>.</u>   | 37          |
|  |  | was erected in 1882 by D. B. McMec'<br>was Julia Conklin and her two son   |  |             |
| Conklin was seco   | retary of the Far                                | m & Investment Co. And Roland Conk   | lin was co-pertner of the  | jed         |
| The prominent lo   | ocal investment f                                | irm of Jarvis & Conklin.   | parener or the   | 3175        |
|  |  |  |  | 16          |
|  | 1000   |  | 0 1:- 2:-  | 1           |
| 44. Description of Environment   |  | The Structure is located in the "of downtown Kansas City, Missouri.  |  | 7           |
|  |  | or multi-family residential structu  |  | 200         |
| Last and west all  | c erenet single c                                | - marer rampy resident services  |  | TUT         |
| 5 Sources of tolermation   | Caruina Parmit                                   | No. 2496, Water Department, 5th Fl   | 46. Prepared by  |             |
|  |  | is City, Missouri 64106.   | Ed Miszczuk  | 10          |
|  |  | Directory Co., Kansas City, Years  | 47 Organization K. C.  | 7           |
| and the second s |  |  |  | - ST        |

Landmarks Commission

45. Date 49 Revision Date(s)

Hoye's City Directory, Hoye City Directory Co., Kansas City, Years

1882-1890



35 Sources of Information Service Permit No. 4972, Water Department, 5th Fl.

Hoye's City Directory, Hoye City Directory Co. Kansas City, Years

City Hall 414 E. 12th St. Kansas City, Missouri 64106

46 Prepared by

43. Date

4/77

47. OrganizationC.

Ed Miszczuk

Landmarks Commission

49. Revision Date(s)

CENT

1. No.

Lal.

Long


1905-6.




|   |   |  | ibla, Missouri 65201                                 |  |
|---|---|--|--|--|
|   | 200   | Training of the Control of the Contr | 1A-AS-005-502  | -  |
| 104-D CBD   |   | ent Name(s)  |  | СВД  |
| 2 County Hou.   |   | e (1213 Pennsylvania Avenue)   |  |  |
| 3 Location of Negatives F   | C. C. D.  | M. McMechan Residence  |  | -62  |
| Landmarks Commis  | 28-8  | 16. Thematic Category  | 28. No of Stories 23                                 | 2  |
|   |   | Architecture   | 29. Basement? Yes!X                                  | 3.   |
| 1213 Pennsylvania Avenue  |   | 17. Date(s) or Period  | No i .   | icksc  |
| 7 City or Town H. Rural, Township & Vicinity<br>Kansas City, Missouri 64105 |   | 18 Style or Design<br>Queen Anne   | Rubble Limestone 31. Wall Construction               | T) T   |
| 6. Site Plan with North Ar  | row   | 19. Architect or Engineer  | Masonry and Wood                                     | and a  |
| PA. AVI   | ₹.  | 20. Contractor or Builder  | 32. Roof Type & Material Gable: Asph. Comp.          |  |
|   |   | 21. Original Use, if apparent  | 33. No. of Bays<br>Front 2 Side 2                    | H  |
| ا لم  |   | Single Family Residence  | 34. Wall Treatment                                   | Sno  |
|   |   | 22 Present Use Multi-Family  | Br. Ven. Over Com. Br                                | H  |
|   |   | Residential 23 Ownership Public !  | 36. Changes Addition:                                | (12  |
| 1_  |   | Private IX  24. Owner's Name & Address,  | (Explain Altered I in #42) Moved I                   | 13 P   |
|   |   | if known Henry & WilmaDembrosky  | 37. Condition<br>Interior                            | enn  |
| Coordinates Lat.  | UTM ,   | & Myrtle N Schleen, 10418 Lee<br>Blvd. Shawnee Mission, Ks. 6620   |  | syl  |
| Long  |   | 25. Open to Yes 🖔  | 38 Preservation Yes X                                | ולא  |
| 0. Site<br>Building X   | Structure<br>Coject   | Public? Restricted No:   | Underway? No :                                       | lia  |
| 11. On National Yes :X  | 12 Is It Yes X<br>Eligible? No !  | 26. Local Contact Person or Organization Landmarks Commission  27. Other Surveys in Which Included   |  | Aver   |
| Register? No !!  3. Part of Estab. Yes M Hist. Dist ? No !!                 | 14. District Yes X Potent'l? No   | (None)   | 40. Visible from Yes!X Public Road? No !:            | nue)   |
| 15. Name of Established D   |   |  | 41. Distance from and                                | TE E   |
| Quality Hill Neighborhood   |   |  | Frontage on Road 25'                                 | SECTION AND ADDRESS OF THE PERSON AND ADDRES |
|   | THE RESERVE TO SHARE THE PARTY OF THE PARTY | e main facade faces west. The west   | T arong remit and                                    | 1  |
| facade is domin<br>porch. The porc<br>contains a thre-<br>gable is a sing   | ated by a L-shape<br>h shelters an enc<br>e window, semi-he<br>le attic window.T  | single story, shed roof wood frame losed main entrance. The second storangonal bay. Within the pedimented he fenestration consists of one-overlaced in rectangual openings.  | ry   | D. M. McMechan   |
| Stove Co., to se  | erve as his resid   | was erected in 1883 by D. M. McMech.<br>ence.  | an, manager of the Cash                              | n Residence  |
|   | Business District   | The structure is located in the "Quof downto-m Kansas City, Missouri. residential structures.  |  | A CONTRACTOR   |
| Sources of Information Service Permit                                       |   | No. 2899, Water Department, 5th Fl<br>s City, Missouri 64106   | 48 Prepared by<br>Ed Miszczuk                        | Territor.  |
|   |   | Directory Co. Kansas City, Mo.,  | 47. Organization K. C.                               | 7  |
| Years 1883-18   |   |  | Landmarks Commission  48. Date   49 Revision Date(s) | 1  |
|   |   |  | 4/77   | 7  |




|  | ey and Planning Office, 900 Universi  | ty Azenue, Suite 215,<br>umbia, Missouri 65201      |
|--|---|---|
| HISTORIC IN  | Marie Control of the | JA-AS-005-503                                       |
| 103-S CBD .  | resent Name(s)  | atown.  |
| 2 County Landson   | ouse (1216 Pennsylvania Ave.)   | and C   |
| 3 Location of Negatives K. C.  | Other Name(s)   |   |
| Landmarks Commission (AO# T  | . A. Griffith Residence William B. k  | night Residence                                     |
| 6 Specific Location 28-9   | 16. Thematic Category   | 28 No of Stories 2                                  |
| 1216 Pennsylvania Ave.   | Architecture 17. Date(s) or Period  | 29. Basement? Yes x                                 |
|  | 1884  | 30. Foundation Material                             |
| 7. City or Town If Rural, Township & Vicini  | ty 18. Style or Design Italianate   | Rubble Limestone 531. Wall Construction             |
| Kansas City, Missouri 64105  | 19 Architect or Engineer  | Masonry and Wood                                    |
|  |   | 32. Roof Type & Malerial                            |
|  | 20. Contractor or Builder   | Flat: Prepared Roll 5                               |
|  | 21. Original Use, if apparent   | Front 3 Side 3                                      |
|  | Residence   | 34. Wall Treatment                                  |
|  | 22. Present Use   | Br. Ven over Com. Br.                               |
| Z  | Unoccupied 23 Ownership Public !:   | 35. Plan Shape Rectangular 36. Changes Addition 12. |
|  | Private   X   | (Explain Altered I                                  |
| PA. AVE.   | 24. Owner's Name & Address,   | in #42) Moved :                                     |
| DTV  | if known Edith Asher Frapasella<br>830 N. E. 46th Terr. Kansas  | 37. Condition                                       |
| 9 Coordinates UTM Lat.   | City, Missouri 64116  | Exterior Excellent                                  |
| Long.  | 25. Open to Yes Public? No 🔀  | 38. Preservation Yes x                              |
| 10. Site : Structure : Building ix Object :  |   | 39. Endangered? Yes x                               |
| 11. On National Yes IX 12 Is It Yes  | X Landmarks Commission  | By What? No I:                                      |
| Register? No L! Eligible? No L! Straight Part of Estab Yesty 14 District Yes   | 27. Other Surveys in Winds included   | Future Redevelopment                                |
| Hist. Dist.? No !! 14. District Yes Potent'l? No !   |   | 40. Visible from Yes X. Public Road? No : :         |
| 15. Name of Established District   |   | 41. Distance from and 151 Frontage on Road          |
| Quality Hill Neighborhood  |   | 21' along Penn. Ave.                                |
| 42. Further Description of Important Features  | Main facade faces east. The east fac  |   |
|  | o stories in height. The north bay i  |   |
| [ - [  | od frame porch, with a shed roof. Fe  | ne-   |
|  | one light double hung sash windows,<br>nings. The parapet of the east faca  | de fa   |
| contains a projecting box corn   |   | i e   |
|  |   |   |
| 43 History and Supplicance The building  | was erected in 1884 by T. A. Griffi   | the alocal coal dealer                              |
| for his residence. The building  | is an excellent example of local It esidence for William B. Knight, natigineer during the period of 1882-86.  | alianate design. From                               |
| 1888-91, the building was the re   | esidence for William B. Knight, nati  | onally renowned civil                               |
| engineer, who served as city eng   | gineer during the period of 1882-86.  | Knight was co-partner of                            |
| the civil engineering firm of Ki   | night & Bont ecou.  |   |
| 44. Description of Environment and Outbuildings  | The building is located in the "Qu  | ality Hill" Neighborhood                            |
|  | of Downtown Kansas City, Missouri.  | To the north, south,                                |
| east and west are either single  | or multi-family residential structu   | res.  |
| 45 Sources of Information Service Permil   | No. 3601, Water Department, 5th Fl  | . 46 Prepared by                                    |
| City Hall, 414 E. 21th St. Kans  |   | Ed Miszczuk   |
|  | rectory Co. Kansas City, Missouri 18  | 3 4-850 rganization                                 |
| 1884-89.<br>Case, T. S., <u>History of Kansas</u>  | City 1888, pp. 534-36   | 48. Date 49. Revision Date(s)                       |
| the state of the s | 2000, pp. 554-50  | 2/77  |





State Historica' "urvey and Planning Office, 909 "riversity Avenue, Suite 215. Columbia, Missouri 65201 HISTORIC INVENTORY JA-AS-005-505 1. No. 4. Present Name(s) CBD 103-T House (1218 Pennsylvania Avenue) 2. County 5. Other Name(s) Jackson 3 Location of Negatives D.P. Bigger Residence; William H. Moore Residence Landmarks Commission (BOH 16. Thematic Category 6 Specific Location 28. No. of Stories 28-10 ackson Architecture Yes XX 29. Basement? 17. Date(s) or Period 1218 Pennsylvania Avenue No 1880 30. Foundation Material . If Rural, Township & Vicinity 18. Style or Design Rubble Limestone "Builder's Vernacular" 31. Wall Construction Kansas City, Missouri 64105 19. Architect or Engineer 8. Site Plan with North Arrow Masonry and Wood 32. Roof Type & Material 20. Contractor or Builder Hipped; Asph. Comp VENNSYLW ANI 33. No. of Bays Front Side 1218 21. Original Use, if apparent 34. Wall Treatment Single Family Residence Pennsylvania 22. Present Use Br. Ven. over Com. Br 35. Plan Shape Rectangular Unoccupied 36. Changes Addition :: 23 Ownership Public 1! Private XIX (Explain Altered I in #42) Moved i 24. Owner's Name & Address, if known WM. F. & Lena M. Yates 37. Condition %David H. Burgard, 2130 Glendale Interior UTM Coordinates Wichita, Kansas 67218 Excellent Exterior Lat. Long 25. Open to Yes I i Preservation YesXX Public? Unoccupied No XX Underway? No i Structure I 10. Site ! : BuildingXX Object | 1 26. Local Contact Person or Organization 39. Endangered? YesXX By What? No II Yes XX Yes XX 11. On National 12 Is It K.C. Landmarks Commission Eligible? Register? No. 27. Other Surveys in Which Included 13. Part of Estab. Yes KX 14. District Yes XX 40. Visible from YesXX **Public Road?** Hist. Dist.? No Potent'l? No ! No ! ! (none) 41. Distance from and 15. Name of Established District 25' Frontage on Road Quality Hill Neighborhood 20' along Penn. St. 42. Further Description of Important Features Main facade faces east. The east facade is dominated by a single story wood frame porch, sheltered the main entrance. The porch ajoins the semi-hexagonal bay. The fenestration consists of one-over-one light double hung sash windows placed Photo in segmental arched openings. The windows are crowned by stone keystones. Secondary facades have segmental arched windows. Main entrance door is surmounted by a transom. 43. History and Significance The structure was erected in 1880 by D.P. Bigger, a local physician, for his residence. In 1887, the building became the home of William H. Moore, co-partner of the firm of Champlain, Moore & Co. 44. Description of Environment and Outbuildings The structure is located in the "Quality Hill" Neighborhood of Central Business District in downtown Kansas City, Missouri. To the north, south, east and west are single and multifamily residential structures, to the immediate south is a small cinder block structure. 45 Sources of Information 46. Prepared by Service Permit No. 1527 Water Department, 5th Fl., City Hall, 414 E. Ed Miszczuk 12th St., Kansas City, Missouri 64106. 47. Organization Hoye's City Directory, Hoye City Directory Co., Kansas City. Landmarks Commission 48. Date Years 1880-1890. 49. Revision Date(s) 4/77



State Historic Survey and Planning Office, 9 University Azenue, Suite 215. Columbia, Missouri 65201 ORIC INVENT JA-AS-005-504 Present, Name(s) 1 No CBD 104-F House (1219 Pennsylvania Avenue) 2 County Jackson Other Name(s) 3 Location of Negatives K. C. Landmarks Commission (BD# J. J. Maloney Residence 6 Specific Location 16. Thematic Category 28 No of Stories Architecture 29. Basement? Yes x 1219 Pennsylvania Avenue Date(s) or Period No i . 1882 30. Foundation Material 7. City or Town If Rural, Township & Vicinity 18. Style or Design Rubble Limestone Kansas City, Missouri 64105 "Builder's Vernacular" 31. Wall Construction 8. Site Plan with North Arrow 19. Architect or Engineer Masonry and Wood 32. Roof Type & Material 20. Contractor or Builder Truncated Hin: P.R 33. No. of Bays Front 21. Original Use, if apparent Side Single Family Residence 34. Wall Treatment 22 Present Use Br. Ven. over Com. Br. Residential 35. Plan Shape L-shape 23 Ownership Public ! 36. Changes Addition : : Private 1x (Explain Altered I in #42) 24. Owner's Name & Address, Moved i if known Tek, Inc., 5316 Oak St. 37. Condition Interior Kansas City, Missouri 64112 9 Coordinates UTM Lat. Exterior Excellent Long 25. Open to Yes X 38 Preservation Yes X Public? Restricted No : Underway? Site . Structure No : Sudding is Coject .. 26. Local Contact Person or Organization 39. Endangered? Yes IX Yes XX Landmarks Commission By What? 11. On National Yes X No 1: Register? Eligible? Noil No 27. Other Surveys in Which Included Future Redevelopment 13. Part of Estab Yes KX District Yes X 40. Visible from Yes !X Hist. Dist.? No 1 Potent'1? No : (None) Public Road? No !! 15. Name of Established District 41. Distance from and Frontage on Road 251 Quality Hill Neighborhood 25' along Penn. St. 42. Further Description of Important Features Main facade faces west. The west facade is dominated by a two story, semi-hexangonal bay. The first story of the west facade has a single leaf main entrance sheltered by a shed roof, cinder blockporch. The fenestration consists of oneover-one light, double hung sash windows placed in segmental arched openings. The west facade windows are crowned by stone keystones. The attic level has gable roof dormers. 43. History and Significance The structure was ercted in 1882 by Robert Anderson, a conductor for the Metropolitan Streetcar Railway System, for spectulation. The earliest known resident was J. J. Maloney. 44 Description of Environment and Outbuildings The structure is located in the "Quality Hill" Neighborhood in the Central Business District, of do ntown Kansas City, Missouri. To the north, south, and west are single and multi-family residential structures. 45 Sources of Information Service Permit No. 2296, Water Department, 5th Fl. 45. Prepared by City Hall, 414 E. 12th St., Kansas City, Missouri 64106 Ed Miszczuk Hoye's City Directory, Hoye City Directory Co. Kamas City. Years 47. Organization K. C.

Landmarks Commission

49 Revision Date(s)

48. Date

4/77

1882-1888



4/77




State Historica, Survey and Planning Office, 90. niversity Azenue, Suite 215, Columbia, Missouri 65201 HISTORIC INVENTORY JA-AS-005-508 4. Present Name(s) 1 100 CBD 103-V CUD House (1222 Pennsylvania Ave.) 2 County Jackson 5 Other Name(s) 70 K. C T. A. Griffith Residence 3 Location of Negatives Landmarks Commission CBD# 4 28. No of Stories 16. Thematic Calegory 25 6 Specific Location Architecture 29. Basement? Yes X Jackson 17 Date(s) or Period 1222 Pennsylvania Avenue 30. Foundation Material 1887-1888 Rubble Limestone 18 Style or Design Il Rural, Township & Vicinity 7 City or Town 31. Wall Construction Kansas City, Missouri 64105 Queen Anne 19 Architect or Engineer Masonty and Wood B. Site Plan with North Arrow 32. Roof Type & Material ZK PA. ALE 20. Contractor or Builder Gable; Asph. Comp. 33. No. of Bays Side Front 21. Original Use, if apparent 34. Wall Treatment Single Family Residence 22. Prasent Use Br. Ven. over Com 35. Plan Shape Rectangular Residential 23 Ownership Public IX 36. Changes Addition : 222 Private I I Altered I (Explain in #42) Moved i 24 Owner's Name & Address, if known Shirley Shaw, 3505 King 37. Condition Interior Highway, Kansas City, Mo. 64137 UTM 9 Coordinates Exterior Excellent Lai. Long 25. Open to Yes X 38. Preservation Yes X No : Underway? Public? No : Restricted Structure :3 Sile Local Contact Person or Organization 39. Endangered? Object . Yes : Building X By What? No 1: Landmarks Commission Yes X Yes X 12 Is It 11 On National Eligible? Future Redevelop No 27. Other Surveys in Which Included No :: Register? Yes X 40. Visible from Yes X Yes X District 13 Part of Estab Public Road? No (None) No 1: Potent'i? Hist. Dist.? 41. Distance from and 15. Name of Established District Frontage on Road 20' Quality Hill Neighborhood 25' along Penn. St. 42. Further Description of Important Features Main facade faces east. The east facade is dominated by a two story, projecting bay. The south bay is dominated by a single story wood, frame porch with a shed roof . Fenestration consists of one-over-one light double hung sash windows placed in rectangular openings on the east, the windows on the second ary facades are placed in segemental arched openings. The attic level contains a pedimental gable ornamented with dentils. 43 History and Significance The residence was erected in 1887-1888 by T. A. Griffith a coal merchant, to serve as his residence. 44 Description of Environment and Gulbuildings The structure is located in the "Quality Hill" Neighborhood in the Central Business District in Downtown Kansas City, Missouri. To the north, south, east and west are single and multi-family residential structures. 45 Sources of Information Service Permit No. 7115, Water Department, 5th Fl. 46 Prepared by Ed Miszczuk City Hall, 414 E. 12th St., Kansas City, No. 64106. 47. Organization K. C. Kansas City Journal, January 1, 1888 p.5 Landmarks Commission 49 Revision Date(5) 48. Date

4/77



State Historica Jurvey and Planning Office, 909 hiversity Avenue, Suite 215, Columbia, Missouri 65201 HISTORIC INVENTORY TA-AS-005-509 1 No 103-W 4. Present Name(s) Double Townhouse (1224-1226 Pennsylvania Avenue 2 County CBD-71 5 Other Name(s) Double Townhouse (1224-1226 Pennsylvania Avenue) Pennsylvania Hotel 3 Location of Negatives K. C. CBD Landmarks Commission 16. Thematic Category 6 Specific Location 25 28 No of Stories Architecture 29. Basement? Yes X Jacks 1224-1226 Pennsylvania Avenue 17 Date(s) or Period No L. 1886-1887 30 Foundation Material Rubble Limestone 18 Style or Design If Rural, Township & Vicinity Kansas City, Missouri 64105 Chateauesque 31. Wall Construction 8. Site Plan with North Arrow 19. Architect or Engineer Masonry and Wood Henry E. Hill 32. Roof Type & Material DA. AVE 20. Contractor or Builder Hip ; Asph Comp. 33. No of Bays Front Side 21. Original Use, if apparent 34. Wall Treatment Two family Residential 22. Present Use Br. ven, over Com.Br 35. Plan Shape Rectangular Multi-Family Residential Public 😾 Private 🕱 23 Ownership 36 Changes Addition . : (Explain Altered 11 in #42) Moved i 24. Owner's Name & Address, Margaret Goosley, 1224 37. Condition Interior Pennsylvania, Apt. 5, Kansas 9 Coordinates City, Missouri 64105 Exterior Lat Excellent Long 25. Open to Yes X 38 Preservation Yes X Public? No : Underway? Restricted 10 Structure No : 5.18 Building | X Opject 25. Local Contact Person or Organization 39 Endangared? Yes X By What? Landmarks Commission Yes XX Yes X No ! . 11. On National 12 15 11 NOIX Eligible? No Register? 27. Other Surveys in Which Included Future Redevelopment 13 Part of Estab Yes XX 14. District Yes X 40. Visible from Yes k Potent'l? No Hist. Dist.? No ' (None) Public Road? No 1: 41. Distance from and 15. Name of Established District 251 Fightage on Road 25 along Penn. St. Quality Hill Neighborhood 42. Further Description of Important Features The complex is composed of two units The main facade faces east. The east facades contains a central recessed bay containing two single leaf main entrances, sheltered by a hip roof, wood frame porch. The fenestration consists of one-over-one single sash windows, surmounted by transoms placed in crosette-designed stone frames. The attic level contains two gable roof dormers with Chicago 'sash windows. brick chimneys are placed along the north and south facades. 43 History and Significance The structure was erected in 1886-1887 by Rev. Timothy Hill, a local Presbyterian minister, for spectulation. Earliest occupants were L. P. Davis and B. Stone Faul. The design is attributed to Henry E. Hill who was Reverend Hill's son and a prominent architect in Kansas City. In 1901, the structure became the Pennsylvania Hotel. 44 Description of Environment and Outbuildings The structure is located in the "Quality Hill" Neighborhood in the Central Business District in downtown Kansas City, Missouri. To the north, south, east, and west are single and multi-family residential structures. 45 Sources of Information Service Permit No. 5992. Water Department 5th Fl. 48 Prepared by City Hall, 414 E. 12th St. Kansas City, Mo. 64106 Ed Miszczuk Hove's City Directory, Hoye City Directory Co., Kansas City, Years 47. Organization K. C. 1887-1901; Kansas City Journal, January 1, 1837, p.9. Landmarks Commission 43. Date Kansas CityStar, May 21, 1887, p.1. 49. Revision Date(s) 4/77



Kansas City (Missouri) Journal, January 1, 1888 P. 8

1886-89

Hoye's City Directory , Hoye Directory Co. Kansas City, Missouri

47. Organization

2/77

K. C. Landmarks Comm

48. Date 49. Revision Date(s)



State Historica Survey and Planning Office, 90 University Avenue, Suite 215. Columbia, Missouri 65201 INVENT TA-AS-005-511 resent Name(s) I No CBD 104-I House (1225 Pennsylvania Avenue, Rear) 2 County 5. Other Name(s) Jackson 3 Location of Negatives K. C.CBD# Carriage House/ Stables (1225 Pennsylvania Avenue, rear) Landmarks Commission 8 Specific Location 16. Thematic Category 28. No of Stories 11 Architectrue 29. Basement? Yes ! 1225 Pennsylvania Avenue (Rear) 17. Date(s) or Period No L c.1886-1887 30. Foundation Material 7 City or Town Il Aural, Township & Vicinity 18. Style or Design Rubble Limestone Kansas City Missouri 64105 "Builder's Vernacular" 31. Wall Construction 8. Site Plan with North Arrow 19 Architect or Engineer Masonry and Wood 32. Roof Type & Material 20. Contractor or Builder Gable: Asph. Comp 33. No. of Bays Front Side 21. Original Use, if apparent 3 34. Wall Treatment Carriage House/Stables 22. Present Use Br. Ven. over Com. 35. Plan Shape Rectangular Single Family Residential 23 Ownership Public 11 36. Changes Addition : : Private IX Altered IX (Explain in #42) Moved : 24. Owner's Name & Address. if known Edith Asher Frapasella, 37. Condition 830 N. E. 40th Terr. Kansas City Interior 9 Ccordinates UTM Missouri 64116 181 Exterior Fair Long 25. Open to Yes X 38. Preservation Yes X Public? Restricted No: Underway? Site No : Structura Building X Coject ... 26. Local Contact Person or Organization 39. Endangered? Yes X By What? No I: 11. On National Yes IX 12. Is It Yes X Landmarks Commission Register? No I-Eligible? No :! 27. Other Surveys in Which Included Future Redevlopment 13 Part of Estab. Yes IX District Yes X 40. Visible from Yes 'x Hist. Dist.? No ! Potent'1? No: Public Road? No L. (None) 41. Distance from and 15. Name of Established District 100' Frontage on Road Quality Hill Neighborhood app. 30' along Penn. 42. Further Description of Important Features Main facade faces north. The north facade is dominated by a single story shed roof wood frame veranda. The fenestr ation originally consisted of one-over-one light double-hung sash windows placed in segmental arched openings. Some windows of this kind still remain. The remaining windows are double sash windows placed in partially bricked in rectangular openings. The alley entrance has been bricked in and replaced with windows. A gable roof wall dormer addition is placed along the east facade. 43. History and Significance The structure was ercted in about 1886-1887 presumbly by M. B. Behney prominent local contractor and brick manufacturer, for his carriage house and stables. 44. Description of Environment and Outbuildings The structure is located in the "Quality Hill" Neighborhood in the Central Business District of downtown Kansas City Missouri. To the west are single and multi-family residential strucutres. To the east are surface parking lots. -5 Sources of Information Service Permit No. 5919, Water Department, 5th Fl. 46 Prepared by 414 E. 12th St. City Hall, Kansas City, Missouri 64106: Ed Miszczuk Kanaas City (Missouri) Journal, January 1, 1888 p. 8 47. Organization K. C. Landmarks Commission

48. Date

4/77

49 Revision Date(s)



State Historical Survey and Planning Office, 909 University Avenue, Suite 215, Columbia, Missouri 65201 HISTORIC INVENTORY JA-AS-005-512 resent Name(i) 1 No 103-X CED CBD Double Townhouse (1228-1230 Pennsylvania Avenue) 2 County Jackson 5. Other Name(s) 3 Location of Negatives K. C. 73 Double Rental House (1228-1230 Pennsylvania Avenue) Landmarks Commission (BD# 16. Thematic Category Specific Lucation 28 No of Stories 28-14 2 Architecture 29. Basement? Yes x Jackson 1228-1230 Pennsylvania Avenue Date(s) or Period No 1. 1877 30. Foundation Material Style or Design If Rural, Township & Vicinity Rubble Limestone Kansas City, Missouri 64105 Italianate 31. Wall Construction B. Site Plan with North Arrow 19. Architect or Engineer Masonry and Wood 32. Roof Type & Material 20. Contractor or Builder Flat: Prepared Roll 33. No. of Bays Doub Front Side 21. Original Use, if apparent 3 Two family Residential 34. Wall Treatment 22. Present Use Ven 35. Plan Shape Rectangular Two Family Residential 23 Ownership 36 Changes Public Addition Private X (Explain Altered I in #421 Moved i 24. Owner's Name & Address, il known Edward A. & Lucille 37. Condition Roche 619 Romany Rd., Kansas Interior 9 Courdinates UTM City, Miseouri 64113 Lai. Exterior Excellent Long 25. Open to Yes X Preservation Yes X Public? No 11 Underway? No: Site ! Structure : Restricted Object | | Building IX Local Contact Person or Organization 39. Endangered? Yes X Landmarks Commission By What? No I: 11 On National Yes x Yes IX Is It Register? No 13 Eligible? No I 27. Other Surveys in Which Included Future Redevelopment Yes X Historic Building Preservation 40. Visible from 13 Part of Estab Yes IX 14. District Yes X Potent'1? No ! Hist. Dist.? No Ist Public Road? Analysis, Pre. by Land Clearance No 1: 41. Distance from and 15 Name of Established District for Redevelopment, Kansas City, 25' Frontage on Road Quality Hill Neighborhood Missouri, 1973 45' alone Penn 42. Further Description of Important Features Main facade faces east. The complex is Double composed of two units. The central bay is dominated by a single story hip roof porch consisting of brick pedestals supporting wooden posts. The flanking bays on the first story have projecting bays semi-hexangonal bays, with one-over-one light double hung sash windows. The second story have paired windows, one set per bay, which are crowned by pressed stone segmental arched lintels. The parapet is embellished with a classical entablature and central broken pedin 43 History and Significance The structure was erected in 1877 for the Reverend Timothy HillFamily. for speculation and rental property. The structure is an excellent example of local Italianate style architecture in Kansas City, Missouri. Italianate style architecture in Kansas City, Missouri.

A Description of Environment and Outbuildings The structure is located in the "Quality Hill" Neighborhood in the Central Business District in downtown Kansas City, Missouri. To the north, south, in the Central Business District in downtown Kansas City, Missouri. To the north, south, east and west are single and multifamily residential structures. 5 Sources of Information Service Permit No. 457, Water Department 5th Fl., 46. Prepared by City Hall, 414 E. 12th S . Kansas City, Missouri 64106 Ed Miszczuk 47. Organization K. C. Kansas City Journal, May 21, 1887 p. 1. Landmarks Commission Ebenezer Hill: The Little Minister of Mason, M. H. by Charles E. 48. Date 49. Revision Date(s)

4/77

Hill, 1923 p.58-59



State Historic Survey and Planning Office, 909 University Avenue, Suite 215, Columbia, Missouri 65201 HISTORIC INVENTORY JA-AS-005-5/3 'resent Name(s) 1 140 CSD-103-Y Double Townhouse (1232-1234 Pennsylvania Avenue 2 County Jackson 5. Other Name(s) Double Townhouse 1232-1234 Pennsylvania Avenue) Location of Negatives K. C. CBD# 4-Hypatia Flats/Hotel Landmarks Commission 16. Thematic Category 6 Specific Location 28 No of Stories 3 Architecture 29. Basement? Yes X 1232-1234 Pennsylvania Avenue 17 Date(s) or Period 1886-1887 30. Foundation Material Style or Design Rubble Limestone if Rural, Township & Vicinity City of Town Kansas City, Missouri 64105 Chateauesque 31. Wall Construction 8. Site Plan with North Arrow 19. Architect or Engineer Masonry and Wood Henry E. Hill 32. Roof Type & Material 20. Contractor or Builder Gable; Asph. Comp 33. No of Bays Front Side 21. Original Use, if apparent Two Family Residence 34. Wall Treatment 22. Present Use Br. Ven. over Com. 35. Plan Shape Multi- Family Residential Rectangular 23 Ownership 36. Changes Public !! Addition . Private X (Explain Altered ! in #42) Moved: 24. Owner's Name & Address. if known Edward A. Roche; 619 37. Condition Interior UTM 9 Coordinates Romany Rd. Kansas City, Mo. Exterior Excellent lal 64113 Long 25 Open to YasX Preservation Yes X Restricted Public? Underway? 5 . 5 Structure No Bunding X Object 39 Endangered? 26. Local Contact Person or Organization Yes X By Wha!? 11 On National Yes X 12 Is II YesX Landmarks Commission No ! : Eligible? No Register? No is Future Redevelopmen 27. Other Surveys in Which Included Yes X 13 Part of Estab. Yes !X 14. District 40. Visible from Yes X Potent'1? Hist. Dist.? No 1 Public Road? No: (None) 41. Distance from and 15. Name of Established District 25' Frontage on Road Quality Hill Neighborhood 49 along Penny. St 42. Further Description of Important Features The complex is composed of two units. The main facade faces east. The east facade contains two roundarched recessed main entrances placed in the central bay. The fenestration consists of one to multi-light double-hung bash windows, so surmounted by transoms, placed in crossette frames. The attic level contains two types of dormers; gable roofed, wall dormers containing paired double sash windows and conical roofed, partially recessed, roof dermers containing single windows.

43. History and Significance The structure was erected in 1886-1887 by Reverend Timothy Hill, a local Presbyterian minister, for spectulation. The earliest occupants included renowned American architect Henry Van Brunt (1888) and G. K. Davidyan, The design is attributed to Henry E. Hill, who was Reverend Hill's son and a prominent architect in Kansas City, In 1901, the structure was renamed the Hypatia Flats/Hotel. 44 Description of Environment and Outbuildings The structure is located in the "Quality Hill" Neighborhood in the Central Business District in downtown Kansas City, Missouri. To the north east and west are single and multi-family residential structures, to the south is the Swedish Evangelical Lutheran Church. 45 Sources of Information Service Permit No. 5802, Water Department 5th Fl. 46. Prepared by City, Hall, 414 E. 12th St. Kansas City, Missouri 64106 ,Ed Miszczuk 47. Organization Hoye's City Directory, Hoye City Directory Co., Kansas City. Years K. C. 1886-1901; Kansas City Journal, January 1, 1887 p. 9 Landmarks Cormission 48. Date 49. Revision Date(s) Kansas City Star, May 21, 1887 p.1. 4/77

25


1 4 3 3



State Historie Survey and Planning Office, 5 University Azenue, Suite 215, Columbia, Missouri 65201 HISTORIC INVENTORY JA-AS-005-514 sent Name(s) I No CBD -103-Z mmercial Builting 2 County 5 Other Name(s) Jackson 3 Location of Negatives K. C. CBD#4 Swedish Evangelical Lutheran Church Landmarks Commission 6 Specific Location 16. Thematic Category 28 No of Stories Architecture/religion 29. Basement? Yes ix 17 Date(s) or Period No i 1238 Pennsylvania Avenue 30. Foundation Material 1886-88 18 Style or Design Rubble Limestone Il Aural, Township & Vicinity 31. Wall Construction Kansas City, Missouri 64105 High Victorian Gothic (Modified) 19. Architect or Engineer 8 Site Plan with North Arrow Masonry and Steel 32. Roof Type & Material 20. Contractor or Builder Gable; Slate No. of Bays Front Side 21. Original Use, if apparent 34. Wall Treatment Church 22. Present Use Br. Ven. and Cut Ct 35. Plan Shape Rectangular Commerical 36. Changes 23 Ownership Public 1 Addition X Private 1x (Explain Altered X in #42) Moved i 24. Owner's Name & Address, PA. AVE. il known Mr. & Mrs. Edward A. 37. Condition Interior Roche, 619 Romany Rd. Kansas 9 Coordinates Fair Exterior City, Missouri 64113 Lai. Long 25. Open to Yes x Preservation Yes X Public? No : Underway? No : Restricted Structure Building & Object : : 26. Local Contact Person or Organization Endangered? Yes X By What? Yes X Landmarks Commission 11. On National Yes XX 12 Is !! Register? Eligible? No W 27. Other Surveys in Which Included Future Redevelopment 40. Visible from Yes x District 13. Part of Estab Yes XX Yes 'X Public Road? Potent'1? No : Hist. Dist ? No :: (None) 41. Distance from and 15. Name of Established District Frontage on Road Quality Hill Neighborhood 46' along Penn Ave 42. Further Description of Important Features The main facade faces east. The east facade is dominated by a single story brick store front addition. The upper stories of the east facade is dominated by a projecting belfry, altered with the removal of the spire (in1925). Engaged brick buttresses visually and structurally separate the facades in various bays. The fenestration is composed of pointed arched windows with alternating brick and stone voussoirs. The facades are embellished with stone stringcoursing and brick corbelling. Windows are bricked 43 History and Significance The building was erected during the years 1886-88 to serve as the church for the Swedish Evangelical Lutheran congregation, organized in 1870. Significant for being a rare surviving example of the High Victorian Gothic style architecture in Kansas City. The building is reflective of the Swedish community. Originally services were conducted in Swedish. 44. Description of Environment and Outbuildings The building is located in the "Quality Hill" Neighborhood in the Central Business District of Downtown Kansas City, Missouri. To the north, south east and west are single or multi-family residental structures. - KC POST Sept 8, 1928 5 Sources of Information Service Permit No. 5158, Water Department 5th Floor 46 Prepared by City Hall, 414 E. 12th St, Kansas City, Missouri 64106. Ed Miszczuk 47. Organization Building Permit No. 82342, Public Works Department 18th Floor, City K. C. Landmarks Comm. City Hall, 414 E. 12th St. Kansas City, Missouri 64106. History of Kansas City Illustrated, 1888. Ke TIMES 7/12/48.P 11 43. Date 49 Revision Date(s) KAUSAS CITY (History) Journal January 1, 1888. D. 8 2/77



State Historican Survey and Planning Office, 905 niversity Avenue, Suite 215, Columbia, Missouri 65201 HISTORIC INVENTORY JA-AS-005-515 1 10 ent Name(s) 103-- R CBD se (1240 Pennsylvania Ave.) 2 County 5 Other Name(s) Swedish Evangelical Lutheran Parsonage 3 Location of Negatives K. C. CRD #4-Reverend C. J. Hatterus Residence Landmarks Commission Specific Location 16. Thematic Category 28 No of Stories 23 Architecture 29. Basement? Yes x Jack 17 Date(s) or Period 1240 Pennsylvania Avenue No 1886 (Son 30. Foundation Material 18. Style or Design If Aural, Township & Vicinity 7 City or Town Rubble Limestone Kansas City, Missouri 64105 Queen Anne 31. Wall Construction 19 Architect or Engineer 8. Site Plan with North Arrow Masonry and Wood 32. Roof Type & Material 20. Contractor or Builder Gable; ashh. comp. 33. No. of Bays Kreisher Brothers Front Side 21. Original Use, if apparent 34. Wall Treatment Single Family Residence 22. Present Use Br. Ven over Com Br. 35. Plan Shape Rectangular Apartments 23 Ownership Public ! 36. Changes Addition . : Private x (Explain Allered I . in #42) Moved: 24. Owner's Name & Address. il known Joe Hoffman & Harry 37. Condition Interior Hoffman, 1242 Penn. Kansas City 9 Coordinates UTM Lat Exterior Fair Long 25 Open to Yes X Preservation Yes x Public? No i Underway? No i Site : Structure Restricted Building X Object 11 26. Local Contact Person or Organization 39. Endangered? Yes X By What? YesXX Landmarks Commission No ! : It On National 12 15 11 Yes X Eligible? No Register? 27. Other Surveys in Which Included Future Redevelopement Yes X Part of Estab YesXX District Yes X Visible from Potent'1? No : Hist. Dist ? No W Public Road? (None) No : 41. Distance from and 15. Name of Established District Frontage on Road Quality Hill Neighborhood 22' along Penn Ave. 42. Further Description of Important Features Main facade faces east. The east facade Swedish Evange is assymetrical with a recessed north bay dominated by a single story wood frame porch. Fenestration on the primary facade consists of twoover-two light double hung sash windows placed in rectangular openings. Windows on the secondary facades are placed in segmental arched openings. The attic level is a gable with fish scale shingles. Two brick chimneys are located along the south facade. 4) History and Significance The building was erected in 1886 by Reverend C. J. Hatterus, pastor of the the Swedish Evangelical Lutheran Church for his parsonage. The building survives as the only known work done by the Kreisher Brothers. Lutheran 44 Description of Environment and Outbuildings The building is located in the "Quality Hill" Neighborhood in the Central Business District in Downtown Kansas City, Missouri. To the north is the Swedish Evangelical Lutheran Church, to the south, east and west are single and multifamily residential structures. Service Permit No. 5158, Water Department, 5th flogr Prepared by 45 Sources of Information City Hall 414 E. 12th St. Kansas City, Missouri 64106 Ed Miszczuk C. Organization Hove's City Directory, Hoye Directory Company Kansas City, Mo. K. C. Landmarks Comm. 1886-89. 48. Date 49. Revision Date(s)



|   |  | mbia, Missouri 65201   |                             |
|---|--|--|-----------------------------|
| HISTORIC IN                                       | VENTURY 5  | A-AS-005-516   |                             |
| 1 No.   | ent Name(s)  | - South and the second control of the second | E.                          |
| 103-UCBD .  | 0  |  | -                           |
|   | Pennington Cleaners  |  | CBD                         |
| o de troon  | her Name(s)  |  |                             |
| 3 Location of Negatives K. C.                     | Moses Schoonmaker Residence  |  | 80                          |
|   | The state of the s |  | 1                           |
| 6 Specific Location                               | 16 Theinatic Category  | 28 No of Stories 2½  |                             |
| 1242 Pennsylania Avenue                           | Architecture   | 29. Basement? Yes X  | Ja                          |
| 1242 Tehnsylania Avenue                           | 1886; additions 1938, 1945   | 30. Foundation Material  | 5                           |
| 7 City or Town If Rural, Township & Vicinity      |  | Rubble Limestone   | 105                         |
| Kansas City, Missouri 64105                       | Queen Anne (Modified)  | 31. Wall Construction  | 1                           |
|   | 19. Architect or Engineer  | Masonry and Wood   | 1                           |
|   | Halsey B. Prudden (attrib)   | 32. Roof Type & Material   |                             |
| 14  | 20. Contractor or Builder  | Hip: asph. comp.   |                             |
| <u> </u>  |  | 33. No. of Bays  |                             |
| Z   | 21. Original Use, if apparent  | Front 3 Side 4   | 3                           |
| 2   | Residence  | 34. Wall Treatment   | cni                         |
| PENNSYLUANIA                                      | 22. Present Use  | Br. Ven. over Com. B   | 44                          |
|   | Cleaners and Laundry   | 35. Plan Snape Rectangular   | 31                          |
| 2   | 23 Ownership Public I !  | 36 Changes Addition X  | 10                          |
|   | Private 1x   | (Explain Altered k   | 10                          |
| <u>K</u>  | if known Joe Hoffman & Harry   | 37. Condition  | 10                          |
| 9 Coordinates UTM                                 | Hoffman, 1242 Penn. Ave., Kansa  |  | in in                       |
| 9 Coordinates UTM Lat.                            | City, 64105  | Extenor Fair   |                             |
| Long  | 25. Open to Yes X  | 38. Preservation Yes X   | 3                           |
| 16 Site : Structure                               | Public? Restricted No!   | Underway? No:  | THE PARTY OF                |
| Building 1/2 Object                               | 26. Local Contact Person or Organization   | 39. Endangered? Yes X  |                             |
| 11. On National YesXX 12 Is It Yes X              | Landmarks Commission   | By What? No I:   |                             |
| Register? No !! Eligible? No                      | 27. Other Surveys in Which Included  | Future Rei velopennt   |                             |
| 13 Part of Estab Yes XX 14 District Yes X         |  | 40. Visible from Yes X   |                             |
| Hist. Dist.? No ? Potent'l? No :                  | (None)   | Public Road? No 11   |                             |
| 15. Name of Established District                  |  | 41. Distance from and 81   |                             |
| Quality Hill Neighborhood                         |  | 21' along Penn. Ave.   | 7                           |
| 13 Further Description of Important Factures. The | The cost   | T drong renn. Ave.   | -                           |
| 42. Further Description of Important Features. Th |  |  | 1                           |
|   | story brick addition with a central windows. The second story contains   |  | 5                           |
|   | in the south bay and within the nor  |  | 0.0                         |
|   | oriel bay capped by a conical. root  | e i  | ics .                       |
|   | y placed along the facade. The fene  |  | Sc                          |
|   | one light double hung sash windows   |  | 300                         |
| placed in segmental arched openin                 |  |  | C C                         |
|   | as erected in 1886. The earliest re-   | sident in the structure !  | Spr                         |
|   | r in the prominent local firm of Bro   | own, Schoonmaker & Co.,  | 6                           |
| which specialized in real es                      | tate investment & loans. The building  | ng is rare surviving   | 7                           |
| work of the local architect, Hal                  | sey B. Prudden.  |  | So                          |
|   |  |  | 10                          |
| 14 5  |  |  | Moses Schoophaker Residence |
|   | The building is located in the "Qua  |  | 95                          |
|   | of Downtown Kansas City, Missouri.   |  |                             |
| are residential structures. To the                | e immediate south and east are vacar   | nt lots.   |                             |
|   |  |  |                             |
|   | No. 5105, Water Department, 5th F1.  |  |                             |
| City Hall, 414 E. 12th St. Kansas                 | City, Missouri 64106.  | Ed Miszczuk  |                             |
| Hoye's City Directory, Hoye Directory             | tory Co., Kansas City, Mo. 1886-88   | 47. Organization   |                             |
| Building Permits Nos. 5514-A, 181                 | 18-A, Public Works Department, 18th  | 48 Date 49 Revision Date(s)  |                             |
| Floor, City Hall, 414 E. 12th St                  |  | 46. Date 45 Hevision Date(s)   | 1                           |
|   |  | 2/77   |                             |



State Historica Survey and Planning Office, 90° University Avenue, Suite 215, Columbia, Missouri 65201 INVENTORY -AS-005-517 Present Name(s) No. CBD 118-B The Electric Association of Missouri & Kansas CISD 2 County Jackson Other Name(s) 3 Location of Negatives K. C. 83 Landmarks Commission #4-1 John G. Conkey Residence Caroline E. Reeder Residence 6 Specific Location 16. Thematic Category 28 No of Stories 23 Architecture 29. Basement? Jackson Yes X 1308 Pennsylvania Avenue 17 Date(s) or Period No i 1886 30. Foundation Material If Rural, Township & Vicinity 18 Style or Design Rubble Limestone Queen Anne Kansas City, Missouri 64105 31. Wall Construction 8 Site Plan with North Arrow 19. Architect or Engineer Maaonry and Wood ' AU 32. Roof Type & Material 20. Contractor or Builder Gable; Asph. Comp 33. No of Bays PENNSYLVANIA Front Side The 21. Original Use, if apparent Residence 34. Wall Treatment 22. Present Use Ven. Office Building 35. Plan Shape Rectangular 23 Ownership Public 11 36. Changes Addition : : Private 1x (Explain Altered IX in #42) Moved : 24. Owner's Name & Address, Association if known The Electrician Associa- 37. Condition Interior tion of Missouri & Kansas, 1308 9 Ccordinates UTM Pennsylvania Ave. KCMo. 64105 Exterior Lat Good Long Open to Yes X Preservation Yes X Public? Underway? Site Structure Restricted No : Building X Object . 26. Local Contact Person or Organization 39 Endangered? Yes i Landmarks Commission By What? Yes XX Yes X No X 11. On National 12 Is It Register? No 12 Eligible? No 27. Other Surveys in Which Included 13 Part of Estab Yes XX District Yes X Visible from Yes X Potent'l? Hist. Dist ? No No : Public Road? (None) No : : Distance from and 15. Name of Established District 20' Frontage on Road Quality Hill Neighborhood 30' along Penn. Ave. 42 Further Description of Important Features The Main facade faces east. The east John facade is dominated by a single story veranda composed of brick pier supporting a shed roof. The fenestration of the facades consists of one-over-one light double hung sash windows placed in rectangular EL aronkey openings. The north facade is dominated by a two story semi-hexagonal bay with a central chimney. Chimneys have upper portions removed. Attic level contains paired windows flanked by brick corbeling. 43. History and Significance The building was erected in 1886 by John G. Conkey, prominent local Residence dry goods merchant, for this residence. In 1903 the building became a boarding house under John Siemon. The building is fine example of local residential design in Kansas City. 44. Description of Environment and Outbuildings The building is located in the "Quality Hill" Neighborhood in the Centrel Business District in Downtown Kansas City, Missouri. The structure is isolated by vacant lots and portions of I-70. To the east are Multi-family structures. 5 Sources of information Pen and Sunlight Sketches of Kansas City and Envir-46 Prepared by ons, 1892, p. 184 Ed Miszczuk 47. Organization Hoye's City Directory, Hoye Directory Co. Kansas City, Mo. Years

K. C. Landmarks Comn.

49 Ravision Date(s)

48. Date

2/77



| HIST   | ORIC IN                  | VENTORY   | A-AS-005-518                                |
|--|--------------------------|---|---|
| No 34-C  | 4 Pres                   | Technographic Computer Services   |   |
| Jackson toration of Negatives CB                 | D #58-5                  | er Namo(s)  |   |
| Landmarks Commi                                  | ssion                    | 16 Thematic Category  | 28. No of Stories 2                         |
| Specific Location                                |                          | To Thematic Category  | 29. Basement? Yes : 1                       |
| 718 Troost                                       |                          | 17 Date(s) or Period<br>1983  | No 30. Foundation Material                  |
|  | . Township & Vicinity    | 18 Style or Design  |   |
| Kansas City, Mo.                                 |                          | 19. Architect or Engineer   | 31. Wall Construction concrete T's          |
|  |                          | John Hueser Assoc.  | 32. Roof Type & Material                    |
|  | NI                       | 20 Contractor or Builder  | flat, tar and gravel                        |
| Г  | 1                        | A. L. Huber & Son  21. Original Use, if apparent  | 33. No. of Bays Front Side                  |
|  | 158                      | commercial  | 34. Wall Treatment                          |
|  | FOOST                    | 22 Present Use  | precast concrete                            |
|  |                          | commercial  | 35. Plan Shape rectangular                  |
|  |                          | 23 Ownership Public   Private   | 36. Changes Addition .<br>(Explain Altered) |
|  |                          | 24. Owner's Name & Address,   | in #42) Moved i                             |
|  |                          | if known  | 37. Condition                               |
|  | TM                       | English and the second  | Exterior excellent                          |
| Lung   |                          | 25 Open to Yes txl  | 38. Preservation Yes                        |
| Site<br>Building X                               | Structure 1 - Object 1 1 | Public? No I I  | Underway? No XX                             |
| On National Yes                                  | 12 is it Yes ! !         | 26 Local Contact Person or Organization Landmarks Commission                              | 39. Endangered? Yes 11 By What? NoXX        |
| Register® No.X                                   | Eligible? No 80          | 27. Other Surveys in Which Included   | 40 Visible from YesXX                       |
| HIST DIST? NO X Potent'I? No K                   |                          |   | Public Road? No                             |
| Name of Established Di                           | sterc1                   |   | 41. Distance from and<br>Frontage on Road   |
| 2 Further Description of h<br>ior walls are of p |                          | is building faces east. The exter T's.  | Photo                                       |
| History and Significance<br>similar in style     |                          | ouilding in a growing industrial and to the south.  | rea. The building is                        |
| area is in front                                 | of it, to the ea         | The building sits back from the stast. Other commercial buildings a interstate connector. |   |
| Sources of Information                           | Las de la company        |   | 46. Prepared by                             |
| WP #148172<br>BP #1126A                          |                          |   | Piland                                      |
|  |                          |   | 47. Organization<br>Landmarks Commission    |
|  |                          |   | 48. Date 49 Revision Date(s)                |
|  |                          |   | 7/13/84                                     |



INVENTORY JA-AS-605-519 4 Present Name(s) No 53-C 53-C County St Clair Apartment/Hotel 160 5 Other Name's) Jackson Lu ation of Negatives CBD #25-10 Landmarks Commission 16 Thematic Category 26 No of Stories Specific Location 29. Basement? Jackson Date(s) or Period No 814 Troost partial 1927 30. Foundation Material If Rural, Township & Vicinity 18 Style or Dusign stone 7 City or Town Italianate elements Kansas City, Missouri 31. Wall Construction I Site Plan with North Arrow 19 Architect or Engineer masonry William J. Koch 32. Roof Type & Material flat: comp. & gravel Harry Goldberg Construction Co 33. No. of Bays Front 3 Side 18 00 21. Original Use, if apparent Present 14 010 34 Wall Treatment apartment/hotel 0/6 Troost 22 Present Use brick & stone 35 Plan Shaper Nemela apartments 36. Changes 23 Ownership Public 1 4 Addition Private 44 (Explain Altered i m 842) Moved . 24. Owner's Name & Address. Other 9TH 5T. of known 37 Condition 40 30 Interior UTM Currdinales Exterior Lat fair Lung 25 Open to Yes !! 38. Preservation Yes . Public? No ki Underway? No ix Structure L. Site Building X Object I i 26 Local Contact Person or Organization 39 Endangered? Yes II By What? Yes XI No IX 1 On National 12 15 11 Yes . Landmarks Commission Reuister? No X Eligible? No 11 27 Other Surveys in Which Included Yes X Part of Estab Yes 14 District Visible from Yes . X Potent'1? MIST DIST ? No X Public Road? No : : 41 Distance from and 5 Name of Established District Frontage on Road 39 feet on Troost Further Description of Important Features Varigated brick with dark brown brick window surrounds decorate the east facade. The central doorway 0170 has 2 side lights. The windows of the east facade are placed in triplicate arrangement. Stone quoining marks the corners and a simple string course band is placed near the top. Missory and Seguificance The contractor, Harry Goldberg, was also owner of this apartment building. Description of Environment and Outbuildings Vacant lots are to the north, south, and east of this building. To the west/is a church. Sources of Information 46. Prepared by Helmer WP #141 Western Contractor March 9, 1927, p. 38 47. Organization Landmarks Commission 48. Date 49 Revision Dele(s)

10/22/80

Office of Historic Preservation, P.O. Box 176, Jefferson City, Missouri 65101



Office of Historic Preservation, P.O. Box 176, Jefferson City, Missouri 65101 HISTORIC INVENTORY JA-AS-005-520 4 Present Name(s) No 69-E J. M. & W. Company; F. P. Williams & Assoc. 69-2 County Other Name's) Jackson rest 3 Lucation of Negatives CBD 40-10 entered J. Q. Moffat Livery; Portland Livery Co. Landmarks Commission 16 Themalic Calegory 28 No of Stories 6 Specific Location Jackson 29. Basement? Yes II NOXX 17 Date(s) or Period 912 Troost 1903 30. Foundation Material Il Rural, Township & Vicinity 18 Style or Design 7 City or Town 31. Wall Construction Kansas City, Missouri & Site Plan with North Arrow 19 Architect or Engineer masonry 32. Roof Type & Material 9TH 5T. 20 Contractor or Builder flat; tar & gravel 33. No. of Bays M. E. Tomlinson 912 Front Side 21. Original Use, if apparent livery stable 34 Wall Treatment ROOS. 22 Present Use 35. Pian Shape black commercial rectangular 36 Changes Public I ! 23 Ownership Addition Attered XX (Explain m 842) Moved 24. Owner's Name & Address. of known 37 Condition Interior Coordinates UTM Exterior boop Lunu 25 Open to Yes IX Preservation Yes . Public? No II Underway? Structure ! . No XX Sile Building X . Object I i 26 Local Contact Person or Organization 39 Endangered? Yes II No XX By What? Yes IX Landmarks Commission 11 On National Yes .. 12 is II Register? Eligible? NoII No X 27 Other Surveys in Which Included Yes X 13 Part of Estab Yes 14 District Visible from Yes XX Nox HIST DIST ? Potent'l? No I I Public Road? No : Distance from and 15 Name of Established District 50 feet on Troost 42 Further Description of Important Features The east facade consists of painted brick. One large plate glass window and a single door exists near Olher Names the center of this front. To the north end of this facade are 2 plate glass windows. A large metal fascia covers the upper portion of the facade. A 1949 remodeling by the Royal Construction Company included rebuilding portions of the north and south walls with concrete blocks. 43 Missory and Significance This building was used for a number of years as a livery. It later was used as a garage. 44 Description of Environment and Outbuildings To the north and south are equipment storage lots. A vacant lot is to the east and a surface parking lot is to the west. 45 Sources of Information 46 Prepared by Paul Helmer/Piland WP #23205 BP #25913A 47. Organization

Landmarks Commission
48 Date 49 Revision Date(s)

10/20/80



HISTORIC INVENTORY JA-AS-005-521 4 Present Name(s) 1 No 86-C 1000-06 Troost Bbleward Building 2 County 5 Other Nameral Jackson 3 to ation of Negatives CBD #24-14 Landmarks Commission 16 Themalic Calegory 28 No of Stories & Specific Location 29. Basement? XXXxex 1000-06 Troost & 17 Date(s) or Period No 1921-22 30 Foundation Material stone 40 H Rural, Township & Vicinity 18 Style or Design 7 City or Town 65 31. Wall Construction Kansas City, Missouri tapestry brick 8 Site Plan with North Arrow 19 Architect or Engineer masonry UL 32 Roof Type & Material IOTH ST. 20 Contractor or Builder flat: tar & gravel 33. No. of Bays Front Side 21. Original Use, if apparent commercial OPE 34 Wall Treatment 22 Present Use brick 35 Pian Shape rectangular vacant Troost 36 Changes Public 11 23 Ownership Addition . Private ly (Explain Attered u m #42) Moved 24 Owner's Name & Address. other d known 37 Condition Interior UTM Currdinales Exterior good Land 25 Open to Yes II PIRSOLVATION No XX Public? NO 1 t Underway? Sile Structure 1 . Building X . Object 11 Endangered? 26 Local Contact Person or Organization Ves II By What? Yes in No XX Landmarks Commission 11 On National Yes . 12 Is fi NoX Eligible? No 11 Register 27 Other Surveys in Which included 14 District Yes X 13 Part of Estab Yes Visible from Yes XX MIST DIST ? Poleni'1? No I Public Road? NoX No . 41 Distance from and 15 Name of Established District Frontage on Road 97 feet on Troost 22 Further Description of Important Features The east facade makes use of brick common bond with stone trim. The glass storefronts have stucco spandrels beneath the windows. The transoms have been covered with plywood. Name! 43 Missory and Symplecance This building was erected by realtor Ben J. Schell. It housed various small firms including Fred Smallwood Drugs, a restaurant, meat market, barber shop and bakery. 44 Description of Environment and Outbuildings An apartment building is west of this building. To the north and east are commercial buildings. A small former restaurant is to the south. 45 Sources of Information 46 Prepared by WP #'s 5044; 66568; 67766 Helmer BP #12852 47. Organization Landmarks Commission 48 Date | 49 Revision Dala(8)


12/6/80

Office of Historic Preservation, P.O. Box 176, Jefferson City, Missouri 65101



Office of Historic Preservation, P.O. Box 176, Jefferson City, Missouri 65101 HISTORIC INVENTORY JA-AS-005-523 4 Present Name(s) 86-E Demolished 1008 Troost (vacant) County Other Name's) Jackson Lunding of Negatives CBD #24-13 Landmarks Commission Snappy Service Lunch 16 Themalic Calegory 26 No of Stories 1 Specific Location 29. Basement? Yes II 1008 Troost 17 Date(s) or Period No X. 30. Foundation Material If Rural, Township & Vacinity concrete 65 18 Style or Design City or Town Kansas City, Missouri 31. Wall Construction Site Plan with North Arrow 19 Architect or Engineer masonry 32. Roof Type & Material 20 Contractor or Builder flat: composition 33. No. of Bays Front 2 21. Original Use, If apparent 34 Wall Treatment 6 restaurant 22 Present Use cinder block & stucco 35 Plan Shape rectangular vacant 36 Changes 23 Ownership Public II Addition . Private X 1 (Explain Attered . m 842) Moved . 24. Owner's Name & Address. d known 37 Condition Interior Currdinales UTM Exterior pood Lung 25 Open to Yes II Preservation Yes . Public? No +1 Underway? No X Sile Structure 1 . Building X' Object 11 39 Endangered? 26 Local Contact Person or Organization Yes II By What? No X On National Yes .. 12 Is II Yes II Landmarks Commission Register? Eligible? No IX NO X 27 Other Surveys in Which Included Part of Estab 14 District Yes II Yes . Visible from Yos .X No X MIST DIST ? Potent'1? No IX Public Road? No :: Distance from and Name of Established District Frontage on Road 14 feet on Troost 2 Further Description of Important features This cement block building has a light coating of stucco. Above the parapet wall blocks are spaced Olher Names to form crenellations. History and Significance This small restaurant was originally operated by Glen Dunlap. The building was constructed for George Lyddon, of the Lyddon Lumber Company, who had also been involved in the construction of the apartment building to the west of this structure in 1912. Description of Environment and Outbuildings Apartment buildings are to the west and south of this structure. A commercial building is to the north. Commercial/residential structures are to the east. Sources of Information 46. Prepared by WP #78637 Helmer BP #80396 47. Organization Landmarks Commission & Date 49 Revision Dele(s)

9/23/80




|  | Survey and Planning Uttice, 909 University   | y Avellue, Juice 213,  |         |
|--|--|--|---------|
| HISTORIC   |  | mbia, Missouri 65201<br>-AS-005-523  |         |
| 1. No.   | 4. Present Name(s)   | 113 000-023  |         |
| 86-D   | T. Frederic Hameley  | ed .6000   | 8       |
| 2. County  | 1008½ Troost Demolis   | 1980   | 86-D    |
| Jackson  | 5. Other Name(s)   |  |         |
| 3 Location of Negatives CBD 37-7 Landmarks Commission  |  | 0163   |         |
| 6. Specific Location   | 16. Thematic Category  | 28. No. of Stories 31 Stories  |         |
|  |  | 29. Basement? Yes IX   | Jac     |
| 1008½ Troost   | 17. Date(s) or Period  | No L   | Jackson |
|  | 1912 Vicinity - 18. Style or Design  | 30. Foundation Material stone  |         |
| 7 City or Town If Rural, Township &<br>Kansas City, Missouri   | vernacular 59  | 31. Wall Construction  |         |
| 8. Site Plan with North Arrow  | 19. Architect or Engineer  | masonry as   |         |
|  |  | 32. Roof Type & Material   |         |
| [] N   | 20. Contractor or Builder  | flat; tar & gravel   |         |
| 1  | 21. Original Use, if apparent  | Front 6 Side 2   | H .     |
|  | apartment 6/8  | 34. Wall Treatment   | 10081/2 |
|  | 22. Present Use  | brick  |         |
| r1   8   II  | apartment  | 35. Plan Shape rectangular   | Tro     |
|  | 23 Ownership Public I ! Private \( \frac{1}{2} \)  | 36. Changes Addition 1:  | 300     |
| L  | 24. Owner's Name & Address.  | in #42) Moved i  | + 3     |
|  | if known   | 37. Condition  |         |
| 9. Coordinates UTM   | 40   | Interior   |         |
| Lat. Long.   | 25 0   | Exteriorgood   |         |
|  | 25. Open to Yes 11 Public? No X1   | 38. Preservation Yes : Underway? No ix   |         |
|  | Object 11 26. Local Contact Person or Organization   | 39. Endangered? Yes I  |         |
| 11. On National Yes 1: 12 Is It  | YesX: Landmarks Commission   | By What? No ½  |         |
| Register? No 1½ Eligible?  | Er: Other Garteys in tenter merces   | Them the place of the data of the control of the co |         |
| 13. Part of Estab. Yes 11 14. District Hist. Dist.? No 12 Potent'll  |  | 40. Visible from Yes X:<br>Public Road? No 11  |         |
| 15. Name of Established District   |  | 41. Distance from and<br>Frontage on Road  |         |
|  |  | 77 feet from Troost  |         |
| 42. Further Description of Important Fea   | tures The main facade faces south. This  |  |         |
|  | with an exterior stair. The red brick was<br>ar, one-over-one, double hung sash windows  |  |         |
|  | ne windows have stone sills.   |  |         |
| see in segmentar arenes. I   | To write the state of the state | Photo  |         |
|  |  |  |         |
|  |  |  |         |
| This hu  | ilding was first-owned by H. Ray Lyddon, w   | who later was involved   |         |
| in the Lyddon Lumber Company   |  | who later was involved   |         |
|  |  |  |         |
|  |  |  |         |
|  |  |  |         |
| 44 Description of Environment and Outb   | buildings This building, without street from   | ntage sets back 77 feet  |         |
|  | between Troost andthis building, is a small  |  |         |
|  | acant lots. An apartment building is to  |  |         |
|  |  |  |         |
| 45 Sources of Information  |  | 46. Prepared by  |         |
| WP 2626<br>BP 10565  |  | Helmer/Piland  |         |
| 51 10303   | 47. Organization Landmarks Commission  |  |         |
|  |  | 48. Date 49. Revision Date(s)  |         |
| The second secon |  | 10/20/80   |         |



Office of Historic Preservation, P.O. Box 176, Jefferson City, Missouri 65101 HISTORIC INVENTORY 86-F 1010 Troost (residence) 2 County 5 Other Name's) Jackson 3 Lucation of Negatives CBD 24-12 James Montgomery residence Landmarks Commission 16 Themalic Calegory 28 No of Stories Specific Location 29. Basement? VesXX 1010 Troost Date(s) or Period c. 1890 30. Foundation Material If Rural Township & Vicinity 18 Style or Design stone 7 City or Town 31. Wall Construction Italianate with Eastlake elements Kansas City, Missouri LUD 19. Architect or Engineer masonry Site Plan with North Arrow 32. Roof Type & Material IOTH ST. 20 Contractor or Builder flat: composition 33. No. of Bays Side Front Original Use, If apparent Present residential 34. Wall Treatment Present Use running bond brick pnch residential 35. Plan Shape rectangular FL Nemela 23 Ownership Public I ! 36. Changes Addition . Private XI (Explain Attered i IITH ST. m #42) Moved : 24. Owner's Name & Address. other of known 37 Condition 30 20 Interior UTM Coordinates Exterior fair Lung 25 Open to Yes ! ! 38. Preservation Yes . Public? Underway? No VI Noxx Structure ! . Sile Building X Object 11 26 Local Contact Person or Organization Endangered? Yes II By What? NoXX Yes XI Landmarks Commission 11 On National Yes .. 12 Is II Eligible? Register? No .X 27. Other Surveys in Which included 40 Visible from 13 Part of Estab Yes 14 District Yes X Yes XX Potent'1? No I Hist Dist ? No Y Public Road? No i 41. Distance from and 15 Name of Established District 21 feet on Troost 42 Further Description of Important Features THTS DUTIGING'S Flat DYICK Tront 15 punctuated by a door and windows with segmented arches. A porch Other Names extends across the first floor with ornamental spindle columns and small spindles in the frieze below the entablatine. The porch has a gable over its dorway. At the building's top is a modillion cor cornice. 43 History and Significance James Montgomery, a Black porter, occupied a residence at this location This residence is not depicted in the 1886 Kansas City Atlas, but is beginning c. 1875. shown in the 1891 Atlas. Montgomery was still living at this address in 1903 when the water service was added. 44 Description of Environment and Outbuildings Commercial buildings are located to the north and east of this residence. To the south is a multi-story apartment/commercial building. To the west is a vacant lot. 45 Sources of Information 46. Prepared by Helmer/Piland WP #23623 47. Organization Kansas City Atlas, 1891. Landmarks Commission 48. Date 49 Revision Deles

11/12/80



Western Contractor, March 8, 1911, p. 8. W.P. #45092 BP #10096; 49479

86-G

2 County

Jackson

Lung

Register?

46. Prepared by Helmer/Piland 47. Organization Landmarks Commission 48. Date 9/80 49 Revision Dale(s)





Office of Historic Preservation, P.O. Box 176, Jefferson City, Missouri 65101 HISTORIC INVENTORY JA-AS-005-527 4 Present Name(s) 1 No 103-A Witt Corrugating Inc. 103-2 County 5 Other Name(s) Jackson nama 3 Lucation of Negatives CBD# 24-8 80 JA0272 Safeway Grocery Store Landmarks Commission 16 Themalic Calegory 28 No of Stories 6 Specific Location lacksor 29. Basement? Yes II Date(s) or Period No : . 1102-04 Troost 1940 30. Foundation Material concrete If Rural, Township & Vicinity 18 Style or Design 7 City or Town 31. Wall Construction Kansas City, Missouri Art Deco elements masonry 19. Architect or Engineer M Site Plan with North Arrow 32. Roof Type & Material flat; tar/gravel 20 Contractor or Builder T. D. Bryant Construction Co. No. of Bays Side 6 Front 21. Original Use, If apparent 1102-04 Present Name(s) 34 Wall Treatment commercial ROOST 22 Present Use brick pnch 35. Plan Shape rectangular commercial AW Troost Public 11 36. Changes Addition X 23 Ownership Altered : Private IXI (Explain Moved i 10 8421 24. Owner's Name & Address. if known Condition oltres Interior UTM 9 Curidinales fair Exterior Lung Open to Yes Kı Preservation Yes . Underway? Public? No X Structure ! . Sile By What? Tuture demolition and/or redevelopment Yes XI Building X Object 11 26. Local Contact Person or Organization No I Landmarks Commission 12 Is It 11 On National Yes .. No XI Eligible? 27 Other Surveys in Which Included Register? No . Yes X Yes X 40 Visible from 14 District 13 Part of Estab Yes Potent'1? Noli Public Road? No . HIST DIST ? No " 41. Distance from and 15 Name of Established District Frontage on Road 50 feet on Troost 42 Further Description of Important Features The main (east) facade has been Olher Name(s) altered. A horizontal band of glass runs across the middle of the facade, with the entrance on the north end. The wall below the windows is faced with ceramic tile. A canopy roof extends across the Photo facade, immediately above the windows. The concrete parapet has Art Deco elements. Several loading docks mark the north facade. A concrete block addition is at the rear of the building. 43 History and Significance In 1940, the national chain grocery firm, Safeway, undertook a major expansion effort in Kansas City with its "revolving fund" program. They acquired property, erected a building, sold the building and then reacquired the property on a long-term lease. This is one of two buildings that were erected by Safeway in the downtown area. 44 Description of Environment and Outbuildings Gravel surfaced vacant lots are located to the south & west of this building. A small surfaced parking lot is to the north. To the east is a large apartment building. 46. Prepared by 45 Sources of Information Sherry Piland WP# 8086 47. Organization BP# 15944 Landmarks Commission 49 Revision Date(s) 48. Oate KC Star, July 7, 1940


11/6/80

KC Star, Sept. 8, 1940, p. 6D



JA-AS-005-308

HISTORIC INVENTORY



ISTORIC INVENTORY JA-AS-005-529 1. No. Missouri State Highway Department Project Office (garage) 148-B 2. County 5. Other Name(s) Jackson 3 Location of Negatives CBD #37-19 andmarks Commission 16. Thematic Category 28. No. of Stories 6 Specific Location 29. Basement? Yes I Jackson County 806 Truman Road 17. Date(s) or Period No XX 1953 30. Four fation Material 18. Style or Design concrete 7. City or Town . If Rural, Township & Vicinity 31. Wall Construction Kansas City, Missouri 8. Site Plan with North Arrow 19. Architect or Engineer 32. Roof Type & Material 20. Contractor or Builder 33. No. of Bays Front Side 21. Original Use, if apparent Present Named 806 Truman 34. Wall Treatment garage steel 22. Present Use 35. Plan Shape garage rectangular Public IXX 36. Changes 23 Ownership Addition 1: Private | | TRUMAN Road (Explain Altered 1 in #42) Moved i 24. Owner's Name & Address, if known 37. Condition Interior J. Coordinates UTM Exterior Lal. Long 25. Open to Yes ! i 38. Preservation Yes i No XX Public? Underway? No XX Site!: Structure | Object | | Buildingxx 39. Endangered? 26. Local Contact Person or Organization Yes I By What? No IXX 1. On National Yes ! Landmarks Commission Yesli 12 Is It Eligible? Register? No XX Noxx 27. Other Surveys in Which Included Part of Estab. Yes II District Yes 40. Visible from YesXX Hist. Dist.? No \*\* Potent'1? No XX Public Road? No ! ! 41. Distance from and 5. Name of Established District Frontage on Road 36 feet on Truman Road of ribbed steel and 2. Further Description of Important Features This Quonset hut type garage has walls sits on a concrete base. A garage entrance is on the east. the south facade. A door is The building measures 20 x 36 feet. Photo The building was originally owned by Lee Wilson, owner of Wilson 3. History and Significance Trailer Sales which was located at 800 Truman Road. . Description of Environment and Outbuildings Surface parking lots are to the east and west. To the nor is an interstate connector. To the south is a small residence used as an office. Sources of Information 46. Prepared by BP #34525A Sherry Piland 47. Organization Landmarks Commission 48. Date 49. Revision Date(s) 1/27/81

State Historical Survey and Planning Office, 909 University Avenue, Suite 215,

Columbia, Missouri 65201



State Historical Survey and Planning Office, 909 University Avenue, Suite 215,

Columbia, Missouri 65201

1/28/81



survey and Planning Office, 909 University Avenue, Surte 213 Columbia, Missouri 65201 HISTOR! TA-AS-005-531 4. Present Name(s) 1. No. 149-B 149-B Evangelistic Center Church 2. County 5. Other Name(s) Jackson CBD #37-20 3 Location of Negatives Scottish Rite Temple 80 JA0273 Landmarks Commission u. Thu is a Gelegary 28. No. of Stories 6 Specific Location 29. Basement? County Yes I 17. Date(s) or Period alt. date No i 1024 Truman Road 1903-04 (addition 1981) 30. Foundation Material 18. Style or Design 7. City or Town · If Rural, Township & Vicinity stone Kansas City, Missouri English Gothic 31. Wall Construction masonry UD B. Site Plan with North Arrow 19. Architect or Engineer 32. Roof Type & Material Frank M. Howe 20. Contractor or Builder varied 33. No. of Bays John T. Neil Front Side 21. Original Use, if apparent Present Masonic Hall 34. Wall Treatment brick; stone 30 40 22. Present Use church 35. Plan Shape rectangular Public 11 36. Changes Addition : 23 Ownership Private I, Altered XX (Explain TRuman Road in #42) Moved i 24. Owner's Name & Address, if known 37. Condition cher Interior 9. Coordinates 90 Exterior Lat. good Long. 25. Open to Yes IX 38. Preservation Yes I Public? No II Underway? Nox Structure 1 10. Site!: Building L Object 11 39. Endangered? Yesi 26. Local Contact Person or Organization By What? No X Yes X Landmarks Commission 11. On National 12 Is It Yesli Eligible? No I Register? No L 27. Other Surveys in Which Included 13. Part of Estab. Yes II District Yes 40. Visible from YesX Potent'l? No Hist. Dist.? No ! Public Road? No i i 41. Distance from and 15. Name of Established District Frontage on Road 75 feet on Truman Road 42. Further Description of Important Features The main facade faces outh with the entrance centrally locate The entrance is set in a decorative arched stone surround. Above the entrance are 4 joined windows with arched stone surrounds. The end bays are 3 stories in height, with each floor fenestrated by a set of paired windows. The end bays form tower-like projects and ginally were crenelated, but the battlements have recently been removed. An addition for church offices is currently being erected on the west side of the building (arch: Horner & Blessing). 43. History and Significance This was reportedly the lst building to be erected in Missouri for purely Masonic purposes. The building was to be used by four bodies of Free Masons. It continued in use as a Masonic Temple until a new temple was constructed in 1930 at Linwood and Paseo.

The building was purchased by the Friendship Baptist Church. The building contains a 1,000 seat auditorium. C. P. Schmidt served as associated architect on the original design of 44. Description of Environment and Outbuildings An interstate connector is to the north of this building. To the west and south are vacant lots. A commercial building is to the east. 45 Sources of Information 46. Prepared by Sherry Piland KC Star, July 31, 1940 47. Organization KC Star, March 20, 1904. Landmarks Commission KC Star, July 19, 1903, p. 5. 48. Date 49. Revision Date(s) KC Architect & Builder, Aug 1903, p. 24 12/22/80 Western Contractor, April 8, 1903; Aug. 5, 1903; Feb. 25, 1903; April 29, 1903.

KC Star, Aug. 4, 1940.



Office of Historic Preservation, P.O. Box 176, Jefferson City, Missouri 65101 HISTORIC INVENTORY JA-AS-005-529 Present Name(s) 9-A Crown Sales 601-607 Walnut Street Builder 5 Other Name's) Jackson Landmarks Commission 26 No of Stories 16 Themalic Calegory & Specific Location Yes X 29 Basement? 601-07 Walnut No : 17 Date(s) or Period 30. Foundation Material 1900 18 Style or Design N Aural. Township & Vicinity 7 City or Town 31. Wall Construction Kansas City, Missouri masonry Sile Plan with North Arrow 19 Architect or Engineer 32 Roof Type & Material 20 Contractor or Builder flat; tar & gravel Front 21. Original Use, If apparent unknown 34 Wall Treatment 22 Present Use brick 35 Plan Shape N rectangular commercia1 36 Changes 23 Ownership Public 11 Addition . Privatext (Explain Aftered . on 8421 Moved I Walnut 24 Owner's Name & Address, d known 37 Condition Interior UTM Cuprdinates fair Exterior Lung 25 Open to Yes XX Preservation Public? No II Underway? No X. Structure ! . Sile Building X' Object I i Endangered? 26 Local Contact Person or Organization Yes !! By What? No X VesXX 11 On National 12 15 11 Landmarks Commission Yes . Engible? Register? NO A 27 Other Surveys in Which Included Yes . 13 Part of Estab Yes ! 14 District Visible from Ves X No V Polent'1? No IX Public Road? MIST DIST ? No .: Distance from and 15 Name of Established District Frontage on Road 82 feet on Walnut 42 Further Description of important Features The first floor of this building Other features glass display windows that have probably been altered from 40/30 Olher Namets the original. The centrally located entrance is flanked by cast iron pillars. Brick piers with stone caps further divides the 1st floor facade. The north and south bays of the main facade have shaped parapets. These bays are fenestrated with triple windows. The wider central bay contains a single window in the center of each floor, flanked by triple windows. Many of the windows have (come 43 Missory and Sminicence This building was constructed for attorney, Phillip S. Brown. 44 Description of Environment and Outbuildings Surface parking lots are to the south and west of this building. To the north is an interstate connector. A small commercial building is to the east. 45 Sources of information 46 Prepared by Kansas City Architect & Builder, Oct. 1900, p. Sherry Piland 303. 47. Organization Landmarks Commission 4 Date 49 Revision Delets)

HISTORIC INVENTORY COI-07 Walnut K.C. Crown Sales
Page 2

42. (cont'd) stone sills, transoms, and/or keystones-most of which are in a deteriorated condition.



Office of Historic Preservation, P.O. Box 176, Jefferson City, Missouri 65101 HISTORIC INVENTORY JA-AS-005-530 4 Present Name(s) 25-B Sam's 7th & Walnut Garage 0167 2 County 5 Other Name(s) Jackson Location of Negatives CBD# 12-21 700-706 Walnut Street Bulling Grand Opera House Landmarks Commission 16 Themalic Category 28 No of Stories 6 Specific Location 4 29. Basoment? Yes IX 700-06 Walnut 17 Date(s) or Period No : . 30. Foundation Material 1891 stone 18 Style or Design If Rural, Township & Vicinity 31. Wall Construction Kansas City, Missouri 19. Architect or Engineer UD Site Plan with North Arrow 32. Roof Type & Material PR 20 Contractor or Builder flat; tar/gravel 33. No. of Bays Front 4 Side 21. Original Use, If apparent theater O8A 34. Wall Treatment 22 Present Use brick 35. Plan Shape rectangular parking garage 23 Ownership Public 11 36. Changes Addition . Walnut Attered X Private IX (Explain in #42) Moved i 24. Owner's Name & Address. N of known 37. Condition Interior 9 Condinates UTM Exterior fair Lung 25. Open to Yes IX 38. Preservation Yes . Public? Underway? No X. Structure ! . Site Building X Object 11 26. Local Contact Person or Organization 39 Endangered? Yes II By What? No X. Yes IX 11 On National Yes .. Landmarks Commission Register? Eligible? No 11 No X 27. Other Surveys in Which Included Yes IX District Part of Estab Yes Visible from Yes X No X Potent'l? No I I HIST DIST ? Public Road? 41. Distance from and 15 Name of Established District Frontage on Road approx. 100 feet on Wallut 42 Further Description of Important Features The first floor has been altered by the conversion of the building into a garage. A portion of the Other Name(s) facade projects slightly forward. It is flanked by one bay on the south and 2 bays on the north. The windows of the central projection are united by columns that terminate in rounded arches containing tracery windows. Each of the side bays contain rectangular double hung sash windows, separated by pilasters. The original interior was of a Moorish design and seated 1800. It now provides parking for 350 cars.

43 History and Significance -- This theater was constructed by Kansas City theater men Melville Hudson and A. Judah, operating as Kansas City Amusement Association. The Midland Theater was razed for this building. Previously on the site was the cylorama of the Battle of Gettysburg. Opening night for the theater was October 3, 1891 and it continued in operation for legitimate theater until 1916. It briefly was converted for motion picture use between 1916-18, 44 Description of Environment and Outbuildings Surface parking lots are located to the north and east of this building. To the south is a high rise apartment building. A motel is to the west.

WP# 5188, BP# 85011

<u>Kansas City Star,</u> Oct. 3, 1891, p. 3

<u>Kansas City Star</u>, Oct. 4, 1916

<u>Kansas City Journal Post</u>, Sept. 26, 1926

45 Sources of Information

46. Prepared by Sherry Piland

47. Organization
Landmarks Commission

8. Date 49 Revision Date(s)

HISTORIC INVENTORY--page 3 700-06 Walnut

43. and then resumed live theater. It was converted into a parking garage in 1926. Many famous theatrical personalities appeared on the stage, including Ethel Barrymore, Maude Adams and Eddie Foy.



Office of Historic Preservation, P.O. Box 176, Jefferson City, Missouri 65101 HISTORIC INVENTORY JA-AS-005-531 4 Present Name(s) 25-C Walnut Tower Apartments County 5 Other Name(s) not entered Jackson 3 Lucation of Negatives CBD# 30-11 Landmarks Commission 16 Themalic Calegory 28 No of Stories Ja 6 Specific Location Ckson 29. Basement? Yes 17 Date(s) or Period No : 708 Walnut 30. Foundation Material 1962-63 concrete 18 Style or Design 7 City or Town Il Rural, Township & Vicinity 31. Wall Construction Kansas City, Missouri 19. Architect or Engineer concrete block Site Plan with North Arrow 32. Roof Type & Material Keene, Simpson, & Murphy 20 Contractor or Builder flat; tar/gravel Winn-Senter Construction Co. 33. No. of Bays Walnut Tower Front 9 Side 21. Original Use, if apparent 34 Wall Treatment apartments brick 22 Present Use apartments 35. Plan Shape rectangular 23 Ownership 36. Changes Public I Addition . Walnut Private KK Attered i (Explain m 842) Moved I Apartments 24. Owner's Name & Address. of known 37 Condition Interior UTM Cupidinales Exterior boop Lung 25 Open to Yes I 38. Preservation Yes . Public? Underway? No ix Structure ! . Sile Building X Object 11 39 Endangered? 26 Local Contact Person or Organization Yes II By What? No IX Yes II 11 On National Yes ... 12 Is II Landmarks Commission Eligible? No XI Register? No .X 27. Other Surveys in Which Included 14 District Yes X 13 Part of Estab Yes Visible from Yes . X Potent'l? No HIST DIST ? No " Public Road? No . : 41 Distance from and 15 Name of Established District Frontage on Road 208 feet on Walnut 42 Further Description of Important Features Concrete piers running the heighth of the building divide it into bays. Buff brick veneers the building between the piers. The building is fenestrated with casement windows with sidelights. The first floor is set back and provides 6,000 square feet of commercial space. The upper floors contain 180 rental units. 2 1/2 levels of underground parking are provided 43 History and Significance This downtown apartment building was a project of the Downtown Redevelopment Corporation. 44 Description of Environment and Outbuildings Commercial buildings are located to the east and south of this structure. To the west is a motel and to the north is a parking garage. 45 Sources of Information 46. Prepared by Sherry Piland WP# 119294 , BP# 19374 47. Organization KC Star, Sept. 10, 1961. Landmarks Commission

49 Revision Dale(s)

10/9/80



Office of Historic Preservation, P.O. Box 176, Jefferson City, Missouri 65101 HISTORIC INVENTORY JA-AS-005-532 No 26-B Racket Merchandise Company 80JA 0168 2 County 5 Other Name's) Jackson Missouri, Kansas and Texas Railway Ticket and Freight Office 3 Lucation of Negatives CBD #34-20 Landmarks Commission 16 Themalic Calegory 28 No of Stories 6 Specific Location 713 Walnut Courty 29 Basement? Yes KI ackson 17 Date(s) or Period No 1916 30. Foundation Material concrete 18 Style or Design 7 City or Town H Rural. Township & Vicinity 31 Wall Construction Kansas City, Missouri Neo-Classic elements Architect or Engineer Site Plan with North Arrow reinforced concrete Wight & Wight 32. Roof Type & Material PP flat; tar & gravel N 20 Contractor or Builder Geo. A. Fuller Const. Co. 33. No. of Bays Front Side Original Use, if apparent Present Namels commercial 34 Wall Treatment 22 Present Use brick commercia1 35. Pian Shape rectangular 36. Changes 23 Ownership Public 11 Addition Walnut Aftered IX Private KI (Explain m 842) MOVEU : 24. Owner's Name & Address, of known 37 Condition Interior UTM Coordinates Ехтегю boop Lung 25 Open to Yes 11 38. Preservation Yes . Public? No II Underway? Structure ! . Nox Sile BuildingX Object 11 26 Local Contact Person or Organization 39 Endangered? Yes II By What? NoX Landmarks Commission Yes XI 11 On National Yes . 12 Is II NoX Eliqible? No 11 Register? 27. Other Surveys in Which included Yes X District 13 Part of Estab Yes. Visible from Yes X NoX Potent'1? Public Boad? HIST DIST ? No . 41 Distance from and 15 Name of Established District Frontage on Road 80 feet on Walnut 42 Further Description of Important Features The 1st floor has undergone major The 1st floor doors and windows are recessed in beveled concrete surrounds. The remaining wall surface has a metal veneer. Running between the 1st and 2nd floor is a concrete panel and a strip of structural glass. The 2nd floor windows are hidden by metal panels Four pilasters with ornate capitals divide the building into three bays. corbelled cornice runs below the parapet wall. 43 Mistory and Significance The Midland Building was previously located on the site to the north of this building. In 1916, the 1st floor of the Midland Building was leased and this building was constructed to consolidate the various railway ticket offices (with the exception of the Union Pacific). 44 Description of Environment and Outbuildings A surface parking lot is to the north of thisbuilding. To the west is an apartment building. Commercial buildings are to the south and a parking facility is to the east. Scurces of Information BP #11902 46. Prepared by Sherry Piland KC Star, March 14, 1916. 47. Organization Western Contractor, July 26, 1916, p. 20.

WP # 66268

Landmarks Commission

48. Date 49 Revision Date(s)



|  |  |  | JA-A3-005-533  |
|--|--|--|--|
| 1. No.   |  | sent Name(s)   |  |
| 2. County  |  | l Sereno Lounge  | 0169   |
| Jackson  3 Location of Negatives Landmarks Commiss   | s CBD #34-19   | 721-731 Walnut   | Street Building  |
| 6. Specific Location   |  | 16. Thematic Category  | 28. No. of Stories 3   |
| 721-31 Walnut (10  | 00-02 East 8th St)   | 17. Particle of Particle   | 29. Basement? Yes I  |
|  |  | 17. Date(s) or Period .  | 30. Foundation Material  |
| 7 City or Town If Rural, Township & Vicinity   |  | 18 Style or Design   | . Foundation Material  |
| Kansas City, Missouri  |  | 69   | 31. Wall Construction  |
| 8. Site Plan with North  | Arrow  | 19. Architect or Engineer  | masonry  |
|  | $\uparrow$   | 20. Contractor or Builder  | 32. Roof Type & Material flat; tar & gravel  |
|  |  | 21. Original Use, if apparent O/D  | 33. No. of Bays Front F Side F   |
| X  | N  | commercial   | 34. Wall Treatment   |
| 3  | IN .   | 22. Present Use  | stucco; tile 6/  |
| Whom   |  | commercial   | 35. Plan Shape rectangular   |
|  |  | 23 Ownership Public   ! Private   1  | 36. Changes (Explain in #42)  Addition : Altered   X Moved   |
| : 8  | E. 8ª Street   | 24. Owner's Name & Address, if known   | 37. Condition  |
| 9. Coordinates UTM   |  |  | Interior good  |
| Lat.<br>Long.  |  | 25. Open to Yes IX   | 38. Preservation Yes   |
| 10. Site!: Structure!: Building L. Object!!  |  | Public? No 1 1  26. Local Contact Person or Organization   | Underway? No :X  39. Endangered? Yes   |
| 1. On National Yes Li<br>Register? No 🖟  | 12 Is It Yes 🔀<br>Eligible? No 🖂   | Landmarks Commission   | By What? Yes 1   |
| 3. Part of Estab. Yes    <br>Hist. Dist.? No   | 14. District Yes X<br>Potent'l? No   | 27. Other Surveys in Which Included  | 40. Visible from Yes!X Public Road?  |
| 15. Name of Established District   |  |  | Public Road? No 1:   |
|  |  |  | Frontage on Road approx. 96 ft on Walnut   |
| 2. Further Description   |  | e building has undergone extensive inal brick of the 2nd and 3rd   |  |
| alteration. Stuc<br>Floors. Shop win<br>Veneer of new bri  | dows and an angled   | corner have been replaced and a floor walls. The entrance to the eet facade.   | Photo  |
| alteration. Stuc<br>floors. Shop win<br>veneer of new bri<br>upper floors is o   | ndows and an angled<br>ck covers the 1st<br>on the East 8th Str  | floor walls. The entrance to the eet facade.   |  |
| alteration. Stud<br>floors. Shop win<br>veneer of new bri<br>upper floors is o<br>13. History and Significat<br>CCOrmick was a ho  | ndows and an angled<br>ck covers the 1st<br>on the East 8th Str  | floor walls. The entrance to the eet facade.  mit for this building was issued to his structure was probably used as   | E. I. McCountal  |
| alteration. Stud<br>floors. Shop win<br>veneer of new bri<br>upper floors is o<br>13. History and Significat<br>CCormick was a ho<br>ater was used to  | ndows and an angled ck covers the 1st on the East 8th Structure.  The water permotel manager and the house railroad tickness.  | floor walls. The entrance to the eet facade.  mit for this building was issued to his structure was probably used as   | E. J. McCormick.<br>sleeping rooms. It   |
| alteration. Stude floors. Shop win veneer of new briupper floors is on the state of the state of this building.  | and an angled of the last on the East 8th Structure. The water permotel manager and the house railroad tickness. To the west is an angled on the west is an angled on the last of the last | floor walls. The entrance to the eet facade.  mit for this building was issued to his structure was probably used as seket offices.  Commercial buildings are to the nor | E. J. McCormick. sleeping rooms. It  rth, south, and east  |
| alteration. Stuce floors. Shop win veneer of new bri upper floors is on the state of the state o | and an angled of the last on the East 8th Structure. The water permotel manager and the house railroad tickness. To the west is an angled on the west is an angled on the last of the last | floor walls. The entrance to the eet facade.  mit for this building was issued to his structure was probably used as seket offices.  Commercial buildings are to the nor | E. J. McCormick. sleeping rooms. It  rth, south, and east  46. Prepared by Sherry Piland  47. Organization |
| alteration. Stude floors. Shop win veneer of new briupper floors is on the state of the state of this building.  Sources of Information of Sources of Information floors and the state of t | and an angled of the last on the East 8th Structure. The water permotel manager and the house railroad tickness. To the west is an angled on the west is an angled on the last of the last | floor walls. The entrance to the eet facade.  mit for this building was issued to his structure was probably used as seket offices.  Commercial buildings are to the nor | E. J. McCormick. sleeping rooms. It  rth, south, and east  46. Prepared by Sherry Piland                   |



State Historical Survey and Planning Office, 909 University Avenue, Suite 215. Columbia, Missouri 65201 INVENTORY ISTORIC JA-AS-005-534 1. No. CBD 4. Present Name(s) 44-4 Gumbel Building 2. County Jackson CBD 5. Other Name(s) 3 Location of Negatives CBD# 31-21 Landmarks Commission 6 Specific Location 16. Thematic Category 28. No. of Stories 801 Walnut 29. Basement? Jackson 17. Date(s) or Period No I 1904 30. Foundation Material . If Rural, Township & Vicinity 18. Style or Design masonry 7. City or Town Missouri 64106 31. Wall Construction Kansas City Commercial B. Site Plan with North Arrow 19. Architect or Engineer reinforced concrete John W. McKecknie 32. Roof Type & Material 20. Contractor or Builder flat; material unknown 33. No. of Bays Front 4 Side 6 21. Original Use, if apparent 34. Wall Treatment commercial 22. Present Use terra cotta 35. Plan Shape commercial rectangular 23 Ownership 36. Changes Public 11 Addition . Private | | (Explain AlteredX private in #42) Moved i 24. Owner's Name & Address. Walnut if knownJeanette McDonald Groves 37. Condition Interior 5353 Ward Parkway 9. Coordinates UTM Exterior Kansas City, Mo. 64112 Lat. boop Long 25. Open to Yes IX 38. Preservation Yes Public? Underway? No i 10 Site!: Structure ! restricted Building XI Object 11 26. Local Contact Person or Organization 39. Endangered? future yes X By What?demolitionNo!; Yes X Landmarks Commission 11. On National Yes IXX 12 Is It Eligible? No !! and/or redevelopment Register? No ]! 27. Other Surveys in Which Included 13. Part of Estab. Yes I I Yes i Kansas City, A Place in Time. 40. Visible from 14. District No X Hist. Dist.? No X! Potent'1? Public Road? Landmarks Commission of No 11 Distance from and 61 15. Name of Established District Kansas City, Missouri, 1977. Frontage on Road 721 42. Further Description of Important Features This six-story building features reinforced concrete construction faced with terra cotta. "Chicago" style windows provide ample fenestration. Italianate decorative details are noted including the rounded columns marking bays, the ornate cornice and decorative terra cotta Roman eagles at the corners of the of the building. The first floor window treatment has been modernized. 43. History and Significance This building is the first commercial structure in Kansas City to be constructed utilizing reinforced concrete. John W. McKecknie, a prominent Kansas City architect and designer of this building, was a pioneer in this method of construction. 44. Description of Environment and Outbuildings The building is located in Kansas City's Central Business District. Commercial structures are located to the north, south, east, and west. 45 Sources of Information 46. Prepared by Hoffman, Skylines and Midwest Architect, Dec.-Jan. 1965, pp. 13-22. Sherry Piland Kansas City Star, 20 October 1934, p.2. 47. Organization Western Contractor, 20 May 1903, p.1. Landmarks Commission 48. Date 49. Revision Date(s) 11/77 10-24-79



Office of Historic Preservation, P.O. Box 176, Jefferson City, Missouri 65101 HISTORIC INVENTORY JA-AS-005-535 44-B J & C Auto Park Jackson 5 Other Name(s) notentered Landmarks Commission #34-18 16 Themalic Calegory 28 No of Stories 6 Specific Location 29. Basement? 811-15 Walnut 17 Date(s) or Period No 1959 30. Foundation Material H Aural, Township & Vicinity 18 Style or Design 31. Wall Construction City or Town Kansas City, Missouri reinforced concrete & Site Plan with North Arrow 19 Architect or Engineer 32. Roof Type & Material 20 Contractor or Builder flat; concrete 33. No. of Bays Front Side 21. Original Use, if apparent Proper Names parking facility 34 Wall Treatment 22 Present Use concrete parking facility 35. Plan Shape rectangular 23 Ownership Public I 36. Changes Addition . Walnut Private IX (Explain Attered : m #42) Moved . 24. Owner's Name & Address, of known 37 Condition Interior & Curidinales Exterior Lat poop Lung 25 Open to Yes IX Preservation Yes . Public? No II No X Underway? Structure IX Sile Object I i Building Local Contact Person or Organization Endangered? Yes II Landmarks Commission By What? No X 11 On National Yes I Yes .. 12 Is II Eligible? No IX Register? No . X 27. Other Surveys in Which Included 13 Part of Estab District Yes Visible from Yes X No . X Potent'1? No IX HIST DIST ? Public Road? No . : Distance from and 15 Name of Established District Frontage on Road approx 125 feet on Walnut 42 Further Description of Important Features This multilevel parking garage Olher Nameis faces west. The southern bay of the 1st floor contains a commercial space. A ramp across the alley to the east connects this structure to the J & C Auto Park at 800-08 Grand. 43 History and Significance Original owners of this parking facility were Joseph and Dominic Cervello. 44 Description of Environment and Outbuildings Commercial buildings are located to the north and south of this parking garage. Other parking facilities are to the east and west. 45 Sources of Information 46. Prepared by WP # 12312 Sherry Piland 47. Organization Landmarks Commission 48 Date 49 Revision Dele(s) 12/3/80



HISTORIC INVENTORY JA-A5-005-536 4 Present Name(s) 43-B Columbia Union Motor Bank & Auto Parking 2 County 5 Other Name's) Jackson I Lux ation of Negatives CBD #42-17 entered Landmarks Commission 42-18 16 Themalic Calegory 28 No of Stories & Specific Location Jackson 29. Basement? Yes 816 Walnut 17 Date(s) or Period No 1938; 1977 30. Foundation Material 18 Style or Design stone City or Town If Rural, Township & Vicinity Kansas City, Missouri 31. Wall Construction 19 Architect or Engineer Site Plan with North Arrow masonry 32. Roof Type & Material 20 Contractor or Suider see #42 33. No. of Bays see # 43 Front Side 21. Original Use, If apparent 816 Present Namels parking garage 34 Wall Treatment 22 Present Use Walnut brick 35. Plan Shape parking garage/drive-in bank 36 Changes 23 Ownership Public I ! Addition Private IX (Explain Derett m 842) Moved . E. 875 street 24. Owner's Name & Address. of known 37 Condition Interior UTM 9 Currdinales Exterior good Lung 25 Open to Yes IX Preservation Public? No II Underway? No K. Sile Structure ! Building X Object 1 i 26 Local Contact Person or Organization Endangered? Yes II By What? 11 On National Yes ! ! No X Yes .. 12 Is II Landmarks Commission No . X Eligible? No IX Register? 27 Other Surveys in Which Included 3 Part of Estab Yes ' 14 District Yes : ! Visible from Yes X No IX Mist Dist ? Potent'l? Nox Public Road? No . : 15 Name of Established District Distance from and Frontage on Road 105 feet on Walnut 2 Further Description of Important Features This parking facility sits on a grade sloping to the west. An interior parking facility, constructed i Other Names 1938 by the Hiram Elliott Construction Company, is entered from the East 9th Street facade. This facade veneered in brick, is fenestrated with multipaned, hinged windows. In 1977 a drive-in banking facility was erected on the roof-top parking area by the J. E. Dunn Construction Company. This building has brick walls and a metal pent roof with deep eaves. The roof extends on the west for the drive-through a 43 History and Significance The original structure on this property was a 1 story garage, constructed in 1938 by the Hiram Elliott Construction Company. In 1959 the property was leased for parking by the Columbia Union Bank across the street to the south. In 1977 the bank had a drive-in banking facility added to the property, with the entrance from Walnut. The J.E. Dunn Construction Company handled this project Description of Environment and Outbuildings Commercial buildings surround this structure. Sources of Information 46. Prepared by WP #28192 Sherry Piland BP #'s 15861; 69575A 47. Organization KC Star, March 1, 1959 Landmarks Commission 48. Date 49 Revision Deta(s)

12/22/80

Office of Historic Preservation, P.O. Box 176, Jefferson City, Missouri 65101

TUR BANK . AUTO PARKING

CLEARANCE 7'-0"

BANK PARKING ENTRANCE



State Historic - Survey and Planning Office, 90° University Azenue, Suite 215, Columbia, Missouri 65201 ORIC INVENTORY -AS-005 4. Present Name(s) No CBD CBD 44-C Scarritt Arcade . County 5. Other Name(s) Jackson Location of Negatives Kansas City andmarks Commission Specific Location CBD# 34-17 16. Thematic Category 28 No. of Stories 819 Walnut Architecture 29. Basement? Yes IX Kansas City, Missouri 17. Date(s) or Period No I 1907 30. Foundation Material 18. Style or Design . If Rural, Township & Vicinity City or Town masonry Cansas City Sullivanesque 31. Wall Construction 19. Architect or Engineer . Site Plan with North Arrow . steel frame Root & Siemens 32. Roof Type & Material 20. Contractor or Builder flat tar and gravel 33. No. of Bays Front Side 21. Original Use, if apparent commercial 34. Wall Treatment 22. Present Use masonry ashlar 35. Plan Shape rectangula commercial 23 Ownership Public 11 36. Changes Addition . . Private XI (Explain Altered 1x in #421 Moved i 24. Owner's Name & Address, if known Carl Ragsdale & others 37. Condition WALNUT STREET 101 W. 11th St. good... UTM Coordinates Kansas City, Mo. 64105 Exterior good Lat. Long. Yes X: 25. Open to Preservation Yes X Public? restrictive Underway? No : Structure I Site ! Object | | 26. Local Contact Person or Organization Landmarks Commission - K.C. Endangered? Building & Yes By What? No lx Yes X 12 Is It Yes ! 1. On National No I 27. Other Surveys in Which Included Preliminary Inventory of Register? Eligible? No I! YesX 40. Visible from Yes X J. Part of Estab. Yes 11 14 District Architecture and Historic Siteso Public Road? Potent'1? No: Hist. Dist.? No X' No !: Landmarks Commission of Kansas 41. Distance from and 10 ft 5. Name of Established District City, 1974 Frontage on Road The Need for the Preservation 2. Further Description of Important Features The Scarritt arcade is a four tory, steel frame structure connected to the Scarritt Building y a tunnel running from the ground floor of the Arcade to the ub-basement of the main building. The west (main) facade has Photo recessed triple entranceway. It is flanked by two slightly arrower areas which enclose a large show window. A band of laborate terra cotta ornament runs the width of the facade. ne Arcade contains Sullivanesque Art Nouveau decorations. 3. History and Significance The Scarritt Arcade is significant as having the last of the kylighted interior open walls in Kansas City. The arcade is also a fine example f the Chicago school of architecture, particularly with the Sullivanesque decorations. oth the interior and exterior designs are of the same vernacular of the main building nich was designed by an outstanding architectural firm, Root and Siemen. 4. Description of Environment and Outbuildings The Scarritt arcade is surrounded by commercial tructures. 46. Prepared by S. Piland & 5 Sources of Information Linda F. Becker ational Register Form Prepared July 28, 1970 47. Organization Kansas City Landmarks Commission 49 Revision Date(s) 48. Date 8/12/80 12/1



WP# 90001

HISTORIC INVENTORY
Waltower Building
Page 2 823 Walnut K.C

42. (cont'd) the Walnut Street facade are set back at an angle.



Office of Historic Preservation, P.O. Box 176, Jefferson City, Missouri 65101 HISTORIC INVENTORY JA-AS-005-539 4 Present Name(s) 59-B Columbia Union National Bank 2 County 5 Other Name's) Jackson 3 Lu ation of Negatives CBD #27-6 Union National Bank Landmarks Commission 16 Themalic Calegory 26 No of Stories & Specific Location 29. Basement? 900-06 Walnut Yes X 17 Date(s) or Period No : 30. Foundation Material 1947-49 (1968, remodeled) 18 Style or Design H Rural, Township & Vicinity cut stone 31. Wall Construction Kansas City, Missouri Site Plan with North Arrow 19 Architect or Engineer steel frame (engineer) 32 Roof Type & Material Edward B. Delk: Tracy Wood flat; tar & gravel 9 the Stree 33. No. of Bays Winn-Senter Construction Co. Front 21. Original Use, if apparent Present bank Oab 34 Wall Treatment 22 Present Use bank stone 35 Plan Shape rectangular Nemela Walnut Public II 36 Changes 23 Ownership Addition (Explain Aftered ! Walnut m 842) Moved : 24 Owner's Name & Address. d known 37 Condition Interior UTM Curryingles marble excellent Exterior Luni 25 Open to Yes XX 38 Preservation Yes No X Public? No II Underway? Sile Structure I Building X' Object 11 26 Local Contact Person or Organization 39 Endangered? Yes II By What? No IX 11 On National 12 15 11 Yes II Landmarks Commission Yes . Eligible? Noxx Register? No X 27 Other Surveys in Which included Yes XX 14 District 13 Part of Estab Yes Visible from Yes .X Potent'1? MIST DIST ? No V Public Boad? No . 41 Distance from and 15 Name of Established District Frontage on Road 115 feet on Walnut 42 Further Description of Important Features This corner building sits on a grade sloping to the west. The recessed main entrance faces Walnut and was remodeled in 1968. At this time white marble was added through the 2nd floor level. The 1968 remodeling was by William B. Fullerton & Assoc., architects and the Universal Construction Co. The base of the building is veneered with a dark green stone, while lighter colored green stone is used for the upper floors. The northeast corner of the building features a rounded silo-like projection. (cont'd)

43 History and Significance The 19th century Keith and Perry Building formerly was on this site. Part of its shell and foundation were incorporated into this building for the Union National Bank, which took occupancy in May, 1949. In 1969 the bank merged with the Columbia National Bank to form the Columbia Union National Bank. 44 Description of Environment and Outbuildings Commercial buildings are to the east, south, and west of this structure. To the north is a parking facility. 45 Sources of Information 45 Prepared by BP #13567 Sherry Piland 47. Organization KC Star, Dec. 22, 1968 Landmarks Commission KC Star, Jan. 9, 1949, p. 5D. 48 Date 49 Revision Data(s) KC Star, June 11, 1944, p. 4D 112/11/80

KC Star, April 20 1948, p. 5

HISTORIC INVENTORY
Columbia Union National Bank
Page 2

42. (cont'd) The building contains 60,000 square feet.



2/11/81

KC Star, June 17, 1951

KC Star, June 28, 1931, p. 1D.

WP #1402



Office of Historic Preservation, P.O. Box 176, Jefferson City, Missouri 65101 HISTORIC INVENTORY JA-AS-005-541 4 Present Name(s) 59-C Demaree Stationery Company; Moss Instant Printers Jackson 5 Other Name(s) 3 Location of Negatives CBD #27-7 Doric Theater 0173 Landmarks Commission Jackson 16 Thematic Category 6 Specific Location 28. No of Stories 29. Basement? YesXX 17 Date(s) or Period 908-10 Walnut 1917; 1923 30. Foundation Material Style or Pesion classical elements 72 If Rural, Township & Vicinity stone 7 City or Town 31. Wall Construction Kansas City, Missouri 8 Site Plan with North Arrow 19. Architect or Engineer Greenebaum & masonry Hardy(1917); McIlvaine (1923) 32. Roof Type & Material 20 Contractor or Builder Swenson Const. flat; tar/gravel Co.(1917); Patti-Moore Const. Co. 33. No. of Bays Front Side 21. Original Use, If apparent theater OSA ODF 34. Wall Treatment 22 Present Use terra cotta Q+ 35. Plan Shape rectangular commercial 23 Ownership Public 14 36 Changes Addition . Walnut Private XI Altered . X (Explain in 842) Moved i 24. Owner's Name & Address. if known N Condition Interior 9 Condinates UTM Exterior good 25. Open to Yes XI Preservation Yes . Public? Underway? No i X Sile Structure 1 . Building X Object i i 26. Local Contact Person or Organization 39 Endangered? Yes II By What? Landmarks Commission No IX 11 On National Yes . 12 Is II Eligible? No XI No . X 27. Other Surveys in Which Included Yes X 13 Part of Estab Yes 14 District Visible from Yes · X No X Hist Dist ? Potent'l? No I Public Road? 41. Distance from and 15 Name of Established District Frontage on Road 41 feet on Walnut 42 Further Description of Important Features The facade is divided into 2 store The facade is faced with terra cotta. The only decorative feature is a cavetto molding across the lower parapet wall with an anthemion band below it.

43 History and Significance -- In 1917 Mrs. Margaret Ridge had a two-story theater constructed on this site. The theater was never financially successful, so in 1923 it was remodeled for commercial use. One of its first uses after remodeling was as the Doric Billiard Parlor. It has been leased to the Demaree Stationery Company since 1935.

44 Description of Environment and Outbuildings Commercial buildings surround this structure.

45 Sources of Information

Western Contractor, Aug. 29, 1917, p. 18; Aug. 22, 1923, p. 36 Kansas City Star, April 22, 1923, p. 4F

WP# 61134

2 County

Lat Lung


Register?

BP# 77951; 23288A; 12306 KC Star, Sept\_15, 1935, p 4D.

Sherry Piland 47. Organization


46. Prepared by

Landmarks Commission 49 Revision Date(s) 48. Date 6/10/80



Office of Historic Preservation, P.O. Box 176, Jefferson City, Missouri 65101 HISTORIC INVENTORY JA-AS-005-542 No. 60-B 80. First Federal Building 2 County 5 Other Name's) Jackson 3 Lucation of Negatives CBD# 34-15 Landmarks Commission 16 Themalic Calegory & Specific Location 28 No of Stories 29. Basement? Courty acksor Ves IX 915 Walnut 17 Date(s) or Period 1956-58 30. Foundation Material H Aural, Township & Vicinity 18 Style or Design 7 City or Town concrete 31. Wall Construction Kansas City, Missouri 19 Architect or Engineer Site Plan with North Arrow concrete block J.F. Lauck 32. Roof Type & Material Contractor or Builder Winn-Senter Const.Co. flat: tar/gravel 33. No. of Bays Front Side 915 21. Original Use, If apparent Present Name(s) commercial 34 Wall Treatment Walnut 22 Present Use stone; terra cotta 35. Plan Shape rectangular commercial 23 Ownership Public 1 1 36. Changes Addition . Walnut Private XX (Explain Attered . m #42) Moved . 24. Owner's Name & Address. N of known 37 Condition Interior Curryingles Exterior good Lat Lung 25 Open to YesXX Preservation Yes . Public? No II Underway? No X. Sile Structure L Object | | Building 26 Local Contact Person or Organization Endangered? Yes II By What? No IX 11 On National Ves I 12 is it Landmarks Commission NoXX Eligible? Register? No X 27. Other Surveys in Which included Yes XX 13 Part of Estab 14 District Yes Visible from Yes X Potent'17 HIST DIST 7 No X Public Road? No . 15 Name of Established District Distance from and Frontage on Road 24 feet on Walnut 42 Further Description of important Features This building is visually joined by the facade treatment to 917-19 Walnut, to the south. Red granite Other Name(s) veneers the 1st floor of both buildings. Theupper floors are veneered with terra cotta. The 2nd & 3rd floor windows are rectangular, fixed, and set in aluminum frames. Metal spandrels are placed above each window. 43 Missory and Significance The First Federal Savings and Loan Association erected this building and joined it to their headquarters to the south. The building cost \$200,000. firm was organized in 1934. 44 Description of Environment and Outbuildings Commercial buildings are located to the north, south, east and west of this structure. 45 Sources of information 46. Prepared by BP# 18583, WP# 10444 Sherry Piland 47. Organization il 1" 9999 1 69 th Landmarks Commission 48. Date | 49 Revision Date(s)

12/17/80



Office of Historic Preservation, P.O. Box 176, Jefferson City, Missouri 65101 HISTORIC INVENTORY JA-AS-005-543 4 Present Name(s) 1 No 916 Walnut Street Building 59-D County Other Name(s) Jackson 3 Lucation of Negatives CBD# 27-8 Ridge Arcade Landmarks Commission 28 No of Stories 16 Themalic Calegory Specific Location 29. Basement? Yes IX Date(s) or Period 916 Walnut 1915 30. Foundation Material 18 Style or Design concrete Il Rural, Township & Vicinity City or Town 69 Kansas City, Missouri 31. Wall Construction Gothic elements steel frame 19. Architect or Engineer M Site Plan with North Arrow Smith, Rea, & Lovitt 32. Roof Type & Material flat; tar/gravel 20 Contractor or Builder G.A. Fuller Construction Co. No. of Bays Front Side 21. Original Use, if apparent commercial 34. Wall Treatment Present Use terra cotta 35. Plan Shape rectangular commercial 23 Ownership Public I 36. Changes Addition . Walnut Atteredxix Private X X (Explain in 842) Moved i 24. Owner's Name & Address. if known Condition Interior 9 Coordinates good Exterior Lal Lung 25. Open to Preservation Yes XX Yes . Public? Underway? No ix Sale Structure ! . Object I i Building X Endangered? 26 Local Contact Person or Organization Yes II By What? No IX Landmarks Commission Is II Yes IX 11 On National Yes .. Eligible? No II Register? No X 27. Other Surveys in Which included District Yes IX 13 Part of Estab Yes Visible from Yes X No X No I Public Road? Potent'l? HIST DIST 7 No i 41. Distance from and 15 Name of Established District Frontage on Road 57 feet on Walnut 42 Further Description of Important Features The 1st floor appears altered by the Other Name(s) application of marble veneer. The upper floors are divided into bays slender colonettes. These floors are fenestrated with double hung, sash windows. Metal spandrels are above the windows in floors 3 through Photo Terra cotta spandrels separate the 2nd & 3rd floor windows. pilasters with tabernacle terminations divide the 2nd floor into 3 bays. Terra cotta Gothic ornamentation and a floral frieze are above the 7th floor windows. 43 History and Significance -- In 1891 Dr. Isaac M. Ridge, a pioneer physician, erected a four-story building on this site. That building burned in 1909 and was replaced by this building. completed in 1916. A wide variety of tenants have occupied the building, including doctors, lawyers, and investment firms. The building was originally connected by an arcade to the New Ridge Building on Main, that has since been demolished. 44 Description of Environment and Outbuildings Commercial buildings are located to the north, south, east and west of this structure. 46. Prepared by Sherry Piland 45 Sources of Information Western Contractor, May 5, 1915, p. 27 BP# 11612 47. Organization Kansas City Star, Aug. 15, 1915, p. 8A. WP# 3003 Landmarks Commission

48. Date 49 Revision Date(s)

12/16/80

Kansas City Star, June 20, 1915

Kansas City Star, Oct. 16, 1932

Kansas City Star, August 10, 1947



Office of Historic Preservation, P.O. Box 176, Jefferson City, Missouri 65101 HISTORIC INVENTORY JA-AS-005-544 4 Present Name(s) 60-C First Federal Savings and Loan Association 803A 0175 County 5 Other Name's) Jackson 919 Walnut Street Builder 3 LU ation of Megatives CBD #34-14 Landmarks Commission 26 No of Stores 16 Themalic Calegory & Specific Location Courty 29. Basement? 917-19 Walnut Ves I ackson 17 Date(s) or Period MO c. 1916 30. Foundation Material 18 Style or Design M Aural Township & Vicinity concrete 7 City or Town 31. Wall Construction Kansas City, Missouri msaonry WD 19 Architect or Enginee Sile Plan with North Arrow 32. Roof Type & Material 20 Contractor or Buildar flat: tar & gravel 33. No of Bays Front 21. Original Use, if apparent Prosent Name(s) ACC 34 Wall Treatment 4 commercial stone; terra cotta 22 Present Use 19 commercial 35 Pien Shape rectangular Walnu Public I ! 36 Changes 23 Ownership Addition Private IX (Explain Affiered I Walnut m 842) Moved I 24 Owner's Name & Address. d known 37 Condition MATERIA Curringles UTM dood FERMINO Lung 25 Open to XXXeV Preservation Public? Underway? No y Structure 1 Sile Building XX Object 11 39 Endangered? 26 Local Contact Person or Organization Ves II By What? No Y 11 On National Yes II 12 Is II Yes .. Landmarks Commission NO XX Engible? Novy Register? 27 Other Surveys in Which Included Yes XX 14 District 40 Visible from 13 Part of Estab Yes Aes X. No XX Poleni'l? Public Road? MIST DIST ? No . Distance from and 15 Name of Established District Frontage on Road 50 feet on Walnut 42 Further Description of important features The facade treatment visually joins this building and the building to the north, 915 Walnut. The 1st floors Other Nametal of both buildings are veneered with red granite, while terra cotta veneers the upper floors. Plate glass windows and a recessed entrance mark the 1st floor. 43 Missory and Significance This building was purchased by First Federal Savings and Loan Association in 1950 and remodeled at that time. When the company constructed a new building adjoining this building on the north, the two buildings were visually united by the facade treatment. The building had previously housed various commercial firms. 44 Description of Environment and Outbuildings This building is surrounded by other commercial structure WP #28500 46 Prepared by Sherry Piland BP #86931 47. Organization KC Star, March 4, 1956 Landmarks Commission KC Star, Jan 5, 1958 48 Date 49 Revision Dolets) KC Star, Jan 10, 1958 1/5/81



HISTORIC INVENTORY TA-AS-005-545 Present Name(s) No 59-E Missouri Bank & Trust Company County 5 Other Name's) Jackson Lux ation of Negatives CBD #38-4 Missouri Savings Association Bank Landmarks Commission 16 Themalic Calegory 28 No of Stories Specific Location Jacksor 29. Basement? 920 Walnut 17 Date(s) or Period No : 30. Foundation Material 1910-11 If Rural, Township & Vicinity Style or Design City or Town 31. Wall Construction Kansas City, Missouri steel frame Site Plan with North Arrow 19 Architect or Engineer 32. Roof Type & Material Shepard and Farry flat; tar & gravel H. L. Stevens and Co. 33. No. of Bays 920 21. Original Use, If apparent Front 1 Present bank 020 34 Wall Treatment Walnut 22 Present Use stone Nem 35. Plan Shape bank rectangular 23 Ownership Public I 36. Changes Addition Walnut AtteredXX Private N (Explain m 842) Moved . 24. Owner's Name & Address. of known 37 Condition Interior Curdinales Exterior good Lat Lunu 25 Open to Yes IX 38. Preservation Yes . Public? No II Underway? Sile Structure ! . No K BuildingX Object 11 26 Local Contact Person or Organization Endangered? Yes II By What? On National Yes IX No K Landmarks Commission Yes .. 12 Is It Eligible? Register? NoX No II 27 Other Surveys in Which included Yes 'X' 3 Part of Estab Yes 14 District Visible from Yes X Nox Potent'1? No I i HIST DIST ? Public Road? No . : 5 Name of Established District Distance from and Frontage on Road 27 feet on Walnut 2 Further Description of Important Features The 1st floor was modernized in 1954 other (architects: Keene & Simpson, with associate John T. Murphy). this time two granite columns which flanked the entrance were removed. Now the 1st floor is total glass set in aluminum frames in an irregular manner. The 2nd & 3rd floors also feature varied window treatment, with the 3rd floor windows set in an arch. A shaped parapet wall tops the building. Missory and Significance This bank was founded in 1891 by Watt Webb and was originally located at 720 Delaware. It first operated primarily as a savings bank. Description of Environment and Outbuildings This building is surrounded by other commercial buildings. Sources of Information 46. Prepared by WP #42635 BP #9840 Kansas City Star, Aug 22, Sherry Piland Kansas City Journal, i Western Contractor, May 11, 1910, p. 7. 47. Organization March KC Star, March 26, 1911, p. 4A. Landmarks Commission 28, 1911 48. Date 49 Revision Dete(s) Kansas City Star, Sept 30, Kansas City Journal, August 8, 1926.

1/2/81

1973.

Office of Historic Preservation, P.O. Box 176, Jefferson City, Missouri 65101



Kansas City Star, December 13, 1959; January 11, 1970

1111 01 11-- - 101/ - /0 -



| THE RESERVE OF THE PARTY OF THE | C INVENTORY  | JA-AS-005-54  |
|--|--|---|
| 0<br>59-F  | Commerce Bank of Kansas City   | y 803A0177 5  |
| ounty  | 5 Other Namers)  | name -  |
| Jackson  Hation of Negatives CBD #53-  | National Bank of Commerce;   |   |
| andmarks Commission  | 16 Thematic Category   | 28 No of Stories 15                                   |
| 222-24 Walnut  |  | 29. Basement? Yes IX No :                             |
| 722-24 Wainut  | 17 Data(s) or Period   | 30. Foundation Material                               |
| Iv or Town If Rural, Townsh  | 1908  1908  19 & Vacanty 18 Style or Design  | 01  |
| Cansas City Missouri   | 00   | 69 31. Wall Construction                              |
| e Plan with North Arrow  | Jarvis Hunt (Chicago)  | 32. Roof Type & Material                              |
| 3  | 20 Contractor or Builder   | flat: tar & gravel                                    |
| 24   | George A. Fuller Co.  21. Original Use, if apparent                                | 33. No. of Bays<br>Front 9 Side 7                     |
| (12  | bank O2D O2A   | 34 Wali Treatment stone                               |
| E, 102 Sheet   | 22 Present Use<br>bank   | rogtangular   |
|  | 23 Ownership   | Public 11 36 Changes Addition .                       |
| ·Walnut  |  | Private M (Explain Moved )                            |
|  | 24. Owner's Name & Address, of known   | 37 Condition  |
| cordinates UTM   |  | Interior  |
| d .  |  | Yes IX 38 Preservation Yes                            |
| unij   | 25 Open to Public?   | No 11 Underway? No x                                  |
| Site:  | Object 11 26 Local Contact Person or Organi  | Dy What? No L   |
| on National Yes 12 is it   | Ves X Landmarks Commission  Die? No : 1 27 Other Surveys in Which include          | X   |
| Part of Fernan Year 14 Dist  | rict Yes w   | then 40 Visible from Yes X                            |
| rist Dist ? No X   | entil? No ii   | Public Road? No ::                                    |
| Name of Established District   |  | Frontage on Road                                      |
|  |  | 162 feet on Walnut                                    |
|  | feetwes The main facade faces east.  |   |
|  | 3 arches that extend through the 2   | A secondary entrance, at the north                    |
|  | is protected by a large metal cano   |   |
|  | south facade. The first 3 floors   |   |
|  | ed with a lighter colored stone.   |   |
| nestrated with pair, d   | ouble hung sash windows. The top   | floor windows terminate in ornate                     |
| Tistory and Significance The   | ate projecting modificed was roigan  | mized in 1865 as the Kansas                           |
| ty Savings Association   | . In 1882 the name was changed to<br>Bank of Commerce. In 1921 the bank            | ok merged with the Commerce                           |
| 188/ to the National   | has occupied this site since 1898  | with the present building                             |
| placing an earlier str   | ucture.  |   |
|  |  | lanated to the worth could be                         |
|  | Dutbuildings Commercial buildings are To the west is a commercial/parkin           |   |
| of or this partaing.   | To the wood to a commercial, parking   | -3 343 Compton  |
|  |  |   |
|  |  |   |
| Sources of information   | KC Times, Nov 21, 1908 KC Star S   | Sept 34, p 3 46 Prepared by                           |
| Scurces of Information  WP #'s 5836; 22963   | KC Star, Nov 20, 1940  | Sherry Piland   |
| WP #'s 5836; 22963   | KC Star, Nov 20, 1940<br>KC Star, March 15, 1921                                   | Sherry Piland  47. Organization  Landmarks Commission |
|  | KC Star, Nov 20, 1940<br>KC Star, March 15, 1921<br>06, p. 1; Nov. 14, 1906, p. 2. | Sherry Piland   |



| HISTORIC   | c Preservation, P.O. Box 176, Jefferson INVENTORY  | JA-AS-005-54   |
|--|--|--|
| No 60-E County Jackson Lucation of Negatives CBD# 27-9   | 4 Present Name(s) United Missouri Bank (Bankcard Divisions) 5 Other Name(s) Missouri Abstract and Title Insurance  | on) 80 JA 0178   |
| Landmarks Commission  Specific Location  925-27 Walnut  City or Town II Rural Township & Kansas City, Missouri  Site Plan with North Arrow   | 19. Architect or Engineer  Keene & Simpson  20 Contractor or Builder  H.H. Fox  21 Original Use, if apparent  commercial   | 28 No of Stories 2  29. Basement?  Yes Xi No:. 30. Foundation Material Concrete  31. Wall Construction masonry  32. Roof Type & Material flat; tar/gravel  33. No. of Bays  Front 3 Side |
| Walnut Coordinates UTM   | 22 Present Use  COMMERCIAL  23 Ownership  Public 1 * Private XX  24. Owner's Name & Address, if known  | 35. Pian Shape rectangular  36. Changes (Explain in #42)  37. Condition Interior Exterior Good   |
| Site Stre  | 25 Open to Public?  26 Local Contact Person or Organization  Landmarks Commission  27 Other Surveys in Which Included  Yes :X No ::  | 38. Preservation Underway? Yes :- No X:  39. Endangered? Yes :- No X:  40. Visible from Yes :- No ::  41. Distance from and Frontage on Road  48. feet on Walnut                         |
| is used as a base for the mather lst & 2nd floor windows stone. A strip of 10 paire windows flank the entry. The windows flank the entry. This but 1955 this company merged windows of this building were by Title Company. In 1967 to | The centrally located entrance is read ain facade, for the entry surround, and . The rest of thefacade is veneered wid, casement windows fenestrates the 2nd the building contains 14,880 square feet liding was erected by the Missouri Abstrath the Kansas City Title Company. At the coined with the building to the south, on the building was purchased by the City No. | as inserts between the alight colored floor. Similar  act and Title Company. his time the interior ccupied by the Kansas ational Bank and Trust  |
| Sources of Information  NP# 7121, BP# 16227 Cansas City Star, July 15, 1   | Commercial buildings are to the in   | 46 Prepared by Sherry Piland 47. Organization  |

Kansas City Times, Sept. 2, 1971



Office of Historic Preservation, P.O. Box 176, Jefferson City, Missouri 65101
HISTORIC INVENTORY JA-AS-005-549 Nº60-F United Missouri Bank 2 County 805A0179 Other Name(s) Jackson 3 Lucation of Negatives CBD 11-7 Kansas City Title and Trust Building Landmarks Commission 28. No of Stories 16. Themalic Category 6 Specific Location 29. Basement? Jackson No 17 Date(s) or Period 935 Walnut 30. Foundation Material 1922 concrete 18 Style or Design If Rural, Township & Vicinity 7 City or Town 31. Wall Construction classical elements Kansas City, Missouri reinforced concrete 19. Architect or Engineer 8 Site Plan with North Arrow 32. Roof Type & Material Sunderland and Besecke flat; tar/gravel 20 Contractor or Builder Mosby-Goodrich Construction Co. 33. No. of Bays United Side Front 21. Original Use, if apparent 34. Wall Treatment commercial O2A brick 22 Present Use 35. Plan Shaperectangular commercial Public 11 36. Changes Addition . 23 Ownership Aftered IX Walnut (Explain Private XI Moved I in #42) 24. Owner's Name & Address, 37. Condition if known Interior 9 Coordinates good Exterior Lat 38. Preservation Yes XI 25. Open to Lung Underway? No iX Public? Structure ! Sile 39. Endangered? Yes II 26. Local Contact Person or Organization Object | 1 Building X' No IX By What? Landmarks Commission Yes X 11 On National Yes .. 12 Is II Eligible? No II 27. Other Surveys in Which Included Register? No .Y Visible from Yes ·X Yes XI 13 Part of Estab Yes 14. District Public Road? No : Potent'l? Hist Dist ? No X 41. Distance from and 15 Name of Established District Frontage on Road 49 feet on Walnut 42 Further Description of Important Features The first floor of this building was Ather radically altered in 1971 by steel piers and bars. A recessed glass wall and entrance are framed by stainless steel. The original terra cotta frieze runs above this. The second and third floor windows Photo are united in a terra cotta surround with a decorative panel between the windows. The remainder of the fenestration consists primarily of paired double hung sash windows. A string course runs between the top windows and a denticulated cornice. 43 History and Significance The Kansas City Title and Trust Company, incorporated in 1915, was the first Missouri company established for the purpose of insuring titles to real estate. By 1954 the company was operating in 22 states. The Kansas City firm was purchased by the Chicago Title Insurance Company in 1961. The firm occupied the building until 1971. 44 Description of Environment and Outbuildings -- Commercial buildings are I coated to the north, south, east, and west of this structure. A passageway at the upper level connects this building, across an alley, to the building on the east. 46. Prepared by 45 Sources of information Kansas City Star, Sept. 24, 1961. Sherry Piland WP# 6494 Kansas City Times, March 23, 1961; Sept. 2, 1971. 47. Organization BP# 13317 Western Contractor, July 5, 1922, p. 34 Kansas City Star, May 21, 1922, p. 15D KC Star, Oct Landmarks Commission KC Star, Oct. 17, 1971. 48. Date 49 Revision Date(s) Kansas City Star, July 30, 1922, p. 12D 1/21/81 Kansas City Star, July 16, 1922, p. 12D



Kansas City Star, Sept. 14, 1969, p. 2F



HISTORIC INVENTORY TA-AS-005-551 4 Present Name(s) 76-F National Fidelity Life Company 2 County 5 Other Name(s) Jackson Lucation of Negatives CBD #38-2 Republic Building; Continental Building Landmarks Commission 16 Thematic Category 28 No of Stories Specific Location Jackson 1002 Walnut Courty 29. Basement? Yes IX 17 Date(s) or Period No : 30. Foundation Material 1912-13 If Aural Township & Vicinity 18 Style or Design concrete 7 City or Town Sullivanesque (00 31. Wall Construction Kansas City, Missouri steel frame 19. Architect or Engineer Site Plan with North Arrow Frederick Gunn 32. Roof Type & Material 100 Free Contractor or Builder flat; tar & gravel Harvey Stiver 33. No. of Bays Front 1002 21. Original Use, if apparent Side 3 Present Namels Bank 34 Wall Treatment 22 Present Use terra cotta Walnut commercial 35. Plan Shape rectangular 23 Ownership 36. Changes Public I Addition Walnut Private VI (Explain Attered i m 842) Moved 24. Owner's Name & Address, N if known Condition Interior UTM Cuordinates poop Friend Lung 25 Open to Yes KI 38. Preservation Yes . . Public? Underway? Structure ! . Sile Building X Object I i 39 Endangered? 26 Local Contact Person or Organization Yes II By What? No IX Yes XI 11 On National Yes ... 12 Is II Landmarks Commission Register Eligible? No 11 No .X 27. Other Surveys in Which Included sthen 13 Part of Estab Yes 14 District Yes X 40 Visible from Yes . A No 'X Potent'1? HIST DIST ? Noli Public Road? No : Distance from and 15 Name of Established District Frontage on Road 48 feet on Walnut 42 Further Description of Important Features The first floor has been modernized, Sossibly around 1959. The corner building is veneered with white terra cotta. Paired corinchian pilasters mark Olher Name(s) the bays of the 2nd floor, which is fenestrated with triple pane, fixed windows with metal panels in the transom areas. The upper floors contain paired, double hung, sash windows. Panels of swag ornamentation are located above each window pair. Sullivanesque ornament adorns the top floor, surrounding the curved window lintels. 43 History and Significance The National Bank of the Republic, for whom this building was constructed, was formed around 1910 through a merger with the Central National Bank. The new bank The building was acquired by the National Fidelity Life was headed by G. M. Smith. Insurance Company in 1928. 44 Description of Environment and Outbuildings Commercial buildings are located to the north, south, east and west of this structure. 45 Sources of Information 45. Prepared by WP #3898 Kansas City Journal Post, Aug 26, 1928, p. 8B Sherry Piland Western Contractor, March 27, 1912, p. 23. KC Star, March 18, 1923 47. Organization KC Star, June 1, 1912, p. 8. Landmarks Commission p. 4F 48 Date 49 Revision Data(s) BP #10617; 59797 KC Star, Jan 28, 1951, 1/21/81 p. 16D


KC Star, April 14, 1912.

Kansas City Times, Feb. 19, 1910

Office of Historic Preservation, P.O. Box 176, Jefferson City, Missouri 65101



|  |  | ty Avenue, Suite 215,<br>mbia, Missouri 65201<br>JA-AS-005-552 | 2                |
|--|--|--|------------------|
| 1. No. 76-G  | Present Name(s) Pebley Floral (1004 Walnut) Dixon's Chili (1006 Walnut)  |  | 76               |
| 2. County Jackson 5.   | Other Name(s)  |  | 9-0              |
| 3 Location of NegativesCBD#23-12,<br>Landmarks Commission 23-11  | Weber Brothers   | 4ED BY FIFE  | -                |
| 6 Specific Location  | 16. Thernatic Category   | 26. No. of Stories 2   | ~                |
|  |  | 29. Basement? Yes!   | Jackson          |
| 1004 Walnut  | 17. Date(s) or Period<br>1886  | No 1.  | KS               |
| 7. City or Town If Rural, Township & Vice  |  | rubble stone   | 9                |
| Kansas City, Missouri  |  | 31. Wall Construction  |                  |
| 8. Site Plan with North Arrow  | 19. Architect or Engineer  | brick 32. Roof Type & Material                                 |                  |
|  | 20. Contractor or Builder  | flat; tar/gravel   |                  |
|  |  | 33. No. of Bays Front Side                                     | Pe A             |
|  | 21. Original Use, if apparent commercial   | Front Side  34. Wall Treatment                                 | Pebley I         |
|  | 22. Present Use  | brick  | Sen              |
|  | commercial   | 35. Plan Shape rectangular                                     | FIO              |
| 111.+  | 23 Ownership Public !! Private XX  | 36. Changes Addition :: (Explain Altered IX                    | ra               |
| Walnut   | 24. Owner's Name & Address   | in #42) Moved  |                  |
| N  | if known   | 37. Condition  | 004<br>004       |
| 9. Coordinates UTM   |  | Interior good  | 004 Wal          |
| Lui.<br>Long.  | 25. Open to Yes XX   | Exterior good  38. Preservation Yes                            | a r              |
| 10. Site!: Structure   | Disting.   | Underway? No iX  | nut              |
| Building IXI Object  | 26. Local Contact Person of Organization   | 39. Endangered? Yes I  | ut)              |
|  | Landmarks Commission  27. Other Surveys in Which Included  | By What? No 1X   |                  |
| or the college to the | 3 <del>  X</del>   | 40. Visible from Yes !X Public Road? No !:                     | (1000            |
| 15. Name of Established District   |  | 41. Distance from and  | Wd               |
|  |  | Frontage on Road<br>48 ft. on Walnut                           | -                |
| 42 Further Description of Important Features   |  |  | - Ę              |
| store fronts. 1004 Walnut has windows. The upper portion of metal sheathing. The first floof natural wood and brick to estretches across the first floof facade is hidden behind metal   |  | tion Photo   | Circi italine(5, |
| first located at 1007 Main. In huge harness contracts for earl of the Wells-Fargo Express Comp for Swift and Company.  | Brothers established a leather busine 1886 they moved to this location on y railroad construction work, made stany, and for 50 years did all the lea | Walnut. The firm filled<br>orm covers for the horses           | 100              |
| west of this building. A surf  | Commercial buildings are located to face parking lot is to the east.   | the north, south, and  |                  |
| 5 Sources of Information   |  | 46. Prepared by  |                  |
| Kansas City Star, August 12, 1   | Sherry Piland  |  |                  |
| WP# 4987; 91411  |  | 47. Organization Landmarks Commission                          |                  |
| Kansas City Star, Feb. 7, 1936   |  | 48. Date 49. Revision Date(s)                                  |                  |
| Kansas City Star, June 9, 1938   |  | 9/10/80  |                  |



## Dixon's Chili

State Historical Survey and Planning Office, 909 University Avenue, Suite 215,

Columbia, Missouri 65201



Columbia, Missouri 65201 HISTORIC INVENTORY TA-AS-005-554 1. No. 4. Present Name(s) 2. County Lane Bryant 5. Other Name(s) Jackson Optical Company 905 A0190 3. Location of Negatives CBD# 13-21 Moore Building; Merry Building Landmarks Commission 6. Specific Location 16. Thematic Category 28. No. of Stories 29. Basement? Yes IX 1011 Walnut Jackson 17. Date(s) or Period No I 1890 (addition, 1909) 30. Foundation Material . If Rural, Township & Vicinity 18. Style or Design Kansas City, Missouri 31. Wall Construction Romanesque Revival 4 B. Site Plan with North Arrow 19. Architect or Engineer masonry 32. Roof Type & Material 20. Contractor or Builder flat; tar/gravel C.R. Munger (1909) 33. No. of Bays 1 Present Name(s) 1011 Walnut Front 4 21. Original Use, if apparent commercial O>A 34. Wall Treatment 22. Present Use brick; stone 4/ 35. Plan Shape commercial rectangular 23 Ownership Public 1 36. Changes Addition :: Privatexx Altered XX Walnut (Explain in #42) 24. Owner's Name & Address, Moved 1 if known N 37. Condition Interior 9. Coordinates UTM Lat Exterior dood Long 25. Open to Yes X 38. Preservation Yes i Public? No I Underway? Site ! : Structure 1 No iX **Building XX** Object ! ! 26. Local Contact Person or Organization 39. Endangered? Yes I Yes X 11. On National Yesli 12 Is It By What? No IX: Landmarks Commission Register? Eligible? No K! 27. Other Surveys in Which Included 13. Part of Estab. Yes II District Yes X 40. Visible from Yes XX Hist. Dist.? No KI Potent'l? No: Public Road? No !! 15. Name of Established District 41. Distance from and approx Frontage on Road 48 feet on Walnut 42. Further Description of Important Features An additional story was added to this building in 1909. The 1st & 2nd floors have been more recently modernized, with a marble veneer covering the 2nd floor which is fenestrated by a band of fixed windows. Ornamental stone spandrels divide the rd of fixed windows. floor windows. Piers unite these windows that terminate in rounded arches, springer from ornate corbels that each contain a face. The upper sash of the 4th floor windows consists of a fan light. Corbeled cornices run above the 5th & 6th floor windows. 43. History and Significance -- This building was constructed for Lysander R. Moore, a Kansas City businessman and one of the founders of the Bullene, Moore and Emery Department Store, later known as Emery, Bird and Thayer. This building was probably an investment property. By 1895 it was occupied by the Merry Optical Company. C. L. Merry opened a jewelry store in Kansas City in 1892 and in 1894 formed the Merry Optical Company. By 1920 the company had 33 branches and in 1922 merged with the American Optical Company of Southbridge, Massachusetts.(cont. on 2nd page 44. Description of Environment and Outbuildings Commercial buildings are located to the west and south of this structure. Surface parking lots are to the north and east. 45 Sources of Information 46. Prepared by Water permit #10767 Sherry Piland BP# 46498 47. Organization Kansas City Times, May 8, 1906 Landmarks Commission 48. Date 49. Revision Date(s) Kansas City Star, Nov. 30, 1934 1/14/81

State Historical "Irvey and Planning Office, 909! 'versity Avenue, Suite 215.

HISTORIC INVENTORY--page 2
Lane Bryant
1011 Walnut K.C.

43. In 1906 C. L. Merry was elected to the City Council of Kansas City.



Office of Historic Preservation, P.O. Box 176, Jefferson City, Missouri 65101
HISTORIC INVENTORY
JA-AS-005-55 JA-AS-005-555 Present Name(s) 76-I Metropolitan Savings County 5 Other Name(s) entered Jackson 82790015 3 Lucation of NegativesCBD# 23-14 D.O. Smart Building Landmarks Commission 28. No of Stories 16. Themalic Category 6 Specific Location 29. Basement? Yes XX No : . 17 Date(s) or Period 1012-14 Walnut c. 1888; (1962, remodel) 30. Foundation Material 18 Style or Design If Rural, Township & Vicinity 7 City or Town 31. Wall Construction Kansas City, Missouri masonry 19. Architect or Engineer 8 Site Plan with North Arrow Knox and Guinotte (attrib.) 32. Roof Type & Material flat: tar/gravel 20 Contractor or Builder 33. No. of Bays Jesse Hastings Co (1962) Front Side 21. Original Use, if apparent 34. Wall Treatment commercial brick 22 Present Use 35. Plan Shape rectangular commercial Addition XX 36. Changes Public 1 tan 23 Ownership Private XX (Explain Walnut in #42) Moved : 24. Owner's Name & Address, Savings 37. Condition if known Interior UTM & Cuordinates good Exterior Lat Yes XX Preservation Yes : 25. Open to Lung No iX Underway? Public? Structure 1 Sile: Yes II 39. Endangered? 26. Local Contact Person or Organization Object 11 Building X No IX By What? Landmarks Commission Yes XX 12 Is It 11 On National Yes .. 27. Other Surveys in Which Included Eligible? Register? No .X Visible from Yes . X Yes XX 14 District 13 Part of Estab Public Road? No . Potent'l? Noli No 'y HIST DIST ? Distance from and 15 Name of Established District Frontage on Road 48 feet on Walnut 42 Further Description of Important Features The 1st floor was remodeled in 1962 with a new entrance D. ( featuring white marble and gray solar glass. Marshall & Brown were architects for the remodeling. Some of the 2nd floor windows have been altered. The 3rd, 4th, & 5th Floors are fenestrated with paired double hung, sash windows. The central windows of the central windows of the Smart have arched heads with keystones. Denticulated string courses run above the 2nd & 4th floors The building terminates with a modillion cornice. Building 43 History and Significance An early tenant of this building was the Carl Hoffman Music Company (c. 1895). By 1911 it was occupied by the Household Fair Furniture Company. From 1940-1961 the building was occupied by Mindlin's Clothing. 14 Description of Environment and Outbuildings Commercial buildings are located to the north, south, east and west of this building. 46. Prepared by 45 Sources of Information Sherry Piland Kansas City Star, Jan. 21, 1962 47. Organization WP# 3439 Landmarks Commission

48. Date 49 Revision Date(s)

1/19/81

Kansas City Times, April 22, 1888

Kansas City Views, 1900, p. 37

KC Star. April 6, 1969



Office of Historic Preservation, P.O. Box 176, Jefferson City, Missouri 65101 HISTORIC INVENTORY -AS-005-556 4 Present Name(s) 805A0181 No 77-D Meyer Jewelry Corporation County 1013-1015 Walnut Other Name's) Jackson Les ation of Negatives CBD #34-12 J. W. Jenkins' Sons Music Co. Landmarks Commission 28 No of Stories 16 Thematic Calegory Specific Location fackson 29. Basement? Yes Ki No Date(s) or Period 1013-15 Walnut 1901 (remodeled, 1949) 30. Foundation Material If Rural, Township & Vacinity 18 Style or Design 7 City or Town 31. Wall Construction Missouri Kansas City. masonry ul 19 Architect or Engineer Sile Plan with North Arrow 32. Roof Type & Material flat; tar & gravel F4 20 Contractor or Builder 33. No. of Bays Hollinger & Mitchell
21. Original Use, If apparent Sade Front 3 1013-34 Wall Treatment commercial DOA 22 Present Use brick 35. Pian Shape rectangular 5 commercial Walnut 36 Changes Public I Addition 23 Ownership Walnut Altered XX Private X! (Explain Moved I m 842) Owner's Name & Address, 37 Condition of known Other Interior 62 UTM Currdinales Exterior boop Yes XI Preservation Yes . Lung 25 Open to Public? No II Underway? NoX Structure ! . Sile 39 Endangered? Yes II Building X Object 11 26 Local Contact Person or Organization By What? KOM Yes XI Landmarks Commission is II 11 On National Yes .. NO X Eligible? No II 27 Other Surveys in Which Included Register? Yes X. Visible from 14 District Yes X' Part of Estab Yes . Potent'l? Public Road? No :: NO 'V No I MIST DIST ? Distance from and 15 Name of Established District Frontage on Road 48 feet on Walnut 2 Further Description of Important Festures The first floor and entrance were Olher Nametal remodeled in 1949. A denticulated cornice runs above the 2nd floor. The fixed, paired windows of the 3rd through 5th floors have denticulated lintels, egg-and-dart molding along the sills, and a decorative panel of rosettes running up the sides. A cartouche is placed above each of the 6th floor windows. 13 History and Significance The Jenkins Music Company was founded in Kansas City in 1878 by John W. Jenkins, Sr. The firm became one of the largest guitar and madolin manufacturers in the world. They remained at this location until 1912 when a new building was constructed. 4 Description of Environment and Outbuildings A surface parking lot is located to the east and south of this building. To the north and west are other commercial buildings. 46. Prepared by 5 Sources of Information Sherry Piland WP #12934 47. Organization Kansas City Star, Dec. 12, 1901, p. 8. Kansas City Architect & Builder, May 1902, p. 15. Landmarks Commission 48 Date 49 Revision Date(s)

1/5/81

RP #26867A



HISTORICANVENTORY JA-AS-1005-55 4. Present Name(s) 1. No. 76-J Woolf Brothers 2. County Jackson 5. Other Name(s) 3 Location of Negatives CBD# 23-16 82JA00/6 Hewson Building Landmarks Commission 6. Specific Location 16. Thematic Category 28. No. of Stories Jackson 29. Basement? Yes IX 1016 Walnut 17. Date(s) or Period No I . 30. Foundation Material 1912 7. City or Town . If Rural, Township & Vicinity 18. Style or Design 31. Wall Construction Kansas City, Missouri reinforced concrete B. Site Plan with North Arrow 19. Architect or Engineer Smith, Rea, Lovitt 32. Roof Type & Material 20. Contractor or Builder flat; tar/gravel Harvey Stiver 33. No. of Bays Woolf Brothers 21. Original Use, if apparent Front Present Namels commercial 34. Wall Treatment terra cotta 22 Present Use 35. Plan Shape rectangular commercial 23 Ownership 36. Changes Public I ! Addition : Walnut Private 1X (Explain Altered I in #421 Moved : 24. Owner's Name & Address. N if known 37. Condition Interior 8. Coordinates UTM Exterior \_good Lat. Long 25. Open to Yes IX 38. Preservation Yes : Public? No I Underway? Site ! : Structure 1 No : X Building XI Object ! | 26. Local Contact Person or Organization 39. Endangered? Yes I By What? NoIX 11. On National Yes I i 12 Is It Yes :X Landmarks Commission Register? Eligible? No I! No IX! 27. Other Surveys in Which Included 13. Part of Estab. Yes IX Yes II District 40. Visible from Yes ! X Hist. Dist .? No KI Potent'l? No : Public Road? 15. Name of Established District 41. Distance from and Frontage on Road 48 feet on Walnut The first floor consists of display 42. Further Description of Important Features Hewson Building windows. A metal panel above the 1st floor is used to visually unit this building with the building on the south. Slender piers divide the upper floors into 3 bays. The 3rd through 6th floors are fenestrated by paired sash windows in the end bays while the broader central bay contains a central fixed pane flanked by sash windows. The 6th floor windows are set in a segmental arch that extends across the three bays. The terra cotta spandrels between the windows feature a square pattern. A floral (cont'd) 43. History and Significance -- This building was constructed to replace a former Hewson Building on this site, destroyed by a fire on November 30, 1911. James Hewson, an early Kansas City businessman, came to the city in 1869. He first operated a dry goods store. The first Hewson Building he had constructed for his insurance business. 14. Description of Environment and Outbuildings Commercial buildings are located to the north, south, and west of this structure. To the east is a surface parking lot. 5 Sources of Information 46. Prepared by WP# 8285 Sherry Piland Western Contractor, Aug. 7, 1912, p. 14; Aug. 14, 1912, p. 17 Kansas City Star, Nov. 30, 1911, p. 1. 47. Organization Landmarks Commission 48. Date Whitney, Kansas City, Its History and Its People, 1908, Vol. 2, 49. Revision Date(s) 1/6/81 p. 299.

State Historical Survey and Planning Office, 909 University Avenue, Suite 215.

Columbia, Missouri 65201

HISTORIC INVENTORY
Woolf Brothers
Page 2 | DILe Walnut K.C.

42. (cont'd) band extends up each side of the building and across the top, where a central name plate is located.



Office of Historic Preservation, P.O. Box 176, Jefferson City, Missouri 65101 HISTORIC INVENTORY TA-AS-005-558 Present Name(s) 76-K Woolf Brothers 2 County Other Name's) MODATES Jackson 3 to ation of Negatives CBD #23-15 Landmarks Commission 16 Themalic Calegory 28 No of Stories 6 Specific Location 29. Basement? Yes XI Court 1020-24 Walnut No 17 Date(s) or Period 30. Foundation Material 1909 M Aural, Township & Vicinity 18 Style or Design concrete 7 City or Town 31. Wall Construction Kansas City, Missouri commercial Site Plan with North Arrow 19 Architect or Engineer 32 Roof Type & Material Root and Siemens (north portion (North Portion flat: tar/gravel Urban Construction Co 33. No. of Bays Front 4 Sarte 21. Original Use, if apparent Present 020-24 commercial 34 Wall Treatment 22 Present Use brick: terra cotta 35 Pian Shape rectangular commercial Public I ! 36 Changes 23 Ownership Walnu Addition Walnut Anered X. Private IX (Explain on 842) Moved . 24. Owner's Name & Address. 37 Condition Interior Currinales Exterior boop Lat Lung 25 Open to Yes IX 38 Preservation Public? Underway? No X Sile Structure ! . Building X Object 11 39 Endangered? 26 Local Contact Person or Organization Ves II By What? No X Yes A 11 On National Yes .. 12 is it Landmarks Commission Engible? No II Reuister No X 27 Other Surveys in Which Included Yes X 14 District Visible from 13 Part of Estab Yes . Yes X No X Poleni'1? No I Public Road? MIST DIST ? No .: Distance from and 15 Name of Established District Frontage on Road 96 feet on Walnut 42 Further Description of Important Features The north half of this building was constructed in 1909. The south portion, constructed at an unknown date, was remodeled in 1909 by W. A. Bovard, to be compatible with the new building. Both halves are identical in material and design, but slight differences in window height and positioning are noted. The triple windows of floors three through five have terra cotta lintels and sills. A terra cotta cornice is between cont'd) 43 Missory and Significance The Woolf Brothers clothing firm was established in Kansas City in 1879. 44 Description of Environment and Outbuildings Commercial buildings are located to the north, south, and west of this structure. To the east is a large surface parking lot. 45 Sources of Information 46 Prepared by Western Contractor, March 24, Kansas City Star, Dec. 11, 1949 WP #9619 Sherry Piland 1909, p. 14 47. Organization W estern Contractor, April 7, 1909 BP #9247 Landmarks Commission 48 Date 49 Revision Data(s)

9/23/80

Woolf Brothers
Page 2
1020-24 Walnut K.C.

42. (cont'd) the 5th floors windows and the parapet wall.



Columbia, Missouri 65201 HISTORICHNVENTORY JA-AS-005-559 4. Present Name(s) 1. No. 93-G Krigel's Jewelry 2. County 5. Other Name(s) Jackson 3 Location of Negatives CBD# 23-17 Landmarks Commission Lillis Building 82JA0018 6. Specific Location 16. Thematic Category 28. No. of Stories 29. Basement? County Yes I X 1100 Walnut 17. Date(s) or Period 30. Foundation Material 1907 . If Aural, Township & Vicinity 18 Style or Design 7. City or Town 31. Wall Construction Kansas City, Missouri Commercial 8. Site Plan with North Arrow 19. Architect or Engineer steel frame Shepard & Farrar 32. Roof Type & Material 20. Contractor or Builder flat; tar/gravel 33. No. of Bays George L. Brown and Son Side 2 Front 21. Original Use, if apparent Present Name(s) commercial 34. Wall Treatment 22. Present Use brick 35. Plan Shape rectangular commercia1 23 Ownership Public 11 36. Changes Addition : E. 11th Street Private XX (Explain Altered X in #42) Moved i 24. Owner's Name & Address. if known 37. Condition Interior 9. Coordinates Lat. Exterior good Long 25. Open to Yes XX 38. Preservation Yes Public? Underway? No X 10. Site ! : Structure I Building K' Object ! I 26. Local Contact Person or Organization 39. Endangered? Yes I By What? 11. On National Yes I i 12 Is It Yes X Landmarks Commission No X: Register? No K! Eligible? No 1! 27. Other Surveys in Which Included 3. Part of Estab. Yes ! ! 14. District Yes X 40. Visible from Yes X Hist. Dist.? Potent'1? No : No XI Public Road? No !! 15. Name of Established District 41. Distance from and Frontage on Road feet on Walnut 42. Further Description of Important Features -- The first floor has been altered in attempts at modernization. The main entrance to the building was originally centrally located on the north facade. Brick piers divide double sash windows surmounted with transoms into groups of three on Photo the north facade and groups of 4 on the east facade. A slightly projecting cornice tops the building. 43. History and Significance -- This building was constructed as an investment property by J.S. Lillis, President of the Western Exchange Bank. Original plans called for a cafe in the basement, shops on the first floor, and offices above. Liggett Drugs was a long-term tenant. The building was known as the Lillis Building until 1941. 44. Description of Environment and Outbuildings -- Commercial buildings are located to the north, south, east and west of this structure. 5 Sources of Information 46. Prepared by BP # 8533 WP# 14218 Sherry Piland 47. Organization Kansas City Star, April 19, 1907, p. 3 Landmarks Commission Kansas City Star, Mar. 26, 1907, p. 1 48. Date 49. Revision Date(s) Kansas City Star, Aug. 23, 1925 6/25/80 Kansas City Star, Mar. 6, 1960

State Historical Survey and Planning Office, 909 University Avenue, Suite 215,



HISTORIC INVENTORY--page 2 Mercantile Bank & Trust Company

1101 Walnut K.C.

- 42. is housed in the area immediately above the support columns. Moving stairs at the corner of the building site lead to a sunken exterior courtyard, ringed with retail shops. The courtyard is 8 feet below the sidewalk level.
- 43. Associates were also involved in the project.



Office of Historic Preservation, P.O. Box 176, Jefferson City, Missouri 65101
HISTORIC INVENTORY

JA-AS-005 JA-AS-005-561 4 Present Name(s) 1 No 93-H Lerner Shops 2 County 5 Other Name(s) PIDOATES Jackson 3 Lucation of Negatives CBD# 19-18 Landmarks Commission Deardorff Building 16. Themalic Category 28. No of Stories 5 Jackson 6 Specific Location 29. Basement? Yes XI 1104 Walnut 17 Date(s) or Period No : c. 1916 30. Foundation Material 18 Style or Design If Rural, Township & Vicinity 7 City or Town 31. Wall Construction Kansas City, Missouri Gothic elements 19. Architect or Engineer H Site Plan with North Arrow masonry 32. Roof Type & Material flat; tar/gravel 20 Contractor or Builder 33. No. of Bays Front 10 21. Original Use, if apparent Present Name(s) commercial 34. Wall Treatment 22 Present Use terra cotta 35. Plan Shape rectangular commercial 36. Changes 23 Ownership Public 1 Walnut Addition Altered XX Private IXI (Explain In 842) Moved : 24. Owner's Name & Address, if known 37 Condition Interior 9 Cuordinates Exterior good Lung 25. Open to 38. Preservation Yes IXI Public? Underway? No XX 10 Site Structure ! Building X Object 11 26. Local Contact Person or Organization Endangered? Yes II By What? No XX Yes XI Landmarks Commission 11 On National 12 Is II Yes .. Eligible? No II Register? No . X 27. Other Surveys in Which Included Yes X' Hist Dist ? No X 14 District 40 Visible from Yes XX Potent'l? Noli Public Road? No . 41. Distance from and 15 Name of Established District Frontage on Road 48 feet on Walnut 42 Further Description of Important Features The 1st two floors of this building have Other Name(s) been altered. The 10 bays of the upper floors are created by narrow piers that extend to the roof line. Each bay contains a double hund sash window. The bays above the 5th floor windows contain 2 narrow Photo Gothic terra cotta arches. A finial projects above the roof line above each of the piers. The building contains 35,000 square feet. 43 History and Significance This building was constructed by the Deardorff estate. In 1926 it won a 2nd place award from the Business District League for its remodeling. Lerner Shops has occupied the building since 1935. An earlier tenant was Diamond Brothers apparell. 44 Description of Environment and Outbuildings A surface parking lot is to the south of this building. To the north, east, and west are other commercial structures. 45 Sources of Information 45. Prepared by Sherry Piland WP# 9802 47. Organization KC Star, Feb. 9, 1926. Landmarks Commission KC Star, Aug. 7, 1955. 48. Date 49 Revision Date(s)

12/1/80



HISTORIC INVENT TA-AS-005-562 4. Present Name(s) 1. No. 94-B Myron Green Cafeteria; Myron Green Building 2. County 805A0182 Jackson 5. Other Name(s) other Landmarks Commission 20 - 7Evans Building 16. Thematic Category 28. No. of Stories 6 Specific Location Jackson 29. Basement? Yes IX 1113-15 Walnut 17. Date(s) or Period No I . 1912 30. Foundation Material 18. Style or Design 7 City or Town . If Rural, Township & Vicinity Neo-Classical 31. Wall Construction Kansas City, Missouri 8. Site Plan with North Arrow 19. Architect or Engineer steel frame Smith, Rea, Lovitt 32. Roof Type & Material 20. Contractor or Builder flat; tar/gravel F+ PR 33. No. of Bays Fogel & Son Construction Co Myron Front Side 21. Original Use, if apparent Present Namels commercial OPA 34. Wall Treatment 22. Present Use terra cotta N Green 35. Plan Shape rectangular commercia1 23 Ownership Public 1! 36. Changes Addition :: Private XI (Explain Altered I Walnut in #42) Moved i Ca Owner's Name & Address. if known fe 37. Condition Interior teri 9. Coordinates UTM Exterior good Lat. la Long 25. Open to Yes Ki Preservation Yes Public? No II Underway? No iX Site ! : Structure I Myron Building IXI Object ! ! 26. Local Contact Person or Organization Endangered? Yes IX By What? future No I : 11. On National Yes :X Landmarks Commission Yes I i 12 Is It emolition and/or edevelopment Register? No IX Eligible? No i! 27. Other Surveys in Which Included 9 Yes IX 13. Part of Estab. Yes II 14. District reen Visible from Yes ! X Hist. Dist.? No IXI Potent'1? Public Road? 15. Name of Established District 41. Distance from and 8 Frontage on Road l dg 48 feet on Walnut 42. Further Description of Important Features Plate glass windows dominate the first floor, with the wall area surfaced with marble. A metal panel has been placed above the 1st floor windows in an attempt at modernization. Floors 2 through 5 are fenestrated with five windows each, those on Photo each end being slightly narrower. The double hung sash windows have been replaced on the second floor with fixed single pane windows. The main facade is faced with a light green terra cotta. A modillioned cornice runs across the west (main) facade. Four keystone-like 43. History and Significance -- This building was erected for Kansas City businessman, Harry M. Evans. The Weber Meat Market was razed to make way for this structure. It retained the name Evans Building until 1927, when it became known as the Myron Green Building. Evans was the first President of the Security National Bank and established the Harry Evans Children's Home (later known as the Kansas City Cradle). 14. Description of Environment and Outbuildings -- Surface parking lots are located to the west and south of this building. Newer commercial buildings are located to the north and east. 5 Sources of Information 46. Prepared by WP# 58 Sherry Piland KC TIMES, Dec. 19, 1931 47. Organization Western Contractor, Jan. 3, 1912, p. 16 Landmarks Commission and Jan. 10, 1912, p. 18 48. Date 49. Revision Date(s) Western Contractor, Feb. 28, 1912, p. 20 4/15/80 Western Contractor, May 10, 1911, p. 5

State Historical Survey and Planning Office, 909 University Avenue, Suite 215,

Columbia, Missouri 65201

HISTORICAL INVENTORY
Myron Green Cafeteria; Myron Green Building
Page 2

decorations are placed on the parapet wall.



|  | 110 111  | VENTORY JA  | -AS-005-543  |
|--|--|---|--|
| 1. No. 93-L  |  | sent Name(s)  |  |
| 2. County  |  |   | alnut Street Building  |
| Jackson CRD# 10  | The second state of the second | ner Name(s)   |  |
| 3 Location of Negatives CBD# 19<br>Landmarks Commission  | 0v   | vl Drug Co.   | 0183   |
| 6. Specific Location   |  | 16. Thernatic Category  | 28. No. of Stories 3   |
| 1122 Walnut  |  | O Davids - David  | 29. Basement? Yes ! X  |
| 1122 Maillac   |  | 17. Date(s) or Period   | 30. Foundation Material  |
| City or Town - If Rural, Town  | ship & Vicinity  | 18 Style or Design  |  |
| Kansas City, Missouri  |  | Moderne 69  | 31. Wall Construction  |
| . Site Plan with North Arrow   |  | 19. Architect or Engineer   | masonry as   |
|  |  | Owen & Payson 20. Contractor or Builder   | 32. Roof Type & Material flat; tar & gravel [4]  |
|  |  | Friman, W. Emil   | 33. No. of Bays  |
|  |  | 21. Original Use, if apparent   | Front Side   |
|  |  | commercial OPA ODE  | 34. Wall Treatment   |
|  |  | commercial  | stucco; metal 35. Plan Shape rectangular   |
|  |  | 23 Ownership Public !!  | 36. Changes Addition ::  |
| Walnut   |  | Private XI  | (Explain Altered IX in #42) Moved I  |
|  | A1 >   | 24. Owner's Name & Address, if known  | 37. Condition  |
| Coordinates UTM  | <u> </u>   |   | Interior   |
| Lat.   |  |   | Exterior fair  |
| Long.  |  | 25. Open to Yes XI  | 38. Preservation Yes :   |
| Site!: Building IXI  | Structure 1 :<br>Object : 1  | Public? No 11   | Underway? No i   |
|  |  | 26. Local Contact Person or Organization  | 39. Endangered? Yes IX By What? future No 1:   |
|  |  | landmarks (ommission  | By wingt: []][][P NO !   |
|  | gible? Yes :X  | Landmarks Commission 27. Other Surveys in Which Included  |  |
| Register? No IX Eli  | gible? No 1!   | 27. Other Surveys in Which Included   | demolition and/or redeveropment/or   |
| Register? No IX Eli Part of Estab. Yes I I 14. Di Hist. Dist.? No IX Po  | gible? No 1!   |   | demolition and/or redevelopment  40. Visible from Yes !X Public Road? No ::  |
| Register? No IX Eli Part of Estab. Yes 11 14. Di Hist. Dist.? No IX Po   | gible? No 1!   |   | demolition and/or redeveropment/or   |
| Part of Estab. Yes 11 14. Di Hist. Dist.? No IX Po   | gible? No i:<br>estrict Yes iX<br>otent'l? No :  | 27. Other Surveys in Which Included   | demolition and/or redevelopment  40. Visible from Public Road? No i:  41. Distance from and  |
| Register? No IX Elin Part of Estab. Yes II Hist. Dist.? No IX Post II Hist. Dist. | gible? No:: strict Yes:X otent'!? No:.  It Features The wall area play window cealed behis remodeled.  | e facade of this building has been of the first floor is faced with ws flank a recessed central entrancind a metal panel with geometric in 1952 with the design by  | demolition and/or redeveropment  40. Visible from Public Road? No i:  41. Distance from and Frontage on Road 24 feet on Walnut   |
| Part of Estab Yes II Hist. Dist.? No M Name of Established District  Parther Description of Important ompletely altered. The tucco. Plate glass distinct tucco. Plate glas | gible? No:: strict Yes:X btent'l? No:.  I Features The wall area play window cealed behis remodeled s remodeled had 108 st   | e facade of this building has been of the first floor is faced with ws flank a recessed central entrancind a metal panel with geometric in 1952 with the design by  was constructed as an investment by the Owl Drug Company for their hea  | demolition and/or redevelopment  40. Visible Irom Public Road? No::  41. Distance from and Frontage on Road 24 feet on Walnut  Photo  y lawyer, Lloyd Medes. dquarters and warehouse.  |
| Part of Estab Yes II Hist. Dist.? No M  Name of Established District  Further Description of Important ompletely altered. The tucco. Plate glass district of the upper floors are conditiented. The building was rehitect W. Emil Forman of 1929 the building was that time the company.  Description of Environment and and east of this building   | gible? No:: strict Yes:X btent'l? No:.  I Features The wall area play window cealed behis remodeled s remodeled had 108 st   | e facade of this building has been of the first floor is faced with ws flank a recessed central entrancind a metal panel with geometric in 1952 with the design by  was constructed as an investment by the Owl Drug Company for their heatores in 25 cities.   | demolition and/or redevelopment  40. Visible Irom Public Road? No::  41. Distance from and Frontage on Road 24 feet on Walnut  Photo  y lawyer, Lloyd Medes. dquarters and warehouse.  |
| Part of Estab Yes II Hist. Dist.? No IX  Part of Estab Yes II Hist. Dist.? No IX  Name of Established District  Further Description of Important of  | gible? No:: strict Yes:X btent'l? No:.  I Features The wall area play window cealed behis remodeled s remodeled had 108 st   | e facade of this building has been of the first floor is faced with ws flank a recessed central entrancind a metal panel with geometric in 1952 with the design by  was constructed as an investment by the Owl Drug Company for their heatores in 25 cities.   | demolition and/or redevelopment  40. Visible Irom Public Road? Noi:  41. Distance from and Frontage on Road 24 feet on Walnut  e  Photo  y lawyer, Lloyd Medes. dquarters and warehouse.  to the north dings.  |
| Part of Estab. Yes 11 Hist. Dist.? No 10 Name of Established District  Purther Description of Important of Im | gible? No::  Istrict Yes:X  Intent'!? No::  It Features The wall area play window cealed behis remodeled to had 108 st   | e facade of this building has been of the first floor is faced with ws flank a recessed central entrancind a metal panel with geometric in 1952 with the design by  was constructed as an investment by the Owl Drug Company for their headores in 25 cities. Surface parking lots are located south and west are commercial buil | demolition and/or redevelopment  40. Visible Irom Public Road? Noi:  41. Distance from and Frontage on Road 24 feet on Walnut  e  Photo  y lawyer, Lloyd Medes. dquarters and warehouse.  to the north dings.  46. Prepared by Sherry Piland  47. Organization |
| Part of Estab. Yes 11 Hist. Dist.? No M Name of Established District  Parther Description of Important of Imp | gible? No::  Istrict Yes:X  Intent'!? No::  It Features The wall area play window cealed behis remodeled to had 108 st   | e facade of this building has been of the first floor is faced with ws flank a recessed central entrancind a metal panel with geometric in 1952 with the design by  was constructed as an investment by the Owl Drug Company for their headores in 25 cities. Surface parking lots are located south and west are commercial buil | demolition and/or redevelopment  40. Visible Irom Public Road? Noi:  41. Distance from and Frontage on Road 24 feet on Walnut  e  Photo  y lawyer, Lloyd Medes. dquarters and warehouse.  to the north dings.  |



| HISTORIC II   | NVENTORY   | UIIIDIA, 19155UUTI UUZUI<br>A-AS-005-560        |
|---|--|---|
|   | Present Name(s)  |   |
| CBD 93-M  | Boley Building   |   |
| 2. County   | Other Name(s)  | ·   |
| Landmarks Commission Cabatto                                | 71TA8001   |   |
| 6. Specific Location  | 16. Thematic Category  | 28. No. of Stories U                            |
| 1130 Walnut St.   | Architecture/Engineering   | 29. Basement? Yes X                             |
| Kansas City, Missouri                                       | 17. Date(s) or Period  | No i .  |
| 7. City or Town II Rural, Township & Vicin                  |  | 30. Foundation Material masonry                 |
| 7. City or Town - If Rural, Township & Vicin<br>Kansas City | semi-Art Nouveau   | 31. Wall Construction iron.gl                   |
| 8. Site Plan with North Arrow                               | 19. Architect or Engineer  | brick, terracotta                               |
|   | Louis S. Curtiss 20. Contractor or Builder   | 32. Roof Type & Material flat sur faced with    |
| M   | 20. Contractor of Builder  | 33. No. of Bays                                 |
| 15  | 21. Original Use, if apparent  | Front 10 Side .11                               |
| ¥   · ·   | Commercial   | 34. Wall Treatment                              |
| \$ £  | 22. Present Use<br>Commercial  | glass curtain wall<br>35. Plan Shape rectangula |
| 2   | 23. Ownership Public !!  | 436. Changes Addition .:                        |
|   | restrictive Privatex!  | (Explain Altered &                              |
| WALNUT STREET   | 24. Owner's Name & Address, and others if known E.W.&A.P. Tureman  | in #42) Moved i                                 |
| Variable of the second                                      | c/o First National Bank -E.La  | 137. Condition Interior good                    |
| 9. Coordinates UTM Lat.                                     | P.O. 38, K.C. MO. 64141  | Exterior good                                   |
| Long.   | 25. Open to Yes 1x   | 38. Preservation Yes :                          |
| 10. Site 1: Structure Building Xi Object                    |  | Underway? No X                                  |
| 11. On National Yes X: 12. Is It Yes                        | 8 20. Local Collect Person of Organization   | 39. Endangered? Yes X By What? No 1:            |
| Register? No !! Eligible? No                                |  | possible redevelopmt.                           |
| 13. Part of Estab. Yes 1 14. District Yes                   |  | 40. Visible from Yes X                          |
| Hist. Dist.? No 1 Potent'l? No                              | Landmarks Commission  The Need for Preservation of   | Public Road? No 1:                              |
| 15. Name of Established District                            | Kansas Citys' Architectural  | 41. Distance from and TUT Frontage on Road      |
|   | Heritage, AIA KC Chapter   |   |
|   | The Boley Building is a six story  |   |
| steel frame commercial bu                                   | ilding of the "semi Art Nouveau "  |   |
|   | S. Curtiss, an outstanding Kansas  |   |
|   | el columns of the frame are  |   |
|   | outh facade is divided horizontall   | y by  |
|   | to six levels of continuous glass  |   |
| ribbon windows. The east                                    | facade is similar in design.<br>uilding is significant for its ex  | tnaondinany structural                          |
|   | t metal-and-glass curtain-wall bu  |   |
|   | e use of rolled steel columns rat  |   |
|   | has further significance as one o  | f the most important                            |
| works of Louis Curtiss.                                     |  |   |
| 44. Description of Environment and Outbuilding              | The Boley Building is situated   | in an all commercial                            |
| area. To the south is th                                    | e Chambers Building and to the ea  | st is the S.S. Kresge                           |
| Store.  |  |   |
| 46 Course at late was                                       | The second secon | Las   |
| 45 Sources of Information                                   |  | 46. Prepared by Linda F. Becker                 |
| National Register Form                                      | Prepared July 23, 1970   | 47. Organization Kansas Cit                     |
|   |  | Landmarks Commission                            |
|   |  | 48. Date 49. Revision Date(s) 11/76 10-24-79    |
|   |  | 1 1 10-24-79                                    |


1130 Walnut K.C.

No. 27 (cont.)

Historic Building Preservation Analysis, Kansas City, Missouri Downtown Plan

1973

Johnson, Brickell, Mulcahy and Associates, Inc. Transportation and Planning Consultants Suite 105, 8301 State Line Road Kansas City, Missouri



Office of Historic Preservation, P.O. Box 176, Jefferson City, Missouri 65101 HISTORIC INVENTORY JA-AS-005-565 4 Present Name(s) 110-H Twelfth and Walnut Street Building CBD #31-3 County Jackson 5 Other Name(s) 8JJA0020 CBD# 3 Lucation of Negatives Chambers Building Landmarks Commission 31-3 16 Themalic Calegory 28 No of Stories 6 Specific Location 12 29. Basement? Yes II 17 Date(s) or Period No : . 1202 Walnut 1915; 1922-23 (addition) 30. Foundation Material Kansas City, Missouri 18 Style or Design concrete 31. Wall Construction steel frame 19. Architect or Engineer 8 Sile Plan with North Arrow 32. Roof Type & Material Charles A. Smith (1915 & 1922-23) flat; tar/gravel 20 Contractor or Builder 33. No. of Bays Swenson Const. Co. (1922-23) 3 Front Side 21. Original Use, if apparent commercia1 34. Wall Treatment 22 Present Use terra cotta 35. Plan Shape commercial rectangular Public 11 36. Changes Addition . X 23 Ownership Walnut Altered X Private KI (Explain In 842) 24. Owner's Name & Address, if known Condition Interior UTM Condinates good Exterior Lal Lung 25. Open to Yes XI Preservation Yes . . Public? No i X No II Underway? Structure ! . Sile Object i i Building X 26 Local Contact Person or Organization Endangered? Yes II By What? No IX Landmarks Commission Yes XI 11 On National 15 11 Yes Eligible? No II Register? No . X 27 Other Surveys in Which Included District Yes X Visible from 13 Part of Estab Yes ! Yes X No 'X Potent'1? No I Public Road? HIST DIST ? No :: 41. Distance from and 15 Name of Established District Frontage on Road 58 feet on Walnut 42 Further Description of Important Features Various alterations have occured to the Other Name(s) 1st floor shops and main entrance on East 12th Street. The building is fenestrated by double hung, sash windows grouped in pairs. Spandrels beneath the windows feature a pattern of squares. Above the 5th floor windows Photo are spandrels with a floral design. Colonnettes supported by corbels decorate the top floor. The parapet wall features decorative terra cotta work. The building contains 72,000 square feet. 43 History and Significance -- The first five stories of this building were erected in 1915, with plans to later enlarge the building. Seven floors were added in 1922-23. second building phase, concrete was poured at night to avoid disturbing the tenants. The building was erected by the Chambers estate of California, who paid \$10,000 a front foot for the lot in 1912, the highest amount paid for real estate in Kansas City up to 44 Description of Environment and Outbuildings -- Commercial buildings are located to the north, south, east, and west of this structure. 45 Sources of Information 46. Prepared by Sherry Piland Kansas City Star, Oct. 31, WP# 13360 47. Organization 1915, p. 6A. Kansas City Journal-Post, April 22, 1923 Kansas City Star, July Landmarks Commission

Kansas City Star, April 16, 1922

Western Contractor, Jan. 14, 1914, p. 13

48. Date

1/20/80

20, 1922, p. 12

49 Revision Date(s)



State Historical Survey and Planning Office, 909 University Avenue, Suite 215.




Office of Historic Preservation, P.O. Box 176, Jefferson City, Missouri 65101 HISTORIC JA-AS-005-567 4 Present Name(s) No 110-J Jones Store Company 2 County 5 Other Name(s) Jackson Lucation of Negatives CBD# 27-16 Landmarks Commission 16 Themalic Category 28 No of Stories 4 Specific Location Yes X Basament? 1216 Walnut 17 Date(s) or Period No : . 1907;1956 30. Foundation Material concrete 18 Style or Design Il Rural, Township & Vicinity 31. Wall Construction Kansas City, Missouri 19 Architect or Engineer Wm. Fullerton; Sile Plan with North Arrow Voskamp & Slezak (1956) 32. Roof Type & Material 20 Contractor or Builder flat; tar/gravel 33. No. of Bays Front Side 21. Original Use, If apparent Present Name(s commercial 34 Wall Treatment 22 Present Use stone; metal 35. Plan Shape rectangular commercial 23 Ownership Public 11 36. Changes Addition X Walnut Altered K Private IX (Explain n #42) Moved i 24. Owner's Name & Address. if known Condition Interior Currdinates good Exterior Lat Lung Yes IX 25. Open to Preservation Yes Public? Underway? No X Site Structure ! Object | | Building X Endangered? 26 Local Contact Person or Organization Yes II By What? No K. 11 On National 12 IS II Yes II Landmarks Commission YHL Eligible? No . X No IX Register? 27. Other Surveys in Which Included Yes X District 13 Part of Estab Yes Visible from Yes X No 1 X Potent'1? No I Public Road? HIST DIST ? No . : 41. Distance from and 15 Name of Established District Frontage on Road approx. 350 feet on Walnut 42 Further Description of Important Features .- This structure was remodeled in 1956 The first floor features display windows set in a "sunset red" Other Namels marble base, protected by a canopy roof. The upper floors are faced with pink and gray porceline paneling and aluminum trim. Photo 43 History and Significance The Jones Store began business in Kansas City in 1895. destroyed their store at 6th and Main in 1899, they relocated at 12th and Main. In 1907 the store expanded east with this building on Walnut. The architect for the 1907 expansion was Charles A. Smith. 44 Description of Environment and Outbuildings -- A commercial building is located to the north of this structure. Located to the east and west are both commercial buildings and surface parking lots. A surface parking lot is located to the south. 45 Sources of Information 46. Prepared by Sherry Piland Kansas City Star, July 28, 1929, p. 1D. WP# 3604; 34444 47. Organization Kansas City Star, July 13, 1956

48. Date 49 Revision Date(s)

12/1/80





## JENKINS

PIANOS ORGANS STEREO RADIO RECORDS BAND Instruments

SHEET MUSIC AND'S RIDERS. CLOTHES!SHOES State Historical Survey and Planning Office, 909 University Avenue, Suite 215,

Columbia, Missouri 65201

12/8/80




| State Historical Trve  |   | y Avenue, Suite 215,<br>mbia, Missouri 65201  |
|--|---|---|
| 是在1000年间,1000年中央1200年间,1200年间 | resent Name(s)  | 11 13 003 3 7 10  |
| 126_1  | Copeland's Western Store  | 0187  |
| 2. County  |   |   |
| 3 Location of Negatives CBD# 6-15<br>Landmarks Commission  | 1305-13   | 307 Walnut Street &<br>Building   |
| 6. Specific Location   | 16. Thematic Category   | 28. No. of Stories 4  |
| 1305-07 Walnut Street  | 17. Date(s) or Period   | 29. Basement?  Yes! No!. 30. Foundation Material  COncrete  |
|  | 1912  | 30. Foundation Material   |
| 7. City or Town - If Rural, Township & Vicini<br>Kansas City, Missouri   | y 18. Style or Design<br>Neo Classical elements 52 69   | Concrete 31. Wall Construction  |
| 8. Site Plan with North Arrow  | 19. Architect or Engineer   | brick; reinf. concrete  |
| 13   | Frederick Gunn 20. Contractor or Builder  | 32. Roof Type & Material flat; tar/gravel F+ PR   |
| Street   | Fogel & Sons Construction Co.   | 33. No. of Bays   |
| ۲۱ .   | 21. Original Use, if apparent   | Front 4 Side 7  |
| , m  | Commercial OPE OPH  | 34. Wall Treatment 30 Periods; terra cotta 35. Plan Shape rectangular 36. Changes Addition: (Explain Affered) |
| W  | Commercial  | brick; terra cotta  |
|  | 23 Ownership Public 1 !   | 36. Changes Addition :  |
| Walnut   | Private ly  | (Explain Altered in #42) Moved  |
|  | 24. Owner's Name & Address, Other   | in #42) Moved 1   |
| 9. Coordinates UTM   | 62  | Interior D  |
| Lat.<br>Long.  |   | Exterior good   |
| 10. Site!: Structure!  | 25. Open to Yes XI Public? No I I   | 38. Preservation Yes 1 On No 1 X  |
| Building X1 Object 1   |   | 39. Endangered? Yes I X   |
| 11. On National Yes ! 12 Is It Yes !   | Landmarks Commission  | By What? future No!:  |
| Register? No K! Eligible? No I   | 27. Other Surveys in winch included   | redevelopment   |
| Hist. Dist.? No XI Potent'I? No :  |   | 40. Visible from Yes X Public Road? No 11   |
| 15. Name of Established District   |   | 41. Distance from and Frontage on Road  |
| R <sup>1</sup>   |   | 50 feet on Walnut   |
|  | -Large display windows flank the cen-   |   |
| Chicago-style windows. The 3rd pairs of double hung sash window  | The second floor contains 2 large and 4th floor are fenestrated by 4 s. The entire west facade is faced classical ornament and a slightly | Photo   |
| lawyer James Cravens. Numerous chas been occupied by Copeland's W  |   | tive investment by ilding. The building   |
| 44. Description of Environment and Outbuildings  |   |   |
| Surface parking lots surround th   | e building.   |   |
| 45 Sources of Information  |   | 46. Prepared by   |
| Water Permit #402  | •   | Sherry Piland   |
| Western Contractor, October 30,  | 1912, p. 19   | 47. Organization  |
| Building Permit #10766   |   | Landmarks Commission  48. Date 49. Revision Date(s)   |
| Kansas Čity Star, Oct. 26, 1912  | , p. 10   | 7/14/80   |



Columbia, Missouri 65201 HISTORIC INVENTORY JA-AS-005-57 4. Present Name(s) I. No. 126-B,C Mercantile Drive-In Bank 126-в 2. County Jackson 5. Other Name(s) 3 Location of Negatives CBD#6-164 17 not entered Landmarks Commission 6. Specific Location 16. Thematic Category 28. No. of Stories Jackson 29. Basement? Yes I 17. Date(s) or Period No I 1323 and 1331 Walnut 1957 30. Foundation Material 7. City or Town If Rural, Township & Vicinity 18. Style or Design 31. Wall Construction Kansas City, Missouri B. Site Plan with North Arrow concrete block 19. Architect or Engineer Hardy & Schumacher 32. Roof Type & Material 20. Contractor or Builder flat; tar/gravel Estrin Construction Co. 33. No. of Bays Mercantile Front Side 21. Original Use, if apparent Present Name(s) Bank 34. Wall Treatment 22. Present Use brick 35. Plan Shape irregular Bank 36. Changes 23 Ownership Public 1! Addition : Private IXI (Explain Altered I Drivein #42) Moved i 24. Owner's Name & Address, Walnut if known 37. Condition Interior 9. Coordinates In good Exterior Lat Long 25. Open to Yes IX 38. Preservation Yes Public? No II Underway? No : X Structure | Site ! : Building IX Object 11 26. Local Contact Person or Organization 39. Endangered? Yes ! Landmarks Commission By What? No IX 11. On National Yesli 12 Is It Yes ! No IX Eligible? No X Register? 27. Other Surveys in Which Included 13. Part of Estab. Yes !! 14. District Yes IX 40. Visible from Yes !X Potent'l? No : Public Road? Hist. Dist.? No XI No II 41. Distance from and 15. Name of Established District Frontage on Road 12 feet on Walnut 42. Further Description of Important Features -- Two separate buildings are located on this site. A 14 x 9 foot rectangular parking attendant's office (1323 Walnut) is located near the front center of the property. drive-in bank (1331 Walnut) extends back 115 feet from the street along Photo the south border of the property. The three drive-in windows angle out, forming a jagged facade. A metal canopy roof projects over the drivein windows. This building contains 2,000 square feet. 43. History and Significance -- This building was originally described as a "motormatic bank adjunct," and was one of the first drive-in banking facilities in the city. This facility was linked to the main bank (then at 1119 Walnut) by a 1,000 foot long underground pneumatic tube system and by closed circuit television. It reputedly was the largest pneumatic tube layout of any bank in the United States. 44. Description of Environment and Outbuildings Surface parking lots are located to the west and north of these buildings. Commercial buildings are located to the south and east. 46. Prepared by Sherry Piland 45 Sources of Information BP# 18685 47. Organization WP# 1734 Landmarks Commission 48. Date 49. Revision Date(s) Kansas City Star, Dec. 15, 1957 6/16/80

State Historical Survey and Planning Office, 909 University Avenue, Suite 215,





Columbia, Missouri 65201 JA-AS-005-57 I. No. 4. Present Name(s) 126-D 1335-37 Walnut (vacant) 2. County Jackson 5. Other Name(s) crothing Company 80JA0188 CBD# 3 Location of Negatives BALTIMORE BUILDING Landmarks Commission 16. Thematic Category 6 Specific Location 28. No. of Stories 29. Basement? Yes 4 1335-37 Walnut 17. Date(s) or Period No I (and 104-112 E. 14th St.) 1920 30. Foundation Material 7. City or Town . If Rural, Township & Vicinity 18 Style or Design 69 31. Wall Construction Kansas City, Missouri B. Site Plan with North Arrow 19. Architect or Engineer reinforced concrete Edward H Gill, Jr. 32. Roof Type & Material 20. Contractor or Builder flat; tar/gravel 33. No. of Bays Front 8 Side 21. Original Use, if apparent commercial 34. Wall Treatment 22. Present Use brick 30 35. Plan Shaperectangular vacant 23 Ownership 36 Changes Public 1 Addition 5. 14 " Street Private XX Altered IX (Explain in #42) Moved i 24. Owner's Name & Address, if known 37. Condition Interior 9. Coordinates UTM fair Exterior Lat. Long 25. Open to Yes I 38. Preservation Yes . Public? No iX Noxx Underway? Site ! : Structure I Building XI Object ! I 39. Endangered? 26. Local Contact Person or Organization Yes IX By What? future demolition or redevelopment 11. On National Yes :X Landmarks Commission No I i Yes I i 12 Is It Register? No IX Eligible? No 1 ! 27. Other Surveys in Which Included 13. Part of Estab Yes ! ! District Yes X 40. Visible from Yes !X Hist. Dist.? No XI Potent'1? No : Public Road? No 1 : 41. Distance from and 15. Name of Established District 110 ft Frontage on Road on East 14th Street 42. Further Description of Important Features

The main entrance to the building is centrally located on East 14th Street. The store fronts on the west half of the building have been enclosed. The 2nd floor is fenestrated with paired, one-over-one, double hung sash windows. The windows have terra cotta sills and lintels. The corners of the building are quoined with terma cotta A simple terra cotta cornice runs above the 2nd floor windows. building contains 16,700 square feet. 13. History and Significance The building was constructed for the Baltimore Clothing Company. 1957 a drive-in bank was constructed to the north of this building and in 1960 the bank purchased this building to secure space for expansion. 14. Description of Environment and Outbuildings
Surface parking lots are located to the east and south of this building. To the west is a commercial building. To the north is a drive-in bank facility. 5 Sources of Information 46. Prepared by Sherry Piland WP# 44800 47. Organization BP# 12755 (#1) Landmarks Commission 48. Date KC Star, Feb. 14, 1960 49. Revision Date(s) 11/26/80

State Historical Survey and Planning Office, 909 University Avenue, Suite 215



|   |  | nbia, Missouri 65201.   |
|---|--|---|
|   |  | A-AS-605-573  |
| No.<br>125-R  | I. Present Name(s)  Upsher Laboratories  | 2 2   |
| County  |  | 0189 5  |
| Jackson Location of Negatives CBD# 17-6 Landmarks Commission  | 5. Other Name(s)<br>14-22 East Fourteenth  | Quet Building   |
| Specific Location   | 16. Thematic Category  | 28. No. of Stories 2  |
|   | 030  | 29. Basement? Yes I X w O   |
| 1336-42 Walnut<br>(and 14-22 E. 14th Street)  | 17. Date(s) or Period<br>1923  | 29. Basement? Yes IX No I. O CO C  |
| City or Town If Rural, Township & Vi  | cinity 18. Style or Design   | Concrete 31. Wall Construction  |
| Site Plan with North Arrow  | 19. Architect or Engineer  | reinforced concrete   |
|   | McKecknie and Trask  | 32. Roof Type & Material  |
|   | 20. Contractor or Builder Machy Condition Construction Co.   | flat; tar & gravel F  |
| Valnut  | Mosby Goodrich Construction Co.  21. Original Use, if apparent commercial  |   |
| 1   | commercial Op A  | Front 7 Side 3 1336 3 1336 4 Treatment terra cotta 62 14  |
| 3   | commercial   | 35. Plan Shape rectangular 2  |
| E. H. Street  | 23 Ownership Public I! Private XI  | 36. Changes Addition :: ₩ ₩ ₩ ₩ ₩ ₩ ₩ ₩ ₩ ₩ ₩ ₩ ₩ ₩ ₩ ₩ ₩ ₩   |
| N   | 24. Owner's Name & Address, Other  | in #42) Moved i   |
|   |  | 37. Condition   |
| Coordinates UTM Lat.  |  | Exterior good   |
| Long.   | 25. Open to Yes I i  | 38. Preservation Yes : 14   |
| Site!: Structu  |  | Oliderway: No 1 X 1   |
| Λ   | es:X Landmarks Commission  | 39. Endangered? Yes I i No I 次 Est  |
|   | No : ! 27. Other Surveys in Which Included   |   |
|   | es iX<br>No :  | 40. Visible from Yes! X 4- 4- 17 Public Road? No!   |
| Name of Established District  |  | 41. Distance from and   |
|   |  | Frontage on Road  |
| Further Description of Important Footune  |  | 50 feet on Walnut   |
| been altered with stone agg<br>large tinted windows. An e   | The first floor of this building has regate panels being interspersed with   | 1   |
| double hung sash windows wit<br>surrounds. The parapet wall<br>panels.  | ntrance is centrally located on the he 2nd floor is fenestrated by triple h transoms. They are set in decorative is decorated with ornate terra cotta  | Photo Pame(s.   |
| double hung sash windows with surrounds. The parapet wall panels.  History and Significance The origin of the Mehorney-North Furnithe Grolier Society, Frank Inc.  Description of Environment and Outbuild                                    | h transoms. They are set in decorative   | ney, Vice-President of the building were owledge Co.  |
| double hung sash windows with surrounds. The parapet wall panels.  History and Significance The origin of the Mehorney-North Furnithe Grolier Society, Frank Inches Surface parameters of the Structure. Surface parameters of the Structure. | h transoms. They are set in decorative is decorated with ornate terra cotta al owner of this building was J.N.Mehor ture Company. Among the early tenants of Siggs Electrical Company and Book of KnownsCommercial buildings are located | ney, Vice-President of the building were owledge Co.  to the east and west of                               |
| double hung sash windows with surrounds. The parapet wall panels.  History and Significance The origin of the Mehorney-North Furnithe Grolier Society, Frank Inches Structure. Surface parasociety of Information                             | h transoms. They are set in decorative is decorated with ornate terra cotta al owner of this building was J.N.Mehor ture Company. Among the early tenants of Siggs Electrical Company and Book of KnownsCommercial buildings are located | ney, Vice-President of the building were owledge Co.  to the east and west of                               |
| double hung sash windows with surrounds. The parapet wall panels.  History and Significance The origin of the Mehorney-North Furnithe Grolier Society, Frank Inches Surface parameters of Information  NP# 61251                              | h transoms. They are set in decorative is decorated with ornate terra cotta al owner of this building was J.N.Mehor ture Company. Among the early tenants of Siggs Electrical Company and Book of KnownsCommercial buildings are located | ney, Vice-President of the building were owledge Co.  |
| double hung sash windows with surrounds. The parapet wall panels.  History and Significance The origin of the Mehorney-North Furnithe Grolier Society, Frank Inches Surface parameters of Information WP# 61251 BP# 13459 (1)                 | h transoms. They are set in decorative is decorated with ornate terra cotta al owner of this building was J.N.Mehor ture Company. Among the early tenants of Siggs Electrical Company and Book of KnownsCommercial buildings are located | ney, Vice-President of the building were owledge Co.  to the east and west of  46 Prepared by Sherry Piland |



| A Present Name(s)   Stanley Sargent Company   Stanley Sargent Coateny   Stanley Sargent Coaten   |  |   | VVENTORY   | ty Avenue, Suite 215,<br>umbia, Missouri 65201<br>JA-AS-005-5 | 74                |
|--|--|---|--|---|-------------------|
| Stanley Sargent Company   Stanley Sargent    | THE RESERVE TO A PERSON NAMED IN                                     |   |  | 314.13-803-2  | -                 |
| 3   Cestion of Negatives (BD# 17-5   Landmarks Commission  |  |   |  | 0190  | i z               |
| 1   Caration of Negatives (BDF 17-5   Landmarks Commission   1406 Walnut   120 March   1   |  |   |  | 0.10  |                   |
| 7 City or Town - If Ruis, Township & Vicinity Ransas City, Missouri 8 Sits Plan with North Arrow 9 Contractor or Builder Flanagan Brothers 20 Contractor or Builder Flanagan Brothers 21 Criginal Use, if apparent 22 Present Use 23 Ownership Public 11 24 Owner's Name & Address. If Anoen 15 Available Privately 12 Sits I Ves X Building XX 16 Owner's Name & Address. 17 Owner's Name & Address. 18 Owner's Name & Address. 19 Owner's Name & Address. 10 Sits 1: Structure I Object: 17 Ob | 3 Location of Negatives (  | CBD# 17-5   |  | treet Building  | H                 |
| Site Plan with North Arrow   18 Nursh Construction   19 Architect or Engineer   20 Contractor or Builder   19 Architect or Engineer   20 Architect or Engineer   21 Architect or Engineer   22 Contractor or Builder   23 Architect or Engineer   24 Architect or Engineer   25 Contractor or Builder   26 Contractor or Builder   27 Condition   27 Condition   28 Contractor or Building X   | 6 Specific Location  |   | 16. Thematic Category  | 28. No. of Stories 5  | ر<br>ا            |
| Site Plan with North Arrow   18 Nursh Construction   19 Architect or Engineer   20 Contractor or Builder   19 Architect or Engineer   20 Architect or Engineer   21 Architect or Engineer   22 Contractor or Builder   23 Architect or Engineer   24 Architect or Engineer   25 Contractor or Builder   26 Contractor or Builder   27 Condition   27 Condition   28 Contractor or Building X   | 1406 Walnut  |   | 47 Desired and Desired   |   | Ck Co             |
| Site Plan with North Arrow   18 Nursh Construction   19 Architect or Engineer   20 Contractor or Builder   19 Architect or Engineer   20 Architect or Engineer   21 Architect or Engineer   22 Contractor or Builder   23 Architect or Engineer   24 Architect or Engineer   25 Contractor or Builder   26 Contractor or Builder   27 Condition   27 Condition   28 Contractor or Building X   |  |   |  |   | SON               |
| 8. Site Plan with North Arrow  9. Architect or Engineer  10. Contractor or Builder Flanagan Brothers 12. Present Use 12. Present Use 12. Owner's Name & Address. 13. Wall Treatment 14. Wall Treatment 15. Open to Public 11 16. Site 1. Structure 1 16. Site 1. Structure 1 16. Site 1. Structure 1 16. Depublic 7 17. Open to Public 11 16. National Yes 1. 12 is il Yes X Register? No XX 15. Engole? No 1. Structure 1 16. Shale 1. Structure 1 17. Open to Public 11 18. Depublic 7 19. Architect or Engineer 19. Architect or Engineer 19. Architect or Engineer 19. Architect or Engineer 19. Contractor or Builder 19. Architect or Engineer 19. Contractor or Builder 19. Architect or Engineer 19. Contractor or Builder 19. No of Bays 19. From 13. Side 21. Wall Treatment 22. Present Use 23. Ponn 15. Public 11 23. Owners Name & Address. 19. Address. 19. No of Bays 19. From 13. Side 24. Wall Treatment 25. Open 10 27. Owners Name & Address. 19. No of Bays 19. From 13. Side 26. Commercial Date of Commercial Private Address. 27. From 19. Structure 1 28. Depublic 7 29. Owners Name & Address. 29. Depublic 7 20. Owners Name & Address. 21. Wall Treatment of Commercial Private Address. 29. Engole 2. Structure 1 20. Owners Name & Address. 21. Wall Treatment of Commercial Private Address. 21. Wall Treatment of Commission 22. From 19. Wall Treatment of Commercial Private Address. 29. From 19. Structure 1 20. Owners Name & Address. 20. Owners Name & Address. 20. Owners Name & Address. 21. Wall Treatment of Commercial Private Address. 22. From 19. Wall Treatment of Commercial Private Address. 23. From 19. State of Commercial Private Address. 24. Wall Treatment of Commission and Public of Commercial Private Address. 25. Ponn 19. Public 11 26. Open 10 27. Open 10 28. Wall Treatment of Commercial Private Address. 28. Wall Treatment of Commercial Private Address. 29. Engole 2. Wall Treatment of Commercial Private Address. 29. Engole 2. Wall Treatment of Commercial Private Address. 29. Roof 19. Wall Treatment of Commercial Private Address. 29. Roof 19.  | 7 City or Town - If Rui  | al, Township & Vicin                                |  |   |                   |
| ## Panagan Brothers   20. Contractor or Builder   Flanagan Brothers   Flanagan Brother | Kansas City, Miss  | souri   | 69   |   |                   |
| ## Contractor or Builder   Flanagan Brothers   133 No. of Bays   120 regimer Use   139 parent   130 parent    | 8. Site Plan with North A  | row   | 19. Architect or Engineer  |   |                   |
| Flanagan Brothers 21. Original Use, if apparent commercial ## OBE OF IT 12 Present Use commercial ### OBE OF IT 12 PRESENT USE commercial #### OBE OF IT 12 PRESENT USE commercial ### OBE OF IT 12 PRESENT US |  |   | 20 Contractor or Builder   |   | PR                |
| 21. Original Use, if apparent   34. Wall Trainment   34. Wall Trainment   35. Plan Shaper ectangular   36. Commercial   37. Surface   37. Public   11. Private   37. Public   12. Private   37. Condition   16. Public   17. Public   17. Public   17. Public   18. Public   19. Pub   |  |   |  | 33. No. of Bays   | 4                 |
| Condinates   UTM   25 Open to   Public   1   26 Local Contact Person or Organization   Interior   No   11   Onational Ves   12 is it   Yes   X   Biguiler   No   X   No   1   10   National Ves   12 is it   Yes   X   Biguiler   No   X   Yes   Xes   Xes   Yes   Xes     |  |   | 21. Original Use, if apparent  | Front 3 Side  | Sta               |
| Condinates   UTM   25 Open to   Public   1   26 Local Contact Person or Organization   Interior   No   11   Onational Ves   12 is it   Yes   X   Biguiler   No   X   No   1   10   National Ves   12 is it   Yes   X   Biguiler   No   X   Yes   Xes   Xes   Yes   Xes     |  |   |  |   | anl               |
| ## Public   Private   18 Changes   Addition   Relation   Relation  |  |   |  |   | ey                |
| Description of Environment and Outbuildings ——Surface parking lots are located to the north, east, and west of this building. A commercial building is located to the south.  19. Coordinates Luty Long  25. Open to Public?  25. Open to Public?  26. Local Contact Person or Organization Landmarks Commission  27. Other Surveys in Which Included  28. Local Contact Person or Organization Landmarks Commission  29. Endangered?  20. Local Contact Person or Organization Landmarks Commission  30. Perservation Underway?  30. Preservation Underway?  31. Perservation Underway?  32. Contact Contact Person or Organization Landmarks Commission  33. Perservation Underway?  34. Preservation Underway?  35. Open to Public Results  36. Local Contact Person or Organization Landmarks Commission  40. Visible from Work Yes XX Public Read?  40. Visible from West X Public Read?  41. Distance from and Frontage on Road  50 feet on Walnut  42. Further Description of Important Features —The first floor of the facade has been modernized with display windows set in a metal frame. The upper floors are hidden behind a metal grill. A stepped parapet  43. History and Significance —This building has been used by a number of commercial firms over the years, including an electronic company, chandelier company, and an advertising company.  45. History and Significance —This building has been used by a number of commercial firms over the years, including an electronic company, chandelier company, and an advertising company.  46. Prepared by Sherry Piland  47. Organization Landmarks Commission  48. Prepared by Sherry Piland  47. Organization Landmarks Commission  48. Prepared by Sherry Piland  47. Organization Landmarks Commission  48. Prepared by Sherry Piland  49. Prepared by Sherry Piland  49. Prepared by Sherry Piland  40. Prepared by Sherry Piland  41. Prepared by Sherry Piland  42. Prepared by Sherry Piland  43. Prepared by Sherry Piland  44. Prepared by She |  |   |  |   | Si                |
| Description of Environment and Outbuildings ——Surface parking lots are located to the north, east, and west of this building. A commercial building is located to the south.  19. Coordinates Luty Long  25. Open to Public?  25. Open to Public?  26. Local Contact Person or Organization Landmarks Commission  27. Other Surveys in Which Included  28. Local Contact Person or Organization Landmarks Commission  29. Endangered?  20. Local Contact Person or Organization Landmarks Commission  30. Perservation Underway?  30. Preservation Underway?  31. Perservation Underway?  32. Contact Contact Person or Organization Landmarks Commission  33. Perservation Underway?  34. Preservation Underway?  35. Open to Public Results  36. Local Contact Person or Organization Landmarks Commission  40. Visible from Work Yes XX Public Read?  40. Visible from West X Public Read?  41. Distance from and Frontage on Road  50 feet on Walnut  42. Further Description of Important Features —The first floor of the facade has been modernized with display windows set in a metal frame. The upper floors are hidden behind a metal grill. A stepped parapet  43. History and Significance —This building has been used by a number of commercial firms over the years, including an electronic company, chandelier company, and an advertising company.  45. History and Significance —This building has been used by a number of commercial firms over the years, including an electronic company, chandelier company, and an advertising company.  46. Prepared by Sherry Piland  47. Organization Landmarks Commission  48. Prepared by Sherry Piland  47. Organization Landmarks Commission  48. Prepared by Sherry Piland  47. Organization Landmarks Commission  48. Prepared by Sherry Piland  49. Prepared by Sherry Piland  49. Prepared by Sherry Piland  40. Prepared by Sherry Piland  41. Prepared by Sherry Piland  42. Prepared by Sherry Piland  43. Prepared by Sherry Piland  44. Prepared by She | Waln   | ut  |  | (Explain Altered XX   | arc               |
| Description of Environment and Outbuildings ——Surface parking lots are located to the north, east, and west of this building. A commercial building is located to the south.  19. Coordinates Luty Long  25. Open to Public?  25. Open to Public?  26. Local Contact Person or Organization Landmarks Commission  27. Other Surveys in Which Included  28. Local Contact Person or Organization Landmarks Commission  29. Endangered?  20. Local Contact Person or Organization Landmarks Commission  30. Perservation Underway?  30. Preservation Underway?  31. Perservation Underway?  32. Contact Contact Person or Organization Landmarks Commission  33. Perservation Underway?  34. Preservation Underway?  35. Open to Public Results  36. Local Contact Person or Organization Landmarks Commission  40. Visible from Work Yes XX Public Read?  40. Visible from West X Public Read?  41. Distance from and Frontage on Road  50 feet on Walnut  42. Further Description of Important Features —The first floor of the facade has been modernized with display windows set in a metal frame. The upper floors are hidden behind a metal grill. A stepped parapet  43. History and Significance —This building has been used by a number of commercial firms over the years, including an electronic company, chandelier company, and an advertising company.  45. History and Significance —This building has been used by a number of commercial firms over the years, including an electronic company, chandelier company, and an advertising company.  46. Prepared by Sherry Piland  47. Organization Landmarks Commission  48. Prepared by Sherry Piland  47. Organization Landmarks Commission  48. Prepared by Sherry Piland  47. Organization Landmarks Commission  48. Prepared by Sherry Piland  49. Prepared by Sherry Piland  49. Prepared by Sherry Piland  40. Prepared by Sherry Piland  41. Prepared by Sherry Piland  42. Prepared by Sherry Piland  43. Prepared by Sherry Piland  44. Prepared by She |  |   | A STATE OF THE PARTY OF THE PAR |   | en                |
| Comparison   Com   |  | $N \longrightarrow$                                 |  |   |                   |
| Building XX  Object:  11. On National Yes 1:   |  | UTM   |  |   | Om                |
| Building XX  Object:  11. On National Yes 1:   |  |   | 25. Open to Yes IX   | 38. Preservation Yes  | pai               |
| 11 On National   Yes   |  |   |  | Underway? No XX   |                   |
| Register? No XX Eligible? No 1:  13. Part of Estab Yes 1: Hist District Yes X Hist Dist.? No XX Potent? No :  15. Name of Established District  16. Further Description of Important Features — The first floor of the facade has been modernized with display windows set in a metal frame. The upper floors are hidden behind a metal grill. A stepped parapet wall is visible above the grill.  17. History and Significance — This building has been used by a number of commercial firms over the years, including an electronic company, chandelier company, and an advertising company.  18. Description of Environment and Outbuildings — Surface parking lots are located to the north, east, and west of this building. A commercial building is located to the south.  19. Part of Estab Yes 1:  10. Visible from Yes XX Public Road? No 1:  11. Distance from and Frontage on Road 50 feet on Walnut  12. Further Description of Important Features — The first floor of the facade has been metal frame. The upper floors are hidden behind a metal grill. A stepped parapet  10. History and Significance — This building has been used by a number of commercial firms over the years, including an electronic company, chandelier company, and an advertising company.  18. Description of Environment and Outbuildings — Surface parking lots are located to the north, east, and west of this building. A commercial building is located to the south.  18. Pare yellow of Environment and Outbuildings — Surface parking lots are located to the north, east, and west of this building. A commercial building is located to the south.   |  |   | 20. Local Contact Ferson of Organization   | 39. Endangered? Yes XX  |                   |
| 13 Part of Estab Yes   1   |  |   | Editalia KS Collin 133 IOI   | - demolition and/or   |                   |
| Hist. Dist.? No XX Potenti? No:  15. Name of Established District  16. Name of Established District  17. Distance from and Frontage on Road 50 feet on Walnut  18. Further Description of Important Features — The first floor of the facade has been modernized with display windows set in a metal frame. The upper floors are hidden behind a metal grill. A stepped parapet wall is visible above the grill.  18. History and Significance — This building has been used by a number of commercial firms over the years, including an electronic company, chandelier company, and an advertising company.  19. Description of Environment and Outbuildings — Surface parking lots are located to the north, east, and west of this building. A commercial building is located to the south.  19. Public Road? No::  10. Distance from and Frontage on Road 50 feet on Walnut  10. Public Road? No::  11. Distance from and Frontage on Road 50 feet on Walnut  12. Further Description of Important Features — The first floor of the facade has been made and the south of the property o | 13. Part of Estab. Yes 11  |   |  |   | 18.5              |
| ### Prepared by  Sources of Information  WP# 25165  ### 25165  ### A Stapped paraget  ### 15 Sources of Information  ### 25165  ### 15 Perpared by  Sherry Piland  ### 15 Pate   ## Prevision Date(\$)  ### 25165  ### 15 Perpared by  Sherry Piland  ### 25165  ### 15 Pate   ## Prevision Date(\$)   |  |   |  |   |                   |
| 42. Further Description of Important Features The first floor of the facade has been modernized with display windows set in a metal frame. The upper floors are hidden behind a metal grill. A stepped parapet wall is visible above the grill.  43. History and Significance This building has been used by a number of commercial firms over the years, including an electronic company, chandelier company, and an advertising company.  44. Description of Environment and Outbuildings Surface parking lots are located to the north, east, and west of this building. A commercial building is located to the south.  45. Prepared by Sherry Piland  47. Organization Landmarks Commission  48. Date 49. Revision Date(s)  | 15. Name of Established D  | District  |  |   |                   |
| been modernized with display windows set in a metal frame. The upper floors are hidden behind a metal grill. A stepped parapet wall is visible above the grill.  43. History and Significance This building has been used by a number of commercial firms over the years, including an electronic company, chandelier company, and an advertising company.  44. Description of Environment and Outbuildings Surface parking lots are located to the north, east, and west of this building. A commercial building is located to the south.  5 Sources of Information WP# 25165  46. Prepared by Sherry Piland 47. Organization Landmarks Commission 48. Date 49. Revision Date(s)  |  |   |  |   |                   |
| years, including an electronic company, chandelier company, and an advertising company.  14. Description of Environment and OutbuildingsSurface parking lots are located to the north, east, and west of this building. A commercial building is located to the south.  5 Sources of Information WP# 25165  46. Prepared by Sherry Piland 47. Organization Landmarks Commission 48. Date 49. Revision Date(s)  | been modernized wall is visible a                                    | vith display wi<br>hidden behind<br>above the grill | ndows set in a metal frame. The<br>a metal grill. A stepped parapet  |   | in Conc. hannels, |
| WP# 25165  Sherry Piland  47. Organization  Landmarks Commission  48. Date 49. Revision Date(s)  | years, including a  14. Description of Environment west of this buil | nent and Outbuilding                                | company, chandelier company, and an a  | to the north, east, and                                       |                   |
| 47. Organization  Landmarks Commission  48. Date 49. Revision Date(s)  |  |   |  |   |                   |
| 48. Date 49. Revision Date(s)  | NI # 23103   |   |  |   |                   |
|  |  |   |  | Landmarks Commission  |                   |
|  | 1 11   |   |  |   | 1                 |



Office of Historic Preservation, P.O. Box 176, Jefferson City, Missouri 65101 HISTORIC INVENTORY JA-AS-005-575 Present Name(s) 1-B Ramada Inn Central 2 County 5 Other Name(s) Jackson not entered Landmarks Commission 16 Themalic Calegory 28 No of Stories 6 & Specific Location 29. Basement? Yes XX 610 Washington 17 Date(s) or Period 1961 30 Foundation Material concrete H Aural, Township & Vicinity 18 Style or Design 7 City or Town 31. Wall Construction 19 Architect or Engineer reinforced concrete & Site Plan with North Arrow Kivett & Meyers; McCallum 32 Roof Type & Material 20 Contractor or Builder flat; tar/gravel JASHING TON 33. No. of Bays Winn-Senter Front Side 21. Original Use, if apparent Propert Name a 34 Wall Treatment motel 22 Present Use brick mote1 35 Plan Shape Y-shaped 36 Changes 23 Ownership Public 11 Addition Private XX (Explain bereff on 842) Moved . 24 Owner's Name & Address. d known 37 Condition Interior & Cumdinates Exterior dood Lat Lung Ves XX 25 Open to Preservation Yes . Public? Underway? No iX Structure ! Sile 10 Object 11 Building 26 Local Contact Person or Organization 39 Endangered? Ves IX By What? Landmarks Commission Yes II 12 Is II 11 On National Yes No .X Eligible? No XI Register? 27 Other Surveys in Which Included Yes X 3 Part of Estab 14 District Visible from Yes .X No X MIST DIST ? Potent'1? Public Road? No . 41 Distance from and 15 Name of Established District Frontage on Road approx 100 feet on Washingt 12 Further Description of Important Features The Y-shape design was used to give all rooms an outside exposure. The building fronts to the north to Olher Names provide a view of the rivers and the downtown airport. The main entrance is on Washington Street. Exposed concrete beams and columns form a grid on the exterior of the building. Interspersed are brick panels and rectangular windows with aluminum trim. 13 History and Significance The construction of this \$21/2 million motel was announced 5 years before it was built. Organizational changes and plan revisions delayed the project. building contains 189 rooms. Description of Environment and Outbuildings Vacant land is to the south and west of this building. To the east are a surface parking lot and commercial buildings. North of this building is it's parking structure, which extends over a commercial building. Sources of Information 46 Prepared by Sherry Piland WP# 125935 47. Organization Kansas City Star, Jan. 15, 1961 Landmarks Commission 48 Date 49 Revision Dole(s) 1/16/81



STORIC INVENTORY JA-AS-005-576 4. Present Name(s) 1. No. 35-0 Street House 710 Washington 0191 2. County 5. Other Name(s) Jackson 3 Location of Negatives CBD #39-6 Landmarks Commission 16. Thematic Category 6. Specific Location 28. No. of Stories 29. Basement? Yes X. [ackson No I . 710 Washington 17. Date(s) or Period 1886 30. Foundation Material stone 45 - If Rural, Township & Vicinity 18. Style or Design 7. City or Town Kansas City, Missouri 19 31. Wall Construction Italianate masonry LB B. Site Plan with North Arrow 19. Architect or Engineer 32. Roof Type & Material 20. Contractor or Builder flat; tar & gravel 33. No. of Bays Front Side 21. Original Use, if apparent Present 710 residence 34. Wall Treatment 22. Present Use Washington brick 35. Plan Shape residence rectangula: 36. Changes 23 Ownership Public 11 Addition : Private XX (Explain Altered D in #421 Moved i 24. Owner's Name & Address. if known 37. Condition Interior 9. Coordinates UTM fair Exterior Lat Long 25. Open to Yes ! Preservation Yes . Public? No XX Underway? No Site!: Structure 1 Building IXX Object 11 39. Endangered?future 26. Local Contact Person or Organization Yes XX By What? No Î Yes 11. On National Yes II Is It Landmarks Commission Register? No IXX Eligible? No 11 27. Other Surveys in Which Included redevelopment YesXX Yes !XX 13. Part of Estab. Yes II District 40. Visible from Hist. Dist.? No IXX Potent'l? Public Boad? No II 41. Distance from and 15. Name of Established District Frontage on Road 25 feet on Washingto 42. Further Description of Important Features The main facade faces east and is 3 bays in width. bay on the north contains the entrance. Slender wood posts, with decorative capitals, a flat roof over the 1st floor, east facade. The first floor windows are set in semi-circula The 2nd floor windows are set in segmental arched openings. The double hung sash windows have stone sills. Keystones decorate the east facade windows. metal cornice runs above the 2nd floor windows on the east facade. 43. History and Significance This is the only residence remaining on this block. Samuel Kraus resided here in 1887-88. 44. Description of Environment and Outbuildings A commercial building is to the east. To the north and west is vacant land. A surface parking lot is to the south. The building sits above grade. garage is located at the rear of the property. 45 Sources of Information 46. Prepared by WP #609 Piland/Uguccioni 47. Organization Landmarks Commission 48. Date 49. Revision Date(s)

State Historical Tryey and Planning Office, 909 University Avenue, Suite 215,

Columbia, Missouri 65201

2/11/81




| da d                                | IC INVEN   |  |                                | -005-5        |
|---|--|--|--------------------------------|---------------|
| "18-C   |  | rage Consultants, Inc.   | C-67/                          | 4 0192        |
| unly<br>ackson  | 5 Other Name/s   | AND DESCRIPTION OF THE PROPERTY OF THE PROPERT | 7051                           | 10110         |
| stion of Negatives CBD #3   | 9-5 Western B  | Soiler Compound and Chemi  | ical Company                   |               |
| andmarks Commission   |  |  | A Marie Marie                  |               |
| ecilic Location   | 16 Then  | natic Category   | 28 No of Stor                  | 1-2<br>Yea Xi |
| 13-15 Washington  | 17 Date  | (s) or Period  |                                | No :          |
|   |  | 1924 (1941, addition)  | 30. Foundation                 | Material      |
| ly or Town II Rural, Towns  | hip & Vicinity 18 Style  | or Design  | 31. Wall Consti                | /             |
| ansas City, Missouri  | 19 Arch  | itect or Engineer  | reinforced                     |               |
| E FIEL WILL FROM  | Geor   | rge W. Swehla  | 32. Roof Type                  | & Material    |
|   | A CONTRACTOR OF THE PARTY OF TH | Brand Manual A   | flat; tar 33. No of Bays       | & gravel #4   |
| N   |  | Brand / The State A  | - Ernat                        | Side          |
|   | com  | mercial ONA SOA  | 34 Wall Treatm                 |               |
| 1.50  | 22 Pres  |  |                                | 30            |
| 1   | 23 Own   | mercial Public   | 35 Plan Shape<br>11 36 Changes | rectangular   |
| \ \sqrt{\delta} \ \ \sqrt{\delta} \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ | 23 04/14   | Private  | k! (Explain                    | Aftered 1     |
| É   |  | er's Name & Address,   | in 842)                        | Moved :       |
|   |  | nown athen   | 37 Condition<br>Interior       |               |
| ordinates UTM   |  | 7  | Exterior                       | aooq          |
| ny  | 25 Open  |  | 38. Preservation               | Yes           |
| Sile:   | Structure 1 . Publi  | ic? No i<br>ii Contact Person or Organization  | Underway?  39 Endangered:      | No X          |
| National Yes 12 Is I  | ZO LOCA  | dmarks Commission  | By What?                       | Yes III       |
|   | ible? No X 27 Other  | Surveys in Which included  |                                |               |
| st Dist ? No . Po   | entil? No is   |  | 40 Visible from<br>Public Road |               |
| arise of Established District   |  |  | 41 Distance fro                |               |
|   |  |  | Frontage on                    | Road          |
|   | The main   | tagada tagag wagt. An  |                                | n Washington  |
|   |  | facade faces west. An egroups of 4, one-over-one   |                                |               |
|   |  | tone coping. A 2 story   |                                |               |
| m 1941 (Morris Hoffm  | an Const. Co.).  |  | 1                              | note          |
|   |  |  | /                              |               |
|   |  |  | /                              |               |
|   |  |  | 1                              |               |
|   |  | this structure was the   | western boller                 |               |
| Compound and Chemical   | Company.   |  |                                |               |
|   |  |  |                                |               |
|   |  |  |                                |               |
| scription of Environment and  | Outbuildings Surface   | e parking lots are to the  | e north and soul               | th of this    |
|   |  | uilding, while a residence   |                                |               |
|   |  |  |                                |               |
|   | R WALLER BOOK  |  |                                |               |
| urces of, information   |  |  | 46. Prepared by                |               |
| WP #718   |  |  | Diland                         |               |
| WP #718<br>Western Contractor, 3  | July 2, 1924, p. 4   | 12.  | Piland 47. Organization        |               |

2/6/81 49 Revision Dele(s)




10/77



Columbia, Missouri 65201 HISTORIC INVENTORY -AS-005-579 1. No. 4. Present Name(s) 35-S Dan Dee Transfer Company 80 JA0199 . County Jackson 5. Other Name(s) 3 Location of Negatives CBD Landmarks Com mission #39-4 Dan Dee Delivery 6. Specific Location 16. Thematic Category 28. No. of Stories 29. Basement? 810 Washington Yes I 17. Date(s) or Period No I 30. Foundation Material 1946 7. City or Town - If Rural, Township & Vicinity 18. Style or Design 69 31. Wall Construction Kansas City, Missouri concrete block 19. Architect or Engineer 8. Site Plan with North Arrow 32. Roof Type & Material 20. Contractor or Builder PR flat; tar & gravel H 33. No. of Bays Front Side 21. Original Use, if apparent 3 Present Name(s) commercial 34. Wall Treatment 22. Present Use concrete block 35. Plan Shape rectangular commercia1 23. Ownership Public 11 36. Changes Addition 1: Private IXX (Explain Altered 1 : in #42) Moved i 24. Owner's Name & Address, if known 37. Condition Interior 9. Coordinates UTM Exterior Lal. good Long 25. Open to Yes I i 38. Preservation Yes I Public? No XX Underway? No XX 10 Structure | Site!: Building XX Object 11 26. Local Contact Person or Organization 39. Endangered? Yes ! By What? No XX Yes! 11. On National Yesii 12 Is It andmarks No XX Register? Eligible? No KK 27. Other Surveys in Which Included 13. Part of Estab. Yes 11 Yes i 40. Visible from 14. District Yes XX No XX Potent'l? Hist. Dist.? No XX Public Road? No II 41. Distance from and 15. Name of Established District Frontage on Road 33 feet on Washington 42. Further Description of Important Features This concrete block building faces to the east. A garage door is located on the south side of the east facade, while the other half contains an Unici itame(S, entrance door and a window. Three windows on the south wall have been filled in Photo 43. History and Significance The original owner of this building, and operator of the Dan Dee Delivery Service, was Joseph Young. 44. Description of Environment and Outbuildings Surface parking lots are to the north and south of this building. To the west is vacant land. A commercial building is to the east. 46. Prepared by 45 Sources of Information Piland BP #16304 47. Organization WP #5004 Landmarks Commission 48. Date 49. Revision Date(s) 1/29/81

State Historical Survey and Planning Office, 909 University Avenue, Suite 215,



HISTORIC INVENTORY TA-AS-005-580 No 53-E Washington Street Station (restaurant) 2 County 5 Other Name's) Jackson 3 Lucation of Negatives CBD# 29-14 J.E. Walker Manufacturing Co.; Burlington Manufacturing Co. Landmarks Commission 16 Themalic Calegory 28 No of Stories & Specific Location ackson 29. Basement? 900-02 Washington 17 Date(s) or Period No : . 1909 (c.1925, addition) 30. Foundation Material H Aural, Township & Vicinity 18 Style or Design City or Town 31. Wall Construction Kansas City, Missouri LB mill Sile Plan with North Arrow 19 Architect or Engineer Greenebaum, Hardy & Schumacher 32. Roof Type & Material 9TH ST flat; tar/gravel Ft PR 20 Contractor or Builder 33. No. of Bays Daniel Sutter WASHING TON From 6 21. Original Use, If apparent Side Present Name(s) commercial OPA 34 Wall Treatment 22 Present Use brick commercia1 35. Plan Shape rectangular Washington 36 Changes 23 Ownership Public I Addition . Privatery (Explain Attered i m 842) Moved : 24. Owner's Name & Address, of known other 37 Condition dood Interior Cuprdinates UTM Exterior good Lung 25 Open to YesXX 38. Preservation Yes X Public? Underway? No : Sile Structure ! Building Object 11 26 Local Contact Person or Organization Endangered? By What? No X 11 On National 12 Is II Yes IX Yes Landmarks Commission No . X Eligible? No II Register 27 Other Surveys in Which Included Yes IX Yes ... 13 Part of Estab 14 District 40 Visible from Yes X HIST DIST ? Potent'1? Public Road? No :: Distance from and 15 Name of Established District 122 ft Frontage on Road on Washington 42 Further Description of important features An addition (the south portion of the building) in 1925 increased this building to 36,000 square feet The addition is identical to the original building. Brick piers divide the building into 6 bays. The 1st floor has undergone some Names minor alterations. Each bay of the 2nd & 3rd floors contains paired, double hung, sash windows. The piers extend slightly beyond the roof line. 43 Missory and Significance From 1909 to 1914 this building was the home of the J.E. Walker Manufacturing Company, a firm that produced shirtwaists. From 1915 to 1966 it was occupied by the makers of overalls and work clothes, the Burlington Manufacturing Company. In 1966 the Burlington Manufacturing Company was purchased by the Genesco Corporation and the building was vacated. After interior remodeling, it was reopened in 1972 as a restaurant. 44 Description of Environment and Outbuildings The building is surrounded by surface parking lots. Sources of Information Kansas City Star, April 1, 1973 Western Contractor, July 14, 45. Prepared by WP# 40659, BP# 9361 Sherry Piland 1909, p. 3. 47. Organization Wednesday Magazine, June 14, 1972. Kansas City Star, June 11, 1972, p. 2E. Landmarks Commission 48. Date 49 Revision Dale(s) BP #14281

1/19/81

Office of Historic Preservation, P.O. Box 176, Jefferson City, Missouri 65101



State Historice Survey and Planning Office, 9( Iniversity Azenue, Suite 215, Columbia, Missouri 65201 ORIC INVENTORY TA-AS-005-4. Present Name(s) No CED Apartment House (1013-15 Washington St.) 2 County Jackson 3 Location of Negatives ( D# 0-Elenora Lehman Boarding House .89 Landmanks Commission 16. Thematic Category 28. No of Stories 5 Specific Location Jac architecture Yes X 29. Basement? 17 Date(s) or Period No ! 1013-1015 Washington St. 30. Foundation Material 1901 97 If Aural, Township & Vicinity \$18. Style or Design masonry 31. Wall Construction Kansas Citv. Mo. 64105 Georgian Revival 19 Architect or Engineer 3. Sile Plan with North Arrow brick N John C. Williams 32. Roof Type & Material 120. Contractor or Builder flat, tar/gravel 33. No of Bays WASHINGTON ST. Front 3 Side 7 21. Original Use, if apparent 34. Wall Treatment Boarding house 22. Present Use brick 35. Plan Shape rectangle apartments 36. Changes 23 Ownership Public 1 Addition . : Altered X Private +1 (Explain in #42) Moved 24. Owner's Name & Address, Cecil T & Lola it known 37. Condition Hastings, 1015 Washington St. Interior UTM y Coordinates Kansas City, Missouri 64105 Exterior Lat Long YesIX 25. Open to Preservation Yes X Public? No 1 restricted Underway? No . Structure Object : i Building X 39 Endangered? 26 Local Contact Person or Organization Yes X Landmarks Commission By What? No 1: YesX 11. On National 12 Is It Yes X Eliqible? No ! 27. Other Surveys in Which Included redevelopment Register? Yes IX District Visible Irom Yes X 13. Part of Estab Yes IXX Public Road? Potent'1? Hist. Dist.? No ' No :: (None) Distance from and 21 15. Name of Established District Frontage on Road Quality Hill Neighborhood 45' Washington 42. Further Description of Important Features The main facade faces west and is three bays wide. On each corner of the main facade were three story open porches with flat roofs supported by square wooden columns. The porches have been screened in and the wooden columns replaced with brick piers. The central porjecting bay contains two oeil-de-boeuf windows located between each story. Small single light square windows are located along both corners of the projecting bay, again between each story. The 43. History and Significance remaining windows are one over one double hung sash windows in segmental openings. A wide plain box cornice runs along the main facade. This apartment house was designed by and for John C. Williams, a Kansas City architec in 1901. In 1902 the structure was a boarding house run by Elenora Lehman. 4: Description of Environment and Outbuildings This building is located in the Quality Hill neighborhoo in the Central Business districtof downtown Kansas City, Missouri. To the north is a parking lot, to the south the Musicians Union, to the west an empty lot and to the east a commercial structure. 45 Sources of Information Hoye City Directory, 1902, p. 1338 46. Prepared by Linda F. Becker Water Permit No. 17848, Water Dept. Kity Hall Kansas City Mo. 47. Organization Landmarks Commission 43. Date 49. Revision Date(3)

The stra and Apartments, 515 W. 11th ...

1013-15 washington Kic.


topped with a gable. On the second floor are three windows grouped in a segmental arch opening. The windows are six over six double hung sash windows. On the first floor are four windows grouped in a segmental arched opening. The windows are four over six double hung sash windows. Rusticated stones are used for decoration at the lower edge of the first floor and main entrance.



JA-AS-005-582 State Historical Levey and Planning Office, 909 ( versity Avenue, Suite 215, Columbia, Missouri 65201 HISTORIC INVENTORY 11. 10 111.6-00 4. Present Name(s) Musicians' Union Building CBD 71-F County Jackson 5 Other Name(s) Location of Negatives Kansas City Progress Club House Landmarks Commission 16 Thematic Calegory 28 No of Stories Specific Location Architecture 29. Basement? 1017 Washington Yes !X 17 Date(s) or Period No i Kansas City, Missouri 30 Foundation Material 1893 Son rubble stone 18 Style or Design If Rural, Township & Vicinity ' City or Town Chateauesque 31. Wall Construction Kansas City brick Site Plan with North Arrow 19 Architect or Engineer Louis Curtiss, Frederick Gunn 32. Roof Type & Material 20 Contractor or Builder hip/shingle DASHINGTON 33. No of Bays Front Side 21 Original Use, if apparent Musica 34. Wall Treatment Private club house 22 Present Use brick 35. Plan Shape Union office for musicians 36 Changes 23 Ownership Public 11 Addition : : Private U (Explain Altered X: in #421 Moved i 24. Owner's Name & Address, il known Kansas City Musician 37. Condition Ton Interior excellent --Coordinates 1017 Washington, K.C., Mo. Exterior excellent Lat. Long 25 Open to Yes X Preservation Yes . Public? No II restrictive Underway? No ix Site ! Structure 1: Building M Object ! ! 26. Local Contact Person or Organization Endangered? Yes IX By What? No 1: Yes XX 12 15 11 Yes ! : Landmarks Commission Kansas Cit 11. On National Eliqible? No X' Register? No C 2/ Other Surveys in Which Included possible redevmt. Preliminary Inventory of 3. Part of Estab. Yes XX 14 District Yes I 40. Visible from Yes IX on Public fload? Potent'1? NOX Hist. Dist.? No : Kansas City, Landmarks Commiss No ! : Distance from and 10ft. 15. Name of Established District Frontage on Road Quality Hill Neighborhood 42. Further Description of Important Features The Music lans' Union Hall has a balanced, well organized Chateauesque facade with neoclassic decorative elements. Individual decorative details bear a resemblance to the Missouri State Building designed the same year. Square towers flank a center bay which contains the elevated main entrance at the apex of an areade of round arched windows. Above are three ocular windows with ornate copper surrounds connected by bellflower swags. 43. History and Significance The Progress Club served as headquarters for a social club composed of locally prominent families of Jewish descent. Cards, suppers and balls were the most usual social activities. The Ohio delegates to the 1900 Democratic Convention used the building as their headquarters. The structure is also architecturally significant in that it was designed by two outstanding Kansas City architects, Louis S. Curtiss and Frederick Gunn. 44 Description of Environment and Outbuildings Located on the western edge of the downtown area, the building is situated amid parking lots and the remnants of a 19th century residential district. 46 Prepared by Linda F. Pecker 45 Sources of Information Landmarks Survey Form B Commission - Kansas City 47. Organization Kansas City City Hall Landmarks Commission Kansas City, Missouri 48. Date 49. Revision Date(5) . 1199



State Historical Sur J and Planning Office, 909 Univ sity Avenue, Suite 215. olumbia, Missouri 65201 JA-AS-005-583 Present Name(s) 70-L House CBD 1018 Washington) 2 County Jackson 5. Other Name(s) 3 Location of Negatives Landmarks Commission (BO#30-3 J. G. Ladd Residence 6 Specific Location 15. Thematic Category 28. No. of Stones 29. Basement? Jackson Yes X 1018 Washington St. 17 Date(s) or Period addt. c. 1925-40 No 1 . 1879, addt. c. 1907-25, 30 Foundation Material 7 City or Town If Rural, Township & Vicinity Kansas City 18 Style or Design masonry 31. Wall Construction Builder's Vernacular 8. Site Plan with North Arrow 19 Architect or Engineer rame, brick 15 32. Roof Type & Material 20. Contractor or Builder gable, flat, shingle の名といいのでわる 33. No. of Bays Front 2 Side 21. Original Use, if apparent residence 34. Wall Treatment 1018 22. Present Use brick, frame multi family dwelling 35. Plan Shape mod . L 36 Changes 23 Ownership Public 11 Addition X Washington Private 1 x (Explain Altered i in #42) Moved : 24. Owner's Name & Address. if known 37. Condition Interior R.J. Cyr IITM Coordinates fair Exterior 920 Main, Rm. 707, K.C. Mo. iat Long 25 Open to Yesx Preservation Yes X S Underway? Public? No i restricted No : Site Structure Building X Object 26. Local Contact Person or Organization 39. Endangered? Yes X By What? No 1: Yes :X Landmarks Commission Yes XX 11. On National Eligible? No 1! redevelopment Register? No 3. 27. Other Surveys in Which Included Yes X 14. District 13 Part of Estab. YesXX 40. Visible from Yes X Hist. Dist ? Potent'l? No: Public Road? No 1 No 11 41. Distance from and 15. Name of Established District 351 Frontage on Road Ouality Hill Neighborhood 42. Further Description of Important Features The main entrance faces east and is three bays wide. The fenestration consists of two-over-two lights, double hung sash windows in rectangular window openings with molded lintels. A .. one story, wood and brick open porch, with a flat roof is located on the main facade. The rear section add Residence of the structure is brick while the front section is frame. The house was constructed in three stages, the front section done in 1879 and the rear section built c. 1907-25 and the mid section 43. History and Significance built sometime between 1925-1940. The first person to live in the house was a J.G. Ladd, a railroad conductor. structure is an example of the builder vernacular style. 44. Description of Environment and Outbuildings This structure is located in the Quality Hill neighbor hood of the Central Business District of downtown Kansas City, Missouri. To the north is an empty lot, to the west the architectural firm of Monroe & Lefebvre. to the south a multi family dwelling and to the east an apartment house and the Musician' WP #964 5 Sources of Information 46. Prepared by Kansas City Hoye City Directories, 1879--1888 Linda F. Becker Public Works Department, City Hall, Kansas City , Missouri 47. Organization Landmarks Commission 48. Date 49 Revision Date(s) 4/77



State Historical Survey and Planning Office, 909 Uni sity Avenue, Suite 215. Columbia, Missouri 65201 HISTORIC INVENT JA-AS-005-58 4. Present Name(s) I No C DD 70-M House (1026 Washington St.) 2 County CBD Jackson 5. Other Name(s) 3 Location of Negatives (b) + 6-2 Landmarks Commission Peyton Montgomery Residence 5. Thematic Category architecture Specific Location 28 No of Stories 2 29. Basement? Yes ! 1026 Washington Jackson 17. Date(s) or Period No I 1877 30. Foundation Material City or Town Ransas City, Mo. 64165 18 Style or Design masonry 31. Wall Construction Kansas City Peak 8. Site Plan with North Arrow 19 Architect or Engineer brick 32. Roof Type & Material 20. Contractor or Builder K.C. peak 33. No. of Bays Front Side Original Use, if apparent 3 residence 34. Wall Treatment 22. Present Use brick 35. Plan Shape mult-family dwelling cross 1026 23 Ownership Public 11 35. Changes Addition Altered X Private 1x (Explain in #42) Moved i 24. Owner's Name & Address, if known Demtra Koutsoubos 37. Condition Interior 7420 Terrace 9 Coordinates UTM Kansas Citv. Mo. 64114 Exterior Lat. Long 25 Open to YesX 38. Preservation Yes X Public? Underway? S :e Structure restricted No i Building X Object : 1 26 Local Contact Person or Organization 39. Endangered? Yes X By What? 11. On National YesXX 12 Is It YesX Landmarks Commission No I: Register? Eligible? No I No: : 27. Other Surveys in Which Included redevelopment 13 Part of Estab YesXX Yes X 14. District Visible Irom Yes X Potent'l? No: Public Road? Hist. Dist.? No: (None) No :: 15. Name of Established District 41. Distance from and Frontage on Road Quality Hill Neighborhood 42 Further Description of Important Features The main facade faces east and is three bays wide. The fenestration is one-over-one double hung sash windows in segmental arch openings on the senond floor and rounded arch opening on the first floor. The main entrance is placed in a rounded arch opening. on the second floor are eccented with cut stone keystones. A one story porch with a shedroof supported by wooded piers Pevton runs along the main facade. The roof is Kansas City peak. 43 History and Significance The structure is a fine example of the Kansas City peak style of architecture. The first resident that could be found living in the house was Payton Montgomery, of Quilan, Montgomery & Co. Kansas City Stock Yards. Montgome@y The house was built for Thomas Corrigan for speculation and is similar in design to 1028 and 1030 Washington , now part of the Virginia Hotel. 44 Description of Environment and Outbuildings This sturcture is located in the Quality Hill neighborh located in the Central Business district of downtown Kansas City, Missouri. Residence To the west is an empty lot, to the north a multi family dwelling, to the south is the Virginia Hotel and to the east a parking lot. Sources of Information Hoye City's Directory, 1886, 1888 46. Prepared by Water Permit No. 373 Water Dept. City Hall, Kansas City Linda F. Becker Missouii. 47. Organization Landmarks Commission 48 Date 49 Revision Date(s)



State Historical Survey and Planning Office, 909 Uni rsity Avenue, Suite 215, Columbia, Missouri 65201 HISTORIC INVENT JA-AS-005-57 esent Name(s) No CBD 70-N CIII Virginia Hotel 2 County Jackson Other Name(s) Ten Thirty Washington Apartments 3 Location of Negatives Landmarks Commission 16. Thematic Category 28. No. of Stories 6 Specific Location 29-16 Jackson Architecture 29. Basement? Yes X 1030 Washington St. 17. Date(s) or Period No i 30. Foundation Material 1877, 1892 masonry 18. Style or Design If Aural, Township & Vicinity 7 City or Town 31. Wall Construction Victorian Eclectic 64105 Kansas City Mo. brick Sile Plan with North Arrow W. 11 15 ST. 19 Architect or Engineer 32. Roof Type & Material attr. Louis Curtiss (addtn.) MASHERATON flat/tar/gravel 20. Contractor or Builder 33. No. of Bays Geo. Brown & Son Front Side 5 21. Original Use, if apparent 34. Wall Treatment apartment hotel brick 22. Present Use 35. Plan Shape apartment hotel 2 36. Changes Addition X 23 Ownership Public 11 Altered X (Explain Private IX in #42) Moved i 24. Owner's Name & Address, if known The Cathedral Sq. Corp 37. Condition Interior c/o Catholic Diocese UTM Coordinates P.O. Box 1037, KC, Mo. 64141 Exterior good Lat Long YesX 38. Preservation 25. Open to Underway? No i restricted Structure 3.ie YesX Building IX Coject . 26. Local Contact Person or Organization 39 Endangered? By What? No 1: Landmarks Commission Yes X 12 Is It Yes X 11 On National redevelopment Eligible? No Register? No 1 27. Other Surveys in Which Included 40. Visible from Yes X Yes ! District 13. Part of Estab Yes IXX Public Road? No: No : Potent'1? Hist. Dist.? (None) 41. Distance from and 15. Name of Established District Frontage on Road Quality Hill Neighborhood 42. Further Description of Important Features The main facade faces east. A Virginia balustrated one story veranda porch supported by wooden turned posts has been removed. The fenestration consists of oneover-one double hung sash windows in segmental arch openings. The roof was gabled with three Kansas City "peaks" on the main facade. A decorative frieze and large brackets supporting the cornice have all been removed. There remains only a flat roof. A central bay projects from the main facade. 43 History and Significance The structure is significant as it is composed of two 1877 residences built for Thomas Corrigan. The addition making it into a hotel was designed by Louis Curtiss and built by GEo. Brown & Sons in 1892 for Thomas Corrigan. Wallace Pratt, a prominent Kansas City Attorney was the first residence of the 1877 structure at 1030 Wash. In 1881 Thomas Corrigan moved into the house at 1030 Washington unffl 1892 when be had the hotel built. Description of Environment and Outbuildings This structure is located in the Quality Hill neighborhood of the Central Business District of downtown Kansas City, Missouri. To the north is a multi family dwelling, to the east is a parking lot, to the west the La Homa Hotel and to the south the Normandy Apartments. 45 Sources of Information Water Permit No. 373, 374 Water Dept. City 45. Prepared by Linda F. Becker Hall, Fansas City, Missouri. Kansas City Times, Janl 1893 47. Organization Londmarks Commission Louis Curtiss, list of his works 48. Date 49 Revision Date(s)

3/77



1110-1120 Washington St. K.C.

located at the souheast corner of the main facade. On the second story is a palladian window. An identical window is on the southside of the tower. On the south side of the building, attached to the tower is a one story, one door garage with a truncated hipped clay tile roof. Four storefront fare located west the single entrance.

windows of



Columbia, Missouri 65201 TA-AS-005-28: 4. Present Name(s) 1 No. 104-L CBD Roslin Hotel/Lykins Residence 2. County Jackson Lykins Residence; Mondamin Hotel K. C. 3 Location of Negatives Landmarks Commission CBD#4-11,12 Specific Location 1204 Washington Street 16. Thematic Category 28. No. of Stories tour Yes X 29. Basement? Southwest corner of West 12th 17. Date(s) or Period No i and Washington Streets 1856-57, 1889 30. Foundation Material Rubble Limestone City or Town II Aural, Township & Vicinity Kansas City, Missouri 64105 18 Style or Design Classic Revival/Victorian Ecl. Style or Design 31. Wall Construction Masonry and Wood 19. Architect or Engineer Alexander Bros. (Lykins Res.) 32. Roof Type & Material Flat; tar and gravel 20. Contractor or Builder Alexander Bros. (Lykins Res.) 33. No. of Bays Front 5 Side 4/5 21. Original Use, if apparent Resdidence; later Hotel 34. Wall Treatment brick 22. Present Use veneers on com. brick Commercial; Hotel 35. Plan Shape Square/ U 23. Ownership Public !! 36. Changes Addition X: Private 1'x (Explain Altered X' in #42) Moved X 24. Owner's Name & Address, WASHINGTON AVE 37. Condition Fair il known Samuel Brancato c/o Interior Zaira Realty Co. Inc., 801 Coordinates Exterior West 68th Terrace, KC, Lat Long 25. Open to Yes Ix Preservation Yesx Public? Underway? Restricted No i Structure 1 -Site ! : Building Ix Object : I Yesix 26. Local Contact Person or Organization 39. Endangered? By What? No 1: Landmarks Commission of KCMo Yes X 11. On National Yes X 12 Is II Eligible? No : 27. Other Surveys in Which Included Register? Noj! Re-development 13. Part of Estab. Yes! A Yes X The Need for the Preservation 40. Visible from 14. District Yes X Potent'l? No : Public Road? Hist. Dist ? of Kansas City's Architecture No 11 41. Distance from and 8ft. Heritage, K. C. Chapter AIA 15. Name of Established District 917West 43rd Street, Kansas app. 59 along Washing Quality Hill Neighborhood City. Missouri 64111 on Stroot 42. Further Description of Important Features The original two and one-half story Classic Revival Style Lykins Residence, 1856-57; residence moved 1889; across washington Street; Masonry ground floor foundation 1889; a fourth story was added after the removal of the hip roof and observatory, ca, 1890-1910; erection of a brick two story addition along the southwest corner of the building1891; a single story store building attached to the northeast corner, ca. 1910; Additional W. 12th Street stores built, 1915 and 1938. The (con't 43. History and Significance The Dr. Johnston-Lykins residence erected 1856-57, is a rare survivng example of Mid-Nineteenth Century, Classic Revival style residence with Late Nineteenth century and Early Twentieth Century Hotel and commercal modifications located in Kansas City's Central Business District. Significantly related to the birth and early development of Kansas City, the residence is association with two of the city's pioneering citizens. Dr. Johnston A. Lykins and Martha A. Lykins-Bingham. 44. Description of Environment and Outbuildings The Roslin Hotel/ Lykins Residence is located in the "Quality Hill" Neighborhood in Downtown Kansas City. The area contains late Nineteenth Century single familyand multi-family residential structures and various commerial structures located to the immediate north and west. A parking lot is placed to the soul 46. Prepared by Sources of Information Kansas City (Missouri) Star, June 26, 1910, p. 2. Ed Miszczuk Kansas City (Missouri) Times, Sept. 21, 1890, p.6. 47. Organization Landmarks Commission Kansas City: Its Resources and Their Development; A Souvenir of the Kansas City Times , (Patterson and White, Philadelphia 48. Date 49. Revision Date(s) Pa.,) Ca., 1891, pp.30, 40. 5/18/76

State Historical Survey and Planning Office, 909 University Avenue, Suite 215,

HISTORIC INVENTORY- State Historic Survey and Planning Office

Roslin Hotel/Lykins Residence 1204 Washington K.C. Kansas City, Missouri

42. Further Description of Important Features (Con't)

oringinal residence presently the second and third floors of the hotel. Ornate limestone sills and carved pediment lintels of the second and third story exteriors. Balcony entrances of the hotel (the original Lykins\_residence) consist of single leaf doors flanked by side windows and transomes, divided into smaller\_rectangle lights by wooden muntins. Interiors have grand U-shape three run staircase guarded by lathe-turned balustrades. Ornate classical doorway and window trim on the second and third floors of the hotel. Pressed Metal ceilings in the ground floor level.





Office of Historic Preservation, P.O. Box 176, Jefferson City, Missouri 65101 HISTORIC INVENTORY TA-A6-005-588 4 Present Name(s) No 105-E First National Bank Drive-In 2 County 5 Other Name(s) Jackson not entered Lucation of Negatives CBD#4-14,4-1 Landmarks Commission 16. Thematic Category 6 Specific Location 28. No of Stories 29. Basement? Yes IX 17 Date(s) or Period 1239 Washington 1960-61 30. Foundation Material 18 Style or Design 7 City or Town If Aural, Township & Vicinity concrete Neo-Colonial (Twentieth Century Kansas City, Missouri 31. Wall Construction 19. Architect or Engineer 8 Site Plan with North Arrow brick Marshall and Brown 32. Roof Type & Material 20 Contractor or Builder flat; tar/gravel MASHINGTON Schweiger Construction Co. 33. No. of Bays 21. Original Use, if apparent Front First Side Present Name(s) drive-in 34. Wall Treatment 22 Present Use brick drive-in 35. Plan Shape square 23 Ownership Public I 36. Changes Addition tiona Private IX (Explain Altered i in #42) Moved i 24. Owner's Name & Address. W. 13th if known 37. Condition Interior excellent Ba 9 Coordinates Exterior excellent 7 Lung 25. Open to Yes IX Preservation Dri Public? Underway? 10 Site Structure ! . No X Building X Object | | ve-26. Local Contact Person or Organization 39. Endangered? Yes !! Landmarks Commission By What? 11 On National 12 is It Yesii No X Yes No IX Eligible? Register? No . X 27. Other Surveys in Which Included Part of Estab District Yes . Yes Visible from Yes X HIST DIST ? No Y Potent'1? No IX Public Road? No i 15 Name of Established District 41. Distance from and Frontage on Road 42 Further Description of Important Features - This Southern Colonial bank building is square in plan and one story in height. An ionic peristyle OTher surrounds the exterior of the building. Between the columns are wrought iron balustrades. The entrances consist of a fifteen light Name(s) Photo door with eight light transom above. 43 History and Significance -- This building along with its parking lot replaced an historic residential structure called "Aldine Place." 44 Description of Environment and Outbuildings To the south is an additional drive-in section to the bank while to the west and east are parking lots and to the north is 45 Sources of Information 46. Prepared by Linda F. Becker WP# 18947, Water Department, City Hall, Kansas City, Missouri 47. Organization BP# 19108, Public Works, City Hall, Kansas City, Missouri Landmarks Commission BP# 63503A (parking lot) 48. Date 49 Revision Date(s) Kansas City Star, March 20, 1960, p. 11E 3/80

Kansas City Star, February 21, 1960, p. 1F





| . No. 120-D   | A. Present Name(s)   |   |
|---|--|---|
| County  | Haden Hall   |   |
| Jackson Location of Negatives CBD #53-  | 5. Other Name(s)   |   |
| Landmarks Commission  |  |   |
| Specific Location   | 16. Thematic Category  | 28. No. of Stories 1  |
| 1301 Washington   | 17 Data(e) or Poyled   | 29. Basement? Yes I. No I.  |
|   | 17. Date(s) or Period<br>1954  | 30. Foundation Material   |
| City or Town . If Rural, Township   |  | concrete  |
| Kansas City, Missouri   |  | 31. Wall Construction   |
| Site Plan with North Arrow  | 19. Architect or Engineer  | masonry   |
|   | Keene & Simpson 20. Contractor or Builder  | 32. Roof Type & Material see #42  |
| 3 N   | Schweiger Const. Co.   | 33. No. of Bays   |
| Ř N   | 21. Original Use, if apparent  | Front 3 Side  |
| WASHINGTON  | ecclesiastical  22. Present Use  | 34. Wall Treatment  |
|   | ecclesiastical   | brick; stone  35. Plan Shape rectangular  |
|   | 23 Ownership Public !!   | 36. Changes Addition ::   |
|   | PrivateXXX   | (Explain Altered 1:<br>in #42) Moved i  |
|   | 24. Owner's Name & Address,.   | 37. Condition   |
| Coordinates UTM   |  | Interior  |
| Lat.  |  | Exterior excellent  |
| Long.   | 25. Open to Yes Li Public? No lyty   | 38. Preservation Yes Underway?  |
| Site ! : S<br>Building XXX  | Structure 1  | AA  |
| On National Yes 🗶 12 Is It  | Yes XX Landmarks Commission  | 39. Endangered? Yes I : By What? No XX  |
|   |  | - AMA   |
| Register? No 11 Eligible  | le? No 1! 27. Other Surveys in Which Included  |   |
| Part of Eslab. Yes XX 14. Distric   | ict Yes i  | 40. Visible from Yes XX   |
| Part of Estab. Yes XX Hist. Dist.? No 11 Poten  | ict Yes i  | Public Road? No 11  |
| Part of Estab. Yes XX 14. District Name of Established District   | ict Yes i  | Public Road? No 1: 41. Distance from and Frontage on Road   |
| Part of Estab. Yes XX 14. District Name of Established District Quality Hill  | ict Yes in the Salveys in Which included   | Public Road? No 1: 41. Distance from and Frontage on Road 140 feet on Washingto   |
| Part of Estab. Yes XX Hist. Dist.? No 11  Name of Established District  Quality Hill  Further Description of Important Footated, flanked by 3 narrohe door. The north facad indows near the top. A leglass-walled passageway  | ict Yes i  | Public Road?  41. Distance from and Frontage on Road  140 feet on Washingto  rance is centrally  fixed on the wall above brick, with a band of windows on the sides.  |
| Part of Estab. Yes XX Hist. Dist.? No 11  Name of Established District  Quality Hill  Further Description of Important Footated, flanked by 3 narrohe door. The north facad indows near the top. A leglass-walled passageway ere also expanded at the  History and Significance This amed in honor of the Rev.  | eatures The main facade faces north. The entrow, vertical fixed windows. A sculpture is the ise is faced with stone. The side walls are now gable, monitor-type roof is used, with we connects this building to the church on the time this building was constructed. Hare & educational building for the Grace and Holy Clarence Haden, former Dean of the Cathedr  | Public Road?  41. Distance from and Frontage on Road 140 feet on Washingto  rance is centrally fixed on the wall above brick, with a band of vindows on the sides.  east. The chusch ground Hare did the landscaping Trinity Cathedral was al.                                      |
| Part of Estab. Yes XX Hist. Dist.? No   1  Name of Established District Quality Hill  Further Description of Important Focated, flanked by 3 narrone door. The north facad indows near the top. A leglass-walled passageway are also expanded at the  History and Significance This amed in honor of the Rev.   | eatures The main facade faces north. The entrow, vertical fixed windows. A sculpture is the is faced with stone. The side walls are now gable, monitor-type roof is used, with we connects this building to the church on the time this building was constructed. Hare & educational building for the Grace and Holy Clarence Haden, former Dean of the Cathedre with the content of the Cathedre Clarence Haden, former Dean of the Cathedre Content of the Grace and Holy Clarence Haden, former Dean of the Cathedre Cat | Public Road?  41. Distance from and Frontage on Road 140 feet on Washingto rance is centrally fixed on the wall above brick, with a band of vindows on the aldes.  Photo east. The church ground Hare did the landscaping Trinity Cathedral was al.                                 |
| Part of Estab. Yes XX Hist. Dist.? No!!  Name of Established District Quality Hill  Further Description of Important Forcated, flanked by 3 narrow are door. The north facad indows near the top. A leglass-walled passageway are also expanded at the  History and Significance This amed in honor of the Rev.  Description of Environment and Outst is a motel. A restaurant        | eatures The main facade faces north. The entrow, vertical fixed windows. A sculpture is the is faced with stone. The side walls are now gable, monitor-type roof is used, with we connects this building to the church on the time this building was constructed. Hare & educational building for the Grace and Holy Clarence Haden, former Dean of the Cathedre with the content of the Cathedre Clarence Haden, former Dean of the Cathedre Content of the Grace and Holy Clarence Haden, former Dean of the Cathedre Cat | Public Road?  41. Distance from and Frontage on Road 140 feet on Washingto trance is centrally fixed on the wall above brick, with a band of vindows on the aides.  Photo east. The church ground Hare did the landscaping Trinity Cathedral was al.  46. Prepared by Sherry Piland |
| Part of Eslab. Yes XX Hist. Dist.? No!!  Name of Established District Quality Hill  Further Description of Important Forated, flanked by 3 narrowed and such a few and a sageway are also expanded at the History and Significance This amed in honor of the Rev.  Description of Environment and Outst is a motel. A restaurance of H104669 ansas City Times, May 24,                | eatures The main facade faces north. The entrow, vertical fixed windows. A sculpture is the is faced with stone. The side walls are now gable, monitor-type roof is used, with we connects this building to the church on the time this building was constructed. Hare & educational building for the Grace and Holy Clarence Haden, former Dean of the Cathedry and the country of the Grace and Holy Clarence Haden, former Dean of the Cathedry of the Grace and Holy Clarence Haden, former Dean of the Cathedry of the Grace and Holy Trinity Cathedry of the Grace and Holy Tr | Public Road?  41. Distance from and Frontage on Road 140 feet on Washingto trance is centrally fixed on the wall above brick, with a band of vindows on the aides.  Photo east. The church ground Hare did the landscaping Trinity Cathedral was al.  46. Prepared by Sherry Piland |
| Part of Estab. Yes XX Hist. Dist.? No!!  Name of Established District Quality Hill  Further Description of Important Focated, flanked by 3 narrow and the control of the north facad andows near the top. A leglass-walled passageway are also expanded at the History and Significance This amed in honor of the Rev.  Description of Environment and Outst is a motel. A restaution | eatures The main facade faces north. The entrow, vertical fixed windows. A sculpture is the is faced with stone. The side walls are now gable, monitor-type roof is used, with we connects this building to the church on the time this building was constructed. Hare & educational building for the Grace and Holy Clarence Haden, former Dean of the Cathedry and the country of the south. Church grounds are the south of the south. Church grounds are the south of th | Public Road?  41. Distance from and Frontage on Road 140 feet on Washingto distance is centrally fixed on the wall above brick, with a band of windows on the sides.  Photo east. The church ground Hare did the landscaping al.  46. Prepared by                                   |

State Historical Survey and Planning Office, 909 University Avenue, Suite 215,



State Historical Sur y and Planning Office, 909 University Avenue, Suite 215, olumbia, Missouri 65201 HISTORIC INVENTORY TA-AS-005-590 1. No. 4. Present Name(s) CBD - # Old Union Mission 5-D 2. County Jackson 5. Other Name(s) 3 Location of Negatives K. C.CBD#8 Missouri, Kansas & Texas Trust Company, Guardian Trust Company Landmarke fo 6 Specific Location 16. Thematic Category 7 28. No. of Stories 030 Architecture/Economics 29. Basement? Yes X 620-624 Wyandotte Street Date(s) or Period No 1. 1889 30. Foundation Material 18 Style or Design 7 City or Town . If Rural, Township & Vicinity Rubble Limstone Kansas City, Missouri 64105 Victorian Eclectic 31. Wall Construction 8. Site Plan with North Arrow 19. Architect or Engineer Masonry & Mill Harry Lindsay 32. Roof Type & Material 20. Contractor or Builder Flat: Tar & Gravel 33. No. of Bays T. Howard Oliver Front 3 Side 6 Original Use, if apparent 34. Wall Treatment Commercial 22. Present Use Br. Ven over Com. Br. WEST 7th ST. Commercial 35. Plan Shape Rectangular 23 Ownership Public 1 ! 36. Changes Addition :: Private IX (Explain Altered I in #42) Moved i 24. Owner's Name & Address, if known Curtis & Mary Yates, et. 37. Condition al., 10617 E. 53rd St., Kansas Interior 9. Coordinates IITM City, Missouri 64133 Lat. Exterior Long 25. Open to Yes K Yes X 38 Preservation Public? Restricted Noil Underway? No i Site ! : Structure 1 Building & Object | | 26. Local Contact Person or Organization 39. Endangered? Yes X By What? No 1: 11. On National Yes K Landmarks Commission Yes X 12 Is It Register? No = Eligible? No 1 ! 27. Other Surveys in Which Included Future Redevlopment 13. Part of Estab. Yes Yes Z 14. District Visible from Yes X Hist. Dist.? Potent'l? No: Public Road? (None) No i 15. Name of Established District 41. Distance from and 151 Wholesale Distratet Frontage on Road 89' along West 7th St 42. Further Description of Important Features The main facade faces east . The east facade is dominated by a two story round arched portico recessed with in the center bay. The ground story is surfaced with rough faced rubas max min ble limestone. Engaged piers and spandrels divide the brick facade into bays. Fenestration consists of one-over-one light, double hung sash windows placed in either rectangular or round arched openings. The parapet is embellished with lozenge patterned, brick corbelling with foliated stone finials and stone balustrades. 43. History and Significance The building was erected in 1888-89 by the distinguished investment firm of the Missouri, Kansas & Texas TrustCompany to serve as their business headquarters. In about 1898, Arthur E. Stilwell, president of the company reorganized the firm into the Guardian Trust Company. The M.K.& T. Building is a rare commercial design by local architect Harry Lindsay. rust 44. Description of Environment and Outbuildings The structure is located in the Wholesale District of the Central Business District of Kansas City. To the immediate south, west & east are surface parking lots. To the north are other commercial buildings. Kansas City (Missouri) Journal, March 6, 1889 p.3 45 Sources of Information Service Permit No. 9444, Water Department, 5th Fl. 46. Prepared by City Hall, 414 E. 12th St., Kansas City, Mo. 64106. Ed Miszczuk 47. Organization Kansas City: Its Resources and Their Development: A Souvenir ofthe K. C. Kansas City Times, Philadelphia; Patterson & White, C. 1891 pp. 34-35 Landmarks Commission 48. Date 49 Revision Date(s) Carrie Westlake Whitney, Kansas City, Mo. Its History and Its People 1880-1908 Vol III, Chicago, S. J. Clarke Pub. Co. 1908 pp.461-465 9/77



HISTORIC INVENTORY JA-AS-005-591 4 Present Name(s) 807-15 Wyandotte Street Bulding 41-A 803A0196 2 County 5 Other Name's) Mark - Deamer Carpet Company Jackson 3 Los ation of Negatives CBD #38-16 Landmarks Commission 16 Themalic Calegory 28 No of Stories Specific Location 29. Basement? Yes X 807-15 Wyandotte No 17 Data(s) or Pariod c. 1904 30. Foundation Material stone 18 Style or Design Il Rural, Township & Vicinity 7 City or Town 31. Wall Construction Kansas City, Misosuri 19 Architect or Engineer LOD # Site Plan with North Arrow 32. Roof Type & Material F+ PR flat; tar & gravel 20 Contractor or Builder 33. No. of Bays Front Side 21. Original Use, If apparent commercial OPA brick 22 Present Use 35. Plan Shape rectangular commercial Wyandotte Public I 36 Changes Addition . 23 Ownership Altered : (Explain m 842) Moved . 24 Owner's Name & Address. Other d known 37 Condition Interior UTM 9 Cucrdinales good Exterior Lung Yes X 25 Open to 38. Preservation Underway? Public? No II NoXX Structure ! Sile Building X Object 11 Endangered? Yes II 26 Local Contact Person or Organization By What? No XX Landmarks Commission Yes X Yes .. 12 Is II 11 On National Eligible? No 11 27 Other Surveys in Which included Register? No .X Yes XX 14 District Yes X Visible from 13 Part of Estab Yes Potent'1? Public Road? No 'X No I MIST DIST ? No. Distance from and 15 Name of Established District Frontage on Road 60 feet on Wyandotte 22 Further Description of Important features Cast iron Ionic columns flank the Other Namets centrally located double entrance doors. The first floor is fenestrated with large display windows with transoms. Cast iron pilasters terminate each end of the 1st floor facade. Above the 1st floor windows is a denticulated metal cornice. A stone string course runs above this. The upper flbors are divided into 3 bays. The narrow central bay contains a single double hung sash windows. Each of the side bays contain triplicate sash windows. All the windows have metal lintels 41 Mistory and Saprificance One of the earliest tenants of this building was the Hallack-Deamer Carpet Company. Other firms have occupied the building over the years, including a dry goods firm and a drug company. 14 Description of Environment and Outbuildings Surface parking lots are located to the north and west. To the south and east are commercial buildings. Sources of Information 45. Prepared by Piland Landmarks Commission 48. Date 49 Revision Dele(s)

1/19/81

Office of Historic Preservation, P.O. Box 176. Jefferson City, Missouri 65101



|  | VENTORY   | JA AS-005-592   |
|--|---|---|
| 1. No. 40-C 2. County Jackson  | 4. Present Name(s) Stanley Type   |   |
| 3. Location of NegativesCBD #29-8  | 5. Other Name(s)  W. P. Moores & Son  | 0JA 0197  |
| Landmarks Commission  6 Specific Location  | 16. Thematic Category   | 1   |
| 816 Wyandotte  | 17. Date(s) or Period<br>c. 1891  | 29. Basement? Yes I No I.   |
| 7. City or Town If Rural, Township &   | /icinity 18. Style or Design  | 30. Poulidation Material  |
| Kansas City, Missouri  B. Site Plan with North Arrow   | 19. Architect or Engineer   | 31. Wall Construction  masonry LB                                   |
|  | 20. Contractor or Builder   | 32. Roof Type & Material flat; tar and gravel A 33. No. of Bays     |
| F F  | 21. Original Use, if apparent commercial  | Front 2 Side  |
| ) . OO   | 22. Present Use commercial  | 34. Wall Treatment perma-stone 35. Plan Shape rectangular           |
| JY ANDO ITE  | 23. Ownership Public I!<br>Private 放  | 36. Changes Addition 1:   |
| 9. Coordinates UTM   | 24. Owner's Name & Address,. if known   | 37. Condition   |
| Lat.<br>Long.  | ; 25. Open to Yes XX  | 38. Preservation Yes  |
|  | lure   Public? No     ject     26. Local Contact Person or Organization   | Underway? No X 39. Endangered? Yes I                                |
| 1. On National Yes I 12 Is It Register? Nov! Eligible?   | Yes: Landmarks Commission No XX 27. Other Surveys in Which Included   | By What? NoX:   |
| 3. Part of Estab. Yes   1  | Yesxix<br>No:   | 40. Visible from YesX: Public Road? No !:                           |
| 5. Name of Established District  |   | 41. Distance from and Frontage on Road approx. 20 feet on Wvandotte |
| reneered with perma-stone. A main facade. On the south end plass blocks. A stone pilaste This is a remnant of the Gibra of this building andwas demoli |   | the south   |
| Moores and Son. By 1917 it was   | ding was probably first occupied by the sthe site of the Goldberg Jewelry Composition of the Goldberg | pany.   |
|  |   |   |
| 5 Sources of Information WP # 29877  |   | <b>46</b> . <b>Prepared by</b> Sherry Piland                        |
| BP #51742<br>Hughes' Views of Kansas Cit   | 7, 1896–97.   | <b>47. Organization</b> Landmarks Commission                        |
|  | -   | 48. Date 49. Revision Date(s) 1/20/81                               |



Office of Historic Preservation, P.O. Box 176, Jefferson City, Missouri 65101 HISTORIC INVENTORY JA-AS-005-593 4 Present Name(s) No 41-B Info-Data 2 County 5 Other Name(s) not entered Jackson CBD #29-7 Location of Negatives Landmarks Commission 16 Themalic Calegory 28 No of Stories 6 Specific Location 29. Basement? Yes IX 17 Date(s) or Period 819 Wyandotte No : 30. Foundation Material 1961 18 Style or Design Il Rural, Township & Vicinity 7 City or Town 31. Wall Construction Kansas City, Missouri masonry 19. Architect or Engineer 8 Site Plan with North Arrow 32. Roo! Type & Material flat; tar & gravel 20 Contractor or Builder Schweiger Const. Co. 33. No. of Bays Front Side Original Use, if apparent 34. Wall Treatment brick 22 Present Use commercial 35. Plan Shape rectangular Wyandotte Public II 36. Changes 23 Ownership Addition . Attered : (Explain m #42) Moved i 24. Owner's Name & Address. of known 37 Condition interior Condinates UTM Exterior excellent Lung Yes XX 25 Open to 38. Preservation Yes No iX Public? No II Underway? Structure ! . Sile Building X Object 11 39 Endangered? 26 Local Contact Person or Organization Yes II By What? No IX Landmarks Commission Yesii 11 On National Yes .. 12 Is II Eligible? Register? No XX No X 27. Other Surveys in Which included 13 Part of Estab Yes 14 District Visible from Yes . X Potent'l? No XX No X Hist Dist ? Public Road? 41 Distance from and 15 Name of Established District approx Frontage on Road 60 feet on Wyandotte 42 Further Description of Important Features The main entrance is at the north end of the west facade and is recessed within a cast concrete surround The remainder of the west wall is faced with brick. Fenestration consists of six fixed tinted glass windows, irregularly spaced. The windows get progressively narrower from north to south across the facade. Concrete coping tops the wall. 43 History and Significance New construction between two earlier and taller buildings. 44 Description of Environment and Outbuildings Commercial buildings are located to the north, south, and east of this structure. To the west is another commercial building and surface parking lots. 46. Prepared by Sources of Information Sherry Piland BP #67640 47. Organization Landmarks Commission The second second section of the second 48. Date 49 Revision Date(s)

1/19/81



Office of Historic Preservation, P.O. Box 176. Jefferson City, Missouri 65101 HISTORIC INVENTORY JA-AS-005-574 4 Present Name(s) 57-B McWhirter Company Printers 2 County 5 Other Name(s) Jackson not entered CBD #29-6 3 Lo ation of Negatives Landmarks Commission 16 Themalic Calegory 28 No of Stories & Specific Location acksor 29. Basement? 17 Date(s) or Period 909 Wyandotte 30. Foundation Material 1956 concrete 18 Style or Design H Aural, Township & Vicinity 7 City or Town 31. Wall Construction Kansas City, Missouri 19 Architect or Engineer reinforced concrete & Site Plan with North Arrow Kivett & Myers & Angus McCallum 32 Roof Type & Material 20 Contractor or Builder flat; tar & gravel 33 No. of Bays Schweiger Const. Co. 909 Sale Front 21. Original Use, If apparent 34 Wall Trealment brick commercial Wyandotte 22 Present Use commercial 35 Plan Shape rectangular 36 Changes Public 1 4 AdditionX 23 Ownership Attered X Private KI (Explain Wyandotte Moved i en #42) 24 Owner's Name & Address, 37 Condition d known Interior Currinales Exterior good Lung Yes KI 38 Preservation 25 Open to No iX Public? No I I Underway? Structure ! . Sile Building X Object 1 i 39 Endangered? Yes !! 26 Local Contact Person or Organization By What? No IX Yes 11 Landmarks Commission 11 On National 12 is H Yes Engible? No XI Register? No .X 27 Other Surveys in Which included 14 District Yes . Visible from Yes . A 13 Part of Estab Yes Public Road? Polent'17 No VI No 'X No . : MIST DIST ? Distance from and 15 Name of Established District Frontage on Road 50 feet on Wyandotte 22 Further Description of Important Features An entrance door is recessed at the north end of the main (west) facade. A narrow strip of windows runs across the 1st and 2nd floors at the south end of this facade. The wall is faced with brick. In 1956, this 21,000 square foot building was created by joining the south half of the present structure with a new 2 story building and unifying both structures with a new facade. A 3 story building which the firm had purchased in 1947 was razed (cont d) 43 History and Significance The McWhirter Company was founded c. 1917. From 1927-1955 they occupied the building that comprises the south half of the present structure. ranked 13th nationally in volume of trade. 44 Description of Environment and Outbuildings To the north and west of this building are surace parking lots. Commercial buildings are to the west and south. 46 Prepared by 45 Sepices of Information Sherry Piland KC Star, July 17, 1955, p. 10D 47. Organization BP # 29446A Landmarks Commission 48 Date 49 Revision Date(s)

11/6/80

McWhirter Company Printers
Page 2

909 Wyandoffe K.C.

42. (cont'd) to make room for this extension to the north.

A row of factory windows runs across the 2nd floor of the north facade.



Office of Historic Preservation, P.O. Box 176, Jefferson City, Missouri 65101
HISTORIC INVENTORY JA-AS-005-595 4 Present Name(s) No 57-C 40 JA0198 915-17 Wyandotte (vacant) 2 County 5 Other Name(s) Jackson 3 Lucation of Negatives CBD# 29-5 Baker-Vawter Building; Remington-Rand Building Landmarks Commission 28. No of Stories 6 16. Thematic Category 6 Specific Location 29. Basement? Yes IX ackson 915-17 Wyandotte No : 17 Date(s) or Period 30. Foundation Material 1920 concrete Il Rural, Township & Vicinity 18 Style or Design 7 City or Town 69 31. Wall Construction Kansas City, Missouri reinforced concrete 19. Architect or Engineer & Site Plan with North Arrow Hoit, Price and Barnes 32. Roof Type & Material flat; tar/gravel # 20 Contractor or Builder Long Construction Co. 33. No. of Bays Front 3 21. Original Use, if apparent Present Name(s) 34. Wall Treatment commercial N 22 Present Use brick: terra cotta vacant 35. Plan Shape rectangular 36. Changes 23 Ownership Addition Public 1 ! Wyandotte Private NI (Explain Altered in #42) Moved I 24. Owner's Name & Address, if known Other 37 Condition 50 Interior UTM 9 Cuordinales good Exterior Lung 25. Open to Yes 11 38. Preservation Yes . Public? Underway? No : X Structure 1 Site Object 11 Building X 26. Local Contact Person or Organization 39. Endangered? Yes II By What? No IX Landmarks Commission Yes XI 11 On National 12 Is II Yes .. Eligible? NoII Register? 27. Other Surveys in Which Included Yes X 13 Part of Estab Yes 14 District 40 Visible from Yes X No 'X Potent'l? No I Public Road? Hist Dist ? No : 41. Distance from and 15 Name of Established District Frontage on Road 50 ft. on Wyandotte 42 Further Description of Important Features Yellow terra cotta veneers the facade which is divided into 3 bays. Each end bay contains an entrance. The entrance on the north has been modernized, with the door on the south has a pediment. Between the doors is a display window with a multipaned transom. The upper floors are fenestrated with large multipaned windows. The spandrels between the windows of the central bay are of metal. A cartouche tops the building. 43 History and Significance -- The building was originally designed for the printing firm of Baker-Vawter, which later became part of the Remington-Rand organization. Remington-Rand owned and occupied the building more than 15 years before selling it to the Sosland family in 1950. The Soslands used it to consolidate their interests of the Sosland Envelope Co., Sosland Press, Inc., and the Southwestern Miller publication. 44 Description of Environment and Outbuildings Surface parking lots are located to the west and south of this building. To the north and east are commercial buildings. 45 Sources of Information 46. Prepared by Sherry Piland WP# 63333, BP# 12686 47. Organization Kansas City Star, June 11, 1950, p. 18D

Western Contractor, May 26, 1920 - 32

Landmarks Commission



Office of Historic Preservation, P.O. Box 176, Jefferson City, Missouri 65101 HISTORIC INVENTORY JA-AS-005-596 1 No Present Name(s) 56-G Comfort Felt Company 2 County 5 Other Name's) Jackson 24-926 ayandotte Steel Buldin 3 Lucation of Negatives CBD # 20 - 4 Landmarks Commission 16 Thematic Category 6 Specific Location 28 No of Stories Jackson 29. Basement? 924-26 Wyandotte 17 Date(s) or Period No : 1922 30. Foundation Material H Aural, Township & Vicinity 18 Style or Design 7 City or Town 31. Wall Construction Kansas City, Missouri steel frame 19 Architect or Engineer Site Plan with North Arrow 32. Roof Type & Material 20 Contractor or Builder flat; tar and gravel William R. Jewell, Jr. (realtor) 33. No. of Bays 924-26 Front 4 Side 21. Original Use, If apparent UUANDOTT commercial Del 34 Wall Treatment 22 Present Use brick; structural gl commercial 35. Plan Shape Wyando Namels rectangular 36. Changes 23 Ownership Public 11 Addition Private XX Aftered XX (Explain m #42) Moved . 24. Owner's Name & Address. of known lother 37 Condition Interior UTM Curidinales Exterior dood Lung 25 Open to Yes IXX 38. Preservation Public? No II Underway? Sile Structure ! . No X. Building X. Object 11 26 Local Contact Person or Organization Endangered? Yes II Yes XX By What? No X 11 On National Yes . 12 is !! Landmarks Commission No X Eligible? Register? No II 27 Other Surveys in Which included 13 Part of Estab Yes X Yes ! District Visible from Yes X Hist Dist ? No X Potent'1? Public Road? No i Distance from and 50 ft. 15 Name of Established District on Wyandotte 42 Further Description of Important Features The main facade faces to the east. The first story includes a garage entrance towards the southerly end. A rectangular window of class blocks is the Other Namets dominant feature of the first floor. The brick has been veneered with a dark purpl structural glass. The second story fenestration consists of four paired double Hung windows with smooth stone lugsills. 43 Missory and Significance This building was originally leased to the Kansas City White Goods Company, and the Spencer Printing Company. 44 Description of Environment and Outbuildings Surface parking lots are located to the east and north of this building. A commercial building is to the south. To the east is an office/garage complex. 45 Sources of Information WP # 1915 45. Prepared by Sherry Piland/Uguccio. BP # 13201 47. Organization Western Contractor, July 12, 1922, p. 42 Landmarks Commission 48. Date 49 Revision Dale(s)

1/23/81



|  |  | and Planning Office, 909 University                      | mbia, Missouri 65201  |
|--|--|--|---|
| HISTOR   | Name of Street, or other   | VENTORY  | JA-AS-005-59  |
| 56-F   |  |  | 80JA0200  |
| 2. County  |  | Place Restaurant and Lounge                              | 80JA0200  |
| Jackson  3 Location of Negatives CBD 20-5              | The state of the s | 928-930 Wypendette St                                    | net Bulden  |
| Landmarks Commission                                   |  | 130 130 Wyerastes es                                     |   |
| 6. Specific Location                                   |  | 16. Thematic Category                                    | 28. No. of Stories 2  29. Basement?  Yes I. No IXX  30. Foundation Material |
| 020 201 3-11   |  | 17. Date(s) or Period                                    | 29. Basement? Yes I   |
| 928-30Wyandotte  |  | 1916   | 30. Foundation Material   |
| 7. City or Town if anal, Townsh                        | ip & Vicinity  | 18. Style or Design                                      | concrete  |
| Kansas City, Missouri                                  |  | 69   | 31. Wall Construction   |
| B. Site Plan with North Arrow                          |  | 19. Architect or Engineer                                | brick US  |
|  | N  | S. B. Tarbet   | 32. Roof Type & Material  |
|  |  | 20. Contractor or Builder                                | flat; tar & gravel  |
| u u  |  | Pratt-Thompson 21. Original Use, if apparent             | 33 No. of Bays Front 3 Side 7  34. Wall Treatment brick                     |
|  |  |  | 34. Wall Treatment  |
| <u></u>  |  | commercial 025   | brick 30  |
| 9  |  |  |   |
| 19   |  | restaurant 23 Ownership Public !!                        | 36. Changes Addition 1:   |
| Эт тодин ри  |  | Private Lyx  | (Explain AlteredXX  |
|  |  | 24. Owner's Name & Address                               | in #42) Moved i   |
|  |  | if known   | 37. Condition   |
| 9. Coordinates UTM                                     | 12 12 6 2 12 2   | 50   | Interior  |
| Lat.   |  |  | Exterior _fair  |
| Long.  |  | 25. Open to Yes ⊠X Public? No 1                          | 38. Preservation Yes  |
| 10. Site!:<br>Building ★★                              | Structure   :  |  | Underway? NoxX  |
|  |  | 26. Local Contact Person or Organization                 | 39. Endangered? Yes I: By What? No↓   |
| 11. On National Yes   12 Is It  Register? No xx Eligit | Yes XX   | Landmarks Commission 27. Other Surveys in Which Included | By What? No XX  |
| 3. Part of Estab. Yes II 14. Dist                      | rict Yes XX  | 27. Other Surveys in Willon included                     | 40. Visible from YesXX Public Road? No 11                                   |
| 15. Name of Established District                       |  |  | 41. Distance from and   |
| is. Name of Established Station                        |  |  | Frontage on Road  |
|  |  |  | 50feet on Wyandotte   |
| 42. Further Description of Important                   | Features The   | e 1st floor has been altered and the                     | e   |
|  |  | divided into 3 bays. The central                         |   |
|  |  | ouble hung, sash windows. They                           |   |
|  |  | lar windows, paired. A simple                            | Photo   |
| metal cornice extends from                             |  |  | 711010  |
|  |  |  |   |
|  |  |  |   |
|  |  |  |   |
|  |  | has been used for a variety of comm                      |   |
|  |  | t Envelope Company. Later occupant                       |   |
| handling silo hardware an                              | d the Cha  | rles Milbank Company, dealers in el                      | ectrical machinery.   |
|  |  |  |   |
|  |  |  |   |
| 44. Description of Environment and C                   | Outbuildings   | Commercial buildings are located                         | to the north and couth  |
| while surface parking lots                             |  |  | to the north and south,   |
| while during parking lots                              | are to t   |  |   |
|  |  |  |   |
| 15 Sources of Information                              |  |  | 46. Prepared by   |
| WP #58298  |  |  | Uguccioni/Piland  |
|  |  |  | 47. Organization  |
| BP #11688  |  |  | Landmarks Commission  |
|  |  |  | 48. Date 49. Revision Date(s)   |
|  |  |  | 1/23/81   |



48. Date 49. Revision Date(s)

1/21/81

State Historical Surve and Planning Office, 909 University Avenue, Suite 215,



HISTORIC INVENTORY JA-AS-005-579 1 No 73 - BCentenial Parking Decks not entered 2 County Jackson Other Name/s) 3 Lucation of Negatives CBD # 29-4 Board of Trade Facility No. 2 Landmarks Commission 16 Themalic Calegory 28 No of Stories 6 Specific Location ackson 29. Basement? Yes I 1000 Wyandotte 17 Date(s) or Period No s 1960-61 30. Foundation Material H Aurai, Township & Vicinity 18 Style or Design 7 City or Town concrete 31. Wall Construction Kansas City, Missouri 19 Architect or Engineer & Site Plan with North Arrow reinforced concrete 32. Roof Type & Material Frank Irask 20 Contractor or Builder flat; concrete J.E. Dunn Construction Co. 33. No. of Bays 1000 Wyandotte Front Side 21. Original Use, if apparent WHANDOTTE Present Name(s) Parking facility 34 Wall Treatment 22 Present Use reinforced concrete 35. Plan Shape rectangular Parking facility 23 Ownership Public 11 36. Changes Addition . Private X X (Explain Attered . m #421 Moved . 24. Owner's Name & Address. el known 37 Condition Interior Curryinales UTM Exterior good Lung Yes XI 25 Open to 38. Preservation Yes . Public? Underway? Structure X . No X. Sile Building 39 Endangered? 26 Local Contact Person or Organization Yes II By What? 11 On National Yes II No IX Yes . Landmarks Commission No X Eligible? NoXI Register? 27. Other Surveys in Which included Yes. 13 Part of Estab 14 District Yes : 40 Visible from Yes X NOIX HIST DIST ? No X Potent'l? Public Road? No . : 41 Distance from and 15 Name of Established District Frontage on Road 101' on Wyandotte 42 Further Description of Important Features The concrete parking facility consists of three levels and can accommodate 444 cars. 43 Missory and Significance This \$500,000 parking facility was built of precast, prestressed and post tensioned concrete beams. The beams make up the structure's main transverse members and afford a span of 681 feet without supporting columns. This allowed for the enlargemen of the available parking areas. 44 Description of Environment and Outbuildings Commercial buildings are located to the north, east and To the south is a surface parking lot. 45 Supress of Information 45. Prepared by WP # 28950 E. J. Uguccioni BP #'s 19232, 64363A 47. Organization Landmarks Commission K.C. Star, Sunday June 4, 1961, p. 14F 48. Date 49 Revision Date(s)

1/2/81

Office of Historic Preservation, P.O. Box 176, Jefferson City, Missouri 65101





STORIC JA-AS-005-601 4. Present Name(s) 1. No. 108-A Radisson Muehlebach Hotel 2. County 5. Other Name(s) Jackson entered 3 Location of Negatives CBD #21-5 Muehlebach Towers Landmarks Commission 16. Thematic Category 28. No. of Stories 6 Specific Location 18 Jackson 29. Basament? Yes I 17 Date(s) or Period No I 1211 Wyandotte 30. Foundation Material 1956-57 7. City or Town . If Rural, Township & Vicinity 18 Style or Design Kansas City, Missouri 31. Wall Construction B. Site Plan with North Arrow 19. Architect or Engineer steel frame W. 12 35t. Neville, Sharp & Simon 32. Roof Type & Material 20. Contractor or Builder flat: tar/gravel 33. No. of Bays Front Side 21. Original Use, if apparent 10 6 Radisson Present Name(s) 34. Wall Treatment hote1 22. Present Use brick 35. Plan Shaperectangular hotel 23 Ownership Public 11 36. Changes Addition : Muehlebach Private XI (Explain Altered I in #42) Moved i 24. Owner's Name & Address, if known 37. Condition Interior UTM 9. Coordinates good Exterior Lat. Long Hote 25. Open to 38. Preservation Yes X Yes XI Public? Underway? No i Structure I Site ! : Building XI Object ! I 39. Endangered? 26. Local Contact Person or Organization Yes By What? No IX 11. On National 12 Is It Yes :X Landmarks Commission Yes ! i Eligible? Register? No IX! No : ! 27. Other Surveys in Which Included Yes IX 13. Part of Estab. Yes !! District Visible from Yes !X Potent'l? No: Hist. Dist.? NO XI Public Road? No I I 41. Distance from and 15. Name of Established District Frontage on Road 135 feet on Wyandotte 42. Further Description of Important Features The ground story of this building is composed of glass store fronts. A five bay central section projects Muehlebach slightly beyond the flanking side bays. The central section is further defined by a rectangular band which surrounds four paired window groupings. Photo Towers 13. History and Significance This was the second of three additions to the Muehlebach Hotel. It was constructed at a cost of \$5 million. 14. Description of Environment and Outbuildings A surface parking lot is to the north. To the east is another section of the hotel. Another hotel is to the south. The Barney Allis Plaza/ Auditorium Garage is to the west. 5 Sources of Information 46. Prepared by Piland/Uguccioni WP# 35062 47. Organization Kansas City Times, Feb. 6, 1971 Landmarks Commission KC Times, Jan. 27, 1962. 48. Date 49. Revision Date(s) 12/17/80 Kansas City Star, Oct. 6, 1957, p. 8D.

State Historical Survey and Planning Office, 909 University Avenue, Suite 215.

Columbia, Missouri 65201



| No. 108-B   | 4. Prese                            | ent Name(s)  |  |   |                        |
|---|-------------------------------------|--|--|---|------------------------|
| County  |                                     | Aladdin Hotel  |  |   |                        |
| Jackson   | 5. Othe                             | r Name(s)  |  | Cherry Services                                 |                        |
| Location of Negatives CBD# 4  | -18                                 | 83JAD  | 092  |   |                        |
| Landmarks Commission  |                                     | A The state of the | Charles Commence   |   | -                      |
| Specific Location   |                                     | 16. Thematic Category  |  | 28. No. of Stories                              |                        |
| 1213 Wyandotte  |                                     | 17. Date(s) or Period  |  | 29. Basement?                                   | Yes!X                  |
|   |                                     | 1925   |  | 30. Foundation Mate                             | erial                  |
| City or Town If Rural, Town   | ship & Vicinity                     | 18. Style or Design  |  | concrete  |                        |
| Kansas City, Mo.  |                                     | Italian Romanesque eleme   | ents   | 31. Wall Construction                           | n                      |
| Site Plan with North Arrow  | ^                                   | 19. Architect or Engineer  |  | reinforced                                      |                        |
|   |                                     | Phillip T. Drotts  20. Contractor or Builder   |  | 32. Roof Type & Ma                              | iterial                |
|   | 5.0                                 | C. O. Jones  |  | 33. No. of Bays                                 |                        |
| 4   | - 1.3                               | 21. Original Use, if apparent  |  |   | Side                   |
| 20  | NI                                  | hotel  |  | 34. Wall Treatment                              |                        |
| De .  | 1/1                                 | 22. Present Use  |  | brick; stone                                    |                        |
| Myandove  | 1                                   | hotel 23. Ownership  |  | 35. Plan Shape "T<br>36. Changes                | Addition :             |
| 3   |                                     |  | Private ki   | (Explain  | Addition : :           |
|   |                                     | 24. Owner's Name & Address.  |  | in #42)   | Moved i                |
|   |                                     | if known   |  | 37. Condition                                   | FIZATION               |
| Coordinates UTM   |                                     |  |  | Interior  |                        |
| .al.<br>.ong.   | - 4                                 | 25. Open to  | Yes II   | Exterior go. 38. Preservation                   |                        |
| Site ! :  | Structure 1:                        | Public?  | No IX  | Underway?                                       | Yes IX                 |
| Building IX   | Object                              | 26. Local Contact Person or Organiza   | ation  | 39. Endangered?                                 | Yes !!                 |
| On National Yes I 12 Is   |                                     | Landmarks Commission   |  | By What?  | No X                   |
| Α   | igible? No i!                       | 27. Other Surveys in Which Included  |  |   |                        |
|   | istrict Yes ix                      |  |  | 40. Visible from Public Road?                   | Yes X                  |
| Name of Established District  |                                     |  |  | 41. Distance from ar                            |                        |
|   |                                     |  | 23   | Frontage on Roa<br>50 feet on                   |                        |
|   |                                     | C i li li c C Mic L  | and the state of t | 30 reet on                                      | wyandocte              |
|   |                                     | ne front portion of this bu  |  |   |                        |
| o front portion thus a  | innears as a                        | ne rear, rectangular project<br>lofty tower. On the upper  | r floors   |   | /                      |
| the north, south, and   | west facade                         | es, terra cotta pillars ext  | tend   | Photo   |                        |
| rough two floors, form  | ning a 5-bay                        | accent. The pillars are t  | topped   | /11010  |                        |
| th rounded arches. A  | series of br                        | rick pilasters rise 10 floo  | ors up   |   |                        |
| e facade. On top of e   | ach pilaster                        | r is a larger than life sizrtion (continued on second  | ze terra   | /   |                        |
| History and Significance T  | his 250 room                        | hotel was erected by the   | Armour Bu  | ilding Company                                  | $\longrightarrow$      |
| introlled by C.O. Jones   | s and W.B. W                        | eaver. Current plans call  | for a \$7.   | -million renova                                 | tion                   |
| begin in spring, 1980   |                                     | ening in spring of 1981.   |  |   |                        |
| named The Embassy.  |                                     |  |  |   |                        |
| lenda de  |                                     |  |  |   |                        |
| Description of Environment and  | Outbuildings                        |  |  | Vinuganie Th                                    |                        |
|   | l is located                        | in Kansas City's Central   | Business   | District. Comm                                  | nercial                |
| The Alladin Hote  | ocated to th                        | e North, South, and East.  | To the W   | est is the land                                 | dscaped                |
| The Alladin Hote  |                                     |  |  |   |                        |
| The Alladin Hote  |                                     |  |  |   |                        |
| The Alladin Hote<br>structures are lo<br>Barney Allis Pla   |                                     |  |  | 46. Prepared by                                 |                        |
| The Alladin Hote<br>structures are lo<br>Barney Allis Pla<br>Sources of Information   | za.                                 | 980, g. 7 <sub>D</sub>   |  | Sherry Piland                                   |                        |
| The Alladin Hote<br>structures are lo<br>Barney Allis Pla<br>Sources of Information<br>Kansas City Star<br>Kansas City Star                     | za.<br>r, Mar. 4, 1<br>, 29 March 1 | 980, p. 7<br>925, p. 1D,   |  | Sherry Piland 47. Organization                  |                        |
| The Alladin Hote<br>structures are lo<br>Barney Allis Pla<br>Sources of Information<br>Kansas City Star<br>Kansas City Star<br>Western Contract | za.<br>r, Mar. 4, 1<br>, 29 March 1 | 980, p. 7<br>925, p. 1D,<br>ber 1925, p.32.  |  | Sherry Piland  47. Organization  Landmarks Comm |                        |
| The Alladin Hote<br>structures are lo<br>Barney Allis Pla<br>Sources of Information<br>Kansas City Star<br>Kansas City Star                     | za.<br>r, Mar. 4, 1<br>, 29 March 1 | 980, p. 7<br>925, p. 1D,<br>ber 1925, p.32.  |  | Sherry Piland  47. Organization  Landmarks Comm | nission<br>ion Date(s) |

HISTORIC INVENTORY - page 2 Aladdin Hotel 1213 Wyandotte K.C.

42. of the building has a gold tile pyramidal-like roof. A l6th floor roof garden provided seating for 700. An underground tunnel links the hotel to the Auditorium Plaza Garage.







Times, Dec 3, 1955

WP #10852

## HISTORIC INVENTORY

Barney Allis Plaza/Auditorium Plaza Garage

Page 2

1220 wyandotte K.C.

43. (cont'd) used water from the garage airconditioning system, was placed in the center of thepark, later known as Barney Allis Plaza.







|   | BUILDING VINCE OF STREET   | VENTORY  | TA-AS-005-60   |
|---|--|--|--|
| . No. 123-D   | A STATE OF THE STA | eni Name(s)<br>19 Wyandotte  |  |
| County  | 13   | 19 Wyandocce   | 80JA 0204  |
| Jackson   | 5. Oth   | er Name(s)   | r- r   |
| Location of Negatives CBD# Landmarks Commission   | 5-8  | Cansas City Power and Light  | company barage   |
| Specific Location   | -  | 16. Thematic Category  | 28. No. of Stories 1   |
| Specific Education  |  | 290  | 29. Basement? Yes IX   |
| 1319 Wyandotte  |  | 17. Date(s) or Period  | No i.  |
|   |  | 1928-29  | 30. Foundation Material  |
| City or Town . If Rural, Tow  |  | 18. Style or Design  | concrete   |
| Kansas City, Missouri   |  |  | 31. Wall Construction reinforced concrete  |
| Site Plan with North Arrow  |  | 19. Architect or Engineer  | 32. Roof Type & Material   |
| <u> </u>  | 1  | 20. Contractor or Builder  | flat; tar & gravel   |
| ta l  |  |  | 33. No. of Bays  |
| 10  |  | 21. Original Use, if apparent  | Front 8 Side   |
| Wyandotte   | NI   | garage (C) (GD)  | 34. Wall Treatment   |
| 1/a   |  | 22. Present Use  | brick  |
| 3   |  | garage 23 Ownership Public !!  | 35. Plan Shape rectangular   |
|   |  | 23 Ownership Public I! Private IXI   | 36. Changes Addition : (Explain Altered )  |
|   |  | 24. Owner's Name & Address,  | in #42) Moved i  |
|   |  | if known glass   | 37. Condition  |
| Coordinates UTM   | ALCOHOL:   | 40   | Interior   |
| Lat.<br>Long.   |  |  | Exterior good  |
|   | £4   | 25. Open to Yes I i Public? No IXI   | 38. Preservation Yes : Voi X   |
| Site!: Building ly  | Structure 1:<br>Object ! I   | 26. Local Contact Person or Organization   | 39. Endangered? Yes 1  |
| On National Yes I 12 I  |  | Landmarks Commission   | By What?   |
|   | ligible? No  | 27. Other Surveys in Which Included  |  |
|   | District Yes IX  |  | 40. Visible from Yes! X  |
| Hist. Dist.? No XI  | Potent'l? No :   | [10] 10 [10] | Public Road? No 11   |
|   |  | [[[[[[[] [[] [[] [[] [[] [[] [[] [[] [[  |  |
| THE REPORT OF THE PARTY OF THE |  |  | 41. Distance from and 125 ft.  |
| THE THE TANK  |  |  |  |
| Name of Established District  | ant Features The   | stepped facade conforms to the gr  | 41. Distance from and 125 ft.<br>Frontage on Road<br>on Wyandotte  |
| . Name of Established District  Further Description of Importation that slopes to the se  | outh. The r  | stepped facade conforms to the gr<br>ectangular window areas of the fac  | 41. Distance from and 125 ft. Frontage on Road on Wyandotte  |
| . Name of Established District  Further Description of Importation that slopes to the se  | outh. The r  | ectangular window areas of the fac   | 41. Distance from and 125 ft. Frontage on Road on Wyandotte  |
| Name of Established District  Further Description of Importation that slopes to the St  | outh. The r<br>lass blocks   | stepped facade conforms to the gr<br>ectangular window areas of the fac<br>and have stone sills. Stone copin   | 41. Distance from and 125 ft. Frontage on Road on Wyandotte  |
| Further Description of Imports that slopes to the se are filled in with g   | outh. The r<br>lass blocks   | ectangular window areas of the fac   | 41. Distance from and 125 ft. Frontage on Road on Wyandotte  |
| Further Description of Imports that slopes to the se are filled in with g   | outh. The r<br>lass blocks   | ectangular window areas of the fac   | 41. Distance from and 125 ft. Frontage on Road on Wyandotte  |
| Further Description of Imports that slopes to the se are filled in with g   | outh. The r<br>lass blocks   | ectangular window areas of the fac   | 41. Distance from and 125 ft. Frontage on Road on Wyandotte  |
| Further Description of Imports that slopes to the sare filled in with gruns across the roof   | outh. The r<br>lass blocks<br>line.  | ectangular window areas of the fac<br>and have stone sills. Stone copin  | 41. Distance from and Frontage on Road on Wyandotte  ade ade g   |
| Further Description of Imports that slopes to the sare filled in with gruns across the roof  History and Significance Thi   | outh. The r<br>lass blocks<br>line.  | ectangular window areas of the fac<br>and have stone sills. Stone copin  | 41. Distance from and Frontage on Road on Wyandotte  ade ade ade g  Photo  As City Power and   |
| Further Description of Importation that slopes to the seare filled in with gruns across the roof  History and Significance  Thi  Light Company, whose   | outh. The r<br>lass blocks<br>line.  | ectangular window areas of the fac<br>and have stone sills. Stone copin  | 41. Distance from and Frontage on Road on Wyandotte  ade ade ade g  Photo  As City Power and   |
| Further Description of Imports that slopes to the se are filled in with g runs across the roof  History and Significance Thi  | outh. The r<br>lass blocks<br>line.  | ectangular window areas of the fac<br>and have stone sills. Stone copin  | 41. Distance from and Frontage on Road on Wyandotte  ade ade ade g  Photo  As City Power and   |
| Further Description of Importation that slopes to the seare filled in with gruns across the roof  History and Significance  Thi  Light Company, whose   | outh. The r<br>lass blocks<br>line.  | ectangular window areas of the fac<br>and have stone sills. Stone copin  | 41. Distance from and Frontage on Road on Wyandotte  ade ade ade g  Photo  As City Power and   |
| Further Description of Imports that slopes to the sare filled in with gruns across the roof  History and Significance This Light Company, whose Baltimore.  | outh. The r<br>lass blocks<br>line.<br>is parking ga<br>e headquarter  | ectangular window areas of the fac<br>and have stone sills. Stone copin<br>trage was constructed for the Kansa<br>es is located at the southeast corr  | 41. Distance from and Frontage on Road on Wyandotte  ade ade g  Photo  As City Power and ner of this block, on   |
| Further Description of Importation that slopes to the sare filled in with gruns across the roof  History and Significance  Thi Light Company, whose Baltimore.  | outh. The r<br>lass blocks<br>line.<br>is parking ga<br>e headquarter  | ectangular window areas of the factor and have stone sills. Stone copin arage was constructed for the Kansars is located at the southeast correct the contract of the hotel is located to the north of   | 41. Distance from and 125 ft. Frontage on Road on Wyandotte  ade ade g  Photo  as City Power and her of this block, on  this building. To the  |
| Further Description of Importation that slopes to the sare filled in with gruns across the roof  History and Significance This Light Company, whose Baltimore.  | outh. The r<br>lass blocks<br>line.<br>is parking ga<br>e headquarter  | ectangular window areas of the fac<br>and have stone sills. Stone copin<br>trage was constructed for the Kansa<br>es is located at the southeast corr  | 41. Distance from and 125 ft. Frontage on Road on Wyandotte  ade ade g  Photo  as City Power and her of this block, on  this building. To the  |
| Further Description of Importation that slopes to the sare filled in with gruns across the roof  History and Significance  This Light Company, whose Baltimore.   | outh. The r<br>lass blocks<br>line.<br>is parking ga<br>e headquarter  | ectangular window areas of the factor and have stone sills. Stone copin arage was constructed for the Kansars is located at the southeast correct the contract of the hotel is located to the north of   | 41. Distance from and 125 ft. Frontage on Road on Wyandotte  ade ade g  Photo  as City Power and her of this block, on  this building. To the  |
| Further Description of Importation that slopes to the sare filled in with gruns across the roof  History and Significance This Light Company, whose Baltimore.  Description of Environment are south and east are said  | outh. The r<br>lass blocks<br>line.<br>is parking ga<br>e headquarter  | ectangular window areas of the factor and have stone sills. Stone copin arage was constructed for the Kansars is located at the southeast correct the contract of the hotel is located to the north of   | 41 Distance from and Frontage on Road on Wyandotte  ade ade g  Photo  as City Power and her of this block, on  this building. To the is located to the west.   |
| Further Description of Imports that slopes to the stare filled in with gruns across the roof  History and Significance This Light Company, whose Baltimore.  Description of Environment are south and east are second south and east are second sources of Information BP # 15295   | outh. The r<br>lass blocks<br>line.<br>is parking ga<br>e headquarter  | ectangular window areas of the factor and have stone sills. Stone copin arage was constructed for the Kansars is located at the southeast correct the contract of the hotel is located to the north of   | 41. Distance from and 125 ft. Frontage on Road on Wyandotte  ade ade g  Photo  as City Power and her of this block, on  this building. To the  |
| Further Description of Imports that slopes to the sare filled in with gruns across the roof  History and Significance This Light Company, whose Baltimore.  Description of Environment are south and east are seconds.  | outh. The r<br>lass blocks<br>line.<br>is parking ga<br>e headquarter  | ectangular window areas of the factor and have stone sills. Stone copin arage was constructed for the Kansars is located at the southeast correct the contract of the hotel is located to the north of   | 41 Distance from and Frontage on Road on Wyandotte  ade ade g  Photo  as City Power and her of this block, on  this building. To the is located to the west.   |
| Name of Established District  Further Description of Imports that slopes to the stare filled in with gruns across the roof  History and Significance This Light Company, whose Baltimore.  Description of Environment are south and east are second south and east are second sources of Information BP # 15295   | outh. The r<br>lass blocks<br>line.<br>is parking ga<br>e headquarter  | ectangular window areas of the factor and have stone sills. Stone copin arage was constructed for the Kansars is located at the southeast correct the contract of the hotel is located to the north of   | 41. Distance from and 125 ft. Frontage on Road on Wyandotte  ade ade grade gra |

