
The properties in this survey are organized alphabetically as follows:

- 1. Town
  - a. Street
    - Address
    - Unknown Address
  - b. Unknown Street
- 2. Township
  - a. Street
    - Address
    - Unknown Address
  - b. Unknown Street

Jennifer Perritt Seasonal Digitization Archivist Missouri State Historic Preservation Office March 20<sup>th</sup>, 2018

1 No C96	4 Pres	ent Name(s)			
ounty		Quick Building			
Ray	5 Oin	Other Namo(s)			
Location of Negatives		Clayburn Burnett Building			
RCHS & M					
ots 21 and 122 in Blo	ock 88 in	16 Thematic Calegory	26 No of Stories two		
original town of Camde	n	17 Date(s) or Period	29. Basement? Yes I I		
		1914	30. Foundation Material		
City or Town II Rural, Tow	waship & Vicinity	18 Style or Design	ashlar stone 40		
Camden		vernacular 64	31. Wall Construction		
Site Plan with North Arrow		19. Architect or Engineer	frame . Wu		
		unknown 20. Contractor or Builder	32. Roof Type & Material		
		unknown	flat-comp. shingle & 1		
	N	21. Original Use, if apparent OSE OIR	Front 3 Side n/a		
	1	residence; store building	34. Wall Treatment 20		
	90	residence; vacant store building	wood siding/claphoard 35. Plan Shape rectangular		
		23 Ownership Public I Private XX	36. Changes Addition		
		24. Owner's Name & Address.	(Explain Allered X)		
Front Street	t	il known	37 Condition		
Coordinates UTM		Mrs. Clyde Quick	Interior good		
t at Long		Camden, Missouri	Exterior good		
		25 Open to Yes II Public? No)(X	38. Preservation Yes Underway? No Y		
Site Li Building (X	Structure 1 i	26 Local Contact Person or Organization	Underway? No X  39 Endangered? Yes !!		
On National Yes II 12 I	s II Yes XI	20 Local Comment Verson of Organization	By What? No X		
	Eligible? No I I	27. Other Surveys in Which Included			
	District Yes XI		40. Visible from Yes X Public Road?		
Name of Established District			Public Road? No		
			Frontage on Road		
Further Description of Imports	and Francisco				
		illing lower story of front facade			
		ore quarters. Second story display	va /		
		windows. Secondary facades have	Photo		
		evel. #36: Alterations to the	Photo		
		ondary facades at both levels, new			
orch on primary facade	e. Flat roof	eagea with coping.			
History and Significance					
		remaining structure in the block wh			
ith two sotry sotres a	and commercia	l buildings. Built in 1914 after	a disastrous fire which		
estroyed all of this b	olock except	one building, it has always been u	used on the first floor		
		nd floor has always been a residence	ce. The back entrance		
Description of Environment ar	nd Outbuildings				
ne of only 5 or 6 comm	mercial build	dings in the once thriving river to	own of Camden, now a		
mall village.					
Jources of Information			12.		
rs. Clyde Quick			46. Prepared by		
ersonal knowledge			Virginia McBee		
			RCHS & M		
-site inspection.			48 Date 49 Revision Date(s)		
			8/79		



FLOORPLANS

NOT TO SCALE



PHOTOGRAPH



RA AS -002 -002

Office of Historic Preservation, P.O. Box 176, Jefferson City, Missouri 65101 HISTORIC INVENTORY

No C9	4 Prese	Present Name(s)  Jackson 'Store				
ounly Ray	5 Othe	er Namo(s)				
Location of Negatives						
	-	16. Thematic Category	28. No of Stories 3			
Specific Lucation Lot 12 in Block 8	5 in Origina	030 050 290	29. Basement? Yes II			
town of Camden		17 Date(s) or Period	Λ			
		1846	30. Foundation Material 40			
Cate or Town II Rural,	Township & Vicinity	18 Style or Design neoclassic	Ashlar Fieldstone 31. Wall Construction			
amden, Mo		vernacular influence	Frame Wu			
Site Plan with North Arro		19. Architect or Engineer	32. Roof Type & Material			
le).		unknown 20. Contractor or Builder	Asbestos Shingles-w			
4	Day N	unknown	33. No. of Bays			
	Standard St.	21. Original Use, if apparent general sto	Front N/A Side N/A			
	18/10	multiple residence OF OLE	34. Wall Treatment			
	7 7	22 Present Use	weatherboard			
	7//./	General Store	35. Plan Shape Rectangula			
60	5 / []	23 Ownership Public I ! Private X !	36. Changes (Explain Altered X in #42) Moved			
u	(6)	24. Owner's Name & Address.	37. Condition			
	K)	Mrs. E.V. (Buck) Jackson	Interior Fair			
B Coordinates U	TM	Camden, Mo	Exterior Fair			
Lat		25 Open to Yes II	38. Preservation Yes			
Long		25. Open to Yes 11 Public? No 11	Underway? No			
) Site I i	Structure 1 i	26. Local Contact Person or Organization	39 Endangered? Yes			
Building ( )		20. Eddar Somest Factor	By What? No !			
Register? No X:	12 Is It Yes IXI Eligible? No I I	27. Other Surveys in Which Included	V			
13 Part of Estab Yes II	14. District Yes II		40. Visible from Yes X Public Road?			
Hist Dist.? No K	Potent'l? No X		41. Distance from and			
15 Name of Established Di	strict	1	Frontage on Road			
42. Further Description of I	mportant Features	214" square pillars of knot	t /			
		ne same sized beams across th				
		fastened together with woods				
		built in 1836 was addition of	f			
		ter the Mo. River changed its				
		d story was partitioned and r	nage			
nto a rental dwe	Ling proper	су.				
43 History and Significance	e mho atomo hi	uilding was built when Camder	n was plated and sott			
t has been enems	ted continuo	usly since then by a member of	of the same Tackson			
_		andson of Clem Jackson, who l				

Hogsheads of molasses, flour, sugar, hegs of nails, etc. were unloaded from steamboats on the Missouri River, which once ran in front of the store, and stood in the second store and Outbuildings This store building faces the front street of this village, so named because it "fronted" on the Missouri River. Later railroad tracks of both Santa Fe and Wabash R.R. were laid in the space between the street and the river.Next door is the Jackson home. All other buildings on this once filled 46. Prepared by


ne block are gone now.
45 Sources of Information

Virginia McBee

(1) Site Visit (2) Richmond News June 14, 1971 (3) Interview 7. Organization (7) On-Site Inspection 48. Date with owner. (4) Personal knowledge of surveyor.

RCHS & M 8/79

(5) Ray County Historians (6) Ray County History, 1873



FLOORPLANS

NOT TO SCALE



PHOTOGRAPH



1 No. C -	101110111	TEITT OIT	
(2		ulkerson House	
Ray		her Namo(s)	
3 Location of Negatives RCHS	Al	lec Douglas House	
6 Specific Lucation lot 58 in Block 74	in oniginal tour	16 Thematic Category	26 No of Stories One
of Camden	in original town	17 Date(s) or Period	29. Basement? Yes III
5	51N 28W	1844	No χ
Camden II Aur.	al. Township & Vicinity	18 Style or Design Vernacular	ashlar stone 48
8 Site Plan with North Ar	row	19. Architect or Engineer	31. Wall Construction
		unknown	frame 32. Roof Type & Material 65
~		20. Contractor or Builder unknown	gable; asbestos shing
1 6	3 /	21. Original Use, if apparent	Side n/a Side n/a
1	Col	residence OPA	34. Wall Treatment
Ψ	1	22 Present Use residence	wood siding 20
	NY/	23 Ownership Public !	35. Plan Shape Square  36. Changes Addition X.
	\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\	Private XI 24. Owner's Name & Address.	(Explain Adjered Moved)
	15/2/	if known	37 Condition
9 Coordinates	UTM	Jeff Fulkerson Camden, Missouri 64017	Interior Good
Long			Exterior excellent
Site 1 , Building i A	Structure 1 i	Public? No **	38. Preservation Yes Underway? No X
11 On National Yes !	Object I I	26. Local Contact Person or Organization	39 Endangered? Yes 11 By What? No K
13 Part of Estab Yes II	Eligible? No I I	27. Other Surveys in Which Included	40. Visible from Yes X
Hist Dist.? No X1	Potent'l? No I		Public Road? No . :
13 Name of Established Di	Strict		41. Distance from and Frontage on Road
42 Further Description of I	mportant Features		
Although this house	has been remode	led on both the exterior andinteri	or,
it is one of the old	dest houses in R	ay County. Originally clapboarded	
architectural detail	ls. Side and back	ng which has obscured the extant k porches were first screened, the	Photo
enclosed in later ye	ears. In the 190	60's, a garage was dug in front of	the
house at street level	el and enclosed w	with wood leading up into a side t owner fenced the top of the garag	
43 History and Symilicance	to 3, the present	t owner renced the top of the garage	ge (cont)
Built shortly after	the town of Came	den was established (it was platted	d in 1836) about
1844.		Tell that established (10 has placed)	111 1030), about
44 Description of Environme	ent and Outbuildings	•	
House itself takes i	up almost all of	front yard; a vegetable garden is	to the rear of
the house. Some tre	es are original	planting.	
Sources of Information			
Previous occupants	(Douglas)		46. Prepared by Virginia Mcbee
Camden residents			
Pensonal knowledge	On=site insp	ection	RCHS & M
			48 Date 49 Revision Date(s)

#42. Cont. and made it into a sundeck. INside walls have been panelled and carpets cover all original flooring throughout.





Present Name(s)

Other Namets

Office of Historic Preservation, P.O. Box 176, Jefferson City, Missouri 65101

U		166	01 11	13 601 11		oci va c	, I UII §	-		
		-		RIC						
L	- 1		1./ 1	$\mathbf{D}$	INI	$\mathbf{V} = \mathbf{I}$				Y
•					1117	VI	VI			
•	-								-	_

4 Present Name(s) 1 Nii First Baptist Church of Camden 5 Other Name(s) Ray 3 Location of Negatives 6 Specific Location Main Street, Camden 16. Thematic Category 28. No. of Stories Yes M 29. Basement? Lot 128 in Block 88 in original 17 Date(s) or Period No I Full. town of Camden. 30. Foundation Material 1890 18 Style or Design concrete 65 7 City or Town If Rural, Township & Vicinity plile end 31. Wall Construction neoclassic Camden H Site Plan with North Arrow 19. Architect or Engineer Frame Wu 32. Roof Type & Material 68 20. Contractor or Builder Gable/Comp. Shingles 33. No. of Bays unknown Front 1 Side 5 21. Original Use, if apparent Church . OGA 34. Wall Treatment .20 22 Present Use weatherboard 35. Plan Shape rectangular Church 23 Ownership Addition > Public I! 36. Changes Private M (Explain Altered I Moved i in #42) 24. Owner's Name & Address. if known 37. Condition Interior Excellant Conorecation of First Baptist 9 Coordinates UTM Exterior Excellant Lat Church, Camden, Missouri Lasting 25. Open to Yes M 38. Preservation Yes Public? No II Underway? No K Structure 1 i Site ! 1 Building Ki Object | 1 39. Endangered? Yes I 26. Local Contact Person or Organization By What? No IX 11 On National 12. Is II Yes K Yesil Eligible? Noil Register? NO N 27. Other Surveys in Which Included 13 Part of Estab Yes II District Yes !! 40. Visible from Yes X NO PA HIST DIST ? Potent'l? No K Public Road? No I: 41. Distance from and 15 Name of Established District Frontage on Road 42 Further Description of Important Features Church features 5 one-over-one windows with neoclassic lintels on each secondary facade. Primary facade obscured with addition of Vestibule. The interior has tongue-and-groove ceiling panelling. #36: In the 60's an addition was made at rear of Photo

building, basement was extended, to house. 2 classrooms and Baptistry. The vestibule was also added in the 1920's, ceiling fans, which still work were added and ten years later the Belfry was removed when it was judged unsafe.

43 History and Significance The building is the only one of 4 early churches in Camden that remains today. It is still in operation, though the size of the congregation had diminished. On ceiling of church is a 2+4 Board with 3" hole in center. This served as pivotal point for yearly "Christmas" Tree which was erected by putting a pole from ceiling to floor, with holes to attach enormous evergreen boughs which the congregation brought in by team and wagon from surrounding hillside areas. Each Branch was decorated before it was fastened to the center contact description of Environment and Outbuildings

In the small town of Camden, Urban Environment.

## 45 Sources of Information

Personal Knowledge and Research Camden Historians on-site inspections.

46. Prepared by Virginia McBee


47. Organization

RCHS & M

48. Date 49 Revision Date(s) 7/79

Public I

#43 Con't pole. For many years this ceremony was the highlight of Camden Christmas celebrations.



FLOORPLANS

NOT TO SCALE



PHOTOGRAPH



CONTRACTOR OF THE PARTY OF THE	4 Present Name(s)			
1 N: C5			,	
? Canty	King Residence			
Ray	5 Other Namo(s)			
3 Location of Negatives	Hardage Lane log Cabin- Warriner Ho	ouse ·		
	16 Thematic Category	28. No. of Stories 2		
6 Main street, Lots 21 and 22	140		2	
in Block 87 Camden, Ray Co.	17 Date(s) or Period	29. Basement? Yes : 1 No %	Courty	
5/N agw Mo. original to	own 1828	30. Foundation Material	44.	
7 City or Town II Rural, Township & V	icinity 18 Style or Design	Fieldstone 40		
Camden	Vernacukar 49	31. Wall Construction		
H Site Plan with North Arroys	19 Architect or Engineer	walnut logs 2		
	unknown	32. Roof Type & Material		
	20. Contractor or Builder	Med. Gable-shingles		
(0)	Hardage Lane 21. Original Use, if apparent	33. No. of Bays Front Side	3	
	Residence O/A			
	22 Present Use	Weatherboarding		
	Residence	35. Plan Shape Modified U		
	23 Ownership Public !!	36. Changes Addition .	T.	
	Private 🖂	(Explain Altered 1)	ES.	
	24. Owner's Name & Address.	(n #42) Moved i		
	Mrs. Rilla Rone,	37 Condition Interior Excellant		
9 Coordinates UTM	Camden, Mo. and Mrs. Virginia	Extenor Excellant		
tong	MeBee Richmond, Mo Yes!	38. Preservation Yes		
10 Site 1 Structe	Dublin?	Underway? No 🔆		
	ect     26 Local Contact Person or Organization	39. Endangered? Yes 11		
	es M	By What? No 💢		
	No 11 27 Other Surveys in Which Included			
	Mo. Historical Sites, published	40 Visible from Yes		
15 Name of Established District	by State Hist. Catalogue Soc. of Mo.	Public Road? No 3/5		
13 Name of Established District	140.	Frontage on Road		
42 Further Description of Important Feature	s Originally 4-room log, two rooms		Un	
remain. #36: Weatherboarding a	added ca. 1840, also a breezeway("dogtro	)t"	ō	
type) to connect a new 20'+=20	o' attached summer kitchen. Under kitche	in.	Other Name(s)	
was put a large cellar, walled	Photo	Z		
	kitchen. About 1917 inside walls were		3	
plastered and papered, breezew	vay and kitchen removed and a narrow		2	
(  wide) added acrossback or	cabin from whatever material was			
42 History and Significance This reside	ence is one of the oldest buildings in R	lay County and has been		
continuously occupied since be	ing built by Hardage Lane in 1828. The	building logs were from		
	and are walnut running the length of the			
long and about 2 feet in diame	eter. The cellar built in 1840 was used	as a station on the		
Underground Railway for slaves	the Civil War when the			
44 Description of Environment and Outbuild	The house is located on a double co	eon't-		
town of Comdon Mo orrest colling	The nouse is located on a double co	rner lot in the original		
cown or camden , wo., over tookin	ig the Missouri River(which did run ther	e until 1915 when it	,	
criminged ros course overmight);	It was built 8 years before the town o	I Camden was platted, con t	С	
4Personalo'khlowielege		46. Prepared by		
0	ri HistorianSites Catalogue, 1963	Virginia King McBee		
Camden Historians- on-site ins		47. Organization		
	_	RCHS & M		
		48. Date 49 Revision Date(s)		
		7/28/79		

#36 Con't

salvageable. The cellar was filled with dirt except for a 5'+ 8' section which was tetained for use as a family root cellar with stones set for steps to go outside. Wide oak flooring planks were laid at this time over the original log puncheon flooring. In 1935 a glassed, enclosed front porch was added across the front of the house. In 1950 the narrow room across back was torn away, a 12' addition put in its place fro dining room, kitchen, bathrrom, and hallway. A door was removed at the back with an 8' archway being put in its place. At sometime during the 1880's the fireplace at each end of the log cabin were closed, boarded, and just a brick chimney, floor to ceiling, left for each. In 1974 complete renovation to the structure was done, including strengthening the logs of the upstairs floor, floors carpeted and wood paneling added after being stripped back to the logs, kitchen cabinets, floor furnaces, outside weatherboarding repaired and replaced where necessary, re-roofed, a large utility room added to the right side of house to which was attached a garage, thus giving the house its present shape. Under the stairs in a closet, the logs were left exposed so as to reveal the original building material. All rafters were found to have been put together with hand-carved pegs, and the original shingles, which were left, were hand-hewn also. Across the front of the site, an ornately wrought-iron fence(built 1888 for Mrs. Kings grandmother's grave-site) was put in place after it became necessary to remove it from the Craven Cemetary to facilitate cemetary upkeep there.

- #42 Con't Willis Warriners lived there from 1837-1864. It was very dangerous, for Warriner's own relatives were of Southern persuasion. The fact that the house was within a block of the Missouri River accounted for its effectiveness. Family of present owners have lived in the house since 1917.
- #44 Con't being located then on the eastern boundries of Bluffton, county seat of Ray County 1821-1828. The root cellar in back is associated with the house, too. (see #42 for details.)





Office of Historic Preservation, P.O. Box 176. Jefferson City, Missouri 65101

HISTORIC INVENTORY 4 Present Name(s) Mosby Residence 5 Other Namo(s) 3 Location of Negatives 28. No of Stories 16. Thematic Category 6 Specific Lucation Ray-Sec: 26-51N Yes !! 29. Basement? 030 No X. 17 Dalu(s) or Period Centrall part of East Camden 40 30. Foundation Material 1890 SR 210 coursed stone rubbe 18 Style or Design Il Rural, Township & Vicinity 31. Wall Construction 09 vernacular frame . Wu 19. Architect or Engineer 8 Site Plan with North Arrow 32. Roof Type & Material 68 unknown gable-shingles 63 Highway 210 20. Contractor or Builder Posch 33. No. of Bays unknown CB Side 2 Front N/A 21. Original Use, if apparent 34. Wall Treatment 63 residence OF Comp. siding over Present Use residence 35. Plan Shape L-Shaped Addition :X 36. Changes Public 11 23 Ownership country road Affered IX (Explain Private XI Moved in #42) 24. Owner's Name & Address. 37. Condition Fair if known Exterior Fair George & Milde Mosby Camden, Mo UTM YPS Preservation Yes II 25. Open to Underway? No . No IX Public? Structure 1 i Site 11 Yes II 39 Endangered? 26. Local Contact Person or Organization Object | | Building XI By What? No I Yes IX 12 Is II Yes II 27. Other Surveys in Which Included Noll No X. Eligible? Yes X Visible from Yes X 14. District 13 Part of Estab Yes I No : : Public Road? Potent'l? Noli No I K 41. Distance from and Frontage on Road 15 Name of Established District 42. Further Description of Important Features I-house with 3 primary facade 2 interior end stove chimneys. #36: Appears originally to have had primary entrance in center of lower story, with a Photo door above. Lower door has been blocked and window and door substituted to left and right of original entrance. Evidence of 2-story porch replaced with shingle story porch with plain post. House modernized in 1950's and bath added at East side. of structure. (con't) 43 History and Significance This house has been continuously occupied by the same family (Mosby) since it was built. An elderly brother and sister(both their spouses are deceased) now live there in the house, their father built. 44 Description of Environment and Outbuildings The old road used to go in front of the house

but when the 210 was constructed, the back entrance was used.

45 Sources of Information On-Site inspection Personal knowledge of Surveyor Garden Historians

1 No

Junty

twp. 28w

Camden

9 Coordinates

11 On National

Register?

Hist Dist ?


Long

City or Town .

Ray

46. Prepared by Virginia McBee 47. Organization RCHS & M 48. Date 8/79 49 Revision Date(s)

#42 Con't The back part was enlarged to include a side porch of the kitchen.



FLOORPLANS


NOT TO SCALE



PHOTOGRAPH



C 12		sent Name(s)			
Ray		J.E. Seward Residence			
3 Location of Megatives	5 01	Hensley House; Colley Residence			
Specific Lucation		16 Thematic Calegory	28 No of Stories one		
East Camden, off	f State hywy		29. Basement? Yesx		
M-210. SR 3/1	Ď	17 Date(s) or Period 1915	partial No		
City or Town, Il Rura	al. Township & Vicinity		30. Foundation Material concrete block 65		
Camdon Vic		Neoclassic details 49	31. Wall Construction		
Sile Plan with North Are	low	19. Architect or Engineer	frame . ww		
	II N	unknown 20. Contractor or Builder	32. Roof Type & Material / gable/comp. shingle		
	1 5	unknown	33. No. of Bays		
	1 10	21. Original Use, if apparent residence	Front 3 Side 2		
		22 Present Use	34. Wall Treatment 20		
		residence	35. Plan Shape L-shaped		
		23 Ownership Public I !	36. Changes Addition		
	M-210	Private XI	(Explain Attered		
		24. Owner's Name & Address,	in #42) Moved		
Coordinates L	• I	Mr.&Mrs. J.E. Seward	37 Condition Interior <b>good</b>		
Lat	31 M	Camden, Missori	Exterior good		
Long	•	25 Open to Yes I I	38. Preservation Yes		
Site 1 i Building Xi	Structure 1 i	Public? No 1 X			
On National Yes II	12 Is II Yes XI	26 Local Contact Person or Organization	39 Endangered? Yes By What? No		
Angister? No X.	Eligible? No I I	27. Other Surveys in Which Included			
Part of Estab Yes II	14. District Yes i		40. Visible from Yes		
Hist Dist.? No Xi Potent'l? No Xi  Namu of Established District			Public Road? No		
Name of Established Dis	SINCI		41. Distance from and Frontage on Road		
Further Description of Ir		addition of siding, triple			
window cut on pri	imary facade. R	etains suggestion of Neoclassic in frieze, narrow molding of	Photo		
History and Significance As originally around 1915. In and in 1950, they the East Camden S	built as a thre 1946, the Jesse y moved it north	etains suggestion of Neoclassic in frieze, narrow molding of e-room house with closed-in porch Ellis Sewards purchased this hous across the railroad tracks. It solves at the contract of the	built by William Hensler se from Virgil Colley sits on the lot where		
Mindow cut on priflavor at boxed of window heads.  History and Significance As originally around 1915. In and in 1950, they the East Camden S Ellis is the son Description of Environme Rural area.	built as a thre 1946, the Jesse y moved it north school had forme of Joseph Sylve	etains suggestion of Neoclassic in frieze, narrow molding of  e-room house with closed-in porch Ellis Severds purchased this house	built by William Hensley is from Virgil Colley its on the lot where to the house. Jesse everal owned by the (cor		
History and Significance As originally around 1915. In and in 1950, they the East Camden S Ellis is the son Description of Environme Rural area.  Sources of Information	built as a thre 1946, the Jessey moved it north chool had forme of Joseph Sylvement and Outbuildings	etains suggestion of Neoclassic in frieze, narrow molding of e-room house with closed-in porch Ellis Sewards purchased this hous across the railroad tracks. It solves at the contract of the	built by William Hensley is from Virgil Colley its on the lot where to the house. Jesse everal owned by the (cor		
History and Significance As originally around 1915. In and in 1950, they the East Camden S Ellis is the son Description of Environme Rural area.  Sources of Information On-site inspection	built as a thre 1946, the Jessey moved it north chool had forme of Joseph Sylvement and Outbuildings	etains suggestion of Neoclassic in frieze, narrow molding of e-room house with closed-in porch Ellis Sewards purchased this hous across the railroad tracks. It solves at the contract of the	built by William Hensley is from Virgil Colley its on the lot where to the house. Jesse everal owned by the (con		
History and Significance As originally around 1915. In and in 1950, they the East Camden S Ellis is the son Description of Environme Rural area.  Sources of Information	built as a thre 1946, the Jessey moved it north chool had forme of Joseph Sylvement and Outbuildings	etains suggestion of Neoclassic in frieze, narrow molding of e-room house with closed-in porch Ellis Sewards purchased this hous across the railroad tracks. It solves at the contract of the	built by William Hensley is from Virgil Colley its on the lot where to the house. Jesse everal owned by the (con  46. Prepared by Jane Williams		



FLOORPLANS

NOT TO SCALE



PHOTOGRAPH

#43. Seward family in the middle part of this century, in East Camden.



32. Roof Type & Material GB 6: comp. shingles over wood

33. No. of Bays

Front 2

36 Changes

(Explain

in #42)

37 Condition

Interior

38. Preservation

39 Endangered?

By What?

Underway?

34. Wall Treatment

weatherboard 35. Plan Shape

Yes

Photo

Yes X No I .

41. Distance from and Frontage on Road

pneh

Public 11

Private D

Yes II

PO

42 Further Description of Important Features House displays Veranda across primary facade with pedmented entryway supported by slender columns. Primary entrance has sidelights and transom interior still has wide oak plank flooring. #36: House has had many alterations. Windows have been replaced, veranda supports are new. Additions were constructed at the rear and southwest facade.

Structure 1 i

Object 11

Yes 10

No II

Yes !!

No N

HISTORIC

6 Specific tocation N2 Lot 60 in Block 74 16 Thematic Calegory

28W

If Rural, Township & Vicinity

Ray ) Location of Negatives

1 City of Town

9 Courdinales

11 On National

Bearster?

11 Part of Estab

Hist Dist ?

141 Lister

Camden, Mo

H Site Plan with North Arrow

in original town of Camden

Site: ! i Building %

Yes II

No De

15 Name of Established District

12 Is II Eliaible?

District

Poteni'l?

51N

4) History and Supulicance House was constructed as the residence for the agent of a Kansas City Steamship line. William G. King was intended as a miniature "Mansion" and when constructed, overlooked the Missouri River, with grounds running to the rivers edge. (The Missouri later changed its course, and the river port of Camden is now several miles inland from the River.)

Office of Historic Preservation, P.O. Box 176, Jefferson City, Missouri 65101

Cravens House; Wm. G. King House

4 Present Name(s)

5 Other Namo(s)

Holloway House

17 Date(s) or Period

18 Style or Dosign

neoclassic

19 Architect or Engineer

20 Contractor or Builder

Residence OIA

22 Present Use

Residence

23 Ownership

il known

25 Open to

Public?

Donald Holloway

Camden, Mo 64017

21. Original Use, if apparent

24 Owner's Name & Address,

26 Local Contact Person or Organization

21 Other Surveys in Which Included

1880

unknown

unknown

44 Description of Environment and Outbuildings Situated on a slight rise, the Lawns once running to the river now belong to a later house to the south.

45 Sources of Information

Camden Historians-Personal Knowledge and Research on-site inspection

46 Prepared by Virginia McBee 47 Organization 49 Revision Date(s) 48. Dale 6/30/79


Other Namers





Present Namers

Office of Historic Preservation, P.O. Box 176, Jefferson City, Missouri 65101 HISTORIC INVENTORY



Urban environment, bordered by sidewalks.

45 Sources of Information Camden Historians-Personal Knowledge on-site inspection

46 Prepared by Virginia McBee 47. Organization RCHS & M 48 Date 49 Revision Date(s) 8/15/79 |

#43 Con't the proprietors of the cafe below.






RCHS &

48. Date 8/79 49 Revision Dale(s)

## Office of Historic Preservation, P.O. Box 176, Jefferson City, Missouri 65101

1 No. C7	4 Pres	esent Name(s)			
	McGs	augh Residence			
2 anty .		er Namo(s)			
3 Location of Negatives		Kirkland Residence-C.C. Cli	ne home		
				11.	
6 Specific Lucation Lot 25, in I	Block 86	16 Themalic Calegory	26. No. of Stories 1		
in original town of Camden		17 Date(s) or Period	29. Basement? Yes the No i.		
5N 28W		1920 alt. 1939	30. Foundation Material	100	
		18 Style or Design	concrete and fieldstone	000	
7. City of Town Il Rural, Township Camden	& Vicinity	Bungalow 22	31. Wall Construction	1	
H Site Plan with North Arrow		19. Architect or Engineer	Frame W4		
a site Field with Rottle Arrow	_ ,	unknown	32. Roof Type & Material GB		
		20. Contractor or Builder	Gable/Comp Slate Shingle	5	
N.		Russell Rush Fu	33. No. of Bays Front Side		
		21. Original Use, if apparent	NA 3		
(15)	4	Residence O/A	34. Wall Treatment Westherhoard		
7	4		35. Plan Shape Rectangular	25	
		Residence 23 Ownership Public !!	36 Changes Addition X		
		Private N	(Explain Altered		
		24. Owner's Name & Address,	in #42) Moved i		
		if known	37. Condition Interior Excellant		
9 Coordinates UTM		Mrs. Harry McGaugh			
t at Larry		Camden, Mo	Exterior Excellent  38. Preservation Yes		
	Structure 1 i	25. Open to Yes !! Public? No M	Underway? No		
Sile ! 1 Sulding ry	Object	26. Local Contact Person or Organization	39. Endangered? Yes II		
1) On National Yes 11 12 Is II	Yes bi		By What? No 1		
Regenter? No 7 Eligibl	e? No 11	27. Other Surveys in Which Included			
13 Part of Estab Yes II 14. Distric			40. Visible from Yes ' Public Road? No i	3.10	
Hist Dist ? No ba Poten	117 No 14		Public Road? No 11		
15 Name of Established District			Frontage on Road		
42 Further Description of Important Fe	satures un	use still has original composition		1 4	
		Front porch was screended a year		- 1	
		till has those original screens.			
Bathroom added in 1934.		5,	Photo		
43 History and Significance		type house was built by the local b	erber C C Cline in 1020		
THIS D	ungarow	me of a modern home, with wall swit	ches to turn on center		
electric light features. L	ater own	ed by a man named Kirkland, a stati	on master, who added a		
bathroom to the house.					
44 Description of Environment and Ou	tbuildings				
In small town environment,		ing landscaped lof			
In small cown environment,	ou stob	rue, randscaped tou.			
45 Sources of Information			46. Prepared by		
Present owner whose father	was the	builder of the house	Virginia McBee		
On-site inspection.			47. Organization		



FLOORPLANS


NOT TO SCALE



PHOTOGRAPH



	1	sent Name(s)	<i>f</i>	
County C8	Qui	ick Rental Property		
Ray				
Location of Regalives	Dot	uglas House		
Specific Lucation Lots 26 ar	nd 27	16. Thematic Category	28 No of Stories 2	
Block 86 in original 1	town of	030	29. Basement? Yes	
		17 Date(s) or Period 1921	Full No 1.	
312 30		BU CITIE	30 Foundation Material	
City or Town If Aural, Towns	ship & Vicinity	18 Style or Design	stone 40	
Camden		bungalow 19. Architect or Engineer	frame WW	
Site Plan with North Arrow		unknown	32. Roof Type & Material GB	
		20. Contractor or Builder .	Gable-Asbestos Shingle	
		Russell Rush · Fu	33. No. of Bays	
		21. Original Use, if apparent	Front 3 Side 2 DR	
		Dwelling OIA	34. Wall Treatment	
		22 Present Use	wood shingles	
		Dwelling Subtraction	35. Plan Shape rectangular 36 Changes Addition:	
		23 Ownership Public I I	36 Changes Addition : · (Explain Altered №	
		24 Owner's Name & Address,	in #42) Moved i	
		il known	37. Condition	
Coordinates UTM		Mrs. Clyde Quick	Interior Good	
Lat		Camden, Mo 64017	Exterior Good	
Long		25 Open to Yes 11 Public? No 11	38. Preservation Yes Underway? No X	
Site ( ) Building M	Structure 1 i	26 Local Contact Person or Organization	39 Endangered? Yes 11	
		26 Local Contact Person of Organization	By What? No 🗵	
	gible? No I I	27 Other Surveys in Which Included		
Part of Estab Yes II 14. Di			40 Visible from Yes X	
Hist Dist? No by Po	otent'i? No DY		Public Road? No ::	
1100 0100 . 1100 45			41. Distance from and Frontage on Road	
Name of Established District	t Features			
Name of Established District  Further Description of Importan	Har	nd-crepted "built-in" china	/-	
Name of Established District  Further Description of Importan  cabinet in dining room	Har m, built al	bout 1940 by an owner(Gelbach) wh		
Further Description of Importance cabinet in dining room	Har m, built al vocation.	bout 1940 by an owner(Gelbach) wh #36: Altered in 1940's porch	Photo	
Further Description of Importance cabinet in dining room	Har m, built al vocation.	bout 1940 by an owner(Gelbach) wh #36: Altered in 1940's porch		
Further Description of Important cabinet in dining room	Har m, built al vocation.	bout 1940 by an owner(Gelbach) wh #36: Altered in 1940's porch		
Further Description of Importance cabinet in dining room	Har m, built al vocation.	bout 1940 by an owner(Gelbach) wh #36: Altered in 1940's porch		
Further Description of Important cabinet in dining room was a woodworker by an screened, fence added,	Har m, built al vocation. # house itse	bout 1940 by an owner(Gelbach) wh #36: Altered in 1940's porch elf remodelled.	Photo	
Further Description of Important cabinet in dining room was a woodworker by an screened, fence added,	Harm, built all vocation. # house itse	bout 1940 by an owner(Gelbach) wh #36: Altered in 1940's porch elf remodelled.	ts construction. Now a	
Further Description of Important cabinet in dining room was a woodworker by an acreened, fence added,	Harm, built all vocation. # house itse	bout 1940 by an owner(Gelbach) wh #36: Altered in 1940's porch elf remodelled.	ts construction. Now a	
Further Description of Important cabinet in dining room was a woodworker by an acreened, fence added,	Harm, built all vocation. # house itse	bout 1940 by an owner(Gelbach) wh #36: Altered in 1940's porch elf remodelled.	ts construction. Now a	
Further Description of Important cabinet in dining room was a woodworker by an screened, fence added,	Harm, built all vocation. # house itse	bout 1940 by an owner(Gelbach) wh #36: Altered in 1940's porch elf remodelled.	ts construction. Now a	
Further Description of Important cabinet in dining room was a woodworker by an acreened, fence added,  History and Supprisonnee Own rental property. Judge	Harm, built all vocation. A house itse	bout 1940 by an owner(Gelbach) wh #36: Altered in 1940's porch elf remodelled.  bach and Douglas families since i as lived in the house at one time	ts construction. Now a	
Further Description of Important cabinet in dining room was a woodworker by an acreened, fence added,  History and Significance Own rental property. Judge	Harm, built all vocation. A house itse	bout 1940 by an owner(Gelbach) wh #36: Altered in 1940's porch elf remodelled.	ts construction. Now a	
Further Description of Important cabinet in dining room was a woodworker by an acreened, fence added,  History and Significance Own rental property. Judge	Harm, built all vocation. A house itse	bout 1940 by an owner(Gelbach) wh #36: Altered in 1940's porch elf remodelled.  bach and Douglas families since i as lived in the house at one time	ts construction. Now a	
Further Description of Important cabinet in dining room was a woodworker by an acreened, fence added,  History and Significance Own rental property. Judge	Harm, built all vocation. A house itse	bout 1940 by an owner(Gelbach) wh #36: Altered in 1940's porch elf remodelled.  bach and Douglas families since i as lived in the house at one time	ts construction. Now a	
Further Description of Important cabinet in dining room was a woodworker by an acreened, fence added,  History and Significance Own rental property. Judge Description of Environment and A garden and fenced from small town of Camden.	Harm, built all vocation. A house itse	bout 1940 by an owner(Gelbach) wh #36: Altered in 1940's porch elf remodelled.  bach and Douglas families since i as lived in the house at one time	ts construction. Now a cling. Located in	
Further Description of Important cabinet in dining room was a woodworker by an screened, fence added,  History and Significance Own rental property. Judge  Description of Environment and A garden and fenced from small town of Camden.  Sources of Information	Harm, built all vocation. A house itse ned by Gelle Ed Dougle outbuildings ront yard a	bout 1940 by an owner(Gelbach) wh #36: Altered in 1940's porch elf remodelled.  bach and Douglas families since i as lived in the house at one time are the other features of the dwe	ts construction. Now a clling. Located in	
Further Description of Important cabinet in dining room was a woodworker by an screened, fence added,  History and Significance Own rental property. Judge	Harm, built all vocation. A house itse ned by Gelle Ed Dougle outbuildings ront yard a	bout 1940 by an owner(Gelbach) wh #36: Altered in 1940's porch elf remodelled.  bach and Douglas families since i as lived in the house at one time are the other features of the dwe	ts construction. Now a  cling. Located in  46 Prepared by Virginia McBee 47 Organization	
Further Description of Important cabinet in dining room was a woodworker by an screened, fence added,  History and Significance Own rental property. Judge Description of Environment and A garden and fenced from small town of Camden.  Sources of Information	Harm, built all vocation. A house itse ned by Gelle Ed Dougle outbuildings ront yard a	bout 1940 by an owner(Gelbach) wh #36: Altered in 1940's porch elf remodelled.  bach and Douglas families since i as lived in the house at one time are the other features of the dwe	ts construction. Now a clling. Located in	



FLOORPLANS

NOT TO SCALE



PHOTOGRAPH



		Present Name(s)			
H3		ardin United Methodist Church			
Kay	5 Other Namo(s)				
Location of Negatives				. No of Stories 2	
Specific Lucation 212-216.	N. First 16. Them	alic Calegory		. Basement?	Yes X
Street		s) or Period		Full	No I .
	1896		30	oncrete 65	ıl (
City or Town II Rural, Town	ship & Vicinity 18 Style	or Design		. Wall Construction	
Hardin		thic Revivial	В	rick 1B	
Site Plan with North Arrow	unkno	wn	43 30 32	Roof Type & Males sbestos Shin	raGabl
<u> </u>	20. Contunkn	rector or Builder	100	No. of Bays	6:
0 t	21. 000	inal Use, if apparent			le Tu
street		urch OGA	34	Common Bond	30
	22 Pres	ent Use urch	35	. Plan Shape Rect	angul
	23 Own	ership	1 00110	6. Changes	Addition :
<u>т</u>		1 Address	Private Ki	in #42)	Moved
	if k	ner's Name & Address, nown	37	7. Condition Excel	lant
Constinutes UTM		in United Metho rdin, Mo	dist Churc	h Interior Excel	
Lat			Yes IA 36	B. Preservation	Yes
Long	Structure 1 i		Noll	Underway?	No
Site 11 Building X	Object     26. Loc	al Contact Person or Orga	nization 3	9 Endangered? By What?	Yes
1 On National Yes II 12 Is	sil YesiX Vir	gil Shirley er Surveys in Which Include	ded	-,	
Migrater	District Yes X	A Surveye in vinen men		0. Visible from Public Road?	Yes
Hist Dist.? No x1	Potent'l? No II			11. Distance from an	
15 Name of Established District				Frontage on Road	İ
	ant Fastures Pariols C	hurch features	gable on		
42. Further Description of Imports	/holl town	+	. 3 7 . 7	-	
primary facade w	/bell tower con	taining primary som. All windo	doublehun		
primary facade w entrance with po corbel arches w/	/bell tower con inted arch tran limestone keyst	som. All windo	ows have	Photo	
primary facade wentrance with posorbel arches w/arches and are o	/bell tower con inted arch tran limestone keyst f leaded, stain	som. All windo one. All have p ed glass. Roof	ows have pointed has coping	Photo	
primary facade wentrance with posorbel arches w/arches and are obell Tower featu	/bell tower con inted arch tran limestone keyst f leaded, stain ares roundel of	som. All windo one. All have p ed glass. Roof stained glass a	ows have pointed has coping and belfry	Photo	
primary facade wentrance with posorbel arches w/arches and are o	hell tower condinted arch tran limestone keyst f leaded, stain res roundel of and decorative p	som. All windo one. All have p ed glass. Roof stained glass a innacles. Inter	ows have pointed has coping and belfry	Photo	/
primary facade wentrance with possible arches w/arches and are of Bell Tower featuwith helm roof achurch hasraised	hell tower condinted arch tran limestone keyst f leaded, stain res roundel of and decorative p	som. All windo one. All have p ed glass. Roof stained glass a innacles. Inter (con't)	ows have cointed has coping and belfry rior of	Photo	to th
primary facade wentrance with positive corbel arches w/arches and are of Bell Tower featuwith helm roof a church hasraised  43 Mistory and Significance Afsettlement near	/bell tower condinted arch translatione keyst fleaded, stain ares roundel of and decorative part chancel area. Ter 1820, Methowhat was to be	som. All windo one. All have ped glass. Roof stained glass a innacles. Inter (con't) dist preachers Hardin, and pre	ows have pointed has coping and belfry rior of made irregulation was	Photo ular visits done at vari	ous
primary facade wentrance with positive corbel arches w/arches and are of Bell Tower featuwith helm roof a church hasraised  History and Significance Afsettlement near homes of Methodi	/bell tower condinted arch translimestone keyst of leaded, stain ares rounded of and decorative part chancel area. Ter 1820, Methowhat was to be sts. Church ser	som. All windo one. All have ped glass. Roof stained glass a innacles. Inter (con't) dist preachers Hardin, and previces later bed	ows have pointed has coping and belfry rior of made irregulation was came more r	ular visits done at vari	ous ere h
primary facade wentrance with positive corbel arches w/arches and are of Bell Tower featuwith helm roof a church hasraised  History and Significance Afsettlement near homes of Methodi in schoolhouses.	/bell tower condinted arch translimestone keyst fleaded, stain ares roundel of and decorative part chancel area. The hardin Met	som. All windo one. All have ped glass. Roof stained glass a innacles. Inter (con't) dist preachers Hardin, and previces later bed hodist Episcopa	ows have pointed has coping and belfry rior of made irregulation was came more rail Church S	ular visits done at vari egular and w	ous ere h anize
primary facade wentrance with possible corbel arches w/arches and are of Bell Tower featuwith helm roof a church hasraised  History and Significance Afsettlement near homes of Methodi in schoolhouses. in 1845, called	hell tower condinted arch translimestone keyst fleaded, stain ares rounded of and decorative pachancel area. The hardin Met the old Walnut	som. All windo one. All have ped glass. Roof stained glass a innacles. Inter (con't) dist preachers Hardin, and previces later bed hodist Episcopa	ows have pointed has coping and belfry rior of made irregulation was came more rail Church S	ular visits done at vari egular and w	ous ere h anize
primary facade wentrance with possible arches w/arches and are of Bell Tower featuwith helm roof a church hasraised  43 History and Significance Afsettlement near homes of Methodi in schoolhouses. in 1845, called Hardin cemetary	/bell tower condinted arch translimestone keyst fleaded, stain res roundel of and decorative part chancel area. The hardin Met the old Walnut	som. All windo one. All have ped glass. Roof stained glass a innacles. Inter (con't) dist preachers Hardin, and previces later bed hodist Episcopa	ows have pointed has coping and belfry rior of made irregulation was came more rail Church S	ular visits done at vari egular and w	ous ere h anize
primary facade wentrance with possible arches w/arches and are of Bell Tower featuwith helm roof a church hasraised  43 History and Significance Afsettlement near homes of Methodi in schoolhouses. in 1845, called Hardin cemetary	/bell tower condinted arch translimestone keyst fleaded, stain res roundel of and decorative part chancel area. The hardin Met the old Walnut	som. All windo one. All have ped glass. Roof stained glass a innacles. Inter (con't) dist preachers Hardin, and previces later bed hodist Episcopa	ows have pointed has coping and belfry rior of made irregulation was came more rail Church S	ular visits done at vari egular and w	ous ere h anize
primary facade wentrance with possible arches w/arches and are of Bell Tower featuwith helm roof a church hasraised  43 History and Significance Afsettlement near homes of Methodi in schoolhouses. in 1845, called Hardin cemetary	/bell tower condinted arch translimestone keyst fleaded, stain res roundel of and decorative part chancel area. The hardin Met the old Walnut	som. All windo one. All have ped glass. Roof stained glass a innacles. Inter (con't) dist preachers Hardin, and previces later bed hodist Episcopa	ows have pointed has coping and belfry rior of made irregulation was came more rail Church S	ular visits done at vari egular and w	ous ere h anize
primary facade wentrance with posorbel arches w/arches and are of Bell Tower featuwith helm roof achurch hasraised  43 History and Significance Afsettlement nearhomes of Methodi in schoolhouses in 1845, called Hardin cemetary.  44 Description of Environment and the school of the sc	/bell tower condinted arch translimestone keyst fleaded, stain res roundel of and decorative part chancel area. The hardin Met the old Walnut	som. All windo one. All have ped glass. Roof stained glass a innacles. Inter (con't) dist preachers Hardin, and previces later bed hodist Episcopa Grove church, l	ows have pointed has coping and belfry rior of made irregulating was came more rall Church Stocated in	ular visits done at vari egular and w outh was org the east of	ous ere h anize
primary facade wentrance with posorbel arches w/arches and are of Bell Tower featuwith helm roof achurch hasraised  43 History and Significance Afsettlement near homes of Methodi in schoolhouses in 1845, called Hardin cemetary.  44 Description of Environment and the school of the s	/bell tower condinted arch translimestone keyst fleaded, stain ares rounded of and decorative pachancel area. The 1820, Methow what was to be sts. Church ser The hardin Method Walnut (con't) and Outbuildings	som. All windo one. All have ped glass. Roof stained glass a innacles. Inter (con't) dist preachers Hardin, and previces later bed hodist Episcopa Grove church, l	ows have pointed has coping and belfry rior of made irregulating was came more rall Church Stocated in	ular visits done at vari egular and w outh was org the east of	ous ere h anize
primary facade wentrance with posorbel arches w/arches and are of Bell Tower featuwith helm roof achurch hasraised  43 Misiory and Significance Afsettlement near homes of Methodi in schoolhouses in 1845, called Hardin cemetary  44 Description of Environment and Mrs. Vir	hell tower condinted arch translimestone keyst fleaded, stain res roundel of and decorative pachancel area. The 1820, Methowhat was to be sts. Church ser The hardin Method Walnut (con't) and Outbuildings	som. All windo one. All have ped glass. Roof stained glass a innacles. Inter (con't) dist preachers Hardin, and previces later bed hodist Episcopa Grove church, l	ows have cointed has coping and belfry rior of made irreg eching was came more r al Church S cocated in	ular visits done at vari egular and w outh was org the east of	ous ere h anize
entrance with po corbel arches w/ arches and are o Bell Tower featu with helm roof a church hasraised  43 Misiory and Significance Af settlement near homes of Methodi in schoolhouses in 1845, called Hardin cemetary  44 Description of Environment and the settlement of Environmen	hell tower condinted arch translimestone keyst fleaded, stain ares rounded of and decorative pachancel area. The 1820, Methow hat was to be sts. Church ser The hardin Method Walnut (con't) and Outbuildings	som. All windo one. All have ped glass. Roof stained glass a innacles. Inter (con't) dist preachers Hardin, and previces later bed hodist Episcopa Grove church, l	ows have cointed has coping and belfry rior of made irreg eching was came more r al Church S cocated in	ular visits done at vari egular and w outh was org the east of	ous ere h anize the


#42 Con't

#36: A full basement and Sunday School addition have been added to the building, and a new chancel constructed.

#43 Con'T

It served several denomination. When the Wabash RR was built, the town of Hardin was moved north to its present site. The church was also moved. The Methodist Church in Hardin was constructed in 1880 at a cost of \$1600. A frame structure, it was located on what was to be the Santa Fe RR right of way, and was moved to the present site in 1887 when the railroad came through. In 1881, Church memberships was 74.

The Church burned in 1895 and the present brick structure was raised on the same site the next yeat, at a cost of \$5600. Memorial windows were placed by many families. Windows were also placed by the Local Epworth League and the social club called "The Circle." They added the circular window in the east with a central C surrounded by 16 opaque panes representing of the club.



FLOORPLANS

NOT TO SCALE




PHOTOGRAPH



NO

4. Present Name(s)

1 Nº H5	4 Present Name(s)		
2 COLY :	Hogan Residence	•	
Ray	5 Other Namo(s)		
3 Location of Negatives	William D. Wushana Allan Wash		
RCHS	William B. Hughes; Allen Hugh	es; William A. Buchanan	
All lots 1, 2, 3, and	4. 1m 16. Thematic Category	28. No. of Stories two	
Block 6 of Hardin Hugh		29. Basement? Yes 00	
Addition, Sec. 32, Twp	52 III Date(s) of Period	full No 1	
Range 26 N. 1st s	theor 1895 all 6,1960	30. Foundation Material 30 65	
City of Town If Rural, Township Hardin	8 Vicinity 18 Style or Design Victorian Romanesque	brick; concrete 31. Wall Construction	
Site Plan with North Arrow	19. Architect or Engineer	fiasonry	
The Flat with Min Min Min	unknown 30 43 2		
	20. Contractor or Builder	hip/comp. shingles	
	William B. Hughes 08	33. No. of Bays	
	21. Original Use, if apparent	Front n/a Side n/a	
	residence O/A	34. Wall Treatment	
	22 Present Use residence	35. Plan Shape T-shape	
The second second	23 Ownership Public I ! Private by	36. Changes Addition : (Explain Altered)	
1	24. Owner's Name & Address,	in #42) Moved i	
Olive Street	if known	37. Condition excellent	
Coordinates UTM	Box 466, Hardin Missouri	THE HOT	
Long		Exterior excellent	
	25. Open to Yes 11 Public? No RO	38. Preservation Yes Underway? No X	
Building 10	Object     26. Local Contact Person or Organization	39. Endangered? Yes	
On National Yes   12. Is II	Yes Ri	By What? No X	
Register? No X Eligible	? No 11 27. Other Surveys in Which Included		
Part of Estab Yes I 14. District Hist Dist ? No bd Potent		40. Visible from Yes X	
	1? ·No I :	Public Road? No 1 :	
Name of Established District		41. Distance from and Frontage on Road	
Of a T-shape plan, the is segmentally arched of arch with row of dentil connect the limestone linto a full bath in 195 modernized and enclosed	sone of the finest in the town of Hardon south wing ends in anpolygonal bay. Fenesone-over-one sash, first floor has relieving over each window. String courses lagsills of each window. #36:Pangry was magnificant to the course windows, outside basement steps with seven windows, outside basement steps	Photo de (cont)	
builder. House is buil north and built of same	family four generations. Second owner was ow and present ewner is his daughter, the get en the normer of 4 lots. Methodist Chure brick. There are 14 windows downstairs to stars there are 12 windows slightly shorter buildings.	ch is next door to the	
Original frame building One side was used as a 'n 1919.	smoke house, the other as a shop. A tile	d is in good shape. garage was constructed	
Sources of Information		46. Prepared by	
Hughes family history.		Mary Hogan	
personal knewledge On-site inspection.		47. Organization	
		48. Date 49 Revision Date(s)	
		48. Date 49 Revision Date(s)	



FLOORPLANS

NOT TO SCALE



PHOTOGRAPH

- 42. included in inside walls. House outside walls are red brick which was tuckpointed and stained in 1960. The interior has original hanging lamps. Fireplace is in dining room. House has always had electricity and water. Original water system was a large tank in the basement and water was pumped from a point about 20 feet into the ground. This area, so close to the Missouri River, has water very close to the surface.
- \$43. door windows and transoms are Bohemian glass in barying shades of red. Original closed porch is on the seuth side. Original bath is upstairs. Only alteration was the removal of a skylight in 1960; the ceiling was covered and a window cut in the east wall. There is a chimney in every room. The first owner's father was the first dector in Hardin.



1 No H7	4 Present Name(s)	
ounty	King Building	
Ray Tocation of Negatives RCHS	5 Other Namo(x) Bank of Hardin 1.00 F	
6 Specific Lucation	CONTRACTOR OF THE PERSON OF TH	28 No of Stories CWO
205 Second Street; Lot 26, Blo 11 Original Town of Hardin	Ck 030 050	29. Basement? Yes Tull No:
7 Gily or Town II Rural, Township & Vi	1888	30. Foundation Material 30 4
B Sile Plan with North Arrow	Victorian storefront  19 Architect or Engineer	31. Wall Construction
1	unknown  20. Contractor or Builder	32. Roof Type & Material Ti
	unknown  21. Original Use, if apparent	33. No. of Bays
	bank and offices ODA OFF	Front 3 Side 4  34 Well Trealment of Common bond brick 30
	gas company	35. Plan Shape rectangula
	23 Ownership Public   Private	36. Changes Addition
	24. Owner's Name & Address, if known	in #42) Moved i
9 Coordinates UTM Lat Long	Mr. and Mrs. Cecil King Hardin, Missouri	Interior GOOd  Exterior GOOd
Site IV Structur		The state of the s
Building IX Object	Allen Rhodes-Cecil King	39 Endangered? Yes III By What? No X
13 Part of Estab Yes 11 14. District Ye	27. Other Surveys in Which included	
Hist Dist.? No IX Potent'I? N	011	Public Road? No ::
		41. Distance from and Frontage on Road
42 Further Description of Important Features	ding has the set of th	
All willdows are one-over-one [1]	ding has three bay primary elevation ght sash under segmental arches.	
brick corber table and corince	surround the building. The first fl modernized with tile sheathing and	OOT
a metal awning. The building of	n the first floor was heated with a	
irreplace, years later a partia	basement was dud for a furnace for	
-5 mistory and Significance	2 vault was built of soft brick on t	
This building is the oldest star	nding in the business section of the	town. Fires destroyed
an odici bullullus bi lilla her	IIII II Was built to May at 1000 $E_{\bullet}$ .	to the Dell City is
sleeping rooms until the Odd Fel	llows lodge bought the second floor	Later it was rented for
building and Loan had an office	at the rear when the Bank of Hardin	was in business (cont)
On Main street in the business s	section of the small town of Hardin.	
45 Sources of Information		
Allen Rhodes, who established th	ne Hardin Building and Loan office	46. Prepared by Mary Hogan
at the rear of the Bank of Hardi	n, June 1, 1910.	ARCHS & Mich
On-site inspection		48 Date 49 Revision Date(s)

#43. Cont. The Bank failed in 1929. The Hardin Building and Loan bought the first floor and sold the upstairs to the Odd Fellows Lodge. The lodge put an outside stairway to the second floor. Before that, the inside stairway door had been used for access to the upper floor. L.Z. Williams boughtthe first floor in October of 1962. After his death, Cecil and Louise King purchased the building and William's business and operate a gas and oil heating business.






48. Date

49 Revision Date(s)

1 Nii LI Q	4 Present Nanio(s)		
H8	D.W. and Mary Linebaugh- Residence		
Ray	5 Other Namo(s) Dr. Marvin Grimes - Residen	ce	
1 Location of Negatives	Sam Redd- Resdience	s Happy- Residence	
6 Specific Location	16 Thematic Category	28 No of Stones 1 1/2	
306 E. Elm	030	29. Basement? Yes:1	
Hardin, Mo 64035	17 Date(s) or Period 1889 and C. (960	No K	
7 Caly of Town Il Rural, Township	& Vicinity 18 Style or Dosign	30. Foundation Material Brick and Stone 30 40	
/ City of lown If Rural, Township Hardin	Victorian 43	31. Wall Construction	
h Site Plan with North Arrow	unknown 3000	Brick LB	
	20 Contractor or Builder Prich	32. Roof Type & Material MN mansard/Asbestos	
/ - =	unknown	33. No. of Bays	
N TI	21 Original Use, if apparent residence	Front N.A. Side N.A.	
	22 Present Use	34. Wall Treatment common bond brick 30	3611
9 5	residence	35. Plan Shapeirregular	
	23 Ownership Public I ! Private 64	36 Changes Addition .	
	24 Owner's Name & Address.	(Explain Altered IX)	
	if known	37 Condition	
9 Coordinates UTM	D.W. & Mary Linebaugh	Interior Excellant.	
tohq	306 E. Elm Hardin, Mo 25 Open to Yeall	Exterior Excellant  38. Preservation Yes	
	ructure 1 i Public? No M	Underway? No x	
building od	Object 11 26 Local Contact Person or Organization	39 Endangered? Yes 11 By What? No IX	
11 On National Yes (1 12 Is II Register? No & Eligible	Yes 04 Po 11 27 Other Surveys in Which Included	b) time!	
Hist Dist ? No N Potent	Yes be	40 Visible from Yes '	
15 Name of Established District		Public Road? No i -	
		Frontage on Road	
A2 Further Describing of Important For		10 ft.	
Primary foods fortunes 1	Mansard roof unusual for this area.  arge semi-polygorel bay window ornamental		0
	and domical roof. Doors and windows are		Other
topped with segmental arc	hes on the first story. Original front	Photo	
	and carved brackets. #36: Mansard roof has		Namers
	ing and original windows replaced. CA. 1960 stained, with cement added between the	't /	9
43 History and Significance		1	
Tristory and Significance		- 5	
	•		
		,	
			•
44 Description of Environment and Outl	ouildings		
Residental section of small	ll town.		
15 Sources of Information Mary Hogo	an-I have known this place for 70 years.	46 Prepared by	
Dora Frances Shirley-Her	parent were second occupants of the home in	Mary Hogan	
1891		47. Organization	

#42 Con't bricks to give the house a "modern" appearance. Original color of Brick probably lighter— as other examples in the town. Garage attached to east facade.



FLOORPLANS

NOT TO SCALE



PHOTOGRAPH



47 Organization RCHS & M


9/15/78

48 Date 49 Revision Date(s)

ZO

4 Present Namers

1 N. HIO	4 Presimi Name(s)			
710	Leach House			
Rav	5 Other Namo(s)	5 Other Namo(s)		
3 Location of Negatives	Stratton House: Shirley House			
6 Specific Location 501 E. El	m S+ 16 Themalic Calegory	28 No of Stories 1 1/2		
Lot 1-4 Block 6 Origin	nel town of	29. Basement? Yes N		
Hardin. Township 52N R	M 17 Data(a) of PHILOD	Full Yes No :		
	1913	30. Foundation Material		
	ship & Vicinity 18 Style or Dosign	Concrete 65		
Hardin	Bungalow 22	31. Wall Construction .		
B Site Plan with North Arrow	19 Architect or Engineer	Brick 32. Roof Type & Material GB		
1	unknown  20 Contractor or Builder	Asbestos/Gable Shingles		
	John Rhodes	33. No. of Bays 64		
	21 Original Use, if apparent	Front 3 Side 2		
	Residence OPA	34. Wall Treatment		
	22 Present Use	Brick Stretches Board		
	Residence	35. Plan Shape L-Shaped		
	23 Ownership Public 11	36 Changes Addition .		
169 2	Private DY	(Explain Allered I in W42) Moved I		
	24 Owner's Name & Address,	37 Condition		
	Suanne Leach	Interior Very Good		
9 Coordinates UTM	501 E. Elm Rt. #1 Hardin, Mo	Exterior Very Good		
Lot		38. Preservation Yes		
10 Site: 1	25 Open to Yes   1 Structure   1 Public? No W	Underway? No x		
10 Site : i	Object     26 Local Contact Person or Organization	39 Endangured? Yes 11		
II On National Yes II 12 Is I	II Yes IX	By What? No 🖔		
	gible? No 11 27 Other Surveys in Which Included			
Hist Dist ? No DC Po	istrict Yes Minute of the Control of	40 Visible from Yes 7 Public Road? No 1		
15 Name of Established District		41. Distance from and		
		Frontage on Road		
		50 ft.		
42 Further Description of Importan	Features House features veranda on primary			
facade, mullioned wind	dows, 2 interior Brick chimneys and roof with			
large overhang, and co	ornice supported by Brackets. On the interior,			
the living room and di	ining room have oak beamed ceilings and solid.	Photo		
oak doors and trim. Li	iving room and dining room have hand painted	2		
	ral designs-hand painted mural over fireplace			
in alcove off living r		1.		
41 History and Significance	use was built by Daniel Stratton in 1913. It w	as later owned by his		
	on Shirley. Present owner is granddaughter of			
,				
		4		
44 Description of Environment and	Outbuildings 1 1/2 story- Carriage House/Garage.	To rear of property.		
	1 1/2 2002 0002 000000000000000000000000			
45 Sources of Information		46 Prepared by		
Personal Knowledge: or	n-site inspection	Dora F. Shirley		



FLOORPLANS

NOT TO SCALE



**PHOTOGRAPH** 



49 Revision Date(s)

48. Date 9/79

Office of Historic Preservation, P.O. Box 176, Jefferson City, Missouri 65101

ISTORIC Present Name(s) 1 N .. (Mrs. Paul W.) - Louise Grimes-Residence . ( 11 Ray 5 Other Namo(s) Dr. Marvin Grimes 3 Location of Negatives 16 Themalic Calegory 28 No of Stories 6 Specific Location Hardin Old Survey 29. Basement? Full Yes X Lot 26 Block 13 Rg. 1040 No I Datu(s) or Period 210 West Elm 1918 30. Foundation Material concrete (= 18 Style or Design 7 City of Town If Rural, Township & Vicinity 31. Wall Construction Hardin, Mo Shirtwaist 19 Architect or Engineer WU frame H Site Plan with North Arrow Other 32. Roof Type & Material unknown 20 Contractor or Builder Gable/Asbestos Shingle FU 33. No. of Bays George Tinsley Side Front 21. Original Use, if apparent Present Namels 34. Wall Treatment Residence O 22 Present Use Shingles Clapboard 35. Plan Shape square Residence Altered X 36 Changes 23 Ownership Public I Private M (Explain Mrs. Paul W. Grimes Moved i in #42) 24 Owner's Name & Address, 37 Condition Mrs! Paul W. Grimes Good Interior Box 433 Hardin, Mo UTM 9 Conthinales Good Exterior Lat 1 . sterl 25 Open to 38. Preservation Yes II Yes No .y. Public? No M Underway? Structure 1 i 10 Sile: ! i Object | | 39 Endangered? Building X Yes ! 26 Local Contact Person or Organization No IX By What? 11 On National 12 Is II Yes M Yes 11 Eligible? Noll Henryles? X on 27 Other Surveys in Which included Yos I Visible Irom Yes X 14 District 11 Part of Estab Yes !! Public Road? Potent'l? No X No I Hist Dist? NO M Distance from and 15 Name of Established District Frontage on Road 20 feet 42 Further Description of Important Features Primary facade is dominated by wide Other Namers gable with overhanging boxed cornice supported by brackets. First story has veranda across facade, with gable and cornice echoing that of the house. Veranda gables filled with 6 lightswindows, primary Photo entrance has door with 8 lights and sidelights. It is balanced by a triple window to the left, with upper sashes of leaded panes. Assymetrical second story has similar windows. A triple window over 4) History and Supulcance Dr. Marvin Grimes built this house in 1918. He lived there until he was in his 80's. In 1896, young Dr. Grimes, a graduate of Old Missouri Medical College of St. Louis came to Hardin and began his practice as a physician. His equipment consisted of a diploma and a medicine case filled mostly with a large supply of Juinine. Dr. Grimes was born Sept. 13, 1868 near Milville, Mo, 10 miles north of Hardin. On March 21, 1950 Dr. Grimes was 44 Description of Environment and Outbuildings In a Residnetal section. Garage (Wood Shed) to rear. 5 Sources of Information 46 Prepared by Mary Hogan Mrs. Paul W. Grimes Allen Rhodes- on-site inspection 47 Organization RCHS &


#42 Con't entrance.Lower story covered with clapboarding, upper story, painted dark brown, with shingles. Interior has 2 staircases to upper floor and fireplace in living room.

#43 Con't honored at the Hardin Methodist Church for his 54 years of Service. He died September 7, 1952, just prior to his 84th birthday, after 56 years of practice. He and Mrs. Grimes adopted a son. His widow is the present owner.





10/78



FLOORPLANS

NOT TO SCALE



**PHOTOGRAPH** 

#43. Cont. The Masonic Lodge dissolved and the third floor was sold to Hardwick and from him to Falls. F modern apartments were built on that floor, with storage space on the north side of the bailding. False ceilings and new flooring were installed on all floors. There is an outside enclosed stairway to the third floor, a freight elevator on the north side that descends to the basement and to the third floor. Present owner has replaced third floor windows with steel and aluminum sashes.




RA -AS 002 019

48 Date 5/79

49 Revision Date(s)

69	4 Present Name(s)			
County	Tommy Wollard Residence	Tommy Wollard Residence		
Ray	5 Other Namo(s)			
RCHS & M	Reed Wollard Residence	ce		
Specific Lucation	16 Thematic Category	28 No of Stories 21/5		
6 3 - 7 - 2 - 3 -	030	29. Basement? Ye.		
525 T53N 26	Tir Deldier of Feriod	No		
	1918 Ship & Vicinity 18 Style or Design	30. Foundation Material		
ic Hardin		concrete		
Sile Plan with North Arrow	Neoclassic  19. Architect or Engineer	31. Wall Construction		
N		frame.  32. Roof Type & Material		
	20. Contractor or Builder	Posh hin w/dormers-comp		
<b>A</b>	Tinsley	33. No. of Bays		
9	21. Original Use, if apparent residence	1/2 1/2		
	22 Present Use	34. Wall Treatment weatherboarding		
	residence	24 81 81		
	23 Ownership	Public 1 : 36. Changes Addition		
· WIII		Private M (Explain Altered		
	3 aut 24. Owner's Name & Address			
Coordinates UTM	Vaughn Wollard	37 Condition recgood		
Lat	Hardin, Missouri			
Long	25. Open to			
Site 1 i	Structure 1 : Public?	No lxi Underway? No		
On National Yes I 12 ts	Object 1 1 26. Local Contact Person or	Organization 39 Endangered? Yes		
		By What? No		
Part of Estab Yes II 14. Di	27. Other Surveys in Which I			
11	lent'l? No I X	40. Visible from Yes Public Road? No		
Name of Established District		Public Hoad? No		
		Frontage on Road		
Further Description of Importan				
leoclassic house featur shingled dormers. Two story. Singleleaf entr	es weatherboarded first and seco projecting bays on primary facad ance flanked by irregularly spac	de at second ced windows.		
	, all 1-over-1 light sashes. Bo			
ind plain trieze. Dorm	ers feature molding on cornice w d lunettes in the center of thei	vith returns,		
ightning rods remain	Porch with Tuscan collonettes w	wrans around (cont)		
History and Significance	be eith housed and the surrent	one was built in 1918. It was owned		
by Samuel Pugh and wife rented the farm since l	Lva, and left to mis daughter A	Alice in 1941. Present occupants ha		
Description of Environment and	Out to the			
and inemining to Environment and	Outpulldings .			
Several outbuildings in	good condition. Picket fence s	surrounds the property.		
Sources of Information				
		46. Prepared by		
augin worldru				
aughn Wollard resent Occupants		Clara Allison  47 Organization		

#42. Cont. primary and north facades. Interior has one fireplace, hardwood floors, and eight rooms, and entrance hall. Carbide lights remain. #36: Very few alterations to the house. A bathroom and water were added in 1955.



FLOORPLANS

NOT TO SCALE




PHOTOGRAPH



**48. Date** 49 Revision Date(s) 9/26/78

RA-AS-002-021

Nii 83	4 Present Name(s)	
inty	Mr. & Mrs. Harlen Dean, Hardin, Mo	4
Rav	5 Other Name(s)	
Location of Negatives	Paul Rankin	
RCHS & M	16 Themalic Calegory	28. No. of Stories 2
Sec.8 Twp	52 Range26 6 630	29. Basement? Yes XI
4 miles north of Hard	in on State 17 Dale(s) or Period	Full No.
Road A	1923	30. Foundation Material
City or Town Il Rural, Town	ship & Vicinity 18 Style or Design	concrete U5
Rural, Hardin		31. Wall Construction Wu
Site Plan with North Arrow	19. Architect or Engineer	132. Roof Type & Material
1/	unknown  20. Contractor or Builder	Med. hip-asphalt shingles
	Paul Rankin	33 No of Bays
	21. Original Use, if apparent	Front NA Side Na
10	residence (F)	34. Wall Treatment
9	22 Present Use	weatherboard 3/
	residence	35. Plan Shape square
	23 Ownership Public !!	36. Changes Addition : (Explain Altered )
	24. Owner's Name & Address,	in #42) Moved
	il known	37. Condition
Coordinates UTM	Mr. & Mrs. Harlen Dean	Interior good
Lal	RR 1 Hardin, Mo	Exterior good
Long	25. Open to Yes ! !	38. Preservation Yes
Site ! i	Structure 1: Public? No Po	Underway? No 🖟
Building (s)	Object 1 26. Local Contact Person or Organization	39. Endangered? Yes !!  By What? No X
On National Yes 11 12. Is Register? No X El	II Yes Maria 27. Other Surveys in Which Included	
Part of Estab Yes II 14. D	istrict Yes I I other Surveys in Which included	40. Visible from Yes ℜ Public Road? No 1:
5 Name of Established District		41. Distance from and
		Frontage on Road
		72 ft.
2 Further Description of Importar	of Features nclosed and some windows added. The house	
has been painted in the		
noo been parifect in o	ic Tabo Jear,	
		Photo
History and Significance Mr.	Dean came from the east part of the state and	d Mrs. Dean from
Tennessee. Mrs. Dean	has spent most of her life in Ray County. Mr	. Dean came in 1930 and
bought the farm and r	aises stock and field crops. They have two cl	hildren, the daughter
lives in Kansas City	and the son is superintendent of the Hardin-Co	entral School.
Description of Environment and	Outbuildings The house is surrounded by beauti	ful trees and has a wall
kept lawn. The outhur	ildings, in good condition, are located in a	
		and the state of the mouse.
		•
Sources of Information		46. Prepared by
Mr. & Mrs. Harlen Dea	n	Mr. & Mrs. Marvin Holsinge:
on site inspection		47. Organization
		RCHS & M



FLOORPLANS


NOT TO SCALE



PHOTOGRAPH



17 City or Tope, JI Rural, Township & Vicinity 19 Style or Design 19 Architect or Engineer 19 Architect or Engineer 10 Architect or Engineer 11 Architect or Engineer 12 Architect or Engineer 13 No. of Bays 14 Nouncation or Builder 15 Architect or Engineer 16 Contractor or Builder 17 Architect or Engineer 18 Style Play with North Arrow 19 Architect or Engineer 19 Architect or Builder 19 Architect or Builder 19 Architect or Builder 10 Architect or Builder 10 Architect or Builder 10 Architect or Builder 11 Architect or Builder 12 Architect or Builder 13 No. of Bays 13 No. of Bays 14 Awall Treatment 12 Individual X Wall Teatment 12 Architect or Builder 19 Architect or Builder 10 Architect or Builder 10 Architect or Builder 10 Architect or Builder 11 Architect or Builder 12 Architect or Builder 13 No. of Bays 13 No. of Bays 14 Awall Treatment 12 Individual X Wall Teatment 12 Architect or Builder 13 No. of Bays 14 Architect or Builder 13 No. of Bays 15 Plan Shape I Shape 15 Architect or Builder 17 Architect or Builder 18 Architect or Builder 19 Architect or Builder 10 Architect or Builder 11 Architect or Builder 12 Architect or Builder 13	, 8	5 4 90	esent Name(s)	
Lone Prine Farm   Lone Prine Farm	County			
Specific Luration   STT TSO N   34.00   18   Themstic Category   17   Davisty or Period   18   Style for Design   18   Style for Design   18   Style for Design   19   Architect for Engineer   19   Architect for Eng				
To National Yes 1 12 is 11 Object 1 10 National Yes 1 Is 11 Is	RCHS & N	1	Lone Pine Farm	
17 Dates of Period 22 18 Site or Design Next Site of Design Next Site of Design Next Site or Design Next S	6 Specific Lucation		16 Thematic Calegory	26 No of Stories two 2-
Ca. 1890  Ca. 18	517 T52N	3610		29. Basement? Yes II
Cuty or Taggr.   Burst. Township & Vicinity   Vic. Harding   Street   Str	Hury. A			Νοχ
Solution	Vic. Hardin		18 Style or Design	
Distance from year   10 Content Person or Organization   10 Content Person   10 Content Person or Organization   10 Content Person   10 Content Person or Organization   10 Content Person   10 Content Person or Organization   10 Content Person   10 Content Person organization   10 Content Person organiza			Neoclassic 40 07	31. Wall Construction
20 Contractor of Builder  Information  21 Original Use, if apparent resi dence DIA  22 Present Use residence 23 Ownership  Public 1 Private XX  24 Owner's Name & Address, if known  25 Open to Yes 11  Long  Site 11 Object 11  26 Open to Yes 11  10 Open to Yes 11  11 On National Yes 11  12 Is II Yes 12  13 No. X  14 Description of Important Features  Neoclassic house has been remodelled several times. Central entrance on primary facade priginally was south facade, but was changed to from the road. Many windows have had their positions changed. Cornice is molded and has plain frieze/ Both continue on secondary facades to form pediment. #36: Two additions to rear, side porch post replace with apples, peaches, apricots, and pecanttrees. Rust awas the first in the (cont)  40 Description of Environment and Outbuildings  On a working farm with modern outbuildings.  10 Control Building X  11 Original Use, if apparent residence  23 Ownership  Provided X  24 Owner's Name & Address, if known  15 Open to Yes 11  16 Open to Yes 11  17 Original Use, if apparent residence  26 Ownership  18 Open to Yes 11  27 Other Surveys in Which Included  28 Preservation Yes 12  29 Endangerd Yes 13  20 Endangerd Yes 13  20 Endangerd Yes 13  20 Endangerd Yes 14  21 Other Surveys in Which Included  30 Visible from Yes 14  40 Visible from Yes 14  40 Visible from Yes 15  41 Distance from and Frontage on Road  42 Further Description of Important Features  Neoclassic house has been remodelled several times. Central entrance on primary facade originally was south facade, but was changed to from the road of the roa	B Site Plan with North A	llow .		
School   Structure   Structure   Structure   Sundament   Sundame	THE THE	A)	20. Contractor or Builder	
residence OiA  22 Present Use residence OiA  33 Wall Treatment Clamboard  35 Plan Shape   Shap	11, 11T		unknown	33. No. of Bays
22 Person Use residence 23 Ownership Public! Private/XX 24 Owner's Name & Address. It known  Building (X) Structure: Object   10 Owner's Name & Address. It known  Building (X) Structure: Object   10 Owner's Name & Address. It known  Building (X) Structure: Object   10 Owner's Name & Address. It known  Building (X) Structure: Object   12 Is II Potentil? No. I   12 Is II Potentil? No. I   14 District Yes I   Potentil? No. I   15 Is II Potentil. No. I		1/1/2010	21. Original Use, If apparent	
residence  23 Ownership Public: Private Address. It known Edward L. Rust Hardin, Missouri Esteror excellent Esteror exce		7////		
23 Ownership Private XX 24 Owner's Name & Address.  14 Nown Standing X  25 Owner's Name & Address.  15 Nown Standing X  26 Owner's Name & Address.  16 Nown Standing X  27 Owner's Name & Address.  18 Nown Standing X  28 Owner's Name & Address.  19 Owner's Name & Address.  10 Owner's Name & Address.  11 Nown Standing X  26 Owner's Name & Address.  18 Nown Standing X  27 Owner's Name & Address.  18 Nown Standing X  28 Owner's Name & Address.  19 Owner's Name & Address.  10 Owner's Name & Address.  11 Nown Standing X  29 Condition Standing S	VIII			as all large
Private XX  24. Owner's Name & Address.  15. Normational Vesting in 842 of the Normation of				L SHADE
Conditional established District   Content Positions   Control enterior   Content Positions   Control enterior   Control ente	-	77.7.		(Explain lered)
Bedward L. Rust Hardin, Missouri    Edward L. Rust Hardin, Missouri   25 Open to   26 Local Contact Person or Organization   26 Local Contact Person or Organization   27 Mox   28 Local Contact Person or Organization   28 Endangered?   28 Mox   27 Other Surveys in Which Included   28 Endangered?   27 Mox   28 Local Contact Person or Organization   29 Mox	* *	•		27 Condition
Site of the public of Structure is Building ix Object is Building ix Pess it Building ix Poss it Building ix Poss it Building ix Poss it Building ix Object is Building ix Object ix Object is Building ix Object ix	9 Coordinates	UTM	Edward L. Rust	
Site 1 Structure 1 Object 1 Ob			Hardin, Missouri	Exterior excellent
Building y Object 1 On National Yes 1 12 Is It Yes 1   12 Is It Flightle? No 1   12 Is It Flightle? No 1   12 Is It Flightle? No 1   14 District Yes 1   15 Hist Dist.? No 1   14 District Yes 1   15 Hist Dist.? No 1   15 Name of Established District   15 Name of Established District   15 Name of Established District   16 District Yes 1   16 District Yes 1   17 District Yes 1   18 Dist.? No 1   19 District Yes 2   19 Distric		<u> </u>	0	
Register? No.X.    12 Is It   Yes Xi   Eligible? No.IT   Potenti? No.IT   Potenti? No.X.   14 District   Yes Xi   Potenti? No.X.     15 Name of Established District     16 Name of Established District     17 District   Yes Xi   Potenti? No.X.     18 Name of Established District     19 Name of Established District     10 District   Yes Xi   Potenti? No.X.     10 District   Yes Xi   Potenti? No.X.     11 District   Yes Xi   Potenti? No.X.     12 Further Description of Important Features     13 Name of Established District     14 District   Yes Xi   Public Road?     15 Name of Established District     16 Name of Established District     17 District   Yes Xi   Public Road?     18 District   Yes Xi   Public Road?     19 District   Yes Xi   Public Road?     10 District   Yes Xi   Public Road?     11 District   Yes Xi   Public Road?     12 District   Yes Xi   Public Road?     13 District   Yes Xi   Public Road?     14 District   Yes Xi   Public Road?     15 Name of Established District     16 District   Yes Xi   Public Road?     17 District   Yes Xi   Public Road?     18 District   Yes Xi   Public Road?     19 District   Yes Xi   Public Road?     10 Distr			W XX	
3 Part of Estab Yes]: Hist Dist.? No.X: Hist Dist.? No.X: 14 District 15 Name of Established District 16 Further Description of Important Features  Neoclassic house has been remodelled several times. Central entrance on primary facade flanked with windows and two windows above. Appears primary facade originally was south facade, but was changed to front the road. Many windows have had their positions changed. Cornice is molded and has plain frieze/ Both continue on secondary facades to form pediment. #36: Two additions to rear, side porch post replace with concrete. (cont)  3 History and Significance 3 History and Significance 3 History and Significance 4 District Many of the house ca. 1890. At the time there were many varieties of trees on the land, but a single pine was outstanding so the farm was named Lone Pine Farm. The pine tree is extant. North of the house was a large orchard with apples, peaches, apricots, and pecanttrees. Rust awas the first in the (cont)  4 Description of Environment and Outbuildings  On a working farm with modern outbuildings.  5 Sources of Information  Troy Rust, son of owner.  Ray County History, L1973	<b>**</b>			
Neoclassic house has been remodelled several times. Central entrance on primary facade flanked with windows and two windows above. Appears primary facade originally was south facade, but was changed to front the road. Many windows have had their positions changed. Cornice is molded and has plain frieze/ Both continue on secondary facades to form pediment. #36: Two additions to rear, side porch post replace with concrete. (cont)  3 History and Symmicance  Jacob Jackson Rust, born 1865 in Lacey Springs, Virginia, built the house ca. 1890. At the time there were many varieties of trees on the land, but a single pine was outstanding so the farm was named Lone Pine Farm. The pine tree is extant. North of the house was a large orchard with apples, peaches, apricots, and pecanttrees. Rust awas the first in the (cont)  4 Description of Environment and Outbuildings  On a working farm with modern outbuildings  On a working farm with modern outbuildings  Afermation  Troy Rust, son of owner.  Ray County History, L1973	Λ			
Neoclassic house has been remodelled several times. Central entrance on primary facade flanked with windows and two windows above. Appears primary facade flanked with windows and two windows above. Appears primary facade originally was south facade, but was changed to front the road. Many windows have had their positions changed. Cornice is molded and has plain frieze/ Both continue on secondary facades to form pediment. #36: Two additions to rear, side porch post replace with concrete. (cont)  13 History and Significance  Jacob Jackson Rust, born 1865 in Lacey Springs, Virginia, built the house ca. 1890. At the time there were many varieties of trees on the land, but a single pine was outstanding so the farm was named Lone Pine Farm. The pine tree is extant. North of the house was a large orchard with apples, peaches, apricots, and pecanttrees. Rust awas the first in the (cont)  4 Description of Environment and Outbuildings  On a working farm with modern outbuildings.  5 Sources of Information  Troy Rust, son of owner.  Ray County History, L1973  46 Prepared by Camperon  47 Organization RCHS & M  48 Date 49 Revision Date(s)	Hist Dist.? NoX			
Neoclassic house has been remodelled several times. Central entrance on primary facade flanked with windows and two windows above. Appears primary facade originally was south facade, but was changed to front the road. Many windows have had their positions changed. Cornice is molded and has plain frieze/ Both continue on secondary facades to form pediment. #36: Two additions to rear, side porch post replace with concrete. (cont)  3 History and Significance  Jacob Jackson Rust, born 1865 in Lacey Springs, Virginia, built the house ca. 1890. At the time there were many varieties of trees on the land, but a single pine was outstanding so the farm was named Lone Pine Farm. The pine tree is extant. North of the house was a large orchard with apples, peaches, apricots, and pecanttrees. Rust awas the first in the (cont)  4 Description of Environment and Outbuildings  On a working farm with modern outbuildings.  46 Prepared by Camperon RCHS & M  47 Organization RCHS & M  48 Date 49 Revision Date(s)	15 Name of Established D	District	1	
Neoclassic house has been remodelled several times. Central entrance on primary facade flanked with windows and two windows above. Appears primary facade originally was south facade, but was changed to front the road. Many windows have had their positions changed. Cornice is molded and has plain frieze/ Both continue on secondary facades to form pediment. #36: Two additions to rear, side porch post replace with concrete. (cont)  3 History and Significance  Jacob Jackson Rust, born 1865 in Lacey Springs, Virginia, built the house ca. 1890. At the time there were many varieties of trees on the land, but a single pine was outstanding so the farm was named Lone Pine Farm. The pine tree is extant. North of the house was a large orchard with apples, peaches, apricots, and pecanttrees. Rust awas the first in the (cont)  4 Description of Environment and Outbuildings  On a working farm with modern outbuildings.  5 Sources of information  Troy Rust, son of owner.  Ray County History, L1973  46. Prepared by Cameron  A7 Organization RCHS & M  48 Date 49 Revision Date(s)				Frontage on Road
on primary facade flanked with windows and two windows above. Appears primary facade originally was south facade, but was changed to front the road. Many windows have had their positions changed. Cornice is molded and has plain frieze/ Both continue on secondary facades to form pediment. #36: Two additions to rear, side porch post replace with concrete. (cont)  3 History and Significance  Jacob Jackson Rust, born 1865 in Lacey Springs, Virginia, built the house ca. 1890. At the time there were many varieties of trees on the land, but a single pine was outstanding so the farm was named Lone Pine Farm. The pine tree is extant. North of the house was a large orchard with apples, peaches, apricots, and pecanttrees. Rust awas the first in the (cont)  Description of Environment and Outbuildings  On a working farm with modern outbuildings.  46. Prepared by Camperon  Troy Rust, son of owner.  Ray County History, L1973  47. Organization RCHS & M  48. Date 49 Revision Date(s)	42 Further Description of	Important Features		
on primary facade flanked with windows and two windows above. Appears primary facade originally was south facade, but was changed to front the road. Many windows have had their positions changed. Cornice is molded and has plain frieze/ Both continue on secondary facades to form pediment. #36: Two additions to rear, side porch post replace with concrete. (cont)  3 History and Significance  Jacob Jackson Rust, born 1865 in Lacey Springs, Virginia, built the house ca. 1890. At the time there were many varieties of trees on the land, but a single pine was outstanding so the farm was named Lone Pine Farm. The pine tree is extant. North of the house was a large orchard with apples, peaches, apricots, and pecanttrees. Rust awas the first in the (cont)  Description of Environment and Outbuildings  On a working farm with modern outbuildings.  46. Prepared by Camperon  Troy Rust, son of owner.  Ray County History, L1973  47. Organization RCHS & M  48. Date 49 Revision Date(s)	Neoclassic house h	as been remodell	ed several times Contral enture	
primary facade originally was south facade, but was changed to front the road. Many windows have had their positions changed. Cornice is molded and has plain frieze/ Both continue on secondary facades to form pediment. #36: Two additions to rear, side porch post replace with concrete. (cont)  Wistory and Suppriscance  Jacob Jackson Rust, born 1865 in Lacey Springs, Virginia, built the house ca. 1890. At the time there were many varieties of trees on the land, but a single pine was outstanding so the farm was named Lone Pine Farm. The pine tree is extant. North of the house was a large orchard with apples, peaches, apricots, and pecanttrees. Rust awas the first in the (cont)  Description of Environment and Outbuildings  On a working farm with modern outbuildings.  **County History, L1973**  46. Prepared by Cameron and Outbuildings  47. Organization RCHS & M  48. Date 49. Revision Date(s)	on primary facade	flanked with win	idows and two windows above. Annea	e
molded and has plain frieze/ Both continue on secondary facades to form pediment. #36: Two additions to rear, side porch post replace with concrete. (cont)  3 History and Significance  Jacob Jackson Rust, born 1865 in Lacey Springs, Virginia, built the house ca. 1890. At the time there were many varieties of trees on the land, but a single pine was outstanding so the farm was named Lone Pine Farm. The pine tree is extant. North of the house was a large orchard with apples, peaches, apricots, and pecanttrees. Rust awas the first in the (cont)  4 Description of Environment and Outbuildings  On a working farm with modern outbuildings.  5 Sources of Information  Troy Rust, son of owner.  Ray County History, L1973  46 Prepared by Camperon  47 Organization RCHS & M  48 Date 49 Revision Date(s)	primary facade ori	ginally was sout	h facade, but was changed to front	Photo
form pediment. #36: Two additions to rear, side porch post replace with concrete. (cont)  13 History and Supplicance  Jacob Jackson Rust, born 1865 in Lacey Springs, Virginia, built the house ca. 1890. At the time there were many varieties of trees on the land, but a single pine was outstanding so the farm was named Lone Pine Farm. The pine tree is extant. North of the house was a large orchard with apples, peaches, apricots, and pecanttrees. Rust awas the first in the (cont)  14 Description of Environment and Outbuildings  15 Sources of Information  16 Prepared by Camperon  17 Organization RCHS & M  18 Date 19 Revision Date(s)	the road. Many wi	ndows have had t	heir positions changed. Cornice i	s
Jacob Jackson Rust, born 1865 in Lacey Springs, Virginia, built the house ca. 1890. At the time there were many varieties of trees on the land, but a single pine was outstanding so the farm was named Lone Pine Farm. The pine tree is extant. North of the house was a large orchard with apples, peaches, apricots, and pecanttrees. Rust awas the first in the (cont)  Description of Environment and Outbuildings  On a working farm with modern outbuildings.  Sources of Information  Troy Rust, son of owner.  Ray County History, L1973  46. Prepared by Cameron  Ar Organization RCHS & M  48 Date 49 Revision Date(s)	molded and has pla	in frieze/ Both	continue on secondary facades to	A STATE OF THE STA
Jacob Jackson Rust, born 1865 in Lacey Springs, Virginia, built the house ca. 1890. At the time there were many varieties of trees on the land, but a single pine was outstanding so the farm was named Lone Pine Farm. The pine tree is extant. North of the house was a large orchard with apples, peaches, apricots, and pecanttrees. Rust awas the first in the (cont)  4 Description of Environment and Outbuildings  On a working farm with modern outbuildings.  5 Sources of Information  Troy Rust, son of owner.  Ray County History, L1973  46 Prepared by Camperon  47 Organization RCHS & M  48 Date 49 Revision Date(s)	43 History and Significance	e Iwo addictions	to rear, side porchi post replace	with concrete. (cont)
time there were many varieties of trees on the land, but a single pine was outstanding so the farm was named Lone Pine Farm. The pine tree is extant. North of the house was a large orchard with apples, peaches, apricots, and pecanttrees. Rust awas the first in the (cont)  Description of Environment and Outbuildings  On a working farm with modern outbuildings.  Sources of Information  Troy Rust, son of owner.  Ray County History, L1973  46. Prepared by Camperon  A7. Organization RCHS & M  48. Date 49. Revision Date(s)			acov Springs Vinginia built the	house on 1900. At the
the farm was named Lone Pine Farm. The pine tree is extant. North of the house was a large orchard with apples, peaches, apricots, and pecanttrees. Rust awas the first in the (cont)  Description of Environment and Outbuildings  On a working farm with modern outbuildings.  Sources of Information  Troy Rust, son of owner.  Ray County History, L1973  46. Prepared by Camperon  Camperon  47 Organization RCHS & M  48 Date 49 Revision Date(s)	time there were ma	nv varieties of	trees on the land, but a single ni	ne was outstanding so
Orchard with apples, peaches, apricots, and pecanttrees. Rust awas the first in the (cont)  4 Description of Environment and Outbuildings  On a working farm with modern outbuildings.  5 Sources of Information  Troy Rust, son of owner.  Ray County History, L1973  46 Prepared by Cameron  47 Organization RCHS & M  48 Date 49 Revision Date(s)	the farm was named	l Lone Pine Farm.	The pine tree is extant. North	of the house was a large
On a working farm with modern outbuildings.  Sources of Information  Troy Rust, son of owner.  Ray County History, L1973  46. Prepared by Cameron  47. Organization RCHS & M  48. Date 49. Revision Date(s)	orchard with apple	s, peaches, apri	cots, and pecanttrees. Rust awas	the first in the (cont)
Troy Rust, son of owner.  Ray County History, L1973  46. Prepared by Cameron  47. Organization RCHS & M  48. Date 49. Revision Date(s)	14 Description of Environm	nent and Outbuildings		
Troy Rust, son of owner.  Ray County History, L1973  46. Prepared by Cameron  47. Organization RCHS & M  48. Date 49. Revision Date(s)	On a working farm	with modern outh	uildings.	
Troy Rust, son of owner.  Ray County History, L1973  A7 Organization RCHS & M  48 Date 49 Revision Date(s)				
Troy Rust, son of owner.  Ray County History, L1973  A7 Organization RCHS & M  48 Date 49 Revision Date(s)	Sources of Information			
Ray County History, L1973  47 Organization RCHS & M  48 Date 49 Revision Date(s)		owner		46. Prepared by Cameron
RCHS & M  48 Date 49 Revision Date(s)				47 Organization
	Ray County History	, L19/3		RCHS & M
				48 Date 49 Revision Date(s) 8/80



FLOORPLANS

NOT TO SCALE



PHOTOGRAPH

- 42. Cont. The house has one original fireplace. It was remodelled in 1902 and again in 1920.
- #43. Cont. community to build an ice house. The farm and house Mare now Mowned by Jacob Rust's grandson.



1 Nii 98	resent Name(s)	
Ray 5 C	Early-Residence Diner Name(s)	
6 Specific Location ( miles north of Hardin on State, Route A, then East 2 miles on state Road AA ec. 35 Twp. 53 Range 26 7 City or Town H Rural, Township & Vicini Hardin Vic. H Site Plan with North Arrow		28. No. of Stories  29. Basement?  Partial  30. Foundation Material  Masonry Block  31. Wall Construction  frame  32. Roof Type & Material  Gable-asphalt shingles  33. No. of Bays  Front 3 Side 3 M2  34. Wall Treatment  weatherboard  35. Plan Shape square  36. Changes  (Explain  in #42)  Moved i
Coordinates  t at t ong  Site !   Structure   Building M Object  National Yes !   12. Is It Yes pister? No IX Eligible? No	26. Local Contact Person or Organization	37. Condition Interior Good  Exterior Good  38. Preservation Yes Underway? No X  39. Endangered? Yes II By What? No X
Part of Estab Yes   14. District Yes   15. District Yes   Potent'l? No   15. Name of Established District	X Oner Surveys III Which included	40. Visible from Yes X No 1:  41. Distance from and Frontage on Road  50 feet
the house. Back porch was enc	Typical bungalow, with shed dormers. and modernized since the owner bough losed.	Photo
	ol was originally across the road fr rented rooms to teachers that did "l	


44 Description of Environment and Outbuildings

Large yard. Garage to the rear.

45 Sources of Information

Mr. & Mrs. Floyd Early- on site inspection

46. Prepared by Mr. & Mrs. Holsinger 47. Organization RCHS & M 48. Date 49 Revision Date(s)



FLOORPLANS


NOT TO SCALE



PHOTOGRAPH



77	Foster Farm Home	
ounty Ray		
Location of Menutives	Namo(s) B.G. Minnick Residence	
Specific Lucation	16 Thematic Calegory	
5 miles northeast of Hardan	030	26 No of Stories one
Hwy.E	17 Datu(s) or Period	29. Basement? Yes III
57T52N 26W	ca. 1890	30. Foundation Material
City or Town If Rural, Township & Vicinity Hardin Vic. Morton community	Queen Anne/Neoclassic 45	ashlar stone 40
	19. Architect or Engineer Other	31. Wall Construction
, 111	unknown 63 30	32. Roof Type & Material
CELLAR	O. Contractor or Builder	cross gable/comp. shir
	unknown 21. Original Use, If apparent	33. No. of Bays Front 5 Side 1
SHOP	residence OIA	34. Wall Trealment,
- [ ]	22 Present Use	clapboard
	residence	35. Plan Shape rectangular
BARA	23 Ownership Public 11	36 Changes Addition . ·
	Private XX 24. Owner's Name & Address.	(Explain Altered or in #42) Moved
TSHED T	il known Barb A. Foster	37 Condition
Coordinates UTM	Morton, Missouri	Interior good
Lunu		Exterior good
Site 1   Structure 1	Public? Yes I i	38. Preservation Yes Underway? No X
Building X	6 Local Contact Person or Organization	
On National Yes II 12 Is II Yes M		By What? Yes !!
	7. Other Surveys in Which Included	
Hist Dist.? No IX Potent'!? No IX		40. Visible from Yes X
Name of Established District		Public Road? No
		Frontage on Road
Further Description of Important Features		
Unspoiled, with the exception of t	he removal of porch on primary	
facade. Gables decorated with fan	cy butt shingles. Cornice	
continues on secondary facades to lome-over-one with molded window h	form pediments. Fenestration is	
to give Neoclassic flavor to the h	ouse with its Queen Anne magging	Photo
Prominent projecting polygonal bay	on primary afacade.	
History and Significance		
Description		
Description of Environment and Outbuildings		
Root cellar, frame shop on temant	quarters and period barn remain.	Recent metal
Description of Environment and Outbuildings Roet cellar, frame shop on tenant implement shed and frame hen house	quarters and period barn remain. in association. Rural environme	Recent metal
Root cellar, frame shop on tenant	in association. Rural environme	nt.
implement shed and frame hen house	in association. Rural environme	nt.  46. Prepared by
Root cellar, frame shop on tenant implement shed and frame hen house  Sources of Information	in association. Rural environme	46. Prepared by Jim Pease
Root cellar, frame shop on tenant implement shed and frame hen house  Sources of Information	in association. Rural environme	nt.  46. Prepared by




FLOORPLANS

NOT TO SCALE





2 County	09	sent Name(s)	
		Fould Property	
Ray	5 OII	ner Namo(s)	
RCHS &	M		
6 Specific Lucation	43	16 Thematic Calegory	28 No of Stories two
24 5/N 271	2	17 Date(s) or Period	29. Basement? Yes
twy. J		ca. 1880	30. Foundation Material
7 City or Town II Ru	ral, Township & Vicinity	18 Style or Design	ashlar stone 40
vic. Hardin S Sile Plan with North A	WOW A	vernacular Neoclassic details	31. Wall Construction
	, 3	unknown	frame WU.  32. Roof Type & Material GB
( )	- ()	20. Contractor or Builder	Lsaltbox-wood shingle
W		unknown 21. Original Use, if apparent	33. No. of Bays Front A Side 2
		residence OIA	34. Wall Treatment
		22 Present Use	weatherboard 2/
(3)	()	Vacant 23 Ownership Public !!	35. Plan Shape rectangula
1 6		Private X I	36. Changes Addition (Explain Altered
6,3	-0-	24. Owner's Name & Address,	in #42) Moved
Coordinates	UTM	L.K. Fould	37 Condition poor
Lat		Hardin, Missouri	Exterior fair
Lony		25 Open to Yes I I	38. Preservation Yes
Site 1 i Building i k	Structure 1 : Object 1 :	Public? No XX  26 Local Contact Person or Organization	Underway? No
1 On National Yes II	12 Is II Yes Ix	20 Local Collect Person of Organization	39 Endangered? Yes By What? No
Register? No X.	Eligible? No i i	27. Other Surveys in Which Included	neglect
Hist Dist.? No XI	14. District Yes I Potent'l? No lx		40. Visible from Yes Public Road? No
5 Namu of Established [	District		41. Distance from and
			Frontage on Road
2 Further Description of	Important Features		
2 Further Description of Vernacular house		Neoclassic details of facades inc	lude
Vernacular house pilaster corner b	is in dis <b>cep</b> air. oards, molded lin	tels of windows and doors, boxed	ude
Vernacular house pilaster corner be cornice and frieze	is in dis <b>ce</b> pair. oards, molded lin e. Double pen ty	tels of windows and doors, boxed pe house has two entrances on	ude
Vernacular house pilaster corner be cornice and frieze primary facade. #42: No alteration	is in dis <b>cep</b> air. oards, molded lin e. Double pen ty Unusual for Ray C ns except removal	tels of windows and doors, boxed pe house has two entrances on ounty is the Saltbox roof type. of chimneys. But house is	
Vernacular house pilaster corner be cornice and frieze primary facade. #42: No alteration	is in dis <b>cep</b> air. oards, molded lin e. Double pen ty Unusu <b>al</b> for Ray C	tels of windows and doors, boxed pe house has two entrances on ounty is the Saltbox roof type. of chimneys. But house is	
Vernacular house pilaster corner be cornice and frieze primary facade. #42: No alteration abandonned and open	is in dis <b>ce</b> pair. oards, molded lin e. Double pen ty Unusual for Ray C ns except removal en to weather and	tels of windows and doors, boxed pe house has two entrances on ounty is the Saltbox roof type. of chimneys. But house is	
Vernacular house pilaster corner be cornice and frieze primary facade. #42: No alteration abandonned and open the corner with	is in dis <b>ce</b> pair. oards, molded lin e. Double pen ty Unusual for Ray C ns except removal en to weather and	tels of windows and doors, boxed pe house has two entrances on ounty is the Saltbox roof type. of chimneys. But house is	
Vernacular house pilaster corner be cornice and frieze primary facade. #42: No alteration abandonned and open thistory and Septimicance.	is in dis <b>ce</b> pair. oards, molded lin e. Double pen ty Unusual for Ray C ns except removal en to weather and	tels of windows and doors, boxed pe house has two entrances on county is the Saltbox roof type. of chimneys. But house is vandals.	
Vernacular house pilaster corner be cornice and frieze primary facade. #42: No alterationabandonned and open the corner was Septimental Control of the corner	is in dis <b>ce</b> pair. oards, molded lin e. Double pen ty Unusual for Ray C ns except removal en to weather and	tels of windows and doors, boxed pe house has two entrances on county is the Saltbox roof type. of chimneys. But house is vandals.	
Vernacular house pilaster corner be cornice and frieze primary facade. #42: No alteration abandonned and open thistory and Septimicand Saltbox roof type	is in dis <b>re</b> pair. oards, molded lin e. Double pen ty Unusual for Ray C ns except removal en to weather and appears nowhere	tels of windows and doors, boxed pe house has two entrances on county is the Saltbox roof type. of chimneys. But house is vandals.	
Vernacular house pilaster corner becornice and frieze primary facade. #42: No alterationabandonned and operationabandonned and operational selections and selections of type  Description of Environment on an overgrown leading to the selection of	is in discepair. oards, molded lin e. Double pen ty Unusual for Ray C ns except removal en to weather and ce appears nowhere  ment and Outbuildings ot surrounded by	tels of windows and doors, boxed pe house has two entrances on county is the Saltbox roof type. of chimneys. But house is vandals.  else in Ray County.  farmland. Lot used now for farm ma	Photo
dernacular house bilaster corner becornice and frieze primary facade.  442: No alteration abandonned and operations and Significant fallows roof type  Description of Environment and overgrown leading to the second state of the	is in discepair. oards, molded lin e. Double pen ty Unusual for Ray C ns except removal en to weather and ce appears nowhere	tels of windows and doors, boxed pe house has two entrances on county is the Saltbox roof type. of chimneys. But house is vandals.  else in Ray County.  farmland. Lot used now for farm ma	Photo
Vernacular house bilaster corner becomice and frieze orimary facade. #42: No alteration abandonned and operations and Septimental Saltbox roof type  Description of Environmental Control of Environmental Planting	is in discepair. oards, molded lin e. Double pen ty Unusual for Ray C ns except removal en to weather and ce appears nowhere  ment and Outbuildings ot surrounded by	tels of windows and doors, boxed pe house has two entrances on county is the Saltbox roof type. of chimneys. But house is vandals.  else in Ray County.  farmland. Lot used now for farm ma	chinery storage.
Vernacular house pilaster corner be cornice and frieze primary facade. #42: No alteration abandonned and operation and September 10 Description of Environment on an overgrown 10 Original planting Sources of Information	is in discepair. oards, molded lin e. Double pen ty Unusual for Ray C ns except removal en to weather and ce appears nowhere  ment and Outbuildings ot surrounded by trees still exta	tels of windows and doors, boxed pe house has two entrances on county is the Saltbox roof type. of chimneys. But house is vandals.  else in Ray County.  farmland. Lot used now for farm ma	chinery storage.
Vernacular house pilaster corner be cornice and frieze primary facade. #42: No alteration abandonned and operation and September 10 Description of Environment of an overgrown 10 Original planting Sources of Information	is in discepair. oards, molded lin e. Double pen ty Unusual for Ray C ns except removal en to weather and ce appears nowhere  ment and Outbuildings ot surrounded by trees still exta	tels of windows and doors, boxed pe house has two entrances on county is the Saltbox roof type. of chimneys. But house is vandals.  else in Ray County.  farmland. Lot used now for farm ma	chinery storage.  46. Prepared by Cameron  47. Organization
Vernacular house pilaster corner be cornice and frieze primary facade. #42: No alteration abandonned and open beautiful and Significant Saltbox roof type  Description of Environment on an overgrown leading to the same of t	is in discepair. oards, molded lin e. Double pen ty Unusual for Ray C ns except removal en to weather and ce appears nowhere  ment and Outbuildings ot surrounded by trees still exta	tels of windows and doors, boxed pe house has two entrances on county is the Saltbox roof type. of chimneys. But house is vandals.  else in Ray County.  farmland. Lot used now for farm ma	achinery storage.  46. Prepared by Cameron



**FLOORPLANS** 


NOT TO SCALE



PHOTOGRAPH



1 No	A Pro	sent Namo(s)	4.6. 4.7.		
H4		Clemens Residence			
Ray	5 OIN	er Namo(s)			
3 Location of Negatives RCHS & M					
6 Specific Lucation		16 Thematic Category		28 No of Stories	71/2
111	Olive street	030		29. Basement?	
		17 Date(s) or Period		partial	Yes XX
2 64		ca. 1860 (1821 early struc	cture)	30. Foundation Ma	
7 City or Town If Rura Hardin	I, Township & Vicinity	vernacular, Gothic Revival	dotai	ASHLARS tone	
8 Site Plan with North Arr	ow	19. Architect or Engineer		frame www.	ion
7/2//	a /	unknown		32. Roof Type & N	
	N N	20. Contractor or Builder		gable-comp. :	shingles
	1	William Hughes C	B	33. No. of Bays Front	Side 1
		residence DIA		34. Wall Treatment	
-		22 Present Use		metal siding	50
		residence		35. Plan Shape T	shape
	]		blic I I	36 Changes	Addition
		24. Owner's Name & Address.	VAIGNA	(Explain in #42)	Moved i
		if known	1	37 Condition	
	TM	Mrs. Sadie Clemens 111 Olive Street, Hardin <sub>64</sub>		Interior	boop
Lat			1035	Exterior	good
Site 11	Structure 1;	25. Open to Public?	Yes I I No XX	38. Preservation Underway?	Yes
Building 1)	Object	26 Local Contact Person or Organization		39 Endangered?	Νοχ
11 On National Yes II	12 Is It Yes XI		"	By What?	Yes ! !
Register? No IX	Eligible? No 11	27. Other Surveys in Which included			
Hist Dist.? No IX	14. District Yes vi Potent'l? No fi			40. Visible from Public Road?	Yes X
15 Name of Established Di	strict			41. Distance from a	
				Frontage on Ro	ad
42 Further Description of Ir	mportant Features		-		
I-house features th	ree gable dorme	rs on front facade with cent	ral		
dormer with door, f	lanking dormers	with windows. Lower story d	isplays		
central primary ent	rance flanked by	paired windows. All efenes	tration	Photo	
spindles at porch f	rior chinmeys.	Front porch (later addition) ts and carved brackets. Upp	has	/	
lower doors have wi	ndows of stained	glass. #36: Part of house a	er and		
was constructed abo	ut same time as	main house, moved some dista	nce (co	nt.	
43 Mistory and Significance					
follows: William a	uilt January 182	1 by William and Martha Hugh	es. Ot	her owners are	as
TOTTOWS. WITH all a	na Altrea Huanes	. Jess Moran, James S Snowd	an Sr	Jonathan Sno	udon
man, Nancy Scacklef	ord and husband	Katherine Happy, Dr. A.H. Bu James H., William F. Shaw an	chanan,	James Happy,	Nacy Simmer
			u wire,	molias meanin	is (cont)
44 Description of Environme					
east porch (which h	nce used as an o as been enclosed	uthouse. The cellar is on the by glass recently). It is	he east of bric	side and has and stone.	door from
45 Sources of Information			- 1	16 Property	
Allen Rhodes				Manual II	
Sadie Clemens			1	Mary Hogan Organization	
Abstract				RCHS & M	
On-site inspection			4		ion Date(s)
			1	10/79	



FLOORPLANS

NOT TO SCALE




PHOTOGRAPH



5/20/79

1 Nu 70	4 Presi	ent Namu(s)	
3 13	Whit	e House	
Ray Ray	5 Othe	Namo(s)	
RCHS & M	Rust	House	
Specific Location		16 Thematic Category	28 No of Stories 1 1/2
		030	29. Basement? Yes X
Route 1 Hardin, Mo	CR	17 Dale(s) or Period	Partial No!.
Sec. 31 T53 R 26		CA. 1905	30 Foundation Material
City or Town II Rural, To	waship & Vicinity	18 Style or Design	Ashlar stone 10
Rockemman Vic.		Bungalow 22	31. Wall Construction Wu
Sile Plan with North Arrow			Frame 32. Roof Type & Material HP
		OCCUPATION OF THE PROPERTY OF	32. Roof Type & Material HP Hip- Shake Shingles 25
	7	unknown . PR	Maa No of Davis
100		21. Original Use, if apparent	Front 2 Side 1
		Home OIA	34. Wall Treatment
DIA	Y	22 Present Use	Clapboard 24
7/1		Home	35. Plan Shape SO
D W V		23 Ownership Public I !	36. Changes Addition :
		Private W	(Explain Altered I ! in #42) Moved I
•		24. Owner's Name & Address, if known	
		Allen and Dorothy White	37 Condition Interior Excellant
Coordinates UTM		Rt. 1 Hardin, Mo	Exterior Excellent
Lung		25 Open to Yes 11	38. Preservation Yes ×
Site 11	Structure 1 i	Public? No M	Underway? No i
Building lys	Object I I	26 Local Contact Person or Organization	39 Endangered? Yes !!
	ts It Yes M Eligible? No I I	27 Other Surveys in Which Included	By What? No 🕅
Part of Estab Yes 11 14. Hist Dist? No M	District Yes !! Potent'l? No X		40 Visible from Yes X Public Road? No :
Name of Established District			41. Distance from and
	. 1		Frontage on Road
	Ber and the late of the Property of Property		200 feet
		se features a corner porch	/-
		e with 4 colonettes. Each facade	
		aired or triple windows.	
		wild cherry, black walnut and	Photo
		m, with 2 fireplaces. #36:	
		s since its construction. It is work by the present owners.	
	preservation	work by the present owners.	1
History and Significance Ir	1902, a pre	vious house on the lot burned, a	nd three years later
		d with lumber from trees on the	
		roperty from 1860-1899, Lillie F	Rust until 1954. The
present owner purcha	ased the hous	e in 1957.	
Description of Environment a		1 1 1 1 1 1 1	
On a farm of 160 acr	res, situated	on a nigh hill.	l l
Sources of Information			46 Prepared by
Allen and Dorothy Wh	nite		Clara Allison
On-site inspection			47. Organization
			RCHS & M
			1 4 1 0 - 4 - 1 40 D 0 - 1 4 - 1



FLOORPLANS

NOT TO SCALE




PHOTOGRAPH

125%



	08 1	Present Name(s)	
County Ray	-	Doss Residence	
Rav		Other Name(s) Miles Farm	
Location of Monatives	М .		
Specific Lucation	•	16 Thernatic Category	28 No of Stories 2
		17 Date(s) or Period	29. Basement? Yes II No X.
			30 Foundation Material
T 53 R 26W	. To ask a Manual	CA. 1860	Ashlar Stone 40
Hardin, Mo R	ral, Township & Vicini	Federal 09	31. Wall Construction
		19. Architect or Engineer	Frame Wu
Site Plan with North A	1	unknown	32 Roof Type & Material
VIINIII	N	20. Contractor or Builder .	High Gable-Comp. Shing
	_ 1	unknown	33. No. of Bays
1	/h	21. Original Use, if apparent	Front NA Side NA
0		Residence	34. Wall Treatment
		22 Prosent Use	Weatherboarding  35. Plan Shape T-Shaped
	E3	Residence 23 Ownership Public	36 Changes Addition:
	(U)	Private M  24. Owner's Name & Address,	(Explain in #42) Altered Moved
		il known	37. Condition
Coordinates	UTM	Thomas & Maxine Doss	Interior Excellant
Lal		Hardin, Mo	Exterior Excellant
Lung		25. Open to Yes 11	38. Preservation Yes
Site 11	Structure		Underway? No X
Building 5/	Object	20 Local Comaci varion or organization	39 Endangered? Yes II By What? No 1/4
On National Yes II	12 Is II Yes Eligible? No		- Sy what:
Register? No X		21 Other Surveys in Winds included	40. Visible from Yes X
Part of Estab Yes !! Hist Dist? No PA	14. District Yes Potent'l? No		Public Road? No ::
Name of Established			41. Distance from and
			Frontage on Road
			1/8 mile
2 Further Description of	- 0 - 7	T-Shaped house has irregularly spa ral entranceway. There is no fenest	
indows on primary n secondary faca 36: Addition was	des. Cornice is	s bordered by undecorated friege. of a bathroom and new fireplace an	Photo
indows on primary facao n secondary facao 36: Addition was himney.	des. Cornice is added in 1979	s bordered by undecorated friege. of a bathroom and new fireplace an	Photo Photo
indows on primary facadases: Addition was himney.  3 History and Significan	des. Cornice is added in 1979	s bordered by undecorated friege. of a bathroom and new fireplace an United States Government deeded th	ne land to Williave
indows on primary facados: Addition was himney.  3 History and Sugnificant Warreu. In about	des. Cornice is added in 1979  The second of	s bordered by undecorated friege. of a bathroom and new fireplace an	ne land to Williave the house. He died
indows on primary facadas: Addition was himney.  3 History and Significant Warreu. In about 1893 and his son	des. Cornice is added in 1979  The state of	s bordered by undecorated friege. of a bathroom and new fireplace an  United States Government deeded the Miles bought the land and built to	ne land to Williave the house. He died has W. Pugh in 1906.
indows on primary facados: Addition was himney.  3 History and Significant Warreu. In about 1893 and his son	des. Cornice is added in 1979  The state of	of a bathroom and new fireplace and united States Government deeded the Miles bought the land and built to inherited the place. Sold to Thom	ne land to Williave the house. He died has W. Pugh in 1906.
indows on primary facadase: Addition was himney.  3 History and Supplicant Warreu. In about 1893 and his son Goldeu E. Pugh	des. Cornice is added in 1979  The In 1848 the the 1860 Robert Andrew Wirgil Miles inherited the property of the second s	of a bathroom and new fireplace and united States Government deeded the Miles bought the land and built to sinherited the place. Sold to Thomplace in 1964 and sold it to Harliu	ne land to Williave the house. He died has W. Pugh in 1906.
indows on primary facases: Addition was nimney.  3 History and Sugnificant Warreu. In about 1893 and his son Goldeu E. Pugh	des. Cornice is added in 1979  The In 1848 the the 1860 Robert Andrew Wirgil Miles inherited the property of the second s	of a bathroom and new fireplace an United States Government deeded the Miles bought the land and built to sinherited the place. Sold to Thom place in 1964 and sold it to Harliu	ne land to Williave the house. He died has W. Pugh in 1906.
indows on primary secondary faced 36: Addition was himney.  3 History and Significant Warreu. In about 1893 and his sor Goldeu E. Pugh:	des. Cornice is added in 1979  The In 1848 the 1860 Robert And Wirgil Miles inherited the part of the	United States Government deeded the A Miles bought the land and built to inherited the place. Sold to Thomplace in 1964 and sold it to Harlium.  Jacobson 1964 and Sold it to Doss.	ne land to Williave the house. He died has W. Pugh in 1906. In Deau.  March 3, 1975.
indows on primary secondary faced 36: Addition was himney.  3 History and Significant Warreu. In about 1893 and his son Goldeu E. Pugh:	des. Cornice is added in 1979  The In 1848 the 1860 Robert And Wirgil Miles inherited the part of the	United States Government deeded the A Miles bought the land and built to inherited the place. Sold to Thomplace in 1964 and sold it to Harlium.  Jacobson 1964 and Sold it to Doss.	ne land to Williave the house. He died has W. Pugh in 1906. Deau.  March 3, 1975.
n secondary facad 36: Addition was himney.  3 History and Significant Warreu. In about 1893 and his son	des. Cornice is added in 1979  The In 1848 the table 1860 Robert in Virgil Miles inherited the part of	United States Government deeded the Miles bought the land and built to inherited the place. Sold to Thomplace in 1964 and sold it to Harlium.  November 24, 1964. Deau to Doss.	ne land to Williave the house. He died has W. Pugh in 1906. In Deau.  March 3, 1975.
indows on primary n secondary facad 36: Addition was himney.  3 History and Significant Warreu. In about 1893 and his son Goldeu E. Pugh :	des. Cornice is added in 1979  The In 1848 the 1860 Robert And Wirgil Miles inherited the part of the	United States Government deeded the Miles bought the land and built to inherited the place. Sold to Thomplace in 1964 and sold it to Harlium.  November 24, 1964. Deau to Doss.	Photo  The land to Williave the house. He died that W. Pugh in 1906.  The Deau.  The Prepared by Clara Allison  The Organization
indows on primary a secondary facadom secondary facadom secondary facadom secondary facadom secondary and Supulican Warreu. In about 1893 and his son Goldeu E. Pugh :	des. Cornice is added in 1979  The In 1848 the table 1860 Robert in Virgil Miles inherited the part of	United States Government deeded the Miles bought the land and built to inherited the place. Sold to Thomplace in 1964 and sold it to Harlium.  November 24, 1964. Deau to Doss.	ne land to Williave the house. He died has W. Pugh in 1906. Deau.  March 3, 1975.



FLOORPLANS

NOT TO SCALE



PHOTOGRAPH




9/79

- They are trimmed with limestone lugsils. #36: The original red brick of the school house was stuccoed a brick red about 30 years ago. This is peeling rather badly. A chimney for a store originally existed at the ridgeline, to the rear but has been closed. Windows and porch are original. None of the original outbuildings are standing.
- #43 A few of the early teachers were Allen Broughten, Hattie McGrew, G.E. Kelso, Allie Sprinkle, W.R. Meador and the last teacher, Nadine Huffman. The school was often the social center for the community and some favorite entertainments were Spelling Bees, Ciphening matches and Literary societies. Later it became the center for 4H Club Community meetings and Extension Club entertainments. For a member of years Rural Sunday was a special project of the Riverside Extension Club. Everyone attended the church of their choice then to Little Brick for a bountiful basket dinner; Afterwards the entertainment consisted of community singing, book reviews, talks by well known speakers, etc. The school was in session until consolidation with Hardin in 1950. There are no outbuildings standing. It originally had the out door privacyone for the boys and one for the girls, also a small building to keep kindling and coal for the stove that reated the building. The hitch rack that was in front is gine- om the early days boys and girls rode horses to school.

After the Riverside Club discontinued their meetings the school building was sold-and a daughter of the original ower bought it to square out her farm.

List if , within to our the la

A present, the farm operator stores grain and hay in the building. The school yard is used to park farm machinery.



FLOORPLANS

NOT TO SCALE





NO HZ		& Mrs. Ronald W. Sadler: Res	sidence
uniy Ray	5 Othe	Namo(s) Chase Residence; Hardin	United Methodist
Location of Negatives	Chu	rch Parsonage; Huss Residence	
Specific Lucation A22	of lot7	16. Thematic Category	28. No of Stories 2½
Block 7. Hughe		035	29. Basement? Yes XI Full No I.
Stratton address	SS.	17 Date(s) or Period 1917	30. Foundation Material
Township 52N.			Concrete
Only or real	, Township & Vicinity	18 Style or Design Eclectic 50	31. Wall Construction
Site Plan with North Arro	w	19. Architect or Engineer unknown	Brick, U.S. 32. Roof Type & Material GB
		20. Contractor or Builder Porch	ashphalt gable shin
		John Rhodes	33. No. of Bays
	H	21. Original Use, if apparent Residence O	Front N/A Side N/A)  34. Wall Treatment 30
			Stretcher Bond
		22 Present Use residence	35. Plan Shape square
		23 Ownership Public I !	36. Changes Addition :
(77.1) (110)		Private XI	(Explain Altered I in #42) Moved I
	- lout	24. Owner's Name & Address,	
		Ron Sadler	Interior good
Continues	MTL	Hardin, Mo	Exterior good
Lal Long		25. Open to Yes I i	38. Preservation Yes Underway? No E
Site 11	Structure 1 i	Public? NoX1	39 Endangered? Yes!
Building M	Object 11	26. Local Contact Person or Organization	By What? No D
1. On National Yes II Register? No E	12 is it Yes IX Eliqible? No I I	27. Other Surveys in Which Included	
Register? No ES	14. District Yes IX		40. Visible from Yes 24 Public Road?
Hist Dist.? No ki	Potent'l? No 1 i		41. Distance from and
15 Name of Established D	estrict		Frontage on Road
	•		50 ft.
living rooms,	with solid oa	use features: Oak Beams in k doors and trim and wood ass front porch.	Photo
43 History and Significan		Mr. & Mrs. E.M. Chase	
		Hardin United Methodist Chur	ch
		Lesher Long Inc. Clarence Huss	
	5th owner:		
44 Description of Environ			
Brick double g			
45 Sources of Information	n		46. Prepared by
personal knowl		Vors	Mr. & Mrs. V.M. Sh
POT DOHAT WHOMI	. Cabo or par ve	7 - 2 -	147. Organization

On-Site inspection

RCHS & M

48. Date 9/78

49 Revision Date(s)






1 Nii 92 96	4 Pres	sent Name(S)		7 1 411	
& sunty .	Roo	ckingham Church of Breth	ren		3.1
Ray or ation of Negatives RCHS & M	5 Oth	TARY DOI	0		
		16 Thematic Calegory		28. No of Stories	
6 Specific Location		16 Inematic Calegory			s M a
Twp. 53 Range 26,	Sec. 2635	17 Date(s) or Period			01.
		1905		30. Foundation Material	-
to the second se	al. Township & Vicinity	18 Style or Design		Ashlar stone 31. Wall Construction	
Vic. of Hardin	IOW .	Shirtwaist  19. Architect of Engineer		frame	- 10
		unknown		32. Roof Type & Material	
*. /	6.3	20. Contractor or Builder		center gable/com. Sh	ingl
	7	John Rhodes		33. No. of Bays Front 6 Side 5	
	( W	21. Original Use, if apparent church		34. Wall Treatment	-
10 -		22 Present Use		weatherboard	17.1
		church		35. Plan Shape irregula	r
		23 Ownership	Public I !	36. Changes Additio	
(3)		24. Owner's Name & Address,	Private M	(Explain Altere in #42) Move	
		if known		37. Condition	-
9 Continues	UTM	Congregation of Rocking	gham Church	Interior Good	
lal		of Brethren Hardin, Mo	0	Exterior Good	3.0
Long		25. Open to Public?	Yes M	38. Preservation Ye Underway? N	
f! Site! i Building 1/9	Structure 1 i				S 1 1
n National Yes 11	12. Is It Yes IX	26. Local Contact Person or Org	janization		OIX
agister? No N	Eligible? No 11	27. Other Surveys in Which Inclu	uded		Table
Hist Oist ? No M	14. District Yes I)			The state of the s	s X
	Potent'1? No 14			Public Road? No.	011
15 Name of Established D	District	1000000		Frontage on Road	0.0
					1
42 Further Description of	Important Features L	arge church features doul	bleleaf		/
		ic moldings. Dominant fee			-00
		ved stoop porch over the			
		ackets. Above the porch and balcony in the interior		Photo	
		cade in the northwest co			
		red by a porch identical			
the main entrance	, and a hipped ro	of #36: An addition was	added on th	con!t	7
		60's, a few families of			m
		omes and schoolhouses. In gham, Pleasant View), late			
		1/2 miles north of the			5.
		the same year. In 1918 a			
44 Description of Environ				con't	
		the church on a concrete	e foundation	In a rurel eree	
Parsonage(1922) ad			e roundation	i. The runal area.	
45 Sources of Information				46. Prepared by	
County History				Marvin Holsinger	
hardin Centennial	•	in, Mo 1970		47. Organization	
				RCHS & M	
				48. Date 49 Revision Date	5)
				8/13/79	

#42 Con't west in 1918, do serve as Sunday School rooms.

#43 Con't parsonage constructed. Rev. W.W. Blough was the first paid pastor. In 1958 the Wakenda and Rockingham churches merged, worshipping at Rockingham.



FLOORPLANS

NOT TO SCALE



PHOTOGRAPH



HI4		Jarren Residence	
ay ay		ner Namo(s)	
Location of Negatives	3 0111	Nomo(s)	
		16 Themslic Calegory	28 No of Stories 2212
Specific Location E4 of D Lot 21 Lst	t. south.	030	29. Basement? Yes
f town of Hardin		17 Datu(s) or Period	full No
		1917	30. Foundation Material concrete and bricks
ardin Town II Rus	al, Township & Vicinity	Classic Revival 50 02	31. Wall Construction
Site Plan with North Ar	row	19. Architect or Engineer	brick 4
	WHITH THE	unknown 30 30	32. Roof Type & Material HP
Site Plan with North Ar	.	George Tinsley	high gable/tile 70
Till		21. Original Use, If apparent	33. No. of Bays Side
		residence OIA	34. Wall Treatment
TH		22 Present Use residence	stretcher bond 30
		residence 23 Ownership Public !	35. Plan Shape square
		Private XI	36. Changes Addition (Explain Altered
		24. Owner's Name & Address,	in #42) Moved
Contact		William J. Warren	37 Condition excellent
Coordinates	UTM	Hardin, Missouri	Exterior excellent
Long		25. Open to Yes I I	38. Preservation Yes
Site 1 i Building i i	Structure 1;	Public? No XI	Underway? No
On National Yes II	Object	26. Local Contact Person or Organization	39 Endangered? Yes By What? No
Rogister? No L.	Eligible? No I I	27. Other Surveys in Which Included	By What? No
Part of Estab Yes II	14. District Yes II		40. Visible from Yes
Name of Established D	Potent'l? No I	•	Public Road? No
Name of Calabiished D	isinci		41. Distance from and Frontage on Road
2. Further Description of I	Important Features		
lassic Revival bri	ck house is one	of the finest in Hardin. Symmetri	cal /
		rabeated singleleaf entry with fined with sidelights. Large	
		st story are flanked by smaller	Photo
indows, as is the	window in the se	cond story center bay, in a	
erivation of the P	'alladian window	type. Three dormers pierce the	
History and Significance	and west tacade	s, with 8/8 windows and corner (co	init).
		ted in 1917. Since then, owners h	ave been as follows:
alph Seward; W.G.	Williams; B.F. L	aws; Ed Chase.	
An .			
	gamage and an th	e property which is landscaped.	
	yaraye are on th		
arriage House and	garage are on th		
Sources of Information	garage are on th		46 Prepared by
arriage House and  Sources of Information illiam J. Warren	garage are on th		46 Mary Hogan
arriage House and		ll abstract On site in	47. Organization
Sources of Information Iliam J. Warren M. Shirley	Hardin City Ha	ll, abstract On-site inspection.	

#42. Cont. pilasters. A heavy frieze and boxed cornice continue around the house, strongly marked by brackets. The design of the veranda frieze, which extends across the primary facade and wraps around both secondary facades is identical to that of the main house. There have been no major additions or alterations to the structure.





48. Date 9/26/78


49 Revision Date(5)

Office of Historic Preservation, P.O. Box 176, Jefferson City, Missouri 65101

HISTORIC INVENTORY

1 N: H13	4 Present Namo(s)			
2 (0	Christian Ch	urch of Hardin, Mo		o o
Ray	5 Other Namo(s)		, , , , , , , , , , , , , , , , , , , ,	
1 Location of Negatives	The state of the s			
6 Specific tocation All that par	16 Thematic	Category	28 No of Stories 1 - /	2
Lot A in Block 14-original	town of	0	29. Basement? Yes	F. CO
Hardin, Mo	17 Date(s) o	r Period	No i .	Courty
			Masonary Block 65	*
I City or Town II Rural, Township		A sh	Masonary Block (3)	-1
H tole Plan with North Arrow	Gothic F	or Engineer 73	Frame Wu	
V	unknown	13	32. Roof Type & Material GB	
'I	20 Contracto	or or Builder	High Gable/Asphalt Shi	ngles
	unknown		33. No. of Bays	
	29	Use, if apparent  DGA	Front 2 Side 5TW	100
	Church 22 Present		34. Wall Treatment	sen
	Church		Clapboard -1.  35. Plan Shape rectangular	- z
	23 Ownershi	Public I !	36 Changes Addition	Present Names
**		Private M	(Explain Altered W	HS)
'	24 Owner's	Name & Address,	<b>{</b>	
			37 Condition Interior Good	
9 Courdinates UTM	Hardin,	hristian Church Mo 64085	Exterior Good	
Lottig	25 Open to	Yes M	38. Preservation Yes	
	ucture 1 i Public?	No i i	Underway? No ⊀	
. Building 🕅	Object 11 26 Local Co	ntact Person or Organization	39. Endangered? Yes	
Hegester? No % Engible	Yes III		By What? No 🛚	
3 Part of Estab Yes-11 14 Distric		voys in Which Included	40 Visible from Yes	-
	? No ii		Public Road? No 1.	
15 Name of Established District			41. Distance from and	
			about 200 feet	
22 Futther Description of Important Fo			about 200 feet	
2 Further Description of Important Fe.	Church featur	es high Gables on primary		0
facade with triple Lancet w	_			770
with Tri-Partite transom of			Photo	Other Name(S)
Belfry has pointed arches of				ame
imbricated shingles. Small				(S)
which is topped with a helm	roof. Secondary f		1	
1) History and Significance Service	were first held	in The present building	constructed 1801) in the	
present seward grove. First	pastor was Claude	Taylor. Church was organi	ized in 1902, the year	
the building was moved to i				
vestibule, Sunday School ro	oms, new door and	windows. A Baptistry was b	ouilt. Parsonage adjoinin	3
built 1946. Remodelled agai	n in 1955, and in	1962, more rooms were adde	ed, by the membership.	
Description of Environment and Out	uildings			
Residential Area				
5 6				
5 Sources of Information	H34 W- 3070		46. Prepared by	
Hardin Centennial 1870-1970			Mary F. Swinney.	
Church History-on-site inspection		47. Organization		

#42 spaced windows with neoclassic Lintell moldings. #36: Interior has been remodelled recently. An addition has been added to the rear.



FLOORPLANS

NOT TO SCALE



PHOTOGRAPH



QA A 002 033
Office of Historic Preservation, P.O. Box 176, Jefferson City, Missouri 65101

Ray Location of Negatives	Swinney-Residence  5 Other Name(s)	
	16. Themalic Category	28. No. of Stories
Specific Location south part West 1/2 mile. lot 6, "B" (10-60	))	29. Basement? Yes M. Full No!
Lots 7-8-9- Hardin Hughes & City of Town II Rural, Township &	1918	30. Foundation Material
Hardin Sile Plan with North Arrow	Electric 49	31. Wall Construction Frame
	George M. Tinsley  20. Contractor or Builder	32. Roof Type & Material B Gable-Asphalt
	George M. Tinsley  21. Original Use, if apparent	33. No. of Bays Front 3 Side 2
	Home O F	34. Wall Treatment 21 25 Weatherboard-Shingles
•	Home  23 Ownership Public I ! Private M	35. Plan Shape Retangular  36. Changes Addition (Explain Allered )
	24. Owner's Name & Address, if known	in #42) Moved :
Coordinates UTM	Mary F. Swinney Hardin, Mo 64035	Interior Very Good  Exterior Very Good
Site ! i Stru	25. Open to Yes II Public? No II	38. Preservation Yes Underway? No 💢
	bject i 1 26. Local Contact Person or Organization  Yes ⋈	39. Endangered? Yes II By What? No M
Register? No X Eligible? Part of Estab Yes   1	Yes 🖂 27. Other Surveys in Which Included	40. Visible from Yes X
Name of Established District	No II	Public Road? No 1: 41. Distance from and 20 ft.
		Frontage on Road 36 ft. 26'x 36'-corner lot
exterior fire-place chimney exposed. The entrance door are double hung. All doors porch across the front has	res The house has a center chimney and any. The eaves project with no rafters on the east is plate glass. The windows and windows are plain molded. The concre 3 colmns, mode of brick. Assymmetrical leaf entrance flanked on left by large paired windows. A veranda with pedementers most of the front of the house. Shed(co	te Photo
triple window, on right by		
triple window, on right by entryway is situated across		. 10 IS NOW ONE NOME
triple window, on right by entryway is situated across History and Significance This hor	nter.	. 10 IS NOW ONE NOME

personal knowledge- on site-inspection.


46. Prepared by Mary F. Swinney

47. Organization RCHS & M 48. Date Sept 26

49 Revision Date(s)

SE Printed Use Se problems THE WHITE THE

#42 Con't dormer tops the facade. #36: There have been no major alterations to the house since its construction.



FLOORPLANS

NOT TO SCALE




**PHOTOGRAPH** 



48 Date 10/79

## Office of Historic Preservation, P.O. Box 176, Jefferson City, Missouri 65101 HISTORIC INVENTORY

1 No H6	4 Pres	sent Name(s)	
. County		Craven Residence	
Ray	5 OIN	er Namo(s)	
3 Location of Negatives RCHS & M		Hudson Residence	
6 Specific Lucation		16 Thematic Category	CON March Charles
Hardin Hughes Addition:	East part	030	26 No of Stories 112 /
of Lots 4, 5 & 6, Block		17 Date(s) or Period	29. Basement? Yes I
		1888	30. Foundation Material
7 City or Town II Rural, Town Hardin	ship & Vicinity	18 Style or Design	Lashlar stone 40
Site Plan with North Arrow		Queen Anne cottage 45	31. Wall Construction
		19. Architect or Engineer Unknown	frame . WU. 32. Roof Type & Material GB
(	2	20. Contractor or Builder Poch	gable-asphalt shingle
	رر	Unknown	33. No. of Bays 63
		21. Original Use, If apparent	Front n/a Side n/a
		residence OIA	34. Wall Treatment weatherboard
2		residence	35. Plan Shape rectangular
V/////////////////////////////////////		23 Ownership Public !	36. Changes Addition
		Private XX	(Explain Altered
		24. Owner's Name & Address,	in #42) Moved i
Coordinates UTM		Mr & Mrs. Willis Craven	37 Condition good
Lat		Hardin Missouri 64035	Exterior good
Luny		25 Open to Yes I I	38. Preservation Yes
Site 1 i Building i X	Structure 1 i	Public? No XX	Underway? No X
1 On National Yes II 12 Is I		26 Local Contact Person or Organization	39 Endangered? Yes I By What? No
- 1	gible? No i i	27. Other Surveys in Which included	By What? No )
Part of Estab Yes I 1 14. Di		The server in which included	40. Visible from Yes
	ient'i? No l		Public Road? No
5 Name of Established District			41. Distance from and Frontage on Road
			Tiomage on Hoad
Further Description of Important	Features		
Pyramidal-roofed center	bay domina	tess the primary facade. Each	
commer is marked with p	ilasters.	All windows 1-over-1 light with Ne	20-
classic window heads. (	Ornate East	lake semicircular porch with	Photo
#36. Addition to the sou	carved brac	kets and cut-out porch frieze. uble garage and utility room.	
"SO. Madreton to the sol	ucii oi a uo	uble garage and utility room.	
3 History and Significance			1.
	on huilt th	e house. They kept boarders, espe	oiollu usus sinal
who came to town to work	. Numerou	s owners followed. Porch is one of	clally young single men
decoration in the county	/.	The state of the s	Tem remarring Lastrake
Description of Environment and	Outbuildings		
	_	siness district on a corner lot.	A college leasted 10
feet south of the house	is in exce	llent shape. Maples and a pecan t	ree shade the bouse
		the state of the s	ice shade the nouse.
Sources of Information			46. Prepared by
Mr. and Mrs. Willis Crav Abstract	/en	·	Mary F. Swinney
On-site inspection.			47 Organization
This pection.			RCHS & M
			48 Date 49 Revision Date(s)



FLOORPLANS

NOT TO SCALE



PHOTOGRAPH

- #42. Cont. and attached. Recent aluminum siding addition obscures facade details. Some interior walls have been paneled. Bath added.
- #43. Cont. Rhoda Pugh, Charles Dawson, Robert Wright and wife, Elizabeth Simmerman, Marvin Dawson, Virgil Boggess and wife, Nealy and Nettie Harlan, Effie Simmerman, and present owner purchased house in 1947.




48 Date

8/79

49 Revision Date(s)

Office of Historic Preservation, P.O. Box 176, Jefferson City, Missouri 65101
HISTORIC INVENTORY

THOTOTIO		
H I	esent Name(s)	
2 Jounty	Shauer residence	
Nay	ther Namo(s)	
3 Location of Negatives RCHS & M	Wood Farm, McGinnis Residence	
6 Specific Lucation	16 Thematic Category	28 No of Stories two
	030	29. Basement? Yes 1 X
52N 26W	17 Date(s) or Period	full No i
7 City or Town II Rural, Township & Vicinit	1903	30. Foundation Material
Hardin II Rural, Township & Vicinit	Neoclassic: Eastlake details	ashlar stone 40 31. Wall Construction
B Sile Plan with North Arrow	19. Architect or Engineer	frame wa
	unknown 20	32. Roof Type & Material (M)
1-1/	20. Contractor or Builder Prich unknown	aspestos shingles (A
. 1	21. Original Use, if apparent	33. No. of Bays Front 5 Side 4
1 1 9	residence OIA	34. Wall Treatment
11/105-1	22 Present Use	Wasthanhased 21
11 - 6	residence	35. Plan Shaperectangular
1/00 62	23 Ownership Public   Private X X	36. Changes Addition
1/43	24. Owner's Name & Address.	(Explain Altered )
	if known	37 Condition
9 Coordinates UTM	Allen L. Shauer	Interior good
Lat	Box 542, Hardin, Missouri 64035	Exterior good
Site 1   Structure 1	25 Open to Yes II Public? No ½½	38. Preservation Yes Underway? No X
Building 1 Diject 1		39 Endangered? Yes II
11 On National Yes II 12 Is It Yes X		By What? No X
X Ringister? No X. Eligible? No 1	_ 127. Other Surveys in which included	
Hist Dist.? No 1 Potent'l? No 1		40. Visible from Yes X Public Road?
15 Name of Established District		41. Distance from and
		Frontage on Road
42 Earlbox December - 1 to - 1	J	
42 Further Description of Important Features		
House displays two story, gabled supported by turned posts. Secon		
	Neoclassic heads. Primary entrance	
featues transom and sidelights.		Photo
Interior: main stairway and back	stairway to servants' quarters	
which are not connected to the re	st of the second floor. Fireplace	
43 History and Significance	(cont.	
•	to Handin from Vincinia . He was a	f
cattle and hogs Numerous roads	to Hardin from Virginia. He was a and highways were bult through this	Tarmer and raised
was taken for the Hardin Public S	chool. His second wife Sarah France	acreage. Then so acres p
property until her death in 1943.	The place went to her daughter Luc	cy (wood) Shauer. (Cont)
44 Description of Environment and Outbuildings		(00.13)
-	rn down. This house was on a farm o	of 200 acres at the
dedge of Hardin, now is in city 1	imits, and a residential area.	. Loo deles de tile
45 Sources of Information		46. Prepared by
Personal knowledge.		Mary Hogan
Present owners.		47 Organization
On-site inspection.		RCHS & M



FLOORPLANS

NOT TO SCALE



PHOTOGRAPH

#42. Cont. in every room. Full basement once contained a coal furnace. Bathroom downstairs originally has own water system.

#43. Cont. It is presently owned by the Lucy Shauer estate.



Office of Historic Preservation, P.O. Box 176, Jefferson City, Missouri 65101

1 No	4 Pres	ent Name(s)		
2 County .	San	te Fe Station	N.	o S
Ray	5 Oin	er Namo(s)	9	
3 Location of Negatives	Lex	ington Junction; Henrietta Station	4 C	
6 Specific Lucation .		16. Thematic Category	28. No. of Stories 1	N
			29. Basement? Yes : 1	0
•		17 Date(s) or Period	No 1%	Courty
7 City or Town II Rural, Townsh	and I Vicinity	1913 18 Style or Design	30. Foundation Material brick	
Henrietta	ip & vicinity	Eclectic	31. Wall Construction	
n Site Plan with North Arrow		19. Architect or Engineer	brick	
N   HYWY 13		unknown 20. Contractor or Builder	32. Roof Type & Material gable & flat-asphalt & t	r
		Santa Fe and Wabash railroads	33. No. of Bays	-
Atchison Tope Santa Fe(St	Ka eph Br	21. Original Use, if apparent	Front 8 Side 2	Pre
Atchis Fe(Ste	HHHH	train depot  22 Present Use	34. Wall Treatment Running bond.	sen
Santa Fe(Street	7	RR switch station and freight depo		Z
	manage	23 Ownership Public I !	36. Changes Addition	Present Name(s)
1   Language	R	Private to	(Explain Altered 1 ' Moved 1	8
AT&S	*	if known	37. Condition	
9 Coordinates UTM		Santa Fe Division Hdqts.	Interior fair	
t of toras		Ft. Madison, Wisconsin attn: E.O. Shaddock	Exterio.	
10 Site!	Structure 1 i	25. Open to Yes 1xt Public? No I I	38. Preservation Yes Underway? No x	
Building 1%	Object	26. Local Contact Person or Organization	39. Endangered? Yes II	
11 On National Yes (1) 12. ts tt Register? No k Eligi	Yes 14	OT Other Communic Which leaded	By What? No 坎	
13 Part of Estab Yes II 14. Dist	rict Yes II	27. Other Surveys in Which Included	40. Visible from Yes 'X	
	ent'l? -No Ki		Public Road? No 1:	
15 Name of Established District			41. Distance from and Frontage on Road	
y				
42 Further Description of Important	Features Sta	ation features a central projecting		U
bay with triple window	under a se	mi-circular arch, and topped with		5
ornamentation.	The stati	on is flanked by lower flat-roofed is window. All arches have radiating	Photo	Other Name(s)
voussoirs. Entrances	to the pri	mary facade have 8-light transoms.		me
The interior has brick	floors an	d the original scale for weighing		S
freight, under the floor	or, remain	8.		
		road was established in 1867, and the		
		orthern Railroad (later bought by Sa		
		h Lexington Junction on the river(no aying its tracks 400' north of the		
Western). In 1908 the	Wabash st	ation at Henrietta burned, and the	two railroads built a	
"Union Station", the p	resent bui	lding, in 1913. A large duel coal	loading chute (con't)	
		A freight storage building faces		
		road tracks and has brick walks sur		
45 Sources of Information			46. Prepared by	
Personal knowledge.			Clara Chenault	
Ray County History, 19	73.		RCHS & M	
On-site inspection.			48. Date 49 Revision Date(s)	
			8/78	

#43. Con't. straddled the tracks. (burned 1948) Two large water towers, cattle pens for sorting and loading were built, and switch tracks to bring the coal from surrounding mines. An ice house and beer distributing center constructed. A round house had been built a year previously, which was large enough to service the largest locomotives and could hold six at a time. It was equipped with a turn table on which the largest engine could be revolved. (razed 1957) All this made the Henrietta station a key depot for the line: in addition it was the junction for the St. Joseph spur, and for many years a line ran to the river to meet a ferry. At one time, one of the famous Harvey restaurants was connected to the depot.









Office of Historic Preservation, P.O. Box 176. Jefferson City, Missouri 65101


HISTORIC INVENTORY

No 12	esent Name(s)	
County	Thompson House	
Ray 5 0	her Namo(s)	
Location of Negatives		
RCHS & M	16. Thematic Category	28. No of Stories 2
Specific Location nile East of Knoxville on	030 AD	29. Basement? Yes !
ite HH	17 Date(s) or Period	No !
536 T54N ROSW	1844	30. Foundation Material Ashlar Stone
City or Town If Rural, Township & Vicini	y 18 Style or Design	31. Wall Construction
knowille vic	Federal 2	brick 48
Site Plan with North Arrow	19. Architect or Engineer unknown	32. Roof Type & Material GB
Route HH	20. Contractor or Builder Porch	gable-wood shingle
	unknown ce ms	33. No. of Bays Front 5 Side 1
(19	21. Original Use, if apparent	34 Wall Treatment
4	residence OF	common bond 32
B B	22 Present Use residence	35. Plan Shape T-Shaped
	D. A. W. A. L.	36. Changes Addition
	23 Ownership Private 4	(Explain Altered
	24. Owner's Name & Address,	111 112)
	if known	37. Condition excellan
Coordinates UTM	Don & Jan Thompson	Exterior good
Lat	Rt. 1, Rayville, Mo	
Long	25. Open to Yes 11 No 1 X	38. Preservation Yes Underway?
Site 1 Structure  Building Xi Object	1 i	39 Endangered? Yes
Dunting 12		By What? No
On National Yes II 12 Is II Yes Register? No IX: Eligible? No		
Part of Estab Yes II 14. District Yes		40. Visible from Yes Public Road? No
Hist Dist.? No XI Potent'l? No	11	41. Distance from and
5 Name of Established District		Frontage on Road
	Early I-House of common bond by	rie
2. Further Description of Important realures	in center of each story on prin	nary
cade: 5-light transom with	sidelights. Central 2 story	
dimented portio on front.	All fenestration doublehung 6-0	over 6 Photo
ghts. Interior end brick	chimneys. Hedy molded cornice	
th large returns. Interio	r ceiling 12 feet high.	
		1
TT	built in 1844. Bricks were bu	rned on the site to
History and Significance House was	ork and lumber is cherry and wa	alnut from the farm
e north of the road. woodw	rs mother acquired it from an	insurance company
1965. Is said to have s	ecret passage and rooms used d	uring the Civil War
d possibly a station on th	e underground Railroad.	
14 Description of Environment and Outbuilding	03	

Jan Thompson- On-Site Inspection Mary Richardson

45 Sources of Information

46. Prepared by Cloe Baldwin 47. Organization RCHS & M 48. Date 49 Revision Date(s) 9/79



FLOORPLANS

NOT TO SCALE



PHOTOGRAPH



Office of Historic Preservation, P.O. Box 176, Jefferson City, Missouri 65101

HISTORIC INVENTORY

No 9 10	4 Present Name(s)  Monks Residence	
County Ray Ray	5 Other Namo(s)	
Location of Negatives RCHS & M	Green House	
Specific Lucation	16. Thematic Category	29. Basement? Yes II Nox:
Hwy 13 to unmarked gravel ro then east 3/4 mile.	ca. 1855	30. Foundation Material ashlar stone
City or Town II Rural, Township & Vicinity of Knoxville	neoclassic/vernacular	31. Wall Construction frame . L.)
Site Plan with North Arrow 64 N	unknown  20. Contractor or Builder unknown	32. Roof Type & Material  gable/asphalt  33. No. of Bays
	21. Original Use, if apparent residence OIA	Front 5 Side 2
	residence	clapboarding  35. Plan ShapeL_Shaped  36. Changes AdditionXX
3	23 Ownership Public !! Private ½!  24. Owner's Name & Address.	(Explain in #42) Addition
dirt road  B Coordinates UTM	24. Owners Name & Address.  Il known  Samuel Monbs	37. Condition Interior Fair  Exterior Poor
Lat . Long	25. Open to Yes 11 Public? No 13	38. Preservation Yes Underway? No ±
	cture 1 i 26. Local Contact Person or Organization  Yes X1	39 Endangered? Yes X By What? No! planned demolishion
Register? No IX Eligible?	Yes i   27. Other Surveys in Which Included	demolishion  40. Visible from Yes ' Public Road? No
Hist Dist.? No 12 Potent'l'	No X	41. Distance from and Frontage on Road
window sashes remain, with mentrance has 3- light sidelidetails include pilasters at	I-House, 4 rooms wide by one room de ary and east facades some original 4-ove eoclassic lintel decoration. Primary ghts and a five-light transom. Further reach corner and an undecorated frienge se has undergone several additions and a ear at an unknown time, and more recent	neoclassic beneath

44 Description of Environment and Outbuildings House is situated on a gravel road at the edge of a large working farm. The large barn to the east of it is at least comtemporary with the house and has hand-hewn beams.

45 Sources of Information

46. Prepared by Cameron Richardson 47. Organization

RCHS & M 49 Revision Date(s) 48. Dale


8/79

Buy 13 to minucked amovel road,

then east 3/h mile.

#42 Con't.

room added to that. The original central stairway was removed and a new one constructed in the room to the east, the upstairs hallway made into a closet. Electricity has been added but not plumbing and most original plank flooring remains. #39: The house is in very deteriorated condition and the present owners plan to move and demolish the house in a year or two.



FLOORPLANS

NOT TO SCALE




PHOTOGRAPH



Office of Historic Preservation, P.O. Box 176, Jefferson City, Missouri 65101 HISTORIC INVENTORY

Convolution   18 Aural, Township & Vicinity   18 Style or Design   19 Activities or Builder   19 Act	L-No	4 Pres	sent Name(s)	
Ternshaw Residence  Crenshaw Crenshaw  Shart Sale Crenshaw Residence  Crenshaw Crenshaw  Shart Sale Crenshaw Sale	·		Richardson Residence	
Specific Lucation  Specific Luca		5 OIN	er Namo(s) Crenshaw Residence	
Same part   Same   Sa			or change hear delice	
Convolutional   Skill   Plant   Skill   Plant   Skill   Plant   Skill   Plant   Skill   Plant   Plan				28 No of Stories one
Total or Town if Russi. Township & Vicinity  Vic. Knoxville  a Site Plan with Nurth Arrow  a She Plan With Arrow  a She Plan With Arrow  a She Plan With She Plan With I She	535			
7 City to Town 1 Rural, Township & Vicinity 18 Style or Design  9 Architect or Engineer  19 Architect or Engineer  10 Control or Builder  20 Control or Builder  21 Present Use  12 Present Use  13 New I Treatment  22 Ownship  24 Owner's Name & Address,  14 Present Use  15 Part of East Vest I 12 Is II  16 Part of East Vest I Petrol IV No II  17 Part of East Vest I Petrol IV No II  18 Preservation  19 Architect or Engineer  19 Architect or Builder  20 Ownship  21 Original Use, II apparent  19 Public I  22 Present Use  18 Structure I  23 Ownship  24 Owner's Name & Address,  18 Preservation  18 Public II  26 Open In  27 Open II  28 Preservation  29 Consider II  29 Preservation  29 Consider II  20 Ownship  20 Open II  20 Ownship  21 Open II  20 Open II  21 Public II  22 Preservation  23 Ownship  24 Open II  25 Open II  26 Open II  27 Open II  28 Open II  29 Open II  20 Open II  20 Open II  20 Open II  21 Public II  22 Open II  23 Open II  24 Open II  25 Open II  26 Open II  27 Open II  28 Open II  29 Open II  20 Open II  20 Open II  20 Open II  21 Preservation  22 Open II  23 Open II  24 Open II  25 Open II  26 Open II  27 Open II  28 Open II  29 Open II  20 Open II  20 Open II  20 Open II  21 Preservation  22 Open II  23 Open II  24 Open II  25 Open II  26 Open II  27 Open II  28 Open II  29 Open II  20 Open II  20 Open II  20 Open II  21 Preservation  22 Open II  23 Open II  24 Open II  25 Open II  26 Open II  27 Open II  28 Open II  29 Open II  20 Open II  20 Open II  20 Open II  21 Preservation  22 Open II  23 Open II  24 Open II  25 Open II  26 Open II  27 Open II  28 Open II  29 Open II  20 Open II  20 Open II  20 Open II  21 Open II  22 Open II  23 Open II  24 Open II  25 Open II  26 Open II  27 Open II  28 Open II  29 Open II  20 Open II  20 Open II  21 Open II  22 Open II  23 Open II  24 Open II  25 Open II  26 Open II  27 Open II  28 Open II  29 Open II  20 Open II  20 Open II  20 Open II  21 Open II  22 Open II  23 Open II  24 Open II  25 Open II  26 Open II  27 Open II  28 Open II  29 Open II  20 Open II		SRID		
# Sure Plan with North Arrow  # Site Plan with North Arrow  # Site Plan with North Arrow  # Conditional Use I appearent residence Offs I appearent residence		al, Township & Vicinity	18 Style or Design	
UNKNOWN  TO Contribute Description of Environment and Outbuildings  On outskirts of the village of Knoxville.  UNKNOWN  To Sure 1 separate Description of Environment and Outbuildings  On outskirts of the village of Knoxville.  UNKNOWN  To Sure 1 separate Description of Environment and Outbuildings  On outskirts of the village of Knoxville.  UNKNOWN  To Sure 1 separate Description of Environment and Outbuildings  On outskirts of the village of Knoxville.  UNKNOWN  To Sure 2 separate Description of Environment and Outbuildings  On outskirts of the village of Knoxville.  UNKNOWN  To Sure 2 separate Description of Environment and Outbuildings  On outskirts of the village of Knoxville.  UNKNOWN  To Contribute Description of Environment and Outbuildings  On outskirts of the village of Knoxville.  UNKNOWN  To Sure 2 separate Description of Environment and Outbuildings  On outskirts of the village of Knoxville.  UNKNOWN  To Sure 2 separate Description of Environment and Outbuildings  On outskirts of the village of Knoxville.  UNKNOWN  To Sure 2 separate Description of Environment and Outbuildings  On outskirts of the village of Knoxville.				
20 Contractor of Builder  unknown  21. Original Use, if apparent residence 22. Ownership  Public 1  PrivateXX  24. Owner's Name & Address. If Anown Carl Name & Carl Name Carl N	in and Plan with North Ar	TOW .		
Currillates   UTM   Explain   Provide   Signature   Siding hazard   Signature   Signature   Siding hazard   Signature   Siding hazard   Signature   Sign		J	20. Contractor or Builder	
22 Present Use residence		7		33. No. of Bays
22 Present Use 23 Ownership 24 Owner's Name & Address. 24 Owner's Name & Address. 25 Open to 26 Public 1 26 Open to 27 Ownership 27 Owner's Name & Address. 28 Plan Shape i predular 29 Ownership 20 Ownership 20 Ownership 21 Address. 21 Anown Carl ton Richardson Knoxville, Missouri 25 Open to 26 Open to 27 Owner's Name & Address. 27 Owner's Name & Address. 28 Changes 29 Open to 20 Ope		K A	residence of	3
residence 23 Ownership Public 1: 24 Owner's Name & Address. 14 Nown Richardson Rowoffle, Missouri  8 Site 1: 8 Site		TT' 4	22 Present Use	siding board 20
## Conditional Structure   1	1 17			
24. Owner's Name & Address. In 842) Moved: Interior Garlton Richardson Knoxville, Missouri  25. Open to Public?  Building ix B			Toolio .	36. Changes Addition
Countinates   UTM   Carlton Richardson   Site   Structure   Description of Established District   Public?   Some Stained glass   Public Publ	1.			
Conditinates   Lat   L			Carlton Richardson	
Site   1   Building     Structure	. =	UTM		IIII J
Building 1/2 Object 1  Building 1/2 Cab Cocal Contact Person or Organization  39 Endangered 2 Yes 1  By What?  30 Visible from Proximation  40 Visible from and Frontage on Road  41 Distance from and Frontage on Road  42 Further Description of Important Features  Gable ends retain decorative shingle work. Some stained glass remains in window transoms. Additions and alterations have "in-filled" original cross plan to produce square effect.  4 Description of Environment and Outbuildings  On outskirts of the village of Knoxville.  5 Sources of Information  Mrs. Carlton Richardson  On-site inspection.  46 Prepared by Jim Pease 47 Organization Richs & Mac 48 Date 49 Revision Date(s).  48 Date 49 Revision Date(s).			25 Open to Year I	
10 On National Yes   12 is   12 is   12 is   13 is   14 is   15 is   1			0	
Register? No   X   Eligible? No   1   14. District   Yes   1   14. District   Potent   17. No   17.   Potent   17.			26 Local Contact Person or Organization	
Part of Estab Ves   1			27 Other Surveys to Which Included	By What? No A
Public Road?  No.  15 Name of Established District  16 Name of Established District  17 Further Description of Important Features  Gable ends retain decorative shingle work. Some stained glass remains in window transoms. Additions and alterations have  "in-filled" original cross plan to produce square effect.  Photo  The History and Septimicance  4 Description of Environment and Outbuildings  On outskirts of the village of Knoxville.  5 Sources of Information  Mrs. Carlton Richardson  On-site inspection.  46 Prepared by  Jim Pease  47 Organization  RCHS & M  48 Date 49 Revision Date(s)	3 Part of Estab Yes II		The salveye in which included	40. Visible from Yes X
Gable ends retain decorative shingle work. Some stained glass remains in window transoms. Additions and alterations have "in-filled" original cross plan to produce square effect.  Photo  History and Significance  4 Description of Environment and Outbuildings On outskirts of the village of Knoxville.  5 Sources of Information  Mrs. Carlton Richardson On-site inspection.  46 Prepared by Jim Pease 47 Organization RCHS & M  48 Date 49 Revision Date(s)				Public Road? No
Gable ends retain decorative shingle work. Some stained glass remains in window transoms. Additions and alterations have "in-filled" original cross plan to produce square effect.  Photo  History and Supplicance  4 Description of Environment and Outbuildings  On outskirts of the village of Knoxville.  5 Sources of Information  Mrs. Carlton Richardson  On-site inspection.  46. Prepared by  Jim Pease  7 Organization  RCHS & M  48 Date 49 Revision Date(s)	traine of Lataonship D			41. Distance from and Frontage on Road
Gable ends retain decorative shingle work. Some stained glass remains in window transoms. Additions and alterations have "in-filled" original cross plan to produce square effect.  Photo  History and Supplicance  4 Description of Environment and Outbuildings  On outskirts of the village of Knoxville.  5 Sources of Information  Mrs. Carlton Richardson  On-site inspection.  46. Prepared by  Jim Pease  7 Organization  RCHS & M  48 Date 49 Revision Date(s)	12 Further Description of I	mportant Features		
4 Description of Environment and Outbuildings  On outskirts of the village of Knoxville.  5 Sources of Information  Mrs. Carlton Richardson  On-site inspection.  46 Prepared by  Jim Pease  47 Organization  RCHS & M  48 Date 49 Revision Date(s)	remains in window	transoms. Addit	ions and alterations have	Photo
On outskirts of the village of Knoxville.  5 Sources of Information  Mrs. Carlton Richardson On-site inspection.  46 Prepared by Jim Pease 47 Organization RCHS & M  48 Date 49 Revision Date(s)	3 History and Significance	8		
On outskirts of the village of Knoxville.  5 Sources of Information  Mrs. Carlton Richardson On-site inspection.  46 Prepared by Jim Pease 47 Organization RCHS & M  48 Date 49 Revision Date(s)				Ì
On outskirts of the village of Knoxville.  5 Sources of Information  Mrs. Carlton Richardson On-site inspection.  46 Prepared by Jim Pease 47 Organization RCHS & M  48 Date 49 Revision Date(s)	14 Constability	·		
Sources of Information  Mrs. Carlton Richardson  On-site inspection.  46. Prepared by  Jim Pease  47. Organization RCHS & M  48. Date 49. Revision Date(s)				
Mrs. Carlton Richardson On-site inspection.  46. Prepared by  Jim Pease  47. Organization RCHS & M  48. Date 49. Revision Date(s)	on outskirts of th	e village of Knox	(VIIIe.	
Mrs. Carlton Richardson  On-site inspection.  46 Prepared by  Jim Pease  47 Organization  RCHS & M  48 Date 49 Revision Date(s)	5 Sources of Information			
On-site inspection.  47 Organization RCHS & M  48 Date 49 Revision Date(s)		rdson	-	
RCHS & M  48 Date 49 Revision Date(s)				47 Organization
	- I I I I I I I I I I I I I I I I I I I	•		RCHS & M
				48 Date 49 Revision Date(s) 6/80



FLOORPLANS

NOT TO SCALE



PHOTOGRAPH




48. Date 6/79

49 Revision Date(s)

2 Courty

RA AS 002-040
Office of Historic Preservation, P.O. Box 176, Jefferson City, Missouri 65101

No.	4 Pres	ent Name(s)	
nty .	Me	eyers House	
Ray	5 Oih	er Namo(s)	
Location of Negatives		abbert House	
Specific Location Route	#1 ·	16. Thematic Category	28. No. of Stories 2
1621			29. Basement? Yes Di
16 T54N	39W	17 Date(s) or Period	half No 1.
		1924 18 Style or Design	30. Foundation Material limestone ashlar43
City of Town If Aural, T	Township & Vicinity	vernacular 49	31. Wall Construction
Site Plan with North Arrow		19. Architect or Engineer	frame www.
		unknown	32. Roof Type & Material
	ELMIRA ->	20. Contractor or Builder	gable-asbestos shingle
8		John Gabbert	33. No. of Bays Front 3 Side
	1	21. Original Use, if apparent residence.	34. Wall Treatment 65
	Ŋ	22 Present Use	aluminum siding
\\ PII	A <sub>0</sub>	residence	35. Plan Shape T-shaped
	Ψ	23 Ownership Public I !	36. Changes Addition 3:
		Private to	(Explain Altered Moved 1
//		24. Owner's Name & Address, if known	37. Condition
Coordinates UTM	4	John Meyers	Interior good
Lal	•	Route #1, Box 148, Lawson MO	Exterior good
Long		25. Open to Yes 11	38. Preservation Yes
Site ! i	Structure I i	Public? No lat	Underway? No · X
Building i K	Object I I	26. Local Contact Person or Organization	39. Endangered? Yes   Yes   No X
On National Yes 1 1	2. Is It Yes *I		By What? No X
	4. District Yes II	27. Other Surveys in Which Included	40. Visible from Yes 'X
Hist Dist ? No Ki	Potent'l? No to		Public Road? No 1:
Name of Established Distri	cl		41. Distance from and
,			Frontage on Road
Further Description of two		rimary facade is dominated by veran	
across its length. not original. Two 7 rooms, with 10' some hardwood oak	It is now su wall dormers ceilings. Woo beams in the h	pported by castiron posts, which are placed above. The house contain dwork is stained dark. There are ouse. #36.: The house has asbesto arding. Windows are not original.	ns Photo
History and Significance			1
	out 1924 by Jo	hn Gabbert on 118 acres.	
Description of Environment	and Outbuildings		
On wooded lot of 1	18 acre farm.	Several outbuildings are on the pr	operty.
Sources of Information			46. Prepared by
Sharon Myers (Mrs.	John Meyers)		Tom Stokes
On-site inspection	١.		47. Organization



FLOORPLANS

NOT TO SCALE




PHOTOGRAPH



Office of Historic Preservation, P.O. Box 176. Jefferson City, Missouri 65101

HISTORIC INVENTORY

No		nt Name(s)	
	Jarm	an Funeral Home	
Ray	5 Othe	( Namo(s)	
Location of Negatives	Laws	son Hotel	
		18 Thematic Calegory	28. No of Stories 2-
Specific Lucation 214 North Penn St.,	Lawson Mo.	050 290	29. Basement? Yes I
		17 Date(s) or Period	No
53	3N 29W	ca. 1890	30. Foundation Material molded brick
City or Town If Rural, 1	Township & Vicinity	18 Style or Design	31. Wall Construction
awson		Victorian 19. Architect or Engineer	brick . LB
Site Plan with North Arrow		unknown	32. Roof Type & Material
1		20. Contractor or Builder Parch	flat-tar ++
		A.W. Rainwater	33. No. of Bays Front 5 Side 8
	N	21. Original Use, if apparent	na Well Treetment
PENN		hotel OLD	stucco 6/
4	0	funeral home and rooming house	35. Plan Shape rectangula
NORTH	4	23 Ownership Public   1	36. Changes Addition
NO		Private 1x	(Explain Altered in #42) Moved
<del>intramentalia</del>		24. Owner's Name & Address,	37. Condition
AT&SF rail	road	Lyndell Jarman & Marion O'Dell	Interior good
Coordinates UT	М	Excelsior Springs, Missouri	Exterior good
Lat Long		25. Open to Yes Ki	38. Preservation Yes
Site 11	Structure 1 i	Public? restricted No!!	Underway? No
Building X	Object	26. Local Contact Person or Organization	39 Endangered? Yes By What? No
On National Yes !!	12 Is II Yes IX		by what:
Register? No X:	Eligible? No 11	27. Other Surveys in Which Included	40. Visible from Yes
Part of Estab Yes     Hist Dist.? No XI	14. District Yes II Potent'l? No IX		Public Road? No
Name of Established Dist		1	41. Distance from and Frontage on Road
TARINO OF ESTADISHED DIS	•		20 ft.
		1 1111	20 10.
. Further Description of Im	portant Features E	xterior of this large building	
features two-over-	-two windows un	der segmental arches of headers. are set under large rectangular tr	ansoms.
se a saladah susu	ed the length o	the primary lacade. Is supported	Photo
	is the renger o	when her 24 moons with ten-foot	
a CAI Tourist	ak hases. Inte	rior has 24 rooms, with ten rece	
by posts with bric	an ilasman I.	rior has 24 rooms, with ten-foot orknobs remain throughout. There	are
by posts with brice ceilings. Original	al porceline do	orknobs remain throughout. There	are
by posts with brice ceilings. Origina 13 chimneys for bo	al porceline do oth wood and co	al stoves. Most rooms have wainsco	are oting (bon't)
by posts with brice ceilings. Origina 13 chimneys for be and living room (c) History and Significance	al porceline do oth wood and co once lobby) has The building	al stoves. Most rooms have wainscome panelled ceiling. #36.: The hotel was first constructed as the Lawson tracks and tracks are the restricted tracks.	are oting (bon't) on Hotel, in a very os from the Santa Fe de
by posts with brice ceilings. Origina 13 chimneys for be and living room (company and Significance prominent location)	al porceline do oth wood and co once lobby) has The building n in the town,	panelled ceiling. #36.: The hotel was first constructed as the Lawse directly across the railroad track	are oting (bon't) on Hotel, in a very as from the Santa Fe de
by posts with brice ceilings. Origina 13 chimneys for be and living room (component location (destroyed) In 199	al porceline do oth wood and co once lobby) has The building n in the town, 36, with the wa	al stoves. Most rooms have wainscome panelled ceiling. #36.: The hotel was first constructed as the Lawson directly across the railroad track aning of the railroad and the increase.	are oting (bon't) on Hotel, in a very as from the Santa Fe dependence of small motels all odelled into a funeral
by posts with brice ceilings. Origina 13 chimneys for be and living room (component location (destroyed) In 199	al porceline do oth wood and co once lobby) has The building n in the town, 36, with the wa	al stoves. Most rooms have wainscome panelled ceiling. #36.: The hotel was first constructed as the Lawson directly across the railroad track aning of the railroad and the increase.	are oting (bon't) on Hotel, in a very as from the Santa Fe depease of small motels ale
by posts with brice ceilings. Original 13 chimneys for be and living room (c) 3 History and Significance prominent location (destroyed) In 197 highways, the hote with rooms and approximately services and approximately services are services as a services of the services	al porceline do oth wood and co once lobby) has The building in the town, 36, with the wall was sold to artments above.	al stoves. Most rooms have wainscome panelled ceiling. #36.: The hotel was first constructed as the Laws directly across the railroad track aning of the railroad and the increase the present owners family and removed. It was the first undertaking estimated	are pting (bon't) on Hotel, in a very as from the Santa Fe depease of small motels alcoholded into a funeral h
by posts with brice ceilings. Original 13 chimneys for be and living room (c) 3 History and Significance prominent location (destroyed) In 197 highways, the hote with rooms and ap	al porceline do oth wood and co once lobby) has The building in the town, 36, with the wall was sold to artments above.	al stoves. Most rooms have wainscome panelled ceiling. #36.: The hotel was first constructed as the Lawson directly across the railroad track aning of the railroad and the increase the present owners family and removed. It was the first undertaking estimated	are oting (bon't) on Hotel, in a very as from the Santa Fe dependence of small motels ale odelled into a funeral le tablishment in Lawson.
by posts with brice ceilings. Original 13 chimneys for be and living room (constraint and living room).  3 History and Significance prominent location (destroyed) In 197 highways, the hote with rooms and approximate of Equations.	al porceline do oth wood and co once lobby) has The building in the town, 36, with the wall was sold to artments above.	al stoves. Most rooms have wainscome panelled ceiling. #36.: The hotel was first constructed as the Laws directly across the railroad track aning of the railroad and the increase the present owners family and removed. It was the first undertaking estimated	are oting (bon't) on Hotel, in a very as from the Santa Fe dependence of small motels ale odelled into a funeral le tablishment in Lawson.
by posts with brice ceilings. Original 13 chimneys for be and living room (c) 3 History and Significance prominent location (destroyed) In 197 highways, the hote with rooms and ap	al porceline do oth wood and co once lobby) has The building in the town, 36, with the wall was sold to artments above.	al stoves. Most rooms have wainscome panelled ceiling. #36.: The hotel was first constructed as the Lawson directly across the railroad track aning of the railroad and the increase the present owners family and removed. It was the first undertaking estimated	are oting (bon't) on Hotel, in a very as from the Santa Fe dep ease of small motels ale odelled into a funeral h tablishment in Lawson. (constrict.
by posts with brice ceilings. Origina 13 chimneys for be and living room (company and Significance prominent location (destroyed) In 19 highways, the hotowith rooms and approximate the secretary of the secretar	al porceline do oth wood and co once lobby) has The building in the town, 36, with the wall was sold to artments above.	al stoves. Most rooms have wainscome panelled ceiling. #36.: The hotel was first constructed as the Lawson directly across the railroad track aning of the railroad and the increase the present owners family and removed. It was the first undertaking estimated	are pting (bon't) on Hotel, in a very as from the Santa Fe depease of small motels alcoholeled into a funeral hablishment in Lawson. (constrict.
by posts with brice ceilings. Original 13 chimneys for beand living room (constraint of the strong and Significance prominent location (destroyed) In 197 highways, the hotowith rooms and appearance of the strong and appearance of the strong	al porceline do oth wood and co once lobby) has The building in the town, 36, with the wall was sold to artments above.	al stoves. Most rooms have wainscome panelled ceiling. #36.: The hotel was first constructed as the Lawson directly across the railroad track aning of the railroad and the increase the present owners family and removed. It was the first undertaking estimated	are pting (bon't) on Hotel, in a very as from the Santa Fe der case of small motels alcodelled into a funeral habitablishment in Lawson (constrict.
by posts with brice ceilings. Origina 13 chimneys for be and living room (company and Significance prominent location (destroyed) In 199 highways, the hotowith rooms and application of Environment In a residential Sources of Information Mary Jarmon	al porceline do oth wood and co once lobby) has The building in the town, 36, with the was sold to artments above.	al stoves. Most rooms have wainscome panelled ceiling. #36.: The hotel was first constructed as the Lawson directly across the railroad track aning of the railroad and the increase the present owners family and removed. It was the first undertaking estimated	are pting (bon't) on Hotel, in a very as from the Santa Fe der ease of small motels alc odelled into a funeral h tablishment in Lawson (constrict.



FLOORPLANS

NOT TO SCALE



**PHOTOGRAPH** 

- #42. Con't. has had many alterations since its conversion into a funeral home. The lobby was converted into a large living area, and two parlors in the west became bedrooms, the original sliding wood doors between them removed. The hotel's large dining room is now used as a chapel for funeral services. When the Jarmons acquired the building in 1936, it was still heated with stoves, and serviced by outhouses to the rear, 4 for women and 4 for men. The Jarmons added central heating, removing the stoves which were in every room. Some walls were taken out to increase the size of the rooms upstairs and bathrooms were added, as was an attached garage. Several apartments were constructed upstairs out of some of the rooms. The hotel originally had its own water system, but later the Jarmons added the city water and sewage system.
- #43. Con't. The building is significant as one of the few remaining examples in Ray County of the nineteenth century railroad hotel, and additionally, in its role as a rooming house, one of the few to continue, at least in part, in the same use for which it was constructed.




6/80

4. Present Name(s)

5 Other Name(s)

Nu	65 4 Pres	sent Name(s)	
<u> </u>	63	Hall Place	•
Ray	5 Oth	er Namo(s)	
Location of Negatives RCHS	& M	White Property	
Specific Lucation		16. Thematic Category	28. No. of Stories two 2 -
1-3/4 miles nort	h of Richmond on	030	29. Basement? Yes !
	miles to unmarke	17 Date(s) or Period	No
	iles to Route(cor		30. Foundation Material
A STATE OF THE STA	al, Township & Vicinity		ashlar stone 40
tillvillevio	WU E	Greek Revival 3/	31. Wall Construction
lite Plan with North Ar	ow W	19. Architect or Engineer	frame WW
1	100	unknown 20. Contractor or Builder	32. Roof Type & Material G P gable-asphalt shing
N		unknown	33. No. of Bays
1		21. Original Use, if apparent	Front 3 Side 4
10		residence OIA	34. Wall Treatment
1	7	22 Present Use	weatherboard. 34
		vacant	35. Plan Shape T-shaped
		23 Ownership Public !!	36. Changes Addition
1	200	Private XI	(Explain Altered Moved
525 T53N	2400	24. Owner's Name & Address, if known	37. Condition
		Allen White	Interior poor
ourdinates '	UTM		Exterior Poor
ong		25. Open to Yes I I	38. Preservation Yes
Site ! i	Structure I i	Public? No M	Underway? No
Building ¥1	Object 1 i	26. Local Contact Person or Organization	39. Endangered? Yes
n National Yes II	12. Is II Yes IX		By What? No
legister" No k	Etigible? No I I	27. Other Surveys in Which Included	neglect
Part of Estab Yes (1)	14. District Yes     Potent'l? No X		40. Visible from Yes Public Road?
Name of Established D			41. Distance from and
			Frontage on Road
by projecting witrabeated window stove chimneys. #36: Small addit	ouse unusual for a ng on primary fac heads, pilaster Interior feature ion to rear conta tiorating rapidly.	area. Has primary entrance flanked cade. Neoclassic details include corner boards, etc. Interior es plain pine woodwork, mantels. Aining wellhouse. #39: House is the present owner of the land	Photo
in 1857. He pro	bably constructed	am County, Virginia in 1832. He em I this house around 1870. Merle Bri purchased in 1979 from Marian Wrigh	ght remembers her mothe:
Description of Environm In the center of	ent and Outbuildings farmland. Seven	ral modern barns in close proximity	to the house.
Sources of Information			46. Prepared by
Sources of Information Merle Bright.			Cameron
-	, 1877.		



FLOORPLANS

NOT TO SCALE



PHOTOGRAPH



14 34	1	sent Name(s)	
2 County		Brethren Church of Millville	
Ray	5 OII	her Namo(s)	
3 Location of Negatives RCHS		Dreves Property	
Specific Lucation 2 miles north of	Milluille on	16 Thematic Category	26 No of Stories One
unmarked gravel r		030	29. Basement? Yes I
CR SZ	53N 27W	17 Datu(s) or Period BEFORE 1897	Noxi
	ral Township & Vicinity		30. Foundation Material
vic'Miliville	ral, Township & Vicinity	vernacular; Neoclassic details	31. Wall Construction
Sile Plan with North A	mow L3	19. Architect or Engineer	frame .ωμ
. \11	- 63	unknown 20. Contractor or Builder	32. Roof Type & Malerial gable-asphalt shingl
111	F F	unknown	33 No of Bave
	7 8	21. Original Use, if apparent	Front 1 Side
9 111	4.3	church OGA	34. Wall Treatment
1 //		barn	weatherboard 2/ 35. Plan Shape rectangula
		23 Ownership Public ! !	36. Changes Addition
		Private M	(Explain Altered
111		24. Owner's Name & Address,	in #42) MovedX
Coordinates	UTM	Charles Roy Dreves	37 Condition poor
Lat		Millville, Missouri	Exterior Poor
Long		25. Open to Yes I.) Public? No I'l	38. Preservation Yes
Site 1 i Building iXi	Structure 1 i		Underway? No X
On National Yes IJ	12 Is II Yes I I	26 Local Contact Person or Organization	39 Endangered? Yes X By What? No !
Rugister? No IX	Eligible? No XI	27. Other Surveys in Which Included	neglect
	14. District Yes !!		40. Visible from Yes X
Hist Dist.? No IX	Potent'l? No X		0.44 5
Hist Dist.? No IX			Public Road? No
Hist Dist.? No IX			0.11 0
Hist Dist.? No IX  5 Name of Established (	District		Public Road? No .  41. Distance from and
Hist Dist.? No iX Name of Established i Further Description of  /ernacular church	Important Features Still exhibits so	ome delineation of Neoclassic deta	Public Road? No .  41. Distance from and Frontage on Road
Hist Dist.? No iX Name of Established if Further Description of dernacular church in its boxed corni	Important Features still exhibits so	ome delineation of Neoclassic deta pilaster corner boards. Door and	Public Road? No .  41. Distance from and Frontage on Road
Hist Dist.? No iX Name of Established if Further Description of  /ernacular church  in its boxed cornivindows crowned wi	Important Features still exhibits so ice, plain frieze, ith simple lintel	, pilaster corner boards. Door and heads. Interior has tongue and qu	Public Road? No .  41. Distance from and Frontage on Road
Hist Dist.? No iX Name of Established if Pernacular church in its boxed corni rindows crowned with reiling. #39: Ch	Important Features still exhibits so ice, plain frieze, ith simple lintel	pilaster corner boards. Door and	Public Road? No .  41. Distance from and Frontage on Road
Representation of Partition of	Important Features still exhibits so ice, plain frieze, ith simple lintel	, pilaster corner boards. Door and heads. Interior has tongue and qu	Public Road? No .  41. Distance from and Frontage on Road
Hist Dist.? No iX Name of Established if Pernacular church in its boxed cornivindows crowned with eiling. #39: Cheteriorating.	Important Features still exhibits so ice, plain frieze, ith simple lintel nurch is now used	, pilaster corner boards. Door and heads. Interior has tongue and qu	Public Road? No.  41. Distance from and Frontage on Road
5 Name of Established ( 2 Further Description of Vernacular church in its boxed cornivindows crowned windows crowned windows #39: Chapteriorating.	Important Features still exhibits so ice, plain frieze, ith simple lintel nurch is now used	, pilaster corner boards. Door and heads. Interior has tongue and grape for hay storage and is rapidly	Public Road? No.  41. Distance from and Frontage on Road
Hist Dist.? No iX  Name of Established if Pernacular church in its boxed cornivindows crowned with the chiral management of the church was builting.	Important Features still exhibits so ice, plain frieze, ith simple lintel nurch is now used	pilaster corner boards. Door and heads. Interior has tongue and grape for hay storage and is rapidly	Public Road? No.  41. Distance from and Frontage on Road  Add Coove Photo
Hist Dist.? No ix Name of Established is Perither Description of dernacular church its boxed cornivindows crowned with the church was builtourishing town.	Important Features still exhibits so ice, plain frieze, ith simple lintel nurch is now used  It sometime befor The congregation	pilaster corner boards. Door and heads. Interior has tongue and grape for hay storage and is rapidly  re 1897 as the Brethren church of Norshipped there many years until	Public Road?  No.  11. Distance from and Frontage on Road  No.  No.  11. Distance from and Frontage on Road
Hist Dist.? No ix Name of Established is Name of Established is Pernacular church its boxed cornivindows crowned wite iling. #39: Cheteriorating.  History and Significant the church was builting town. ethany Church of	Important Features still exhibits so ice, plain frieze, ith simple lintel nurch is now used  The congregation the Brethren near	re 1897 as the Brethren church of Norshipped there many years until	Public Road?  All Distance from and Frontage on Road  Millville, then a the erection of a new sold to John W. Moyon W.
History and Significant the church was builtoning town.	Important Features still exhibits so ice, plain frieze, ith simple lintel nurch is now used  It sometime befor The congregation the Brethren near it into a house.	pilaster corner boards. Door and heads. Interior has tongue and grape for hay storage and is rapidly  re 1897 as the Brethren church of Norshipped there many years until	Public Road?  All Distance from and Frontage on Road  Millville, then a the erection of a new sold to John W. Moyon W.
Further Description of ernacular church n its boxed cornivindows crowned wielling. #39: Cheteriorating.  History and Significant the church was buillourishing town. ethany Church of anted to remodel	Important Features still exhibits so ice, plain frieze, ith simple lintel nurch is now used  It sometime befor The congregation the Brethren near it into a house.	re 1897 as the Brethren church of Nor worshipped there many years until Stet. In 1929, the building was The original straight back benche	Public Road?  All Distance from and Frontage on Road  Millville, then a the erection of a new sold to John W. Moyon W.
Further Description of ernacular church n its boxed cornindows crowned wielling. #39: Cheteriorating.  History and Significant he church was buillourishing town. ethany Church of anted to remodel	Important Features still exhibits so ice, plain frieze, ith simple lintel nurch is now used  It sometime befor The congregation the Brethren near it into a house.	re 1897 as the Brethren church of Norshipped there many years until	Public Road?  All Distance from and Frontage on Road  Millville, then a the erection of a new sold to John W. Moyon w.
Further Description of ernacular church n its boxed cornindows crowned wielling. #39: Cheteriorating.  History and Significant he church was buillourishing town. ethany Church of anted to remodel  Description of Environment has been that	Important Features still exhibits so ice, plain frieze, ith simple lintel nurch is now used  It sometime befor The congregation the Brethren near it into a house.  The condition of the brethren near it into a house.  The condition of the brethren near it into a house.	re 1897 as the Brethren church of Nor worshipped there many years until Stet. In 1929, the building was The original straight back benche	Public Road?  All Distance from and Frontage on Road  Millville, then a the erection of a new sold to John W. Moyon w.
History and Significant the church was builtoning town.  History and Significant the church of the church has been the church has been the sources of information.	Important Features still exhibits so ice, plain frieze, ith simple lintel nurch is now used  It sometime befor The congregation the Brethren near it into a house.  The condition of the brethren near it into a house.  The condition of the brethren near it into a house.	pilaster corner boards. Door and heads. Interior has tongue and grape for hay storage and is rapidly re 1897 as the Brethren church of National worshipped there many years until Stet. In 1929, the building was The original straight back benche rural environment.	Public Road?  Al. Distance from and Frontage on Road  Millville, then a lathe erection of a new sold to John W. Moyer wes from the church (cont
Histo Dist.? No ix Name of Established is Pernacular church in its boxed cornivindows crowned with the church was builted in the church of the church of the church of the church in the church of the church in the church of the church has been	Important Features still exhibits so ice, plain frieze, ith simple lintel nurch is now used  It sometime befor The congregation the Brethren near it into a house.  ment and Outbuildings oved; is now in a  History of Millyi	pilaster corner boards. Door and heads. Interior has tongue and grape for hay storage and is rapidly re 1897 as the Brethren church of National worshipped there many years until Stet. In 1929, the building was The original straight back benche rural environment.	Public Road?  Al. Distance from and Frontage on Road  Millville, then a lithe erection of a new sold to John W. Moyer was from the church (contage).  46. Prepared by Cameron
Histo Dist.? No ix Name of Established is Permacular church in its boxed cornivindows crowned with the church was builted in the church of the church was builted in the church of the church of the church has been the churc	Important Features still exhibits so ice, plain frieze, ith simple lintel nurch is now used  The congregation the Brethren near it into a house.  ment and Outbuildings oved; is now in a  History of Millvi	pilaster corner boards. Door and heads. Interior has tongue and grape for hay storage and is rapidly re 1897 as the Brethren church of National worshipped there many years until Stet. In 1929, the building was The original straight back benche rural environment.	Public Road?  Al Distance from and Frontage on Road  Millville, then a lithe erection of a new sold to John W. Moyer wes from the church (continues from the church)
Hist Dist.? No IX  5 Name of Established in Principle of Vernacular church in its boxed cornivindows crowned windows crowned windows crowned windeteriorating.  3 History and Significant fle church was built flourishing town. Bethany Church of wanted to remodel  4 Description of Environment	Important Features still exhibits so ice, plain frieze, ith simple lintel nurch is now used  The congregation the Brethren near it into a house.  ment and Outbuildings oved; is now in a  History of Millvi	pilaster corner boards. Door and heads. Interior has tongue and grape for hay storage and is rapidly re 1897 as the Brethren church of National worshipped there many years until Stet. In 1929, the building was The original straight back benche rural environment.	Public Road?  Al. Distance from and Frontage on Road  Millville, then a lithe erection of a new sold to John W. Moyer where from the church (continues from

#43. Cont. were sold, Moyer never completed his plans and the building was vancant until 1930 when the present owner purchased it for a sheep barn. It is now used to store hay.





37 37	4 P	resent Name(s)	
/ County		Judge Grimes House	
Ray	5 (	Other Namo(s)	
3 Location of Negatives			
RCHS & M			
6 Specific Lucation		16 Thematic Category	26 No of Stories one
38 T53N 3	1710	17 Dalu(s) or Period	29. Basement? Yes II
CR		ca. 1880	Noiy
	Township & Vicini		30. Foundation Material
vic. Millville		Neoclassic/ Eastlake details	ashlar stone 90
8 Sile Plan with North Arrow	011	19. Architect or Engineer	frame , will
	コーライン	unknown	32. Roof Type & Material G
	401	20. Contractor or Builder Porch OH OB	gable-asphalt shingles
		unknown OH OB 21. Original Use, If apparent	33. No. of Bays Front 5 Side 2
7	7 (2)	residence O/A	34. Wall Treatment
	11 9 1	22 Present Use	weatherboard 21
1	4	vacant	35. Plan Shape rectangular
	6	23 Ownership Public I ' Private ¥ I	36. Changes Addition
616	2 (8)	24. Owner's Name & Address,	(Explain Altered i ! Moved i
- W G		if known	37 Condition
V Coordinates UTI	М		Interior poor
Let Long	•		Exterior poor
Site Li	Structure	25 Open to Yes 1 1 Public? No XX	38. Preservation Yes Underway? No Y
Building i x	Object (		Α
	12 Is II Yes I	1	By What? Yes X'
Augister? No IX	Eligible? No f	21. Other Surveys in which included	neglect
Hist Dist.? No IX	14. District Yes (		40. Visible from Yes :
15 Name of Established Distr			Public Road? No X
The state of the s			41. Distance from and Frontage on Road
42. Further Description of Imp	ortant Features		
pilaston compon boar	ttage with Ne	oclassic details in window heads, rnice and frieze. Two porches, both	
feature tuned nosts.	carved brack	ets, row of spindles on frieze.	
Windows had border o	of stained gla	iss in upper sash. Interior: double,	Photo
paneled doors betwee	n parlor and	diningroom and kitchen. Bull'seye	
woodwork, original h	ardware on do	ors. #36: there have been no alter-	
ations except for ad	<u>ldition</u> of ele	ectricity, but the house is (cont)	1.
and aigmireance			
This was the home of	Judge Frank	Grimes until his death. Currently it	: is open to elements
and farm animale			
and farm animals.			

Hous is located on a hill with a magnificent view of the surrounding countryside. Usual farm outbuildings contemporary with the house in equal state of deterioration.

## 45 Sources of Information

On-site inspection.

Mrs. Earl Miller.


History of Millville.

46. Prepared by
Miller and Cameron
47 Organization

RCHS & M

48 Date 49 Revision Date(s)

10/79



FLOORPLANS

NOT TO SCALE



PHOTOGRAPH


#42. Cont. in a deteriorated condition and has been vandalised. It is now open to the weather, stores hay and sometimes provides shelter for animals.



48 Date 49 Revision Date(s)

5/80

1 No	OHA PINE	ent Name(s)	
. County	7 171	Cox Residence	
Ray	5 Olh	r Namo(s)	
3 Location of Negatives			
RCHS & M			
6 Specific Lucation		16 Thematic Category	28 No of Stories 71/2
CR		17 Date(s) or Period	29. Basement? Yes II
525 T53N a	27 W	1916	No XX
7 City or Town Il Rural,	Township & Vicinity	18 Style or Design	ashlar stone
vic. Millville			31. Wall Construction
8 Site Plan with North Arrow		19. Architect or Engineer other	frame . Wu
	./	unknown 20. Contractor or Builder	32. Roof Type & Material 16
	- "	(20)	cross gable-asphalt sh
	1 1	21. Original Use, if apparent	Front Side
<del>  X</del>		residence OIA	n/a side n/a 34. Wall Treatment clapboard
		22 Present Use	diag. plank/imbricated
	*	residence	35. Plan Shape Square
	.	23 Ownership Publi	c ! ! 36. Changes Addition .
100	57.	24. Owner's Name & Address.	(Explain Altered XX
		il known	
Coordinates UT	м	Wayne Cox	37 Condition excellent
l at Long		Richmond, Missouri	Exterior excellent
Sile Li	Structure 1 i		38. Preservation Yes OXX Underway? No XX
BuildingXX	Object	26. Local Contact Person or Organization	The Alan
	12 Is II Yes VIX Eligible? No 11	20. Local Contact Person of Organization	By What? Yes III
Register? No XX		27. Other Surveys in Which Included	
3 Part of Estab Yes I I Hist Dist.? NoXX	14. District Yes I Potent'l? No XX		40. Visible from Yes XX
15 Name of Established Distr			Public Road? No ^^
			Frontage on Road
12 Further Description of Imp	ortant Features		
Queen Anne derivatio	n house has cro	ss gable roof, Eastlake detai	1s /
intersperced with di	which displays	lines of imbricated shingles iding. First story is clapbo	
Primary facade has to	wo entra-ces fl	anked by windows. Each gable	ard. Photo
version of Palladian	window with la	rge l-over-1 light window flan	nked /
by smaller 1-over-1	windows, sharing	q lintels and sills. Origina	
window sasnes with w	eights remain.	Interior displays dark oak (	cont)
is mistory and Significance			
house was built appr	oximately 1916.	Built probably by Joe Bryan.	Farm owned ca. 1920's
remodelling.	was later owne	d by the Rippy family who inst	tituted much of the interior
· cmode i i i i i g ·			
A Description of Farmer			
Description of Environment	_		
un working farm, wit	n large barn pr	edating house (see #60B)	
5 Sources of Information			
On-site inspection.			46. Prepared by
Mrs. Wayne Cox.			Miller and Cameron
Abstract.			47 Organization RCHS & M



FLOORPLANS

NOT TO SCALE




PHOTOGRAPH

#42 Cont.

woodwork. Doors have ovals of beveled glass. Stairway with turned balusters. #36: Although the exterior is virtually unchanged, except for a new porch on the primary facade, the interior has been remodeled to an extent. Brick firewall added for wood stove in livingroom, kitchen completely remodelled, porch to rear enclosed. Frnech doors between diningroom and livingroom were replaced with sliding doors. Bath added, new door cut into hallway. Paneling throughout. Newel post of stair way replaced by pier when stairway enclosed.



	04B 1 Pre	sent Name(s)	
County	OPO	Cox Barn	
Ray		ner Namo(s)	
3 Location of Negatives RCHS & M	1		14.
6 Specific Lucation		16 Themslic Category	28 No of Stories one & 10
	2010	010 030	29. Basement? Yes
525 T53N	2100	BEFORE 1905	30. Foundation Material
vic Millvillo	al, Township & Vicinity	18 Style or Design vernacular	ashlar stone 15
Sile Plan with North A	WIIII	19. Architect or Engineer unknown	- Curana I II
		20. Contractor or Builder i unknown	32. Roof Type & Material gable-tin
			33. No. of Bays 54
' ' '	h	21. Original Use if apparent barn	34. Wall Treatment 20
	Φ	22 Present Use	vertical planking
		barn 23 Ownership Public II	35. Plan Shape rectangula
		PrivateXX	36. Changes Addition (Explain Altered in #42) Moved
		24. Owner's Name & Address, if known	27 C41
Coordinates	UTM	Wayne Cox	Interior fair
Lat		Richmond, Missouri	Exterior fair
Site Li	Structure	25 Open to Yes I I Public? No XX	38. Preservation Yes Underway? No
BuildingXX	Object I I	26. Local Contact Person or Organization	39 Endangered? Yes
On National Yes !! Rigister? No XX	12 Is II Yes I I Eligible? NoXXI		By What? No
Part of Estab Yes II	14. District Yes II	27. Other Surveys in Which Included	40. Visible from Yes
Hist Dist.? NoXX	Potent'l? No XX		Public Road? No
Name of Established D	istrict		41. Distance from and Frontage on Road
Further Description of			
ransverse crib ba	arn with shed add nain as does tin	ition. Vertical plank siding. roofing.	Photo
, , , , , , , , , , , , , , , , , , ,			
History and Significance	e e		./
Barn built for mileart of the barn words installed ca.	es by Zachary Ta vas dismantled ca 1915 when prope	ylor White. Property purchased 19 . 1907 and replaced with shed and rty was owned by Joe Bryan. His s roof while installing the rods.	grainery. Lightning
History and Significance arn built for mile art of the barn we rods installed ca. hoes with spikes	es by Zachary Ta vas dismantled ca 1915 when prope to walk over the	. 1907 and replaced with shed and rty was owned by Joe Bryan. His s	grainery. Lightning
History and Significance arn built for mile art of the barn words installed cachoes with spikes	es by Zachary Ta vas dismantled ca 1915 when prope to walk over the	. 1907 and replaced with shed and rty was owned by Joe Bryan. His s	grainery. Lightning
History and Significance arn built for mile art of the barn words installed cachoes with spikes	es by Zachary Ta vas dismantled ca 1915 when prope to walk over the	. 1907 and replaced with shed and rty was owned by Joe Bryan. His s	grainery. Lightning
History and Significance arm built for mile art of the barn words installed cachoes with spikes  Description of Environment a working farm.	es by Zachary Ta vas dismantled ca 1915 when prope to walk over the	. 1907 and replaced with shed and rty was owned by Joe Bryan. His s	grainery. Lightning on, Joe <del>Jr</del> . wore track
History and Significance Barn built for mile art of the barn words installed ca. Shoes with spikes  Description of Environment of a working farm.	es by Zachary Ta vas dismantled ca 1915 when prope to walk over the	. 1907 and replaced with shed and rty was owned by Joe Bryan. His s	grainery. Lightning on, Joe Jr. wore track  46. Prepared by
History and Significance arm built for mile art of the barn words installed ca. hoes with spikes  Description of Environment and working farm.  Sources of Information are.	es by Zachary Ta vas dismantled ca 1915 when prope to walk over the nent and Outbuildings	. 1907 and replaced with shed and rty was owned by Joe Bryan. His s	grainery. Lightning on, Joe Jr. wore track  46. Prepared by  Miller and Cameron
History and Significance Sarn built for mile art of the barn woods installed ca. hoes with spikes  Description of Environmental and working farm.	es by Zachary Ta vas dismantled ca 1915 when prope to walk over the nent and Outbuildings	. 1907 and replaced with shed and rty was owned by Joe Bryan. His s	grainery. Lightning on, Joe Jr. wore track  46. Prepared by



FLOORPLANS

NOT TO SCALE



PHOTOGRAPH




1 No / 2 4 Pr	esent Name(s)	
63	Miller Residence	
Ray 5 0	her Namo(x)	
CHS & M	White Residence	
Specific Lucation Il miles northeast of Richmond	16 Thematic Calegory	26 No of Stories $1\frac{1}{2}-1-1$
on unmarked road east off highway	17 Datu(s) or Period	29. Basement? Yes it
B. 526 T530 27W	ca. 1894	No ½
7 City or Town If Rural, Township & Vicinity		30. Foundation Material ashlar stone
Millville Vic.	vernacular 09	31. Wall Construction
8 Site Plan with North Arrow	19. Architect or Engineer	frame LUL
,	unknown	32. Roof Type & Material
VIII N	20. Contractor or Builder	gable-comp, shingles
	unknown	33. No. of Bays Front 3 Side 163
	21. Original Use, if apparent residence	
	22 Present Use	34. Wall Treatment weatherboard 2
y - No	residence	35. Plan Shape rectangular
	23 Ownership Public !	36. Changes Addition X:
9 7 ,	Private k	(Explain Altered X
233	24. Owner's Name & Address,	in #42) Moved
	- Mr & Mrs. Earl Miller	37 Condition good
9 Guardinates UTM	Route 4, Richmond, Missouri	
Luny	20.0	Exterior good
Site 1   Structure 1	Public 2	38. Preservation Yes Underway? No X
Building XI Object 1 1	26 Local Contact Person or Organization	
11 On National Yes 11 12 Is II Yes M	The second of Signification	By What? Yes II
Register? No.4. Eligible? No.11	27. Other Surveys in Which Included	
13 Part of Estab Yes I 14. District Yes II Hist Dist.? No XI Potent'I? No XI		40. Visible from Yes X
15 Namu of Established District	4	Public Road? No
13 Name of Established District		41. Distance from and Frontage on Road
		100 feet
42 Further Description of Important Features		
12 story central hall house. Neoc.	lassic detailing of facade and	
windows. Interior features plain	Mondwork: manalad doors with	
glass panes. #30: Addition of roo	om and bath to moon of house and	Photo
enclosed porch to primary facade. Stove chimneys remain although stor	A utility room was a later addition	· ·
Total Chilming's Temain although Stor	res removed.	
43 History and Significance	•	
	Jr. 4 m 1026	
Land was deeded to Nehemiah Comstoo	in 1830. House constructed ca.	1894 by the White family
White Brothers Allan, Hugh and Ashl Present owners acquired the property		
Tanada wa property	- 1741 IIOM Bankers Lile Insuran	ce Co. of Nebraska.
44 Description of Environment and Outbuildings		

Abstract of Property.
Keener Wall.
On-site inspection.

On a working farm with later outbuildings.

46. Prepared by
Mrs. Thelma Miller
47 Organization
RCHS & M
48. Date 49 Revision Date(s)



FLOORPLANS


NOT TO SCALE



PHOTOGRAPH



RAI	4 Present Name(s)	
2 County	Dollins House	
Ray	5 Other Name(s)	
3 Location of Negatives	Riggs House; Hawkins House; Crowley H	louse
6 Specific Lucation	16. Thernatic Category	28. No. of Stories 2
West half of Northeast quart	ter 030	29. Basement? Yes 05 half No 1.
of Section 5, Township 52,	17 Date(s) or Period	half No!
Range 28.	ca. 1880	30. Foundation Material
7 City of Town Il Rural, Township & \	Vicinity 18 Style or Design	masonry Ol
Rayville	Second Empire 40 20	31. Wall Construction
H Sity Plan with North Arrow	19. Architect or Engineer	frame WW
N II-	unknown	32. Roof Type & Material HP SA
1	20. Contractor or Builder	truncated hip-asphalt
(1)	unknown OB	33. No. of Bays
	21. Original Use, if apparent	Front 3 Side 2
	residence DIA	Front 3 Side 2  34. Wall Treatment
	22 Present Use	metal siding
	residence	35. Plan Shape cruciform
	23 Ownership Public !!	36. Changes Addition :
	Private 😾	
	24. Owner's Name & Address,	in #42) Moved :
	if known	37. Condition
9 Coordinates UTM	Robert William Dollin	Interior fair
t at	P.O. Box 163, Rayville MO	Exterior good
Light	25. Open to Yes !!	38. Preservation YesX
10 Site ! 1 Struc	ture   i Public? No lx	Underway? No
Building Ki Ob	ject     26. Local Contact Person or Organization	39. Endangered? Yes 11
11 On National Yes II 12. Is It	Yes Ki	By What? No 6
Register? No X Eligible?	No 11 27. Other Surveys in Which Included	
	Yes II	40. Visible from Yes X
Hist Dist? No Xi Polent'l?	·No XI	Public Road? No 1:
15 Name of Established District		41. Distance from and
		Frontage on Road
,		
42 Further Description of Important Featur	es House dominated by low, truncated hip	ped
Windows have lintels support facade has a front porch wi Interior chimneys at center Metal siding obscures origin	nd frieze, supported by carved brackets. rted by smaller brackets. The primary ith spindle decoration and turned posts. r of house. Interior has 9 rooms. #36. inal clapboarding. A small lean-to additional clapboarding.	Photo
tion was attached to the we	est facade.	
	iggs and his wife Leah homesteaded the predators all the property in Rayville.	
Thomas Hawkins were the own also one of the men who, ac called at the time, lacked	ners of the house in 1889. Thomas Hawking coording to local tradition, since Rayvi a post office of their own, decided to	ns was a banker. He was lle, or Hallard as it was rectify the lack. They
44 Description of Environment and Outbuil	ling miles west, pulling aflat car behin	a a rallroad hand (con't)
In the small town of nayvi.	lle. A shed is nin the rear of the prop	erty.
		(
	1	
45 Sources of Information		46. Prepared by
Ray County History, 1973.		Tom Stokes
Arla Hawkins, Rayville, Miss	aumi	47. Organization
	OUT 1	RCHS & M
On-site inspection.		48, Date 49 Revision Date(s)



FLOORPLANS

NOT TO SCALE



**PHOTOGRAPH** 


#43. Con't.car and "swiped" the post office of Foote Station and repositioned it in their town.



#43 Con't

AND STREET

sold general goods for that era to the people of the surrounding area. Thomas Jeptha Ogg was born in Kentucky in 1837. He travelled to Missouri and settled on a farm 2 miles east of the town of Albany where he lived until 1864 when he moved to this property. Part of this he owned in partnership with his brother, William A Ogg. The house was built about 1865. Thomas built a steam-powered grist mill which drew trade from a wide area. A sawmill was also constructed, both mills running from about 1867-1905. The house has remained in the Ogg family to the present. It is now vacant and has not been lived in since 1973.



FLOORPLANS 1

NOT TO SCALE



PHOTOGRAPH



48. Date 5/79


49 Revision Dale(s)

Office of Historic Preservation, P.O. Box 176, Jefferson City, Missouri 65101

On-site inspection.

Stage of the Name(s)  Sigh House; Barger House  Special Totalion Hwy 10, Sikhorn  Second Totalion Hwy 10, Sikhorn  Sikhar Second Hwy 10, Sikhorn  Sunding X  Somethin Sikhar Hwy 11, Sikharn  Sunding X  Somethin Sikharn  Somethin Sikha	N: 48	4 Pres	Present Name(s)	
Size in Structure is Structure	ntu .	St	tage Coach Inn	
Specific location Hay 10, Eikhorn  16 Themsile Caisgory  17 Date(s) or Period  28. No of Stores 2  29. Sasement?  18 Style or Design  18 City or Ioen  18 Themsile Caisgory  29. Sasement?  19 Architect or Engineer  10 Consistence or Builder  20 Concination of Builder  20 Concination of Builder  21 Orignal Use, if apparent  12 Present Use  22 Present Use  23 Ownership  24. Ownership  25. Open to  16 Public 1  17 Private by  26 Concination of Builder  27 Present Use  28 Present Use  29 Ownership  20 Ownership  20 Ownership  21. Ownership Public 1  22 Present Use  23 Ownership  24. Ownership Public 1  25. Open to  26 Public 1  26 Used Contact Person or Organization  26 Concination of World Interior  27 Ownership Public 1  28 Used Contact Person or Organization  29 Endangered? Ves 11  29 Endangered? Ves 11  29 What?  20 Ownership  20 Ownership  21 Ownership Public 1  22 Ownership  23 Ownership  24. Ownership Public 1  25 Open to  26 Used Contact Person or Organization  26 Used Contact Person or Organization  27 Ender Organization  28 Used Contact Person or Organization  29 Endangered? Ves 11  29 What?  20 Used Style Interior  20 Ownership  20 Ownership  21 Ownership Public 1  22 Ownership  23 Ownership  24. Ownership Public 1  25 Open to  26 Used Contact Person or Organization  26 Used Contact Person or Organization  27 Ender Organization  28 Used Contact Person or Organization  29 Endangered? Ves 11  29 Endangered? Ves 11  29 Endangered? Ves 11  29 What?  20 Used Style Interior  20 Ownership  20 Ownership  21 Ownership Public 1  22 Ownership  23 Ownership  24 Ownership  25 Open to  26 Used Contact Person or Organization  26 Used Contact Person or Organization  27 Endangered? Ves 11  28 What?  28 Used Contact Person or Organization  29 Endangered? Ves 11  29 What?  20 Used Style Public 1  20	Ray	5 Other Namo(s)		
To baids or Period  Caty in Town  18 Rural, Township & Vicinity Richanond  The Plan with Nurth Arrow  19 Architect or Engineer unknown  20 Contractor or Engineer unknown  21 Original Use, if apparent tavern of the residence  22 Present Use  23 Ownership Private by 14 Wall Treatment  24 Ownership Private by 25 Open to Rt. 2, Excelsior Springs, MO  26 Contractor or Organization  The Stab Yes I I I I I I I I I I I I I I I I I I I	Location of Negatives	Si	sk House; Barger House	
To Dated or Period 20. Basement?  17 Dated or Period 20. 18 Siyle or Design Richmond  18 Rural Township & Vicinity Richmond  19 Architect or Engineer unknown 20 Contractor or Builder unknown 21. Original Use, if apparent tavern old or to or tavern old or to or tavern old or tavern old or to	Specific Lucation Hwy 10.	Eikhorn	16. Thernalic Calegory	28. No. of Stories 2
City of Tuwn II Hard, Township & Vicinity Richard Of Rederal 30. Foundation Material ashlar stone 31. Well Construction Federal 31. Well Construction Frame Unknown 31. Well Construction Frame Unknown 32. Roof Spys & Malerial Construction				
If Street or Service is public in the state of the interior best or state or service from the service from the state or service from the service from service f				UGTT
Richmond Site Plan with Nuth Allow  19. Architect of Engineer unknown 20. Contractor or Builder unknown 21. Original Use, if apparent taverm old 22. Present Use residence 23. Ownership Private or 24. Owner's Name a Address, if known Katherine Sisk Long  25. Open to Public 1: Building K  Contractor No. K  Engible? No. I  27. Owner's Name a Address, if known Katherine Sisk Long  28. Open to Public 1: Building K  Contraction				
19. Architect or Engineer unknown 30. Contractor or Builder unknown 31. Conjugative, if apparent tavern 32. Roof Type & Material dealth shingles unknown 32. Roof Type & Material dealth shingles unknown 32. Roof Type & Material dealth shingles unknown 33. Roof Bays 5 Front 3 Side 1 34. Wail Treatment of 32. Roof Bays 5 Front 3 Side 1 34. Wail Treatment of 32. Roof Bays 5 Front 3 Side 1 35. Plan Shape rectangular residence 23. Ownership Fublic it Private to 35. Plan Shape rectangular Ratherine Size Rt. 2. Excelsior Springs, NO.  8 Sine it Structure it Object it Public?  8 Open to Public?  8 Open to Public?  9 Open to Public?  9 Open to Public?  10. On National Yes it Building X 11. District Yes it Public?  12. Structure it Object it Public?  13. Condition interior good 14. Limit Part of Estab Yes it H. District Yes it Public?  15. Other Surveys in Which Included  16. Persarvation Yes X 17. Other Surveys in Which Included  17. Other Surveys in Which Included  18. Wail Treatment of a Surveys in Which Included  19. What Yes It H. District Yes It Public Road?  19. What Yes X 10. Structure it Object It No. X 21. Other Surveys in Which Included  19. What Yes X 10. Structure it Public Road?  10. Wail Treatment of Surveys in Which Included  10. Visible from Yes X 11. District Yes It Public Road?  10. Visible from Yes X 12. District Yes It Public Road?  10. Visible from Yes X 11. District From Surveys are dominated by a walnut stair-case, #36., The house has undergrone great atteration over the years. Its primary facade originally faced south, now faces north to new Hwy 10. Original two-story porch on that side was removed. In 1934, the house was purchased by the Sisks, and was in very poor condition. A kitchen, bedroom and bath was added on the east (con't Hustory and Missouri City. The cld road can still be seen in the back of the house. People would get off the boats at Westport Landing close to Missouri City, cape to the Stagescoach Inn and stayed overnight of longer. Then they continued west to St. Joseph or to inber		ownship & Vicinity		
miknown  20. Contractor or Builder unknown  21. Original Use, if apparent tavern of the state of				frame wu
Unknown 21. Original Use, if apparent tavern 110 12 Present Use residence 23 Ownership Public 11 Private W 24. Owner's Name & Address, if shown Katherine Sisk Rt. 2, Excelsior Springs, MO 25. Open 10 No. 18 Preservation Katherine Sisk Rt. 2, Excelsior Springs, MO 25. Open 10 No. 18 26. Local Contact Person or Organization Windows 12 No. 18 27. Other Surveys in Which Included 28. Cocal Contact Person or Organization Windows 19 No. 18 29. Endangered? Yes; If his libra? No. 18 20. Cocal Contact Person or Organization Windows? No. 18 20. Other Surveys in Which Included 27. Other Surveys in Which Included 28. Cocal Contact Person or Organization Windows? No. 18 29. Endangered? Yes; If his libra? No. 18 20. Other Surveys in Which Included 29. Other Surveys in Which Included 40. Visible from Yes X Public Road? No. 18 41. Distance From and Frontage on Road 41. Distance from and Frontage on Road 42. The house has undergone great alteration over the years. Its primary facade originally faced south, now faces north to new Hay 10. Original two-story porth on that side was removed.  In 1934, the house was purchased by the Sisks, and was in very poor condition. A kitchen, bedroom and bath was added on the seat (on the House.)  People would get off the boats at Westport Landing close to Missouri City, came to the Stagecoach Inn and stayed overnight or longer. Then they continued west to St. Joseph or to iliberty. A local tradition says that Jenny Lind once sang on the second story of the south porch. The Inn was looted during the Civil Nar. The land on which the Inn stands has (cont Oesception of Environment and Outbuildings)  On a hilly lot, with woods behind. A barn east of the house is in poor condition. It is a the outskirts of the tiny town of Elkhorn.  Sources of Information "History of Elkhorn" by Kathy Duncan, The Daily Standard of Windows of Elkhorn.  Sources of Information "History of Elkhorn" by Kathy Duncan, The Daily Standard of Tom Stokes  40. Prepared by The	/	6	unknown	32. Roof Type & Material
21. Original Use, if apparent tavern 1 22 Present Use residence 23 Ownership Public	/	20		
Coundinates Lat Linin    24. Owner's Name & Address.   1	0/	-		9.4
Coundinates Lat Linin    24. Owner's Name & Address.   1	37		tavern 015 036	) 1
Coundinates Lat Linin    24. Owner's Name & Address.   1	CHAIL			
Coundinates Lat Linin    24. Owner's Name & Address.   1	1		residence	
24. Owner's Name & Address.  If known  Katherine Sisk Rt. 2, Excelsior Springs, MO  Site:   Structure   Open to		77.7		
Conditionales   UTM   Katherine Sisk   Rt. 2, Excelsior Springs, MO   Exterior   good   Exterior   Good				(Explain
Rt. 2, Excelsior Springs, MO    Structure			if known	
Site:   Structure   Object   Oh National Year   Object   Object   Object   Object   Object   Oh National Year   Object	Coordinates UTM			
Site:   Structure   Object   Public?   No   Mo   Mo   Mo   Mo   Mo   Mo   Mo				
On National Yes it Register? No K 12.15 It Yes Kt Eligible? No It 27. Other Surveys in Which Included 27. Other Surveys in Which Included 27. Other Surveys in Which Included 28. Other Surveys in Which Included 29. Other Surveys in Which Included 40. Visible from Yes Xt Public Road? No It 14. District Yes It Potentif? No Kx 14. District Yes It Potentif? No Kx 15. Other Surveys in Which Included 41. Visible from Yes Xt Public Road? No It 15. Other Surveys in Which Included 41. Visible from Yes Xt Public Road? No It 15. Other Surveys in Which Included 41. Visible from Yes Xt Public Road? No It 15. Other Surveys in Which Included 41. Visible from Yes Xt Public Road? No It 15. Other Surveys It Survey		60		
On National Yes   12 is it Eligible? No   13 is it is			26 Local Contact Person or Organization	39. Endangered? Yes 11
Part of Established District  No Ky  Name of Established District  Further Description of Important Features The building is 70° long with central hallways on both floors. End interior brick chimneys service fireplaces in each room. The hallways are dominated by a walnut staircase. #36.: The house has undergone great alteration over the years. Its primary facade originally faced south, now faces north to new Hwy 10. Original two-story porch on that side was removed. In 1934, the house was purchased by the Sisks, and was in very poor condition. A kitchen, bedroom and bath was added on the east (con't)  History and Significance The Inm was built in 1830, a stage stop on the old State road between Liberty and Missouri City. The old road can still be seen in the back of the house. People would get off the boats at Westport Landing close to Missouri City, came to the Stagecoach Inn and stayed overnight of longer. Then they continued west to St. Joseph or to ilberty. A local tradition says that Jenny Lind once sang on the second story of the south Description of Environment and Outbuildings  On a hilly lot, with woods behind. A barn east of the house is in poor condition. It is a the outskirts of the tiny town of Elkhorn.  Sources of Information  "History of Elkhorn" by Kathy Duncan. The Daily Standard of Excelsior Springs, Mo., June 29, 1978, p. 7.	On National Yes II 12.	Is It Yes Ki		
Name of Established District  Further Description of Important Features The building is 70° long with central hallways on both floors. End interior brick chimneys service fireplaces in each room. The hallways are dominated by a walnut starcase. #36.1 The house has undergone great alteration over the years. Its primary facade originally faced south, now faces north to new Hwy 10. Original two-story porch on that side was removed. In 1934, the house was purchased by the Sisks, and was in very poor condition. A kitchen, bedroom and bath was added on the east (con't)  History and Significance The Inn was built in 1830, a stage stop on the old State road between Liberty and Missouri City. The old road can still be seen in the back of the house, People would get off the boats at Westport Landing close to Missouri City, came to the Stagecoach Inn and stayed overnight or longer. Then they continued west to St. Joseph or to Liberty. A local tradition says that Jenny Lind once sang on the second story of the south porch. The Inn was looted during the Civil War. The land on which the Inn stands has (cont Description of Environment and Outbuildings)  On a hilly lot, with woods behind. A barn east of the house is in poor condition. It is not the outskirts of the tiny town of Elkhorn.  Sources of Information  "History of Elkhorn" by Kathy Duncan. The Daily Standard of Excelsior Springs, Mo., June 29, 1978, p. 7.	.,		27. Other Surveys in Which Included	
Further Description of Important Features The building is 70° long with central hallways on both floors. End interior brick chimneys service fireplaces in each room. The hallways are dominated by a walnut staircase. #36.: The house has undergone great alteration over the years. Its primary facade originally faced south, now faces north to new Hwy 10. Original two-story porch on that side was removed. In 1934, the house was purchased by the Sisks, and was in very poor condition. A kitchen, bedroom and bath was added on the east (con't).  History and Missouri City. The old road can still be seen in the back of the house. People would get off the boats at Westport Landing close to Missouri City, came to the Stagecoach Inn and stayed overnight or longer. Then they continued west to St. Joseph or to Liberty. A local tradition says that Jenny Lind once sang on the second story of the south porch. The Inn was looted during the Civil War. The land on which the Inn stands has (cont Description of Environment and Outbuildings  On a hilly lot, with woods behind. A barn east of the house is in poor condition. It is a the outskirts of the tiny town of Elkhorn.  Sources of Information  "History of Elkhorn" by Kathy Duncan. The Daily Standard of Excelsior Springs, Mo., June 29, 1978, p. 7.				
Further Description of Important Features The building is 70' long with central hallways on both floors. End interior brick chimneys service fire-places in each room. The hallways are dominated by a walnut staircase. #36.: The house has undergone great alteration over the years. Its primary facade originally faced south, now faces north to new Hwy 10. Original two-story porch on that side was removed. In 1934, the house was purchased by the Sisks, and was in very poor condition. A kitchen, bedroom and bath was added on the east (con't).  History and Significance The Inn was built in 1830, a stage stop on the old State road between Liberty and Missouri City. The old road can still be seen in the back of the house.  People would get off the boats at Westport Landing close to Missouri City, came to the Stagecoach Inn and stayed overnight or longer. Then they continued west to St. Joseph or to inberty. A local tradition says that Jenny Lind once sang on the second story of the south porch. The Inn was looted during the Civil War. The land on which the Inn stands has (cont. Description of Environment and Outbuildings  On a hilly lot, with woods behind. A barn east of the house is in poor condition. It is not the outskirts of the tiny town of Elkhorn.  Sources of Information  "History of Elkhorn" by Kathy Duncan. The Daily Standard of Excelsior Springs, Mo., June 29, 1978, p. 7.  46. Prepared by Tom Stokes  47. Organization  ACC. organization				
hallways on both floors. End interior brick chimneys service fire- places in each room. The hallways are dominated by a walnut stair- case. #36.: The house has undergone great alteration over the years. Its primary facade originally faced south, now faces north to new Hwy 10. Original two-story porch on that side was removed. In 1934, the house was purchased by the Sisks, and was in very poor condition. A kitchen, bedroom and bath was added on the east (con't  history and Significance The Inn was built in 1830, a stage stop on the old State road between Liberty and Missouri City. The old road can still be seen in the back of the house. People would get off the boats at Westport Landing close to Missouri City, came to the Stagecoach Inn and stayed overnight or longer. Then they continued west to St. Joseph or to ilberty. A local tradition says that Jenny Lind once sang on the second story of the south porch. The Inn was looted during the Civil War. The land on which the Inn stands has (cont. Description of Environment and Outbuildings  On a hilly lot, with woods behind. A barn east of the house is in poor condition. It is  The outskirts of the tiny town of Elkhorn.  Sources of Information "History of Elkhorn" by Kathy Duncan. The Daily Standard of Excelsior Springs, Mo., June 29, 1978, p. 7.  46. Prepared by Tom Stokes  47. Organization Porce & M.	,	•		Frontage on Road
hallways on both floors. End interior brick chimneys service fire- places in each room. The hallways are dominated by a walnut stair- case. #36.: The house has undergone great alteration over the years. Its primary facade originally faced south, now faces north to new Hwy 10. Original two-story porch on that side was removed. In 1934, the house was purchased by the Sisks, and was in very poor condition. A kitchen, bedroom and bath was added on the east (con't  history and Significance The Inn was built in 1830, a stage stop on the old State road between Liberty and Missouri City. The old road can still be seen in the back of the house. People would get off the boats at Westport Landing close to Missouri City, came to the Stagecoach Inn and stayed overnight or longer. Then they continued west to St. Joseph or to ilberty. A local tradition says that Jenny Lind once sang on the second story of the south porch. The Inn was looted during the Civil War. The land on which the Inn stands has (cont. Description of Environment and Outbuildings  On a hilly lot, with woods behind. A barn east of the house is in poor condition. It is  The outskirts of the tiny town of Elkhorn.  Sources of Information "History of Elkhorn" by Kathy Duncan. The Daily Standard of Excelsior Springs, Mo., June 29, 1978, p. 7.  46. Prepared by Tom Stokes  47. Organization Porce & M.	,			
Stagecoach Inn and stayed overnight or longer. Then they continued west to St. Joseph or to Liberty. A local tradition says that Jenny Lind once sang on the second story of the south porch. The Inn was looted during the Civil War. The land on which the Inn stands has (cont. Description of Environment and Outbuildings)  On a hilly lot, with woods behind. A barn east of the house is in poor condition. It is not the outskirts of the tiny town of Elkhorn.  Sources of Information "History of Elkhorn" by Kathy Duncan. The Daily Standard of Excelsior Springs, Mo., June 29, 1978, p. 7.  46. Prepared by Tom Stokes 47. Organization Double 1. M.	hallways on both fl places in each room case. #36.: The h years. Its primary to new Hwy 10. Ori In 1934, the house condition. A kitch history and Significance Liberty and Missour	toors. End in the hallwa house has under facade original two-sto was purchased hen, bedroom a The Inn was buri City. The	terior brick chimneys service fire- ys are dominated by a walnut stair- rgone great alteration over the nally faced south, now faces north ry porch on that side was removed. by the Sisks, and was in very poor and bath was added on the east (con ilt in 1830, a stage stop on the of old road can still be seen in the	Photo  Id State road between back of the house.
"History of Elkhorn" by Kathy Duncan. The Daily Standard of Excelsior Springs, Mo., June 29, 1978, p. 7.  Tom Stokes  47. Organization	Stagecoach Inn and Liberty. A local to porch. The Inn was Description of Environment On a hilly lot, with	stayed overni tradition says looted durin and Outbuildings the woods behin	ght or longer. Then they continued that Jenny Lind once sang on the seg the Civil War. The land on which d. A barn east of the house is in	d west to St. Joseph or to second story of the south the Inn stands has (cont.
Excelsior Springs, Mo., June 29, 1978, p. 7.	Sources of Information	" by Vather De	noon The Delle Chandens of	
DOUG & M	Excelsion Spri	nes. Mo. Jun	e 29. 1978. p. 7.	
			/9 -/109 20 10	

- #42. Con't. fireplaces improved, siding added to the exterior. A new portico was constructed on the new primary facade, two new triple windows flank the original front door, which was moved from the south side.
- #43. Con't. changed hand several times. In 1879 Christian Barger bought a little over 200 acres. He was a farmer and merchant. The land was sold to W.G. O'Dell after Christian's death. In 1911, it was acquired by T.C. Hamilton Other legends about the tavern say that Barnum & Bailey Circus stayed there at the height of their fame, and that Jesse James stopped there once and had his horse shod at the barn to the east, which still remains. Owners of the tavern have included: Jacob Stallings, its first owner; and Clayton Jacobs who ran the tavern in the 1850's.







Office of Historic Preservation, P.O. Box 176, Jefferson City, Missouri 65101

HISTORIC INVENTORY 4 Present Name(s) No Ш Easthill 2 County 5 Other Namo(s) Gooch House; Allen-Jacobs House 3 Location of Negatives 28. No of Stories 16. Thematic Category 6 Specific Lucation I mi. E of Hywy 13S Yes X 29. Basement? 030 No I . root cellar 17 Date(s) or Period S4 T510 27W 30. Foundation Material 1835-1836 ashlar limestone Style or Design Il Rural, Township & Vicinity 31. Wall Construction LB 7 City or Town 09 Federal Richmond vicinity brick 19. Architect or Engineer 8 Site Plan with North Arrow 32. Roof Type & Material unknown gable-asphalt shingles 20. Contractor or Builder pnch 33. No. of Bays Gunnells & McGonigal Side Front 5 21. Original Use, if apparent 34. Wall Treatment common bond brick residence OIA 22 Present Use 35. Plan Shape L-shaped residence Addition ... 36. Changes Public | 23 Ownership Allered IX (Explain Private ly Moved I in #42) 24. Owner's Name & Address. Dec 37. Condition if known good Kenneth R. Gooch Interior Rt. 4, Box A-33, Richmond MO UTM Exterior good Coordinates Lat Yes X Preservation 25. Open to Long No I Underway? No KI Public? Structure 1 i Site Li Yes II 39 Endangered? 26. Local Contact Person or Organization Object | | Building I By What? Yes XI 12 Is It Yes II 11. On National 27. Other Surveys in Which Included No II Eligible? No X: Register? Yes ' X Visible from Yes 14. District Part of Estab Yes II No i i Public Road? No E Missouri Historic Sites Potent'l? No be Hist Dist.? 41. Distance from and Catalogue, 1963. 15 Name of Established District Frontage on Road 42. Further Description of Important Features House features doublehung windows with limestone sills, and central primary entrance. Exterior end chimneys. Facade is devoid of ornamentation. Walls are three bricks in width (ca. 14"). All floor joists are made of walnut Photo logs 12" deep with bark still visible. The house has 2 attic windows on each secondary facade. On the interior, the house has 2 rooms on each floor which are separated by a wide central hallway with

stairway. A back hall with another stairway and kitchen (con't)

43 History and Significance The land of Easthill was first entered by John McGaugh, in 1821. Dr. Thomas Allen of Virginia purchased itin 1834. After his wife's death, Allen, his 5 children and slaves came to Richmond, where they lived in a log cabin on the farm. The house was begun in 1835. Bricks were made from clay taken from the Allen land and burned in the same kiln as Dr. Allen's brother James' mill. Lumber of oak and walnut was taken from

44 Description of Environment and Outbuildings

None of the original outbuildings exist today. An old barn is located to the rear of the The property consists of 150 acres, with an old cemetery northwest corner of the land.

45 Sources of Information Emma Jean Gooch

HIJOS

HYWY

Ray County History, 1973.

Missouri Historic Sites Catalogue, 1963.

On-site inspection.


46. Prepared by Tom Stokes

47. Organization RCHS & M

49 Revision Date(s) 48. Date

5/79

- #42. Con't. form the lastory "L" in the rear. All rooms have fireplaces, one of which has been closed. All woodwork, even in the attic, is walnut and floors are white oak in wide planks. Windows are recessed in the 'outside walls with wide oak casing and sills. There are chair rails in all the downstairs rooms. #36.: Two porches, which were probably not original, were removed at an unknown time. The present owners added a bathroom and utility room about 1962, and installed a gas furnace. Some renovation has been done and is continuing. Window frames are not original, although sills and casings are.
- #43. Con't. trees on the property. The Gunnells, brick masons, laid the brick and the McGonigle Brothers did the woodwork, all by hand. The house was completed in 1836. Local tradition says that the notorious James Brothers played for a dance in this house once. After the death of Dr. Allen, Easthill came in to the possession of: Col. Benjamin Brown (1856); Dr. W.M. Mosby (1862); James NcCowan (1867); Jerimiah Anderson and Kate I. Murray (1869). It became the home of Kate Murray and family for 21 years. In 1903 S.D. Jacobs purchaseddthe house and it became once again a showplace and social center. Easthill remained in the Jacobs family until 1961, when it was purchased by the Present owners. A barn that was built around and over an original log cabin was tern down shortly after the Gooches moved in. The log house was moved to Liberty Missouri by Mr. & Mrs. Donald Pharis who reconstructed it at their farm. This was possibly the log house first constructed by Dr. Allen and his family as Easthill was under construction.



FLOORPLANS

NOT TO SCALE






PHOTOGRAPH





No III		ire Baber Home	
County	5 Other	Namo(s)	
Location of Negatives	Gro	oteschnour; Duvall Res.; Wagoner H	Res.; Macklin Res; Hill F
RCHS & M	010		128. No of Stories 2
Specific Lucation R.F.D. 4. west of Richmond city	20.00	16. Thematic Category	29. Basement? Yes X
		17 Date(s) or Period	No t
n south on unmarked gradicates and in the south on unmarked gradies.	ver road	1851-1854; ca. 1885	30. Foundation Material
	hin & Vicinity	10 Civila or Design	brick 30
City or Town II Rural, Towns Richmond	mp a vicinity	Federal 31 09	31. Wall Construction brick
Site Plan with North Arrow	10	19. Architect or Engineer	
0	6	unknown 30 20. Contractor or Builder Prich	32. Roof Type & Material GE gable & Flat-asphalt
$\omega_{\underline{}}$	_ (.)	unknown BA	33. No. of Bays
	9	21. Original Use, if apparent	Front 5 Side 6
	IN	residence OIA	34. Wall Treatment
E.3   11		22 Present Use	common bond
	Mb.	residence	35. Plan Shape L-shaped
٦ ــــــــــــــــــــــــــــــــــــ	( ) ( )	23 Ownership Public   Private   †	(Explain Altered)
		24. Owner's Name & Address.	in #42) Moved
smoke house		if known	37. Condition
root cellar		Howard Hill	Interior excellent
Coordinates UTM		R.F.D. 4, Richmond, Missouri	Exterior excellent
Long	•	25. Open to Yes I i	38. Preservation Yes Underway? No.
Site 11	Structure 1 i	Public? Nox !	39 Endangered? Yes
Building 13t	Object	26. Local Contact Person or Organization	By What?
On National Yes II 12 Is		27. Other Surveys in Which Included	
Milgister. 110 .3c		27. Other Surveys in Which included	40. Visible from Yes
Part of Estab Yes II 14. D. Hist Dist.? No IX	otent'l? No I x		Public Road? No
5 Name of Established District		1	41. Distance from and Frontage on Road
J Walle of Editional Control			
two rooms on each floo Windows on this porti of limestone. Doorwa lights. Brick has be	or separate on are fla ys at each een painted	iginal structure was "I-type" with it by central hallway, with end chit-arched, with keystones and skewlevel have 5-light transoms and swhite. Interior features fireplamesque wooden mantlepieces. Originals distanted to the contract of the	packs side- photo ace
ceilings and flooring	in most r	ooms; dining room features intrice	+)//
2 History and Supplicance The	house was	Addition was added by owner (conconstructed from 1851-1854 by "Se	datte luomas passes es
	-lace by C	laves with wooden heams and Illool	LILE TION HEATON METHOD
2 -1 - 1 - 01	Land I Lines +	he Bahare were southern symultilis	BIB. CHEIL ) DOID CHILLD
	0	anontly the house was often naid	Ped pa not mern population
Once while 2 sons wer	re home on	leave, the Squire was ordered to	surrender them to the (C
14 Description of Environment an	nd Outbuildings	The house is located on a 96 ac	re active farm, on a lar
lot surrounded with I	Black Locus	t trees. To the rear and west of use and root cellar, comtemporary	at least with the bric
wells. Also west is	a smoke ho	The house fronts on a circular g	ravel driveway.
addition, now used for	r storage.		10, 110,000
Howard Hill		Caldwell, Dorothy, ed. Missouri	Cameron
Mrs. Alice Darneal To	arry	Historic Sites Catalogue.	47. Organization
			RCHS & M  48. Date 49 Revision Date
Ray County History,	1973	On-site inspection.	7/70

- #42. Con't. Macklin in 1885, with segmetally arched windows. There was no connection between the original house and the addition's second floor at the time of construction. Macklin also added a second story porch to the primary facade and a two-story porch running the length of the new L. A previous frame addition serving as kitchen and diningroom for the house was removed at this time. When acquired by the present owner's father, the second story porch was removed and replaced by a balcony ca. 1934. They renovated one of the upstairs bedrooms, which lad lately been used for raising chickens, added electricity, a hot water heating system from an old house in New Fredricksburg Missouri, and indoor plumbing. The house has lately had structural renovation, and is furnished with many period pieces.
- #43. Con't. maurauders. He replied they were upstairs asleep, and under the ruse of calling them, he began shooting at the intruders from an upstairs window, driving them off. Another time, one of his sons was lowered into a well for three days until the Bushwackers were discouraged and left. After the Squire's death in 1873, the original 1,000 acre farm was divided between his children. The Duvalls and Wagoner family owned the property before it was purchased in 1885 by Bernard "Barney" Macklin, a Richmond tavern owner. He added the additions. In 1930 Macklin died and his window rented the house to tenant farmers until 1934, when it was purchased by Nelson Hill, publisher of The Richmond News. The Hill family restored the house, and Mr. Hill named the house "Grooteschnour," an Afrikaner word he thought meant "great estate" but when he later found it meant "great barn" the title was dropped. Mr Hill's son, Howard, presently resides in the house with his wife. He is also publisher of the Richmond News, as well as another Richmond newspaper.



**FLOORPLANS** 

NOT TO SCALE



**PHOTOGRAPH** 




Office of Historic Preservation, P.O. Box 176, Jefferson City, Missouri 65101 HISTORIC INVENTORY

1 No. 75	4 Present Name(s)	~	
2 anty	Morton Church		
Ray	5 Other Namo(s)		
RCHS & M	Morton Community Church		
6 North from Hardin to Rou	to E 16. Thematic Category	28. No. of Stories	
then west ½ mile to unma	hode	29. Basement? Yes (X)	
road, then south & mile.	. Date(s) or Period	29. Basement? Yes ix No I.	
Sec. T 52N, R26W	CA 1876.1910	30. Poundation Material	
7 City or Town If Rural, Township &	veillacular.	Stone 31. Wall Construction	
Richmond-Vic Richmond	Richard Sonian Details  19. Architect or Engineer	Brick	
a site rian with North Allow	unknown	32. Roof Type & Material	
	20. Contractor or Builder	Gable-Comp.Shingles	
	unknown	33 No. of Bays	
	21. Original Use, if apparent	Front 3 Side NA	
	church	34. Wall Treatment	
	22 Present Use	common bond	
	Church	35. Plan Shape square	
63	23 Ownership Public Private	₩ (Explain Altered ₩	
	24. Owner's Name & Address,	in #42) Moved i	
	il known	37. Condition	
9 Coordinates UTM	Congregation of Morton Baptis		
l'al Lotti	and Methodists	Exterior good	
	25. Open to Yes Public? No		
	Object     26. Local Contact Person or Organization	39. Endangered? Yes !!	
1) On National Yes II 12. Is It	Yes ki	By What? No 1X	
Register? No X Eligible?	No I i 27. Other Surveys in Which Included		
Hist Dist ? No M Potent'll	Yes II	40. Visible from Yes	
	7 - NO 91	Public Road? No 1:	
15 Name of Established District		41. Distance from and Frontage on Road	
		200 ft.	
with lateral bell tower cor brick, it features a large window, with limestone skew	dures Original church was weatherboarded attaining primary entrance. Now sheathed to round arched central triple, stained gradular and keystones detailing arches of covered with weatherboarding and has a	with lass f 3	
roundel of stained glass. He of stained glass, with belf like the central window, wi	Entrance in bell tower has narrow transo fry with round arches open on each side ith 3 header rows and a limestone keysto	one con't	
grocery store should be planting was dedicated Sept	, 1876 Judge Keyes sold an acre+ to the asfor \$200. With the understanding raced on the ground: otherwise it would rember 27, 1913. The four denominations congregation was dissolved on the mid-	no cemetery, saloon on revert to his heirs. The continued to share the	
44 Description of Environment and Outh	uildings	CON't	
	Located in the middle of extensive	e farmlands.	
-			
45 Sources of Information			
	772 Condon school 3	46. Prepared by	
Ray County History, 19 on-site inspection		Clara Allison	
on-site inspection		47. Organization	
		RCHS & M 48. Date 49 Revision Date(s)	
		5/79	

a sauch of milwell nort dire then west | mile to unmarked road, then mouth : mile, is South Touriship & Venicity 52 Real Type & Helseni 21 Original Usal, U appaints Langhad

#42 Con't The belfry is capped by a hipped roof. A boxed cornice and belfry undecorated friege surrounded both churches and belfry. #36: Church entirely remodelled in 1910-13 brick veneer added, Sunday school rooms constructed.

#43 Con't Church in 1970. The building still serves the Baptists and Methodists, each minister serving 2 Sundays a month.



FLOORPLANS

NOT TO SCALE



PHOTOGRAPH


37-180 75%.



Office of Historic Preservation, P.O. Box 176, Jefferson City, Missouri 65101
HISTORIC INVENTORY

40 42 T	Green Residence	
Ray 5 OII	ner Namo(s)	
Location of Negatives	•	
RCHS	16 Thematic Calegory	26 No of Stories   two
Specific Lucation 8 mile east of town of Vibbard		29. Basement? Ye
316 T53 R29W	17 Date(s) or Period ca. 1885	30. Foundation Material
Gity of Town II Rural, Township & Vicinity	Victorian Box	ashlar stone 90
Site Plan with North Arrow	19. Architect or Engineer	frame . Wu
Sile Plan Will No.	unknown  20. Contractor or Builder pach	32. Roof Type & Material mansard-comp shing]
	unknown , Fu	33. No. of Bays Front 3 Side 3
	21. Original Use, if apparent residence	34. Wall Treatment
	22 Present Use	metal siding 50
1	residence 23 Ownership Public   1	36 Changes Addition
6.3	Private IV	(Explain Alter in #42) Mov
	24. Owner's Name & Address, if known	37 Condition good
Coordinates UTM	H.A. Green	Exterior good
Lat .	Vibbard, Missouri 25 Open to Yes !!	38 Preservation
Site 1 Structure	Public? No ly	Underway? 39 Endangered?
Building (X) Object	20 2000.	By What?
On National Yes II 12 is II Yes Riigister? No IX Eligible? No		40. Visible from
Part of Estab Yes I 14. District Yes Hist Dist.? No IX Potent'l? No		Public Road?
5 Name of Established District	1	41. Distance from and Frontage on Road
2 Further Description of Important Features	y primary elevation and mansard roof.	
uch facado dotail has been lost	due to intoriumale addition of metal	
iding but windows retain trahea	ted heads. Doubleleaf front entrance	/ /
ananda which runs the length of	Addition of Bungalow type posts to the facade, and of cast-iron railing	
a accord at may Canada addition	to the north. The nouse undoubtedly	1. "
ad a Wealth of Gingerbread ornam is Mistory and Significance	entation when constructed.	
" · · · · · · · · · · · · · · · · · · ·	unty House is very similar to Roney	House (which see) i
earBy Lawson, built 1884, which	has also been stripped of its Gingerb	read detailing.
	95	

45 Sources of Information On-site inspection.



FLOORPLANS

NOT TO SCALE




**PHOTOGRAPH** 



48 Date 4/80 49 Revision Date(s)

No II	Z A Pres	sent Name(s)	
2 County		Sherman Residence	
Ray	5 Oth	er Namo(s)	
3 Location of Negatives RCHS & M			
Specific Lucation of		18 Thematic Calegory	28 No of Stories two 2-1
	Henrietta on		28 No of Stories two2-1
Route H.	MOTW	17 Date(s) or Period	No
2185	100100	ca. 189 <del>0</del>	30. Foundation Material
/ City or Town II Rui Henrietta vic.	ral, Township & Vicinity	18 Style or Design	concrete blocks 65
B Site Plan with North A	Camden twp.	vernacular 09	31. Wall Construction
a sind salah worth wi	1	19. Architect or Engineer unknown	frame . Wu
42		20. Contractor or Builder	32. Roof Type & Material @ gable-comp, shingles
	7. /	unknown	33 No. of Bays
	$\Pi \mathcal{N} \Gamma$	21. Original Use, if apparent	Front 3 Side 1
1860	H	residence O/A	34. Wall Treatment 52
	Oute Oute	22 Present Use residence	metal siding 50
	<b>4</b> 12		35. Plan Shape rectangula
3	h 1	23 Ownership Public ! Private M	36 Changes Addition (Explain Altered
7		24. Owner's Name & Address.	in #42) Moved
		Mr&Mrs. James Sherman	37 Condition
9 Coordinates	UTM	Route 2, Richmond, Mo.	Interior excellent
Lat Long			Exteriorexcellent
Site Li	Samuel Line	25. Open to Yes I I Public? No lid	38. Preservation Yes Underway? Nox
Building 20	Structure 1 i	26. Local Contact Person or Organization	
II On National Yes II	12 Is II Yes KI	20. Local Collect Person of Organization	By What? Yes
Angister? No X	Eligible? No I I	27. Other Surveys in Which Included	-
Hist Dist.? No XI	14. District Yes III		40. Visible from Yesx
15 Namu of Established D			Public Road? No
to them of Established D	/IST/ICT		41. Distance from and Frontage on Road
42 Further Description of	Important Features	y rprimary facade. Siding has	
		letails. Narrow boxed cornice and	
		Front with concrete floor and squa	
columns. Small r	round window high	in south gable. #36: k1968-69	Photo
		undation laid, Kitchen and bath	
		ided. 1970 the house had the from	t
		on the ceiling, panelling, fire-	1.
43 History and Significance Henry Sherman obt	e sined the proper	ty in 1895 and built the present h	ouse. His son Ray owned
the house from 19	17 to 1965, when	his son James became the owner.	The Shermans have
farmed in this ar	rea since Henry ar	nd his family came here.	
M. December	-		
14 Description of Environm	•	·	
	outbuildings to	house livestock, grain and machin	ery. There is also
rootcellar.			
5 Sources of Information			
Mrs. James Sherma	n		46. Prepared by Jane Williams
On-site inspectio			
			47 Organization



FLOORPLANS

NOT TO SCALE



PHOTOGRAPH


#42. Cont. place on north end. Hallway wall was removed bringing into view the curved pine stairway.



48 Pate 8/79

49 Revision Date(s)

		VEITION		
EN0 11	3	sent Name(s)		
2 County		Stockton House		
Ray	5 Oth	er Namo(s)		
3 Location of Negatives RCHS &	M	Reavis Residence; Stevinson Res	idence;	
6 Specific Lucation	M	18 Thernalic Calegory		
3 miles west of Her	nrietta on	010	26 No of Stories two	
Route H.		17 Datu(s) or Period	29. Basement? Yes III	
		1890 ca. att 1951 0000	30. Foundation Material	
	. Township & Vicinity	18 Style or Design	cacrete block 65	
vic. Richmond; Camo		Queen Anne derivation 07	31. Wall Construction	
8 Site Plan with North Arro	w	19. Architect or Engineer Olke	frame. Wu	
	. 1	unknown 20. Contractor or Builder	32. Roof Type & Material	
	N	unknown	gable-comp. shingles  33. No. of Bays	
	d	21. Original Use, if apparent	33. No. of Bays Front n/a Side n/a	
		residence DIA	34. Wall Treatment	
		22 Present Use	asbestos siding	
	B	residence	35. Plan Shape L-shape	
3	9/	23 Ownership Public !	36. Changes Addition	
63	5.1	Private 13	(Explain   1908 Moves	
	3out	if known	37 Condition	
V Coordinates U	TM	R.C. Stockton	Interior good	
Lat		Route 2, Richmond	Exterior good	
Long		25 Open to Yes 11	38. Preservation Yes	
Site 1 i	Structure 1	Public? No 10	Underway? No X	
	Object ( )	26 Local Contact Person or Organization	39 Endangered? Yes !!	
Pingister? No IX	12 Is II Yes Ki	27 Other C	By What? No X	
13 Part of Estab Yes II	14. District Yes II	27. Other Surveys in Which Included	40 11 11 1	
Hist Dist.? No Ri	Potent'l? No to		40. Visible from Yes X Public Road?	
15 Namu of Established Dis	Incl		41. Distance from and	
			Frontage on Road	
42 Euriber Descripture of In-				
House was moved in	1908 from the S	unshine Lake area. This was the		
third move for the	house through t	he years to try to avoid the		
		ood of 1951 caught it at this		
spot anyway. Most	architectural d	etails obscured by recent addition	Photo	
or staring. Frimary	y lacade with ba	y whdow on first story.		
43 History and Significance		•	/	
	0091 become bed	by Tom B. Reavis. When E.B. Stock	A C 11	
owner nurched the	ed around 1990	g room was added. When present ow	ton, father of present	
they added a bedroo	om. bathroom and	closed-in porch. At the present t	ime the owners! son	
reside here. The	Stockton family	have farmed and held political of	fice in Ray County.	
		Frank Va.		
44 Description of Environme				
On a working farm.	Large garden t	o rear.		
A				
45 Sources of Information				
R.C. Stockton			46. Prepared by	
On-site inspection.			Jane Williams	
			RCHS & M	



FLOORPLANS

NOT TO SCALE



PHOTOGRAPH



Office of Historic Preservation, P.O. Box 176, Jefferson City, Missouri 65101

HISTORIC INVENTORY

RA AS - 002 - 057

No 111		nt Name(s)		
No 114		Ed Williams Residence		
Ray	5 Other	Namo(s)		
Location of Negatives		Bates Estate		
		16. Thematic Category		26. No of Stories 2
Specific Location	O Warmintte			29. Basement? Yes !!
77	of Henrietta	Fahly 1900 as	Hc 1950	30. Foundation Material Concrete block
City or Town II Rural.	Township & Vicinity aden Twn.	18 Style or Gesign	49	31. Wall Construction Frame
Site Plan with North Arron		19. Architect or Engineer		32 Roof Type & Material GB
	11/5	20. Contractor or Builder		Hip Comp. Sningle
	1 1			33. No. of Bays Front Side
	1 W	21. Original Use, if apparent Residence		As bestos siding 4
		22 Present Use		
		Residence		35. Plan Shape T
		23 Ownership	Public 11 Private 11	(Explain Altered k
All Ho		24. Owner's Name & Address,		111 112/
	1	if known		37. Condition Good
Cuordinales	ITM			Exterior Good
Lat Long		25. Open to	Yes II	38. Preservation Yes- Underway? No
Site LI	Structure 1 i	Public?		39 Endangered? - Yes I
Building M	Object   1	26. Local Contact Person or Organ	112411011	By What? No!
Register? No 1:	12 is it Yes ! ! Eligible? No ! !	27. Other Surveys in Which Include	ed	V
3 Part of Estab Yes I I	14. District Yes II			40. Visible from Yes ' Public Road? No
Hist Dist.? No 11	1 010.11 11			41. Distance from and
15 Name of Established Di	istrict			Frontage on Road
42. Further Description of		wnstairs were added to	o the 3	
ve been consumed	l by a bathroo	m in the mid-fifties a	and a dir	Photo
g room in the mi	id-sixties.	l waingcote: veranda-	tvpe	
ig; kitchen walls	ight-angle sta	irway. Asbestos sidi	ng was	
ded in the early	y 50's.			/
43 History and Significant	ce and Ella Bates	purchased the part o	f the fa	rm where the house

James French and Ella Bates purchased the part of the farm where the house stands from the Wm. Rider heirs in 1897. Three rooms are probably the original. A long time renter of the farm was the Robt. Stanton family (1907-1950). The Ed Williamses moved here in 1951 a


Passers-by often remark about the attractiveness of this homestead.

45 Sources of Information

46. Prepared by Jane Williams

47. Organization
Ray County Local

48. Date 49 Revision Date(s) 6/29/80



NOT TO SCALE FLOORPLANS





1 No C 10	4 Pres	ent Name(s)		
2ounly		Goodman Residence		
Ray  3 Location of Negatives RCHS	5 Other	Cooper Residence; Hudgens Resid	ence	
6 Specific Lucation		16 Thernalic Calegory	28 No of Stories one /-/	
la miles east of Camder Missouri Route 210.	n on	030 140	29. Basement? Yes II	
SR 210		17 Date(s) or Period ca. 1840; 1876	No X	
City or Town Il Rural, Towns	hip & Vicinity	18 Style or Design	30. Foundation Material concrete block 65	
Camden vic. Camden to	ownship	pieneer vernacular; Neoclassic	31. Wall Construction	
8 Site Plan with North Arrow	.)	19. Architect or Engineer unknown	log; frame L Wu	
M-210	_ /	20. Contractor or Builder	32. Roof Type & Material GB & gable/comp. shingles	
		unknown 68	33. No. of Bays	
111	1/6	21. Original Use, if apparent residence 0/9	Front 3 Side	
Hely	Ψ	22 Present Use	34. Wall Treatment 0/	
		residence	35. Plan Shape L-Shapen	
		23 Ownership Public 1 Private IX	36. Changes Addition X. (Explain Alfered A	
country road	-	24. Owner's Name & Address,	in #42) Moved	
		Mr. & Mrs. Rick Goodman Camden, Missouri	37 Condition good	
UTM Lat 5/N 284				
Long 5/N Sak		25 Open to Yes I I	38. Preservation Yes	
Site 1 i Building Xi	Structure I i	Public? No 1x	Underway? No X	
11 On National Yes II 12 Is II	Yes DO	26 Local Contact Person or Organization	39 Endangered? Yes   Yes   No X	
Angister? No x. Eligi	ible? No I I	27. Other Surveys in Which included	- NO X	
Hist Dist.? No DO Pote	Inct Yes I I		40. Visible from Yes X	
15 Name of Established District	- 100 01		Public Road? No	
			41. Distance from and Frontage on Road	
42 Further Description of Important	Fanturas			
later removed. Now pro and returns, frieze, mo Interior features oak we under the house, a cond west side.	oclassic I- sents Neoc olded windo woodwork.	which two rooms remain. To it house, the top floor of which was lassic details with molded cornic w heads, pilaster corner boards. In 1956 a foundation was construct, pattic and cistern added on the	Photo	
in 1822. In 1846 he can the farms of Captain Jonear Lexington. By ca., a large warehouse and h	ohn Richard , 1858 he h Degan a gen	rm about 1873. He was born in e County, and managed a farm, later son and William Moore, in the riv ad moved to Camden with Seth H. Meral shepping and commission busi	becoming overseer of erbottoms of Ray County oore, and they erected	
A well with a pulley for	or deawing	water remains to the west of the he also constructed a garage and	house. The well house	
Sources of Information			46. Prepared by	
On-site inspection. Ray County History, 188	R1 .		Cameron	
Tours nibity, 100	/ de 0		47 Organization RCHS & M	
			48 Date 49 Revision Date(s)	


#43.

looper began a dry goods store, a pork packing and a tobacco business. In 1873, he began to deal in livestock and purchased the present property, then a farm of 156 acres. He constructed the present house, apparently incorporating a log structure already on the property in a new I-house.

Across the road Cooper had earlier built a warehouse on the riverfront. Dining room and kitchen fof Cooper's new house were heated with fireplaces. The kitchen entrance was on the east. Sometime through the years the upper flowr was removed and the kitchen entrance was changed to the west facade. Some remodeling was done around 1900 by Elizabeth and Johnny Hockensmith, daughter of Mr. Cooper. Later Thomas M. Cooper purchased the place and lived there until his death in 1951. His .wife died the . following year, and their daughter Marguerite Hudgens lived there until 1978 when she sold it to the present owners.

M-210 cut through the farm just back of the house, destroying the barn. A new barn was built on the notth side of the highway. J.E. Se ward now owns the acreage.

North of M-210 is a cemetery enclosed by a chain link fence, known as the Cooper Cemetery. There are 13 graves: Thomas M. Cooper and wife Elizabeth, several of their children.




FLOORPLANS NOT TO SCALE



PHOTOGRAPH



C 13	4 Present Name(s)		
	DuBois Se	ward Residence	
Ray	5 Other Namo(s)		
Location of Negatives RCHS	Ellis Sew	ard Residence	
Specific Lucation	16 Thematic C	alegory	8 No of Stories 11/2
East Camden, off St	ate Highway 03	A .	9. Basement? Yes IX
210. SR 210	17 Dalu(s) or F	Period	full No :
			0. Foundation Material 65
	ownship & Vicinity 18 Style or De		concrete, cement block
Camden Vic Camde	n Township Neoclassi	c 22	on the construction control cross gable/comp. Shin
1	unknown	Engineer Ather	12. Roof Type & Material
1	20. Contractor	or Builder Polich	frame
	unknown	re i	3 No of Bave
	21. Original Us		
	residence		4. Wall Treatment
	residence		clapboard/weatherboard
	23 Ownership		5. Plan Shape rectangular  6. Changes Addition X.
1150 -	29	Private 1x	(Explain Altered X
169 6	24. Owner's Na	me & Address.	in #42) Moved i
	# known	. DuBois Seward	7 Condition excellent
Coordinates UTM	Camden, M		Exterior excellent
ony	25. Open to		
Site 11	Structure 1; Public?	Yes II 34	3. Preservation Yes Underway? No X
BuildingXX		ct Person or Organization 3	9 Endangered? Yes !!
	Is It Yes XI		By What? No X
Augister? No T.		s in Which Included	
	District Yes I !	4	0. Visible from Yes X
	Potent'l? No IX		Buckling Day 100
Hist Dist.? No IX			Public Road? No ::
Hist Dist.? No IX		4	Public Road? No ::  1. Distance from and Frontage on Road
Mist Dist.? No IX  Name of Established Distric		4	Distance from and
Name of Established Distric	Leat Features		Distance from and
Name of Established District  Further Description of Import Neoclassic houseunus leveloof water table	tant Features Sual treatment on facades e(at level of window sill	weatherboarding to	Distance from and
Name of Established District  Further Description of Import Neoclassic houseunus leveloof water tablesheathing the remain	tant Features Sual treatment on facades e(at level of window sill ader of the house. Front	weatherboarding to s) and clapboarding gable is covered in	1. Distance from and Frontage on Road
Name of Established District  Further Description of Import Neoclassic houseunus leveloof water table sheathing the remail boards of vaning win	sual treatment on facades e(at level of window sill ader of the house. Front iths. All decoration is	weatherboarding to s) and clapboarding gable is covered in	Distance from and
Name of Established District  Further Description of Import Neoclassic houseunce leveloof water table sheathing the remains boards of varying window heads, pilast	tent Features sual treatment on facades e(at level of window sill nder of the house, Front iths, All decoration is er corner boards, boxed of	weatherboarding to s) and clapboarding gable is covered in meoclassical with molded	1. Distance from and Frontage on Road
Name of Established District  Further Description of Import Neoclassic houseunus leveloof water table sheathing the remains boards of varying window heads, pilaste Windows originally	tant Features sual treatment on facades e(at level of window sill nder of the house. Front iths. All decoration is er corner boards, boxed co	weatherboarding to s) and clapboarding gable is covered in meoclassical with molded ornice and frieze.	1. Distance from and Frontage on Road
Further Description of Impor Neoclassic houseunus leveloof water table sheathing the remail boards of vaping will whow heads, pilast Windows originally in perch on southwere	tant Features Sual treatment on facades e(at level of window sill nder of the house. Front iths. All decoration is er corner boards, boxed co 3-over-1, some now change st corner of primary faca	weatherboarding to s) and clapboarding gable is covered in meoclassical with molded ornice and frieze. d to 1-over-1. Built- de. Interior originally	1. Distance from and Frontage on Road  Photo  (cont)
Further Description of Import Neoclassic houseunus leveloof water table sheathing the remail boards of varying win whdow heads, pilaste Windows originally in perch on southwer History and Supportionance Zesse Ellis Seward	tant Features Sual treatment on facades e(at level of window sill nder of the house. Front iths. All decoration is er corner boards, boxed c 3-over-1, some now change st corner of primary faca and the house constructed	weatherboarding to s) and clapboarding gable is covered in meoclassical with molded ornice and frieze. d to 1-over-1. Built- de. Interior originally	Photo  Photo
Further Description of Import Neoclassic houseunus leveloof water table sheathing the remains boards of varying window heads, pilast Windows originally in perch on southwes  Mistory and Significance desse Ellis Seward is and work was halted	sual treatment on facades e(at level of window sill ader of the house. Front iths. All decoration is er corner boards, boxed of 3-over-1, some now change at corner of primary faca and the house constructed for a time because of the	weatherboarding to s) and clapboarding gable is covered in meoclassical with molded ornice and frieze. d to 1-over-1. Built- de. Interior originally 1918-1919. It was begu	Photo  Photo
Further Description of Import Neoclassic houseunus leveloof water table sheathing the remains boards of varying window heads, pilast Windows originally in perch on southwes  Mistory and Significance desse Ellis Seward is and work was halted	tant Features Sual treatment on facades e(at level of window sill nder of the house. Front iths. All decoration is er corner boards, boxed c 3-over-1, some now change st corner of primary faca and the house constructed	weatherboarding to s) and clapboarding gable is covered in meoclassical with molded ornice and frieze. d to 1-over-1. Built- de. Interior originally 1918-1919. It was begu	Photo  Photo
Further Description of Import Neoclassic houseunus leveloof water table sheathing the remain boards of varying windows originally in perch on southwest tables see Ellis Seward and work was halted	sual treatment on facades e(at level of window sill ader of the house. Front iths. All decoration is er corner boards, boxed of 3-over-1, some now change at corner of primary faca and the house constructed for a time because of the	weatherboarding to s) and clapboarding gable is covered in meoclassical with molded ornice and frieze. d to 1-over-1. Built- de. Interior originally 1918-1919. It was begu	Photo  Photo
Further Description of Impor Neoclassic houseunus leveloof water table sheathing the remail boards of vaping window heads, pilast Windows originally in perch on southwer desse Ellis Seward land work was halted Dubois and his wife	sual treatment on facades (at level of window sill ander of the house. Front iths. All decoration is ar corner boards, boxed of 3-over-1, some now changes t corner of primary facant the house constructed for a time because of the purchased the house in 1	weatherboarding to s) and clapboarding gable is covered in meoclassical with molded ornice and frieze. d to 1-over-1. Built- de. Interior originally 1918-1919. It was begu	Photo  Photo
Further Description of Import Neoclassic houseunus leveloof water table sheathing the remail boards of varying win whdow heads, pilaste Windows originally in perch on southwell History and Supportionance Zesse Ellis Seward and work was halted Dubois and his wife	tant Features sual treatment on facades e(at level of window sill nder of the house. Front iths. All decoration is er corner boards, boxed c 3-over-1, some now change at corner of primary faca had the house constructed for a time because of th purchased the house in 1	weatherboarding to s) and clapboarding gable is covered in meoclassical with molded ornice and frieze. d to 1-over-1. Built- de. Interior originally 1918-1919. It was begue Armistice. After Sewar	Photo  Photo
Further Description of Import Neoclassic houseunus leveloof water table sheathing the remail boards of varying win whdow heads, pilaste Windows originally in perch on southwell History and Supportionance Zesse Ellis Seward and work was halted Dubois and his wife	sual treatment on facades (at level of window sill ander of the house. Front iths. All decoration is ar corner boards, boxed of 3-over-1, some now changes t corner of primary facant the house constructed for a time because of the purchased the house in 1	weatherboarding to s) and clapboarding gable is covered in meoclassical with molded ornice and frieze. d to 1-over-1. Built- de. Interior originally 1918-1919. It was begue Armistice. After Sewar	Photo  Photo
Further Description of Import Neoclassic houseunus leveloof water table sheathing the remail boards of varying win windows originally in perch on southwel History and Significance desse Ellis Seward I and work was halted Dubois and his wife Description of Environment of Landscaped lot in re	tant Features sual treatment on facades e(at level of window sill nder of the house. Front iths. All decoration is er corner boards, boxed c 3-over-1, some now change at corner of primary faca had the house constructed for a time because of th purchased the house in 1	weatherboarding to s) and clapboarding gable is covered in meoclassical with molded ornice and frieze. d to 1-over-1. Built- de. Interior originally 1918-1919. It was begue Armistice. After Sewar	Photo  Photo
Name of Established District  Further Description of Import Neoclassic houseurs leveloof water table sheathing the remail boards of varying win whdow heads, pilast Windows originally in perch on southwer  Mistory and Significance desse Ellis Seward I and work was halted Dubois and his wife  Description of Environment at Landscaped lot in re- Sources of Information	tant Features sual treatment on facades e(at level of window sill nder of the house. Front iths. All decoration is er corner boards, boxed c 3-over-1, some now change at corner of primary faca had the house constructed for a time because of th purchased the house in 1	weatherboarding to s) and clapboarding gable is covered in meoclassical with molded ornice and frieze. d to 1-over-1. Built- de. Interior originally 1918-1919. It was begue Armistice. After Sewar 973.	Photo  (cont)  n in november of 1918 d's death, his son
Further Description of Impor Neoclassic houseunus leveloof water table sheathing the remains boards of varying window heads, pilast windows originally in perch on southwest was and work was halted Dubois and his wife Description of Environment of Landscaped lot in reserved.	tant Features sual treatment on facades e(at level of window sill nder of the house. Front iths. All decoration is er corner boards, boxed c 3-over-1, some now change at corner of primary faca had the house constructed for a time because of th purchased the house in 1	weatherboarding to s) and clapboarding gable is covered in meoclassical with molded ornice and frieze. d to 1-over-1. Built- de. Interior originally 1918-1919. It was begue Armistice. After Sewar 973.	Photo  (cont)  n in november of 1918 d's death, his son
Further Description of Impor Neoclassic houseunus leveloof water table sheathing the remains boards of varying with which who are the sheathing the remains of varying with which will be sheathing the remains and which will be sheathing the remains with the sheathing the remains with the sheathing the remains with the sheathing the remains and work originally in perch on southwest with the sheathing and significance desse Ellis Seward and work was halted bubois and his wife.  Description of Environment and sheathing the sheathing	tant Features sual treatment on facades e(at level of window sill nder of the house. Front iths. All decoration is er corner boards, boxed c 3-over-1, some now change at corner of primary faca had the house constructed for a time because of th purchased the house in 1	weatherboarding to s) and clapboarding gable is covered in meoclassical with molded ornice and frieze. d to 1-over-1. Built- de. Interior originally 1918-1919. It was begue Armistice. After Sewar 973.	Photo  (cont)  n in november of 1918 d's death, his son



FLOORPLANS




PHOTOGRAPH

#42. had wordwork of \*8" redwood boards. But only the front room still retains the original woodwork. House hwas remodelled ca. 1948, ceilings were lowered, one bedroom was added, and a bathroom made from a bedroom.



## Sq

C 14	4 Pres	sent Namo(s)		
aunty		Sylvester Seward		
Ray	5 Oin	Other Namo(s)		
1 tocation of Negatives RCHS				
Specific Lucation		16 Thematic Category	28 No of Stories two	
East Camden off	State Highway		29. Basement? Yes 2	
210. SR210		17 Date(s) or Period	ca. 1930 No	
		1907 alt c 1930	30. Foundation Material	
	al, Township & Vicinity	18 Style or Design	concrete (45	
Camden Cam Site Plan with North Ar	den township	Neoclassic details 49	31. Wall Construction	
Site Plan Willi North At		19. Architect or Engineer  1unknown	frame , WK	
110	N	20 Contractor or Builder Rush Pref.	32. Roof Type & Material (3) gable/comp, shingles	
		Russell "chick" Rush		
	12	21. Original Use, if apparent	Front 3 Side 4	
		residence DIA	34. Wall Treatment asbestos siding 4	
114		22 Present Use residence vacant		
			35. Plan Shape rectangul	
		23 Ownership Public   1 Private \$1	36. Changes Addition (Explain Altered)	
1169		24. Owner's Name & Address.	in #42) Moved	
	•	il known	37 Condition	
	UTM	Don R. Seward	Interior Poor	
Long		Route 2, Box 93, Ballwin, Mo.	Exterior poor	
Site Li		25 Open to Yes I I Public? No I K	38. Preservation Yes	
Building 1x	Structure 1 i	26 Local Contact Person or Organization	Underway? No	
On National Yes II	12 Is II Yes X	20 Local Contact Person or Organization	39 Endangered? Yes By What? No	
Register? No IX	Eligible? No 11	27. Other Surveys in Which included	- No	
Part of Estab Yes II	14. District Yes LI	The state of the s	40. Visible from Yes	
Hist Dist.? No IX	Potent't? No P		Public Road? No	
Name of Established De	istrict		41. Distance from and	
			Frontage on Road	
pbrick. 1 stor and, sace abando	la on primary fac- ry addition to re- onned, is in deter on of the first of le has painted the	ils, including molded w ndowheads ade, posts have been replaced with ar. House has been greatly altereriorated condition. The present wner, is renovating the house as e house and added a new roof. Healaster extensively. The outstandi	Photo	
time permits. H	nd the interior p		ng (cont)	
History and Significance The house was bu came from Fayett on the Santa Fe timekeeper becau he went to San F	ilt by Sylvester te County Pennsll railroad on its use of his unusua. Trancisco to work	(Ves) Seward, who was born 1860 i vania, and settled in Ray County i trancontinental tracks to New Mexil ability with mathematics. When in a logging camp, then on a frei	n Hardin. His parents n 1855. Ves worked co. He became a the railroad was comple	
History and Significance The house was but came from Fayett on the Santa Fe timekeeper becauthe went to San F	ilt by Sylvester te County Pennsll railroad on its use of his unusua. Trancisco to work	(Ves) Seward, who was born 1860 i vania, and settled in Ray County i trancontinental tracks to New Mexil ability with mathematics. When	n Hardin. His parents n 1855. Ves worked co. He became a the railroad was comple	
time permits. He rains had damage. The house was but came from Fayett on the Santa Fe timekeeper because he went to San F. Description of Environmerural area.	ilt by Sylvester te County Pennsll railroad on its use of his unusua. Trancisco to work	(Ves) Seward, who was born 1860 i vania, and settled in Ray County i trancontinental tracks to New Mexil ability with mathematics. When	n Hardin. His parents n 1855. Ves worked co. He became a the railroad was comple ghter to England (cont)	
time permits. He rains had damage this had damage the house was but came from Fayett on the Santa Fe timekeeper because he went to San For Description of Environm rural area.  Sources of Information	ilt by Sylvester te County Pennsll railroad on its use of his unusua rancisco to work ent and Outbuildings	(Ves) Seward, who was born 1860 i vania, and settled in Ray County i trancontinental tracks to New Mexil ability with mathematics. When	n Hardin. His parents n 1855. Ves worked co. He became a the railroad was comple ghter to England (cont)	
time permits. He rains had damage thistory and Supprison of Environmental area.  Sources of Information On-site inspection	ilt by Sylvester te County Pennsll railroad on its use of his unusual rancisco to work ent and Outbuildings	(Ves) Seward, who was born 1860 i vania, and settled in Ray County i trancontinental tracks to New Mexil ability with mathematics. When	n Hardin. His parents n 1855. Ves worked co. He became a the railroad was comple ghter to England (cont)  46. Prepared by Cameron	
time permits. He rains had damage History and Supplicance The house was but came from Fayett on the Santa Fe timekeeper because he went to San F Description of Environme rural area.  Sources of Information	ilt by Sylvester te County Pennsll railroad on its use of his unusual rancisco to work ent and Outbuildings	(Ves) Seward, who was born 1860 i vania, and settled in Ray County i trancontinental tracks to New Mexil ability with mathematics. When	n Hardin. His parents n 1855. Ves worked co. He became a the railroad was comple ghter to England (cont)	



FLOORPLANS NOT TO SCALE



PHOTOGRAPH

- 42. front door had etched glass, but was stolen by vandals.
- #43. by way of Cape Horn. On his return to America, Ves worked on a New Jerry farm, Where he learned to grow potatoes and water melons. He returned to Ray County ca. 1885, married Clemie Green of Tipton in 1885. They had four children, all of whom settled in the general area of this farm.

The farm became one of the largest potato-producing areas in Missouri, and was known throughout the state for its water mekons. Ves owned one of the first trucks in the state to be used for farming, but refused to use trackors, as he frilfelt they packed the ground. He plowed with 10 mule teams until 1943, when an accident with a male team left him nin failing health until his death in 1948.

This was one of the first pre-cut houses in Ray County. Seward had left his house in Hardin after the 1903 flood and moved to West Plains. In 1907 he shipped the pre-cut sections of the house by rail to Gamden. They were then transported to East Camden by wagon where the house was quickly assembled. The land had been purchased from Richard Mitchell. It had been part of the Mick place. The house when completed boasted carbide lights. Seward annually bought seed potatoes in Minnesota and the Dakotas, and had them shipped on the riarailroad to

be stored in three large cellars he had built on the property.



COLUMN TO THE PARTY OF THE PART	HAVEITIOH	
1 115	4 Present Name(s)	
2 county.	Vandiver House	
Ray	5 Other Namo(s)	
3 Location of Negatives RCHS & M	Elliott House	•
6 Specific Lucation 2 ml. North of	Camde 116. Thernatic Category	28. No. of Stories 2 =  -
NW 4 of Section 22. Township	030 010	29. Basement? Yes 🖂
Range 28.	17 Date(s) or Period	partial No!.
2620	1856	30. Foundation Material
Vicinity of Camden; Camden	Vicinity 18 Style or Design twsp. Federal	ashlar stone 31. Wall Construction
H Site Plan with North Arrow	19. Architect or Engineer	brick US
(W) (W)	unknown	32. Roof Type & Material
	20. Contractor or Builder	gable-comp. shingles
	unknown 21. Original Use, if apparent	33. No. of Bays Front 5 Side 1
	residence	34. Wall Treatment
/	22 Present Use	stucco 61.
7 1	residence	35. Plan Shape L-shaped
<b>6</b> 1	23 Ownership Public I !	36. Changes Addition X Altered X
	24. Owner's Name & Address.	(Explain Altered % Moved i
m	if known	37. Condition
9 Coordinates UTM	Harold Vandiver Route #1, Camden MO	Interior good
l al Long		Exterior good
O Site!   Struc	25. Open to Yes 11 Public? No log	38. Preservation Yes Underway? No X
51100	oject     26. Local Contact Person or Organization	39. Endangered? Yes 11
11 On National Yes I 1 12. Is It	Yes to	By What? No IX
Register? No iX Eligible?	No 11 27. Other Surveys in Which is	
Formula Potent's Potent		40. Visible from Yes X Public Road?
15 Name of Established District	1963.	41. Distance from and
		Frontage on Road
22 Further Description of Important Francisco		
this All interior wall	res this large brick house has walls 12" partitions are also of brick. The primary	
	y veranda running the length of the facade	
	at each floor. The are interior end	
chimneys of brick. On the	interior, there are three fireplaces, one	Photo
of which has been closed,	the other two of stone. The original	
	basement of the house. #36. Some	
remodelling was done in 19	ll, but original floorplan was not (con't)	
The house	was built by John Elliot in 1856 with br	ick made from clay found
	rs it wremained in the Elliot family. In	
	ndson of John Elliot, who was killed by bu	
	ch. It was owned by an insurance company ners in 1941. The original money crop can	
14 Description of Environment and Outbui		(con't)
	of the town of Camden, it has the husual	. farm structures which
e not original.		(
5 Sources of Information		AS Commend & McDin Co. 1
Ray County History, 1973.		46. Prepared by McBee and

Camden and Ray County historians.

On-site inspections.

Mrs. Harold Vandiver.

Mrs. Virginia McBee.

Hockemeier-Williams


49 Revision Date(s)

RCHS & M

47. Organization

4. Present Name(s)

- #42. Con't. changed. Some windows have been replaced and the original two-story columns have been changed, and the lower story of the veranda screened. Stucco was put on the exterior because the soft brick was beginning to crumble. A kitchen area was attached to the north facade. The present owner is gradually restoring the house, has added a double garage to the kitchen addition. He plans to restore the four columns of the primary facade in time.
- #43. Con't. from the extensive apple orchards in back of the house. This was shipped out by steamboat from the Camden River warehouses.



FLOORPLANS

NOT TO SCALE






PHOTOGRAPH





L. NO. 120	4. PRESENT LOCAL NAME(S) OR DESIGNATION(S)		I. NO
2. COUNTY Ray	Smithey Residence		, o
_	5. OTHER NAME(S)		
NEGATIVES RCHS		Han to of stooms One	
6. SPECIFIC LEGAL LOCATION TOWNSHIP 51 RANGE 28		29. BASEMENT? YES() NO(X)	S. COUNTY
l mile west, l mile	north of 1902	30. FOUNDATION MATERIAL TO	33
7. CITY OR TOWN IF RURAL, VI	den twp.	- M	
6. DESCRIPTION OF LOCATION	19. ARCHITECT OR ENGINEER unknown	32. ROOF TYPE AND MATERIAL	
	John Brockman	gable /comp. shingles	-
	21. ORIGINAL USE, IF APPARENT residence	FRONT 4 SIDE 2	PHE
0	22. PRESENT USE	asbestos siding	SENT
W W	residence 23. OWNERSHIP PUBLIC(	35. PLAN SHAPE L-Shape	L00
and the second	PRIVATE(X	(EXPLAIN IN ALTERED ( X ) NO. 42) MOVED ( )	P 2
	IF KNOWN Mr. and Mrs. Vernon Smithey	37. CONDITION	PHESENT LOCAL NAME(S)
9. COORDINATES UT	Canden, Missouri	EXTERIOR good	9) 0A
LONG SITE ( )	25. OPEN TO PUBLIC? YES( STRUCTURE()) NO(X	38. PRESERVATION YES ( ) UNDERWAY ? NO ( X )	
BUILDING ( X)	OBJECT ( 1 26. LOCAL CONTACT PERSON OR ORGANIZATIO	39. ENDANGERED? YES( ) BY WHAT? NO(X)	DESIGNATION(S)
NO ( **)	LIGIBLE ? NO ( ) 27. OTHER SURVEYS IN WHICH INCLUDED		NOIL
HIST. DISTRICT? NO ( X)	STRICT YES( ) OTENTIAL? NO(X )	40. VISIBLE FROM YES (X ) PUBLIC ROAD ? NO ( )	
IS. NAME OF ESTABLISHED DISTRI	ст	41. DISTANCE FROM AND FRONTAGE ON ROAD	
porch on primary fac	been sheathed with asbestos siding. Eastlake cade has spindle frieze on porch, and turned ive rooms and a both which was originally	PHOTO MUST BE PROVIDED	5. OTHER NAME(8)
house burned in 1902	ther of present owner, came to Missouri from K 2, and this house was built the same year on t	he brick foundation	
and the family lived	the fire. The fire destroyed the house on a S in the smokehouse until this one was complet by dwelling with three bedrooms upstairs.		6. TOWNSHIP
			-
On outskirts of small	it and outsuildings il town of Camden. Some original planting rem	ains.	RANGE
45. Sources of information On-site inspection.		46. PREPARED BY	-
Present owners.	Jane Williams 47 ORGANIZATION RCHS & M	SECTION	
To-GUT .OHIETS!		48. DATE 49. REVISION DATE(S)	N ON




FLOORPLANS

NOT TO SCALE




PHOTOGRAPH



49 Revision Date(s)

1 No	78 1 Pie	Sent Name(s)	
County		Letzig Residence Jehnson	Letrig House
Ray	5 011	ner Namo(s)	3-1
3 Location of Negatives	2. 3.0	Johnson Residence; Minnick Residence	dence
RCHS &	E M		
North of Hardin or	Route A to	16 Thernelic Calegory	28 No of Stories two
intersection of E		17 Dated at Period	29. Basement? Yes
ed dirt road ½ mil	Le.	2044	half No
City or Town If Rur	al, Township & Vicinity	18 Style or Design	30. Foundation Material 30
vic. Hardin; Crook	ked River twp.	Federal influenced vernacular	brick & ashlar stone 31. Wall Construction
Sile Plan with North Ar	10W	19. Architect or Engineer	frame Wu
T50N2,W	CT 1	unknown 20	32. Roof Type & Material CE
	(E) W	20. Contractor or Builder	gable-comp, shingl
		unknown ms	33. No. of Bays 43
- V	As:	21. Original Use, if apparent residence OIA	Front 5 Side 1
	4	22 Present Use	34. Wall Treatment
-		residence	asbestos shingles
			35. Plan Shape rectangul
		23 Ownership Public I Private x I	36. Changes Addition
		24. Owner's Name & Address,	(Explain Moved
		if known	37 Condition
Coordinates	UTM	Annabel Letzig	Interior good
Lat		Richmond, Missouri	Exterior good
Cong		25 Open to Yes I i	38. Preservation Yes
Site 1 i Building ix	Structure I i	Public? No KI	Underway? No
	Object 1 1	26 Local Contact Person or Organization	39 Endangered? Yes
On National Yes II	12 Is II Yes M Eligible? No I I		By What? No
Part of Estab Yes II	14. District Yes II	27. Other Surveys in Which included	
Hist Dist.? No IX	Potent'l? No Ki		40. Visible from Yes Public Road?
Name of Established D	istrict		41. Distance from and
			Frontage on Road
Further Description of emacular I-house	has large two si	have nowhile a with two 1	
rackets. Origina	lly house had two	tory portico with turned posts with rooms on each floor with two	
entral hallways a	nd eight foot ce	ilings #36: An addition of two	
ore rooms was att	ached to the real	r at an unknown time. Firenlaces	Photo
ere closed. Bath	room and water ad	ided between 1906 and 1940. Hard-	
ood floors and fr	ench doors added	in 1944.	
History and Significance	6		
ames and Mollie J	ohnson woned the	house from about 1856 to 1905. Ed	Chase bought it in
ames and Mollie Jo 905 and sold it to	ohnson woned the Casper Minnick	in 1906. In 1940 Steve Trager has	14. 10/17 II-7
ames and Mollie Jo 905 and sold it to nnabel Letzig move	ohnson woned the o Casper Minnick ed into the house	house from about 1856 to 1905. Ed in 1906. In 1940, Steve Frazer box e. Annabel has owned it since 1941	14. 10/17 TI-7
ames and Mollie Jo 905 and sold it to nnabel Letzig move	ohnson woned the o Casper Minnick ed into the house	in 1906. In 1940 Steve Trager has	14. 70/17 TE-7
ames and Mollie Jo 905 and sold it to nnabel Letzig move ccupies the house	ohnson woned the o Casper Minnick ed into the house	in 1906. In 1940 Steve Trager has	14. 30/17 II-7
you and sold it to	ohnson woned the o Casper Minnick ed into the house	in 1906. In 1940 Steve Trager has	14. 70/17 TE-7
ames and Mollie Jo 905 and sold it to nnabel Letzig move ccupies the house	ohnson woned the o Casper Minnick ed into the house	in 1906. In 1940 Steve Trager has	14. 70/17 TE-7
ames and Mollie Jo 905 and sold it to nnabel Letzig move ccupies the house	ohnson woned the o Casper Minnick ed into the house	in 1906. In 1940 Steve Trager has	14. 70/17 TE-7
ames and Mollie Jo 905 and sold it to nnabel Letzig move ccupies the house Description of Environm pocated on a large	ohnson woned the o Casper Minnick ed into the house of the house of the and Outbuildings farm.	in 1906. In 1940 Steve Trager has	whit it: 1941 Welmon an and their son now
ames and Mollie Jo 905 and sold it to nnabel Letzig move ccupies the house	ohnson woned the o Casper Minnick ed into the house of the house of the and Outbuildings farm.	in 1906. In 1940 Steve Trager has	and their son now  46. Prepared by
ames and Mollie Jo 905 and sold it to nnabel Letzig move ccupies the house Description of Environm pocated on a large	ohnson woned the o Casper Minnick ed into the house for and Outbuildings farm.  Letzig.	in 1906. In 1940, Steve Frazer both a. Annabel has owned it since 1941	writ it; 1941 Welmon ar and their son now



FLOORPLANS


NOT TO SCALE



PHOTOGRAPH



1 No. 82	4 Present Name(s)	
. ounty	Kirkland House	
Ray	5 Other Name(s)	
3 toration of Negatives RCHS & M	Bates House	
Decific Location .	16 Thematic Category	28. No. of Stories 2
N.E. quarter of N.E. quarter	of	.29. Basement? Yes 50
#52/R26/Sec. 8 Hwg. A	17 0210(8) 01 7 01100	Partial No.
	1851-1854 Vicinity 18 Style or Dougn	30. Foundation Material Ashlar Stone
crooked river TWP Vic. of Har		31. Wall Construction
H Sile Plan with North Arrow	19. Architect or Engineer	Frame/Log LC Wu
	unknown	32. Roof Type & Material GB
A	V 20. Contractor or Builder pnch	Gable/Asphalt Shingles
	unknown WA	33. No. of Bays Front Side
All land	21. Original Use, if apparent residence	34. Wall Treatment
Allining	22 Present Use	Asbestos Shingles
n	Residence (Rental Property)	35. Plan Shape irregular
62	23 Ownership Public I !	36. Changes Addition X
17	Private 저	(Explain Altered W
	24 Owner's Name & Address,	
	French Bates Kirkland	37 Condition Interior Good
9 Coordinates UTM	503 N. Thornton St. Richmond, Mo	Exterior Good
Long	25. Open to Yes II	38. Preservation Yes
	reture 1 i Public? No M	Underway? No ☆
Building Xi O	Object     26 Local Contact Person or Organization	39. Endangered? Yes 11
11 On National Yes   1 12 Is It	Yes 🖟	By What? No ⋟
Register? No % Eligible?	No 11 27 Other Surveys in Which Included	
Hist Dist? No X Potent'l?	Yes III	40 Visible from Yes 🔀 Public Road?
15 Name of Established District		41. Distance from and
		Frontage on Road
42 Further Description of Important Feati	original room of house is of logs.	
Present appearance of house f	eatures, a wide veranda across primary	
	y posts. House has heavy cornice with	
with molding #36. House has	sic fintels, two interior end chimneys been remodelled 3 times, now consists of	Photo
ten or eleven rooms. One fire	place is still working.	
	F-100 - 10 - 10 - 10 - 10 - 10 - 10 - 10	
42 Manage and Completion		1
43 History and Significance Thomas J	. Bates came from Kentucky to Ray Co. in	1856. He returned home
but came back in 1838 on horse	eback to Missouri. In 1839, Bates located	d here with his mother,
and 3 years later enlarged it	land was made July 9, 1849. In 1851, he to 8 rooms. He was killed in a horseback	built a one-room house,
His only son James French Bat	es, inherited the farm. He remodelled the	house in 1006 The prosest
Windeschaugh of Environmentant Output		induse in 1900. The present
on a Large Farm, surrounded by	y trees and various outbuildings.	
0		
45 Sources of Information		46 Prepared by
Frank & Mary Kirkland, Wayne	Kirkland & Allison	
Ray County History, 1973. on.	47 Organization	
	1	RCHS & M
		48. Date 49 Revision Date(5) 5/79



FLOORPLANS

NOT TO SCALE




PHOTOGRAPH



1 1/8 84	4 Present Name(s)	
qualy	Spurlack-Rust House	
Ray	5 Other Namo(s)	
3 Location of Negatives RCHS	Yates Rust property	
6 Specific Lucation	16 Thematic Category	28 No of Stories two 2
Route A, $\frac{1}{2}$ mile north of Hardin.	030	29. Basement? Yes!
Huy &	17 Date(s) or Period	No x
	ca. 1870	30. Foundation Material
7 City or Town II Rural, Township &		ashlar stone 40
Morton vic. Crooked River	twp. Vernacular 49	31. Wall Construction
	unknown	frame , WU
W 63 000 C	20. Contractor or Builder	32. Roof Type & Material GB gable/comp shingles
	unknown	33. No. of Bays
GY THE	21. Original Use, if apparent	Front 2 Side 1
	residence OIA	34. Wall Treatment
	22 Present Use residence vacant	weatherboard
2		35. Plan Shape T shape
CY	23 Ownership Public   Private XX	36. Changes Addition X
0	24. Owner's Name & Address,	(Explain Altered in #42) Moved in
	if known	37 Condition
9 Coordinates UTM	Yates Rust	Interior poor
La SIT TERN DOW	Hardin, Missouri	Colonia
Long	25 Open to Yea I I	38. Preservation Yes
<b>A</b>	clure 1 . Public? No IX	Underway? No X
	bject 1 i 26. Local Contact Person or Organization	39 Endangered? Yes X
11 On National Yes I 12 Is It Register? No IC Engine?	Yes Xi	By What? No!
	No 11 27. Other Surveys in Which Included	bneglect
Hist Dist.? No Ki Potent'!?	Yes III	40. Visible from Yes X
15 Name of Established District		Public Road? No .
		41. Distance from and Frontage on Road
42 Further Description of Important Featu	ires	
Vernacular house has two ba	ay primary facade withlateral hallway	
alongside single room with	two rooms on second floor, and single	
Corner boards: plain friend	Interior end stove chimneys of brick	Photo
across primary facada once	and boxed cornice. I story veranda had turned posts. These have been	1
replaced with plain posts h	out carved brackets remain. Additin	
to rear of house contains of	lining room and kitchen. Interior featu	
43 History and Significance		
House was probably built by	M.M. Spurlock, who was born in Cabell	County West Virginia in
orphaned at / years.	at 1) he accompanied his brother-in-la	W SM Harrimon to
Missouri. He located in Ra	ly County and worked on farms at interva	le until he come of are
ne became a minister, who s	served congregations throughout the coun	ty Un neguted this
44 Description of Fourteement and Outbuil	1888, when he settled in Richmond, prea	ching occasionally (cont)
Original plantings, but lot	is overgrown and neglected. Outbuilding	g to the northeast of
house of later date.	O TO THE OWNER OF THE OWNER OWNER OF THE OWNER OW	O O ONIO HOL WHOMA C OI
_		
Sources of Information		
		46. Prepared by
hay country actas, 1077.	Ray County atlas, 1877.	
Ray County History, 1883. Onsite inspection.		RCHS & M
Biographical Dectionary of		
		48 Date 49 Revision Date(s)

- #42, Cont. include panelled doors, plain woodwork and curving, L-shaped staircase with plain bannister of vernacular design.
- #43. Cont. in the Missouri Baptist Church. His first wife was Eliza Bates, with whom he had four children. They married in 1845. His second wife was Margaret Morris, whom he married in 1856. They had 5 children. Spurlock served also as Director of the Hardin bank while farming.




FLOORPLANS NOT TO SCALE



PHOTOGRAPH



	4 Pres	sent Name(s)		
8, 86		D		
		Kemey Residence		
3 Location of Negatives RCHS & M	Rus	st Residence Rust Make	mey	
		Colones	28. No o	- Staring
	com Hardinl miles	16 Thernalic Calegory	28. No o	
to unmarked grav		17 Date(s) or Period	Full	nent? Yes!! No!.
Sec. 16 to intersec	inge 26 road	1925	30. Found	Jalion Malerial E
7 City or Town II Rue	al. Township & Vicinity	18 Style or Design		concrete 65
Hardin-Vic Crooked	River Twp	Eclectic 50 44  19. Architect or Engineer		Construction
H Site Plan with North Ar	row .	A.C. Rust	Brick 32. Roof	Type & Material
1,0	A /	20 Contractor or Builder	Gable-a	16
163	/\( \)	William Bohannon	33 No. of	Side
	a h	Residence	34. Wall T	NA Side NADR
TOTAL	1 9	22 Present Use	Common	Bond 30
		Residence		Shape Square
	7		blic I 36 Chang	in Aftered I
000	1	24. Owner's Name & Address,	in #42	
(0)		Al Con 3 M IZ	37. Condit	tion for Good
9 Coordinates	UTM	Alfred McKemey Hardin, Mo RR #1		or Good
Long		25. Open to	Yes II 38. Preser	vation Yes
Situ 1 1	Structure 1 i	Public?	No 1/2 Under	V-
11 On National Yes, 11	12 Is II Yes N.	26 Local Contact Person or Organization	on 39. Endan By Wh	
Register? No X	Eligible? No I I	27. Other Surveys in Which Included	40. Visible	e Irom Yes 🗡
Hist Dist? No N	Potent'l? No			Road? No 11
15 Name of Established D	District		7	ce from and
		7		ge on Road
42 Further Description of	Important Features	use has hipped roof with cent	150	
	110	use has hipped roof with cent Woodworks in rooms on the fir	ral brick chim	ney and
harvested on the f	arm. Cherry wood	in bedroom, walnut in living	room dining r	rom lumber
and kitchen. Spec	ial made door is	walnut on living room side bu	t cherry	Photo
wood on bedroom si	de, plastered. Whe	n built this was one of the	first rural	
homes in the area	to have electrici	ty. A Delco system furnished	32 volt	
power from a gasor	ine engine. Enclo	sed glassed front porch.	1.	
43 History and Significant	Land was first	purchased CA. 1890 by Dr. Bu	shrod Rust, M.1	D. who came to
rRay county from V	irginia. Bushrod	Rust never practiced medicine	e in Missouri bu	ut became a
prosperous farmer	with 10 children.	The present land was given a	as a wedding pre	esent to his son,
Later owned by don	no married Blanch	e Bayne, March7, 1893. The pr	esent house was	s built in 1925,
44 Description of Environ		ust McKemey, present owner is	ner son, great	grandson of Dr. Rus
Farm purchase in 1	890 included pres	ent large barn with hay loft.	Tile, building	g built
1918-1920 include	elevator for stor	ing grain, smoke house, and o	hicken house, h	Metal machine shed.
0				
45 Sources of Information			46. Prepare	ed by
Alfred McKemey on-site inspection				rs. Marvin Holsinger
on-site inspection Ray County History			47 Organi	
and country miscory	, 1713		RCHS & 48. Date	M 49 Revision Date(s)
			9/21/78	



FLOORPLANS

NOT TO SCALE



PHOTOGRAPH




## Office of Historic Preservation, P.O. Box 176, Jefferson City, Missouri 65101

1 No GX	4 Pres	sent Nam <b>e(s)</b>	The state of the s	
		S H McCuino In		
2 County Ray	5 Oth	S. H. McGuire, Jr. Other Namo(s)		
3 Location of Negatives		•		
RCHS & M		Calcacus	On No of Co.	
6 Specific Location		16 Thematic Category	28 No of Stories 2	
5 miles north of on Route A	Hardin, Mo	17 Date(s) or Period	Full Yes by No 1.	
TWP 52/R26/Sec.	10	1915	30 Foundation Material	
	Township & Vicinity	18 Style or Design	concrete 65	
Crooked River, TW		Vernacular -18	31. Wall Construction	
d Site Plan with North Arro		19. Architect or Engineer	frame Wu	
		John Rhodes	32. Roof Type & Material GB	
		20. Contractor or Builder . Proch	High Gable-Shingles 3	
1	<del></del>	John Rhodes · Fu	33. No. of Bays Front 3 Side	
1- 63		21. Original Use, il apparent		
((1))	100	residence: O/A	34 Wall Treatment 1st floor weather poarded	
		residence	2nd wood shingles 35. Plan Shape square	
(3)		23 Ownership Public     Private 14	36. Changes Addition : (Explain Altered)	
1		24 Owner's Name & Address,	in #42) Moved i	
		if known	37 Condition	
9 Coordinates U	TM	S.H. McGuire, Jr.	Interiorvery good	
Lat Long		Hardin Mo RR1	Extenorvery good	
10 Site ! )	Structure I i	25. Open to Yes II Public? No JA	38. Preservation Yes Underway? No X	
Building N	Object	26 Local Contact Person or Organization	39 Endangered? Yes	
11 On National Yes 11 Register? No K	12 Is II Yes DC Eligible? No I I	27 Other Surveys in Which Included	By What? No IX	
Hist Dist? No 34	14. District Yes 11 Potent'l? No p4		40 Visible from Yes X Public Road? No :	
15 Name of Established Dis	trict		41. Distance from and Frontage on Road	
42 Further Description of Im		4		
	no	use features wide veranda across	/-	
primary facade w	th gable echoi	ng that of the house itself.		
		anced by triple window to the le		
		indows. #36: Garage and porch	Photo	
appears to be an veranda.	addition to st	ructure, as is possible the		
veranda.				
			1	
43 History and Significance	Was built by G	randfather of present owner. The	is farm has been in the	
McGuire family s	ine th <b>e</b> late 18	90's. The old house was moved a	nd lived in while the	
		have been made on the outside by	ut some remodeling has	
been done on the	terior.			
44 Description of Environme	nt and Outbuildings	This beautiful home is on a hill	A woll kent ward	
shows lots of car	re. Several vo	ars ago some out-buildings were	destroyed and others	
torn down. A new	machine shed	is being huilt	desortoyed and others	
TOTAL GOWILL IN LICH	, machine shed	TO DETING DUITTO.		

45 Sources of Information

Mrs. Lula Wurtgel-Richmond, Mo daughter of owner at time house was built and aunt of present owner.

46 Prepared by Mrs. Marvin Holsinger RCHS & M 49 Revision Date(s) 8/14/79



FLOORPLANS NOT TO SCALE




PHOTOGRAPH



L NO. 90	4. PRESENT LOCAL NAME(S) OR DESIGNATION(S)		I. NO
2. COUNTY Ray	McCann Property  5. OTHER NAME(S)		
3. LOCATION OF RCHS	G.W. Stratton		
& SPECIFIC LEGAL LOCATION	N IS THEMATIC CATEGORY	\$ 28. NO. OF STORIES 111/2	io.
TOWNSHIP 500 RANGE ALOW SECTION IF CITY OR TOWN, STREET ADDRESS	17. DATE(S) OR PERIOD	29. BASEMENT? D- / YES ( )	COUNTY
from Hardin, take A north 3/4 i	ni. the ca. 1870	30. FOUNDATION MATERIAL	ALN
ardin vic. IF RURAL, VICINITY Crooked River	twp Greek Revival	ashlar stone 40	1.
8. DESCRIPTION OF LOCATION	19. ARCHITECT OR ENGINEER	frame WW. 32. ROOF TYPE AND MATERIAL	
	20. CONTRACTOR OR BUILDER		5
	unknown OH	33. NO. OF BAYS FRONT 4 SIDE 4	*
	21. ORIGINAL USE, IF APPARENT residence	34. WALL TREATMENT	RESE
	22. PRESENT USE	weatherhoard 2	N
	23. OWNERSHIP PUBLIC ( PRIVATE (	NO. 421	PRESENT LOCAL NAME(S)
	24. OWNER'S NAME AND ADDRESS	MOVED ( )	MAN
9. COORDINATES UTM	Jeff and Robert McCann	INTERIOR	
LAT LONG	25. OPEN TO PUBLIC? YES	EXTERIOR POOT  36. PRESERVATION YES ( )	OR
	CTURE( ) NO (X	) UNDERWAY? NO (X )	DESI
II. A NATIONAL YES ( ) 12. IS IT	YES (X)	BY WHAT? NO()	DESIGNATION(S)
SISTER ? NO ( X) ELIGIBLE !		neglect	NON
HIST. DISTRICT? NO ( X)	? NO(X 1.	PUBLIC ROAD ? NO()	
15. NAME OF ESTABLISHED DISTRICT		41. DISTANCE FROM AND FRONTAGE ON ROAD	•
42. FURTHER DESCRIPTION OF IMPORTANT	T FEATURES		Ç.
House of Greek Revival style	derivation presents heavy trabeated	PHOTO	OTHER
exception of half windows on	tion. Windows are two-over-two with the the second floor level. Pilaster boards		. 2
mark corners; boxed cornice a	and frieze continue around the house.	BE	NAME (S)
Window treatment on the other	r facades is less elaborate. Shed roof atinues styling of main block but with (	PROVIDED	9
43. HISTORY AND SIGNIFICANCE		CODE	
	ratton in county atlas of 1877.		
ar proper di co como co	radian in county actus of 1077.		0
			e. TOWNSHIP
			SHE
44. DESCRIPTION OF ENVIRONMENT AND	OUTRUL DINGS		3
	ed by cultivated farmland, no original ou	uthuildings or	MANGE
45. SOURCES OF INFORMATION 46. PREPARED BY Cameron			-
Ray County Atlas 1877.	47. ORGANIZATION	9501107	
July Acids 18//.	On-site inspection.	RCHS & M	2
		5/80	

- 6. Cont. 1/16th mile west on pathway through farmland.
- 42. Cont. detail. #39: House is abandonned and in poor condition.



FLOORPLANS NOT TO SCALE



PHOTOGRAPH



RCHS & M


8/79

48 Date 49 Revision Date(s)

Office of Historic Preservation, P.O. Box 176, Jefferson City, Missouri 65101

		OERIT (Namio(s)	
91		Dean Residence	
County	5 010	Dean Residence	
3 Location of Negatives	3 011	· · · · · · · · · · · · · · · · · · ·	
RCHS & M		Stevenson Residence	
5 miles north of Hard	14 P	16 Thematic Calegory	28 No of Stories 1-
J miles north of Hard	in on Route A	010	29. Basement? Yes X
54T521	NRabio	17 Date(8) or Period . 18 76	addition No:
	Township & Vicinity	1856 alt C, 1910 0000	30. Foundation Material 4047 ashlar stone/concrete
	River twp.	Neoclassic/Bungaloid additions	
8 Site Plan with North Arrow		19. Architect or Engineer	10g and Irame LC WU
Route A	J	unknown	32. Roof Type & Material (3)
	- 5	20. Contractor or Builder	gable-comp. shingles
		ППКЛОМП	33. No. of Bays
	4	21. Original Use, if apparent	Front 3 Side 1
13		residence OIA 22 Present Use	34. Wall Treatment 3
1	7	residence	composition siding 35. Plan Shape rectangular
All III	7	23 Ownership Public !	36 Changes Addition X
All IIII W		Private to	(Explain (Itered)
301111111111111111111111111111111111111	D	24. Owner's Name & Address,	in #42) Moved
9 Coordinates UT		Mr. and Mrs. James Dean	37 Condition Interior good
Lat	2 out	Hardin, Mo. 64035	Exterior good
Long		25. Open to Yes 11	38. Preservation Yes
Site 1 i Building iX	Structure 1 i	Public? No la	Underway? No X
	Object 11	26. Local Contact Person or Organization	39 Endangered? Yes II
Rugister? No 1X	2 Is It Yes i'll Eligible? No I I	27 011-0	By What? No k
13 Part of Estab Yes IJ	4. District Yes I I	27. Other Surveys in Which Included	
Hist Dist.? No 17	Potent'l? No Ki		40. Visible from Yes X Public Road?
15 Name of Established Distri	ict		41. Distance from and
			Frontage on Road
42. Further Description of Imp	orlant Features		
House consists of two	log rooms with	additions to rear. Was probably	
originally a dogtrot	nouse, but cent	er bay has been filled in. Many	
other alterations. On	riginal firepla	ce opening on the west facade.	
Primary foods fi	narrowed and a	new chimney constructed. #36:	Photo
as pediment shaped with	rst altered ca.	1870 by Neoclassic additions, suctor alterations obscured primary	14
facade, with two new	larger windows	cut on either side of doorway. (cor	
43 mistory and Significance			
The house was built in	1856 by John	Stevenson. The front two rooms we	ere the original house.
THE TAME TO BEAUTION	BANG THE HUITE	was built by neighbors of Stevenso	n. When the family
lived in the house th	ne yard was alw	ays swept with buck brushes of the	property.
44 Description of Environment	and Outbuildings		
Surrounded by locust t	rees of origin	al planting, in farmland. Farm ou	thuildings to the
south of the house.			resultatings to the
Sources of Information			46. Prepared by
Present owner			Marvin Holsinger
Stewenson family On-site inspection			47 Organization

On-site inspection.



FLOORPLANS

NOT TO SCALE



PHOTOGRAPH


#42. Cont. Bungaloid dormer added over primary entrance and shed roofed porch running the length of the primary facade. Interior was also altered ca. 1910, with french doors cut to communicate between dining and livingroom(log).



49 Revision Date(s)

Office of Historic Preservation, P.O. Box 176, Jefferson City, Missouri 65101

	INVENTORY  4 Present Name(s)	
James T. Williams Residence		
Ray	5 Other Namo(s)	
1 Location of Negatives RCHS & M	Blacks; Stevenson; Maiden, Bri	lght ·
	16. Thematic Category	28. No. of Stories one
6 Specdar Location north of Hardin county road A, east on	n on	29. Basement? Yes ! 1 1
road + mile. 53 52 N	Date(s) of Period	No K.
Rockinsham		30. Foundation Material ashlar stone 40
1 City of Town If Rural, Township & Hardin VL Crooked Riv		31. Wall Construction
H Site Plan with North Arrow	19. Architect or Engineer	frame www
	unknewn 20	32. Roof Type & Malerial Cross gable/comp. sh.
I A	20. Contractor or Builder unknown	33. No. of Bays 63
المالم	21. Original Use, if apparent	Front 1 Side 3
	residence O	34. Wall Treatment clapboard
11111	residence	35. Plan Shape C shaped
Room	25 Cwildianip	36. Changes Addition X
	Private IX  24. Owner's Name & Address.	(Explain Altered)
METAL DIE	SARN if known James T. Williams	37. Condition
9 Goordinates UTM	Hardin, Missouri	Interior good
Lat 2-001		Exterior good
	25. Open to Yes I I Public? No IX	38. Preservation Yes Underway? No X
	Object     26. Local Contact Person or Organization	39. Endangered? Yes 11
11 On National Yes 1 12. Is It Register? No 1x Eligible?	NO 11 27 Other Surrous in Which leakeded	By What? No %
13 Part of Estab Yes I 1 14. District	Yes i 27. Other Surveys in Which Included	40. Visible from Yes X
	? -No ix	Public Road? No 1:
15 Name of Established District		41. Distance from and Frontage on Road
wing added early in thi Neoclassic Molded fenes	dition of contemporary conveniences. East s scentury. Site predates Civil War. tration, pilaster connerboards, marrow turns and plain frieze surround the	Photo
43 History and Significance		
44 Description of Environment and Outborn Rural envieronment.	uildings	
45 Sources of Information		46. Prepared by
On-site inspection.		Jim Pease
		47. Organization




FLOORPLANS





-1 No 93	4 Pres	sent Name(s)	
2 County Ray		Williams Residence	
3 Location of Negatives	5 Oih	er Namo(s)	
RCHS & M  4 Specific Location 6 miles north of Hardi	P A	16 Thematic Category	28 No of Stories 2, 15
			29. Basement? Yes
road.		17 Dalo(s) of Period	No rx
Sec. 34 Twp. 5		ca. 1860	30. Foundation Material
	waship & Vicinity	18 Style or Design	äshlar stone 40
vic. Hardin Crooked R	iver twp.	vernacular  19. Architect or Engineer	31. Wall Construction
		unknown	frame . W u  32. Roof Type & Material GB
7 199		20. Contractor or Builder	gable-asphalt shingles
/a     L		Shanks and Williams family	33. No. of Bays 63
4 11 1		21. Original Use, if apparent	Front 3 Side 7
		residence ()IA	34. Wall Treatment 20
		22 Present Use residence	weatherboarding
Rocking	nam		35. Plan Shape rectangular
200-013	Vic.	23 Ownership Public   Private   X	36. Changes Addition 2
		24. Owner's Name & Address.	in #42) Moved
		Mrs. Callie Williams, Hardin, M	37 Condition
Coordinates UTM		J.T. Williams, Jr., Hardin, Mo.	
l at Long			Exterior good
Site Li		25. Open to Yes 11 Public?	38. Preservation Yes
Building Xi	Structure 1 i	140 (4)	Underway? No X
1 On National Yes II 12 I		26 Local Contact Person or Organization	39 Endangered? Yes   By What? No X
	Eligible? No 11	27. Other Surveys in Which Included	- No X
14	District Yes K	The state of the s	40. Visible from Yes X
	Potent'l? No Li		Public Road? No
5 Name of Established District			41. Distance from and
			Frontage on Road
2 Further Description of Imports	ent Features		
I-house has three-bay	primary facad	de, fenestration is two-over-two	
light aasnes with Neoc.	tassic window	neads. Central primary entrance	
		ont porch. L-story addition to re	
for the back rooms th	e front used	l two stairways. The back was used by the family. Later a door was	Photo
		rooms upstairs and the back stair	
		and balustres are made of walnut.	
pand Ga TX8 Sudifficance		· · · · · · · · · · · · · · · · · · ·	1
The Williams family car	me as pioneer	rs to Ray County before the Civil	War. Their first house
was a log house and li	ved there whi	ile the present home was being bui	lt. In the present
nome are several piece	s of furnitu	re that were built from the walnut	log house.
4 Description of Environment an	nd Outbuildings		
		Several farm outbuildings on th	e property.
	3 = == ==		- Inches
Sources of Information			
Mrs. Callie Williams			46. Prepared by Mr&Mrs Marvin Holsinger
J.T. Williams, Jr.		1	47 Organization
On-site inspection.			RCHS & M
		14	48 Date 49 Revision Date(s)

#42. Cont. and were handcarved by the builder.



FLOORPLANS

NOT TO SCALE




PHOTOGRAPH



Ray  A Present Name(s)  Hickory Grove Bap  5 Other Name(s)		
S Other reality	ptist Church	
RCHS & M	40005	
Specific Lucation 12 miles north from Richmond on	28 No of Stories one	
Route 13: east on B to F: east	29. Basement?	Yes
2½ miles. T52 R27 S11	full	No
City or Town If Rural, Township & Vicinity 18, Style, or Design		
Richmond vic Crooked River twp. 18 Style or Design	ashlar stone 31. Wall Construction	
Site Plan with North Arrow 19. Architect or Engineer	frame with brick v	ene
unknown	32. Roof Type & Material	
20. Contractor or Builder	gable/comp. shing	les
unknown	33. No. of Bays	1.
21. Original Use, If appare church		4
n 22 Present Use	34. Wall Treatment brick veneer	
church	35. Plan Shape rectan	on I
23 Ownership	Public 11 36. Changes Addi	
4 1		red
24. Owner's Name & Addr	ress. In #42) Mc	ved
il known	Hickory Crove Interior good	
Congregation of last	mickory drove	
Lanet Baptist Church	Exterior good	
Site 1: Structure 1: Public? restri	Yes XX 38. Preservation Cted No II Underway?	Yes
Building IXX Object     26 Local Contact Person		No
On National Yes!   12 Is II Yes!   Michael Hernoon,		Yes
Ringister? No IXX Eligible? No XX 27. Other Surveys in Which		
Part of Estab Yes   1	40. Visible from	Yes
Name of Established District	Public Road?	No
TO THE CONTROL OF STREET	41. Distance from and Frontage on Road	
Further Description of Important Features Single room church has four regularly spaced windows facades, double leaf primary entrance, covered by por Church has been given a veneer of brick and facade d obscured. New glass doubleleaf door on primary faca cornice and frieze remain.	rtico. #36:	/
Number of the state of the stat		
History and Significance Organized March 28, 1874 with 11 members, first pasto in Liberty Schoolhouse, then in Hickory Grove School 1877, originally had three walnut columns supporting was large blocks of wood cut from white oak trees. with stone. In 1934, an extensive remodelling progra Description of Environment and Outbuildings Hickory trees surround the hilltop where the church its name. A new church has been constructed to the	the present structure was built the roof in the center. Foundation In 1898 the wood blocks were replacement was begun. A full basement (continuous located from which it desired	in
Organized March 28, 1874 with 11 members, first pasto in Liberty Schoolhouse, then in Hickory Grove School 1877, originally had three walnut columns supporting was large blocks of wood cut from white oak trees. with stone. In 1934, an extensive remodelling programment and Outbuildings  Hickory trees surround the hilltop where the church its name. A new church has been constructed to the sources of information	the present structure was built the roof in the center. Foundation In 1898 the wood blocks were replacement was begun. A full basement (consist located, from which it derived north.  46. Prepared by	in
Organized March 28, 1874 with 11 members, first pasto in Liberty Schoolhouse, then in Hickory Grove School 1877, originally had three walnut columns supporting was large blocks of wood cut from white oak trees. with stone. In 1934, an extensive remodelling programment and Outbuildings Hickory trees surround the hilltop where the church its name. A new church has been constructed to the Scurces of Information Ray County History, 1973.	the present structure was built the roof in the center. Foundation In 1898 the wood blocks were replacement was begun. A full basement (consist located, from which it derived north.  46. Prepared by Cameron	in
Organized March 28, 1874 with 11 members, first pasto in Liberty Schoolhouse, then in Hickory Grove School 1877, originally had three walnut columns supporting was large blocks of wood cut from white oak trees. With stone. In 1934, an extensive remodelling programment and Outbuildings  Hickory trees surround the hilltop where the church its name. A new church has been constructed to the sources of Information	the present structure was built the roof in the center. Foundation In 1898 the wood blocks were replacement was begun. A full basement (consist located, from which it derived north.  46. Prepared by	in

#43. Cont. was palced under the church, the sanctumry redecorated and new windows installed. In 1848 a brick veneer was added and a new porch constructed. An new sandwary was built in 1970 just northeast of the old church. The furniture of the old church (not contempory with its first construction) was used in the new building.




FLOORPLANS NOT TO SCALE



PHOTOGRAPH



M.	[4 Pau	serit Name(s)	
	3	Jenkins Residence	
Ray Ray	5 01	ner Namo(s)	
Location of Negatives RCHS			
Specific Lucation		16 Thematic Calegory	28 No of Stories TWO1_
North of Richmon		030	29. Basement? Yes
13, then east the		17 Date(s) or Period	No
county road B.	C	ca. 1880	30. Foundation Material
Richmond vic. C	I. Township & Vicinity	18 Style of Design Vernacular	ashlar stone 40
Sile Plan with North Arr		19. Architect or Engineer	31. Wall Construction frame www.
V7///V7/7	A/	unknown	32. Roof Type & Material
	/X	20. Contractor or Builder Pnch	gable/asphalt shingl
V//X///	. h	21. Original Use, If apparent	33. No. of Bays Front 3 Side 1
n n	(4)	residence OIA	34. Wall Treatment U3
4 9 11	1	22 Present Use	asphalt shake shingl
1		residence	35. Plan Shape T shaped
•	ea	23 Ownership Public   Private   tr	36 Changes Addition
511 52N 27W		24. Owner's Name & Address.	in #42) Moved
		John Jenkins	37 Condition good
Coordinates (	JTM	Richmond, Missouri	
Long		25 Open to Yes II	38. Preservation Yes
Site Li	Structure 1 i	Public? NoXI	38. Preservation Yes Underway? No
Building of	Object 1 1	26 Local Contact Person or Organization	39 Endangered? Yes
On National Yes I I Register? No IX	12 Is II Yes Ki Eligible? No I I	27 Other C	By What? No
Part of Estab Yes II	14. District Yes II	27. Other Surveys in Which included	40. Visible from Yes
Hist Dist.? No Ki	Potent'l? No K		Public Road? No
Name of Established Di	strict		41. Distance from and Frontage on Road
interior stove cl	se has been shea himmeys. #36: orch reuses orig	thed in asphalt shingles. Two one story addition to rear. New inal turned posts. New stove	Photo
History and Significance			1
Description of Environmentary outbuildings	•		
Sources of Information			
on-site inspection	on.		46. Prepared by Cameron
			47 Organization RCHS & M
			48 Date 49 Revision Date(s)
			5/80



FLOORPLANS NO

NOT TO SCALE



PHOTOGRAPH

36-185

- #42. Cont. The same pattern is recommended in several of Asher Benjamin's plan books.

  The frieze design is a row of garlands, also created with drilled holes and carving. The design has no counterpart extant in Ray County. Interior end chimneys are of brick. Fenestration of primary facade is not regular, although close inspection does not reveal evidences of two stages of building.
- #43. Cont. lumber, both great needs of people in the area. Zimmerman's mill served people from great distances, who would capp out while their grinding was being done. The "saw rig" of the mill was what was known as a sash saw. On it Zimmerman fashioned the lumber for this house, which he built shortly after settling here.



47 Organization


RCHS & M

48 Date 49 Revision Date(s) 9/78

#### Office of Historic Preservation, P.O. Box 176, Jefferson City, Missouri 65101

1 No 8	7 4 Pies	ent Namo(s)	
2 County	-	Holsinger Residence	
Ray	5 Oth	er Namo(s)	
3 Location of Negatives RCHS &	М		
6 Specific Lucation		16 Thematic Category	28 No of Stories 12
$\frac{1}{2}$ mile northeast	of Hardin on		29. Basement? Yes 1%
County Route DD.		17 Datu(s) or Period	No I
Sec. 28, Twp. 52,		1915	30. Foundation Material
7 City or Town If Aural. Vic. Hardin; Croo	Township & Vicinity	18 Style or Design	concrete 65
8 Sile Plan with North Arro		vernacular 49	31. Wall Construction
	tes.	unknown	frame. Wu 32. Roof Type & Material 16
R I		20. Contractor or Builder Prich	cross gable-asphalt
1	- 1	John Rhodes	33. No. of Bays
80		21. Original Use, if apparent	Front n/a Side n/a
V	4'	residence OIA	34. Wall Treatment
		residence	vinyl siding 42  35. Plan Shape square
		23 Ownership Public   1	36. Changes Addition.
		Private ki	(Explain Altered
Route DD		24. Owner's Name & Address,	in #42) Moved i
		Marvin Holsinger	37 Condition Interior good
Coordinates UT	М	Hardin, Mo. RR #1.	
Ling		25 Open to Yes I I	Exterior good
Site 11	Structure 1 i	Public? No Id	38. Preservation Yes Underway? No X
Building Xi	Object 11	26 Local Contact Person or Organization	39 Endangered? Yes II
Register? No 1.	12 Is II Yes to Eligible? No I I		By What? No IX
3 Part of Estab Yes II	14. District Yes i	27. Other Surveys in Which included	
Hist Dist.? No IX	Potent'l? No 04		40. Visible from Yes 'X Public Road? No
5 Name of Established Dist	rict		41. Distance from and
			Frontage on Road
12 Further Description of Im	portant Features		
		rimary facade at northeast corner.	
shaped him roof. I.	ow sable on each	er porch is cupola, with bell- h facade has triple window in	
center. Other fene	stration is irr	egular. #36: There have been no	Photo
additions to the ho	use. Only alte:	ration is addition of vinyl	
siding, obscuring of	riginal facade	details.	
			1.
House built on land	homostooded be-	Lorgo Forms in 10kli vi	10.11
present owner. Second	and owners Niles	Jesse Esry in 1844. He was greates Esry; Minnie Esrey Holsinger; to	-grandiather of the
house was one of the	e first to have	electric lights, powered by a gas	present owner. This
basement.		ponozou oj a gas	OTPLIE TH MIC
4.0			
4 Description of Environmen	and Outbuildings	1 1 2	
outbuildings.	and; wooden fram	me double garage, chicken house and	d metal barn are only
THOURTTOTING.			
5 Sources of Information	-		
	- C		46. Prepared by
Personal knowledge	or surveyor.		Marvin Holsinger

On-site inspection.



**FLOORPLANS** 

NOT TO SCALE




PHOTOGRAPH



49 Revision Date(s)

4/78

1 Nu 80	4 Present Name(s)	
County	Meador Residence	
Ray	5 Other Namo(s)	
CHS & M	Kallenberger Residence	
6 Specific Lucation	18 Thematic Category	28 No of Stories two
2 miles north of Hardin	on State 030	29. Basement? Yes IX
Route DD 315 T52 A	J 26W 17 Dalu(s) or Period	No I
	1926	30. Foundation Material
7 City or Town II Rural, Towns		ashlar stone 40
vic, Hardin Crooked Riv		31. Wall Construction
a Sile Flan with North Arrow	19. Architect or Engineer Tom Williams	frame, wu
	N 20 C-1-1-1- S 11	32. Roof Type & Material GB
		gable-asphalt shingles
	21. Original Use, If apparent	Front 3 Side n/a
-	residence OIA	24 Minit Treatment
M M	22 Present Use	weatherboarding
	residence	os. Fian Shape Square
	23 Ownership	Public 1 36. Changes Addition
	24. Owner's Name & Address.	Private 1): (Explain Altered 1: In #42) Moved 1
'Route DD	il known	37 Condition
• Coordinates UTM	Mrs. Russell Meador	Interior good
Long	Norborne, Mo. RR 2	Exterior good
	. 25 Open to	Yes I i 38. Preservation Yes
Site 1 i Building Xi	Structure	No IX Underway? No X
II On National Yes II 12 Is II	To rocal Contact Letson of Ordanis	
	ible? No 11 27. Other Surveys in Which included	By What? No X
3 Part of Estab Yes I 1 14. Dis		
	ent'l? No Ki	Public Road? No ::
15 Name of Established District		41. Distance from and
		Frontage on Road
42 Further Description of Important	Features	
Eclectic house has Neocla	Features assic window heads, l-over-1 window s	sashes.
rrimary facade displays	central primary entrance flanked by	double
story are covered by gami	e window on east. Double windows on brel-roofed dormers which are sheather	second
imbricated shingles. Br	ick interior chimney on west facade.	ed in Photo
veranda on two-thirds of	primary facade wraps around to east	front
There have been no altera	ations to the structure.	racade.
The Kallenberger grandfa	ather came from Ohio and bought this	land in 1864. He built a log
" O OF O OF OTHER TOTAL TITLE	om the present nome. He then him it a	a larger home and in 1026 big
sout wittigm varieuperdel	r. Dullt this house. The fourth and	fifth generation are now living
on the raim. (Mrs. Meado	or is the daughter of William).	
4 Description of Environment and C	Outhuildings	
House is located on a hi	igh hill with a view of the surroundi	ng country The
farm buildings on the pro	operty.	inere are several
Sources of Information		
Mrs. Russell Meador, North	ponrne.	46. Prepared by
On-site inspection.		Mr&Mrs. Marvin Holsinge:
•		RCHS & M
		HIGHS & M



FLOORPLANS

NOT TO SCALE




**PHOTOGRAPH** 



49 Revision Date(s)

48. Date 8780

No 7 76	4 Present Name(s) White Residence	smoke have ok
Ray	5 Other Namo(s) Gaer-Wall	wash him ore Barra 09809 Shed 09F
Location of Negatives RCHS & M		The second secon
Specific Lucation 2 miles porth of Hardin on	4 to P. D3D DIO	28 No of Stories one 29. Basement? Yes!
yest 1/2 mi to gravel road 4 mi then west 1/8 mi.	ca. 1880	30. Foundation Material ashiar stone
City of Town It Rural, Township lardin vic. Crooked River	twp. Neoclassical	31. Wall Construction frame
Site Plan with North Arrew 1 Rot	19. Architect or Engineer unknown 20. Contractor or Builder	32. Rool Type & Material gable-comp. shingles
WASH HOUSE	unknown 21 Original Use, if apparent	33. No. of Bays Front 3 Side ]
B 11 B	residence 22 Present Use	34. Well Treatment weatherbeard 35. Plan Shape L shape
	residence  23 Ownership Public   1 Private Kil	36. Changes Addition (Explain Altered
N O TT	24. Owner's Name & Address.	37 Condition excellent
Coordinates UTM	Clifton and Hazel White Box 74, Hardin, Missouri	Exterior excellent
tony 51 T53N 261	25 Open to Yes 11 Public? N9XXX	
Building XI  1 On National Yes II 12 Is II	Object 11 26 Local Contact Person or Organization Yes Ivi	39 Endangered? Yes By What? No
Register? No X: Eligible 14. Distri	ct Yes II	40. Visible from Yes Public Road? No
Hist Dist.? No XI Poten  15 Name of Established District	117 No 1X	41. Distance from and Frontage on Road
42 Further Description of Important F	eatures	
This is an unspoiled example century. Small Neoclassic conrice and frieze with repilaster cornerboards. A elevation with cornices and sawn brackets. Primary fawindows 1/1 sash. El to red 3 History and Significance	le of Ray County farm at the turn of the cottage features heavy, molded boxed turns, trabeated windows and doors with veranda runs the length of the primary d brieze carried by turned posts with jigcade has central entrance flanked by pairs ear contemporary with main block, enclosed	d rear porch.
first settlers in RayCount (1807-1910) in 1868. Wern Wall (1884+1959) married M	lt by Octavius Wall, 1857-1940, whose gramy. this property was part of the original er's daughter Agnes married Octavius; the ary Lydia Stephens of Monroe County in 19	i warner daer rarm ir only son William Warn
44 Description of Environment and C		
House is surrounded by con and washhouse. Original p	temporary outbuildings; barn, root cellar lantings.	, shed , smoke house
45 Sources of Information		46. Prepared by Cameron
On-site inspection.	Ray County History 1973	47 Organization RCHS & M



FLOORPLANS

NOT TO SCALE



PHOTOGRAPH



Office of Historic Preservation, P.O. Box 176, Jefferson City, Missouri 65101

No	14 A Presen	Name(s)	
	7	Travillion Residence	
Ray	5 Other	Namo(s)	
Location of Negatives RCMS	9	Renick House	
Specific Lucation north	of Richmond on	16 Thematic Category	28 No of Stories two 29. Basement? Yes
ww 13 to County r	road B; east to	17 Date(s) or Period	29. Basement? Yes y
, then 2 mi. til Foad; 1/2 mi. to di	becomes gravel	mi. ca. 1870 alt C 1916	30. Foundation Material
City or Town II Rural	, Township & Vicinity	18 Style or Design	ashiar stone
ichmond vic. Croc	oked River Twp.	vernacular/Neoclassic	frame .Wu
Site Plan with North Arre	M	unknown	32. Roof Type & Material
twy F	11 6	20 Contractor or Builder	gable-comp. shingles
h	ا (ر ۲	21. Original Use, if apparent	Front 5 Side 1
OF IT	1 0	residence OIA	34. Wall Treatment 63
1 11 1	(3)	22 Present Use r esidence	comp. shingles 35. Plan Shape T-shape
	7		ublic 11 36. Changes Addition
-	0	Pri	ivate 1/2 (Explain Altered Moved
	~ 4 7	24. Owner's Name & Address, if known	37 Condition
$m \sim$	M W	Gary Sneed	Interior good fair
Coordinates Lat Stl	T 53N R 27W	Norbonne, Missouri	Exterior
Long		25 Open to Public?	Yes I i 38. Preservation Yes No VI Underway? No
Site Li Building Xi	Structure 1 i	26 Local Contact Person or Organizat	ion 39 Endangered? Yes
On National Yes !!	12 is ii Yes ix		By Whai? No
Register? No 1x	Etigible? No 17	27. Other Surveys in Which Included	40. Visible from Yes
Hist Dist.? No XI	14. District Yes 11 Potent'l? No IX		Public Road? No
5 Name of Established (	District		Frontage on Road
12 Further Description of	Important Features		
Vernacular I-House	with large two	story el extending from mai	n block
to the north. One	remaining inter	iorbrick fireplace chimney (	now
stuccoed) I remove Most likely had Ne	ed. Kemaining Dr	ick stove chimney at gable one, but this has been obscur	red /
by addition of shi	ingles. Original	windows are 4/4light. Porc	ches
added ca. 1910.	12		1.
43 History and Significan	nce		
This is the homepl	lace of the Renic	k family, which is according	to a 1898 biography, "synono-
mous with anaray	thrift and moral	qualities." The father Jan	nes w. Renick wassburn in lolo
HIS tather died ve	ery young and ne er to lafavette C	ounty, 1830. James apparent	When she became a widow, he tly had inherited enough (cont
44 Description of Environ			
		house was recently demolish	ned Original plantings
front the house.	ary date with the	house was recently demolish	ica. Original plantings
			46. Prepared by
45 Sources of Information		County Atlan 1977	Cameron
On-site inspection	n Kay	County Atlas, 1877.	47 Organization RCHS & M

Biographical History of

Clay, Ray, etc.. 1898.


49 Revision Date(s)

48. Date

7/80

Ron Travillion, occupant fof the house.

#42. Cont. money to buy 100 acres which he cultivated. In 1839, He married Willie Warden. In 1844 James began freighting for the U.S. Government to western points like Colorada, New Mexico and California. He became very successful and acquired 1200 acres of land. The Civil War, during which he traded to both sides but supported the Confederacy, left his land greatly depreciated and lost him his business, owing to "the ravages of both armies". In 1869 he came to Ray County and bouth 640 acres on the present site and constructed this house. He died here in 1892. The farm was inherited by his six surviving children.



FLOORPLANS

NOT TO SCALE




**PHOTOGRAPH** 



7/80

No 108		it Name(s)	
County		Gill Property	
Ray	5 Other	Namo(s)	
Location of Negatives		Old Gill Place	
RCHS		16 Theinetic Category	28 No of Stories two 2-
Specific Location 1 mi. southeast of Hen		030	20 Basement? Yes
Route 13, east on coun		17 Date(s) or Period	No y
J 1 1/2 mîles.	•	ca. 1880	30. Foundation Material
City or Town Il Rural, Towns	hip & Vicinity	18 Style or Design	ashlar stone 40 6
Cily or Town Il Rural, Townsl Henrietta vic. Crooke	d River two	vernacular/Neoclassic details	frame wu
Site Plan with North Arrow		19. Architect or Engineer unknown	32 Roof Type & Material es sall thox-compshingles
636363		20. Contractor or Builder	
	)	unknown	33. No. of Bays Front A Side
		21. Original Use, if apparent	34. Wall Treatment
<u> </u>		residence OIA	weatherboard
			35. Plan Shape rectangul
		Vacant 23 Ownership Public I !	36. Changes Addition
S13 TOIN 2	iu)	Private XX	(Explain Altered
513 15116		24. Owner's Name & Address,	
		if known	interior fair
Coordinates UTM		Ray Gill	Exterior fair
Long		Henrietta, Missouri	38. Preservation Yes
	Structure 1 i	Public? NoXX	Underway? No
Building ***	Object	26 Local Contact Person or Organization	39 Endangered? Yes By What? No
On National Yes II 12 Is I	, , , ,		neglect
Villagistar VXX	gible? No II	27. Other Surveys in Which Included	40. Visible from Yes
Part of Estab Yes I 14. Di	strict Yes II		Public Road? No
Name of Established District			41. Distance from and
Traine of Established States			Frontage on Road
2. Further Description of Importan			
Two story doublepen ve	ernacular h	ouse with saltbox roof covering	
rear portion which app	pears to be	original. Usual Neoclassic se form: boxed cornice, pilaster	Photo
corner boards trabeat	tacular nous	dows. House sits on concrete	
foundation: enclosed r	porch on ea	st facade. One interior center	
stove chimney remains.	. #39: Ho	use is vacant, slowly deteriorating	9
but still in fair cond	dition.Has	new roof.	
	C A F-:-	in 1977 This house tune is wytan	t only in southern
Pay County area in	o.A. Fain	in 1877. This house type is wxtan s of the Missouri River. There ar	e two houses of this
vernacular type within	n a mile of	this one, but both in very poor s	tate of preservation.
. armadarar og po midnin			
4 Description of Environment and	d Outbuildings		
Some original planting	g to rear o	f house. Modern outbuildings surr	ound house, but are in
disrepair.	5		
15 Sources of, Information			46. Prepared by
On-site inspection.	Ray C	ounty Atlas, 1877.	Cameron 47. Organization
	٦		RCHS & M
			48 Date 49 Revision Datel



FLOORPLANS


NOT TO SCALE



PHOTOGRAPH



	06	Basil Gibson House	
Ray	5 Olhe	Namo(). Campbell House	
Location of Negatives RCHS		16 Thematic Category	28 No of Stories two
Specific Location 3/4 mi. south of 1	Hardin on J.	030	29. Basement? Yes I No Iy
east on ummarked	gravel road 3/8	17 Date(s) or Period	30. Foundation Material
mi; south 3/4 mi.		ca. 1900	ashlar stone 40
City or Town II Rural, Hardin Vice Croo	Township & Vicinity	18 Style or Design Neoclassic	31. Wall Construction
Site Plan with North Arrow	Wed Hive tup	19. Atchillect of Engineer	frame UM
		Unknown 20. Contractor or Builder	32. Roof Type & Material Cap gable-comp shingles
1 Ш		Unknown	33. No. of Bays
- VIXIX	(9)	21. Original Use, if apparent	Front 3 Side
( )	4671	residence O(A	34. Wall Treatment weatherboard
43	1 /b	22 Present Use	35. Plan Shape rectangula
		residence 23 Ownership Public   1	36. Changes Addition
0		Private X	(Explain Attered Moved
6.9	300	24. Owner's Name & Address,	37 Condition
0			Interior good
COOMMINGTON	TM	Basil Gibson, Jr. Hardin, Missouri	Exterior good
Long		25. Open to Yes 11	A1-
Site Li	Structure 1	Public? No XI	39 Endangered? Yes
Building XI	Object	26. Local Contact Person or Organization	By What? No
Register? No k	12 Is II Yes !) Eligible? No !		
Part of Estab Yes II	14. District Yes I		40. Visible from Yes Public Road? No
Hist Dist.? No XI	Potent'l? No ly		41. Distance from and
5 Name of Established Dis	strict		Frontage on Road
	•		
Addition of shut single story add primary elevation and frieze a recremoved.	tury three bay ters to primary lition of kitch on is later add cent addition.	I-house, nearly unspoiled.  y and secondary facades. Small en to rear. ONe story porch on ition. Also, with cast=iron posts One interior stove chimney has be	Photo
43 History and Significance	e		on this cite but
	ned by Mrs. M.	Campbell in 1877; a house is showr ture.	I OII CIII'S STOCY DAG
probably not the	nent and Outbuilding	5	
probably not the	ment and Outbuilding	the house include shed, root cel	
OUtbuildings columnes predate to	nent and Outbuilding ntemporary with he house.	the house include shed, root cel	46. Prepared by
OUtbuildings contrees predate to	nent and Outbuilding ntemporary with he house.	the house include shed, root cel	46. Prepared by Came ron 47. Organization
OUtbuildings contrees predate to	nen and Outbuilding ntemporary with he house.	the house include shed, root cel	46. Prepared by Came ron



FLOORPLANS


NOT TO SCALE



PHOTOGRAPH



1 No	A Pre	sent Name(s)	
96		arion Wright Residence	
. County		wright Residence	
Location of Negatives RCHS		(Namo(s)	
Company of the Compan			
3/4 mile east of c	ity limits of	16 Thematic Category	28 No of Stories two
Wardin on Route 10		17 Datu(s) or Period	29. Basement? Yes
SR	10	ca. 1890	30. Foundation Material
	al, Township & Vicinity	18 Style or Design	ashlar stone 40
vic. Hardin Croo	ked River twp.	vernacular 09	31. Wall Construction
3 Sile Plan with Worth Ar	row	19. Architect or Engineer unknown	frame WLL
1 69		20. Contractor or Builder	32. Roof Type & Material GE gable-comp. shingles/
N O		unknown CP	33. No. of Bays
10		21. Original Use, if apparent	Front 3 Side 1
	-	residence //	metal siding 50
CJ		residence	35. Plan Shape rectangular
40		23 Ownership Public ! !	36. Changes Addition 3
		Private ld 24. Owner's Name & Address.	(Explain Altered 2
Route 10		if known	37 Condition
	MTM	Marion C. Wright, Sr. Hardin, Mo.	Interior good
Lung	5 520 2600	25 0	Exterior good
Site Li	Structure	Public? Yes I I	38. Preservation Yes Underway? No
Building ig	Object 1 1	26 Local Contact Person or Organization	39 Endangered? Yes
On National Yes II Register? No IX	12 is it Yes M		By What? No
Part of Estab Yes I I	14. District Yes I I	27. Other Surveys in Which Included	
Hist Dist.? No IX	Polent'l? No IX		40. Visible from Yes 2 Public Road? No
Name of Established D	istrict		41. Distance from and
			Frontage on Road
2 Further Description of	Important Features		
ernacular I-house	has three-bay pr	rimary facade. Central primary	
window heads. #36	: House has large	o lights all have Neoclassic addition to rear facade. Origin	
irchitectural deta	ils are obscured	by addition of metal siding. New	Photo
one-story porch to	primary facade.		
3 History and Significance	e		1.
	•		
Description of Environm		·	
outside of small to	own of Hardin, on	working farm. Several outbuilding	gs on the property.
1			
Sources of Information			
y County Atlas,	1877		46. Prepared by
n-site inspection,			Cameron  47 Organization
20000000			RCHS & M
			48 Date 49 Revision Date(s)
			8/80



FLOORPLANS

NOT TO SCALE



PHOTOGRAPH




RCHS 48 Date

4/78

49 Revision Date(s)

1 No 05 101 4 Pr	esent Name(s)		
97 101	Summers Residence		
	Other Namo(s)		
tocation of Negatives RCHS & M	Hughes Residence; Myers Residence	ce	
6 Specific Location	16 Thematic Category	28 No of Stories two	
2½ miles east of Hardin on Highway		29. Basement? Yes III	
0 on south side of road. Se 10	17 Daidial of Letton	No X	
ec. 2, Twp. 51, Range 26	1883	30. Foundation Material	
7 City or Town If Rural, Township & Vicinity		brick	
vic. Hardin Crooked River twp.	vernacular  19. Architect or Engineer	31. Wall Construction	
Highway 10	William B. Hughes	frame . WW.  32. Roof Type & Material GB	
	20. Contractor or Builder	gable-asbestos shingles	
	John McGregor TO	33. No. of Bays	
	21. Original Use, If apparent residence OLA	Front 3 Side 1	
	22 Present Use	34. Wall Treatment	
	residence	weatherboarding	
<b>**</b>	23 Ownership Public ! !	35. Plan Shape rectangular 36. Changes Additionx	
	Private X I	36. Changes Addition X (Explain Altered X)	
	24. Owner's Name & Address,	In #42) Moved 1	
	Mrs. Ada Mae Summers, Hardin, Mo	37 Condition	
9 Guardinates UTM	J,W. Lentz, Prairie Village, Ks.	Boot Boot	
Luny	25 Open to Yes II	Exterior	
Site 1   Structure 1	Public 2	38. Preservation Yes Underway? No X	
Object 11	26 Local Contact Person or Organization	39 Endangered? Yes !!	
On National Yes II 12 Is it Yes M Register? No IX Eligible? No II		By What? No IX	
13 Part of Estab Yes I 1 14. District Yes I 1	27. Other Surveys in Which Included		
Hist Dist.? No I K Potent'l? No K		40. Visible from Yes X Public Road?	
15 Name of Established District	1	41. Distance from and	
		Frontage on Road	
42 Euriber Description - A least		100 ft.	
42 Further Description of Important Features	oclassic heads on doors and windows,		
Interior brick stove chimneys. #3	Classic heads on doors and windows,		
The original front porch has been	rebuilt. Screen and storm windows		
have been added. Otherwize house	is as built except for addition to	Photo	
rear ofhouse.			
43 History and Sumilicance	·	1	
William B. Hughes built the house	and remaining outbuildings in 1883.	The land was inherited	
from his father Berry Hughes.			
44 Description of Environment and Outbuildings			
Large well-kept yard with outbuild	ings contemporary with the house.	Original plantings	
including a bush brought from the	Holy land in the 1880's and given t	o Mrs. William Hughes,	
te of the first owner.			
45 Sources of Information		46 Proposed by	
s. Ada Mae Summers.		46. Prepared by Mr&Mrs. Marvin Holsinger	
on-site inspection.		Marvin Holsinger	



FLOORPLANS


NOT TO SCALE



PHOTOGRAPH



	0.3	Weisz Residence	
2 County		er Namo(s)	
3 Location of Negatives		er (tellio(s)	
3 Location of Negatives RCHS & N	1	Quinn Residence	
6 Specific Lucation		16 Thematic Category	28 No of Stories two
$l_2^{\frac{1}{2}}$ miles east of h	lardin on State		29. Basement? Yes 11
Highway 10.	- A	17 Date(s) or Period	No ½
Sec. 26 Range 26 T		ca. 1880	30. Foundation Material
Vic. Hardin Groo	al. Township & Vicinity oked River two.	16 Style or Design Vernacular	ashlar rubble 90
8 Site Plan with North Ar		Vernacular  19. Architect or Engineer	31. Wall Construction
	W	unknown	frame: Wu  32. Roof Type & Material (2)
		20. Contractor or Builder	gable-asphalt shingles
		unknown	33. No. of Bays
m	7	21. Original Use, if apparent	Front 3 Side 1
	• 1	residence OIA	34. Wall Treatment 50
	<b>4</b>	22 Present Use residence	INCOURT DIGITIE
	1 7		35. Plan Shape L-shaped
		23 Ownership Public 1: Private 1-	36. Changes Addition X: (Explain Altered 20
		24. Owner's Name & Address,	in #42) Moved i
Highway 10		il known	37 Condition
	UTM	Peter Weisz	Interior excellent
Lat Long		Hardin, Mo.	Exterior excellent
Site 11		25. Open to Yes I i Public? No IX	38. Preservation Yes
Building ix	Structure 1 i	26 Local Contact Person or Organization	Underway? No x
11 On National Yes II Register? No IX	12 Is It Yes XI Eligible? No I I		39 Endangered? Yes II By What? No IX
13 Part of Estab Yes II	14. District Yes II	27. Other Surveys in Which Included	00 Winds 4
Hist Dist.? No by	Potent'l? No XI		40. Visible from Yes X Public Road? No :
15 Name of Established D	istrict		41. Distance from and Frontage on Road
Two interior brick	as original detai erior is unaltere stove chimneys n	als obscured on the exterior by ad except for addition to the rear now serve still wood stoves. #36: rears ago. Metal siding and shutter	
	ve been construct	ed by J. Quinn about 1880.	
44 Description of Environm Surrounded by farm		dern outbuildings on the property.	
45 Sources of Information			
Mrs. Peter Weisz			46. Prepared by
Ray County Atlas, ]	877.		Cameron !
On wsite inspection.			RCHS & M
•			48. Date 49 Revision Date(s)
			8/80



**FLOORPLANS** 

NOT TO SCALE




PHOTOGRAPH



## Office of Historic Preservation, P.O. Box 176, Jefferson City, Missouri 65101 HISTORIC INVENTORY

1 No	104 A PIE	B. C. Timb. Proposition	
ounty	1 00	E.C. Link Property	
Ray	5 01	ner Namo(s)	
RCHS RCHS			
6 Specific Lucation		16 Thematic Category	28 No of Stories $1/1\frac{1}{2}$
	Hardin on State		29. Basement? Yes
Hywy 10. 536 T52 N	21-41	17 Date(s) or Period	No
	ral. Township & Vicinity	ca, 1870 (1900 0000	30. Foundation Material
crooked River to	p. vic Hardin	18 Style or Design Neoca	ashlar stone 40
Sile Plan with North A	ow	19. Architect or Engineer	frame .ww.
	3	unknown	32. Roof Type & Material GR
1		20. Contractor or Builder unknown	gable/asphalt shingl
	Ley,	21. Original Use, if apparent	33. No of Bays Front 3 Side 3
		residence	34. Wall Treatment
	7 (3)	22 Present Use residence	weatherboard
M ~ (1)	<b>-</b>		35. Plan Shape LR
3 63		23 Ownership Public 1 1 Private 1X	36. Changes Addition. (Explain Altered
0		24. Owner's Name & Address,	in #42) Moved
Hywy 10		E.C. Link	37 Condition
Coordinates	UTM	Route 3, Hardin, Missouri	Exterior excellent
Long		25 Open to Yes II	
Site Li	Structure 1 i	Public? No IX	Underway? No
Building X	Object 11	26 Local Contact Person or Organization	39 Endangered? Yes
Register? No K.	12 Is II Yes XI Eligible? No II	27. Other Surveys in Which Included	By What? No
Part of Estab Yes II	14. District Yes I I	27. Other Surveys in Which included	40. Visible from Yes
Hist Dist.? No Ki	Polent'l? No XI		Public Road? No
5 Name of Established D	istrict		41. Distance from and Frontage on Road
carpenter Gothic gable of porch fi	tory cottage has boards, boxed cor porch with turne lled with embrica	Neoclassic details including rnice, undecorated frieze. Good ed posts and jigsawn porch frieze; ated shingles. Extensive additions of compatible styling.	Photo
History and Significance	-	·	1
House has been ve date with thehous	ery little altere	ed and with surrounding outbuildings umple of a Ray County farm during to in the 1870's.	of contemporary the turn of the century
Outbuildings inclusmall working farm	ide: tenanat hou	use; well house; barn; outhouse; ro	otcellar. On a
Sources of Information			I
Ray County Atlas,	1877.		46. Prepared by
On-site inspection			Cameron 47 Organization RCHS & M
			48 Date 49 Revision Date(s)



FLOORPLANS

NOT TO SCALE




PHOTOGRAPH



49 Revision Date(s)

## Office of Historic Preservation, P.O. Box 176, Jefferson City, Missouri 65101 HISTORIC INVENTORY

1 No 6 10	7 4 Pre	sent Name(s)	
. County		Hardin Truss Bridge	
Ray	5 011	ner Namo(s)	
3 Location of Negatives			2
6 Specific Location		16 Thematic Calegory	28 No of Stories n/a
1 3/4 miles east of			26 No of Stories n/a.  29. Basement? Yes III
Hywy 10, then north l mile to fork; east		17 Date(s) or Period	n/a No
- Cl-		ca. 1889-1 <b>9</b> 91	30. Foundation Material
	Township & Vicinity	18 Style or Design	n/a
vic. Hardin; Crooke	d River twp.	Pratt type truss bridge 19. Architect or Engineer	31. Wall Construction
	11 1	unknown	Wrught iron 32. Roof Type & Material
.\ ~~	// N	20 Contractor of Builders de company	n/a
11 -622	3	Dayton, Onto	33. No. of Bays
1/6/1	(3)	21. Original Use, if apparent bridge	Front n/a Side n/a
12363	Se w	22 Present Use	34. Wall Treatment n/a
160		bridge	
The		23 Ownership Public IX	35. Plan Shape rectangular 36. Changes Addition
11		Private 1 i	(Explain Altered 1:
11 52	2 5/N 21W	24. Owner's Name & Address,	in #42) none Moved
		County of Ray	37 Condition good
UTN Lat		Ray County Courthouse, Richmond	Exterior
Long		25 Open to Yes IX	38. Preservation Yes
Site Li	Structure 1 i	Public? No 11	Underway? No X
Building Ki	Object 1 1	26 Local Contact Person or Organization	39 Endangered? Yes II
11 On National Yes II 12 Register? No IX	2 Is II Yes II Eligible? No IXI		By What? NoX
	4. District Yes I	27. Other Surveys in Which included	
Hist Dist.? No to	Potent'l? No by		40. Visible from Yes X Public Road?
15 Name of Established Distri	ct		41. Distance from and
			Frontage on Road
42 Further Description of Impo	riant Festives		
		h wooden plank deck, built'	Photo
43 History and Symplicance		· · · · · · · · · · · · · · · · · · ·	1
Plaque on bridge give	ngo as county	ounty officials at time bridge was clerk, from 1889-1891. One of two	built, dating bridge remaining iron
Over a small creek in but in good condition	n a rural sett		wn with foliage
Sources of Information			46 Proposed by
On-site inspection.			46. Prepared by Cameron
Ray County Atlas, 18		or 61 at 10 at 1 at 1 at 1 at 1 at 1 at 1 at	47 Organization
Comp and Jacks	e recninical L	eaflet "Bridge Truss Types" #15	NCHS & M



FLOORPLANS


NOT TO SCALE



**PHOTOGRAPH** 



	4 Present Name(s) Minnick House	
County Ray	5 Other Name(s) Hoover House	•
Specific location orth of Hard	16. Themalic Calegory	28. No. of StoriesWO
marked gravel road; the	hen west 17 Date(s) or Period	29. Basement? Yes ! 1 No IX
City of Town II Rural, Townsh vic. Hardin Crooked	no & Vicinity 18 Style or Design	ashlar stone  31. Wall Construction
Site Plan with North Arrow	19. Architect or Engineer unknown	frame Wu
ROOT CELLAR	20. Contractor or Builder unknown	32. Roof Type & Material gable-comp Shingles  33. No. of Bays
GARAGE & CO	21. Original Use, if apparent residence OIA	Front 3 Side 1  34. Wall Treatment
TO LA	22 Present Use residence	clapboard of. 35. Plan Shape rectangular
0	23 Ownership Public I I	36. Changes Addition X: (Explain Altered I in #42) Moved I
Guardinates UTM  Lat S4 53N 24 W	24. Owner's Name & Address, it known David Minnick Hardin, Missouri	37. Condition good.  Exterior good.
tong	25. Open to Public? Yes 11 No XX	38. Preservation Yes Underway? No x
On National Yes II 12. Is II	Object     26. Local Contact Person or Organization Yes   X	39. Endangered? Yes II By What? No IX
Part of Estab Yes II 14. Distr	27. Other Surveys in which included	40. Visible from Yes %
HIST DIST 7 NO M POLO	11(1: 140 30 8	
Name of Established District		Public Road? No 1:  41. Distance from and Frontage on Road
Further Description of Important Farm home typical of porch engineed. Retain	Features region. Has toilet room added and side ins period plantings. Primary facade has r door center bay second stopy. Windows al	41. Distance from and Frontage on Road
Further Description of Important F Farm home typical of porch engineed. Retaitwo entryways; anothe: 2/2.	region. Has toilet room added and side ins period plantings. Primary facade has	41. Distance from and Frontage on Road
Further Description of Important F Farm home typical of porch engineed. Retaitwo entryways; anothe: 2/2.	region. Has toilet room added and side ins period plantings. Primary facade has	41. Distance from and Frontage on Road
Further Description of Important F Farm home typical of porch englosed. Retaltwo entryways; anothe: 2/2.  History and Significance	region. Has toilet room added and side ins period plantings. Primary facade has r door center bay second stoyy. Windows al	41. Distance from and Frontage on Road  Photo
Further Description of Important F Farm home typical of porch engineed. Retaltwo entryways; anothe: 2/2.  History and Significance	region. Has toilet room added and side ins period plantings. Primary facade has r door center bay second stoyy. Windows all	41. Distance from and Frontage on Road  Photo
Further Description of Important F Farm home typical of porch enclosed. Retaltwo entryways; another 2/2.  History and Significance  Description of Environment and Or Rural environment; or	region. Has toilet room added and side ins period plantings. Primary facade has r door center bay second stoyy. Windows all	Photo  Photo  Pa.  46. Prepared by Coombs
Further Description of Important F Farm home typical of porch enclosed. Retaltwo entryways; another 2/2.  History and Significance  Description of Environment and Or Rural environment; or	region. Has toilet room added and side ins period plantings. Primary facade has r door center bay second stoyy. Windows all	Photo  Photo  46. Prepared by




**FLOORPLANS** 

NOT TO SCALE



PHOTOGRAPH





FLOORPLANS

NOT TO SCALE



PHOTOGRAPH








48. Date 49 Revision Date(s) 6/80

Office of Historic Preservation, P.O. Box 176, Jefferson City, Missouri 65101

HISTORIC INVENTORY

No 49	4 Prese	James A Rimmer Estate		
County Ray	4 000	Namo(s)		
Location of Nagatives	5 Other	· ·		
		16 Thematic Calegory		28 No of Stories 1/2
was if d west of Richen south on macan	chmond to Elkhorn dam road ½ mile.	17 Date(s) or Period		29. Basement? Yes !: partial No !
52 R. 29 S. 24	Hwy N	ca. 1830 and ca. 1870	00	30. Foundation Material ashlar stone 40
City or Town II Rura C. Elkhorn Site Plan with North Art	Fishing River	vernacular; Neoclassic 19. Architect or Engineer	ache	frame . W.L.
Sile Plan with North At	TOTAL PROF	unknown  20. Contractor or Builder	pada	32. Roof Type & Material C. gable-comp. shingles
₩ W	CELLAR	unknown 21. Original Use, if apparent		33. No. of Bays Front Side  34. Wall Treatment
WELL O	PORTION	residence OLA  22 Present Use vacant		weatherboard of
S L	TOK TOK	23 Ownership		36. Changes Addition (Explain Altered
30	300	24. Owner's Name & Address, il known  James A. Rimmer Estate		37 Condition fair
Coordinates Lat Long		25 Open to	Yes ! !	Exterior fair  38. Preservation Yes Underway? No
Site Li Building Xi	Structure 1 i Object 1 i	Public?  26 Local Contact Person or Organi	No XI	Underway? No 39 Endangered? Yes By What? No
On National Yes II Register? No K	12 is it Yes 1% Eligible? No i i	27. Other Surveys in Which Include	d	neglect
Part of Estab Yes LI Hist Dist.? No Ki	14. District Yes 1% Potent'l? No I i			40. Visible from Yes Public Road? No
Name of Established	District			Frontage on Road
lining room when h flanked by two cup provide access to uttic level; board	one-room log how ouse was occupied boards with panel addition of kitch and batten door to story. Window to	se to rear of main block; d. Brick fireplace on westled doors; one has been rent to rear. Boxed in state and the left. Main block is cents are all 2/2 with lintel	emoved to ircase to also board ntral (con	Photo
land and land an	e listed in the 1 ame to Ray County	877 Atlas as owned by E. R in 1844. He was a farmer	limmer, bor and stock	n în Person County dealer.
4 Description of Environ	nment and Outbuildings			and applies to the
riginal planting est and several wrrounded by far	barns, in deterio	large oak trees. Well to rated condition, are to th	south; a h	t of the house.
5 Sources of Information On-site inspection	on			46. Prepared by Cameron
Ray County Atlas,				47. Organization RCHS & M

\*42 Cont. pilaster boards. Primary elevation has 5 bays, central entrance with transom and sidelights covered by porch of Carpenter Gothic styling (a later alteration) with spindled porch frieze and turned posts. Heavy plain frieze surrounds house; boxed cornice. Interior brick stove chimneys at each end of this facade. Attic windows are narrower than dominant window type and are 1/1 light sash: they are paired on each secondary facade gable. Interior of main block consists of central hallway with entrance door at either end; they are 4 panelled. Heavy woodwork. North and south front rooms have stove chimneys, stoves have been removed. North room has stairway to attic level, which is enclosed, like that of the rear log portion. Wooden flooring in all rooms is in fair condition. #36: addition of kitchen to rear of house and screening of side porch on the south. #39: House has been vacant for several years and although closed to the elements, it is deteriorating slowly.



FLOORPLANS

NOT TO SCALE





PHOTOGRAPH






47 Organization RCHS & M

48 Date 49 Revision Date(s) 8/79

Office of Historic Preservation, P.O. Box 176, Jefferson City, Missouri 65101

1 No 4 50	4 Pres	ent Name(s)	
County		Pettus Residence	
Ray	5 OIN	Namo(x)	
Location of Negatives			
RCHS & M			
Specific Lucation		16 Thematic Category	26 No of Stories two
l mile south of El		030	29. Basement? Yes 11
road N, then 4 mil	e on unmarked	17 Date(s) or Period	Nox
gravel road. Here	5.10	1868 and ca. 1880	30. Foundation Material
	II. Township & Vicinity	18 Style or Design	ashlar stone 90
	ning River twp.	vernacular/Queen Anne 99	31. Wall Construction
Sile Plan with North Art	OW	19. Architect or Engineer	frame, LOW
,-		unknown  20. Contractor or Builder	32. Rood Type & Maleyal Capable Mansard Wydormers as phalt shingles
		12.21	Casphalt shingles mers
		Pettus family  21. Original Use, II apparent	33. No. of Bays Front n/a Side n/a
\	Y	residence OIA	34. Wall Treatment
	1	22 Present Use	clapboarding
		residence	35. Plan Shape irregular
		23 Ownership Public !!	36. Changes Addition X
	lout	Private 1x	(Explain Allered X
		24. Owner's Name & Address,	in #42) Moved
		Glenn T. Pettuss	37 Condition
	JTM	Orrick, Mo. 64077	Interior good
Lat Sas Ts	2N 6380		Exterior good
		25 Open to Yes I i	38. Preservation Yes
Site 1 i Building 00	Structure 1 i	. Х	Underway? No .X
On National Yes II	12 Is It Yes Do	26. Local Contact Person or Organization	39 Endangered? Yes I I By What? No IX
Augister? No IX	Eligible? No 11	27. Other Surveys in Which Included	By What? No IX
Part of Estab Yes II	14. District Yes II	27. Other Sulveys in synich included	40 Markle Array
Hist Dist.? No 1x	Potent'l? No IX		40. Visible from Yes Public Road? No X
Name of Established Di	strict		41. Distance from and
			Frontage on Road
ernacular central	hall house has h	ad many additions to make it	
ashionable, ca. 18	80. Molding on	window heads. #36: Added cross	
gable of Mansard ro	of with hipped d	ormers. Enlarged windows on	
riginal house. Pr	imary entrance a	dded in projecting central hav of	Photo
louse. New porch w	ith Doric collon	ettes.	
he house began wit	h two rooms and	a pantry and was added gradually	to
ake up seven rooms	. Built of nati	ve oak and walnut from the farm.	
History and Symplicance	4- 10/0 1- D +	7 7	
omesteed 360 com	in 1000 by Dani	el Webster Pettus, the seventh so	on of Joseph Pettus who
hildren but reised	es in 1055 enen	he arrived from Ray County from V	irginia. This son had no
HITTOTICE DATE TOTOCA	a nilece who mar	ried and had one son allowed was	loft to that are order
	~ TO OO GIGINI I.	Pettus in the 1930's, so it rema	ined in the Pettus family.
Description of Environme	ent and Outhuildings		
everal outbailding	s including a lo	g barn on the farm.	
Sources of Information			
lwilda Pettus			46. Prepared by
THILLIA TOUCUS			Alwilda Pettus

On-site inspection.



FLOORPLANS

NOT TO SCALE



PHOTOGRAPH



On-Site Inspection

RCHS & M

49 Revision Dale(s)

48. Dale

8/79

Courty

Present Name(S)

#6 3 miles east of Excelsior Springs on Highway 10, then south 14 miles on Route O to a sharp right turn

If Donnerstip Hall

A STATE OF THE PARTY OF THE PAR


#43 Con't

Fibrilials ag street

so-called "test oath" prescribed by the St. Louis Baptist Convention and a division took place. The organization has remained divided, both faction retaining the same name, but attending different church buildings.

out to the second of the secon

The transfer of the control of the c



FLOORPLANS

NOT TO SCALE





48. Date

5/80


49 Revision Date(s)

Office of Historic Preservation, P.O. Box 176, Jefferson City, Missouri 65101

HISTORIC INVENTORY

No 148	4 Prese	ent Name(s)	
County		Clevenger House	
Ray	5 Other	Namo(s)	
Location of Megatives		Wickstrom House	
Specific Lucation	· · · · · · · · · · · · · · · · · · ·	16 Thematic Calegory	28 No of Stories 11/2
ite 0 6½ miles 8 0 and Route 210	rom intersection	17 Date(s) or Period	29. Basement? Yes X No I
52 R. 29 S. 33	ac oroccies	ca. 1840; 1881	30. Foundation Material ashlar stone 40
	ral, Township & Vicinity	18 Style or Design	
City or Town II Ru Lick Vic.	Fishing river	vernacular	31. Wall Construction frame WU
Site Plan with North A	irow /1	19. Architect or Engineer unknown	32. Roof Type & Material Cross gable-comp. shi
		20. Contractor or Builder	cross gable-comp. shi
		unknown	33. No. of Bays Front Side
	2/	21. Original Use, il apparent residence 0/A	34 Wall Treatment 25
/	e 7/	22 Present Use	wood shingle siding
	7/	residence	35. Plan Shape   - shape
		m 23 Ownership	rivateXX (Explain Altered)
No.	LOG PORTION	24. Owner's Name & Address,	in #42) Moved
7	12000	il known	37 Condition good
Coordinates	UTM	Clayton and Hazel Cleveng RR#1 Orrick, Missouri	Exterior good
Lat		25. Open to	Yes I i 38. Preservation Yes
Site Li	Structure 1 i	Public?	No ly Underway? No
Building (X	Object 11	26 Local Contact Person or Organiza	tion 39 Endangered? Yes By What? No
On National Yes !! Register? No 1X	12 Is II Yes XI Eligible? No I I	27. Other Surveys in Which Included	
Part of Estab Yes I I	14. District Yes I I		40. Visible from Yes Public Road? No
Hist Dist.? No IX		4	41. Distance from and
Name of Established	District		Frontage on Road
2. Further Description	of important Features	on the interior and exterior	r, but
interal trun knows	and of log: onial	inal remodelling occured in	1001,
on the house we	a converted into	i Jueen anne style nouseof L	simple, Photo
ton namadalling	added nicture we	idous, knotty pine panetting	on Log
ortion, siding a	o exterior obscur	ing original details. Bedro	
			/
3 History and Signific	ance	e structure by Jacob and Joh	anna Wickstrom, who came to
0 1 1 1	7. 10 days 110 1007 TI	ho bouko ik ounged du kuvan u	MININGS ON A WILL TEMPORED TO THE
	in mach coundition	whom he and his with moved	I THE LIE ITSO S.
. Gross is liste	ed as the owner of	the property and house in t	the Ray County Atlas of 1877.
4 Description of Envir	ronment and Outbuildings		
n a Parae Pandsi	aned lat. surroun	ded by farmland. A modern s	plit rail fence borders the
roperty. Some	old oak trees, pos	sibly of original planting.	
			46 Prepared by
15 Sources of Informat Ray County Atlas			46. Prepared by Jackie Hampton

On-site inspection.



FLOORPLANS

NOT TO SCALE




PHOTOGRAPH



MISSOURI OFFICE OF HISTORIC PRESERVATION - RA AS 002-091 ARCHITECTURAL/HISTORIC INVENTORY SURVEY FORM 4. PRESENT LOCAL NAME(S) OR DESIGNATION(S) L NO. Boyd Clevenger Home. Ray 5. OTHER NAME (S) 3. LOCATION OF **RCHS** NEGATIVES 6. SPECIFIC LEGAL LOCATION TOWNSHIP 521 RANGE 29 SECTION 23 16. THEMATIC CATEGORY 28. NO. OF STORIES YES (XX 29. BASEMENT ? NO ( From Richmond take Hywy 10 to 1/4 mi IT. DATE(S) OR PERIOD 30. FOUNDATION MATERIAL ca. 1890 t of Elkhorn: south on gravel road ashlar stone/concrete IS. STYLE OR DESIGN Trame construction Fishing River twp. VERNACULAR; Queen Anne/Neoclassid Elkhorn vic. 19. ARCHITECT OR ENGINEER 8. DESCRIPTION OF LOCATION 32 ROOF TYPE AND MATERIAL gable-comp. shingles unknown 20. CONTRACTOR OR BUILDER 33. NO. OF BAYS John Walker Allen 4. PRESENT LOCAL NAME(S) n/a SIDE FRONT n/a Done 21. ORIGINAL USE, IF APPARENT 34. WALL TREATMENT FU residence wood shingles 22. PRESENT USE 35. PLAN SHAPE rectangula residence CHANGES (EXPLAIN IN ADDITION ( 23. OWNERSHIP PUBLIC! PRIVATE (X ) ALTERED (X NO. 42) MOVED ( ) 24. OWNER'S NAME AND ADDRESS IF KNOWN 37. CONDITION dood INTERIOR\_ Boyd Clevenger COORDINATES dood EXTERIOR\_ OR DESIGNATION(S) Elkhorn, Missouri LAT LONG 25. OPEN TO PUBLIC? YES ( 38. PRESERVATION UNDERWAY? YES ( NO ( NO (X STRUCTURE ( 10. SITE ( OBJECT ( YES ( BUILDING ( ORGANIZATION 39. ENDANGERED? 26. LOCAL CONTACT PERSON OR BY WHAT ? NO (X ) NATIONAL GISTER ? YES ( IS IT YES (X) NO NO ( 27. OTHER SURVEYS IN WHICH INCLUDED 40. VISIBLE FROM PUBLIC ROAD ? YES ( 14. DISTRICT YES ( POTENTIAL? NO ( X 13. PART OF ESTAB. HIST, DISTRICT? YES ( NO ( X) NO ( 41. DISTANCE FROM AND FRONTAGE ON ROAD 15. NAME OF ESTABLISHED DISTRICT 42. FURTHER DESCRIPTION OF IMPORTANT FEATURES PHOTO Queen Anne massing of vernacular house has led to bay window on east MUST facade, polygonal projecting bay on assymetrical primary elevation.All NAME(S) doors and windows have trabeated heads. Windows one-over-one doublehund RF High pitched gable on primary facade has central window. Large dormers PROVIDED on east facade emphasizes assymmetry of house. Addition of extra bay on west facade with doorway cut on primary facade. Also later addition 43. HISTORY AND SIGNIFICANCE 6. TOWNSHIP DESCRIPTION OF ENVIRONMENT AND **DUTBUILDINGS** Ru. al Environment. 46. PREPARED BY 45. SOURCES OF INFORMATION Pauline Brown 47. ORGANIZATION RCHS & M Boyd Clevenger On=site inspection. 48. DATE 49. REVISION DATE(S) 8/80

#6 Cont. to unmarked gravel road south, then 1/8 mile to east turn, then 1/4 mile.





FLOORPLANS


NOT TO SCALE







LNO 114 4M	4 Present Name(s)	
2 County	O'Dell Church	
Ray	5 Other Namo(s)	
3 Location of Negatives		
RCHS & M		
6 Specific Lucation Hywy 10 west to Wikhorn	then then mi	20 No of Stories one
west to unmarked gravel		29. Basement? Yes I
1 mi. to left tun, then		No 1X
7 City or Town If Rural Tow		30. Foundation Material ashlar stone
	River two. vernacular	ashlar stone 31. Wall Construction
8 Sile Plan with North Arrow	19. Architect or Engineer	frame . WW
CR	unknown	32. Roof Type & Material
5 23 TSON R 390	20. Contractor or Builder	gable-tin 64
	21. Original Use, if apparent	33. No. of Bays Front 2 Side 3
	church Old	34. Wall Treatment
	22 Present Use	clapboard
	vacant	35. Plan Shaperectangular
	23 Ownership	Public ID : 36. Changes Addition .X
	•	Private I   (Explain Altered i
	24. Owner's Name & Address.	in #42) Moved i
9 Coordinates UTM	Community of O'Dell	37 Condition good
t at	Ray County, Mo.	Exterior good
Long	25 Open to	Yes 04 38. Preservation Yes
Site 11	Structure 1: Public?	No 11 Underway? No .X
Building K	Object 11 26. Local Contact Person or Organiza	
11 On National Yes I 1 12 Is Register? No K	El a Adams	By What? No K
	District Yes i	
14	Potent'l? No Ki	40. Visible from Yes X Public Road? No
15 Namu of Established District		41. Distance from and
		Frontage on Road
42 Further Description of Imports	ant Features	
Vernacular church with	high gable on primary facade. Two iden	ntical
entrances on primary fa	acade. Singlelear doors with Neoclassic	cal
	e on each secondary facade, have the sar four-over-four light doublehung sashes	
	at the center of the roof ridgeline. The	
	Inal benches and stove. #36: The church	
	ts construction. Electricity has been	
In February of 1901, a	neighbor of the community died and his	grave dug by the people of the
small chumch budlates of	and there was noplace to get warm so	the people decided to build a
maintenance of the chur	AND CAUCU LINE CONTROL IN TURK CONTROL D.	e left a sum of money for the
44 Description of Environment an	nd Outbuildings	
	ands the church building.	
	and the church building.	
45 Sources of Information		46. Prepared by
Odell family	•	Ogg. and Pettus
McAfee family		47 Organization
On-site inspection.		RCHS & M
		48 Date 49 Revision Date(s)
		8/79




FLOORPLANS NOT TO SCALE



PHOTOGRAPH



MISSOURI OFFICE OF ARCHITECTURAL/HISTORIC INVENT		RATION RATAS 002-093	
1	immer Residence  NAME(S)		I. NO.
6. SPECIFIC LEGAL LOCATION TOWNSHIP 52 RANGE 29 SECTION 22 IF CITY OR TOWN, STREET ADDRESS  TO Elkhorn, I mintake dirt road S. The city of town if RURAL, VICINITY Vic. Elkhorn; Fishing River Twp.  8. DESCRIPTION OF LOCATION C.C.  9. COORDINATES LAT LONG  10. SITE() STRUCTURE() SISTER? NO(X) ELIGIBLE? NO(X)  13. PART OF ESTAB. YES(X) MIST. DISTRICT? NO(X)  15. NAME OF ESTABLISHED DISTRICT  42. FURTHER DESCRIPTION OF IMPORTANT FEATURES Late I-house has unusual window detail; lintels supported by brackets. 3 wall of projecting boxed cornice and frieze swid detail has been lost due to unfortunate	dormers dominate primary facade; round house. Some facade	(EXPLAIN IN NO. 42)  ALTERED (X)  MOVED ( )  37. CONDITION INTERIOR GOOD  EXTERIOR GOOD  38. PRESERVATION YES ( ) X NO (X )  39. ENDANGERED? YES ( ) BY WHAT? YES ( ) NO (X )  40. VISIBLE FROM YES (X ) PUBLIC ROAD? NO ( )  41. DISTANCE FROM AND FRONTAGE ON ROAD  PHOTO MUST  BE	2. COUNTY 4. PRESENT LOCAL NAME(S) OR DESIGNATION(S) 5. OTHER NAME(S)
43. HISTORY AND SIGNIFICANCE  In 1877 the land is listed as owned by the owner in 1897, with no house at this indicated. Reuben Roe is the son of The to Missouri with his mother and sisters 300. He married Jennie Odell, and they 1865 when he enlisted in the Union Army the war, he married Rhoda E Craven and acres. which increased to 140.  44. DESCRIPTION OF ENVIRONMENT AND OUTBUILDING RYPAL area.	s site. He also owns it in 1914 omas and Jennie Odell Roe, born and entered 160 acres of land whad 7 children. Reuben lived what fought at Mobile, Spanish Fithey had 6 children. Afterwards	, when the house is 1843. His father came which soon increased to with his parents until ort and Franklin. After	6. TOWNSH
45. Sources of Information On-site inspection. Present owner Ray County Atlases, 1877; 1897; 1914 Ray County History, 1881		46. PREPARED BY Pauline Brown 47. ORGANIZATION RCHS & M 48. DATE 49. REVISION DATE(S) 6/80	a c c c c c



FLOORPLANS

NOT TO SCALE



PHOTOGRAPH




Uffice of Historic	Preservation.	P.U. Box	176.	Jefferson	City.	Missouri	65
HISTORIC	INVENT	ORY					

1 No 43	Fredricksburg Monument Act	
	Other Namo(s)	
6 Specific Location 1/8 mile east of Excelsior spings to right turn; left for ½ mile to crossroads.  7 City or Town If Rural, Township & Vic Vic, Excelsior Springs; Fishir H Sile Plan with North Arrow River  Golf Course marker  9 Coordinates Lat	1864  Innity  18 Style or Design  n/a  twp. 19. Architect or Engineer  n/a  20. Contractor or Builder  n/a  21. Original Use, if apparent  wooded pasture	28. No. of Stories n/a  29. Basement? Yes   1   n/a   No   1    30. Foundation Material   n/a    31. Wall Construction   n/a    32. Roof Type & Material   n/a    33. No. of Bays   Front   n/a   Side   n/a    34. Wall Treatment   n/a    35. Plan Shape   n/a    36. Changes   Addition   Altered   in                      in                                37. Condition                          Exterior                                      Exterior
Register? No IX Eligible? N	26. Local Contact Person or Organization  S   1	38. Preservation Underway?  39. Endangered? Yes 11 By What? No 1X  40. Visible from Yes 'X Public Road? No 1:  41. Distance from and Frontage on Road
day the area supposedly en in that area. Just south of the fighting ranged over an area for the course. In one corner near the marker with a bronze plaque an soldiers of the Civil War who fredricksburg, August 12, 1864.  day History and Significance The Battle of Fredericksburg to between Union soldiers and southrough the area supposedly en in that area. Just south of the Fighting ranged over an area for the course of	ericksburg is now a landscaped golf e intersection of two dirt roads is a d the inscription "In memory of the gave their lives in the Battle of ."  ook place on this site on August 12, 18 thern sympathisers. A small troop of route to Albany, north of Orrick, to he town of Fredericksburg the Union troop the edge of the town to two miles of	soldiers was passing join other Union forces oop was ambushed. southwest of it (cont.)

Sources of Information 46. Prepared by On-site inspection. Cameron Ray County History, 1973. 49 Revision Date(s) 4 Cont.

mostly unfenced woodland. Possibly ll men were killed, the number is uncertain. These men of Fredericksburg area include: George O'Dell, Philip Siegel, John and Smith Hutchings and Captain Colley, who was the officer in command of the Union troops. J.C. Isley according to a newspaper clipping, owner of the Fredericksburg Store (demolished) was hired by the citizens to gather the bodies and bury them in nearby Pisgah Cemetery in an unmarked grave. The town of Fredericksburg has entirely disappeared.

	80 10	resent Name(s)	
Ray		Wollard Residence	
	5 0	ther Namo(s)	
3 tocation of Negatives RCHS	& M	Heavner Residence	
3 miles north of		16 Thematic Category	28 No of Stories 22
A to unmarked gra		030	29. Basement? Yes 11
road: west & mile	Hug A	17 Datu(s) or Period	No X
road; west ½ mile		1905	30. Foundation Material
vic. Hardin; Gra	ral, Township & Vicinit	Neoclassic	brick 30
8 Sile Plan with North A		19. Architect or Engineer	131. Wall Construction frame
		unknown 33 35	32. Roof Type & Material
	_ ′\	George Tinsley	gable-comp. shingles
	Aò.	George Tinsley  21. Original Use, If apparent	33. No. of Bays Front n/a Side n/a
H	4	residence Ola	34. Wall Treatment
		22 Present Use	weatherboard
		residence	35. Plan Shape square
		23 Ownership Public I Private X	36. Changes Addition
	<b>\( \)</b>	24. Owner's Name & Address.	(Explain Altered is in 42) Moved in
		if known	37 Condition
9 Coordinates	UTM	Hester Wollard Hardin, Missouri 64035	Interior good
Long 5	35 T53N 26W	25 6	Exterior gppd
Site: 11	Structure 1 i	14811	38. Preservation Yes Underway? No X
Building X	Object 1 I	26. Local Contact Person or Organization	39 Endangered? Yes II
Register? No ix	12 is it Yes 12		By What? No IX
13 Part of Estab Yes II	Eligible? No i i	27. Other Surveys in Which included	
Hist Dist.? No X	Potent'l? No 1)		40. Visible from Yes X Public Road? No ::
15 Name of Established D	District		41. Distance from and
			Frontage on Road
42 Further Description of	Important Features		
Neoclassic house	features pedimen	t front gable with triple window	
	e, each window w	ith 6 lights. Gable sheathed in	
in center of gabl	c Domaindon of	house weatherhearding Council	
fishscale shingle		house weatherboarding. Corner	- Photo
fishscale shingle board pilasters.	Boxed cornice a	and frieze. Porch across primary	Photo
fishscale shingle board pilasters. facade also has b capitals. Interi	Boxed cornice a oxed cornice and or displays stai	Ind frieze. Porch across primary I frieze and posts with Tuscan Ined glass window in entrance hall,	Photo
fishscale shingle board pilasters. facade also has b capitals. Interi	Boxed cornice a boxed cornice and or displays stai or additions of	and frieze. Porch across primary I frieze and posts with Tuscan	Photo
fishscale shingle board pilasters. facade also has b capitals. Interial fireplace. #36	Boxed cornice and or displays stails: no additions of	Ind frieze. Porch across primary of frieze and posts with Tuscan ned glass window in entrance hall, or alterations to the structure.	
fishscale shingle board pilasters. facade also has b capitals. Interial fireplace. #36  History and Segmilicance 160 acre farm was	Boxed cornice and or displays states: no additions of the boxes of the	Ind frieze. Porch across primary of frieze and posts with Tuscan ned glass window in entrance hall, or alterations to the structure.  William and Flizabeth Heyner in 18	33 A sod house was
fishscale shingle board pilasters. facade also has b capitals. Interial fireplace. #36  43 History and Symmicance 160 acre farm was built here in 183	Boxed cornice and or displays states: no additions of the states and the states are states as a second seco	Ind frieze. Porch across primary of frieze and posts with Tuscan ned glass window in entrance hall, or alterations to the structure.  William and Elizabeth Hevner in 183 house. Later a frame house was contact the structure.	33. A sod house was
fishscale shingle board pilasters. facade also has b capitals. Interial fireplace. #36  43 History and Symmicance 160 acre farm was built here in 183	Boxed cornice and oxed cornice and or displays states: no additions of the states and the states are also on the states in 19	Ind frieze. Porch across primary of frieze and posts with Tuscan ned glass window in entrance hall, or alterations to the structure.  William and Flizabeth Heyner in 18	33. A sod house was
fishscale shingle board pilasters. facade also has b capitals. Interil fireplace. #36  43 History and Significance 160 acre farm was built here in 183 house was built to the outbuildings	Boxed cornice and oxed cornice and or displays states: no additions of the state and t	Ind frieze. Porch across primary of frieze and posts with Tuscan ned glass window in entrance hall, or alterations to the structure.  William and Elizabeth Hevner in 183 house. Later a frame house was contact the structure.	33. A sod house was
fishscale shingle board pilasters. facade also has b capitals. Interil fireplace. #36  43 History and Significance 160 acre farm was built here in 183 house was built to the outbuildings	Boxed cornice and oxed cornice and or displays states: no additions of the state and t	Ind frieze. Porch across primary of frieze and posts with Tuscan ned glass window in entrance hall, or alterations to the structure.  William and Elizabeth Hevner in 183 house. Later a frame house was contact the structure.	33. A sod house was
fishscale shingle board pilasters. facade also has be capitals. Interial fireplace. #36  43 History and Significance 160 acre farm was built here in 183 house was built to the outbuildings	Boxed cornice and oxed cornice and or displays states: no additions of the state of	Ind frieze. Porch across primary of frieze and posts with Tuscan ned glass window in entrance hall, or alterations to the structure.  William and Elizabeth Hevner in 183 house. Later a frame house was composed. It was threatened by antornado	33. A sod house was
in center of gable fishscale shingle board pilasters. facade also has be capitals. Interial fireplace. #36  43 History and Significance 160 acre farm was built here in 183 house was built to the outbuildings  44 Description of Environment on large farm, us	Boxed cornice and oxed cornice and or displays states: no additions of the state of	Ind frieze. Porch across primary of frieze and posts with Tuscan ned glass window in entrance hall, or alterations to the structure.  William and Elizabeth Hevner in 183 house. Later a frame house was composed. It was threatened by antornado	33. A sod house was
in center of gable fishscale shingle board pilasters. facade also has be capitals. Interial fireplace. #36  43 History and Significance 160 acre farm was built here in 183 house was built to the outbuildings  44 Description of Environment on large farm, us	Boxed cornice and oxed cornice and or displays states: no additions of the state of	Ind frieze. Porch across primary of frieze and posts with Tuscan ned glass window in entrance hall, or alterations to the structure.  William and Elizabeth Hevner in 183 house. Later a frame house was composed. It was threatened by antornado	33. A sod house was onstructed. The present of in 1977 but only
fishscale shingle board pilasters. facade also has be capitals. Interil fireplace. #36  43 History and Significant 160 acre farm was built here in 183 house was built to the outbuildings  44 Description of Environment on large farm, us	Boxed cornice and oxed cornice and or displays states: no additions of the state of	Ind frieze. Porch across primary of frieze and posts with Tuscan ned glass window in entrance hall, or alterations to the structure.  William and Elizabeth Hevner in 183 house. Later a frame house was composed. It was threatened by antornado	33. A sod house was onstructed. The present of in 1977 but only
fishscale shingle board pilasters. facade also has be capitals. Interil fireplace. #36  43 History and Significance 160 acre farm was built here in 183 house was built to the outbuildings  44 Description of Environment on large farm, us  45 Sources of Information  Hester (Hevner) W	Boxed cornice and oxed cornice and or displays states in additions of the state of	Ind frieze. Porch across primary of frieze and posts with Tuscan ned glass window in entrance hall, or alterations to the structure.  William and Elizabeth Hevner in 183 house. Later a frame house was composed. It was threatened by antornado	33. A sod house was onstructed. The present of in 1977 but only  46. Prepared by Clara Allison
fishscale shingle board pilasters. facade also has be capitals. Interil fireplace. #36  43 History and Significant 160 acre farm was built here in 183 house was built to the outbuildings  44 Description of Environment on large farm, us	Boxed cornice and oxed cornice and or displays states in additions of the state of	Ind frieze. Porch across primary of frieze and posts with Tuscan ned glass window in entrance hall, or alterations to the structure.  William and Elizabeth Hevner in 183 house. Later a frame house was composed. It was threatened by antornado	33. A sod house was onstructed. The present of in 1977 but only



FLOORPLANS

NOT TO SCALE



PHOTOGRAPH




48 Date 5/79

49 Revision Date(s)

1 Nu	sent Name(s)	
701		
Ray	Dooley Residence	
3 Location of Meantings	er Namo(s)	
3 Location of Negatives & M	Pugh Residence	
Route A north of Hardin to inter-	16 Thematic Category	28 No of Stories one
section of Route K; west 3/4 mile	030	29. Basement? Yes !!
to unmarked road; southil mile.	17 Date(s) or Period	Noxix
	18 Style or Design	30. Foundation Material
vic. Russellville; Grape grove twp	Queen Anne cottage 45	ashlar stone 40
8 Sile Plan with North Arrow	19. Architect or Engineer pube	frame . Wu
	unknown	32. Roof Type & Material GR
	20. Contractor or Builder	gable=comp. shingle
/h	21. Original Use, If apparent	33. No. of Bays Front n/a Side n/a
	residence O.A	34. Wall Treatment
	22 Present Use residence	weatherboard >1
		35. Plan Shape Trregular
2.00	23 Ownership Public I Private KI	36. Changes Addition
SM T530 R260	24. Owner's Name & Address,	in #42) Moved
# C	if known	37 Condition good
9 Guardinates UTM Lat	J.C. and Freta Dolley Hardin, Missouri	Interior GOOD GOOD
Long	25. Open to Yes I i	
Site 1 Structure 1 : Building X1 Object 1 :	Public? No XI	Underway? No X
11 On National Yes I 1 12 Is II Yes IX	26 Local Contact Person or Organization	39 Endangered? Yes II By What? No X
Register? No X. Eligible? No 11	27. Other Surveys in Which Included	by what? No ?-
Hist Dist.? No ki Potent'i? No ki		40. Visible from Yes X
15 Namu of Established District		Public Road? No i i
The state of the s		41. Distance from and Frontage on Road
		7 1 2 2 2
42. Further Description of Important Features  Oueen Anne cottage features polygon	nal projecting bay on primary face	
Queen Anne cottage features polygor covered with gable roof with blind	lunette Ray's facets highlighted	e.
with pilasters. Primary entrance (	opens on lateral porch with turned	
posts. Porch roof has slight bell.	-cast profile and is surmounted	Photo
by turret with cornerpilasters and	lozenge-shaped decoration The	
turret is covered by a pyramidal re	oof. Similar pilasters ornament	
all facades. Interior displays ent	trance door with oval of glass(cont	
Jacob and Alice Pugh built the hous	se in 1899. J.C. and Freta Dooley	bought it inll963.
	1, 1	
44 Description of Environment and Outbuildings		
An older house (see #24B) still sta	ands on the preparty. It to world	ion obours C
outbuildings are in good condition.	inds on the property. It is used t	or storage. Several
45 Jources of Information		
J.C. and Freta Dooley.		46. Prepared by
On-site inspection.		Clara Allison
on side inspection.		47 Organization

42 Cont. An original large colored glass window. #36: Present owners lowered ceilings about 1963, added bathroom and water in 1969.



FLOORPLANS

NOT TO SCALE




PHOTOGRAPH



48 Pate 8/80 49 Revision Date(s)

9 20	4 Pre	sent Name(s)	
County		Wesley Chapel (Methodist Churc	h)
Ray	5 OII	her Namo(s)	
Location of Negatives			
RCHS & M			
Specific Lucation  4 miles north on C	ounty Pouto MA	16 Thematic Category	28 No of Stories one
after intersection		17 Date(s) or Period	29. Basement? Yes
Sec. 22, t. 54, R		1898	No
	al. Township & Vicinity		30. Foundation Material ashlar stone
ic. Regal Grape	Grove twp.	Romanesque	31. Wall Construction
Site Plan with North &	C) C You	19. Architect or Engineer	frame WW
<b>4</b>	~ w	unknown	32. Roof Type & Material
2		20. Contractor or Builder	gable-comp. shingles
4	A.	Ernest Misel/Haley Tinsley 21. Original Use, If apparent	33. No. of Bays
*	7	church OUF	Front 1 Side 4
6	3 (4)	22 Present Use	clapboard
8	T	church	35. Plan Shape rectangula
	_	23 Ownership Public I !	36. Changes Addition
		Private IX	(Explain Altered
		24 Owner's Name & Address,	in #42) Moved
Coordinates	UTM	United Methodist Church	37 Condition good
Lat	<b>3</b> ·		Exterior good
Long	<b>⊘</b> .	25 Open to Yes it	38. Preservation Yes
Site   1 Building (X	Structure 1 :	Public? restricted No 11	Underway? No
On National Yes !! Rugister? 'No IX	12 Is It Yes Ki Eligible? No 11	26 Local Contact Person or Organization	39 Endangered? Yes By What? No
Part of Estab Yes !   Hist Dist.? No   X	14. District Yes I I	27. Other Surveys in Which Included	40. Visible from Yes
Name of Established De	strict		Public Road? No
			41. Distance from and Frontage on Road
with exposed joist	ends cut on arc	, completely unaltered. Simple eav -unuaual. Round bead windows Original etched glass windows.	е
Fillined in truncat	ed point linter.	original etched glass windows.	Photo
History and Significance			1
For small(now defu	nct) town of Reg	al. One acre aof land was donated	by Henry Penny for
the site. Ernest	Misel supervised	the building of the foundation.	The carpenter was
daley Tinsley. Se	ats were brought	across the Missouri River from Le	xington on the frozen
river; Dedicated	1099 by Reverend	Joe Bone, Sr The first pastor	was Joe Bone, Jr.
Description of Environme	ent and Outhuildings		
	om and odiodnaings		
Country setting.			
Sources of Information			140.0
Ray County History	, 1973.		46. Prepared by
On-site inspection			Pease 47 Organization




FLOORPLANS NOT TO SCALE



PHOTOGRAPH



No 71	4 Pres	ent Name(s)	
County	01	d Dooley House	
Ray	5 Olhe	er Namo(s)	
Location of Negatives RCHS			
		16 Thematic Category	128 No of Stories 1-1/2-
Specific Lucation toute A north from Har	din to K;	030	29. Basement? Yes I
est 1 mile to unmarke	d gravel rd.	17 Date(s) or Period	No I
outh 3/4 miles. T53R2	6817	ca. 1850	30. Foundation Material no foundation
City or Town II Rural, To	waship & Vicinity	18 Style or Design	31. Wall Construction
ussellville vic. Gra	pe Grove twp	vernacular/Neoclassical 19. Architect or Engineer	frame , Wu
Site Plan with North Arrow	()	unknown	32. Roof Type & Material &
WWW.	3	20. Contractor or Builder	gable asphalt shingle
LEY MEN	(o) W	unknown	33. No. of Bays Side 1
PACE		21. Original Use, if apparent residence OIA	34. Wall Treatment
	W \ 3 x	22 Present Use	weatherboard 3/
	VIIA	residence	35. Plan Shape rectangul
		23 Ownership Public I	£11
		Private XI	(Explain Moved
		24. Owner's Name & Address, if known	37 Condition
		Jesse C. Dooley	Interior poor
Coordinates UTM			Exterior poor
Long		25. Open to Yes I	
Site 11	Structure 1 i	, come:	39 Endangered? Yes
Building XI	Object 1 1	26 Local Contact Person or Organization	By What? No
1 On National Yes   12 Register? No 1X	Is It Yes 1x Eligible? No 11		neglect
	. District Yes II		40. Visible from Yes Public Road? No
Hist Dist.? No XI	Potent'l? No IX		Public Road? No 41. Distance from and
5 Name of Established Distric	ct		Frontage on Road
	•		
Applied corner boards:	ernacular for ; boxed corni	m has added Neoclassic details. ce and frieze. Shed garage addit m its original position.	ion
		· · · · · · · · · · · · · · · · · · ·	
43 History and Significance		<u> </u>	
		·	
43 History and Significance			
43 History and Significance  44 Description of Environment			
43 History and Significance  44 Description of Environment			
43 History and Significance  44 Description of Environment			
43 History and Significance			46. Prepared by
43 History and Significance  44 Description of Environment On farm with house of			Cameron
43 History and Significance  44 Description of Environment On farm with house of			Cameron  47. Organization
43 History and Significance  44 Description of Environment  On farm with house of  45 Sources of Information			Cameron



FLOORPLANS


NOT TO SCALE



PHOTOGRAPH



20 21		Sent Name(s)	
County		A. Bisbee Residence	
Ray	5 011	ner Namo(s)	
) Location ACHSURY		Rebinson Residence; Bush Reside	nce
Specific Lucation 12 miles north	of Hamilton	16 Thematic Category	28 No of Stories two
12 miles south		650	29. Basement? Yes
Hwy A. Renal V		17 Datu(s) or Period	No
City or Town II Au	ral, Township & Vicinity	ca. 1860 18 Style or Design	30. Foundation Material
vic. Hardin	Grape Greve twp.	transitional \$2 09	ashlar stone 31. Wall Construction
Sile Plan with North A	MOW BARN	19. Architect or Engineer OLA	frame
1		unknewn 30	32. Roof Type & Material
1	- /	tra lea aven	gable/comp. shingles 33. No. of Bays
1//	0	21. Original Use, if apparent	Front 5 Side 2
A //G IT	T-3 (1)	residence OIA	34. Wall Treatment
	<b>A</b>	22 Present Use residence	clapboard
41	<b>–</b>	23 Ownership Public   1	35. Plan Shape rectangula
~		Privatex	36. Changes Addition . (Explain Altered
(3)	meet	24. Owner's Name & Address,	in #42) Moved
Coordinates	UTM	A. Bisbee	37 Condition good
Lat C =	28 T54N 26W	Hardin, Missouri	
Lung		25. Open to Yes I I	38. Preservation Yes
Site () Building Xi	Structure 1 i	Public? No 80	Underway? No
On National Yes !!	12 is ii Yes XI	26 Local Contact Person or Organization	39 Endangered? Yes
Register? No to	Eligible? No 11	27. Other Surveys in Which included	By What? No I
Part of Estab Yes I I Hist Dist.? No 80	14. District Yes i	The state of the s	40. Visible from Yes X
Name of Established C	Potent'l? No XI		Public Road? No
Name of Established C	ristrict		41. Distance from and Frontage on Road
	Important Features		
Vernacular I-ho	was with Necologe	ic styling and Italianata today	
Vernacular I-ho Pilaster corner of doors and will cornice, two st railing, truned "Stick Style".	buse with Necclass boards, boxed condows. Two intercory portico of proposts and bracker these are underly	ic styling and Italianate trimming rnice and frieze, molded lintels ior brick chimneys. Bracketed imary facade has jigsawn frieze, ts. Upper gable ends decorated in ledly later improvments. House	Photo
of doors and will cornice, two st railing, truned "Stick Style".	buse with Neoclass boards, boxed condows. Two intercory portico of proposts and bracke These are undoubitail all suggest	ior brick chimneys. Bracketed imary facade has jigsawn frieze,	
Vernacular I-ho Pilaster corner of doors and wi cornice, two st railing, truned "Stick Style". ell form and de	buse with Neoclass boards, boxed condows. Two intercory portico of proposts and bracke These are undoubitail all suggest	ior brick chimneys. Bracketed imary facade has jigsawn frieze, ts. Upper gable ends decorated in	
Vernacular I-ho Pilaster corner of doors and wi cornice, two st railing, truned "Stick Style". ell form and de History and Significance	buse with Neoclass boards, boxed coundows. Two intercory portico of proposts and bracker These are undoubtail all suggest	ior brick chimneys. Bracketed imary facade has jigsawn frieze, ts. Upper gable ends decorated in	
Vernacular I-ho Pilaster corner of doors and wi cornice, two st railing, truned "Stick Style". ell form and de  History and Significance	boards, boxed co condows. Two inter- cory portico of pro- posts and bracke. These are undouble tail all suggest	rnice and frieze, molded lintels ior brick chimneys. Bracketed imary facade has jigsawn frieze, ts. Upper gable ends decorated in ledly later improvments. House pre-Civil War construction.	Photo
Vernacular I-ho Pilaster corner of doors and wi cornice, two st railing, truned "Stick Style". ell form and de History and Significance  Description of Environm	boards, boxed co condows. Two inter- cory portico of pro- posts and bracke. These are undouble tail all suggest	ior brick chimneys. Bracketed imary facade has jigsawn frieze, ts. Upper gable ends decorated in	Photo
Vernacular I-ho Pilaster corner of doors and wi cornice, two st railing, truned "Stick Style". ell form and de History and Significance  Description of Environm Rural area, orig	bounds, boxed condows. Two intercory portico of proposts and bracker These are undoubitail all suggest	rnice and frieze, molded lintels ior brick chimneys. Bracketed imary facade has jigsawn frieze, ts. Upper gable ends decorated in ledly later improvments. House pre-Civil War construction.	Photo Photo , remain.
Vernacular I-ho Pilaster corner of doors and wi cornice, two st railing, truned "Stick Style". ell form and de History and Significance  Description of Environm Rural area, orig	bounds, boxed condows. Two intercory portico of proposts and bracker These are undoubitail all suggest	rnice and frieze, molded lintels ior brick chimneys. Bracketed imary facade has jigsawn frieze, ts. Upper gable ends decorated in ledly later improvments. House pre-Civil War construction.	Photo  Photo  Photo  A Prepared by
Vernacular I-ho Pilaster corner of doors and wi cornice, two st railing, truned "Stick Style". ell form and de History and Significance  Description of Environm Rural area, orig	bounds, boxed condows. Two intercory portico of proposts and bracker These are undoubitail all suggest	rnice and frieze, molded lintels ior brick chimneys. Bracketed imary facade has jigsawn frieze, ts. Upper gable ends decorated in ledly later improvments. House pre-Civil War construction.	Photo  Photo  Femain.  46 Prepared by  Jim Pease  47 Organization
Vernacular I-ho Pilaster corner of doors and wi cornice, two st railing, truned "Stick Style". ell form and de History and Significance  Description of Environm Rural area, orig	bounds, boxed condows. Two intercory portico of proposts and bracker These are undoubitail all suggest	rnice and frieze, molded lintels ior brick chimneys. Bracketed imary facade has jigsawn frieze, ts. Upper gable ends decorated in ledly later improvments. House pre-Civil War construction.	Photo  Photo  Photo  A Prepared by



FLOORPLANS

NOT TO SCALE






48. Date 9/79

49 Revision Date(s)


1 Nii 22 23	4 Pres	Kavanaugh Residence	
Ray  Ray  RCHS & M	5 Othe	Pope (1857-1932)	
6 Specific Location Route A north from	Hardin 7½	16. Thematic Category	28. No. of Stories two 29. Basement? Yes ! 1 to
miles.	13 26 W	17 Date(s) or Period 1875	No K
City or Town II Rural, Tow vic. Hardin Grape	onship & Vicinity Grove twp.	18 Style or Design vernacular	30. Foundation Material ashlar stone 40
Sile Plan with North Arrow	11	19. Architect or Engineer	frame WW  32. Roof Type & Material 16
	)	20. Contractor or Builder A. Pope	gable/asphalt shingles  33. No. of Bays
	$   \Phi  $	21. Original Use, if apparent farm residence	Front 3 Side 2
		22 Present Use farm residence	weatherboard. 35. Plan Shapeshape
	~	23 Ownership Public !! Private lyl	36. Changes Addition X: (Explain Altered X:
Guardinates UTM	10	24. Owner's Name & Address, if known Mr. & Mrs. Rea Kavanaugh RR I, Richmond, Missouri	37. Condition excellent  Exterior excellent
) Site ! i	Structure 1 i	25. Open to Yes 1 Public? No IX	38. Preservation Yes Underway? No X
Building iX	Object I i	26. Local Contact Person or Organization	39. Endangered? Yes II No IX
Part of Estab Yes II 14.	District Yes I Potent'I? No 00	27. Other Surveys in Which Included	40. Visible from Yes 'X Public Road? No 1:  41. Distance from and Frontage on Road
entryway. Heavy of by carved wooden in remains. El of Ho Interior has 6 roand back stairs:	assic fenestr cornice featu brackets. On ouse has an i oms and two la there was no	ration details. Single leaf cantral ares plain frieze and is supported by loriginal interior end chimney attributed by the story of the el. A door was cut the story of the el. A door was cut the story of the el. A door was cut the story of the el.	Photo
a log cabin until here until here de	1875 when thath in 1932.	from Kentucky in 1857 and settled ley built the present hous. After he One of their children was the mother the third generation on the land and	is death, Susan lived er of Rea, A.B. and Virgil
Description of Environment ar The Pope Kavanaug 10 barns and a co	h residence s	sits back from the road on a large : oot cellar. Original Plantings.	farm, surrounded by
Sources of Information Rea Kavanaugh			46. Prepared by
On-site inspectio	n.		47. Organization RCHS & M



NOT TO SCALE **FLOORPLANS** 







FLOORPLANS


NOT TO SCALE



PHOTOGRAPH



NO.	95	4. PRESENT LOCAL NAME(S) OR DESIG	GNATION(S)
COUNTY	Ray	Carpenter Property	
LOCATION		5. OTHER NAME(S)	
LOCATION NEGATIVES			The state of the s
. SPECIFIC LI	EGAL LOCATION 26 SE	CTION 35 G. THEMATIC CATEGORY	28. NO. OF STORIES TWO 2-
IF CITY OR	TOWN, STREET ADDRES		partial NO(
CITY OR TO	Q .	ca. 1897	ashlar stone 40
vic. Roc	kingham; grape gr	neociassicai	aframo 1.11.
. DESCRIPTI	ON OF LOCATION	19. ARCHITECT OR ENGINEER UNKNOWN	32. ROOF TYPE AND MATERIAL
- 11		20. CONTRACTOR OR BUILDER UNKNOWN	gable=asphalt shingle
. 11	0,2	21. ORIGINAL USE, IF APPAREI	FRONT 3 SIDE 63
	- B	residence OIA	34. WALL TREATMENT
	CP3	vacant use	35. PLAN SHAPE T-Shape
-	The state of the s	23. OWNERSHIP	PUBLIC ( ) 36. CHANGES ADDITION ( PRIVATE ( X ) E (EXPLAIN IN ALTERED (
110	600	24. OWNER'S NAME AND ADD	DRESS MOVED (
. COORDINA	TES UTM	Layman Carpenter	37. CONDITION INTERIOR DOOR
LAT	:	Hardin, Missouri	EXTERIOR POOR
LONG	SITE ( )	STRUCTURE( )	YES ( ) H 38. PRESERVATION YES ( NO (X ) UNDERWAY? NO (
	BUILDING ( X )	OBJECT ( ) 26. LOCAL CONTACT PERSON	OR ORGANIZATION 39. ENDANGERED? YES
I. ON NATIO		SBLE ? NO( ) 27. OTHER SURVEYS IN WHI	BY WHAT neglect NO (
3. PART OF E	STAB. YES ( ) 14. DIS	TRICT YES( ) ENTIAL? NO(X)	40. VISIBLE FROM YES
	ESTABLISHED DISTRICT		41. DISTANCE FROM AND
			FRONTAGE ON ROAD
Neoclass corner b facades Primary	oards, frieze and to form pediments	<pre>l features: lintel window heads, boxed cornice which continues on , an articulation rare for rural red windows flanking central entr</pre>	n secondary Ray County.
	Y AND SIGNIFICANCE	had on this site first time is 30	207 when the avenanty was somed by
Fred Man	king. By 1914, t	he land and hosue has been inheri s born in Ray County in 1857.	897, when the property was owned by ited by his son, J.F. Manking.,
44. DESCRI	PTION OF ENVIRONMENT	AND OUTBUILDINGS	
Original been all	plantings remain	in front of house; the remaindent. Small outbuildings remain to	er of the surrounding property has o the rear and east of the house,
	s of information	ay County atlases, 1897 and 1914.	Cameron
Un-site	inspection. F	ay county acrases, 1057 and 1514.	47. ORGANIZATION RCHS & M



FLOORPLANS


NOT TO SCALE



PHOTOGRAPH



County Ray	4 Present Name(s)		
HA.Y	Kleibo	beker Residence	
	5 Other Name(s)		
Cocation of Negatives RCHS & M	Silas	Keith Homestead	
Specific Lucation north of	f intersection 16 Theme	lic Calegory 28 No of Stories	two
of Route A and AA, w	wood & -d7E	20 Basement?	Yes
unmarked gravel road	d.		No
City or Town It Rural, To	ownship & Vicinity 18 Style o	Obsign 30. Foundation Mail ashlar stone	
Braymer vic. Grape	Grove twp. transi	tional 09 31. Wall Construction	
Site Plan with North Arrow	19. Archite	ct or Engineer frame .Wu	
HAR BARN		Clor or Builder gable/gomp. s	aterial 6
ONEIL	unknow	n 33. No. of Bays	urugre
TETT (	A 21. Origina	nce / \u00f1	Side 3
	22 Present	Use steel siding	56
	reside	nce 35. Plan Shape T-	
	23 Owners	hip Public ! . 36. Changes	Addition
20ut	24. Owner	Private (Explain in #42)	Altered
O/OUG	I if know	37 Condition	
Coordinates UTM		eiboeker Interior go	od
Long	25 Open to	Catellol 80	od.
Site Li	Structure 1 : Public?	Yes I i 38. Preservation No IX Underway?	Yes No
On National Yes II 12 I		contact Person or Organization 39 Endangered?	Yes
	Is II Yes XI Eligible? No I I 27 Other S	By What?	No
	District Yes I I	40. Visible from	M
Name of Established District	Potent'1? No Xi	Public Road?	Yes
wante of Established District		41. Distance from an Frontage on Roa	nd
Typical early "T-sha"	pe" plan of I-house.	Building now altered with	
address of plue bo	ICh. Day Window and re	nont siding come ont at 17	/
Landscape trees remai	in. Bracketed cornice	dates to owiginal	
construction peri	. Framed in Walnut.	o not original. Interior Photo	
completely removated.		Institut Gildingi Chicked	
construction period completely removated staircase of walnut	remains.		
construction period completely removated, staircase of walnut	remains.		1
completely removated.	remains.	1.00	/
construction period completely removated, staircase of walnut	remains.		
construction period completely removated, staircase of walnut	remains.		
construction period completely removated, staircase of walnut in this long and Significance	remains.		
construction period completely removated, staircase of walnut in this long and Significance	remains.		
construction period completely removated, staircase of walnut in this long and Significance	remains.		
construction period completely removated, staircase of walnut in this lory and Significance  Description of Environment and	remains.		
construction period completely removated, staircase of walnut in History and Significance  Description of Environment an Rural area.	remains.		
construction period completely removated staircase of walnut in History and Significance  Description of Environment and	remains.	46 Prepared by	
construction period completely removated, staircase of walnut in this control and Significance Description of Environment and Rural area.  Sources of Information	remains.	Jim Pease	
construction period completely removated, staircase of walnut in this control and Superiod and Superiod and Rural area.  Sources of Information	remains.		



FLOORPLANS

NOT TO SCALE



PHOTOGRAPH




48 Date 8/79

49 Revision Date(s)

Office of Historic Preservation, P.O. Box 176, Jefferson City, Missouri 65101
HISTORIC INVENTORY

1 No 9'	7 4 Pres	ent Name(s)	
County		Sandy Residence	
Ray	5 OIN	er Namo(s)	
3 Location of Negatives			
RCHS & N	(	W	
2 3/4 miles north	of Hardin on	16 Thernalic Calegory	28 No of Stories two
Route A to Route A		030	29. Basement? Yes 13
miles		17 Date(s) or Period	partial No:
	R 26 Sec. 36	1900 18 Style or Design 4.4	30. Foundation Material, ashlar stone
vic. Rockingham Gr		Neoclassic/Eastlake details	ashlar stone 70
8 Site Plan with North A		19. Architect or Engineer	frame, www.
Route AA		unknown 22 20	32. Roof Type & Material IG
	K	20. Contractor or Builder Prich	gable-comp. shingles63
		John Rhodes CB R2	33. No. of Bays
	4	21. Original Use, if apparent residence of Pr	Front 3 Side n/a
	Y	22 Present Use	34. Wall Treatment weatherboarding
		residence	35. Plan Shape T-shaped
		23 Ownership Public ! !	36. Changes Addition
		Private ly	(Explain Altered):
	2 out	24. Owner's Name & Address,	In #42) Moved i
9 Guardinates	·	Rawley Sandy	37 Condition Interior good
Lat	UTM	Norborne, Mo.	Exterior good .
Long		25. Open to Yes I i	
Site 11	Structure 1 i	Public? No IX	Underway? Yes
Building Q	Object I I	26 Local Contact Person or Organization	39 Endangered? Yes !!
11 On National Yes I I Register? No IX	12 is it Yes 1/2   Fligible? No i i		By What? No 'X
13 Part of Estab Yes II	14. District Yes (	27. Other Surveys in Which Included	
Hist Dist.? No to	Potent'l? No Xi		40. Visible from Yes X Public Road?
15 Name of Established D	istrict		Public Road? No ::
			Frontage on Road
10 5 10			
Neoclassic house w	important Features ith molded window	heads, blind lunette in front	
gable, pllaster co	rner boards, boxe	d cornice and plain frieze. Has	
added Eastlake det	ails such as imbr	ricated shingles in gable and between	een
windows of each le	vel; two story po	rch with carved brackets and	Photo
founda lesses, and	second story with	archway and trellis. Primary	
#36. House has had	ws nave upper lig	tht with border of colored glass. little other alterations.	
		ittle other alterations.	1
43 History and Significance House was built by	John Rhodes in 1	900. Walnut trees on the farm wer	a sawed and hand
planed for the woo	dwork in the down	stairs rooms. House was built for	Samuel A. Sandy who
came irom kockingh	am Co. Virginia i	n 1872. Two years later he marrie	d Mary Catherine Phodos
and they settled o	n the present far	m, now owned by their son, Rawley	Sandy. They had eleven
children.  44 Description of Environm			
	-		
The barn and outbu	ildings are in fa	ir condition. The barn was built	at the time the house
s constructed.			
45 Sources of Information			
Rawley Sandy.			46. Prepared by
Ray County Atlas,	1973.		Marvin Holsinger
On-site inspection			RCHS & M



FLOORPLANS

NOT TO SCALE



PHOTOGRAPH




## Office of Historic Preservation, P.O. Box 176, Jefferson City, Missouri 65101 HISTORIC INVENTORY

County		Early's Store	
D			
Ray Location of Negatives		ner Namo(s)	
RCHS & M		Rockingham Mercantile Company Cen	tral Community Store
n willage of Rock	ingham 44 miles	16 Thematic Category	28 No of Stories 14
north of Hardin on		030 050	29. Basement? Yes
hen 3/4 miles wes		17 Datu(s) or Period ca. 1918	No
53 B26 S35 City or Town II Rus			30. Foundation Material
ockingham Grape	al. Township & Vicinity Grove twp.	vernacular/Neoclassic details	ashlar stone 40 31. Wall Construction
Site Plan with North Ar	row	19. Architect or Engineer	frame . WW
Route AA		unknown	32. Roof Type & Material GR
	N	20. Contractor or Builder Pack unknown	gable-asbestos shingle
	- 1	21. Original Use, if apparent 02 F	Front 4 Side 24
		general store	34 Wall Treatment
		22 Present Use	weatherboarding ~
		vacant	35. Plan Shaperectangular
		23 Ownership Public I Private bd	36. Changes Addition
		24. Owner's Name & Address.	(Explain Altered in #42) Moved
	1	il known	37 Condition
	UTM		Interior good
Long			Exterior good
Site 11	Structure 1	25 Open to Yes I i Public? No XI	38. Preservation Yes Underway? No.
Building iX	Object ( )	26 Local Contact Person or Organization	
On National Yes II	12 is ii Yes XI	organization	By What? Yes
Part of Estab Yes I I	Eligible? No I I	27. Other Surveys in Which Included	
Hist Dist.? No IX	14. District Yes i i Potent'l? No Ki		40. Visible from Yes Public Road?
	anterest.		Public Road? No
Name of Established D	TOTTICI		841 Distance from and
Name of Established D			41. Distance from and Frontage on Road
ypical country of acade displays two wo large 4 light was acades feature smakere has been littut in good repair.	ore building of to entrances; one windows. Stepped all windows. Doottle alteration to	he early twentieth century. Prima to store area, other to storage are gable on primary facade. Secondars have Neoclassic heads. #36: the building. It is vacant now,	Frontage on Road
prical country stored acade displays two large 4 light was acades feature small repair.  History and Significance Before 1918, the Monte Stratton.  burned in 1978 and called the "Rocking Community Store" in the store of the st	bre building of to entrances; one windows. Stepped all windows. Doo tle alteration to building on this The upstairs was do the present strugham Mercantile when the local so	to store area, other to sorage are gable on primary facade. Secondars have Neoclassic heads #26.	ry Photo  med by Samuel Hogan and ffairs, The building the property. It was er became the "Central
pical country state acade displays two large 4 light was acades feature smanere has been litted in good repair.  History and Supplicance Before 1918, the Monte Stratton.  burned in 1978 and called the "Rocking Community Store" in Description of Environments.	building on this The upstairs was d the present strugham Mercantile when the local screen and Outbuildings	gable on primary facade. Secondars have Neoclassic heads. #36: the building. It is vacant now, site was a two-story structure own sused for dinners and community are cucture was immediately erected on Company"for several years and late chool began. E. E. Hogan was the present the second several servers and second se	ry Photo  med by Samuel Hogan and ffairs, The building the property. It was er became the "Central
replicate Country stored of country stored displays two large 4 light was cades feature smalere has been little in good repair.  History and Supplificance Before 1918, the Monte Stratton.  burned in 1978 and called the "Rocking Community Store" in Description of Environments.	building on this The upstairs was d the present strugham Mercantile when the local screen and Outbuildings	gable on primary facade. Secondars have Neoclassic heads. #36: the building. It is vacant now, site was a two-story structure own used for dinners and community a ructure was immediately erected on Company"for several years and late	ry Photo  ned by Samuel Hogan and ffairs, The building the property. It was er became the "Central
replical country of acade displays two large 4 light was cades feature smalere has been little in good repair.  History and Significance Before 1918, the Monte Stratton.  burned in 1918 and called the "Rocking Community Store" in Description of Environment arrounded by farmle	building on this The upstairs was d the present strugham Mercantile when the local screen and Outbuildings	gable on primary facade. Secondars have Neoclassic heads. #36: the building. It is vacant now, site was a two-story structure own sused for dinners and community are cucture was immediately erected on Company"for several years and late chool began. E. E. Hogan was the present the second several servers and second se	ry Photo  med by Samuel Hogan and ffairs, The building the property. It was er became the "Central ropriator. The second(co
rpical country store of pical country store of light was cades feature smalere has been little in good repair.  History and Supplificance Before 1918, the Monte Stratton.  burned in 1978 and called the "Rocking Community Store" of Description of Environmental Sources of Information by County History.	building on this The upstairs was d the present strugham Mercantile when the local scient and, fronting discovery, p. 107.	gable on primary facade. Secondars have Neoclassic heads. #36: the building. It is vacant now, site was a two-story structure own sused for dinners and community are cucture was immediately erected on Company"for several years and late chool began. E. E. Hogan was the present the second several servers and second se	Photo  med by Samuel Hogan and ffairs. The building the property. It was er became the "Central ropriator. The second(control of the property) and the property of the property of the property. The second(control of the property) are property of the prope
replicate Country store acade displays two large 4 light was cades feature smalere has been littled in good repair.  History and Significance Before 1918, the Monte Stratton.  burned in 1918 and called the "Rockin Community Store" of Description of Environment of Country History, orborne Centennial	building on this The upstairs was d the present strugham Mercantile when the local so wind and fronting dispersion, p. 107. Book, 1968.	gable on primary facade. Secondars have Neoclassic heads. #36: the building. It is vacant now, site was a two-story structure own sused for dinners and community are cucture was immediately erected on Company"for several years and late chool began. E. E. Hogan was the present the second several servers and second se	Photo  med by Samuel Hogan and ffairs. The building the property. It was er became the "Central ropriator. The second(control of the property) and the property of the property of the property. The second(control of the property) of the property of the pr
pical country state acade displays two large 4 light was acades feature smanere has been litted in good repair.  History and Supplicance Before 1918, the Monte Stratton.  burned in 1978 and called the "Rocking Community Store" in Description of Environments.	brief brief falling of to entrances; one windows. Stepped all windows. Doot the alteration to building on this The upstairs was do the present strugham Mercantile when the local screen and Outbuildings and, fronting dispersion, p. 107. Book, 1968.	gable on primary facade. Secondars have Neoclassic heads. #36: the building. It is vacant now, site was a two-story structure own sused for dinners and community are cuture was immediately erected on Company"for several years and late shool began. E. E. Hogan was the proceeding on a paved county road.	Photo  med by Samuel Hogan and ffairs. The building the property. It was er became the "Central ropriator. The second(control of the property) and the property of the property of the property. The second(control of the property) are second(control of the property).

443. Cont. owner was Bill Falls. In December of 1937, the present owners purchased the building. Floyd and Clyde Early, and it was then given the name of Early Brothers. In May, 1938, a cyclone practically demolished the store. Floyd crawled off the porch just as the roof caved in. In two months, the store was repaired and open for business. In 1944, Floyd bought his brother's interest in the store. In 1962, a beauty shop was added.

In the thirties and fourties, this store was the highlight of the small community at Rockingham. Pinnocle and pitch games were played every evening

by the men while the women shopped and visited.



FLOORPLANS

NOT TO SCALE



PHOTOGRAPH




48. Date 10779

Present. Name(s

#43 Con't, years. T.B. Hatfield and

N. count

Brother James H. operated General store in Taitsville, East of the house. Vestiges of a road connecting the farm and now. Defunct town can still be observed in field behind house. Also in field was Old Mill, of uncertain date, now destroyed. Grinding Millstones of the mill are in the yard behind house. They are granite and probably imported. T.B. Hatfield later abandoned store and turned to farming full time. T.B.'s Grandson and Daughter-in-law now own the farm, which they rent. Land and house have remained in Hatfield Family since 1834



FLOORPLANS

NOT TO SCALE




PHOTOGRAPH



4/.79

Present Namels


## Office of Historic Preservation, P.O. Box 176, Jefferson City, Missouri 65101 HISTORIC INVEN



, maile is made

# 42 Con't running water, as well as bathrooms added.

#43 Con't husband Robert B. Rust as a wedding present in 1885. In 1896 Robert began remodelling the house with walnut, cherry sycamore, black and white oak and elmwood, each room having a different woodworking. He installed hot and cold running water, by placing a tank in the attic. The water was pumped from a windmill, and heated by running it through a great wood stove in the kitchen. A coal furnace was installed in the basement. Fleet and Frances Rust, children, inherited the farm. It was purchased in 1970 by Halley Frazier. Present owners are Paul and Karen Frazier McBee since 1975.



FLOORPLANS

NOT TO SCALE




PHOTOGRAPH



## Office of Historic Preservation, P.O. Box 176, Jefferson City, Missouri 65101 HISTORIC INVENTORY

1 Nu 31 31	4 Pre	sent Name(s)	
2 County		Wells House	
Ray	5 011	er Namo(s)	
3 Location of Negatives			
RCHS & M			
6 Specific Lucation		16 Thematic Category	28 No of Stories 15
Mary E		030	29. Basement? Yes II
1404 E 52 T53N RS	WYW	17 Date(s) or Period	No ox
		ca, k860	30. Foundation Material
Vic. Millville	ral, Township & Vicinity	vernacular/Neoclassic details	ashlar stone 40
8 Site Plan with North A		19. Architect or Engineer	11. Wall Construction frame, WU
	42	unknown	32. Roof Type & Material
* / F	(/////	20. Contractor or Builder	gable-tin 68
5 /		unknown	33. No. of Bays 54
7 7		21. Original Use, il apparent residence (farm)	
		22 Present Use	34. Wall Treatment
		vacant	weatherboarding
7	J		35. Plan Shape L-Shape
*		23 Ownership Public I ! Private IX	36. Changes Addition X .
	CO	24. Owner's Name & Address.	in #42) Moved
	ma	Howard Wells	37 Condition
9 Coordinates	UTM	Milleville, Mo.	Interior POOT
Lat			Exterior Poor
Sile L	Constant of the constant of th	25 Open to Yes I I Public? No bit	38. Preservation Yes
Building XI	Structure 1 i	26 Local Contact Person or Organization	Underway? No x
II On National Yes II	12 Is II Yes XI	20 Local Contact Person of Organization	39 Endangered? Yes IX By What? No !
Rogister? No X	Eligible? No 11	27. Other Surveys in Which Included	neglect
13 Part of Estab Yes I I Hist Dist.? No by	14. District Yes II		40. Visible from Yes
	Potent'l? No k		Public Road? No X
15 Namu of Established C	DISTRICT		41. Distance from and Frontage on Road
			Tomage on Hoad
42 Further Description of	Important Features	Constant of the contract of th	
House features to	rabeated windows,	primary facade with pediment sha	pea
		Primary entrance has 7-light tr glass. Ell addition to rear is	ansom
		features two-story porch along it	S Photo
		iswork. Brick stove chimneys at	
		pine woodwork. Wlanut stairway	
with carved banis	sters and turned	newel posts. C-shaped stair (con	t.)
43 History and Significant		·	
Andrew Wells was	born in Ray Cou	nty near Richmond in 1833. He wo	rked on his father's
farm until 1853	when he left for	California to join in the gold r	ush. While there he was
1857 with accept	in mining but all	so operated a sawmill and hog ran	ch. He returned home in
married Susan F.	Endsley the same	n to enable him to buy(not build) e year. The Wells remained on the	the present house. He
44 Description of Environm	nent and Outbuildings	Jear. The wells remained on th	e larm until 1804 (cont.)
		farm, surrounded by cypress and pi	nes . Several
outbuildings to	south and east in	varying stages of deterioration	a soldrat
45 Sources of Information			46 0
Mrs. Earl Miller		·	46. Prepared by Cameron
Mrs. Merle Brigh	it		
Mr. Roy Dreves	1001		47 Reastration
Ray County Histo			48 Date 49 Revision Date(s)
On-site inpection			1 4.780

- 42. Cont. leads to upper two bedrooms from central hall, has closet underneath, with vertical plankning. No connection of main house to L on upper floor. Enclosed curving staircase leads from kitchen. arlor features heavy plain chairrail and false fireplace mantel. Four rooms on each floor. House has original paneled doors and hardware. #36: A wellhouse was added to the rear covering original well and connicting it to the house. Electricity added to only parts of the house. Shutters added to windows, otherwise house is unaltered. #39: The house has been abandonned and is deteriorating rapidly, most windows broken by vandals, plaster falling, etc. No plans for demolision at this time.
- 43. Cont. when they moved to Virginia City, Montana territory, where Wells dealt in flour in the winter and mined in the summer. Mrs. Wells accompanied him on all his trips throughout the west. They returned to Ray County sometime before 1870 and returned to the house. It is still owned by a descendent. At one time, oil was suspected on the property about the tune of the century. Drilling was done but none discovered.



FLOORPLANS

NOT TO SCALE



**PHOTOGRAPH** 




RCHS & M

48 Date 49 Revision Date(s) 6/79

Office of Historic Preservation, P.O. Box 176, Jefferson City, Missouri 65101 HISTORIC INVENTORY

1 Ma		sent Name(s)	
County	91	Wall Residence	
Ray	5 011	WALL RESIDENCE	
3 Location of Negatives			
RCHS & M			
2 mi. north of Hard			26 No of Stories one
Route P, then west	2½ mi. to unmark	17 Datu(s) or Period	29. Basement? Yes I I
ed graval road, the	n 1/9 mi	1902	30. Foundation Material
	al, Township & Vicinity	18 Style or Design	ashlar stone 40
vic. Millville G	rape Grove twp.	Neoclassic/Carpenter Gothic det.	
a Sile Flan Willi North Al	100	19. Architect or Engineer Other unknown	frame . WU
N	0	20. Contractor or Builder	32. Roof Type & Material & B. gable-asphalt shingles
7	TI CD	unknown	33. No. of Bays
A	11 00 11	21. Original Use, if apparent	Front n/a Side n/a DR
4	31	residence O/A	34. Wall Treatment Clapboard
	7)	residence	imbricated shingles   35. Plan Shape irregular Te
		23 Ownership Public I !	36. Changes Addition
	T (3)	Private KI	(Explain Altered :
6	> U	24. Owner's Name & Address,	in #42) Moved
9 Coordinates	UTM	Dean Wall	37 Condition excellent
lal 530 T52		Route #1, Richmond, Mo.	Exterior excellent
Luny		25 Open to Yes I i	38. Preservation Yes
Site 1 i Building og	Structure	Public? No bel	Underway? NoX
11 On National Yes !!	Object 1 1	26. Local Contact Person or Organization	39 Endangered? Yes !!
Augister? No IX	12 is ii Yes to Eligible? No i i	27. Other Surveys in Which Included	By What? NoX
13 Part of Estab Yes I I	14. District Yes II	27. Other Surveys in which included	40. Visible from Yes X
Hist Dist.? No IX	Potent'i? No K		Public Road? No ::
15 Namu of Established D	istrict		41. Distance from and
			Frontage on Road
42. Further Description of	Important Features	center bay with central entryway.	
A lateral entrance	ecting polygonal	entrance) is in eastern bay. Bay	
is capped by polygo	nal hipped roof	ith gablet sheathed in diagonal	
pattern shingles.	Entire facade is	fronted by porch with turned posts	Photo
and spindles along	porch frieze. It	s roof is supported by carved brac	kets.
All windows are of	1-over-1 light sa	sh with Neoclassic window heads,	
		corners are ornamented with (cont)	
43 History and Significance	1902 Original b	nouse was of Brick and slaves were	and an labor tuite
construction. Card	y Wall built this	house in 1902. He took the basic	idea of the huilding
from the Barney Min	nick house nearby	(now greatly remodelled)	-400 01 410 041141118
44 Description of F	·		
44 Description of Environm On wooded lot in cer	nent and Outbuildings nter of large tre	ct of farmland. Farm outbuildings	not cont
the house, to the n	orth and south of	house.	, not contemporary to
Sources of Information			
Mrs. Dean Wall			46. Prepared by Cameron, Miller, Bright
On-site inspection.			47 Organization



FLOORPLANS

NOT TO SCALE



PHOTOGRAPH




1	N. (6) 4 Pre	Seni Nanie(s)	
		Clarke Farm House	
3	RCHS & M		•
6	Specific Lucation Sec. 34, T. 53, R. 27. On	16. Thematic Category	28. No. of Stories TWO
	gravel road off Route F, north east of Richmond.	The parallel of the parallel o	29. Basement? Yes 0 No i
7	City or Town II Rural, Township & Vicinity vic. Richmond Grape Grove twp.	before 1867  18 Siyle or Design  Vernacular, Gothic Revival det.	30. Foundation Material ashlar stone 31. Wall Construction
H	Sile Plan with North Arrow	19. Architect or Engineer	frame Wu
	Milloille	unknown  20. Contractor or Builder	32. Roo! Type & Material gable/asphalt shingle
		James Clarke 21. Original Use, if apparent	33. No. of Bays Front 3 Side 1
		residence DIA 22 Present Use	34. Wall Treatment as bestos shingles 64
		residence	35. Plan Shape rectangular
		23 Ownership Public !!	36. Changes Addition (Explain Altered In #42) Moved
	Coordinates UTM	24. Owner's Name & Address, if known Emily Clarke 643 East Main St., Richmond	37. Condition   good   Exterior   good
	Long	25. Open to Yes 11	38. Preservation Yes
0	Site ! 1 Structure ! i Building of Object ! !	Public? No Mi	Underway? No X  39. Endangered? Yes III
1	On National Yes i 12. Is II Yes iX Register? No ix Eligible? No i I	27. Other Surveys in Which Included	By What? No X
3	Part of Estab Yes II Hist Dist? No IX Potent'l? - No IX		40. Visible from Yes 県 Public Road? No に
5	Name of Established District		41. Distance from and Frontage on Road
2	Surther Description of Important Features		
	two rooms upstairs and two more	on the property. Stair baluster are sed to the original two room house down, and added the portico on the s replaced with the present portico.	
3	The Clarke family bought this f	arm in 1867 from Joh H. Smith. Abrathe US government in 1835. It has n	aham Mathena and William remained in the Clarke

slave quarters and a blacksmith shop on the property, which was widely patronized by people in the area 45 urces of Information 46. Prepared by Present owner

Abstract of property On-site inspection.

Hockemeir/Williams 47. Organization RCHS & M 48. Date 49 Revision Date(s) 6/79

5 Other Name(s)



FLOORPLANS


NOT TO SCALE




PHOTOGRAPH



Office of Historic Preservation, P.O. Box 176, Jefferson City, Missouri 65101
HISTORIC INVENTORY



#42 Con't added under half of the Church in 1951. The interior of the church remodelled in 1968. A hardwood floor had been added in 1952 and in 1962 a forced-air furnace.



FLOORPLANS NOT TO SCALE



PHOTOGRAPH



47. Organization

49 Revision Date(s)


Office of Historic Preservation, P.O. Box 176, Jefferson City, Missouri 65101

HISTORIC INVENTORY

1 No 26 26	4 Present Name(s)	
	Barnett Residence	
Ray	5 Other Namo(s)	
3 Location of Negatives	Mansur Residence	
RCHS & M		28. No of Stories
Specific Lucationat intersect:	ion of 16. Themslic Category	29. Basement? Yes Y
outes K & B northeast of	f Patriot or Period	full No
ichmond.	Ca. 1900	30. Foundation Material
14K S 1 53N 27W	Vicinity 18 Style or Design	ashlar stone
7 City or Town II Rural, Township & illville inc., Grove two	Vicinity 10 Style S.	31. Wall Construction
8 Site Plan with North Arrow	19. Architect or Engineer	frame, WW
8 Site Plan with North Allow	unknown	32. Roof Type & Material
	20. Contractor or Builder	gable-ashphalt
	unknown	Front 2 Side 4
[S]	21. Original Use, if apparent school house OSA	34. Wall Treatment
8	22 Present Use	weatherboard
	residence	35. Plan Shape rectangul
oute	23 Ownership Public L!	36. Changes Addition :
K	Private A	(Explain Altered in #42) Moved
1.	24. Owner's Name & Address,	37. Condition
	Sandra Barnett	Interior good
9 Coordinates UTM	Millvile, Missouri	Exterior good
Lat Long	25. Open to Yes 11	38. Preservation Yes
	Public? No Ki	Underway? No
Site 1 St	Object     26. Local Contact Person or Organization	39 Endangered? Yes By What? No.
II On National Yes II 12 Is II	YesXI	By what:
Register? No IX Eligible		40. Visible from Yes
13 Part of Estab Yes   14. Distric	t Yes!	Public Road? No
A A		41. Distance from and
15 Name of Established District		Frontage on Road
	·	
corner pilasters, boxed moldings. A bell tower d Originally the school ha The building has been pa	cornice, windows with neoclassical cornice, windows with neoclassical cominates the primary facade. #36: ad been 2 cloakrooms in the front. artitioned and remodelled. An additional new roof constructed.	Photo
consolidated and it was by the present oweners.  44 Description of Environment and Or Surrounded by farmland;	closed ca. 1938-40. It was remode cubuildings  two storage sheds-one a garage- to	elled into a resident
structure.		
		46. Prepared by
45 Sources of Information		Cameron

Mrs. Merle Bright Mrs. Carl Miller

On-Site Inspection



FLOORPLANS

NOT TO SCALE



PHOTOGRAPH



44 Description of Environment and Outbuildings


Typical outbuildings of Farm surround house.

sources of Information David Hatfield and Ruby Michael Hatfield 46. Prepared by Ray County History- 1973 on site-inspection Adams & Cameron 47. Organization 49 Revision Date(s) 48. Date 10/79

#42 Con't

× 417

structure had door on second story over primary entrance, now replaced by a window. Area now kitchen was added to rear simetime after 1923, and back porch was extended and enclosed.



FLOORPLANS


NOT TO SCALE



PHOTOGRAPH



County Ray	18	Present Name(s)	
Day		Hatfield Barn	
	5	Other Namo(s)	
3 Location of Negatives			
RCHS.	X M	18 Thematic Category	
\$4 miles north of	intersection of		26 No of Stories TWO-
Routes B and K, or		17 Date(s) or Period	29 Basement? Yes!
Tactsville	Huy, B	ca. 1900	30. Foundation Material
7 City or Town II Rus	al, Township & Vicin		ashlar stone 40
Knowxville vic.; k	(noxville twp.	vernacular	31. Wall Construction
8 Sile Plan with North Ar	SI II W	19. Architect or Engineer unknown	frame . wu
		20. Contractor or Builder	32. Roof Type & Material GP gable-tin; shed-shing1
	_ 3	William Hatfield	33. No. of Bays 54
		21. Original Use, if apparent	Front 5 Side 7
	N	barn 098 095	34. Wall Treatment 20
		barn	board and batten sidi
	(ds	23 Ownership Public !	35. Plan Shape rectangula
	Ψ	Private IX	(Explain Altered
·		24. Owner's Name & Address,	in #42) Moved i
Coordinates	11744	David and Ruby Hatfield	37 Condition good
Lat	UTM	David and hady had lord	
Lony >10	T54N27W	25 Open to Yes I i	38. Preservation Yes
Site Li	Structure		Underway? No X
Building IX	Object I	20. Local Contact Person of Organization	39 Endangered? Yes I
Register? No IX	12 Is II Yes I Eligible? No I		By What? No X
Part of Estab Yes II	14. District Yes I	27. Other Surveys in Which Included	40. Visible from Yes X
	Polent'l? No I	X II	
Hist Dist.? No IX			Public Hoad? No
Hist Dist.? No IX			41. Distance from and
Hist Dist.? No IX			110
Mist Dist.? No IX  5 Namu of Established D	ristrict		41. Distance from and
Hist Dist.? No IX  5 Name of Established D  12 Further Description of Transverse crib ba	Important Features	on each side. Interior beams fasten	41. Distance from and Frontage on Road
Hist Dist.? No IX  5 Name of Established D  12 Further Description of Transverse crib ba pins. Interior ho	Important Features orn with sheds orse stalls, hay	y loft, section for surrey later crea	41. Distance from and Frontage on Road
Hist Dist.? No IX  Name of Established D  Pransverse crib ba pins. Interior ho by hacking beam an	Important Features arn with sheds ourse stalls, hay	y loft, section for surrey later creator away. Interesting pacet is lower	41. Distance from and Frontage on Road
Mist Dist.? No IX  5 Name of Established D  12 Further Description of Transverse crib ba pins. Interior ho by hacking beam an level like Pennsyl	Important Features arn with sheds orse stalls, hay d chopping floo vania barn type	y loft, section for surrey later creator away. Interesting pacet is lower with access for animals. Walls	41. Distance from and Frontage on Road
Mist Dist.? No IX  5 Name of Established D  12 Further Description of Transverse crib ba pins. Interior ho by hacking beam an level like Pennsyl	Important Features arn with sheds orse stalls, hay d chopping floo vania barn type	y loft, section for surrey later creator away. Interesting pacet is lower with access for animals. Walls	41. Distance from and Frontage on Road
Hist Dist.? No IX  15 Name of Established D  12 Further Description of Transverse crib ba pins. Interior ho by hacking beam an level like Pennsyl here are of stone	Important Features arn with sheds of the stalls, hay and chopping floor vania barn type without mortar.	y loft, section for surrey later creator away. Interesting pacet is lower with access for animals. Walls	41. Distance from and Frontage on Road
Hist Dist.? No IX  15 Name of Established D  42 Further Description of Transverse crib ba pins. Interior ho by hacking beam an level like Pennsyl here are of stone  43 History and Significance	Important Features orn with sheds orse stalls, hay not chopping floor vania barn type without mortar	y loft, section for surrey later creater away. Interesting pacet is lower with access for animals. Walls	41. Distance from and Frontage on Road
Hist Dist.? No IX  15 Name of Established D  12 Further Description of Transverse crib ba pins. Interior ho by hacking beam an level like Pennsyl here are of stone  13 History and Significance Barn on farm which	Important Features arn with sheds of brse stalls, hay ad chopping floor vania barn type without mortar.	y loft, section for surrey later creator away. Interesting pacet is lower with access for animals. Walls	41. Distance from and Frontage on Road
Mist Dist.? No IX  5 Name of Established D  12 Further Description of Transverse crib ba pins. Interior ho by hacking beam an level like Pennsyl here are of stone  13 History and Significance Barn on farm which	Important Features arn with sheds of brse stalls, hay ad chopping floor vania barn type without mortar.	y loft, section for surrey later creater away. Interesting pacet is lower with access for animals. Walls	41. Distance from and Frontage on Road
Mist Dist.? No IX  5 Name of Established D  12 Further Description of Transverse crib ba pins. Interior ho by hacking beam an level like Pennsyl here are of stone  13 History and Significance Barn on farm which	Important Features arn with sheds of brse stalls, hay ad chopping floor vania barn type without mortar.	y loft, section for surrey later creator away. Interesting pacet is lower with access for animals. Walls	41. Distance from and Frontage on Road
Hist Dist.? No IX  5 Name of Established D  2 Further Description of Transverse crib ba pins. Interior ho by hacking beam an level like Pennsyl here are of stone  3 History and Significance Barn on farm which (now gone) once ra	Important Features arn with sheds of briese stalls, hay d chopping floo vania barn type without mortar has been in Ha n to side of ba	y loft, section for surrey later creater away. Interesting pacet is lower with access for animals. Walls atfield family since land grant. Oldern and is still visible.	41. Distance from and Frontage on Road
Hist Dist.? No IX  5 Name of Established D  12 Further Description of Transverse crib ba pins. Interior ho by hacking beam an level like Pennsyl here are of stone  3 History and Significance Barn on farm which (now gone) once ra	Important Features arn with sheds of the stalls, has deep to the without mortar.  The stalls of base of the stall of the s	y loft, section for surrey later creater away. Interesting pacet is lower with access for animals. Walls atfield family since land grant. Oldern and is still visible.	41. Distance from and Frontage on Road
Hist Dist.? No IX  5 Name of Established D  2 Further Description of Transverse crib ba pins. Interior ho by hacking beam an level like Pennsyl here are of stone  3 History and Significance Barn on farm which (now gone) once ra	Important Features arn with sheds of the stalls, has deep to the without mortar.  The stalls of base of the stall of the s	y loft, section for surrey later creater away. Interesting pacet is lower with access for animals. Walls atfield family since land grant. Oldern and is still visible.	41. Distance from and Frontage on Road
Further Description of Transverse crib bapins. Interior hoby hacking beam an level like Pennsylhere are of stone  3 Mistory and Significance Barn on farm which (now gone) once ra  4 Description of Environm On large wooded ar	Important Features arn with sheds of the stalls, has deep to the without mortar.  The stalls of base of the stall of the s	y loft, section for surrey later creater away. Interesting pacet is lower with access for animals. Walls atfield family since land grant. Oldern and is still visible.	41. Distance from and Frontage on Road
Hist Dist.? No IX  5 Name of Established D  2 Further Description of Transverse crib ba pins. Interior ho by hacking beam an level like Pennsyl here are of stone  3 History and Significance Barn on farm which (now gone) once ra  4 Description of Environm On large wooded ar	Important Features arn with sheds of the stalls, has deep to the without mortar.  The stalls of base of the stall of the s	y loft, section for surrey later creater away. Interesting pacet is lower with access for animals. Walls atfield family since land grant. Oldern and is still visible.	41. Distance from and Frontage on Road  et with the ated Photo
Hist Dist.? No IX  5 Name of Established D  2 Further Description of Transverse crib ba pins. Interior ho by hacking beam an level like Pennsylhere are of stone  3 History and Significance Barn on farm which (now gone) once ra  4 Description of Environm On large wooded are  5 Sources of Information	Important Features arn with sheds of the stalls, has deep to the without mortar.  The stalls of base of the stall of the s	y loft, section for surrey later creater away. Interesting pacet is lower with access for animals. Walls atfield family since land grant. Oldern and is still visible.	41. Distance from and Frontage on Road
Hist Dist.? No IX  5 Name of Established D  2 Further Description of Transverse crib ba pins. Interior ho by hacking beam an level like Pennsyl here are of stone  3 History and Significance Barn on farm which (now gone) once ra  4 Description of Environm On large wooded are  5 Sources of Information David Hatfield.	Important Features arn with sheds of arse stalls, hay ad chopping floo vania barn type without mortar  has been in Ha n to side of ba	y loft, section for surrey later creater away. Interesting pacet is lower with access for animals. Walls atfield family since land grant. Oldern and is still visible.	46. Prepared by Adams and Cameron  47 Organization
Mist Dist.? No IX  5 Name of Established D  12 Further Description of Transverse crib ba pins. Interior ho by hacking beam an level like Pennsyl here are of stone  13 History and Significance Barn on farm which	Important Features arn with sheds of arse stalls, hay ad chopping floo vania barn type without mortar  has been in Ha n to side of ba	y loft, section for surrey later creater away. Interesting pacet is lower with access for animals. Walls atfield family since land grant. Oldern and is still visible.	41. Distance from and Frontage on Road  Photo  road to Taitsville  46. Prepared by Adams and Cameron



FLOORPLANS

NOT TO SCALE




PHOTOGRAPH



1 No 36 36	Present Name(s)	
. County	Schooler House	
	Other Namo(s)	
3 Location of Negatives RCHS & M	Russell House	
6 Specific Lucation	16 Thematic Calegory	26 No of Stories two
of Routes B and K, on Route	B. 17 Date(s) or Period	29. Basement? Yes !!
HUY, B SA TERN 27	ca. 1830	No x
7 City or Town Il Rural, Township & Vic	In Style of Deuton	30. Foundation Material ashlar stone
vic. Millville; Knoxville tw		31. Wall Construction
8 Site Plan with North Arrow	19. Architect or Engineer unknown	frame, Uu
N - WAR	20. Contractor or Builder	32. Roof Type & Material gable-asphalt shingle
- 65 E	Nathan Schooler	33. No. of Bays
1. 4	21. Original Use, if apparent residence	Front 5 Side 1
(30)	22 Present Use	34. Well Treatment weatherboard
	residence	35. Plan Shape rectangular
	23 Ownership Public ! !	36. Changes Addition X
1 6 6 6 6	Private X	(Explain Altered X:
1 000	24. Owner's Name & Address, if known	in #42) Moved i
9 Coordinates UTM	Mr&Mrs. Robert Russell	37 Condition fair
t et Long		Exterior fair
	25. Open to Yes I I	38. Preservation Yes X
Site 1 i Structur Building of Object	W X	Underway? No
	26. Local Contact Person or Organization	39 Endangered? Yes II By What? No K
Angister? No ® Eligible? N	27. Other Surveys in Which Included	- 100
	Missouri Historic Sites	40. Visible from Yes X
15 Name of Established District	Catalogue	Public Road? No ::
		41. Distance from and Frontage on Road
42.5		
42. Further Description of Important Features I-house of walnut cut on the	site. Interior end brick chimneys.	
central door on each story or	Drimary facade has sidelights One	
Print balletted dools' Talke i	11811 Trieze and haved committee at the	
small returns. Secondary fac	ades have no openings Opiginal and	Photo
Some places. # 10: Uriminal	two story porch has been removed.	
House is being restored, and	only half is lived in at this time.	ont)
43 History and Supplicance	Nathan Schooler. He was born in Bedf	
and emigrated to Massouri in	Nathan Schooler. He was born in Bedf	ord County, Tennessee
house of walnut logs found on	the farm and bila dailed by	tructed the present
	OUTCL TAMILLY DULL SAVATAL MARKE AND	When it was sold (cont)
and Outputigit		
In the center of an active fa	rm, outside of the small town of Mill	ville. Original
planting, including many locu	st trees, remain on the site.	
45 Sources of Information		
Missouri Historic Sites Catalo	ogue.	46. Prepared by
		Cameron 47 Organization
Charlene Moyer, "History of Mi		RCHS & M
Ray County History, 1881.	Un-site inspection.	48 Date 49 Revision Date(s) 7/80

- 42. Cont. Interior features walnut woodwork and staircase. Large addition to the rear of the house. #38: House is being gradually restored by new owners.
- 43. Cont. to the present owners.



FLOORPLANS

NOT TO SCALE



PHOTOGRAPH




48 Date 49 Revision Date(s) 10/79

	4 Pres	ent Name(s)	
15		g 44	
/ County		Switzer House	
Ray	5 Othe	Pr Namo(s)	
3 Location of Negatives RCHS & M			
6 Specific Lucation	Newy B	16 Themalic Calegory	
$l^{\frac{1}{2}}$ miles north of	the intersection	0.30	26 No of Stories two-12
of Routes Band K,	on Route B. then	17 Datu(s) or Period	29. Basement? Yes III
west on unmarked gr	ravel road imile	ca. 1870 and 1900	30. Foundation Material
7 City or Town II Rura	I, Township & Vicinity	18 Style or Design	ashbar stone 40
vic. Georgeville		Queen Anne and vernacular	31. Wall Construction
8 Sile Plan with North Are		19. Architect or Engineer when	frame, Wu
	1	unknown 20	32. Roof Type & Material GB
	N	20. Contractor or Builder Prim	gable-asphalt shingles
- KV		J. Switzer	33. No. of Bays DREE
	7 6	21. Original Use, If apparent residence	Front n/a Side n/a
	חן שף ו	22 Present Use	34. Wall Treatment
#		residence	clapboard 4
			35. Plan Shape irregular
		23 Ownership Public I Private Isl	36. Changes Addition X (Explain Altered IX
		24. Owner's Name & Address,	in #42) Moved i
		if known	37 Condition
9 Coordinates L	754N 27W	William T. Switzer Knoxville, Mo.	Interior poor
lat tong	7540 3100	Mioxville, Mo.	Exterior poor
		25. Open to Yes I i Public?	38. Preservation Yes
Site 1 i Building og	Structure 1 i	140 X	Underway? No 💥
		26 Local Contact Person or Organization	39 Endangered? Yes IX
Register? No ix	12 is ii Yes ix	27 Other S	By What? No
13 Part of Estab Yes II	14. District Yes II	27. Other Surveys in Which Included	neglect
Hist Dist.? No 12	Potent'l? No IX		40. Visible from Yesx Public Road? No :
15 Name of Established Di	strict		41. Distance from and
			Frontage on Road
42 Contraction Description			
Queen Anne house wa	s finest in the	area at the time it was constructe	
It features high ga	ble on primary fa	acade with projecting center bay.	
with bay windows, b	alcony, and varie	ed forms of woodworking. Interior	
has carved walnut st	aircase, dining n	room with parquet florming and	Photo
neavy woodwork. Ne	w section is tvo	Ical T-house with Neoclassia	
peaiment-snaped win	dow heads. Inter	rior has plain woodwork #26.	
East portion of nou	se has been recor	structed in a completely differen	t
43 History and Significance	/3	County, Ohio. His parents were Ja	
moved to farm on the	er (born Lincoln	County, Ohio. His parents were J	acob and Sophia Switzer)
place for the area	and reflected the	nestead. When house was first con	structed it was a show-
ornaments, cupolas.	etc. The east no	e prevailing taste for Queen Anne art of the house burned ca. 1900,	architecture with czrved
	eni and Outbulldings		
In the center of a :	large lot, surrou	unded by farmland. There are one	or two outhwells.
including a well, in	n close proximity	to the house.	or two outbuildings,
	_		
Sources of Information			
William Switzer.			46. Prepared by
Ray County History.	1881.		cCameron and Adams
Ray County Atlas, 18	377.		47 Organization RCHS & M
On-site inspection.			48 Date 49 Revision Cate(s)

#42. Cont. style. Some ornamentation of the original house, such as the cupola, have been reused in the new section, irradically. #39: House has been abandonned and is deteriorated.

#43. Cont. an entirely different vernacular style. The house has always been in the Switzer family. About 20 years ago, the present owner built a new house on the property and the old house was abandonned.



FLOORPLANS NOT TO SCALE



PHOTOGRAPH




RA-AS-002-117

49 Revision Date(s)

48. Date

10/79

Office of Historic Preservation, P.O. Box 176, Jefferson City, Missouri 65101 HISTORIC INVENTORY




On-Site Inspection

be miles nowth of intersection of Mautes B, then west on unrared buniel road, then loft one of chip of a mile.

. (Wi allivanil ellivanae) iniv

#42 Con't

wain scoting and plste rail, and window coffered ceiling. Hardwood floors double leaf door between living and dining rooms with plate glass. Dining room also has pass through with paired glass doors in toup pattern, which seems to have once opened onto a pantry. #36: There has been little alternation to the house. The stairway from living room to second floor was enclosed at an unknown time



FLOORPLANS


NOT TO SCALE



PHOTOGRAPH



35	35 4 Pre	sent Name(s)	
2 County		Dreves Residence	
Ray  Tocation of Negatives	5 OIM	ner Namo(s)	
RCHS	& M		
6 Specific Lucation		16 Thematic Category	28 No of Stories one !- !
Route B north of F			29. Basement? Yes I
K through Millvill to first left; the		17 Date(s) or Period ca. 1895	partial No 1
	al, Township & Vicinity	18 Style or Design	30. Foundation Material 40
vic. Millville; KN	Noxville twp.	Neoclassic 💍	rockfaced ashlar stone
8 Sile Plan with North Ar		19. Architect or Engineer	frame .Wu
510 53	MILENS	unknown 20 Contractor or Builder	32. Roof Type & Material GB gable-comp. shingles
1	- S	Lorenz Maisel	33 No. of Base
11 1 1		21. Original Use, If apparent	Front 5 Side 5
		residence Olf	34. Wall Treatment
		22 Present Use	weatherboard 2
U_L		residence 23 Ownership Public !	35. Plan Shape L-Shape 36. Changes Addition X
,		Private t x	36. Changes Addition X (Explain Altered X
	•	24. Owner's Name & Address,	in #42) Moved i
Coordinates	UTM	Charles Roy Dreves	37 Condition excellent
Lat	OTM	Route 1, Box 147, Richmond Mo.	Exterior excellent
-Luny		25 Open to Yes I i	38. Preservation Yes
Site 1 i Building i X	Structure 1 i	Public? No X I	Underway? No X
1 On National Yes II	12 is it Yes Ki	26 Local Contact Person or Organization	39 Endangered? Yes I By What? No X
Rogister? No IX	Eligible? No 11	27. Other Surveys in Which Included	By What? No X
Part of Estab Yes I I Hist Dist.? No IX	14. District Yes !!	The state of the s	40. Visible from Yes X
Namu of Established D	Potent'l? No X		Public Road? No
Name of Established D	ising		41. Distance from and Frontage on Road
Further Description of			
(1 added) in el	All windows have	m to either side and two rooms Neoclasssic molding and are 2-over	
		r transom. Interior has heavy pine	
		rdware. Pilasters corner boards	Photo
		Porch added on north and west facad	
		s and trim. Back porch was enclose	
History and Significance	e a Kitchen white	el the kitchen became the (cont)	1/
		Maisel (family name now Misel) of	Bayreuth Germany.
Before he died, hi	s older brother	asked Lorenz to care for his wife A	nna and their five
children. Lorenz	replied that the	best way to do that would be to ma	rry her and he did.
mey had one child	or their own. I	he Maisel family came to the U.S. i	n 1883 and land was
Description of Environm	_	·	
On large working f	arm with several	modern outbuildings.	
Sources of Information			
Sources of Information Mrs. Merle Bright.	0n-s	ite inspection.	46. Prepared by
Mrs. Earl Miller.	Pov. Deserve		Bright, Miller, Cameror
Mr. & Mrs. Charles Ray County History	1072		RCHS & M
- Journey miscory	, 13/3.		48 Date 49 Revision Date(s)
			4/80



FLOORPLANS

NOT TO SCALE




PHOTOGRAPH

- dining room. A larger door was cut between dining and living rooms.

  New woodstove with brick firewall added. Floors are carpeted. A partial basement was added, stoves removed, hardwood floors laid. A door in parlor leading to hall was closed.
- 43. Cont. purchased in Ray County that year. Their daughter, Cora, who came to this country when she was three years old, married Gus Dreves in 1904. Dreves was born in 1876 in Posen Germany. He became dissatisfied with the regime in Germany and came to the U.S. in 1900 on the ship Kaiser Wilhelm. The Dreves lived in the Maisel family house and it is currently owned by one of their children.



1 10 12 13	4 Pre	Sent Name(s)	
Ray		McElwee House	
3 Location of Negatives	5 01	Gully House	
Specific Lucation North of Richmond	on Route 13. t	16 Thematic Calegory	28 No of Stories /-/one
B; east and north marked gravel roa	5½ miles to un	17 0 10 10 10 10 10 10 10 10 10 10 10 10 1	29. Basement? Yes
	Township & Vicinity	ca. 1890	30. Foundation Material ashlar stone
Taitsville Kno	xville twp.	vernacular/Neoclassic 49	31. Wall Construction
Sile Plan with North Arro	TEAN STUD	19. Architect or Engineer unknown	frame . W.C.  32. Roof Type & Material ( )
Committee (2)	CR	20. Contractor or Builder unknown	gable/asphalt shingl
		21. Original Use, if apparent	Front 4 Side 6
		residence O/A 22 Present Use	34. Wall Treatment clapboard
	#	vacant (storage)	35. Plan Shape rectangul
(3)		23 Ownership Public I 1 Private ½1	36. Changes Addition (Explain Altered
		24. Owner's Name & Address, if known	37 Condition
Coordinates U1	М	Gene McLewee Taitsville, Missouri	Interior Poor
Long		25. Open to Yea I i	Exterior fair  38. Preservation Yes
Sile 1 i Building og	Structure 1 i Object 1 i	Public? No XI 26 Local Contact Person or Organization	Underway? No
On National Yes III Register? No to	12 Is It Yes I I Eligible? No I K		39 Endangered? Yes By What? No
Part of Estab Yes I I Hist Dist.? No I K	14. District Yes II	27. Other Surveys in Which Included	neglect 40. Visible from Yes
Name of Established Dist	Potent'l? No IX		Public Road? No 41. Distance from and
			Frontage on Road
corner pilasters had at least four additions to the One stove chimney several yezrs sin	ssic details su and boxed corni separate addit east. The porc remains. The	ch as pediment shaped window heads ce and frieze. #36: House has ions at various times, two larger h on the south has been enclosed. house is vancant and has been for the owner.	Photo
which once boaste population was 10	d a steam four : 8. Taitsville	but is the only remnant of the t mill, many shops, a church and sc at present is occupied by one fam	hool. In 1880, the ily with a population of
Description of Environmen	tsville (see #1		
Lot is overgrown, of the house are	but some origin direpair.	nal phantings are apparent; OUtb	uldings to the rear
Sources of Information Ray County Atlas.	1877		46. Prepared by
Ray County Histor			Richardson
Mrs. GeneMcElwee Personal knowledge	e of surveyor.	On-site inspection.	47 Organization RCHS & M
		are a residence are the	48 Date 49 Revision Date(s) 6/79



FLOORPLANS


NOT TO SCALE



PHOTOGRAPH



1 No	62 1 Pi	Frazier House	
nty . Ray	5 01	her Namo(s)	
Location of Negatives RCHS 8	k M		
Specific Location	• 315/	16. Thematic Category	28. No. of Stories two 2-1
oute 13 north of Ri ; east 1-3/4 miles			29. Basement? Yes ! !
raval road east; th		17 Date(s) or Period ca. 1860	No X.
	Township & Vicinity		30. Foundation Material ashlar stone 40
ic. Millville; Kno		Neoclassic 3/ 19	31. Wall Construction
Sale Plan with North Arro	a	19. Architect or Engineer	frame wu
Million	6211	unknown 20. Contractor or Builder	32. Roof Type & Material gable-asphalt shingle
4	1	unknown	33. No. of Bays
	100	21. Original Use, if apparent	Front 3 Side 5
	1	residence OIA  22 Present Use	34. Wall Treatment clapboard
	9	residence	35. Plan Shape rectangular
-V		23 Ownership Public !!	36. Changes Addition X
1	~	Private Ki	(Explain Altered IX) in #42) Moved i
y .	1 1 65	24. Owner's Name & Address, if known	37. Condition
Coordinates U	тм	Dorris W. Frazier	Interior good
Lat Luny Salo To 3	CATE CA		Exterior good
Site ! i	Structure I i	25. Open to Yes!! Public? No ki	38. Preservation Yes Underway? No X
Building ix	Object	26. Local Contact Person or Organization	39. Endangered? Yes 11
On National Yes II	12. Is II Yes 🕅		By What? No X
Part of Estab Yes I.i	Eligible? No I I	27. Other Surveys in Which Included	
Hist Dist ? No 1x	Potent'l? No lx		40. Visible from Yes ' X Public Road? No i:
Name of Established Dis	trict		41. Distance from and
			Frontage on Road
Further Description of Im	portant Feathtes	contemporary with main block. Neo-	
/) 1-nouse with lai	rge FI addition	contemporary with main block. Neo- indow heads, pilaster corner boards	
arge plain frieze,	boxed cornice w	ith returns. El facade has two	
tory veranda across	length. Interi	or brick stove chimneys, one	Photo
emoved. Veranda bo	ordered by raili	ng with carved banisters on second andals while house was vacant.	
mall addition to re		madis while house was vacant.	
History and Significance		•	
	wilt by a J.S.	Frazier. It has remained in the Fr	azier family, but
oday is used as a n	cental property.	In the 1830's James and Sarah Fra	zier migrated from
nderson County Ken	tucky. It seems	s likely his son Jackson (1829-1897)	was responsible for the
and the of this	a harren Othern		me area.
onstruction of this	s house. Other	family farms were located in the sa	and along
onstruction of this		iamlly larms were located in the sa	ano aroa,
Description of Environme	nt and Outbuildings		ano azoa,
Description of Environme	nt and Outbuildings		í í
Description of Environment a working farm, s	nt and Outbuildings urrounded by la		46. Prepared by
Description of Environment a working farm, s  Sources of Information ersonal knowledge of	nt and Outbuildings surrounded by la		46. Prepared by Bright, Miller, Cameron
Description of Environment a working farm, so Sources of Information ersonal knowledge of ay County Atlas, 18 m-site inspection.	nt and Outbuildings surrounded by la		46. Prepared by



FLOORPLANS


NOT TO SCALE



PHOTOGRAPH



3 Location of Newtities & M  Separatic Location Material asking a Separation of Separation with Construction log and frame Location and Separation in Newtities & M  Separatic Location Material asking a Separation of Separation with Capacitan Altered Capacitan Altered Capacitan Moved of No Not Not Not Not Not Not Not Not Not	1 No 3'	53 4 Pres	sent Name(s)	
\$ Specific Lucation  \$ Specific Lucation  \$ May mile so north of intersection of Routes K and B on Route B to unemarked road; east 1 mile.  7 Gry un Town II Rural, Township & Vicinity Vic. Milliville; Knoxville twp.  8 Stee Plan with Numb Aureur  20 Special Lucation  18 Style or Design Up Interest Unknown  20 Foundation Material Shirt Style or Design of Vicinity Vic. Milliville; Knoxville twp.  8 Stee Plan with Numb Aureur  20 Special Lucation  21 Acquired or Ruinless  22 Rool Type & Material Capital Use, If apparent Infarm home Oil Acquired or Ruinless  23 No of Bays  24 Owner's Name & Address.  15 Annum II Stricture 1: Object II I Constitute II Copect II I Copect II I Constitute II Copect II I Constitute II Copect II I Constitute II Copect II I	·ounly		Wild House	
Specific Lucation   The Intersection of Part Item Provided   The Intersectio	Ray	5 OIM	er Namo(s)	
18 miles north of intersection of Route 8 to unemarked road; east 1 mile.   17 Jailets 90 Period   23 Jacks 90 Period   24 Jacks 90 Period   25 Jacks 90 Jacks 90 Period   26 Jacks 90 Jacks 9	RCHS 8	& M		
Routes K and B on Route B to un- marked road; east I mile.  7 Gity or Town II Rural, Township & Vicinity Vic. Mill ville; Knoxville twp.  18 Stire or Design Vic. Mill ville; Knoxville twp.  19 Architector of Engineer Unknown 20 Contractor or Builder Unknown 21 Route Plan with Built Arrow 22 Present Use Vacant 23 No of Bays Front 3 Side Plan Wall Treatment Clapboard Springles Vacant 23 Ownership Public II Public I	The state of the s			28 No of Stories
marked road; east 1 mile.  7 Gity or Town II Rural, Township & Vicinity 10. MillYille; KnoxYille twp.  8 Site Plan with Bull Arrow 19 Architect or Enginese Unknown 20 Contractor or Burder Unknown 21 Original Use, II apparent 15 Multimary 22 Present Use 23 Site Plan Site Plan with Bull Arrow 24 Contractor or Burder Unknown 25 Contractor or Burder Unknown 26 Coordinates 14 Use 15 Ownse's Name & Address, 14 Arrow 16 Coordinates 17 Ownse's Name & Address, 18 Arrow 19 Coordinates 19 Coordinates 19 Coordinates 19 Condition 19 Arrow 10 Contractor or Burder 10 Ownse's Name & Address, 18 Arrow 19 Coordinates 19 Contractor or Burder 19 Ownse's Name & Address, 18 Arrow 19 Coordinates 10 Ownse's Name & Address, 18 Arrow 19 Coordinates 19 Ownse's Name & Address, 18 Arrow 19 Coordinates 19 Ownse's Name & Address, 18 Arrow 19 Coordinates 19 Ownse's Name & Address, 18 Arrow 19 Coordinates 19 Ownse's Name & Address, 18 Arrow 19 Ownsership 10 Ownsers				
City or Town   Reveal , Township & Vicinity   Vic. Mill ville; Knoxville twp.				No
vic. Millville; Knoxville twp.  a Site Plan with North Arrow  a Site Plan with North Arrow  20 Conizacior or Builder  21 Orașinal Use. II appearent  22 Present Use  23 Proof Bays Front  23 Proof Bays  24 Councinalise  14 Conser's Name & Address.  15 Plans Stape rectangula  25 Plans Shape rectangula  26 Conizacior or Builder  27 Present Use  28 Proof Bays  29 Proof Bays  29 Proof Bays  20 Conizacior or Builder  20 Ownership  20 Conizacior or Builder  21 Present Use  22 Present Use  23 Present Use  24 Conner's Name & Address.  15 Plans Shape rectangula  26 Changes  27 Present Wild  Hardin, Missouri  28 Ownership  29 Proof II Provide A Missouri  29 Popen Io Public I Proof  20 Conizacior or Builder  21 Present Use  22 Present Use  23 Present Use  24 Conner's Name & Address.  16 Robert Wild  Hardin, Missouri  25 Open Io Public I Provide A Missouri  26 Conizacior or Builder  27 Present Use  28 Conizacior or Builder  29 Present Use  20 Conizacior or Builder  21 Present Use  22 Present Use  23 Roof Yype & Masteral Gable-Comp. Shirigles  33 No. 16 Bays  34 Front 3 Single  35 Plans Shape rectangula  36 Changes  37 Condition  18 Address  37 Condition  18 Address  39 Condition  18 Address  30 Conizacior or Builder  20 Ownership  21 Conizacior Wild  22 Present Wild  23 Roof Yype & Masteral Gable-Comp. Shirigles  33 No. 16 Bays  34 Proof  35 Plans Shape rectangula  36 Changes  37 Condition  36 Changes  37 Condition  37 Condition  38 Pervision Development  38 Changes  39 Condition  30 Conizacior On Poper  30 Conizacior On Poper  30 Conizacior On Bays  30 Conizacior On Poper  30 Conizacior On Bays  31 No. 17 Present  32 Pervision Development  36 Changes  37 Condition  37 Condition  38 Pervision Poper  38 Proof Vie & Masteral Gable  39 Pervision  30 Conizacior  31 No. 14 Popen  32 Pervision  34 Popen  35 Plans Shape rectangula  36 Changes  37 Condition  37 Pervision  40 Vision  40 Vision  40 Vision  40 Vision  40 Vision  40 Vision  40 Vis				30. Foundation Material
Solic Plan with Nurth Arrow   19 Architect or Enginees   19 Architector   19	vic. Millville; Kr	noxville twp.		174
20 Contractor or Builder Unknown 21. Original Use, if apparent farm home 22 Present Use 23 No of Bays 34. Well Treatment 12 Ownership 24. Ownership 25. Plan Shape rectangula 26. Ownership 27. Ownership 28. Ownership 28. Ownership 29. Ownership 20. Ownership 20. Ownership 21. Ownership 21. Ownership 22. Ownership 23. Ownership 24. Ownership 25. Plan Shape rectangula 36. (Esplain 37. Condition interior poor	B Sile Plan with North Ar	row	19. Architect or Engineer	log and frame LL Luc
Unknown  1 Original Use. If apparent farm home IPA  32 Present Use Vacant 12 Present Use Vacant 12 Ownership 12 Ownership 13 No. of Bays From 3 Side 3  33 No. of Bays From 3 Side 3  34 Wall Treatment Clapboard 15 Pier Shape rectangula 15 Ownership 16 Public 1  24 Owner's Name & Address 16 No. 11  25 Ownership 17 Open 10  26 Open 10  27 Open 10  28 Preservation Robert Wild Hardin, Missouri 19 Open 10  29 Public 7  20 Local Contact Person or Organization Public 7  20 Ownership 21 On National Ves II Open 10  22 Preservation No. 1  23 No. of Bays From 3 Side 3  34 Wall Treatment Clapboard 35 Changes (Explain Altered Poor Estation Poor Estatio				32. Roof Type & Material
20 Original Use. If apparent farm home 1/2 Present Use 1/2 (appboard 2) 34. Well Trealment (appboard 3) (appb	F-4-24	//ZZI · V		
Second   S		777 b		
Countinates  UTM Let  Underway?  Situation	LOG		farm home OIA	
SSTIAN 3100  Constitutes Left Long  Constitutes Building 1x  Object 1  1 On National Ves 1  Polenting 1x  Object 1  1 On National Ves 1  Hast Dist. 7  No 1X  Supplies Ves 1  Hast Dist. 7  No 1X  Supplies Ves 1  Potenting No	V		22 Present Use	Ciappoula
S35 T 54 N 3 T W   24 Owner's Name & Address   12 Owner's Name & Address   12 Owner's Name & Address   12 Owner's Name & Address   13 Condition   10 Owner's Name & Address   14 Owner's Name & Address   15 Owner's Name & Ad		///		
24. Owner's Name & Address.  1 In Structure   1	CR			
Robert Wild Hardin, Misspuri  Structure I: Open to Public Robert Wild Hardin, Misspuri  Structure I: Open to Public Robert Wild Hardin, Misspuri  On National Vest I: 12 is II Vest Wester Register No. 1  Part of Estably Yes II Potent? No. 1X  Potent? No. 1X  Name of Established District  Potent? No. 1X  Potent. No. 1X	535 T 54 N 24 L			
Luny    Site   Structure   Sopen to Public?   Sopen			if known	37 Condition
Site   1   Structure   2   Open to   1   Open to   O		UTM		noon
Building X  Structure 1:  Building X  Object: 1  10 National Yes 1: 11 Is it Yes X  Rugister? No IX  Bigible? No II  3 Pair of Established District  14. District Yes 1: Potenti? No XX  Sightly later period. Two entrances on primary facade of original building, with windows to right. Small windows above open into loft area. #36: Original end chimneys removed, one clearly visible on south facade. Interior: two staircases, log portion enclosed with closet beneath. Interior has been modified, walls plastered and paper According to 1877 Ray County Atlas, this property was already in the Wild family. It appears to have been vacated relatively recently.  Public?  Public Poseries  Public Poseries  Public?  Public Poseries  Public?  Public Poseries  Public Poser	• • •			Caldilot
1 On National Yes 1: 12 is it Figible? No it Register? No it Potent? No it Potent. No it Potent. No it Potent. No	Site Li	Structure 1;		38. Preservation Yes Underway? No.
1 On National Vest   12 is it Yes M Eligible? No   12   12 is it Yes M Eligible? No   13   14   District Yes   14   District Yes   16   Potent   17   No   No   No   18   No   No   No   No   No   No   No   N		Object 1 1	^	
3 Part of Estab Ves   1				By What? No
Potenti? No XX  Name of Established District  The properties on Road  The properties of Properties			27. Other Surveys in Which Included	
The property of Established District  41 Distance from and Frontage on Road  2 Further Description of Important Features  ogtrot log cabin with frame addition to rear and to north end, of slightly later period. Two entrances on primary facade of original building, with windows to right. Small windows above open into loft area. #36: Original end chimneys removed, one clearly visible on south facade. Interior: two staircases, log portion enclosed with closet beneath. Interior has been modified, walls plastered and papered.  3 History and Superlicance  According to 1877 Ray County Atlas, this property was already in the Wild family. It appears to have been vacated relatively recently.  4 Description of Environment and Outbuildings  Rural environment. Two barns to rear of property in deteriorated condition.  5 Sources of Information  On-site inspection.  Ray County Atlas, 1877.  46 Prepared by Jim Pease  47 Organization RCHS & M  48 Date   49 Revision Date(s)				
Trither Description of Important Features Orgerot log cabin with frame addition to rear and to north end, of Slightly later period. Two entrances on primary facade of original building, with windows to right. Small windows above open into loft area. #36: Original end chimneys removed, one clearly visible on south facade. Interior: two staircases, log portion enclosed with closet beneath. Interior has been modified, walls plastered and papered  3 History and Significance According to 1877 Ray County Atlas, this property was already in the Wild family. It appears to have been vacated relatively recently.  4 Description of Environment and Outbuildings Rural environment. Two barns to rear of property in deteriorated condition.  5 Sources of Information On-site inspection.  Ray County Atlas, 1877.  46. Prepared by Jim Pease. 47. Organization RCHS & M  48. Date 49. Revision Date(s)	5 Name of Established D	istrict		110
regtrot log cabin with frame addition to rear and to north end, of slightly later period. Two entrances on primary facade of original building, with windows to right. Small windows above open into loft area. #36: Original end chimneys removed, one clearly visible on south facade. Interior: two staircases, log portion enclosed with closet beneath. Interior has been modified, walls plastered and papered.  3 Missiory and Significance  According to 1877 Ray County Atlas, this property was already in the Wild family. It appears to have been vacated relatively recently.  4 Description of Environment and Outbuildings  Rural environment. Two barns to rear of property in deteriorated condition.  5 Sources of Information  On-site inspection.  Ray County Atlas, 1877.  46 Prepared by Jim Pease  47 Organization RCHS & M  48 Date 49 Revision Date(s)				Frontage on Road
ogtrot log cabin with frame addition to rear and to north end, of slightly later period. Two entrances on primary facade of original building, with windows to right. Small windows above open into loft area. #36: Original end chimneys removed, one clearly visible on south facade. Interior: two staircases, log portion enclosed with closet beneath. Interior has been modified, walls plastered and papered.  3 Missiony and Supprissionce  According to 1877 Ray County Atlas, this property was already in the Wild family. It appears to have been vacated relatively recently.  4 Description of Environment and Outbuildings  Rural environment. Two barns to rear of property in deteriorated condition.  5 Sources of Information  On-site inspection.  Ray County Atlas, 1877.  46 Prepared by Jim Pease  47 Organization RCHS & M  48 Date 49 Revision Date(s)	2 Further Description of	moortant Features		
slightly later period. Two entrances on primary facade of original building, with windows to right. Small windows above open into loft area. #36: Original end chimneys removed, one clearly visible on south facade. Interior: two staircases, log portion enclosed with closet beneath. Interior has been modified, walls plastered and papered.  3 Missiory and Significance According to 1877 Ray County Atlas, this property was already in the Wild family. It appears to have been vacated relatively recently.  4 Description of Environment and Outbuildings Rural environment. Two barns to rear of property in deteriorated condition.  5 Sources of Information On-site inspection. Ray County Atlas, 1877.  46 Prepared by Jim Pease Acrondation RCHS & M  48 Date 49 Revision Date(s)			on to rear and to north end, of	
building, with windows to right. Small windows above open into loft area. #36: Original end chimneys removed, one clearly visible on south facade. Interior: two staircases, log portion enclosed with closet beneath. Interior has been modified, walls plastered and papered.  3 History and Supulicance According to 1877 Ray County Atlas, this property was already in the Wild family. It appears to have been vacated relatively recently.  4 Description of Environment and Outbuildings Rural environment. Two barns to rear of property in deteriorated condition.  5 Sources of Information On-site inspection. Ray County Atlas, 1877.  46 Prepared by Jim Pease 47 Organization RCHS & M 48 Date 49 Revision Date(s)	slightly later per	iod. Two entranc	ces on primary facade of original	
According to 1877 Ray County Atlas, this property was already in the Wild family. It appears to have been vacated relatively recently.  Description of Environment and Outbuildings Rural environment. Two barns to rear of property in deteriorated condition.  Sources of Information On-site inspection.  Ray County Atlas, 1877.  Ray County Atlas, 1877.	building, with win	dows to right.	Small windows above open into loft	Short .
Closet beneath. Interior has been modified, walls plastered and papered.  3 History and Significance  According to 1877 Ray County Atlas, this property was already in the Wild family. It appears to have been vacated relatively recently.  4 Description of Environment and Outbuildings  Rural environment. Two barns to rear of property in deteriorated condition.  5 Sources of Information  On-site inspection.  Ray County Atlas, 1877.  46 Prepared by Jim Pease  47 Organization RCHS & M  48 Date 49 Revision Date(s)				Photo
According to 1877 Ray County Atlas, this property was already in the Wild family. It appears to have been vacated relatively recently.  Description of Environment and Outbuildings  Rural environment. Two barns to rear of property in deteriorated condition.  Sources of Information On-site inspection.  Ray County Atlas, 1877.  46. Prepared by Jim Pease 47. Organization RCHS & M 48. Date 49. Revision Date(s)				and /
According to 1877 Ray County Atlas, this property was already in the Wild family. It appears to have been vacated relatively recently.  Description of Environment and Outbuildings  Rural environment. Two barns to rear of property in deteriorated condition.  Sources of Information On-site inspection.  Ray County Atlas, 1877.  46. Prepared by Jim Pease 47. Organization RCHS & M 48. Date 49. Revision Date(s)	Leneath. 1	interior has been	modified, waits plastered and paper	ered.
appears to have been vacated relatively recently.  4 Description of Environment and Outbuildings  Rural environment. Two barns to rear of property in deteriorated condition.  5 Sources of Information On-site inspection.  Ray County Atlas, 1877.  46 Prepared by Jim Pease 47 Organization RCHS & M 48 Date 49 Revision Date(s)	3 History and Significance	e e e e e e e e e e e e e e e e e e e		
A Description of Environment and Outbuildings  Rural environment. Two barns to rear of property in deteriorated condition.  Sources of Information  On-site inspection.  Ray County Atlas, 1877.  46 Prepared by Jim Pease  47 Organization RCHS & M  48 Date 49 Revision Date(s)	According to 1877	Ray County Atlas	, this property was already in the	Wild family. It
Rural environment. Two barns to rear of property in deteriorated condition.  Sources of Information On-site inspection.  Ray County Atlas, 1877.  Atlas, 1877.  Ray Dale 49 Revision Date(s)	appears to have be	en vacated relat	ively recently.	
Rural environment. Two barns to rear of property in deteriorated condition.  Sources of Information On-site inspection. Ray County Atlas, 1877.  Ray County Atlas, 1877.  About the property in deteriorated condition.  46 Prepared by Jim Pease 47 Organization RCHS & M 48 Date 49 Revision Date(s)				
Rural environment. Two barns to rear of property in deteriorated condition.  Sources of Information On-site inspection. Ray County Atlas, 1877.  Atlas, 1877.  Ray Dale 49 Revision Dale(s)	I Description 1.5	**		
Sources of Information  On-site inspection.  Ray County Atlas, 1877.  46 Prepared by Jim Pease  47 Organization RCHS & M  48 Date 49 Revision Date(s)			•	
On-site inspection.  Ray County Atlas, 1877.  Ray County Atlas, 1877.  46 Prepared by Jim Pease  47 Organization RCHS & M  48 Date 49 Revision Date(s)	Rural environment.	Two barns to re	ear of property in deteriorated co	ndition.
On-site inspection.  Ray County Atlas, 1877.  Ray County Atlas, 1877.  46 Prepared by Jim Pease  47 Organization RCHS & M  48 Date 49 Revision Date(s)				
Un-site inspection.  Ray County Atlas, 1877.  Ray County Atlas, 1877.  AB Date 49 Revision Date(s)	Sources of Information			7
Ray County Atlas, 1877.  RCHS & M  48 Date 49 Revision Date(s)				Jim Pease
RCHS & M  48 Date 49 Revision Date(s)				
48 Date 49 Revision Date(s)	nay country Actas,	10//.		
				46 Date 49 Revision Date(s)



FLOORPLANS

NOT TO SCALE



PHOTOGRAPH




48 Date 4/80

49 Revision Date(s)

## Office of Historic Preservation, P.O. Box 176, Jefferson City, Missouri 65101 HISTORIC INVENTORY

1 No '2 3	32 1º	resent Name(s)	
County		Harrison Residence	
		ther Namo(s)	
3 Location of Negatives RCHS &	M	Felix West; Sally Wilkerson; Flo	oyd Smoot
6 Specific Lucation		16 Thematic Category	26 No of Stories 12
24 miles north of in		030	29. Basement? Yes II
Routes K and B, on E road; east and south		17 Date(s) or Period	No &
		1922	30. Foundation Material
	I. Township & Vicinit		concrete 65
vic. Millville; Kno		bungaloid 23	31. Wall Construction
0.0	- 4	19. Architect or Engineer unknown	brick, UD
537 T54N 3	742 N	20 0-1-1-1	32. Roof Type & Material hip with dormers-comp.
537 T54N 5	100	unknown	33. No. of Bays
N 112	- A	21. Original Use, if apparent	Front 3 Side n/a
1	1 9	residence	34. Wall Treatment
-LA	-(A	22 Present Use residence	common bond 30 61
//	14		35. Plan Shape rectang
	7	23 Ownership Public !	36. Changes Addition . ·
		Private & 24. Owner's Name & Address,	(Explain Altered Kin M42) Moved
		if known	37 Condition
9 Coordinates U	JTM	Forrest B. Harrison	Interior excellent
Lat		Hardin, Missouri	Exterior excellent
Long		25 Open to Yes I i	38. Preservation Yes
Site 1 i Building ix	Structure 1;		Underway? No X
	Object	20 Local Contact Person or Organization	39 Endangered? Yes !!
Pingister? No IX	12 Is II Yes Ki Eligible? No I I		By What? No X
3 Part of Estab Yes II	14. District Yes I !	_ 27. Other Surveys in Which included	
Hist Dist.? No IX	Potent'l? No k	N .	40. Visible from Yes X Public Road? No
15 Name of Established Dis	strict		41. Distance from and
			Frontage on Road
42 Fuelbas Deseries			
Bungalow features do	ormers on each	dacade, variety of window sizes, all	
-over-1 lights sash	nes. Built-in	porches on primary and west facades	
with brick piers, st	tuccoed arches.	Limestone lugsills and capping of	
porch railing, also	of brick. Por	ch stairway has concrete urns.	Photo
entral brick dhimne	ey. Interior ha	as large hall with granite fireplace	
loors lead from hall	surmounted with	n large keystnne. Bevelled glass n which has original chandeliers.	
		which has original chandellers.	
History and Significance wilt by Frlix Wilt	in 1022 the he		
team of horses from	Cowgill Misson	ouse was a showplace for the county,	Bricks were hauled by
show rings. House w	vas built during	uri. Wilt showed prize cattle, in he equinox and sets true east and wes	parn on property remain
ATTO TITE MITTE T	river in rue our	ement until the house was finished	Manager and the state of the st
Cambrege of the A Telligh	neu in the base	ement and refused to mess up their r	ew home later (and)
Private de Citationille	The sure Contoning that		
Surrounded by typ	oical farm build	lings, the house is in the midst of	acres of farmland
			a a a a a a a a a a a a a a a a a a a
Sources of Information ersonal knowledge o	f cumous		46. Prepared by
	r surveyors.		46. Prepared by Miller, Bright, Cameron
darrison family.			

On-site inspection.



FLOORPLANS

NOT TO SCALE




PHOTOGRAPH

- 42. Cont. Cast iron floor registers at baseboard level are built on a slant to project heat. Oak woodwork in all rooms. Oak C-shaped staircase to second floor. Each of the four bedrooms has dormer with triple windows. Bathroom with original fixtures and built-in medicine cabinet. House originally had both soft andhard water from well. Cisterns remain on north facade. #36: Little alteration. Some new kitchen cabinets installed, wall-to-wall carpeting over hardwood floors, stairway enclosed. One upstairs closet converted to cedar closet. No exterior alteration.
- 43. Cont. house was owned by Sally Wilkerson, a widow, who sold it to her nephew Wilber Lloyd Smith. Floyd Smoot owned it next, he sold it to present owners in 1967.



No 11		nt Name(s)		79R42054	
County	The second secon	hlehem Beacon Baptist (	lhurch	1K4	
Ray	5 Other			X	
Location of Negatives RCHS & M	Bet	chlehem Christian Church	h		
		16. Thematic Category	2	8. No of Stories	one  -
Specific Location and mile north of Kr.	noxville to		2	9. Basement?	Yes I
nmarked gravel ros	d, then west	17 Date(s) or Period	-	30. Foundation Mater	
	USE UPET	1869	cable and	ashlar stone	
City or Town If Rural	Township & Vicinity	18 Style or Design	giraco -	31. Wall Construction	
Knoxville Twsp., I	MIOXATTE ATOTIC	19. Architect or Engineer	L	frame wu	25
Sie Plan warm prih Arro	Jan 1	unknown		32. Roof Type & Mail gable-asphal	t 6
	7763	20. Contractor or Builder unknown	3	3. No. of Bays	
	(,)	21. Original Use, if apparent		Front 3 S	ide 5
	2347	church ObA	3	34. Wall Treatment	63
	$\omega$	22 Present Use	1	composition s	angula
	5	church		36. Changes	Addition
		23 Ownership	Public 1! Private IX	(Explain	Altered
		24. Owner's Name & Address,		in #42)	Moved
		if known Bethlehem Beacon Bap	tist Church	37. Condition Interior 80	od
Coordinates	UTM	Bethlenem Beacon Day		Exterior exce	
Lat		25. Open to	Yes 00	38. Preservation	Yes
Long	Structure 1 i	Public?	Noll	Underway?	No
Site 1 : Building 10	Object	26. Local Contact Person or Org	ganization	39 Endangered?	Yes
On National Yes II	12 Is II Yes DO			By What?	140
Register? No 00	Eligible? No 11	27. Other Surveys in Which Incl	luded	40. Visible from	Yes
Part of Estab Yes	14. District Yes     Potent'l? No 10			Public Road?	No
5 Name of Established D				41. Distance from an Frontage on Roa	
5 Maille Of Established D	•		1	riontage on no	
with raised char entranceways on neoclassic windo glass transoms. and wainscoting The church has	the primary faca- by lintels. Door Interior featur along all origin been radically al	urch was originally a sign at rear. It features de. Windows are double seach have large recta es an outstanding panel al walls of the structutered recently, although	chung, with angular clear alled celling, are. #36.: the ceiling and	Photo	
		and the second of	menniged in S	entember, 1868.	Amon
its first member building was er	ers were J.D. Gord ected in 1869 and	Christian Church was of lon, A. Moss, R. Moss, a d dedicated in 1869 by l B. Peeler. In 1875 a d members on the subject	William Morto	n and Anderson	Picker out of
4 Description of Environ					
	surrounded by	farmland.	559.51		
5 Sources of Information	0			46. Prepared by	
Mrs. Mary Richa				Richardson &	Camero
				47. Organization RCHS & M	
Ray County His	tory, 1881.			48. Qale 49 Revi	sion Date
On-site inspec	tion.			8/79	



FLOORPLANS

NOT TO SCALE



PHOTOGRAPH

- #42. Con't. wainscoting were retained and restored. Outside, a new neoclassic porico supported by large wooden columns was constructed, and a modern triple window added between the two entrances. New siding was applied and an addition added to the rear of the structure. On the interior, carpeting was applied over the old floor, and new rooms partitioned off in the south end for a nursery and offices. The church was completely refurnished with modern pews and altar, and a balcony was added on the south end. The stairway to the balcony obsures one window.
- #43. Con't. drew and built their own sanctuary, which they called the "House of Prayer."

  Later the Christian Church at Bethlehem became inactive, and the property

  was acquired by private citizens. Recently the church building was

  purchased by the Bethlehem Beacon Baptist Church who began extensive

  restoration and remodelling. On June 12, 1977, the Beacon Baptist Church

  was officially dedicated.



Office of Historic Preservation, P.O. Box 176, Jefferson City, Missouri 65161

HISTORIC INVENTORY

1 No 27	4 Prese	ent Name(s)		
701,		Dean Carter Residence		
Ray	5 Othe	r Namo(s)		
3 Location of Negatives RCHS		Cummins House;		
		16 Thematic Category		28 No of Stories 7 - 1%
6 Specific Lucation Hywy 13 north to Ro	Hwy B			29. Basement? Yes II
Hywy 13 north to Ro	are v, west to	17 Date(s) or Period		No &
Route BB, 3/8 mile	past 90% turn.	ca. 1870		30. Foundation Material ashlar stone 40
7 City or Town If Rura	I. Township & Vicinity	18 Style or Design	99	31. Wall Construction
	oxville twp.	vernacular, Gothic Revi	val det.	frame WU
8 Site Plan with North Arr	ow		ì	32. Roof Type & Material GB
		20. Contractor or Builder		gable-asphalt shingles
(177.172)	A	MadisonCummins		33. No. of Bays Front 3 Side
		residence OP		34. Wall Treatment
		residence 277		weatherboard 21
	4	residence		35. Pian Shape rectangular
		23 Ownership	Public 1 1	36. Changes Addition X
			Private &	(Explain Altered X:
	1 1.	24. Owner's Name & Address,		11 11 11 11 11 11 11 11 11 11 11 11 11
		il known		37 Condition excellent
9 Coordinates	UTM	Dean Carter		Exterior excellent
tal SI9 T	54N 28W	Knoxville, Missouri 25. Open 10	Yes II	38. Preservation Yes
	Structure 1 i	Public?	Noti	Underway? No x
Site 1 1 Building XI	Object	26. Local Contact Person or Organ	nization	39 Endangered? Yes
11 On National Yes !!	12 Is It Yes IX			By What? No χ
Register? No K.	14. District Yes II	27. Other Surveys in Which Includ	90	40. Visible from Yes χ
Hist Dist.? No X	Potent'l? No lx			Public Road? No ::
15 Name of Established C	District			41. Distance from and Frontage on Road
	•			
42. Further Description of	Important Features			
			a fa i ua m fa i t	
Gothic Revival det	ailing is present	t in two wall dormers on p	to	
facade; central ent	rance on primary	elevation; large addition tchen and diningroom. In	terior	Photo
has been areatly n	emadelled Still	retains original plaster	walls;	
wains coting remove	d. New floors we	ere addition upstairs, al	so closet	
installed.	O .			1
43 History and Significan	CG			
		hate wast Change hataush	NC in D	827 He came to Ray Co
House was built by	madeson cummens,	, born near Greensborough ed the gold rush to Calif	ornia and	romained there until the
alose of the Civil	Wan Ho thon no	eturned to Ray Co. perman	ently and	ourchased this farm of
close of the chill	. word the wient the	constitution in the production of the production	1	

44 Description of Environment and Outbuildings

Surrounded by farmland, root cellar to rear of house. Modern garage to east of house.


656 acres, and raised stock. He married Margaret Smith, also of N.C., in 1867.

45 Sources of Information Ray County Atlas, 1877. Mr & Mrs. Dean Carter On-site inspection.

46. Prepared by Richardson

47. Organization RCHS & M

49 Revision Date(s) 48. Date



FLOORPLANS

NOT TO SCALE




PHOTOGRAPH



Nu 38	4 Pre	Serit Name(s)	
2 County		C.O. Branstetter, Jr. House	
Ray 3 Location of Negatives	5 Oth	ner Namo(s)	
RCHS			
6 Specific L-postion	CRE	16 Thematic Category	28 No of Stories ]-1/2-1
2-1/2 mi. north of	Rayville on coun		29. Basement? Yes Ki
road C; north and e gravel road 1 1/2 m	ast on unmarked	17 Datu(s) or Period	partial No:
	al, Township & Vicinity	ca. 1889	30. Foundation Material
vic. Rayville Knox	wille twp.	18 Style or Design Gothic Revival 41 09	ashlar stone 31. Wall Construction
8 Sile Plan with North Ar		19. Architect or Engineer	frame .
	8	unknown	32. Roof Type & Material GB
	- 19	20. Contractor or Builder	<u>qable-asphalt shingles</u>
1)	WWI S	21. Original Use, If apparent	33. No. of Bays Front Side 3
		residence QA	17d 15/-
( ) TIME		22 Present Use	weatherboard
		residence	35. Plan Shape rectangular
		23 Ownership Public I Private X :	36. Changes Addition Y
•		24. Owner's Name & Address.	in #42) Moved
		if known	37 Condition fair
9 Coordinates	UTM	C.O. Branstetter, Jr.	Interior
Lung			Exterior fair.
Site 11	Structure 1 i	25 Open to Yes I I Public? No X I	38. Preservation Yes Underway? No X
Building :X	Object I I	26. Local Contact Person or Organization	39 Endangered? Yes 11
11 On National Yes I I Register? No IX	12 Is It Yes XI Eligible? No I I	27. Other Surveys in Which Included	By What? No X
13 Part of Estab Yes I I Hist Dist.? No IX	14. District Yes I Potent'l? No XI	The state of the s	40. Visible from Yes X Public Road?
15 Namu of Established D	istrict		41. Distance from and Frontage on Road
			Promage on Road
42 Further Description of	important Features		
Windows are capped	entral entrances with molded linte	classic detailing. Vernacular in forming doublepen vernacular houseels, all 2/2 double hung asash.	Photo
Primary racade domin	nated by three re	egularly, high nitched gables	
riain Trieze surrou	nds the structure	e. broken by gable windows Corner	\$ /
		story addition to rear of house.	
43 History and Significance			
Gothic style inspire	ed_dormer detail	is uncommon for Ray County. House	was built by the Rev
44 Description of Environm	a difficil differ	I many years later. He was married.	d at 23 to (cont)
	_		
Surrounded by farmla	and. Some origin	iai piantings.	
45 Sources of Information			
On-site inspection.			46. Prepared by
,			Cameron  47 Organization
			PCHS & M
			48 Date 49 Revision Date(s)
		\	6/80

#43. Cont. Elizabeth Stewart, and they had 5 children. His wife died in 1848, while the family lived at Lexington. That winter, William bought this farm in Ray County and married Mary Lefevre in 1849. They had 15 children, 12 of whom survived. The family moved several times in Ray County. In 1852, William joined the Missionary Baptist Church at Pleasant Valley and he was ordained in 1872. He preached throughout the area, but principally in Ray County. He died here in 1879 and was buried on the farm. His wife Mary Lefevre Mullin is listed in the 1897 atlas as the owner of the farm. J.C. Isley was the owner in 1914, when the farm was on the outskirts of the short-lived Mineral City, established as a resort area about that time.



FLOORPLANS

NOT TO SCALE



**PHOTOGRAPH** 




ssouri 65101

Office of Historic	Preservation.	P.U. BOX	176,	Jefferson	City.	Mis
HISTORIC	INVENT	ORY				

29 <b>29</b> 4 Presen	Tate Residence	
Ray 5 Other or Acquires RCHS	Name(s)	•
coordinates  Site!  Building by  Structure!  Structure!  On National Yes!!  12 Is It Yes to It and It all It	17 Date(s) or Period ca. 1880  18 Style or Design Vernacular/Neoclassic  19. Architect or Engineer unknown  20. Contractor or Builder unknown  21. Original Use, if apparent residence 22 Present Use residence 23 Ownership  24. Owner's Name & Address, if known George Tate Richmond, Missouri  25. Open to Public?  26. Local Contact Person or Organization  27. Other Surveys in Which Included	28. No of Stories ond  29. Basement?  30. Foundation Material Coursed rubble stone  31. Wall Construction frame  32. Roof Type & Material Gable-asphalt shingles 33. No. of Bays Front Side  34. Wall Treatment Clapboard  35. Plan Shape L-shape  36. Changes (Explain in #42)  37. Condition Interior fair Exterior fair to poor  38. Preservation Underway?  39. Endangered? By What?  No i  neglect  40. Visible from Public Road?  41. Distance from and

entry closed. Neoclassic elements include corner boards, boxed cornice and frieze surrounding building. Recent asymmetrical porch addition to primary facade. Rear ell is fronted by shed roofed veranda running the length of the facade. #37: House is at present in fair condition, still occupied, but suffers from neglect.



43 History and Significance

44 Description of Environment and Outbuildings


Rural environment. Original plantings fronting property. More recent farm outbuildings the rear of the house.

45 Sources of Information

46. Prepared by

47. Organization

48. Date 49 Revision Date(s)



FLOORPLANS NOT TO SCALE




PHOTOGRAPH



4. Present Name(s)

1 No.	30 1 Pis	sent Name(s)		
2 ( Ny .	-	Hillcrest Farm		
Ray	5 01	ner Name(s)		
3 Location of Negatives RCHS	5 & M	Wickstrom Residence; Proffitt	Residence	
Route B north of I	Richmond to inter	16. Thematic Category	28. No. of Stories two 2-1-1	-
section of Route	K; east on K to		29. Basement? Yes 🕅	
Route E; south 1/2 1		17 Date(s) or Period	partial No:	
7 City of Town II Rui	ral, Township & Vicinity	1896 18 Style or Design	30. Foundation Material ashlar stone	'
vic. Millville; Kr	moxville twp.	vernacular 49	31. Wall Construction	
H Site Plan with North A		19. Architect or Engineer	frame Wu	
513 T53 N R 2	N N	unknown		4
V/////	199	20. Contractor or Builder Ernest Misel & Henry Macey	gable-asphalt shingles 33. No. of Bays	
V/////	MA AN	21. Original Use, if apparent	Front 3 Side 1	
	9	residence O/A	34. Wall Treatment 64	res
		22 Present Use residence	asbestos shingles	100
12/17/			35. Plan Shape rectangular	Present Name(s)
	-	23 Ownership Public I !	36. Changes Addition X. (Explain Altered	T CH S
		24. Owner's Name & Address,	in #42) Moved :	
0.6		Dennis & Clara Wickstrom	37. Condition good	
9 Coordinates	UTM	Hardin, Missouri		
Long		25. Open to Yes ! !	38. Preservation Yes	
10 Site!! Building Ki	Structure 1 i	Public? No 1x	Underway? No K	
11 On National Yes II	Object   1	26. Local Contact Person or Organization	39. Endangered? Yes !! By What? No !X	
Register? No ix	12. Is It Yes 1x Eligible? No 11	27. Other Surveys in Which Included	By What?	
13 Part of Estab Yes I.I Hist Dist 2 No IX	14. District Yes I I	The state of the s	40. Visible from Yes x	
Hist Dist? No IX	Potent'l? -No IX		Public Road? No 1:	
	nsinci		41. Distance from and Frontage on Road	
exterior and inter	has been nearly rior alterations. One brick inter	obscured with additions and Additions obscured both primary rior chimney removed, other clos	Sed. Photo	5 Other Name(s)
It was then owned remodelled, adding	r and Elizabeth F by Glenn Wickstro rear addition an	in 1896 and he lived in the house of the control of	d Emma Bowman until 1950. In 1968 the house was	
44 Description of Environm	nent and Outbuildings	of one same raming	, TOL ) generations.	
On working farm, n	o outbuildings exc	ept garage.		
15 Sources of Information				
Geneva and Glann W	ickstrom.		46. Prepared by Clara Allison	
Present owners.			47. Organization	
Personal knowledge On-site inspection	of surveyor.		RCHS & M	
	•		48. Date 49 Revision Date(s) 5/79	
			1 2/17	



FLOORPLANS


NOT TO SCALE



PHOTOGRAPH



-No		sent Name(s)	
2 County		Bright Residence	
Ray	5 01	her Namo(s)	
3 Location of Negatives RCHS	& M	Shreve Farm	
6 Specific Lucation		16 Thematic Category	28 No of Stories LWO
12 miles northeast	t of Richmond		29 Basement? Yes X
- Malville Herry	F.	17 Datu(s) or Period	partial No
	al. Township & Vicinity	1904 alt 1948 0000	30. Foundation Material
vic. Richmond	twp. Knoxville	18 Style or Design Vernacular	concrete block 65
8 Site Plan with North Ar		19. Architect or Engineer	frame (A)
	0	unknown	32 Roof Type & Maleual Cal
3	UN	20. Contractor or Builder	gable-comp. shingles
		21. Original Use, If apparent	33. No. of Bays Front 4 Side 7
-Allilli	THE PARTY OF THE P	residence O	34. Wall Treatment
		22 Present Use residence	comp. siding 63
			35. Plan Shape rectangular
	丁、	23 Ownership Public I ' Private IX	36. Changes Addition X (Explain Altered X)
3	63	24. Owner's Name & Address.	in #42) Moved i
W Sas Ts	wrest cit	if known	37 Condition
9 Coordinates	UTM	Mrs. Herbert Bright	Interior good
Luny	•	RR 4 Box 58, Richmond, Missouri	
Site 1 : Building (X)	Structure 1 : Object 1 :	Public? No ly	38. Preservation Yes Underway? NoX
11 On National Yes II	12 Is II Yes IX	26. Local Contact Person or Organization	39 Endangered? Yes III
Register" No IX	Eligible? No 11	27. Other Surveys in Which included	-
Hist Dist.? No ly	14. District Yes II Potent'l? No IX		40. Visible from YesX
15 Name of Established D		1	Public Road? No :
			Frontage on Road
42 Further Description of	important Features		
Vernacular house ha	as Neoclassic de	tails. First story of primary	
racade has two room	ms.each with lare	de window and entrance from nonch	
Two rooms above each	ch have one windo	ow with Neoclassic molding 1-over	Photo
story. Originally	ondary facades ha	ave similar windows, 1 at each	
	ains. Interior b	rick stove chimneys, both now as original panelled doors and	
uaruware, entrance	doors half glass	s. #36 Addition of kitchen in 1948.	
The state of the state of	6		
it was bought by la	ed this place Ser	otember 11, 1829 from U.S. Governmen	nt. After changing hands
. a was bouding by of	THES LATE IN TOV.	He died in 1902 leaving it to the James H. Shreve. The house was but	
1948 a partial base	ement was dug and	the front and back porches enclose	Allt about 1904. In
44 Description of Environm	nent and Outbuildings		.a. Starting was added.
		al outbuildings and shade trees of	ovicinal alasti
7.1.9 1.41111 3	a ounded by usu	ar outburidings and shade trees of	original plantings.
45 Sources of Information			
Abstract.			46. Prepared by
			Merle Bright
Personal Knowledge. On-site inspection.			RCHS & M
on site Thebection.	E.K. Hall.		48 Date 40 Bausian Date



FLOORPLANS


NOT TO SCALE



PHOTOGRAPH



1 No	27 1 Pre	sent Name(s)	
nunly		Coats Residence	
Ray  3 Location of Negatives	5 011	ner Namo(s)	
RCHS	& M		
6 Specific Lucation		16 Themelic Calegory	28 No of Stories two
Route B northeast	of Richmond to		29. Basement? Yes I
intersection of K east on K to inte	then la miles	17 Date(s) or Period	No is
	al. Township & Vicinity	ca. 1917	30. Foundation Material
vic. Millville; K	noxville twp.	vernacular: Neoclassic details	ashlar stone 40
8 Sile Plan with North Ar	row	19. Architect or Engineer	frame Wu
HWYE	Y	unknown 20. Contractor or Builder	32. Roof Type & Material Gas
T5310 07W	_ 6	unknown	saltbox; asphalt shing
	-b 4	21. Original Use, if apparent	33. No. of Bays Front 3 Side n/a
0	_	residence orA	34. Wall Treatment
1)		22 Prement Use regidence	metal siding 50
		23 Ownership Public !	35. Plan Shape rectangular
3 G	3	Private x I	36. Changes Addition . (Explain Altered X
(1) (2)	$\omega$	24. Owner's Name & Address,	In #42) Moved
9 Coordinates	UTM		37 Condition
Lat	91m	William D. Coates Hardin, Missouri	Interior good
Lung		25. Open to Yes Li	38. Preservation Yes
Site 1 i Building ix	Structure 1 i	Public? No IX	Underway? No X
II On National Yes II	12 Is II Yes XI	26 Local Contact Person or Organization .	39 Endangered? Yes i
Augister? No IX	Eligible? No i i	27. Other Surveys in Which Included	By What? No X
Hist Dist.? No IX	14. District Yes I   Polent'l? No X	The state of the s	40. Visible from Yes X
15 Name of Established D			Public Road? No
		·	41. Distance from and Frontage on Road
40 5 40			
Exterior of house	mportant Features has been greatly	remodeled, with addition of metal	
	TYTHAT ALCHITECT	HIGH HEIGHTS LONTHS INTERSELL	
entrance with doub	le window above.	Salt boy roof unusual for and	
original woodwork:	C-shaped staires	hes have been added. Interior has se with plain banisters. Original	Photo
TITCHIACE AND TIGHT	, lixtures, #3h:	Some ceilings amp lowered	
Original kerosene b	ourner for hot wa	ter; wood furnace.	
43 History and Significance			
Alney K. Russell wa	s born August 17	, 1875 in Ray County. In 1898 he	migrated to Oklahoma
TO THE STATE OF TH	CHELECHE MEL AM	I IIIdrried Wilners Wasy of Tonness	The second second
44 Description of 5	and salesman.	He died in 1936. The farm and hou	Rtyerengunghasedbind 1969
44 Description of Environme	ent and Outbuildings		
On a working farm w	ith several outb	uildings surrounding the house. A	
ard family remains	in the rear.	A	nouse for a hired man
5 sources of Information			
Carolyn Coates.			46. Prepared by Miller and Cameron
Ray County History,	1973.		47 Organization
On-site inspection.			RCHS & M
on-site inspection.			48 Date 49 Revision Date(s)
			6/80



FLOORPLANS

NOT TO SCALE




PHOTOGRAPH



48 Date 49 Revision Date(s)

1 No	00	4 Present Name(s)		
:ounty		Parker Ho	use	
Ray		5 Other Namo(s)		
3 Location of Negatives RCHS	<b>►</b> M			
6 Specific Lucation	X M	CON CONTRACTOR		
From Millville on	Route K.	ake 030	.alegory	28 No of Stories One
unmarked gravel re			Period	29. Basement? Yes I No IX
CR		1908		30. Foundation Material
7 City or Town II Rus	al. Township &		ngien A E	ashlar stone 90
Vic. Millville, Kı		Oueen Ann	e. Neoclassic details:	31. Wall Construction
8 Sile Plan with North Ar	row	19. Architect o	r Engineer Other	frame wu
		20. Contractor	or Builder	32. Roof Type & Material CM
		Albert Pe		complex gable-comp. 63
AY		21. Original Us		33. No. of Bays Front N/a Side N/a
		residence	OA	34. Wall Treatment
41		22 Present Us		clapboard of
		residence		35. Plan Shape irregular
	•	23 Ownership	Public 11 Private IX	36. Changes Addition
	•	24. Owner's Na	ome & Address.	(Explain Altered is in #42) Moved i
		if known		37 Condition
9 Coordinates	UTM	Carl Park		Interior excellent
Lat Son T53	NRATH		TSSOUP I	Exterior excellent
		25 Open to	Yes II	38. Preservation Yes
Site Li Building iX		lore i .	κι οΝ	Underway? NoX
II On National Yes II	12 Is II	Yes XI	act Person or Organization	39 Endangered? Yes II By What? No X
Angister? No IX	Eligible?		ys in Which Included	by what:
13 Part of Estab Yes II	14. District	Yesii	,, o viner included	40. Visible from Yes X
Hist Dist.? No IX	Potent'1?	No XI		Public Road? No
15 Namu of Established Di	strict	N.		41. Distance from and
				Frontage on Road
12. Further Description of I	mportant Featu	0.5		
gables sheathed w lunette in its cer heads. Molded corr pediments on all of house has outs woodwork with row	ith fishscanter. Pilanice and partice and partice and partice and partice or so of denti	le shingles. Pri ster corner board ain frieze contin nterior brick sto ginal woodwork:	, window types. All mary facade has diamond s, trabeated window ue across gable forming ve chimneys. Interior handcarved clock shelve paneled doors and (cont	Photo
nouse was Albert	is obscure Pence, a lo	cal craftsman.	y were first occupants.	Carpenter of the
14 Description of Environme	ent and Outbui	lings		
On a working farm	. Usual o	tbuildings.		
5 Sources of Information				
				46. Prepared by
Mrs. Earl Miller,		carpenter.		Miller and Cameron
Mrs. Parker, occup	oant.			47 Organization RCHS & M
	1.			INTELLED BY IT



**FLOORPLANS** 

NOT TO SCALE



PHOTOGRAPH

42. Cont. hardware remain. Etched glass in door of primary entryway. Original doorbells remain as well. #36: Front porch has had original posts replaced with cast iron. New gas stove. Carpeting and linoleum in some rooms.

43. Cont.




48. Date 6/79

49 Revision Date(s)

4. Present Name(s)

1 No. 3 14	4 Pre	sent Name(s)	
2 ly		McElwee General Store	
Ray	5 OII	ner Namo(s)	
3 Location of Negatives	40		
RCHS &	M		
6 Specific Location	•	16. Thematic Category	28. No. of Stories one/-/
4	TEAN JAW	17 Date(s) or Period	29. Basement? Yes ! ! No X.
/	CR	CA. 1900	30. Foundation Material
7 City or Town II Burn	al, Township & Vicinity		rubble stone
Taitsville Know		vernacular 6/	31, Wall Construction
8 Site Plan with North Ari	row	19. Architect or Engineer	frame Wu
tenne	N N	unknown	32. Roof Type & Material GR Pe
		20. Contractor or Builder unknown Aw	gable-tin 33. No. of Bays
1-1	WATER TO	21. Original Use, if apparent OSF 04 H	
		general store, post office	34. Wall Treatment
	9	22 Present Use	weatherboarding
	,	vacant	35. Plan Shaperectangular
		23 Ownership Public 11	36. Changes Addition €
		Private M  24. Owner's Name & Address,	(Explain Altered I in M42) Moved I
	•	if known	37. Condition
9 Goordinates 1	UTM	Gene and Joanne McElwee	Interior fair
Lat		Taitsville, Missouri	Exterior fair
Long		25. Open to Yes !! Public? No M	38. Preservation Yes
10 Site ! i Building iX	Structure 1 i	110 (1	Underway? No X
11 On Nutional Yes II	12. Is It Yes IJ	26. Local Contact Person or Organization	39. Endangered? Yes 🕅 By What? No !
Register? No IX	Eligible? No M	27. Other Surveys in Which Included	neglect
13 Part of Estab Yes I.I	14. District Yes I	The street surveys in which included	40. Visible from Yes %
HIST DIST? NO IX	Potent'l? - No XI		Public Road? No 1:
15 Name of Established Di	strict		41. Distance from and
			Frontage on Road
42 Further Description of I	moortant Features		
		addition on north. Front facade	
		6-over-6 windows. Door has mail	
		ginal store counters remain as does	Photo
		lain knobs on doors. 2 light	
		aly minor alterations but condition	
		Pigeon hole cupboards have been ank floor in places.	
13 History and Significance		din 11001 in places,	
Built probably	by Oliver McElwee	. This is the last of the many st	tores which once made
		It was run as a general store an	
		ok over. Fred continued the store	
		1979. It has since been vacant and	d used for storage by
the McElwee fam	ent and Outbuildings		
In defunct town	of Taitsville.	Two residences in close proximity.	No outbuilding.
-			
			ĺ
5 Sources of Information			46. Prepared by
Joanne McElwee.			Cameron & Richardson
Mary Richardson			47. Organization
Ray County Histo	DEY. 19/3.		RCHS & M

On-site inspection.



FLOORPLANS NOT TO SCALE



PHOTOGRAPH




Office of Historic Preservation, P.O. Box 176, Jefferson City, Missouri 65101
HISTORIC INVENTORY

1 No 1 137	4 Present Name(s)	
2 County	Gordon House	
Ray	5 Other Name(a)	
3 Location of Negatives		
RCHS & M		
Specific Lucation 2mi. east of Orrick city lin	16 Thernalic Category	26 No of Stories one /-/
unmarked gravel road just be	of one DD	29. Basement? Yes I
	- Carago or vertous	No t
	ca, 10)4 and ca, 10/0	30. Foundation Material
vic. Orrick Orrick twp.	pioneer/vernacular -Neoclassi	
B Bitel Plan with North Arlow	19. Architect or Engineer	log and frame
111 6	unknown	20 01 7 0 11
	20. Contractor or Builder	gable-comp, shingles
's (	Benjamin Gordon	.63
	21. Original Use, If apparent	Front 5 Side 4
	residence D/A	34. Wall Treatment
7 4	residence	weatherboarding
	23 Ownership Public	35. Plan ShapeL-shaped
	Private	The state of the s
H	24. Owner's Name & Address.	in #42) Moved i
	Lenice Irons, Orrick Mo.	37 Condition
Lat SC 5/N 280	Alline Boath, Kansas City, Mo.	Interior good
Long	25. A	Exterior good .
Site Li S	25 Open to Yes Public? No	162
Building iX	Object     26 Local Contact Person or Organization	
11 On National Yes II 12 Is II	Yes IX	By What? Yes I
Ringister? No IX Eligible	27. Other Surveys in Which included	
Hist Dist.? No DC Potent	ct Yes!!	40. Visible from Yes 12
15 Name of Established District	11: 110 14	Public Road? No
to the or college brainer		41. Distance from and Frontage on Road
42 Further Description of Important Fe	log house; central doorway flanked by w	
and loft area ventilated by	two small windows on either side of chir	indows
Central hall house added to	one side. %-bay Neoclassic primary face	mney.
with Neoclassic window heads	interior brick stove chimneys. #36:	Photo
Stone chimney removed from 1	log portion and single room divided. How	use
has been modernized but not	greatly altered.	
43 History and Significance		
The land was granted to Benj	jamin Gordon by Franklin Pierce, dated O	ctober 2, 1854.
There was a log structure al	ready on the land which Gordon appropris	ated for his family.
about 1870, a two room house	was added to one side. The house has	remained in the Gordon
amily, is owned now by two	sisters, one of whose grandson lives in	the house.
44 Description of Environment and Out	buildings	
on a working farm, with mode	ern outbuildings. Root cellar to the rea	r of house constructed
	y south of the house has stones dating f	
and grant of property.		A6 Promound t
dea Landa Trans	·	46. Prepared by

Mrs. Lenice Irons.

Family documents. On-site inspection.

Cameron, Ogg, Brown 47 Organization RCHS & M 46 Date 8/80 49 Revision Date(s)



FLOORPLANS



NOT TO SCALE




PHOTOGRAPH





5/80

1 No 107 17	LA Orm	sent Namo(s)	
127 13	8	Wholfe Residence	
Ray	5 OIN	er Namo(s)	
3 Location of Negatives RCHS & M			
6 Specific Lucation		16 Thematic Category	28 No of Stories 11/3
2½ miles north of 0		030	29. Basement? Yes II
0, second house on		17 Date(s) or Period ca. 1840; 1870	No 1 X
**	Township & Vicinity		30. Foundation Material brick 30
vic. Orrick, Orrick	twp.	vernacular, Gothic Revival 09	31. Wall Construction
B Sile Plan with North Arro	Ow 1	19. Architect or Engineer unknown	frame wu
	1/3 K	20. Contractor or Builder	32. Roof Type & Material 6B gable-comp. shingles
	14. Y 16	ulikilowii 73	33. No. of Bays 63
	1 00 49	21. Original Use, If apparent residence	Front 3 Side 1:DR
	1	22 Present Use	siding 99
	3 out	residence	35. Plan Shape T shape
	3900	23 Ownership Public I ' Private XX	. 36. Changes Addition X Altered
	C '	24. Owner's Name & Address.	in #42) Moved
9 Coordinates U	TM	Yvonne Wholfe	37 Condition and
Lat		Route 1, Orrick Missouri	Exterior good
Luny 5 10 51		25 Open to Yes I I	38. Preservation Yes
Site Li Building ix	Structure 1 :	Public? No XX  26 Local Contact Person or Organization	Underway? No X
11 On National Yes II	12 Is II Yes XI	20 Local Contact Person of Organization	39 Endangered? Yes!! By What? No X
Register? No IX	Eligible? No i'l	27. Other Surveys in Which Included	· ·
Hist Dist.? No IX	Potent'l? No Ki		40. Visible from Yes X Public Road? No
15 Namu of Established Dis	trict		41. Distance from and
			Frontage on Road
42 Further Description of Im	portant Features		
		Revival derived central gable County. Neoclassic window heads	
Two entrances, one	on each level of	f primary facade. #36: House show	
evidence of large a	dditions to nor	th and rear. New Bungalow-type	Photo
entirely remodelled	cade replaces of	riginal two story p <b>or</b> tico. Interi <b>o</b>	
	•		
43 History and Significance	have de avenue	- 17 1 - 1 - 1 - 1 - 1	
east of the house.	The north sect	sedly part of an old school that wa ion was built onto it, and an addit	s moved from a hill
William Gross owned	the land from a	grant of the government ca. 1820	and it is possible he
built (or moved) p.a	rt of the house.	. It was later acquired by the Who	lfe family, and has
remained in that fa	mily to the pres	sent.	
	_	noke houses, many large maple trees	
	5 5 7 5 6 6	, , , , , , , , , ,	
45 Sources of Information			
			46. Prepared by
Present owner.			dohn Riddle
On-site inspection.			OYPRG (RCHS & M)
on site inspection.			48 Onto 40 Do




FLOORPLANS NOT TO SCALE



PHOTOGRAPH



	59 1 1	ent Name(s)	
Ray		Townsend House	
3 Location of Negatives RCHS & M	5 Oin	Kirkpatrick; Stouffer	
Specific Lucation 3 miles north of	f Orrick on	16 Thematic Calegory	28 No of Stories two 2-2
Route 0 5 10 51 N		17 Balula) or Period	29. Basement? Yes I No X
			30. Foundation Material
Vic. Orrick Orr	ral, Township & Vicinity	Neoclassic 09	ashlar stone 40
8 Sile Plan with North Ar		19. Architect or Engineer	frame wu
		unknown	32. Roof Type & Material GB
	<b>^</b>	William Stouffer Prus R2	gable/wood shingles
~ []		21. Original Use, If apparent	33. No. of Bays Front 3 Side 3
3/	V-3	residence OIA	34. Wall Treatment
(w)	D	22 Present Use residence	watherboard
	.0		35. Plan Shape L-shape
	69/	23 Ownership Public I ! Private I K	36. Changes Addition
( )		24. Owner's Name & Address.	in #42) Moved
w/	/	Mrs. Helen Townsend	37 Condition Interior excellent
9 Coordinates	UTM	Route 1. Orrick Missouri	Exterior excellent
Long		25 Open to Yes I i	38. Preservation Yes
Site Li	Structure 1 i	Public? No XI	Underway? No X
Building 13	Object 1 i	26. Local Contact Person or Organization	39 Endangered? Yes III By What? No X
Register? No.X.	Eligible? No I I	27. Other Surveys in Which Included	by what:
3 Part of Estab Yes II Hist Dist.? No IX	14. District Yes I ! Potent'l? No Ki		40. Visible from Yes X
15 Namu of Established D	district		Public Road? No -
			Frontage on Road
42 Further Description of	Important Features		
42 Further Description of $\frac{1}{2}$ I-house with 1	large el contempor	cary with main block construction.	
½ I-house with 1 Features Neoclas	large el contempor ssic details as pi	llaster corner boards, pediment wi	ndow
½ I-house with 1 Features Neoclas heads, boxed cor	large el contempor ssic details as pi rnice and pain fri	llaster corner boards, pediment wi	af /
½ I-house with 1 Features Neoclas heads, boxed corentrance on both	large el contempor ssic details as pr mice and pain fr n levels, both wi-	llaster corner boards, pediment will leze. mary facade has single le th trnasom and sidelights. El has	af /
½ I-house with 1 Features Neoclas heads, boxed corentrance on both two story verand fireplaces. Out	large el contempor ssic details as pr mice and pain fr n levels, both wi- da, lower story ha tstanding woodwork	ilaster corner boards, pediment wileze. mary facade has single letth trnasom and sidelights. El has as been screened. Some working #36: Some fireplaces closed or	Photo
½ I-house with 1 Features Neoclas heads, boxed cor entrance on both two story verand fireplaces. Out converted to sto	large el contempor ssic details as pr mice and pain fra n levels, both wi- da, lower story ha tstanding woodwork oves. Addition of	llaster corner boards, pediment will leze. mary facade has single le th trnasom and sidelights. El has as been screened. Some working	Photo
½ I-house with 1 Features Neoclas heads, boxed cor entrance on both two story verand fireplaces. Out converted to sto	large el contempor esic details as prince and pain fri n levels, both wi- da, lower story ha tstanding woodwork oves. Addition of	ilaster corner boards, pediment wileze. mary facade has single leth trnasom and sidelights. El has as been screened. Some working at \$36: Some fireplaces closed or Bungalow-type porch replaces original.	ginal on primary facade
½ I-house with 1 Features Neoclas heads, boxed cor entrance on both two story verand fireplaces. Out converted to sto History and Supplicance House built by W	large el contempor esic details as pirnice and pain fri n levels, both wi- da, lower story ha tstanding woodwork oves. Addition of the william Stouffer of	ilaster corner boards, pediment will leze. mary facade has single leath trnasom and sidelights. El has as been screened. Some working a. #36: Some fireplaces closed or Bungalow-type porch replaces original formative lumber, mostly walnut. for mative lumber, mostly walnut.	ginal on primary facade rom trees on the propert
I-house with large reactures Neoclas heads, boxed corentrance on both two story verand fireplaces. Out converted to story and Significance House built by Wity his brother this house, taki	large el contempor ssic details as prinice and plain fri n levels, both with da, lower story hat tstanding woodwork oves. Addition of the Villiam Stouffer of r-in-law James Rich lng two years to o	llaster corner boards, pediment will leze. mary facade has single let the trnasom and sidelights. El has as been screened. Some working at #36: Some fireplaces closed or Bungalow-type porch replaces original fire and his somplete it. Stouffer was a carpet	ginal on primary facade rom trees on the propertis wife, Stouffer built
I-house with large reactures Neoclas heads, boxed corentrance on both two story verand fireplaces. Out converted to story and Significance House built by Wity his brother this house, taking and did all the interplace in the story and significance with th	large el contempor ssic details as prinice and pain fri n levels, both wi- da, lower story ha tstanding woodwork oves. Addition of the william Stouffer of r-in-law James Richard two years to of liron work for the	laster corner boards, pediment wileze. mary facade has single let the trasom and sidelights. El has as been screened. Some working at #36: Some fireplaces closed or Bungalow-type porch replaces original factive lumber, mostly walnut, fife, who lived with Stouffer and he complete it. Stouffer was a carpe house himself. Present owner is	ginal on primary facade rom trees on the propertis wife, Stouffer built
I-house with large reactures Neoclas heads, boxed corentrance on both two story verand fireplaces. Out converted to story and Supplicance House built by Wity his brother this house, taking and did all the in william Stouffer	large el contempor ssic details as prince and plain frince and plain frince and plain frince and plain frince and powers. Addition of the content and the power and was born and the prince a	llaster corner boards, pediment will leze. mary facade has single let the trnasom and sidelights. El has as been screened. Some working at #36: Some fireplaces closed or Bungalow-type porch replaces original fire and his somplete it. Stouffer was a carpet	ginal on primary facade rom trees on the propertis wife, Stouffer built
I-house with large reactures Neoclas heads, boxed cornentrance on both two story verand fireplaces. Out converted to story and Supplicance House built by Wity his brother this house, taking and did all the in william Stouffer Cescription of Environment.	large el contempor sic details as prince and pain frince and pain frince and pain frince, both with a lower story hat standing woodwork to a detail and stouffer of the content and was born and ment and Outbuildings	laster corner boards, pediment will leze. mary facade has single leath trnasom and sidelights. El has as been screened. Some working at #36: Some fireplaces closed or Bungalow-type porch replaces originally by Bungalow-type porch replaces originally walnut, fire, who lived with Stouffer and he complete it. Stouffer was a carpe house himself. Present owner is a raised in the house.	ginal on primary facade rom trees on the properties wife, Stouffer built inter and a blacksmith the granddaughter of
I-house with large reactures Neoclas heads, boxed cornentrance on both two story verand fireplaces. Out converted to story and Supplicance House built by Wity his brother this house, taking and did all the in william Stouffer Cescription of Environment.	large el contempor esic details as prince and pain fri n levels, both wi- da, lower story ha tstanding woodwork oves. Addition of eves. Addition of trin-law James Rich ing two years to di iron work for the rand was born and ment and Outbuildings	laster corner boards, pediment wileze. mary facade has single let the trasom and sidelights. El has as been screened. Some working at #36: Some fireplaces closed or Bungalow-type porch replaces original factive lumber, mostly walnut, fife, who lived with Stouffer and he complete it. Stouffer was a carpe house himself. Present owner is	ginal on primary facade rom trees on the properties wife, Stouffer built inter and a blacksmith the granddaughter of
I-house with large reactures Neoclas heads, boxed corentrance on both two story verand fireplaces. Out converted to story and Significance House built by Wity his brother this house, taking and did all the in William Stouffer Original planting remain on the present the story of	large el contempor esic details as prince and pain fri n levels, both wi- da, lower story ha tstanding woodwork oves. Addition of eves. Addition of trin-law James Rich ing two years to di iron work for the rand was born and ment and Outbuildings	laster corner boards, pediment will leze. mary facade has single leath trnasom and sidelights. El has as been screened. Some working at #36: Some fireplaces closed or Bungalow-type porch replaces originally by Bungalow-type porch replaces originally walnut, fire, who lived with Stouffer and he complete it. Stouffer was a carpe house himself. Present owner is a raised in the house.	ginal on primary facade rom trees on the properties wife, Stouffer built inter and a blacksmith the granddaughter of
I-house with large reactives needs, boxed corentrance on both two story verand fireplaces. Out converted to story and Significance House built by Wity his brother this house, taking and did all the in William Stouffer Original planting remain on the pressure of Information	large el contempor esic details as prince and pain fri n levels, both wi- da, lower story ha tstanding woodwork oves. Addition of eves. Addition of trin-law James Rich ing two years to di iron work for the rand was born and ment and Outbuildings	laster corner boards, pediment will leze. mary facade has single leath trnasom and sidelights. El has as been screened. Some working at #36: Some fireplaces closed or Bungalow-type porch replaces originally by Bungalow-type porch replaces originally walnut, fire, who lived with Stouffer and he complete it. Stouffer was a carpe house himself. Present owner is a raised in the house.	ginal on primary facade rom trees on the property is wife, Stouffer built inter and a blacksmith the granddaughter of original outbuildings
I-house with la Features Neoclas heads, boxed corentrance on both two story verand fireplaces. Out converted to story and Significance House built by Wity his brother this house, taking and did all the in William Stouffer Obscription of Environm Original planting remain on the prosecution of the p	large el contempor sic details as prince and plain frince and plain frince and plain frince and plain frince and and and and and outbuildings and Modern house coperty.	laster corner boards, pediment will leze. mary facade has single leath trnasom and sidelights. El has as been screened. Some working at #36: Some fireplaces closed or Bungalow-type porch replaces originally by Bungalow-type porch replaces originally walnut, fire, who lived with Stouffer and he complete it. Stouffer was a carpe house himself. Present owner is a raised in the house.	ginal on primary facade rom trees on the property is wife, Stouffer built nter and a blacksmith the granddaughter of original outbuildings
I-house with large reactives needs, boxed corentrance on both two story verand fireplaces. Out converted to story and Significance House built by Wity his brother this house, taking and did all the in William Stouffer Original planting remain on the pressure of Information	large el contempor sic details as prince and plain frince and plain frince and plain frince and plain frince and and and and and outbuildings and Modern house coperty.	laster corner boards, pediment will leze. mary facade has single leath trnasom and sidelights. El has as been screened. Some working at #36: Some fireplaces closed or Bungalow-type porch replaces originally by Bungalow-type porch replaces originally walnut, fire, who lived with Stouffer and he complete it. Stouffer was a carpe house himself. Present owner is a raised in the house.	ginal on primary facade rom trees on the property is wife, Stouffer built inter and a blacksmith the granddaughter of original outbuildings



FLOORPLANS

NOT TO SCALE



PHOTOGRAPH



1-No	40 1 Pre	sent Name(s)	
2 County	10	Orrick Truss Bridge	
Ray	5 OIF	ner Namo(s)	
3 Location of Negatives RCHS &	e M		
Specific lucation la miles northwest	of Orminic on	16 Thematic Category	28 No of Stories n/a
Route O, on unmark		110	29. Basement? Yes
to the southwest.		17 Date(s) or Period	n/a No
7 City or Town Il Rur	S4 SIN FW	1904 18 Style or Design	30. Foundation Material
vic. Orrick; Orric		Pratt truss 6418 6400	ashlar stone 31. Wall Construction St
8 Site Plan with North Ar		19. Architect or Engineer	wrought iron So
	3/11	unknewn	32. Roof Type & Material
	// 1 7	20. Contractor or Builder	n/a
Fishing river	1 1	unknown 21. Original Use, If apparent	33. No. of Bays Front n/a Side n/s
X	/ 11 40	bridge	34. Wall Treatment
		22 Present Use	n/a
//	4	bridge	35. Plan Shape n/a
	4	23 Ownership Public X1	36. Changes Addition
		Private I I	(Explain Altered in #42) Moved
/(		il known	37 Condition
	UTM	County of Ray	Interior good
Lat Long		Ray County Courthouse, Richmond	Exterior
Site Li	C	25 Open to Yes X: Public? No I I	38. Preservation Yes
Building	Structure 00 Object 1 1	26 Local Contact Person or Organization	Underway? No 39 Endangered? Yes
1 On National Yes !!	12 Is II Yes II	20 Local Compet Verson of Organization	39 Endangered? Yes By What? No
Angister? No to	Eligible? No IX	27. Other Surveys in Which Included	
9 Part of Estab Yes I I Hist Dist.? No IX	14. District Yes i Potent'l? No kr		40. Visible from Yes
5 Name of Established Di			Public Road? No 41. Distance from and
			Frontage on Road
12. Further Description of I			
Typical Pratt type floor has covering		904 from marker on bridge. Plank	Photo
3 History and Significance	8		
One of only two re	maining truss br	idges in Ray County.	
•	0		
1 0			
Description of Environm	_		
Across a stream in	the center of f	armland.	
7			
Sources of Information			
On-site inspection			46. Prepared by Cameron
	•		47 Organization
			RCHS & M
			48 Date 49 Revision Date(s)
			8/80






1 No 144	Artman Tenant House	
2 County Ray 3 Location of Negatives RCHS	5 Other Namo(s) Chris Hanne House	
C Specific Lucation From Orrick, take Hyway 21	0 west to	26 No of Stories two 29. Basement? Yes!!
first left, & mile; south to unmarked dirt drive eas	t. Tologs or Period ca. 1880-90	30. Foundation Material ashlar stone 45
V.C. Oruck Oruck Twp.  B Site Plan with North Arrow	19. Architect or Engineer	31. Wall Construction frame, wu  32. Roof Type & Material CB
,	20. Contractor or Builder Chris Hanne  21. Original Use, If apparent	able-standing seam tin 33. No. of Bays Front 3 Side 154
	residence OIA  22 Present Use residence	34. Wall Treatment asphalt shingles 35. Plan Shape T-shape
	23 Ownership Public I Private W	36. Changes (Explain in #42)  Addition X Altered D: Moved i
W Coordinates UTM	24 Owner's Name & Address.  11 known  Elmen Artman	37 Condition poort Interior poort
Luny 528 51 10 3	Orrick, Missouri  25. Open to Public?  Structure 1: No ½	38. Preservation Yes No X
Site 1 1 Building 12	Object     26 Local Contact Person or Organization Yes	39 Endangered? Yes IX By What? neglect
13 Part of Estab Yes I 14. Dis		40. Visible from Yes X Public Road? No ::
15 Name of Established District		Frontage on Road
all facades. Central do	tirely obscured with addition of asphall to orways on both levels of primary facade. ntral brick stove chimney remains. Large el contemporary with it. #39: house is in po	Photo
At the time the house wa	peen 1880 and 1890 by Chris Hanne, who was on us constructed there was also a log barn on a the this one replaced. This has since disappe by the neighboring farm.	ne of the first owners. the property, indicating rared. The house is now
Large oak trees to the wonf recent date abut the	vest and south of the house certainly predate house on the east; yard is fenced.	e it; several outbuildings

45 Sources of Information On-site inspection. Personal Knowledge of surveyor Granddaughter of builder. Elmer Artman.

46. Prepared by B.B. Pigg 47. Organization RCHS & M 49 Revision Date(s) 48. Date



FLOORPLANS


NOT TO SCALE



PHOTOGRAPH



1 No	43 4 Pre	Serit Name(s)	
County		Piggs Landing	
3 Location of Negatives		ner Namo(s)	
RCHS &	Se M	18 Thematic Calegory	
l mile west of Or	rick on State	030 010	20 No of Stories two
Highway 210 to dr		17 Date(s) or Period	29. Basement? Yes II
over railroad trac	cks.	1870	30. Foundation Material
	ral, Township & Vicinity		ashlar stone 45
	ick twp.	Greek Revival 3/ 09	31. Wall Construction
8 Sile Plan with North	l'ow	19. Architect or Engineer	frame. WU
Million	(9)	20. Contractor or Builder Push	32. Roof Type & Material 16
V///W////	1 4	Lewis Pigg Po B	gable-comp. shingles
\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\	2 /	21. Original Use, If apparent	Front 5 Side 1
	2 1 9	residence OIA	34. Wall Treatment
	3 /	22 Present Use	comp. siding 63
	3 //	residence	35. Plan Shape rectangular
2 -		23 Ownership Public 11	.36. Changes Addition .X
( ) ( )	3 Bout	Private lyl 24. Owner's Name & Address.	(Explain Alfered Moved :
he h	9 3000	if known	37 Condition
9 Coordinates	UTM	E.L. Pigg, Jr.	Interior excellent
	MACHI	Orrick, Missouri	Exterior excellent
Lony		25 Open to Yes I I	38. Preservation Yes
Site 1 i Building X i	Structure 1 i	Public? No IX	Underway? No .X
		26 Local Contact Person or Organization	39 Endangered? Yes !!
Register? No K.	12 Is II Yes Ki Eligible? No I I	27 Other Courses Military	By What? No IX
13 Part of Estab Yes I I Hist Dist.? No Ki	14. District Yes i I	27. Other Surveys in Which included	40. Visible from Yes
15 Namu of Established D	Potent'l? No Xi	Į.	Public Road? No X
13 Mante of Established D	rstrict		41. Distance from and Frontage on Road
42 Further Description of	important Features		
Greek Revival hous	e features two s	tory portico with tuscan columns.	
fenestration 6-our	palcony with rail	ing and carved balusters. All	
both levels of pri	mary facade have	nt-shaped window heads. Doors on transoms. #36: Some facade detail	Photo
obscured with addi	tion of siding o	ver original clapboards. One	
chimney removed.	Interior has bri	ck Bireplace (hearth was raised)	
and stairway with	slender, turned	newel post and balusters	
43 History and Significance	e		
House was built in	1870 by Lewis P	igg. At that time, the Missouri R	iver ran a few yards from
the front of the h	louse, and steamb	oats there discharged and loaded ca	argo The house is
the present owner	the county that	has been occupied by the same fami	ly since its con truction
one bresent owner.	is the great-gre	at grandson of the builder.	3
44 Description of Environm	nent and Outbuildings		
On a farm with sev	eral outbuilding	s in the vicinity, including the or	riginal harm Railmond
tracks behind the	house.	,	- Samuel Barne Harrivau
	,		
45 Sources of Information			46. Prepared by
Mrs. Margaret Pigg	•	·	Cameron
Ray County History	, 1973.		47 Organization
Portraits and Biog	raphical Records	of CLAY, Ray and Chariton, etc.	RCHS & M
Countie			48 Date 49 Revision Date(s)
On-site inspection	n.		10/79



FLOORPLANS

NOT TO SCALE



PHOTOGRAPH



No 147	McMullen House			
Ray	5 Other Namo(s)			
Location of Negatives	the state of the s		26 No of Stories	1/2 -1
Specific Location from Orrick to	first 030	13_	29. Basement?	Yes I
ft; 1 mile on unmarked grav fork, then west. 39 W c. C. Wrick Wp.	17 Date(s) or Period 1907-1908  8 Vicinity Neoclassical/Vernacula 19. Architect or Engineer unknown 20. Contractor or Builder Frank McMullen 21. Original Use, II apparent residence O/A 22 Present Use residence 23 Ownership  24. Owner's Name & Address.		34. Wall Treatment weatherboard 35. Plan Shape L-A 36. Changes (Explain in #42)	side 2  Side 2  Addition  Altered  Moved
9 Coordinates UTM Lat Long	Roy McMullen Orrick, Missouri	Yes I I No IX	Interior ex	cellent Cellent Yes Nox
Site 1 : Building : X	Object   1   26. Local Contact Person or Or		39 Endangered? By What?	les Nox
11 On National Yes II 12 Is II Eligit 13 Part of Estab Yes II 14. Dist Hist Dist.? No 1 X Pote	e? No 11 27. Other Surveys in Which Inc	luded .	40 Visible from Public Road?	YesX Nc
15 Name of Established District			41. Distance from Frontage on Re	and
posts and brackets, fig-sal connice. All fenestration	s a fine Carpenter Gothic porch, n porch frieze and dentil row do and doors have Neoclassic molder heavy palin frieze and boxed cor ar of house. On west facade, to	econacing d window head rnice.		10

43 History and Significance

The framing for this house was sawed by a Mr. Johnston in Jackson County and rafted across the Missouri River and-was cotton wood. The finishing lumber was hauled from Liberty, Missouri. The house was built by Frank McMullen, the owner, and the present owner is his grandson.

44 Description of Environment and Outbuildings

On large farm! in rural area, with modern outbuildings to the rear and east. Original plantings.

45 Sources of Information

Personal Knownledge of surveyor

On-site inspection


46. Prepared by

Boyd Pigg

A7 RCHS & M

48 Date 49 Revision C 49

5/80



FLOORPLANS

NOT TO SCALE




PHOTOGRAPH



8/79

No 134 '	Present Name(s)	
	Endsley House	
County	Other Namo(s)	1
Ray		
Location of Negatives RCHS		28 No of Stories 2-2two
Specific Lucation 210 1 mile oas	t 140	29. Basement? Yes II
State hywy 210, 1 mile east of Orrick	17 Date(s) or Period	No X
519 TSIN 28W		30. Foundation Material
	ca. 1857	ashlar stone 40
City or Town If Rural, Township & Vicin	vernacular/Neoclassic details	31. Wall Construction
rick vic, Orrick Twp. Site Plan was North Arrow	19. Architect or Engineer	frame .wu
Site Jan was North	unknown	32. Roof Type & Material gable-comp. shingles
1 will	20. Contractor or Builder	33. No. of Bays
1 1 1	Ethelbert Endsley 21. Original Use, if apparent	Front 5 Side 7
	residence	34. Wall Treatment 63
7	22 Present Use	comp. shingles
Y	residence	35. Plan Shape L-shape
	23 Ownership Public I !	36. Changes Addition X Altered X
US 3 63	Private X 1	(Explain Altered A
9300	24. Owner's Name & Address.	37 Condition
0	if known	DOOD vouseted
Coordinates UTM	Walter Endsley and Alice Skeltor	Exterior good
Lat.	Orrick, Missouri	28 Preservation Yes
Long	Public? No IV	Underway? No x
Site 1 Structur	eli	39 Endangered? Yes
Dunany A.	as XI	By Whal? No
Oli Malifornia 162	27. Other Surveys in Which Included	
Milgister	95   1	40. Visible from Yes) Public Road? No
	lo X <sup>1</sup>	Public Road? No :
5 Name of Established District		Frontage on Road
•		
2. Further Description of Important Features	l l l l l l l l l l l l l l l l l l l	
ive-bay frame I-house has been	somewhat obscured by addition of sidi	oor-vic
out retains many original detail	ls. Boxed cornice with returns, six-ville-in veranda extends across primary	Photo
facada Macalassic ontromay	Two story addition to rear. Brick	
interior and chimneys are extan	t. Addition has brick stove chimney.	
There is the circumetry are expans	, and the state of	
43 History and Significance		0 16. 11.
The house was built by Ethelber	t M. Endsley ca. 1857. His father Joh	nn came from North
Carolina where he was born on a	plantation in 1796. He travelled wes	t with the Smith and
Ashley Company, a party of trap	pers, for two years. On his way back	brought his nother to
and was so delighted with the	and he returned to North Carolina and	brought his hother (cont
44 Description of Environment and Outbuild	dings	
Situated on a bluff overlooking	the bottom lands and (before it change	ged its course) the Miss
River, the site still retains of	some original planting of cypress and p	pine.
miter, one stoe sotti recuills a		
		46. Prepared by
45 Sources of Information		
	Ray County Atlas, 1877.	Cameron
45 Sources of Information On-site inspection. Ray County History, 1883.	Ray County Atlas, 1877. Biographical History of Clay Ray, et	Came ron 47. Organization

12. Cont. settling near the presnet site.in 1824. He made of business of growing tobacco. Ethelbert (Bert) Endsley, was one of 11 children born to John and Hannah (Wells) Endsley, born in 1834. At 17, he hired out on a farm for 11 dollars a month. In 1852, he went west and began mining in Calaveras County where he was fairly successful. Returning to Ray County in 1857, he acquired this property next to his fathers property and constructed this house. Endsley married Eliza Vance in 1857, and they had 7 children. After her death in 1873, Endsley married Maria Owen in 1875 and had 5 more children. After Maria's death Endsley married a third time to Sarah Woodruff. In 1864, Endsley went to Montana and spent a year freighting with teams, but returned to his farm and occupied himself with livestock farming and raising especially shorthorn cattle. The house is at present owned by a descendent of Ethelbert.




FLOORPLANS NOT TO SCALE



PHOTOGRAPH



L NO. 135	4. PRESENT LOCAL NAME(S) OR DESIGNATION(S)	RA- A5-002-140	: 2
2. COUNTY	Moyer Residence		, so
Ray	5. OTHER NAME(S)		
NEGATIVES RCHS	16. THEMATIC CATEGORY	28. NO. OF STORIES 1/2	
TOWNSHIP 51 RANGE 28 SECTION	30 030 010	29. BASEMENT ? YES ( )	
road south, then & mile to	dirt ca. 1900	30. FOUNDATION MATERIAL ashlar stone 40	COUNTY
7. CITY OR TOWN IF RURAL, VICINITY	18. STYLE OR DESIGN 50 09	ashlar stone 40	
B. DESCRIPTION OF LOCATION	vernacular/Neoclassic details  19. ARCHITECT OR ENGINEER	Krame WU	
Q Q	Y unknown 20	gable-comp, shingles.	IG.
9 -	A.J. Riffe (?)	33. NO. OF BAYS	00
200	21. ORIGINAL USE, IF APPARENT residence 010	FRONT 3 SIDE 3	PRE
9 111 -	22. PRESENT USE	weatherboard 21	SEN
6	residence 23. OWNERSHIP PUBLIC(	) 35. PLAN SHAPE L-shaped ) 36. CHANGES ADDITION(x)	5
	PRIVATE(	(EXPLAIN IN ALTERED (X)	PRESENT LOCAL NAME(S)
	24. OWNER'S NAME AND ADDRESS	MOVED ( )	NAM
9. COORDINATES UTM	. Clifton Moyer	INTERIOR good	E(S)
LAT	Orrick, Missouri 25. OPEN TO PUBLIC? YES(	EXTERIOR 9000	2
	25. OPEN TO PUBLIC? YES(	ALLE COMMANDE	DES
IL NATIONAL YES ( ) 12. IS IT	PSJECT ( 1 26, LOCAL CONTACT PERSON OR ORGANIZATION YES (X )	BY WHAT ? NO (%)	DESIGNATION(S
IT DADT OF SCHOOL MEST A DISTRICT	NOT 7 27, OTHER SORVETS IN WHICH INCLUDED	40. VISIBLE FROM YES ( ) PUBLIC ROAD ? NO ( )	(S)
IS. NAME OF ESTABLISHED DISTRICT		41. DISTANCE FROM AND FRONTAGE ON ROAD	1
central entrance flanked by 2 one of two int. brick stove ch story porch supported by sing and doors have molded lintels corner boards. Porch also on dents the atlas of 1897 the land	he-century farmhouse. Primary facade had /2 windows. El to rear of main block had imney, secondary facade of el has one le freestanding Doric column. All window ; boxed cornice and frieze; pilaster central bay of primary facade; both with tils on frieze. was owned by A.J. Riffe, who presumably	built this house.	O. OTHER NAME(3)
stockman.	were the property of J.T. Allen, listed of	is a farmer and	-
44. DESCRIPTION OF ENVIRONMENT AND	OUTBUILDINGS		
• • • • • • • • • • • • • • • • • • • •	ssive oak trees in front yard. Modern fo	ırm outbuildings are	
45. SOURCES OF INFORMATION		Cameron By	
On-site inspection		47. ORGANIZATION	
Atlases of 1897 and 1914		47. ORGANIZATION  RCHS & M  48. DATE 48. REVISION DATE(S)  5/80	The state of the s



FLOORPLANS

NOT TO SCALE






PHOTOGRAPH





1. NO. 4. PRE	SENT LOCAL NAME(S) OR DESIGNATION(S)  Norris House		1. NO.
D	HER NAME(S)		
6. SPECIFIC LEGAL LOCATION JEW SECTION 32	IG. THEMATIC CATEGORY	28. NO. OF STORIES 1 1/2	io
IF CITY OR TOWN, STREET ADDRESS	17. DATE(S) OR PERIOD	29. BASEMENT? YES ( ) NO (X )	COUNTY
1 mile westof Camden on 210 to (cont)	ca. 1880	30. FOUNDATION MATERIAL	ALN
7. CITY OR TOWN IF RURAL, VICINITY	Neoclassic 49	ashlar stone	
Orrick vic. Camden Twp.  8. DEPCHIPMON OF LOCATION :	IS. ARCHITECT OR ENGINEER	frame WU	
S. DESCRIPTION OF EDEXITOR	unknown	32 ROOF TYPE AND MATERIAL	17
63	20. CONTRACTOR OR BUILDER unknown	qable-comp. shingles	-
	21. ORIGINAL USE, IF APPARENT	FRONT 3 SIDE 3	20
	residence DIA	34. WALL TREATMENT	2838
	22. PRESENT USE	metal siding 35. PLAN SHAPE T-shape	N H
2 11 47	23. OWNERSHIP PUBLIC(	36. CHANGES ADDITION (X)	Loc'
	PRIVATE( X	NO. 42) ALTERED ()	۲
	24. OWNER'S NAME AND ADDRESS IF KNOWN	37 CONDITION	PRESENT LOCAL NAME(S)
9. COORDINATES UTM	Nick Norris	INTERIOR GOOD	
LONG	Orrick, Missouri 25. OPEN TO PUBLIC? YES(	EXTERIOR GOOD YES ( )	8
10. SITE ( ) STRUCTURE ( )	NO(X)	E MADERIMAN O	DES
BUILDING ( X) OBJECT ( )  1 ! NATIONAL YES ( ) 12. IS IT YES (X ) SISTER?	26. LOCAL CONTACT PERSON OR ORGANIZATION	39. ENDANGERED? YES (\(\chi\)) 8Y WHAT? NO (\(\chi\))	OR DESIGNATION(S
I3. PART OF ESTAB. YES ( ) 14. DISTRICT YES ( ) HIST. DISTRICT? NO ( X )	27. OTHER SURVEYS IN WHICH INCLUDED	40. VISIBLE FROM YES( ) PUBLIC ROAD? NO( X)	) N(S)
IS. NAME OF ESTABLISHED DISTRICT		41. DISTANCE FROM AND FRONTAGE ON ROAD	
42. FURTHER DESCRIPTION OF IMPORTANT FEATUR	ES '		o
Original primary elevation on the west the roofline. Here what was undoubted Primary facade now on the south with e of main block. Two large plate glass facade to conform to turn of the centuaddition of siding.	where three wall dormers break lly a porch has been enclosed. ntry into what was originally el windows have been cut on this	PHOTO MUST BE PROVIDED	5. OTHER NAME(S)
43. HISTORY AND SIGNIFICANCE			
C.V. Endicott Estate is listed as the prpbably built this house around 1880. again after her death, to Amy Barbers	James marriedMargaret Remley in	1861. He married	d. TOWNSHIP
			NSHIP
			-
44. DESCRIPTION OF ENVIRONMENT AND OUTBUIL	DINGS		RANGE
In Jral environment, with original pl	antings.		
45. SOURCES OF INFORMATION		46. PREPARED BY Cameron	-
RayyCounty History, 1881.		47. ORGANIZATION	SECTION
33 100]		1 RCHS & M	1 6
Ray County Atlas, 1877. On-site		48. DATE 49. REVISION DATE(S)	2




FLOORPLANS



PHOTOGRAPH



NO. 141	4. PRESENT LOCAL NAME(S) OR DESIGNATION(S)	
COUNTY	Union Baptist Church	
Ray LOCATION OF RCHS	5. OTHER NAME(S) 80 84 0003	
SPECIFIC LEGAL LOCATION TOWNSHIP 51 RANGE 29 SECTI	16. THEMATIC CATEGORY	28. NO. OF STORIES ONE
IF CITY OR TOWN, STREET ADDRESS	IT DATE(S) OR PERIOD	29. BASEMENT? YES () FULL NO () A 30. FOUNDATION MATERIAL
city or town if RURAL, VICINITY VIC. Orrick Orrick twp.		ashlar stone
DESCRIPTION OF LOCATION	IS. ARCHITECT OR ENGINEER	brick
	20. CONTRACTOR OR BUILDER	hipped/comp. shingles
	unknown 21. ORIGINAL USE, IF APPARENT	FRONT N/A SIDE N/A
	church 22. PRESENT USE	common bond brick
	church 23. OWNERSHIP PUBLIC	
CEMETERY	PRIVATE (	X ) (EXPLAIN IN ALTERED ( MOVED (
CEMETER	congregation of Union Baptist c	37. CONDITION
LAT UTM	Orrick, Missouri	EXTERIOR GOOD
LONG D. SITE ( ) ST	RUCTURE( ) PEN TO PUBLIC? YES(	
BUILDING (X)	OBJECT ( 1 26. LOCAL CONTACT PERSON OR ORGANIZAT	TON 39. ENDANGERED? YES
REGISTER ? NO (X) ELIGIB	LE? NO(^) 27. OTHER SURVEYS IN WHICH INCLUDED	40. VISIBLE FROM YES
HIST. DISTRICT ? NO (X)	TIAL? NO(XI	PUBLIC ROAD ? NO
5. NAME OF ESTABLISHED DISTRICT		FRONTAGE ON ROAD
12. FURTHER DESCRIPTION OF IMPORT		РНОТО
Polygonal bell tower with h	ipped roof edged by battlements contains af with large transom set under segmental	10000
arch. Fach facade of the t	ower contains a louvered opening. Prmar	У
facade has large triple win	dow under segmental arch; those of the searched with transoms. Raised basement ar	ec- nd PROVIDED
limestone watertable; limes	tone also trims lugsills and keystones of	farches.
43. HISTORY AND SIGNIFICANCE		
The Union Baptist church wa	s organized in 1852 and is affiliated will	th the Southern Baptist
built in 1917.	ird building for the congregation at this	o location, and was
		4
44. DESCRIPTION OF ENVIRONMENT	ND OUTBUILDINGS	
In a rural area, surrounded the gravel road.	by bottom land, the cemetery for the ch	nurch is located across
45. SOURCES OF INFORMATION		46. PREPARED BY Cameron
On-site inspection. Ray County History, 1973.		47. ORGANIZATION
		RCHS & M
		6/80



FLOORPLANS


NOT TO SCALE



PHOTOGRAPH



1 No 133 JA	12 1 Pre	sent Name(s)	
Ray		Battagler Residence	
3 Location of Negatives RCHS & N		her Namo(s)	
6 Specific Lucation S6 5/N	2011	16 Themalic Calegory	26 No of Stories twp
36 314	3700	17 Datu(s) or Period	29. Basement? Yes I
		ca. 1880	30. Foundation Material
	al, Township & Vicinity	18 Style or Design	log pillars 23
Vic. Orrick. Orric		vernacular 09	11. Wall Construction frame WW
o one rian with north at	1	unknown	
	N	20. Contractor or Builder	gable-comp, shingles
		unknown Mace Rakes (?)	33. No. of Bays Front 5 Side 3
I V		residence	34. Wall Treatment
		22 Present Use	comp. siding 63
		residence	35. Plan Shape L-shape
		23 Ownership Public I Private XX	36. Changes Addition X
	1.3211	24. Owner's Name & Address,	(Explain Altered)
		if known	37 Condition good
Coordinates	UTM	Mrs. Elwood Mills	Interior good
Long		Orrick, Missouri	Exterior good
Site Li	Structure 1 i	25 Open to Yes 11 Public? No XX	38. Preservation Yes Underway? No )
Building (X	Object I I	26. Local Contact Person or Organization	39 Endangered? Yes
1 On National Yes II Register? No IX	12 Is II Yes LX Eligible? No XX		By What? No
3 Part of Estab Yes II	14. District Yes II	27. Other Surveys in Which Included	
Hist Dist.? No IX	Potent'l? No X		40. Visible from Yes y Public Road?
5 Name of Established D	istrict		41. Distance from and
			Frontage on Road
2 Further Description of	Important Features		
Vernacular house h	as two entrances	on primary facade: evidence that	
original structure	was 2/3rds I-ho	use on east to which was added sing	gle
pen two story addi	tion on west and	an el on rear. House's foundation	Photo
alterations include	ded piers on which	h the sills rest. #36: Many torm windows, composition siding	
obscuring facade of	letail. One stov	e chimney removed.	
3 History and Significance		- · · · · · · · · · · · · · · · · · · ·	1.
		1000	
Built probably by	a Mace Rakes ca.	1880.	
4 Description of Environm	ient and Outbuildings		
urrounded by farm		·huilding 0	
- J ruilli	and, no rami out	building. Garage to the wast.	
Severage - A A-A			
			46. Prepared by
Ir. and Mrs. Rattac	ller (present res	idents)	Cameron
r. and Mrs. Battac	ler (present res k, 1871.	idents)	
Sources of Information  Ar. and Mrs. Battag  ay County Plat Boo	ller (present res k, 1871.	idents)	Cameron



**FLOORPLANS** 


NOT TO SCALE



PHOTOGRAPH



No. 118	Present Name(s)	
i ily .	Friendship Church 80RY0	904
	Other Namo(s)	
RCHS & M		•
Specific Lucation	16. Thematic Category	28. No. of Stories one
		29. Basement? Yes ! !
515 51 N R 28W	17 Date(s) or Period	No X
	1897	30. Foundation Material ashlar stone
Vic. Richmond, Orrick twp.	ity 18 Style or Design vernacular	31. Wall Construction
Site Plan with North Arrow	19. Architect or Engineer	frame
4,2	unknown	32. Roof Type & Material
N X	20. Contractor or Builder	gable-asphalt shingle
1) 43	unknown 21. Original Use, if apparent	33. No. of Bays Front 2 Side 4
h **	church .	34. Wall Treatment
	22 Present Use	comp. siding.
l e	vacant	35. Plan Shaperectangular
	23 Ownership Public I !	36. Changes Addition
	24. Owner's Name & Address.	(Explain Altered 🕅 in #42) Moved :
690	if known	37. Condition
Goordinates UTM	Congregation of Kriendship	Interior fair
Lat Long	Church, Richmond, Mo.	Exterior fair
Site ! 1 Structure	25. Open to Yes Pa	38. Preservation Yes Underway? No ox
Building K Object		39. Endangered? Yes 1x1
On National Yes   1 12. Is It Yes	Kı	By What? No
Register' No K Eligible? No Part of Estab Yes I.i 14. District Yes	27. Other Surveys in which included	vacant
Part of Estab Yes I.I Hist Dist? No 10 Potent'1? No		40. Visible from Yes X Public Road?
Name of Established District	1	41. Distance from and
		Frontage on Road
Further Description of Important Features		
Example of vernacular church.	Boxed cornice and frieze, double	
	closed). Interior features original in the interior. # 6: Has undergone	
	dition of siding over original	Photo
	urnace, electricity. Original pews	
have been removed from the but		
		1
Congregation, led by J.C. Howe	ell, had been meeting for several year	ars in the Fitch school
	cated on a corner of the T Wilholt	
	inished and paid for at a cost of \$84	
	lendship Christian Church, the name s	
Description of Environment and Outbuilding	r the church were made in Lexington,	and saipped by lerry(Cont
_	secluded area surrounded by woods.	
	•	
		(
Sources of Information		46. Prepared by
Sources of Information  Ray County History, 1973.		Cameron
Ray County History, 1973.		Cameron
Mrs. Vernon Ogg	e inspection.	Cameron



FLOORPLANS

NOT TO SCALE




PHOTOGRAPH

43. Cont. across the Missouri River. Members hauled them to the church with team and wagon. The church became inactive in 1967.



	5	sent Name(s)	
County		Elmer Artman House	
Ray	5 OIM	er Namo(s)	
Location of Negatives RCHS & N	и	Frank Pigg House	
Specific Location	1	16 Thematic Category	28 No of Stories TWO
528 51N	<b>29</b> W	030	
		17 Datu(s) or Period	29. Basement? Ye
CR.		1905	30. Foundation Material
city or Town II Aur	ral, Township & Vicinity	18 Style or Design	brick 30
Site Plan with North A		Vernacular; Neoclassic details  19. Architect or Engineer	31. Wall Construction
	1	unknown	32. Roof Type & Material
1 6,8	Zout N	20. Contractor or Builder Proch	gable-wood shingles:
-		Frank Pigg TO MS	33. No. of Bays
		21. Original Use, If apparent	Front 3 Side ; ]
		residence	34. Wall Treatment weatherboard
	+ 1/2	residence	35. Plan Shape rectangu
		23 Ownership Public I !	.36. Changes Addition
37		Private	(Explain Illered
1 GY 2	2 W	24. Owner's Name & Address,	37 Condition
Coordinates	UTM	Elmer Artman	Interior good
Lat		Orrick, Missouri	Exterior good
Long		25 Open to Yes II Public? No XX	38. Preservation Ye
Sile 1 i Building i X	Structure 1 i		Underway? No
On National Yes II	12 is it Yes VI	26. Local Contact Person or Organization	39 Endangered? Yes
Register? No IX	Eligible? No 1	27. Other Surveys in Which Included	By What? No
Part of Estab Yes II Hist Dist.? No IX	14. District Yes K	The second secon	40. Visible from Yes
	Potent'l? No i		Public Road? No
Manus of Established D	ISTRICT		41. Distance from and Frontage on Road
Name of Established D			
Further Description of	important Features	de de de la companya	
Further Description of ernacular I-house	with Neoclassic	detail including window heads,	
Further Description of ernacular I-house ilaster corner bo	e with Neoclassic pards, Original to	wo story fportice remains: first	nth /
Further Description of ernacular I-house ilaster corner bo tory with denticu tories have turne	e with Neoclassic pards, Original to plated frieze, seed posts. Interio	wo story fportice remains: first cond with railing and pediment. Be cor central hall has plain heavy	oth Photo
Further Description of ernacular I-house ilaster corner bottory with denticutories have turne bodwork and stiar	e with Neoclassic pards, Original to plated frieze, seed posts. Interior newel posts. #	wo story fportico remains: first cond with railing and pediment. Bo or central hall has plain heavy 36: Exterior has virtually no	Photo
Further Description of ernacular I-house ilaster corner botory with denticutories have turned odwork and stiar lterations althou	e with Neoclassic bards, Original to alated frieze, seed d posts. Interior newel posts. #: agh two harge add	wo story fportico remains: first cond with railing and pediment. Be or central hall has plain heavy 36: Exterior has virtually no itions to rear. Old porch encloses	Photo
Further Description of ernacular I-house ilaster corner botory with denticutories have turne oodwork and stiar lterations althouser bath and new k	e with Neoclassic bards, Original to alated frieze, seed d posts. Interior newel posts. # ugh two harge add witchen ca. 1960.	wo story fportico remains: first cond with railing and pediment. Bo or central hall has plain heavy 36: Exterior has virtually no	Photo
Further Description of ernacular I-house ilaster corner botory with denticutories have turne bodwork and stiar lterations although bath and new kerstory and Significance	e with Neoclassic bards, Original to lated frieze, seed posts. Interior newel posts. # ligh two harge add sitchen ca. 1960.	vo story fportico remains: first cond with railing and pediment. Be or central hall has plain heavy 36: Exterior has virtually no itions to rear. Old porch enclosed Stoves removed.	Photo
Further Description of ernacular I-house ilaster corner bottories have turned to be a start and stiar literations although bath and new known and significance is house was builted owner, Framk P	e with Neoclassic bards, Original to lated frieze, seed posts. Interior newel posts. # ugh two harge additchen ca. 1960.	damage done by the flood of 1903 and percent Manage from his brother, John M. Pige	and was constructed by
Further Description of ernacular I-house ilaster corner be cory with denticularies have turned to dention and stiar laterations although bath and new known and Supportions house was builted as foreman.	e with Neoclassic bards, Original to lated frieze, seed posts. Interior newel posts. # ugh two harge add witchen ca. 1960. It in 1905 after ligg's sons with I This house is	damage done by the flood of 1903 and percent manage from his brother, John M. Pigene of three homes within 1½ miles	and was constructed by g's, family. John Pig
Further Description of ernacular I-house laster corner be cory with denticularies have turned to dention and stiar terations although and new known and summicance is house was builted as foreman.	e with Neoclassic bards, Original to lated frieze, seed posts. Interior newel posts. # ugh two harge add witchen ca. 1960. It in 1905 after ligg's sons with I This house is	vo story fportico remains: first cond with railing and pediment. Boor central hall has plain heavy 36: Exterior has virtually no itions to rear. Old porch enclosed Stoves removed.  damage done by the flood of 1903 and the store of the stor	and was constructed by g's, family. John Pig of each other that waty in 1838. The other
Further Description of ernacular I-house ilaster corner bottory with denticutories have turned bodwork and stiar literations although bath and new know and Supportion on the owner, Framk Perved as foreman.	e with Neoclassic bards, Original to lated frieze, seed posts. Interior newel posts. # ugh two harge additchen ca. 1960.  It in 1905 after ligg's sons with I This house is endents of three later.	damage done by the flood of 1903 and percent manage from his brother, John M. Pigene of three homes within 1½ miles	and was constructed by g's, family. John Pig of each other that wa
Further Description of ernacular I-house ilaster corner bottory with denticutories have turned bodwork and stiar literations although bath and new known and Significance is house was builted as foreman. The erved as foreman, when by the descent in the correction of Environment is the correction of Environment in the correction of Environment is the correction of Environment in the correction of the correction o	e with Neoclassic bards, Original to lated frieze, seed posts. Interior newel posts. # ugh two harge additchen ca. 1960.  It in 1905 after ligg's sons with I This house is endents of three later.	damage done by the flood of 1903 and percent manage from his brother, John M. Pigene of three homes within 1½ miles	and was constructed by g's, family. John Pigo of each other that was ty in 1838. The other
Further Description of ernacular I-house ilaster corner bottory with denticutories have turned bodwork and stiar literations although bath and new known and Significance is house was builted as foreman. The erved as foreman, when by the descent in the correction of Environment is the correction of Environment in the correction of Environment is the correction of Environment in the correction of the correction o	e with Neoclassic bards, Original to lated frieze, seed posts. Interior newel posts. # ugh two harge additchen ca. 1960.  It in 1905 after ligg's sons with I This house is endents of three later.	damage done by the flood of 1903 and percent manage from his brother, John M. Pigene of three homes within 1½ miles	and was constructed by g's, family. John Pig of each other that was ty in 1838. The other
Further Description of ernacular I-house ilaster corner be tory with denticularies have turned by the and stiar literations although bath and new known and Supprisoned is house was built ne owner, Framk Perved as foreman. The erved as foreman with the descent of the description of Environment working farm.	e with Neoclassic bards, Original to lated frieze, seed posts. Interior newel posts. # ugh two harge additchen ca. 1960.  It in 1905 after ligg's sons with I This house is endents of three later.	damage done by the flood of 1903 and percent manage from his brother, John M. Pigene of three homes within 1½ miles	and was constructed by g's, family. John Pig of each other that was ty in 1838. The other
Further Description of ernacular I-house ilaster corner botory with denticutories have turned oodwork and stiar literations althouse bath and new keep and Significance his house was builted as foreman. When the description of Environment working farm.	e with Neoclassic bards, Original to lated frieze, seed posts. Interior newel posts. # agh two harge additchen ca. 1960.  It in 1905 after ligg's sons with I This house is condents of three later and Outbuildings	damage done by the flood of 1903 and percent manage from his brother, John M. Pigene of three homes within 1½ miles	and was constructed by g's, family. John Pigg of each other that was ty in 1838. The other
Further Description of ernacular I-house ilaster corner botory with denticutories have turne oodwork and stiar lterations althouse bath and new keeps and Significance his house was builted by the descent of Environment working farm.  Sources of Information ersonal knowledge	e with Neoclassic bards, Original to lated frieze, seed posts. Interior newel posts. # agh two harge additchen ca. 1960.  It in 1905 after ligg's sons with I This house is condents of three later and Outbuildings	damage done by the flood of 1903 and percent manage from his brother, John M. Pigene of three homes within 1½ miles	and was constructed by g's, family. John Pigg of each other that was ty in 1838. The other (cont)  46. Prepared by Boyd Pigg
Further Description of ernacular I-house ilaster corner botory with denticutories have turned oodwork and stiar literations althout or bath and new known and Significant his house was builthe owner, Framk Perved as foreman. When the descent of Environment of En	e with Neoclassic bards, Original to lated frieze, seed posts. Interior newel posts. # ugh two harge additchen ca. 1960.  It in 1905 after ligg's sons with I This house is endents of three I ment and Outbuildings	damage done by the flood of 1903 and percent manage from his brother, John M. Pigene of three homes within 1½ miles	and was constructed by g's, family. John Pigg of each other that was ty in 1838. The other (cont)  46. Prepared by Boyd Pigg  47. Organization
ilaster corner botory with denticutories have turne oodwork and stiar lterations althoutor bath and new kerstory and Superlicance his house was builted by the owner, Framk Perved as foreman.	e with Neoclassic bards, Original to lated frieze, seed posts. Interior newel posts. # ugh two harge additchen ca. 1960.  It in 1905 after ligg's sons with I This house is endents of three I ment and Outbuildings	damage done by the flood of 1903 and percent manage from his brother, John M. Pigene of three homes within 1½ miles	and was constructed by g's, family. John Pigg of each other that was ty in 1838. The other (cont)  46. Prepared by Boyd Pigg

#43. Cont. two were Ruben Pigg to the north and John M. Pigg, whose farm adjoins this on the south. Later owners of the property were Ralph Grubbs, John Hicks ca. 1912, Harve Pointer, Casey Jones in the 1930's. Present owner purchased the farm in 1945.



FLOORPLANS

NOT TO SCALE




PHOTOGRAPH



## Office of Historic Preservation, P.O. Box 176, Jefferson City, Missouri 65101 HISTORIC INVENTORY

1 Nu	4 Present Name(s)	
35 146 -	John Pigg Residence	
Ray	5 Other Namo(s)	
3 Location of Negatives RCHS & M		
6 Specific Lucation		- Carlon Maria
Specific Condition	16 Thernalic Calegory	26 No of Stories two 2 2
	17 Datu(s) or Period	29. Basement? Yes III
	1904	30. Foundation Material
Orrick vic, Orrick twp.	vernacular: Neoclassic details	brick 30 31. Wall Construction
B Sile Plan with North Arrow	19. Architect or Engineer Ottos	frame . Wk.
	unknown >> >o	32. Roof Type & Material GB
	John M. Pigg	gable-wood shingles 33. No of Bays
	21. Original Use, If apparent	Front 3 Side 1
THY	residence ore	34. Wall Treatment Comp siding
	residence	
	23 Ownership Public I !	36. Changes Addition X
	Private IX  24. Owner's Name & Address.	(Explain Altered)(:
20ut	il known	37 Condition
9 Coordinates UTM	John and Alice Pigg	Interior good
Lat Luny	Route 1, Orrick Missouri	Exterior good.
Site 1   Structi	Out to 2	38. Preservation Yes Underway? No X
	ect 11 26 Local Contact Person or Organization	39 Endangered? Yes !!
	No   1 27. Other Surveys in Which Included	By What? No X
11	fes i i	40. Visible from Yes X
Hist Dist.? No IX Potent'l?	No I X	Public Road? No A
13 Name of Established District		41. Distance from and Frontage on Road
42 Further Description of Important Feature		/
I-house with T-shaped addition	is identical to #134 which was built	
I-house with T-shaped addition by the brother of the builder remained in the family, with f		
I-house with T-shaped addition by the brother of the builder remained in the family, with f in a similar manner.	is identical to #134 which was built of this house. Both houses have few alterations, and are kept painted	Photo
I-house with T-shaped addition by the brother of the builder remained in the family, with f in a similar manner. large porch across primary fa	is identical to #134 which was built of this house. Both houses have	
I-house with T-shaped addition by the brother of the builder remained in the family, with f in a similar manner. large porch across primary fa 1904.	is identical to #134 which was built of this house. Both houses have few alterations, and are kept painted	
I-house with T-shaped addition by the brother of the builder remained in the family, with f in a similar manner. large porch across primary fa 1904.	is identical to #134 which was built of this house. Both houses have few alterations, and are kept painted acade with the builder's name and date	
I-house with T-shaped addition by the brother of the builder remained in the family, with f in a similar manner. large porch across primary fa 1904.  43 History and Significance Thei farm was part of Joseph R	is identical to #134 which was built of this house. Both houses have lew alterations, and are kept painted acade with the builder's name and date do estate and was pruchased by John M.	Pigg who was a descenden
I-house with T-shaped addition by the brother of the builder remained in the family, with fin a similar manner. large porch across primary fa 1904.  43 History and Significance Thei farm was part of Joseph R of Joseph Roi from one of Jose	is identical to #134 which was built of this house. Both houses have few alterations, and are kept painted acade with the builder's name and date to estate and was pruchased by John M. oph Roi's daughters. The farm has been	Pigg who was a descenden in the Pigg family for
I-house with T-shaped addition by the brother of the builder remained in the family, with fin a similar manner. large porch across primary fa 1904.  43 History and Significance Thei farm was part of Joseph R of Joseph Roi from one of Joseph ree generations. The house original log house. Most of the state of the stat	is identical to #134 which was built of this house. Both houses have lew alterations, and are kept painted acade with the builder's name and date do estate and was pruchased by John M. In the ph Roi's daughters. The farm has been was built after the 1903 flood had was the framing materials were salvaged along the sa	Pigg who was a descenden in the Pigg family for ned away part of the
I-house with T-shaped addition by the brother of the builder remained in the family, with fin a similar manner. large porch across primary fa 1904.  43 History and Significance Thei farm was part of Joseph R of Joseph Roi from one of Joseph ree generations. The house original log house. Most of the	is identical to #134 which was built of this house. Both houses have lew alterations, and are kept painted acade with the builder's name and date do estate and was pruchased by John M. In the ph Roi's daughters. The farm has been was built after the 1903 flood had was the framing materials were salvaged along the sa	Pigg who was a descenden in the Pigg family for ned away part of the
I-house with T-shaped addition by the brother of the builder remained in the family, with fin a similar manner. large porch across primary fa 1904.  43 History and Significance Thei farm was part of Joseph R of Joseph Roi from one of Joseph Roi from one of Joseph Roi generations. The house original log house. Most of t	is identical to #134 which was built of this house. Both houses have few alterations, and are kept painted acade with the builder's name and date do estate and was pruchased by John M. Ph Roi's daughters. The farm has been was built after the 1903 flood had was the framing materials were salvaged alongons.	Pigg who was a descenden in the Pigg family for ned away part of the
I-house with T-shaped addition by the brother of the builder remained in the family, with fin a similar manner. large porch across primary fa 1904.  43 History and Significance Thei farm was part of Joseph R of Joseph Roi from one of Joseph ree generations. The house original log house. Most of the	is identical to #134 which was built of this house. Both houses have few alterations, and are kept painted acade with the builder's name and date do estate and was pruchased by John M. Ph Roi's daughters. The farm has been was built after the 1903 flood had was the framing materials were salvaged alongons.	Pigg who was a descenden in the Pigg family for ned away part of the
I-house with T-shaped addition by the brother of the builder remained in the family, with fin a similar manner. large porch across primary fa 1904.  43 History and Significance Thei farm was part of Joseph R of Joseph Roi from one of Joseph Roi from one of Joseph Roi generations. The house original log house. Most of t  44 Description of Environment and Outbuild. On a working farm, with later	is identical to #134 which was built of this house. Both houses have few alterations, and are kept painted acade with the builder's name and date do estate and was pruchased by John M. Ph Roi's daughters. The farm has been was built after the 1903 flood had was the framing materials were salvaged alongons.	Pigg who was a descenden in the Pigg family for ned away part of the ng the bank of the (cont)
I-house with T-shaped addition by the brother of the builder remained in the family, with fin a similar manner. large porch across primary fa 1904.  43 History and Significance Thei farm was part of Joseph R of Joseph Roi from one of Joseph Roi from one of Joseph Roi generations. The house original log house. Most of the Description of Environment and Outbuild On a working farm, with later	is identical to #134 which was built of this house. Both houses have few alterations, and are kept painted acade with the builder's name and date do estate and was pruchased by John M. Ph Roi's daughters. The farm has been was built after the 1903 flood had was the framing materials were salvaged alongons.	Pigg who was a descenden in the Pigg family for ned away part of the ng the bank of the (cont)
I-house with T-shaped addition by the brother of the builder remained in the family, with fin a similar manner. large porch across primary fa 1904.  43 History and Significance Thei farm was part of Joseph R of Joseph Roi from one of Joseph Roi from one of Joseph Roi generations. The house original log house. Most of the Description of Environment and Outbuild On a working farm, with later  44 Description of Environment and Outbuild On a working farm, with later  45 Sources of Information  John L. Pigg	is identical to #134 which was built of this house. Both houses have few alterations, and are kept painted acade with the builder's name and date do estate and was pruchased by John M. who had been was built after the 1903 flood had was the framing materials were salvaged alongs.	Pigg who was a descenden in the Pigg family for ned away part of the ng the bank of the (cont)  46. Prepared by Boyd Pigg 47 Organization
I-house with T-shaped addition by the brother of the builder remained in the family, with fin a similar manner. large porch across primary falgod.  43 History and Significance Thei farm was part of Joseph R of Joseph Roi from one of Joseph Roi from one of Joseph Roi from one of Joseph Roi generations. The house original log house. Most of the Description of Environment and Outbuild On a working farm, with later	is identical to #134 which was built of this house. Both houses have few alterations, and are kept painted acade with the builder's name and date do estate and was pruchased by John M. who had been was built after the 1903 flood had was the framing materials were salvaged alongs.	Pigg who was a descenden in the Pigg family for ned away part of the ng the bank of the (cont)  46. Prepared by Boyd Pigg

#43. Cont. Missouri River from lumber yards that had washed away in the flood. The old house had had only fireplaces for heating, so the new house was built in the latest fashion, with a number of stove chimneys. One of the heating stoves was a large nickle-plated one called a base burner, the heat was steady, unlike the usual stove fired by coal. The coal used in this sotve was called hard coal and came from Pennsylvania; it was about the size of a tennis ball and had no dust. This stove at the time was the ultimate in heating and was used by the most prosperous farmers in the county: each fall they would combine their orders and have a car shipped from the mine in Pennsylvania. The farm was a model farm of the time, consisting of a horse barn, cattle barn, milk barn, buggy house, scale house and blacksmith shop, hen house and ice house.



FLOORPLANS

NOT TO SCALE




PHOTOGRAPH



48. Date 49 Revision Date(s) 10/79

## Office of Historic Preservation, P.O. Box 176, Jefferson City, Missouri 65101 HISTORIC INVENTORY

1 Nu 9		sent Namo(s)	
County		Bethel Christian Union Church	
Ray	5 OIM	er Namo(s)	
3 Location of Negatives RCHS & M		House of Prayer	
Specific lucation of		16 Thematic Category	28 No of Stories one
		030	29. Basement? Yes !!
13 to unmarked grav west limi.to sharp		17 Datu(s) or Period	No IX
left = mile		1876	30. Foundation Material
	al, Township & Vicinity	18 Style or Design Salite and	ashlar stone
vic. Knoxville Pol		Neoclassic 73	31. Wall Construction
luy /	- 6	unknown	32. Roof Type & Material & B
BEN		20. Contractor or Builder	gable-comp. shingles
3		unknown B	33. No. of Bays
1	1 11 63	21. Original Use, if apparent church	Front 2 Side 4
	1148.	22 Present Use	34. Wall Treatment comp. siding 63
	1110	church	comp. siding 5
7	22 M	23 Ownership Public I !	36. Changes Addition X
	11 8 3	Private to	(Explain Altered K:
	10	24. Owner's Name & Address,	in #42) Moved
9 Coordinates	11744	Bethel Christin Union Church	37 Condition Interior excellent
tal tonu 54N	DTM DTM	Congregation, Knoxville, Mo.	Exterior excellent
tony 94N	40 00	25 Open to Yes IX	38. Preservation Yes
Site 11	Structure 1 i	Public? restricted No 11	Underway? No X
Building 1X	Object 1 1	26 Local Contact Person or Organization	39 Endangered? Yes II
Ringister? No to	12 Is II Yes IXI Eligible? No I I		By What? No X
13 Part of Estab Yes II	14. District Yes II	27. Other Surveys in Which Included	
Hist Dist.? No 12	Potent'l? No by		40. Visible from Yes X Public Road?
15 Name of Established Di	strict		41. Distance from and
			Frontage on Road
42 Further Description of I	moortant Features		
Most original detai	ls of facade hav	e been obscured by recent alteration	ons.
Windows have Neocla	ssic heads. Two	primary entrances both with	
		four regularly spaced windows.	
as well. Two rooms	s and corner pli	asters. Interior greatly changed south for nursery, etc. Panelling.	Photo
		and new doors. Addition of	
classroom to the re			
43 History and Significance	8		
Church was orstruct	ed in 1876 at a	cost of \$400. The members, number:	ing about 20 at the time,
the church was built	t, nad withdrawn	from the nearby Bethlehem Union Clir denominationdespite the separat:	nurch (see #10). They
Terather one hame o	HITPCIAN TOL ME	ir denominationdespite the separat:	ion.
44 Description of Environm	ent and Outbuildings		
Surrounded by acres	of farmland, the	e church sits on a wooded hill, over	erlooking most of the
county. There is n	o cemetery.		
Mrs. Mary Richardson	n		Cameron and Richardson
Ray County History.			cameron and Richardson
On-site inspection.			47 Organization
-			RCHS & M



FLOORPLANS

NOT TO SCALE



PHOTOGRAPH




Office of Historic Preservation, P.O. Box 176, Jefferson City, Missouri 65101

HISTORIC INVENTORY

No 1		it Name(s)	
	Ma	ddux House	•
County Ray	5 Other	Namo(s)	
ocation of Negatives			
RCHS & M		16. Thematic Category	28. No of Stories 2-1
t Route C to Elmin	D. #1	16. Indinatic Calegory	29. Basement? Yes I
imits take gravel	road west & mi.	17 Date(s) or Period	No 13
o fork; then north	h ½ mile.	1904	30. Foundation Material
	. Township & Vicinity	18 Style or Design	ashlar limestone 3
Lawson vicinity;	Polk twp.	Second Empire	frame .
Site Plan with North Arro	W .	19. Architect or Engineer unknown	32. Roof Type & Material
	N	20. Contractor or Builder	truncated hip-asphalt
	10	Mc Cullen, Arnote	33. No. of Bays Front 3 Side 2
<u>—</u>	ΨΙ	21. Original Use, if apparent	
		residence 6 P	34. Wall Treatment metal siding
		22 Present Use	35. Plan Shape square
		residence (rental property)  23 Ownership  Public !	36 Changes Addition
4		23 Ownership Private XI	(Explain Altered
		24. Owner's Name & Address,	111 112
lat 6	ELMIRA	il known Benton Maddux	37. Condition fair
		Lawson, Missouri	Exterior fair
	54N Daw	25. Open to Yes I i	38. Preservation Yes
Long		Public? No XI	Underway? No
Site 1 i Building 20	Structure 1 i Object 1 1 12 ts It Yes X1	26. Local Contact Person or Organization	39 Endangered? Yes By What? No
On National Yes !! Register? No %	12 ts It Yes XI Eligible? No I I	27. Other Surveys in Which Included	
Part of Estab Yes II	14. District Yes i I		40. Visible from Yes Public Road? No
Hist Dist.? No 80	Potent'l? No Di	·	41. Distance from and
Name of Established D	istrict		Frontage on Road
	•		50 yards
possibly obscur on primary afac them, all flank	ed by addition of ade, two on the f ed by windows. The spindle ornament ceilings. #36.	cades are devoid of ornamentation metal siding. Has three entrancing its story, a third centered above two interior stove chimneys of britation and turned posts. Interior its small addition has been added obscures original clapboarding.	e ck. Photo
has original 10 the west facade	original.	•	
has original 10 the west facade Windows are not	original.		
has original 10 the west facade Windows are not	original.	ntractors McCullen and Arnote.	
has original 10 the west facade Windows are not	original.	ntractors McCullen and Arnote.	
has original 10 the west facade Windows are not	original.	ntractors McCullen and Arnote.	· ·
has original 10 the west facade Windows are not History and Significan A farmhouse, bu	original.	ntractors McCullen and Arnote.	
has original 10 the west facade Windows are not History and Significan A farmhouse, bu  Description of Enviror On a farm of 61	original.  ce  ilt in 1904 by con  ment and Outbuildings  acres. with gar	ntractors McCullen and Arnote.  age and storm cellar on the proper ting from about 1830.	cty. Allen cemetery
has original 10 the west facade Windows are not History and Significan A farmhouse, bu  Description of Environ On a farm of 61 ajoins the farm	original.  ce ilt in 1904 by con ment and Outbuildings acres, with gar a on the east, da	age and storm cellar on the proper	cty. Allen cemetery
has original 10 the west facade Windows are not History and Significan A farmhouse, bu  4 Description of Enviror On a farm of 61	original.  ce ilt in 1904 by con ment and Outbuildings acres, with gar a on the east, da	age and storm cellar on the proper	46. Prepared by Tom Stokes
has original 10 the west facade Windows are not History and Significan A farmhouse, bu  4 Description of Environ On a farm of 61 ajoins the farm	original.  ce ilt in 1904 by con ment and Outbuildings acres, with gar a on the east, da	age and storm cellar on the proper	46. Prepared by Tom Stokes 47. Organization
has original 10 the west facade Windows are not History and Significan A farmhouse, bu  4 Description of Enviror On a farm of 61 ajoins the farm  5 Sources of Informatio	original.  ce ilt in 1904 by con ment and Outbuildings acres, with gar a on the east, da	age and storm cellar on the proper	46. Prepared by Tom Stokes

On-site inspection.



FLOORPLANS

NOT TO SCALE




PHOTOGRAPH



## Office of Historic Preservation, P.O. Box 176, Jefferson City, Missouri 65101 HISTORIC INVENTORY

1 No	4 Pre	Sent Name(s)	
2		lmire Christian Church	
Ray	5 017	ner Namo(s)	
3 Location of Negatives RCHS			
6 Specific Lucation	wy.c	16 Thematic Calegory	20 No of Stories one
At Elmira, take	first right	030	29. Basement? Yes
on unmarked road S 9 T54N	to end of road.		No
	al. Township & Vicinity	ca. 1880	brick 30
	Township	Gothic Revival	31. Wall Construction
8 Sile Plan with North Ar	Now /	19. Architect or Engineer	frame wu
(7)	K (3)(3)	unknown 20 Contractor or Builder	32. Roof Type & Material GE
200	1	unknown	gable/asphalt shingl
NU	/N	21. Original Use, if apparent	Front 2 Side 4
	- 1/2	church DUA	24 144-11 7
	110	22 Present Use	weatherboard
etery	N I	ehurch 23 Ownership Public II	35. Plan Shape rectangul
. 1		23 Ownership Public I Private I +	36. Changes Addition (Explain Altered
1	1. 1	24. Owner's Name & Address,	in #42) Moved
~		Elmira Christian ChurchCongrega	37 Condition
9 Coordinates	UTM	Elmira, Missouri	
Long		25 Open to YesXX	Exterior excellent
Site Li	Structure 1 i	Public? No 1 i	38. Preservation Yes Underway? No
Building iX	Object 1 1	26 Local Contact Person or Organization	39 Endangered? Yes
Rigister? No IX	12 Is It Yes A		By What? No
3 Part of Estab Yes II	14. District Yes II	27. Other Surveys in Which Included	
Hist Dist.? No IX	Potent'l? No X		40. Visible from Yes: Public Road? No
15 Name of Established D	strict		41. Distance from and
			Frontage on Road
windows with tre displays triple windows. Bell t transom under po capped by pysam are the addition  13 History and Significance	tructure with dis foil tracery and window, secondar, owar contains pr inted arch similar idal roof. #36: of electricity	wooden hood moldings. Primary far wooden hood moldings. Primary far y facades have four regularly space imary entrance, doubleleaf door with ar to those of the windows. Tower Only alterations to the structure and the construction of a basement evival church in Ray County.	cade ed th
Sources of Information	the small town or	f Elmira. Beyond a wooded tract be	46. Prepared by
On-site inspecti	On.		Cameron
			RCHS & M
			48 Date 49 Revision Date(s)
			8/80



FLOORPLANS


NOT TO SCALE



**PHOTOGRAPH** 



Office of Historic Pres	VENTORY  Jefferson	City, Missouri 65101
3 Un Ray 5 Oth	sent Name(s) nknown er Name(s)	
Ja	Inc. Thematic Category	28. No. of Stories $1\frac{1}{2}$
7 City or Yown If Ruel, Township & Vicinity Elaira Polk township  Site Plan with North Arrow	17 Date(s) or Period ca. 1925 18 Style or Design bungalow 19 Architect or Engineer unknown	29. Basemeni?  Yes IX No 1.  30. Foundation Material concrete  31. Wall Construction frame  32. Roof Type & Material gable-asphalt shingles
	20. Contractor or Builder unknown  21. Original Use, if apparent residence  22 Present Use vacant  23 Ownership Public I ! Private IX!  24. Owner's Name & Address, if known	33. No. of Bays Front 1 Side 2 DR  34. Wall Treatment stucco  35. Plan Shape Square  36. Changes Addition: (Explain Altered I in #42) Moved I
Coordinates UTM Lat Long  Site 1 Structure Li	unknown  25. Open to Yes !! Public? No k!	37. Condition Interior POOT  Exterior POOT  38. Preservation Yes Underway? No X
1 On National Yes II No K Eligible? No II  3 Part of Estab Yes II Hist Dist? No 80 Potent'!? No K  5 Name of Established District	26. Local Contact Person or Organization  27. Other Surveys in Which Included	39 Endangered? Yes !! By What? No x neglect  40 Visible from Yes X Public Road? No !:  41. Distance from and Frontage on Road
veranda across front primary fac secondary facade. Two interior	use is in poor condition. Features ade. Roof dormers at center of eac central brick chimneys for stoves.	
House is said to have been built  Description of Environment and Outbuildings	by Charles James, a second cousin	of Jesse James.
An a wooded lot in the small tow	m of Elmira. The lot is not kept u	ip.
Sources of Information  Personal knowledge.		46. Prepared by Tom Stokes 47. Organization
On-site inspection.		RCHS & M  48. Date 49 Revision Date(s) 6/79



FLOORPLANS

NOT TO SCALE




PHOTOGRAPH



ARCHITECTURAL/HISTORIC	INVENTORY SURVEY FORM	RA-AS-002-151
. NO. 39	4. PRESENT LOCAL NAME(S) OR DESIGNATION(S)  Jackson Residence	
Ray  8. LOCATION OF RCHS	5. OTHER NAME(S) Albright. Lollar	
6. SPECIFIC LEGAL LOCATION TOWNSHIP 54 RANGE 29 SECTION IF CITY OR TOWN, STREET ADDRESS	34 16. THEMATIC CATEGORY	28. NO. OF STORIES ONE
CITY OR TOWN IF RURAL, VICINITY	ca. 1830	ashlar stone
vic. Lawson Polk twp.	vernacular dog to t	Tog and frame C
B. DESCRIPTION OF LOCATION	- unknown	32 ROOF TYPE AND MATERIAL
	20. CONTRACTOR OR BUILDER unknown	gable-comp. shingles 7
6	21. ORIGINAL USE, IF APPARENT residence	34. WALL TREATMENT
0	22. PRESENT USE residence	asbestos siding #9 35. PLAN SHAPE rectangula
	23. OWNERSHIP PUBLIC PRIVATE	(X) (EXPLAIN IN NO. 42)
	24. OWNER'S NAME AND ADDRESS IF KNOWN	MOVED (
. COORDINATES UTM	Gene Jackson Route 1 Box 338, Lawson, Misson	INTERIOR GOOD
LONG O. SITE ( ) STRUC	25. OPEN TO PUBLIC? YES	38. PRESERVATION YES (
BUILDING (X) OF	YES ( )	TION # 39. ENDANGERED? YES ( BY WHAT? NO ()
REGISTER ? NO (X) ELIGIBLE ?  3. PART OF ESTAB. YES ( ) 14. DISTRICT POTENTIAL	YES ( )	40. VISIBLE FROM YES (
15. NAME OF ESTABLISHED DISTRICT	100018	41. DISTANCE FROM AND FRONTAGE ON ROAD 400 ft.
42. FURTHER DESCRIPTION OF IMPORTANT	FFATURES	400 10.
Original structure was a two- end. Additions have been adde facades, and the whole structu detail remains around windows	room dog-trot with fireplace at each d to the east and west (secondary) are sheathed with asbestos siding. Some from earlier addition, ca. 1880.	ne BE
house across the road and used	nouse was at one time in the Albright of this structure for a corn crib. When se, put in a new wood floor and parition several additions.	the larger house burned,
44. DESCRIPTION OF ENVIRONMENT AND On small farm outside of the		
45. SOURCES OF INFORMATION On-site inspection. Present owners		Kindred/Vermillion
		48 CATE 149. REVISION DETECT

MISSOURI OFFICE OF HIS UNIC PRESERVATION



FLOORPLANS

NOT TO SCALE




PHOTOGRAPH



Office of Historic Preservation, P.O. Box 176, Jefferson City, Missouri 65101
HISTORIC INVENTORY

County		sent Name(s)	
		Zimmerman House	
Ray		ner Namo(s)	
3 Location of Negatives RCHS &	M		
Specific Lucation	north of Lawson	16 Thematic Category	28 No of Stories two
	, 2 miles east on	030	29. Basement? Yes
unmarked gravel	and dirt road.	17 Date(s) or Period	No
7 City or Town II Ru	ural, Township & Vicinity	ca. 1833	30. Foundation Material
vic. Lawson Po	olk twp.	vernacular/Neoclassic details	ashlar stone 40
8 Site Plan with North	C. Cayona	19. Architect or Engineer	frame .
HUNG D IIII	Will COU	unknown	32. Roof Type & Material
	WIN C	20. Contractor or Builder	gable-asphalt shingle
		John Zimmerman 21. Original Use, if apparent	33. No. of Bays Front 3 Side
and the	YMA	residence OrA	34. Wall Treatment
E3 6-	- 6	22 Present Use	clapboarding
2 L	7 6	residence	35. Plan Shape rectangular
大	「大大大 本が	23 Ownership Public I Private(KI	36. Changes Addition 3
3	200	24. Owner's Name & Address.	(Explain in #42) Moved
<u> </u>	W	if known	37 Condition
Coordinates	UTM	Mr&Mrs. George Klein	Interior good
Luny S ald	54N 29W	26.0	Exterior fair
Site 11	Structure 1 ;	25 Open to Yes I I Public? No kil	38. Preservation Yes
Building i 1	Object I I	26. Local Contact Person or Organization	Underway? Nox
1 On National Yes I I Register? No k	12 Is It Yes IX	or organization	39 Endangered? YesXi By What? No I
Rugister? No 1X	Eligible? No 11	27. Other Surveys in Which Included	vacancy
Hist Dist.? No X	14. District Yes II		40. Visible from Yes
	District		Public Road? NoXX
Name of Established L			
5 Name of Established (			Mal. Distance from and
	Imagelon F		Frontage on Road
2 Further Description of I-house with unus	ual decorative fe	atures. Singleleaf primary entrance	Frontage on Road
2 Further Description of I-house with unus in center is topp	ual decorative fe ed with trabeated	atures. Singleleaf primary entrance transom. All fenestration is fou	Frontage on Road
Further Description of I-house with unus in center is topp over-four light w	ual decorative fe ed with trabeated with Neoclassic li	transom. All fenestration is foun	Frontage on Road
I-house with unus in center is topp over-four light w nailed with handw	ual decorative fe led with trabeated with Neoclassic li Brought nails. Al	transom. All fenestration is foun ntels. Weatherboarding is beaded a so corner pilasters with capitals	Frontage on Road
2 Further Description of I-house with unus in center is topp over-four light w nailed with handw are beaded. Neoc	ual decorative fe ed with trabeated with Neoclassic li prought nails. Al	transom. All fenestration is foun ntels. Weatherboarding is beaded a so corner pilasters with capitals th returns. Most important feature	Frontage on Road
2 Further Description of I-house with unus in center is topp over-four light w nailed with handw are beaded. Neoc is decoration of	ual decorative fe ed with trabeated with Neoclassic li prought nails. Al classic cornice wi frieze on primary	transom. All fenestration is foun ntels. Weatherboarding is beaded a so corner pilasters with capitals th returns. Most important feature facade: a row of large muntins	Frontage on Road  Photo
2 Further Description of I-house with unus in center is topp over-four light w nailed with handw are beaded. Neoc is decoration of with drilled hole	dual decorative fe ded with trabeated with Neoclassic li- drought nails. Al- lassic cornice wi- frieze on primary as on the bottom of	transom. All fenestration is fountels. Weatherboarding is beaded as corner pilasters with capitals the returns. Most important feature facade: a row of large muntins feach, substituting for bells.(cor	Frontage on Road  Photo
2 Further Description of I-house with unus in center is topp over-four light w nailed with handw are beaded. Neoc is decoration of with drilled hole Built by John Zim	dual decorative fe ded with trabeated with Neoclassic li- prought nails. Al- classic cornice wi- frieze on primary as on the bottom of the merman soon after	transom. All fenestration is fountels. Weatherboarding is beaded as corner pilasters with capitals the returns. Most important feature facade: a row of large muntins feach, substituting for bells. (con his arrival in Ray County in 1882)	From Toppossoo His
I-house with unus in center is topp over-four light w nailed with handw are beaded. Neoc is decoration of with drilled hole History and Significance Built by John Zimparents came from	dual decorative feed with trabeated with Neoclassic librought nails. All lassic cornice wifrieze on primary son the bottom of the merman soon after Pennsylvania. He	transom. All fenestration is fountels. Weatherboarding is beaded as corner pilasters with capitals the returns. Most important feature facade: a row of large muntins feach, substituting for bells. (con his arrival in Ray County in 1883 arrival to Polly Coffman on the was married to the was married to the was married to the was married to the was marrie	from Tennessee. His
I-house with unus in center is topp over-four light w nailed with handw are beaded. Neoc is decoration of with drilled hole History and Significance Built by John Zimparents came from came to Ray on the	dual decorative fe ded with trabeated with Neoclassic li- prought nails. Also lassic cornice wi- frieze on primary son the bottom of merman soon after Pennsylvania. He e night of "falling	transom. All fenestration is fountels. Weatherboarding is beaded as corner pilasters with capitals the returns. Most important feature facade: a row of large muntins feach, substituting for bells. (con his arrival in Ray County in 1883 was married to Polly Coffman on And Stars" a meteor shower which was not stars, a meteor shower which was	from Tennessee. His August 9, 1818. The two
I-house with unus in center is topp over-four light w nailed with handw are beaded. Neoc is decoration of with drilled hole History and Significance Built by John Zimparents came from came to Ray on the by the new settle John Zimmerman fit	dual decorative feed with trabeated with Neoclassic liver of the Neoclassic liver of the Neoclassic liver of the Neoclassic liver of the Neoclassic cornice with frieze on primary of the Neoclassic cornice with the Neoclassic liver of the Neoclass	transom. All fenestration is fountels. Weatherboarding is beaded as corner pilasters with capitals the returns. Most important feature facade: a row of large muntins feach, substituting for bells. (con his arrival in Ray County in 1883 as was married to Polly Coffman on Ang stars" a meteor shower which was on the banks of Crooked River (the	from Tennessee. His August 9, 1818. The two is said to be a good omen
over-four light we nailed with handwe are beaded. Neoc is decoration of with drilled hole with drilled hole. History and Supplicance Built by John Zimparents came from came to Ray on the by the new settle John Zimmerman fit Description of Environment.	dual decorative feed with trabeated with Neoclassic liver on the lassic cornice with frieze on primary on the bottom of the pennsylvania. He e night of "fallings. They settled the pennsylvania of the pennsylvania of "fallings" they settled the pennsylvania of the pennsylvania of the pennsylvania. He e night of "fallings" they settled the pennsylvania of the pennsy	transom. All fenestration is fountels. Weatherboarding is beaded as corner pilasters with capitals the returns. Most important feature facade: a row of large muntins feach, substituting for bells. (con his arrival in Ray County in 1883 as was married to Polly Coffman on Ang stars" a meteor shower which was on the banks of Crooked River (the total the river and built a mill to gri	from Tennessee. His August 9, 1818. The two is said to be a good omen
I-house with unus in center is topp over-four light w nailed with handw are beaded. Neoc is decoration of with drilled hole History and Significance Built by John Zimparents came from came to Ray on the by the new settle John Zimmerman fit Description of Environm On a still working	dual decorative feed with trabeated with Neoclassic liverought nails. All relations on the bottom of the pennsylvania. He enight of "fallings. They settled rest built a dam or bent and Outbuildings of farm, at the end	transom. All fenestration is fountels. Weatherboarding is beaded as corner pilasters with capitals the returns. Most important feature facade: a row of large muntins feach, substituting for bells.(con his arrival in Ray County in 1883 e was married to Polly Coffman on Ang stars" a meteor shower which was on the banks of Crooked River (the the river and built a mill to grid of private road. Many farm	from Tennessee. His August 9, 1818. The two is said to be a good omen en called Crooked Creek) and grain and saw (cont)
I-house with unus in center is topp over-four light w nailed with handw are beaded. Neoc is decoration of with drilled hole with drilled hole Built by John Zimparents came from came to Ray on the by the new settle John Zimmerman find Description of Environm On a still working contemporary with	dual decorative feed with trabeated with Neoclassic live of the Neoclassic live of the Neoclassic live of the Neoclassic live of the Neoclassic cornice with frieze on primary of the Neoclassic cornice with son the bottom of the Neoclassic live of the N	transom. All fenestration is fountels. Weatherboarding is beaded as corner pilasters with capitals the returns. Most important feature facade: a row of large muntins feach, substituting for bells. (con his arrival in Ray County in 1883 e was married to Polly Coffman on Ang stars" a meteor shower which was on the banks of Crooked River (the the river and built a mill to gri	from Tennessee. His August 9, 1818. The two is said to be a good omen en called Crooked Creek) and grain and saw (cont)
I-house with unus in center is topp over-four light w nailed with handw are beaded. Neoc is decoration of with drilled hole with drilled hole built by John Zimparents came from came to Ray on the by the new settle John Zimmerman fire Description of Environm On a still working contemporary with arround the house	dual decorative feed with trabeated with Neoclassic live of the Neoclassic live of the Neoclassic live of the Neoclassic live of the Neoclassic cornice with frieze on primary of the Neoclassic cornice with son the bottom of the Neoclassic live of the N	transom. All fenestration is fountels. Weatherboarding is beaded as corner pilasters with capitals the returns. Most important feature facade: a row of large muntins feach, substituting for bells.(con his arrival in Ray County in 1883 e was married to Polly Coffman on Ang stars" a meteor shower which was on the banks of Crooked River (the the river and built a mill to grid of private road. Many farm	from Tennessee. His August 9, 1818. The two is said to be a good omen en called Crooked Creek) and grain and saw (cont)
I-house with unus in center is topp over-four light w nailed with handw are beaded. Neoc is decoration of with drilled hole with drilled hole built by John Zimparents came from came to Ray on the by the new settle John Zimmerman fire contemporary with a still working contemporary with a sources of Information	dual decorative feed with trabeated with Neoclassic liver ought nails. All lassic cornice with frieze on primary on the bottom of the pennsylvania. He enight of "fallings. They settled rest built a dam or hent and Outbuildings of farm, at the end the house, are interest.	transom. All fenestration is fountels. Weatherboarding is beaded as corner pilasters with capitals the returns. Most important feature facade: a row of large muntins feach, substituting for bells. (con his arrival in Ray County in 1883 was married to Polly Coffman on Ang stars" a meteor shower which was on the banks of Crooked River (then the river and built a mill to grid of private road. Many farm but disrepair. Many large trees and	from Tennessee. His August 9, 1818. The two said to be a good omen en called Crooked Creek) and grain and saw (cont) wildings, not original plantings
I-house with unus in center is topp over-four light w nailed with handw are beaded. Neoc is decoration of with drilled hole with drilled hole built by John Zimparents came from came to Ray on the by the new settle John Zimmerman find the new settle John Zimmerman on a still working contemporary with Irround the house security settless the settless than the new settless than the	dual decorative feed with trabeated with Neoclassic liver ought nails. All lassic cornice with frieze on primary son the bottom of the pennsylvania. He enight of "fallings. They settled rest built a dam or the house, are in the house, are in the mouse, are in the mouse.	transom. All fenestration is fountels. Weatherboarding is beaded as corner pilasters with capitals the returns. Most important feature facade: a row of large muntins feach, substituting for bells.(con his arrival in Ray County in 1883 e was married to Polly Coffman on Ang stars" a meteor shower which was on the banks of Crooked River (the the river and built a mill to grid of private road. Many farm	from Tennessee. His August 9, 1818. The two is said to be a good omen en called Crooked Creek) and grain and saw (cont)
I-house with unus in center is topp over-four light w nailed with handw are beaded. Neoc is decoration of with drilled hole with drilled hole built by John Zimparents came from came to Ray on the by the new settle John Zimmerman find the new settle John Zimmerman on a still working contemporary with Irround the house securces of Information Richmond Missourie	dual decorative feed with trabeated with Neoclassic liver ought nails. All lassic cornice with frieze on primary son the bottom of the pennsylvania. He enight of "fallings. They settled rest built a dam or the house, are in the house, are in the mouse, are in the mouse.	transom. All fenestration is fountels. Weatherboarding is beaded as corner pilasters with capitals the returns. Most important feature facade: a row of large muntins feach, substituting for bells.(con his arrival in Ray County in 1883 was married to Polly Coffman on Ang stars" a meteor shower which was on the banks of Crooked River (the name that the river and built a mill to grid of private road. Many farm but of private road. Many farm but of disrepair. Many large trees and disrepair. Many large trees and disrepair.	from Tennessee. His August 9, 1818. The two is said to be a good omen on called Crooked Creek) and grain and saw (cont) wildings, not original plantings  46. Prepared by Cameron, Richardson  47. Organization
I-house with unus in center is topp over-four light w nailed with handw are beaded. Neoc is decoration of with drilled hole  History and Significance Built by John Zimparents came from came to Ray on the by the new settle John Zimmerman fither the new settle John Zimmerman fither a still working contemporary with Irround the house sources of Information	dual decorative feed with trabeated with Neoclassic liver ought nails. All lassic cornice with frieze on primary son the bottom of the pennsylvania. He enight of "fallings. They settled rest built a dam or the house, are in the house, are in the mouse, are in the mouse.	transom. All fenestration is fountels. Weatherboarding is beaded as corner pilasters with capitals the returns. Most important feature facade: a row of large muntins feach, substituting for bells.(con his arrival in Ray County in 1883 was married to Polly Coffman on Ang stars" a meteor shower which was on the banks of Crooked River (the name that the river and built a mill to grid of private road. Many farm but disrepair. Many large trees and ition" Dec. 13, 1928.	from Tennessee. His August 9, 1818. The two said to be a good omen on called Crooked Creek) and grain and saw (cont) wildings, not original plantings  46. Prepared by Cameron, Richardson



FLOORPLANS

NOT TO SCALE



PHOTOGRAPH




Office of Historic Preservation, P.O. Box 176, Jefferson City, Missouri 65101

HISTORIC INVENTORY

No 40	4 Present Name(s) Taylor Property	
County Ray	5 Other Namo(s)	
Location of Negatives & M	Crowley House	
	16 Thematic Calegory	28 No of Stories ZWO
rom Lawson, 1/2 mile sout nmarked gravel road whi	h on 030	29. Basement? Yes I
xtension of Route 00	ca. 1870	30. Foundation Material ashlar stone 40
LUYON VEC. POLK top."	ship & Vicinity 18 Style or Design, vernacular	42 09 31. Wall Construction
Site Plan with North Arrow	19. Architect or Engineer unknown	brick LD  32, Roof Type & Malerial H
	20. Contractor or Builder	hipped-wood shingles
WHILLIAM	unknown 21. Original Use, if apparent	Side 1
	residence OIA	34 common Sond brick 2
W	hay barn	35. Plan Shape RC
	23 Ownership	Public 1 36. Changes Addition Private 136 (Explain Altered Moved
57 T5 30 R 39	24. Owner's Name & Address,	37 Condition
Coordinates UTM	Jimmie Taylor	Interior pook Exterior pook
Lal	Lawson, Missouri 25 Open 10	Yes I 38. Preservation Yes
Site 11	Structure 1 i Public?	No lyl Underway? No
On National Yes II 12 Is	Object 1 26 Local Contact Person or Organ	By What? No
Thingston 110 %	igible? No文1 27. Other Surveys in Which Includ	40. Visible from Yes
Hist Dist.? No M	otent'l? No i	Public Road? No
Name of Established District		Frontage on Road
Further Description of Importa	of Features	
ernacular building has attern is 2/2 light wo pediment shaped windowntrance at each story; transoms and sidelights	unusual decorative details. Fenest oden sash, under a segmental arch, so whead. 3 bay primary facade has ce identical, they feature segmental a under pediment shaped heads. Center wo story portico with hipped roof, so pilasters. Interior has been decime	ert under entral vrched bay of supported by
3 History and Significance		· ·
his parents had come to	ility built for John Crowley, vice- Missouri in 1816 and entered this f 812. John Jr. inherited his farm of ter he returned to Ray County and ma	{ 2300 acres. He drove herd to
4 Description of Environment ar to original plantings routbuildings to the wes	emain. The house is in the center o	of plowed fields, with modern
5 Sources of Information		46. Prepared by
In-site inspection.		Cameron
Ray County History, 188	1 Clay, Ray, Carroll, etc.	A7 Organization RCHS & M

- 42 Cont. use as a hay barn; stairway in center hall has been removed. However, woodwork, which is heavy and plain, remains. Exterior details include molded, boxed cornice, plain frieze, and bell-shaped hipped roof.
- #43. Cont. They were the parents of 9 children. John then married Mrs. Carrie S. Pigeon, At one time, he bred cattle, but by 1896 he was engaged in general agriculture and stock raising. In 1867, he entered for the first time in banking in Richmond, and later became vice-president of the bank Later Ray County Atlases show the house and land owned by Carrie S. Crowley by 1914.



FLOORPLANS

NOT TO SCALE





PHOTOGRAPH






Office of Historic Preservation, P.O. Box 176, Jefferson City, Missouri 65101 HISTORIC INVENTORY

1 No	101110111		
- 41	- Piet	Arley F. Chancellor House	
Ray	5 Oin	er Namo(s)	
3 Location of Negatives		J. Peppard, 1940; William W. Sm	ith Residence, 1877.
6 Specific Lucation		16 Thematic Category	28 No of Stories 2-1-1 two
mile north of	lawson on unmark		29. Basement? Yes Ki
unmarked road se	outh ½ mileto lst	17 Date(s) or Period ca. 1870 alte 1940	No 1
	(cont) (al. Township & Vicinity k twp.	18 Style or Design Federal	30. Foundation Material A 6 ashlar stone/concrete
B Site Plan with North A		19. Architect or Engineer	31. Wall Construction frame
Allixi	Z (2	unknwn; remodelling Edward Buch	1 52. Roof Type & Material HP
Hwy 00 mil	- 4	20. Contractor or Builder Delk unknown	hipped/ comp. shingles
MAN	4 672	21. Original Use, if apparent	33. No. of Bays Front 5 Side 1
	1 c3/L	restience OHA PO	34. Wall Treatment
F	1 6) (9	22 Present Use	wood shingles 20
9		residence	35. Plan Shape rectangular
Visit	7 (50)	23 Ownership Public I Private bil	36. Changes Addition X-
		24. Owner's Name & Address,	in #42) Moved
	4	Arley F. Chancellor	37 Condition
U Coordinates	3N29W	RR 1, Lawson, Missouri 64062	Interior excellent
Luny	SNEAM	25. Open to Yes I i	Extensor excellent
Site Li	Structure 1 i	Public? No XI	38. Preservation Yes Underway? Nox
Buildingx	Object 1 i	26 Local Contact Person or Organization	39 Endangered? Yes II
11 On National Yes II Register? No IX	12 Is It Yes I I Eligible? No Ki		By What? No X
13 Part of Estab Yes II	14. District Yes II	27. Other Surveys in Which Included	
Hist Dist.? No XI	Potent'l? No to		40. Visible from Yes Public Road? No X
15 Name of Established D	district		41. Distance from and
			Frontage on Road  1 mile
42 Further Description of	Important Features		- 11220
I house has been	greatly altered.	Hipped roof replaces original	
Nood siding has	obscureds origina	sidelights and simicircular transoral facade detail. Story additions	1
to north and sou	th facades; porch	over primary entrance. l original	Photo
exterior firepla	ace chimney remain	ns. The other has been rebuilt.'	
Open staircase o	on the interior.		
42 Maria			1
43 History and Significance			
He was horn in N	orth Carolina Mar	t of the Lawson Bank, and of the Ex	change Bank of Richmond.
purchased this s	ite. William was	5, 1827. His father Jedidiah cam the youngest of 5 children. Duri	ie to Ray in 1838 and
ne make a great	deal of money tra	iding in mules. In 1850 with 2 com	manions William
44 Description of Environment	ifornian and open	ned a provision store. A year late	r he returned to (cont)
our or torke tallog	caped for at the	end of a private road. Some origi	nal plantings.
Sources of Information	1000		46. Prepared by
Atlas of Ray ou			Kindred and Vermillion
Biography of Cla	y Ray, Etc.		RCHS & M
Arley Chancellor	On-site	inspection.	48 Date 49 Revision Date(s)
			6/24

#6 Cont. first turn, then east  $\frac{1}{2}$  mile on private road.

#43. Cont. Missouri. He married in 1857 and took charge of his parents farm until 1885, raising mules and cattle. In August 1885, William came to Lawson and resided there, occupying and "elegant residence." In addition to his city property, he owned 2,000 acres in Ray, Clay, Clinton and Caldwell Counties. His wife Sallie was the daughter of John U. Miles, a merchant of Kentucky. William was also a trustee of Lawson College, and part owner of the firm Hurt and Smith, a merchantile establishment in Lawson. The house was built sometime in the 1870's, and "restored" in 1940 by Edward Buchler Delk.



**FLOORPLANS** 

NOT TO SCALE




PHOTOGRAPH



Office of Historic Preservation, P.O. Box 176, Jefferson City, Missouri 65101

1 N:: 139 5	4 Present Name(s)		200
inty .	Watkins House		
Ray	5 Other Namo(s)	ww	
3 Location of Negatives	Brown House Brown Barn 045	GB 50 50 40 RC	
6 Specific Lucation Route 1 ·	16. Thematic Category	28. No. of Stories 2	•
CRI	010 .	29. Basement? Yes !!	5
S23 54N 29k	17 Date(s) or Period	No 1 <sub>X</sub>	4.000
	04, 10/)	30. Foundation Material	-
7 City or Town If Rural, Township !		ashlar stone 90	
H. Site Plan with North Arrow	19. Architect or Engineer	frame	
a Sile Flair with North Allow	unknown	32. Roof Type & Material & A	
	20. Contractor or Builder Propo	gable-comp. shingles	
	unknown	33. No. of Bays	
	21. Original Use, if apparent residence	Front 3 Side 1	7
lout	residence AA	34. Wall Treatment weatherboard • 21	Tresent Namers
0	residence	35. Plan Shape T-shaped	2
	23 Ownership Public !!	36. Changes Addition x	
1 47	Private kd	(Explain Altered K	61.01
	. 24. Owner's Name & Address,	in #42) Moved :	
	James Watkins	37. Condition Interior excellent	
9 Coordinates UTM	Route 1, Box 291, Lwason MO	Exterior excellent	
Long	25. Open to Yes 11	38. Preservation Yes X	
10 Site ! 1 Str	ucture ! i Public? No ly	Underway? No	
	Object     26. Local Contact Person or Organization	39. Endangered? Yes 11	
11 On National Yes   12. Is It	Yes IXI	By What? No 1x	
Register? No ix Eligible?	27. Other Sulveys in which included		
Hist Dist? No by Potent'l	? No by	40. Visible from Yes X' Public Road? No i:	
15 Name of Established District	· · · · · · · · · · · · · · · · · · ·	41. Distance from and	
y		Frontage on Road	
Interior chimneys for #36.: Windows all hav	tures House features little ornamentation, stoves of brick. 6 stoves remain on interes been replaced. The roof is new. A smale ith new entryway. House is currently present owners.		5 Other Name(s)
43 History and Significance			
	s obscure, but Rowe Brown is assumed to ha	ave been the original	
44 Description of Environment and Outb	uildings		
	op and barn are on the property, and are a a garage and a storm cellar.	also being restored.	
		46. Prepared by	
45 Sources of Information			
James Watkins		Tom Stokes 47. Organization	
		Tom Stokes	



FLOORPLANS

NOT TO SCALE






PHOTOGRAPH





Office of Historic Preservation, P.O. Box 176, Jefferson City, Missouri 65101

1 No 5 (p	4 Present Name(s)	
5 County	McCollough Log Barn	
Ray	5 Other Namo(s)	
3 Location of Negatives RCHS & M		
	13 Thematic Category	28 No of Stories One
Hywy 13 north to Caldwe	ell to, line 010 030 140	29. Basement? Yes I
then west on unmarked g	ravel froad 17 Datu(s) or Period	NXK
	road 1/6 m. ca. 1830 Pioneer	30 Foundation Material
vic. Lawson Polk twp.	double crib log barn	stone piles 90
B Site Plan with Acets Argenti	19. Architect or Engineer	10g- 4C Wu
A ATTITUTE OF THE PARTY OF THE	unknown	32. Roof Type & Material
N I	20. Contractor or Builder	gable-tin GB
1)	21. Original Use, if apparent	Front 3 Side
10	barn 09B	34. Wall Treatment
4	22 Present Use	half dovetail notching
	hay barn 23 Ownership	35. Plan Shape rectangular
Million		Private k1 .36. Changes Addition X. (Explain Altered X.
	24. Owner's Name & Address,	in #42) Moved i
9 Coordinates UTM		37 Condition fair
1d 56 54N 8	John McCollough Lawson, Mo.	Extensor fair
Long	25. Open to	Yes I i 38. Preservation Yes
Site 1 i Building i k	Structure 1: Public? Object 1 1 24 Level Contact Occupant	No XI Underway? Nox.
II On National Yes II 12 Is I	20 Local Contact Person of Organiza	, and A
Augister? No K. Eli	igible? No I I 27. Other Surveys in Which Included	neglect
	Istrict Yes I I	40 Visible from Yes X
15 Name of Established District	olent'l? No IX	Public Road? No
The state of Established District		41. Distance from and Frontage on Road
42 Further Description of Importan		Sanada Wa
small, square openings	th half-dovetail notching. Exterior f Center bay remains open at both ends.	Half-
doors lead into each cr	ib. Hay loft above north crib. #36.:	: Frame
	led to each end and one side of the nor	rth crib.
additions have been add		
additions have been add Shed roof has been plac	ed over the additions. On the whole t	they do
additions have been add	ed over the additions. On the whole t	they do
additions have been add Shed roof has been plac	ed over the additions. On the whole t	they do
additions have been add Shed roof has been plac not obscure the origina	ed over the additions. On the whole t	they do
additions have been add Shed roof has been plac not obscure the origina	ed over the additions. On the whole t	they do
additions have been add Shed roof has been plac not obscure the origina	ed over the additions. On the whole t	they do
additions have been add Shed roof has been plac not obscure the origina All History and Significance	ed over the additions. On the whole to the structure.	they do
additions have been add Shed roof has been plac not obscure the origina 43 History and Significance	ed over the additions. On the whole to the structure.  Outbuildings	
additions have been add Shed roof has been plac not obscure the origina 43 History and Significance	ed over the additions. On the whole to the structure.	
additions have been add Shed roof has been plac not obscure the origina  43 History and Significance  14 Description of Environment and In the center of dorman north.	ed over the additions. On the whole to the structure.  Outbuildings	er date is situated to the
additions have been add Shed roof has been plac not obscure the origina  43 History and Significance  44 Description of Environment and In the center of dorman	Outbuildings  It farmland. Vacant house of much late	er date is situated to the
Additions have been add Shed roof has been plac not obscure the origina not obscure the origina of Environment and In the center of dorman north.  Sources of Information Ray County Atlas, 1877. On-site inspection.	Outbuildings  It farmland. Vacant house of much late	er date is situated to the  46. Prepared by Cameron  47 Organization
Additions have been add Shed roof has been plac not obscure the origina of the origina of the center of dorman north.  Sources of Information Ray County Atlas, 1877.	Outbuildings  It farmland. Vacant house of much late	er date is situated to the



FLOORPLANS NO

NOT TO SCALE



PHOTOGRAPH



49 Revision Date(s)


8/80

Office of Historic Preservation, P.O. Box 176, Jefferson City, Missouri 65101

HISTORIC INVENTORY

No 54	4 Present Name(s)	
	Thomas Ogg Residence	
County	5 Other Namo(s)	
Location of Negatives	Webb House; Luther Ogg Hou	
NO.	. 16 Thematic Calegory	28 No of Stories two
Specific Lucation % mile west from Ric	chmond to C;	29. Basement? Yes I
mile to unmarked ru	and south at 117 Daids of Period	30. Foundation Material
irst bend of road.	ca. 1700	ashlar stone 40
City or Town II Rural, To	ownship & Vicinity 18 Style or Design	31. Wall Construction
CC/LITO/100 TOO.	mond twp. vernacular	frame. WW
Sile Plan with North Arrow	( ) unknown	32. Roof Type & Material gable-comp shingles
	20. Contractor or Builder	33. No. of Bays
	unknown 21. Original Use, if apparent	Front 3 Side 1
	residence DIA	comp. shingles 63
	22 Present Use	35. Plan Shape L-shaped
	residence	iblic ! . 36. Changes Addition
	m / 1 1 miletanio	vate Ivi (Explain Altered)
	24. Owner's Name & Address.	111 042)
400	if known	37 Condition good
Coordinates UTA	Thomas Ogg Richmond, Missouri	Exterior good
TH 516 T 52	N 3000	Yes I i 38. Preservation Yes
Long	25 Open to	No ly Underway? No
Site 11 Building is	Structure 1; Object 1   26 Local Contact Person or Organizati	ion 39 Endangered? Yes
	2 is it Yes IX	By What? No
Angister? No 1x	Eligible? No 11 27. Other Surveys in Which Included	40 Visible from Yes
Part of Estab Yes II	14. District Yes !! Potent'!? No ! X	Public Road? No
Name of Established Distr		41. Distance from and Frontage on Road
Name of Established Dis.		, tomage on the
Further Description of Im	portant Features	to near.
Vernacular doublepe	en house with large single story addition to be becaused with addition of composition shing	iles.
Facades have been d	are crowned with lintels. Extended eaves.	Photo
windows and downs t	the Ottomed vocal content	
		1.
3 History and Significance		
De anatte mas ammed	by James W. Webb, a farmer, in 1897. Reco	orded as owned by
luther Dag, with a	house in this location, in 1914.	
20000 - 337		
14 Description of Environme	ent and Outbuildings	
Outhuildings to no	ar of house as well as an extensive garden	Original oak trees in
front of house.	<b>U</b>	
45 Sources of Information		46. Prepared by
	0077 1807 1914.	Cameron
Rya County atlases	s, L877, 1897., 1914.	DOUG & M

On-site inspection



FLOORPLANS

NOT TO SCALE




PHOTOGRAPH



No 5, 55	Dale House	
County  Ray  Location of Negatives	5 Other Namo(s)	
RCHS	16 Thernatic Category	28 No of Stories  - ) one
Specific Location west of Richmond	i on 030	29. Basement? Yes )
To to County Road C, nort	th 3/4 17 Dale(s) or Period	30. Foundation Material
mi. to unmarked road, seast	ca. 1860	ashlar stone 90
City or Town If Rural, Township &		31. Wall Construction
Richmond vic. Richmond	19. Architect or Engineer	frame .wu
	unknown	gable-seamed tin
Hwb. C (O)	20. Contractor or Builder Moses Dale	33. No. of Bays
$\omega$	21. Original Use, if apparent	Front 5 Side 2
	residence OIf	34. Wall Treatment
	22 Present Use	weatherboard
	residence (temp. vacant)	35. Plan Shape L-shaped
	23 Ownership Public   1 Private   X	36. Changes Addition (Explain Altered
(3)	24. Owner's Name & Address,	in #42) Moved
	if known	37 Condition good
Coordinates UTM	Dick Dale	Interior
101 SIS TOON & 28	Richmond, Missouri	Exterior good
Long	25 Open to Yes 11	38. Preservation Yes Underway? No
	cture 1: 26 Local Contact Person or Organization	39 Endangered? Yes
1 On National Yes II 12 Is II	Yes by	By What? No
Register? No X: Eligible?	No 11 27. Other Surveys in Which Included	
Part of Estab Yes I 14. District Hist Dist.? No U Potent'l?	Yes III	40. Visible from Yes Public Road? No
X		41. Distance from and
5 Name of Established District		Frontage on Road
Fine example of Greek Re	evival cottage. Original house had two	
rooms, with 5 bay primar doorway has 11 light tra Pilasters flank the door vernacular flavor. A la 1880; later the south powas loval to the origina	ry elevation and central entrance. This ansom with sidelights and panelled revea way. Trabeated 6/6 light windows of arge 1 story addition was added to rear orch of rear el was enclosed. This addition was added to rear all Neoclassic detailing of the house (co	ca photo
13 History and Significance		, 1
M D-1 1070 E:	Isaac Dale in 1834. The house was cons ather had large frame I-house on adjoin is now owned by a descendent of Moses I	ITIU DEBBELLY (IIOW
44 Description of Environment and Outb	uildings	
	ound the house, which is situated on a	low hill.
45 Sources of Information		46. Prepared by
TO SUBICES VICINIVINICATION		140: 1:000:00 01
	3.	Cameron
Ray County History, 197	3.	
	3.	Cameron

continuing boxed commice with returns, frieze and pilaster #42. Cont. corner boards with capitals. House retains Neoclassic porch which originally covered center bay of primary facade; it carries full entablature and presents central gable, covered with imbricated shingles (later addition). It is supported by incongruous turned posts, also a later alteration from original posts with capitals. The interior retains most of its original hardware, two panel doors and pine woodwork with shouldered architrave trimming around doors and window surrounds. Original porch covered only central bay of primary elevation; there have been extensions constructed to either side covering the three central bays.. These were added ca. 1890; original porch had paired posts. In 1880, judging from old photograph of the house, the house had still one exterior brick chimney; the other had been replaced with a stove chimney, also of brick. Both have now been replaced.



FLOORPLANS

NOT TO SCALE




PHOTOGRAPH



No 20 28		saiah Mansur House		
County Ray		5 Other Namo(s)		
Location of Negatives		•		
RCHS & M			28. No of Stories 2-1	
Specific Lucation Route	e E, Richmond	16. Thematic Category	29. Basement? Yes 12	
ut of Richmond, ta	ake B north to	17 Date(s) or Period	No I	
west to E south,	then 3/8 mile.	1842	30. Foundation Material	
12 T53N 27W	Township & Vicinity	18 Style or Design	ashlar stone 40	
Richmond Townshi		Federal	31. Wall Construction	
Site Plan with North Arro		19. Architect or Engineer	log/brick Le La 32. Roof Type & Maleria & B	
ا ش	$m\omega$	unknown 20. Contractor or Builder	gable-comp, shingles	
	log	Isaiah Mansur	33. No. of Bays	
110	L portion	21. Original Use, if apparent	Front 5 Side	
16 (2)		residence OA	34. Wall Treatment 2 / 30	
		22 Present Use	clapboard/common bond	
	C	residence	35. Plan Shape T-shaped  36. Changes Addition	
	-63	23 Ownership Public 1! Private   1/2	36. Changes (Explain in #42)  Addition (Altèred Moved	
	00	24. Owner's Name & Address,	111 11-21	
ROUTE E		if known	37. Condition good	
Coordinates	JTM	multiple ownership-see con't.	Exterior good	
Lat		25 Open to Yes I i	38. Preservation Yes	
Long		Public? No 00	Underway? No	
Site 1   Building X	Structure     Object	26. Local Contact Person or Organization	39 Endangered? Yes By What? No	
On National Yes II Register? No X	12 Is II Yes 1% Eligible? No I I			
Part of Estab Yes II	14. District Yes II		40. Visible from Yes Public Road? No	
Hist Dist.? No D	Potent'l? No ly	MIBOURIE MEDICE	41. Distance from and	
Name of Established D	estrict	Catalogue	Frontage on Road 60 ft.	
under a low gable the joists unde house, with bar	on the property roof, had a lov r the cabin may k still clinging	Rear portion of house is of walnut, and the veranda across the primary facade still be seen in the basement of the to some of them. The newer portion years later, in the common vernace has two rooms at each end of two states.	the Photo cular	
"1-type". The	pollman and a contract to the state of the s	taircase. Interior chimneys at each	ch (ca't)	
wilderness area arrived, Mansur addition to the merchant, and hi and only two own	northeast of Rice recorded that he house was added a son Isaiah Marers, the house ment and Outbuildings	r I came to Ray County in 1837, how chmond. He constructed his first he e carried with him elegant househol by Mansur in 1856. Isaiah Mansur nsur II inherited both business and is owned by sons of the second Isai	nesteading 300 acres in house in 1842. When he ld furnishings. The I was a farmer and a l farm. Today, after 13 lah, Cramer and Charles. (con	
House is located	on a farm of 3	60 acres, the same originally homes	steaded by Isaiah.	
A well house is	to the leaf of	offe Homo.		
A well house is	to the rear or	one nowe.		
A well house is		0,10 110 table 8	46. Prepared by	
A well house is			Mr.& Mrs. Penny	
A well house is	1			

#24. Con't. Cramer Mansur
1710 Webster St.
Chillicothe, Missouri
Charles Mansur
1750 N. Guier Rd.
St. Louis, Missouri

- #42. Con't. end serve fireplaces in each room. The interior features a walnut banister on the staircase, which was brought by Isaiah Mansur when he came to Ray County in 1837. Mantels of two of the five fireplaces, all of which are still working, are solid walnut 3" thick, and were cut from the timbers of the original barn on the property. #36.: Aside from the first large addition to the front, the house has undergone little change throughout the years. In the middle 1900's a modern water system and electricity were added.
- #43. Con't. Isaiah was born in Vermont in 1815. He moved to St. Louis in 1836 and for a year took charge of his brother Charles' drug store. The brothers preferred country life, however, and sold out and moved to Ray County where they began a country store. In 1842, they dissolved their partnership and divided the lands purchased during their business. Isaiah received chiefly the "unimproved lands" where he built his house.



FLOORPLANS NOT TO SCALE





Ogg and Brown

49 Revision Date(s)

47. Organization RCHS & M

48. Date

Office of Historic Preservation, P.O. Box 176, Jefferson City, Missouri 65101


HISTORIC INVENTORY 4 Present Name(s) No Cox Residence 2 County 5 Other Namo(s) Ray 3 Location of Negatives 26. No of Stories 16. Themalic Category Yes IX 61 Specific west of Richmond on Route 29. Basement? partial No 1. 10; take <u>FE</u> south ½ mi. to unmarke 17 Date(s) or Period dirtzroad east; lamile. 30. Foundation Material ca. 1900 ahslar stone 18 Style or Design Il Rural, Township & Vicinity 31. Wall Construction 7 City or Town vernacular Richmond Vic. Richmond twp. frame . Wu 19. Architect or Engineer 8 Sile Plan with North Arrow 32. Roof Type & Material 53 T5N 28W unknown gable-asphalt singles 20. Contractor or Builder 33. No. of Bays unknown Front n/a n/a 21. Original Use, if apparent 34. Wall Treatment residence OIA weatherboard 22 Present Use residence rectangula 35. Plan Shape Addition & 36. Changes Public !! 23 Ownership Altered 1% (Explain Private U Moved I in #42) 24. Owner's Name & Address. 37. Condition if known good Interior J. Cox good UTM Exterior Coordinales Richmond, Missouri Lat Preservation Yes Yes I i 25. Open to No X Long Underway? No KI Public? Structure 1 i Site 11 Yesil 39 Endangered? 26. Local Contact Person or Organization Object | | Building KI No IX By What? Yesii 12 Is II 11. On National Yesil 27. Other Surveys in Which Included No IX Eligible? NO K Register? Yes 'X Visible from Yes II 14. District Part of Estab Yes LI Public Road? No i i No IX Potent'l? Hist Dist.? 41. Distance from and 15 Name of Established District Frontage on Road 42. Further Description of Important Features Much remodelled house dates from the turn-of-the-century. Additions include large dormer to primary facade and hipped roof extensions; oriel window on south facade; small one story addition to north. Photo Apparently the house burned at one time and the upper story was rebuilt. It has been completely modernized. 43 History and Significance There was no house recorded at this location in 1897. A house appears in the atlas of 1914, when the property was owned by J. D. White. 44 Description of Environment and Outbuildings On a small farm surrounded by farmed land. Large cypress tree in front yard dates from original planting. Modern outbuildings to the rear of house. 46. Prepared by 45 Sources of Information

Ray County Atlases, 1897 and 1914.

Pauline Brown.

Present owner.

On-site inspection.



FLOORPLANS NOT TO SCALE




PHOTOGRAPH



Office of Historic Preservation, P.O. Box	176, Jefferson City, Missouri 6510	)1
Office of Historic Preservation, P.O. Box HISTORIC INVENTORY		
THOTOTHO HTTE		

125	4 Present Name(s) New H	ope Primitive Ba	aptist Church	80 84 2001	
.a.y	5 Other Name(s)	1			
Specific Lucation east of Richmond on Hy		Calegory		No. of Stories	one Yes !!
EE; $2\frac{1}{4}$ miles to unmark road then east 1 mile.		or Period		. Foundation Mater	NoX.
City or Town II Rural, Townshi vic. Richmond Richmon Site Plan with North Arrow	nd Twp. Neocl	assic	31	ashlar stone . Wall Construction	
Site Plan with North Arrow	unkno	or Engi <b>neer</b> wn or or Builder	32	frame  Roof Type & Mategable/comp. s	
11 10		Use, if apparent		No. of Bays	de 4
	resid 22 Present resid	Use		weatherboard Plan Shape rec	
1000	23 Ownershi	Name & Address.			Addition
Guardinates UTM	il known Congr		Hope Church	Condition good  Exterior good	
Site <u>!</u> i	25. Open to Public?		Yes Ki 38.	Preservation Underway?	Yes No ¥
Building X₁  On National Yes Xi 12. Is It Register? No i Eligib	Kes IX	ontact Person or Organ		Endangered? By What?	Yes ! No X
Part of Estab Yes I.I 14. Distri	27. Other Su	rveys in Which Include		Visible from Public Road?	Yes X'
Name of Established District			41.	Distance from and Frontage on Road	
Further Description of Important F Neoclassic church with closed). All doors ar boxed cornice with re- area in the west of th	n two primary entran nd windows have tra turns and pilaster	beated heads. N	Narrow	Photo	
The church was organized 1872, the present built. Brown: William Turchurch.	ldirg was erected a	t a cost of \$600	and dedicate	ed by Rev. Wil	liam
Original plantings; lo	•	rea, surrounded	by farmland.		(
Ray County History, 18	381.			Prepared by ameron	



FLOORPLANS


NOT TO SCALE



PHOTOGRAPH



County	26	pent Namo(s)	
		William Proffitt House	
Ray	5 Oth	er Namo(s)	
RCHS			
Specific Lucation			
	Richmond on 10 to	16 Thernalic Calegory	28 No of Stories two
	24 miles s.w. to	17 Date(s) or Period	29. Basement? Ye
unmarked gravel	road, east laile	ca. 1880	30. Foundation Material
City or Town II Ru	ral. Township & Vicinity	18 Style or Design	ashlar stone 40
Richmond vic.		vermacular 09	31. Wall Construction
Sile Plan Willi North A	2	19. Architect or Engineer unknown	frame wu
•	2 11 1	20. Contractor or Builder	32. Roof Type & Material & gable/corregated me
3	WILL	unknown	
5 (/)	3 119	21. Original Use, if apparent	Front 5 Side 1
	300	residence Off	34. Wall Treatment
26	///	vacant	ashhalt siding  35. Plan Shape rectangul
$\sim$ $\omega$	39 514 883	23 Ownership Public !	36. Changes Additio
		Private X !	(Explain Altere
//	59 5/N 28W	24. Owner's Name & Address,	in #42) Move
Coordinates	UTM	Paul Tanner	37 Condition Interior Poer
Lat	01.11		Exterior poor
Long		25 Open to Yes I i	38. Preservation Ye
Site Li Building Ki	Structure 1	Public? No XI	Underway? N
On National Yes ! !	Object	26 Local Contact Person or Organization	39 Endangered? Yes
Angister? No K.	Eligible? No 11	27. Other Surveys in Which Included	By What? Neglect
Part of Estab Yes     Hist Dist.? No to	14. District Yes II	The street of th	40. Visible from Yes
- *	Potent'l? No K		Public Road?
Name of Established C	District		41. Distance from and Frontage on Road
			riontage on Hoad
Eurther Description of	Important Features	don Dulmann Con 11 11 2	
lower window. Staircase and me	Siding has obscure antles. Two end a r for kitchen. #	tion. Primary facada displays cent second story has windows over each of facade detail. Interior has operative channeys. #36: One room 37: house is open to weather and	
lower window. Staircase and maddition to reas	Siding has obscure antles. Two end a r for kitchen. #	ed facade detail. Interior has op	ch walnut
lower window. Statrcase and maddition to real rapidly deterior.  History and Supplicance  Description of Environmatical Surrounded by factors.	Siding has obscure antles. Two end ar for kitchen. #: rating.	ed facade detail. Interior has op	en walnut Photo
lower window. Statecase and maddition to rearrapidly deterior rapidly deterior rapidly deterior rapidly and Significance of Information Surrounded by fa	Siding has obscure antles. Two end ar for kitchen. #: rating.	ed facade detail. Interior has opstove channeys. #36: One room 37: house is open to weather and	pen walnut Photo
lower window. Statrcase and maddition to rear rapidly deterior.  History and Supprisonno.  Description of Environmation Pauline Brown.	Siding has obscure antles. Two end ar for kitchen. #: rating.	ed facade detail. Interior has opstove channeys. #36: One room 37: house is open to weather and	unty.  46. Prepared by Cameron
lower window. Statecase and maddition to rearrapidly deterior rapidly deterior rapidly deterior rapidly and Significance of Information Surrounded by fa	Siding has obscure antles. Two end ar for kitchen. #: rating.	ed facade detail. Interior has opstove channeys. #36: One room 37: house is open to weather and	unty.



FLOORPLANS


NOT TO SCALE



PHOTOGRAPH



6/80



FLOORPLANS

NOT TO SCALE




PHOTOGRAPH



1 Max		Sent Name(s)	
128		Kroupa Residence	
? County Ray	5 Oth	e Namo(s)	
3 Location of Negatives			
RCHS		Brodin House	
West of Richmond on 10	±- 0	16 Themalic Calegory	28 No of Stories two
Road EE, south and west	t 2 miles	17 Date(s) or Period	29. Basement? Yes II
t.51 r. 28 s. 5	e z meces	ca.	No ιχ 30. Foundation Material
7 City or Town II Aural, Tow	nship & Vicinity	18 Style or Design 49	ashlar stone 40
richmond vic. Richmon  B Sile Plan with North Arrow	rd twp.	vernacular	31. Wall Construction
8 Site Plan with North Arrow		19. Architect or Engineer unknown	frame, wu
		20. Contractor or Builder	32. Roof Type & Material GE gable-comp. shingles
		unknown	33. No. of Bays
The second		21. Original Use, il apparent residence 0/A	
*		22 Present Use	34. Wall Treatment metal siding 50
1		residence	35. Plan Shape T-shape
		23 Ownership Public I Private 1	36 Changes Addition x
* *		24. Owner's Name & Address.	(Explain Altered in #42) Moved i
	V	il known	37 Condition
9 Coordinates UTM		Tony S. Kroupa	Interior good
Long		Richmond, Missouri 25 Open 10 Yes 11	38. Preservation Yes
Site 11	Structure 1;	Public? No.t1	38. Preservation Yes Underway? No χ
Building ix	Object 11	26 Local Contact Person or Organization	39 Endangered? Yes II
40	ligible? No I I	27. Other Surveys in Which Included	By What? No X
14 . 5 . 6 . 41 .	District Yes I I	27. Other Surveys in which included	40. Visible from Yes X
Hist Dist.? No 12 P	olent'l? No ½		Public Road? No
13 Marile Of Established District			41. Distance from and Frontage on Road
42 Further Description of Importan	nt Features		
Vernacular house has Qu	een Anne mas	sing with projecting gabled bay or	
primary elevation; porc	h extends ac	ross other two bays. Facado deta	id
replaced by shed realed	the addition	of metal siding; porch has been with bungalow-type posts of brick.	Photo
Gables retain hishscale	shinale det	tails. All windows 1/1.	
0 00000	circing oc act	The west with the same of the	
43 History and Significance			
Atlas of 1877 shows land	d owned by T	homas A. Brown, with no house at a	this location. That of
1891 shows a nouse, and	harm owned	by Henry C. Brown, who undoubtedly	built this house
found the this totation,	uncreasea u	nd came to kay Co. when he was 15. with subsequent purchases until i	t reached 300 acres
Description of Environment and	Outbuildings		
Original plantings in f	nom yara of	nouse.	
5 Sources of Information			A6 Demonstra
On-site inspection			8 Brown and Ogg
Ray County Atlases, 187	7; 1897; 191	4	47 RCHS & Mon
Ray County History, 188	1		
V			48 Date 49 Revision Date(s)

#42 Cont. He married Patsy Crowley, daughter of Jeremiah Crowley, in 1838. They had 15 children, seven of whom survived. On of them, Henry C. apparently inherited this portion of land and built this house. Thomas farmed extensively-raised mules, manufactured cheese and made furniture and caskets. He was also very active in community affairs. His son Henry Crowley Brown (1862-1941) married Naomi Hendrix in 1887. He was a successful farmer. He and Naomi were the parents of 5 children.



FLOORPLANS NOT TO SCALE



PHOTOGRAPH




	4 Present Name(s)	
130	Gowing Residence	
County	5 Olher Namo(s) John Kirkpatrick House	
Location of Negatives RCHS & M	Oom Kirkpaorion mass	
	18 Thematic Calegory	26 No of Stories TWO
Specific Lucation of highway 10 west of Ri	ichmond on	29. Basement? Yes XI
; two miles south and w	West. 17 Date(8) or Period	ashlar stone
Husy EE	ca. 1890	ashlar stone
City or Town II Rural, Towns	ship & Vicinity 18 Style or Design	31. Wall Construction
c. Richmond Richmond	d Twn. vernacular	frame will
Site Plan with North Arrow	19. Architect or Engineer unknown	32. Roof Type & Material GB
~ fa//	20. Contractor or Builder	gable-comp shingles
17	unknown	Front 6 Side ]
/// 4/	21. Original Use, if apparent residence	34. Wall Treatment
		weatherboard 2
a///	22 Present Use residence	35. Plan Shape rectangular
134	S Alle Li	36. Changes Addition
(a)	Private X1	(Explain Altered)
(3)	24. Owner's Name & Address,	27 Condition
0/	Samuel L. Gowing	Interior good
Coordinates UTM		Exterior good
Lat S32 T53N 2	25 Open to Yes I I	Ala Ala
Site 11	Structure 1 i Public? No X	Underway? No 39 Endangered? Yes
Building XI	Object 11 26 Local Contact Person or Organization	By What? No
No National Yes II 12 is Register? No X.	Itigible? No I 27. Other Surveys in Which Included	
Part of Estab Yes II 14. C	District Yes !!	40. Visible from Yes Public Road? No
Hist Dist.? No X1	Polent'l? No (%	41. Distance from and
5 Name of Established District		Frontage on Road
12 Further Description of Importa	and Features	on /
lernacular house has si	x bay primary facade. Two primary entrances (	
	flanked by windows; four windows are spaced above. All fenestration has projecting windows.	
regularly on the story	oclassic ornamentation. A single story porch	on /
nters and the usual ned ne primary facade has to	urned nosts.	
ie primary racade has co	urried poster	
43 History and Significance		Commeties
his is apparently the h	omeplace of the Sanderson Family, although 1	ittle information was
anderson in 1897, when	there is a house indicated on this site; and	by J.N. Sanderson
n 1914.		
44 Description of Environment a	and Outbuildings	•
arge Oak trees of origi	inal planting are in the front yard.	
		The state of the s

45 Sources of Information On-site inspection

Ray County Atlases, 1877; 1897; 1914.

46. Prepared by Ogg and Brown 47 Repanyawon 49 Revision Date(s) 48./801e



FLOORPLANS NOT TO SCALE




PHOTOGRAPH



6/80

No 12Q	4 Present Name(s)	
123	Kennedy House	
County	5 Other Namo(s)	
Location of Nemphives	Proffitt House	
NO.	The Thematic Category	28 No of Stories 2 one 1 -
Rec'Highway 10 west	to County 030	29. Basement? Yes X
ute EE; then south		30. Foundation Material
51, R. 28, S. 5	ca. 1910	ashlar stone 70
City or Town Il Rural, To	with two. 18 Style or Design Neoclassical; Italianate	details 31. Wall Construction
c. Richmond, Richmo		Aramo
Site Plan with North Arrow	unknown	32. Roof Type & Material
11 (3) _	20. Contractor or Builder	gable-comp. shinglest
	Luther A. Proffitt. 21. Original Use, if apparent	Front n/a Side 1
11 (, )	residence DIA	34. Wall Treatment
D 4	22 Present Use	Weatherboard
	residence	35. Plan Shape rectangula  Public II: 36 Changes Addition
	23 Ownership	Private I.I (Explain Altered
	24. Owner's Name & Address.	in #42) Moved
(.)	if known	37 Condition excellent
1 0		Exterior excellent
Coordinates UTM		V
Long	25. Open to Public?	Yes II 38. Preservation Yes NoxiXI Underway? No
Site Li	Structure 1: Object 11 26 Local Contact Person or Organi	zation 39 Endangered? Yes
Building iX	2 Is II Yes XI	By What? No
On National Yes	Eligible? No 11 27. Other Surveys in Which Include	d
A	4. District Yes I	40. Visible from Yes Public Road? No
Hist Dist.? No 1%	Potent'l? No X 1	41. Distance from and
Name of Established Distr	ic1	Frontage on Road
	·	
Further Description of Imp	portant Features	nohi /
inely restored hous	e with unusual detailing. Two wall dorm elevation, each with window two primary	i entrances
a - autored an tha	Landdo hovous Ardinoud du welleuws, one on	photo
was land with a	thing mindom thindher all covered	ny a
1 1 . / - 1	TO THE AND AND AND CONTROL AUTHORIZED UN WILKER	1 Customer 1
1 1	THE VI CONTROL TO COOK OF CHILD IN A CONTROL OF THE	. U.S.COMOCOTTO
String courses conne	ct sills of windows of each story. Auth	occor ico vecipi.
3 History and Significance	ly built by Luther A. Proffitt, ca. 1910	0. He was the first son of John
By 1914, the land is	listed in the county atlas as belonging	g to J.t. thaskey. Luther area
1936		
14 Description of Environme		•
Original plantings.	Surrounded by farmland.	
15 Sources of Information		46. Prepared by
		Oga and Brown
On-site inspection. Ray County Atlases,	1877; 1897; 1914.	



FLOORPLANS NOT TO SCALE



PHOTOGRAPH



Office of Historic Preservation, P.O. Box 176, Jefferson City, Missouri 65101

HISTORIC INVENTORY


	· ·	
131	Coggins Residence	
County	5 Other Namo(s)	
Ray		
Location of Negatives	H.C. Brown; G.M. Schooley	The Mo of Stories Two
Specific Lucation	16 Thematic Category	26 40 01 515
To County Route EE from His	ahway 050	29. Basement? Yes 10
10, south 1 mile	17 Date(s) or Period	30. Foundation Material
T. 51; R. 28; Sec. 32	ca. 1920	ashlar stone 40
City or Town II Rural, Township &	Vicinity 18 Style or Design	31 Wall Construction
vic. Richmond; Richmond t	qp. Queen Anne: Neoclassical  19. Architect or Engineer	frame. WU
Site Plan with North Arrow	20	32. Roof Type & Material
~ JUN	20 Contractor or Builder	hipped; comp shingles
(9)	unknown	33. No. of Bays Front n/a Side n/a
	21. Original Use, if apparent	n/a n/o
	residence DIA	34. Wall Treatment weatherboard
	residence	35. Plan Shape square
(h) (3	O. Mile I.I.	36. Changes Addition 3
9 11 6	23 Ownership Public 1 Private XI	(Explain Altered)
. [ ]	24. Owner's Name & Address,	111 442)
	if known	37 Condition good
Covernates UTM	Frank Griffith	Exterior good
Coordinates UTM	Richmond, Missouri	38. Preservation Yes
Long	25. Open to Yes 11 Public? No X1	Underway? No
9	Object   26 Local Contact Person or Organization	39 Endangered? Yes
Building X1		By What? No
1 On National Yes II 12 Is II Register? No X: Eligible	Yes W 27 No ii 27. Other Surveys in Which Included	
Register? No X: Englose  3 Part of Estab Yes I 14. Distric		40. Visible from Yes Public Road? No
Hist Dist.? No XI Potent		41. Distance from and
5 Name of Established District		Frontage on Road
42. Further Description of Important Fe	style massing of dormers and arrangement	06
manimara Manalassia data	iling Two dormers are alsocayed on poun	ary
- Doughiam thair achias a	another in implication suchuces. Williams	Prioro
holow and all honestratio	n has lintels with moturing. Vetarian worth	
Doric columns stretches a	cross primary elevation.	
	·	1
43 History and Significance	in the possession of R. Lewis in 1877, at	which time no house
is shown at this site.	In 1914, the place is listed as G.M. Scho	ooley, who may well have
had the house constructed		

44 Description of Environment and Outbuildings

Rural area, surrounded by farmland.

45 Sources of Information On-site inspection. Ray County Atlases, 1877; 1897; 1914

46. Prepared by Ogg and Brown 47. Organization RCHS & M 48. Date 49 Revision Date(s) 6/80




FLOORPLANS NOT TO SCALE



PHOTOGRAPH



8/80



FLOORPLANS NOT TO SCALE



PHOTOGRAPH



Office of Historic Preservation, P.O. Box 176, Jefferson City, Missouri 65101

HISTORIC INVENTORY

No 133 4 Preser	nt Name(s)	
County	Brown House	
Ray 5 Other	Namo(s)	
Location of Negatives RCHS		
Specific Lucation	16. Thematic Category	28. No of Stories 11/2
oute 10 west from Richmond 1 mile	030 190	29. Basement? Yes I
o Route EE, then south 1 mile. 5. 51, R. 28, S. 8	17 Datu(s) or Period ca. 1840	30. Foundation Material rubble stone
ic. Richmond Richmond Twp.	vernacular; pioneer	31. Wall Construction log and frame
Sile Plan with Nov	19. Architect or Engineer unknown	32. Roof Type & Material & R gable-standing seam t
	20. Contractor or Builder unknown	33. No. of Bays Front 2 Side 1
<b>)</b>	21. Original Use, il apparent residence DIA	34. Wall Treatment weatherboard
	22 Present Use storage	35. Plan Shape
	23 Ownership Public !!	36. Changes Addition (Explain Altered in #42) Moved
	24. Owner's Name & Address, if known Melvin Brown	37. Condition poor
Coordinates UTM	Richmond, Missouri	Exterior poor
Long	25. Open to Yes 11 Public? No XI	38. Preservation Yes Underway? No
Site ! Structure ! i Building : * Object ! !	26. Local Contact Person or Organization	39 Endangered? Yes By What? No
Register? No ½: Eligible? No ½!	27. Other Surveys in Which included	neglect
3 Part of Estab Yes   1		40. Visible from Yes Public Road? No
15 Name of Established District		41. Distance from and Frontage on Road
42. Further Description of Important Features One and one-half story single pen h	rouse with door and window on	
primary elevation; secondary elevat at attic level. Sashes have been r shed addition has been constructed	tions have window at first story are semoved and boarded with metal. A on northwest facade; interior has	Photo
been stripped and is used for stora	we.	
43 History and Symptocence A house is indicated at this site of Ashley Brown, but is probably not of when the land was owned by Harden A	THIS OND NO NOTING LA STLUWE REVER	was undoubtedly moved

house connected with Thomas B. Brown, who came to Ray County in 1835, when he was 15 and (cont)

44 Description of Environment and Outbuildings


House of later date has been constructed to the southeast of this house, which is used as storage. Other outbuildings of somewhat later date are to the south and west of the house.

45 Sources of Information On-site inspection. Pauline Brown Atlases of 1877; 1897, Ray County History, 1973. 46. Prepared by Ogg and Brown

RCAS & M

49 Revision Date(s) 48. Date 6/80

\*\*13, Cont. later entered plat for this land. In 1881, he had a farm of 300 acres. He married Patsy Crowley, a daughter of Jeremiah Crowley, and they were the parents of 15 children. Tom took part in the "Mormon War" and the "Heatherly War". The atlas of 1914 recordes the property as owned by Jerry Brown., who constructed the modern house on the property.



FLOORPLANS NOT TO SCALE



PHOTOGRAPH




48. Date 8/79

49 Revision Date(s)

Office of Historic Preservation, P.O. Box 176, Jefferson City, Missouri 65101

1 No 56	Todd's Chapel Church	·
Ray 3 Location of Negatives	5 Other Name(s) Methodist Episcopal Church South	
6 Specific Location on dirt road off Hywy 10, west of Richmond  7 City or Town II Rural, Township & Vi Richmond vicinity, Richmond t  8 Site Plan with North Arrow  cemetery	16. Thematic Category  17 Date(s) or Period 1851  County 18 Style or Design Gothic Revival  19. Architect or Engineer unknown  20. Contractor or Builder members of congregation  21. Original Use, if apparent church 22 Present Use church 23 Ownership  Public I! Private Ixk  24. Owner's Name & Address, if known	28. No. of Stories one  29. Basement?  Yes: INOX.  30. Foundation Material ashlar stone-concrete  31. Wall Construction frame  32. Roof Type & Material gable-comp. shingles  33. No. of Bays Front 2 Side 4  34. Wall Treatment weatherboarding  35. Plan Shape rectangular  36. Changes Addition: (Explain Altered IX in #42) Moved i
Register? No ix Eligible?	26. Local Contact Person or Organization  Mrs. Eugene Pettus, sec'y.  27. Other Surveys in Which Included	Interior fair Exterior good  38. Preservation Yes Underway? No X  39. Endangered? Yes!! By What? Yes X No X  40. Visible from Yes X Public Road? No I:  41. Distance from and Frontage on Road
entrance with transom, balance window under a pointed arch. secondary facades, with 4 reg windows are of frosted glass replaced with clear glass. From pews and pulpit chairs.  3 History and Summicance The church A partial list of original memory and facaded and face are also and named inhoror of Reverend church was dedicated by Rev. Services every Sunday, with a Description of Environment and Outbuilding Located on a high hill, far from the second of the secon	Primary facade features singleleaf ed on the facade by a 1-over-1 light The same window type is repeated on the ularly spaced windows on each side. The where original, some panes have been urnishings are of oak, with original  h was organized in 1828 but no building mbers includes: D.H. Thorpe, J. Anderson Carter, J.D. Elliot. The church was bu Joseph S. Todd, who was at one time its william G. Caples, then presiding elder. lay leader.  one om the highway, only one farm dwelling no s of some of the earliest Ray County set	was erected until 1851.  I, Lewis Linville, Thomas  Ill at a cost of \$600  I pastor. In 1852 the  The church still holds  learby. It has a



**FLOORPLANS** 

NOT TO SCALE




PHOTOGRAPH



## Office of Historic Preservation, P.O. Box 176, Jefferson City, Missouri 65101

47 5 T	4 Present Name(s)	
2 ( nly .	Pettus House	
Ray	5 Other Namo(s)	
RCHS & M		
Specific Location West on Hywy 10 from Rich	amond 16. Themalic Calegory	28. No. of Stories $1\frac{1}{2}/2$
3½ miles, south ½ mile or	1 17 Date(s) or Period	29. Basement? Yes !!
private dirt road.	ca. 1840	30. Foundation Material
City or Town If Rural, Township &		ashlar stone 40
vic. Elkhorn Richmond Tw	vernacular/Neoclassic details  19. Architect or Engineer	log and frame LC wu
11 3 3 5	unknown	32. Roof Type & Material
11 0000	20. Contractor or Builder James T. Pettus	gable/asphalt shingles
	21. Original Use, if apparent	33. No. of Bays Front 6 Side 1
	residence OIA	34. Wall Treatment
	22 Present Use vacant	clapboarding 35. Plan Shape rectangular
Summund	23 Ownership Public ! !	36. Changes Addition X
1519 752N 28W 49	PrivateXXX	(Explain Altered ® In #42) Moved
	24. Owner's Name & Address.	37. Condition
Coordinates UTM	Richmond, Missouri	Interior poor
Lat Long		Exterior poor
Site ! 1 Struc	25. Open to Yes 11 Public? No M	38. Preservation Yes Underway? No %
	bject i   26. Local Contact Person or Organization	39. Endangered? Yes KI
On National Yes II 12. Is It	Yes RO	By What? No I
Register? No X Eligible?	NO 11 M 27 Other Common in Miles to at a	neglect
Part of Estab Yes I.I 14. District	Yes I I	neglect  40. Visible from Yes'
Part of Estab Yes I.i Hist Dist? No ki Potent'l?	Yes I I	40. Visible from Yes ' Public Road? No %
Part of Estab Yes I.i Hist Dist? No ki Potent'!?	Yes I I	40. Visible from Yes '
Part of Estab Yes I.i Hist Dist? No ki Potent'!?  Name of Established District  Further Description of Important Featuritrest construction was a measures 18' x 20' and is large 2/3rds I-house was and the log structure was block's Neoclassic details with Neoclassic entrolature.	Yes I I	40. Visible from Public Road? Yes 'No K:  41. Distance from and Frontage on Road  Photo
Part of Estab Yes I.I Hist Dist? No ki  Name of Established District  Puther Description of Important Feature First construction was a measures 18' x 20' and is large 2/3rds I-house was and the log structure was block's Neoclassic details with Neoclassic entablature returns. Primary entrance  History and Significance  Jospeh Pettus came to Ray J.T. and W.R. Pettus. Jose 1958. Pettus entered a pl A rough hewn table used for married Mary E. Jackson.	Yes I No K No	Photo  Public Road?  41. Distance from and Frontage on Road  Photo  Iton Pettus and sons freed upon his death in house the same year.
Part of Estab Yes I.i Hist Dist? No ki Potenti?  Name of Established District  Further Description of important Featuritrest construction was a measures 18' x 20' and is large 2/3rds I-house was and the log structure was block's Neoclassic details with Neoclassic entablaturing returns. Primary entrance  History and Significance Jospeh Pettus came to Ray J.T. and W.R. Pettus. Jose 1958. Pettus entered a place A rough hewn table used for married Mary E. Jackson, a Description of Environment and Outbui Family cemetery on property	Yes I No K No	Photo  Ph
Part of Estab Yes I. Hist Dist ? No ki Potent'!?  Name of Established District  Further Description of Important Feature First construction was a measures 18' x 20' and is large 2/3rds I-house was and the log structure was block's Neoclassic details with Neoclassic entablature returns. Primary entrance Jospeh Pettus came to Ray J.T. and W.R. Pettus. Jose 1958. Pettus entered a pl A rough hewn table used for married Mary E. Jackson, a Description of Environment and Outbui Family cemetery on propert date in poor condition. Yes	Yes   No K   No	40. Visible from Public Road? No King 1. Distance from and Frontage on Road  Photo  Photo  Photo  Photo  Photo  Photo  Photo  Photo  It on Pettus and sons freed upon his death in house the same year. His son James T. Pettus a. 1840. (cont)  Duildings of a later
Part of Estably Yes! 14. District Hist Dist? No ki Potent??  Name of Established District  Further Description of Important Feature First construction was a measures 18' x 20' and is large 2/3rds I-house was and the log structure was block's Neoclassic details with Neoclassic entablature returns. Primary entrance Jospeh Pettus came to Ray J.T. and W.R. Pettus. Jose 1958. Pettus entered a place A rough hewn table used for married Mary E. Jackson, a Description of Environment and Outbuit Family cemetery on propert date in poor condition. Yes 1958.	Yes in No & Walnut log house built ca. 1840 It a single room with loft. About 1860 a constructed to the west with a kitchen win remodelled to correspond with the new s. Pilaster corner boards. 6/6 windows re window heads. Heavy boxed cornice with with 3 light transom and sidelights (conformation of the series of 360 acres in 1835 and built a log or dining is still in the Pettus family. In the log portion of this house coldings  We some original plantings remain. Outland now used for farm storage.	Photo  Ph
Part of Estab Yes! 14. District Hist Dist? No ki Potent??  Name of Established District  Further Description of Important Feature First construction was a measures 18' x 20' and is large 2/3rds I-house was and the log structure was block's Neoclassic details with Neoclassic entablature returns. Primary entrance Jospeh Pettus came to Ray J.T. and W.R. Pettus. Jose 1958. Pettus entered a place A rough hewn table used for married Mary E. Jackson, a Description of Environment and Outbuit Family cemetery on propert date in poor condition. Yes.	Yes in No & Walnut log house built ca. 1840 It a single room with loft. About 1860 a constructed to the west with a kitchen win remodelled to correspond with the new s. Pilaster corner boards. 6/6 windows re window heads. Heavy boxed cornice with with 3 light transom and sidelights (conformation of the series of 360 acres in 1835 and built a log or dining is still in the Pettus family. In the log portion of this house coldings  We some original plantings remain. Outland now used for farm storage.	Photo  Ph

- #42. Cont. #36: House is vancant, used for storage and rapidly deteriorating. Shed has been attached to the primary facade for storing of farm equipment.
- #43. Cont. Upon the death of his father Joseph, James became sole owner of the Pettus property. The house has always remained in the Pettus family.



FLOORPLANS

NOT TO SCALE




**PHOTOGRAPH** 





#42. Cont. addition has recently been attached to the north facade. Two other additions have previously been added to the rear (west) elevation, one is apparently a log structure, much remodelled. The interior of the house features random width pine flooring, bullseye woodwork, stairway with large Newel post and turned balusters.



FLOORPLANS

NOT TO SCALE




PHOTOGRAPH



## Office of Historic Preservation, P.O. Box 176, Jefferson City, Missouri 65101 HISTORIC INVENTORY

1 No 53	4 Pres	sent Namo(s)	
/ County		Boardman Residence	
Ray	5 OIN	er Namo(s)	
3 Location of Negatives RCHS & M		Magill Schoolhouse	
6 Specific Location	SR 10	16 Thematic Calegory	26 No of Stories one
7-1/2 mi. west of	Richmond on Hyway	100	One
10, left 1 mi. on	unmarked dirt rd.	17 Date(s) or Period	29. Basement? Yes 1
to fork:rt.on narr	ow road 1/2 mi.	ca. 1886 at c 1966	30. Foundation Material
	al, Township & Vicinity	18 Style or Design	ashlar stone 46
vic. Richmond Ric		vernacular 89	31. Wall Construction
& Site Plan with North A	192	19. Architect or Engineer	frame . Wu
	<b>24</b>   <b>4</b>	unknown	32. Roof Type & Material Co B
. 4		20. Contractor or Builder	gable-comp. shingles
1 1		unknown	Front 3 Side n/a
1 1		21. Original Use, if apparent OSA	
11		schoolhouse and church	34. Wall Treatment
			metal siding 50
201167		residence 23 Ownership Public I	35. Plan Shape rectangular
1 31163		23 Ownership Public ! Private to	
_ W   0		24. Owner's Name & Address,	(Explain ditered to
S17 T5013	38D	il known	37 Condition
	UTM	John and Dorothy Boardman	Interior good
Lat	O 1 III	Richmond, Mo	Exterior good
Luny	•	25. Open to Yea I	
Site: Li	Structure 1:	Public? No to	
Building &	Object 11	26. Local Contact Person or Organization	39 Endangered? Yes III
11 On National Yes II	12 Is II Yes 🕌		By What? No K
Angister? No 🖼	Eligible? No i i	27. Other Surveys in Which Included	
Hist Dist.? No Li	14. District Yes I I		40. Visible from Yes
15 Name of Established D			Public Road? No X
13 Manua OI ERIRONSUGO D	istrict		41. Distance from and Frontage on Road
			Tromage on Hoad
42 Further Description of	Important Features		
		n theinterior and exterior. A	
balcony was constru	icted to add a se	cond floor and attic. The inter	ior
was gutted, and ret	ains little of the	he original materials. New winder	ows
were cut into the s	secondary facades	, a large addition added to the	Photo
rear; an enclosed s	sunporch to the ea	ast. Metal siding obscures facad	des
Original vestibule	is now a bedroom.	. Wood stove is in original	
position as when th	ne building serve	d as a school.	1.
43 History and Significance			
denominations Esh	for the Christian	Union Church, but free also for	r the use ofoother Christia
before 1000 from U	1, 1886. Church	built immediately after. Was	known as the Magill School
school until the di	dilliam Magill Sr.	, who deeded the land. Reorgani	Ized 1900. Remained a
Reulah who ronted	strict was conso.	lidated, in 1959. Sold in 1961 to	William Graham and wife
44 Description of Environm	ient and Outbuildings	changes. In 1966, purchased by	present owners, who (cont)
		ded hills large conden to	
east a natural spri	ng. Several mode	ded hills. Large garden to rear	or property. In the
January opin	Deverat mode	outputtutilgs.	
5 Sources of Information			
Abstract	Recor	eds of Magill School, ca. 1900	46. Prepared by
Dorothy Boardman		ite inspection.	Lamb and Cameron
Mary Denton Lamb	0 0.		47 Organization
Ray County History,	1973.		RCHS & M
, , , , , , , , , , , , , , , , , , , ,			48 Date 49 Revision Date(s)
			8/80



FLOORPLANS

NOT TO SCALE



PHOTOGRAPH

#43. Cont.remodel!ed interior and exterior to convert it to a private residence.

Forrest Smith, 42nd. governor of Missouri, 1949-1953, first taught at this school from 190/ to 1906 for a salary of \$47 a month. Born February 14, 1886 in the vicinity, Smith taught school near Richmond for nine years, the last five as Richmond Grammar School principal. H served in several county offices, State Tax Commission, State Auditor (1932-1948). He ran for governor in 1948 and was elected, carrying 102 of Missouri's 114 counties, having the largest vote ever given to a gubernatorial candidate in the state. During his tenure, he promoted highway and bridge construction. Smith died in 1962 and is buried in Richmond cemetery.




48 Date

4/80

49 Revision Date(s)

## Office of Historic Preservation, P.O. Box 176, Jefferson City, Missouri 65101 HISTORIC INVENTORY

	8 4 Pre	rsent Name(s)	
County		Fizer Residence	
Ray		her Namo(s)	
CHS &		Case Residence	
Specific Lucation		16 Thematic Category	No. May of States &
1 mile west of Ri	chmond on state	. 630	28 No of Stories two 29 Basement? Yes
highway 10. S L	10	17 Date(s) or Period	29. Basement? Yes
		ca. 1860	30. Foundation Material
Vic. Richmond, Ri	chmond two	18 Style or Design vernacular	ashlar stone 40
Site Plan with North Ar		19. Architect or Engineer	31. Wall Construction frame WW
7777777	Ш	unknown	32. Roof Type & Material G
		20. Contractor or Builder	Gable-asphalt shingl
		unknown 21. Original Use, if apparent	33. No of Bays Front 5 Side
		residence O	34. Wall Treatment
		22 Present Use	weatherboarding 20
3		residence	35. Plan Shaperectangula
W	$\omega    \omega$	23 Ownership Public I Private IX	36. Changes Addition (Explain Altered
HIGHWAY 10		24. Owner's Name & Address,	(Explain Altered In #42) Moved
		Mr. and Mrs. Fizer	37 Condition
	UTM	Richmond, Mo. 65201	Interior good
Luny 526 15	mse neg		Exterior good
Site Li Ki probled	Structure 1: Object 1:	Public? No ly	38. Preservation Yes Underway? No
On National Yes II	12 is it Yes X:	26 Local Contact Person or Organization	39 Endangered? Yes By What? No
Rugister? No IX	Eligible? No I I	27. Other Surveys in Which Included	- J J Milat : NO
D 4 B	14. District Yes I I Potent'l? No XI		40. Visible from Yes
			Public Road? No
Hist Dist.? No IX		1	
Hist Dist.? No IX			41. Distance from and
Namu of Established D	district		
Name of Established D	Important Features		41. Distance from and
Name of Established D  Further Description of ernacular I-hous	Important Features e has one-story	front veranda. Central singleleaf	41. Distance from and Frontage on Road
Name of Established D  Further Description of ernacular I-housentrance on prima	Important Features e has one-story ry facade. 2 op	enings on secondary facades. Neo-	41. Distance from and Frontage on Road
Name of Established D  Further Description of  dernacular I-house  entrance on prima  classic cornice w	Important Features e has one-story ry facade. 2 opi	enings on secondary facades. Neo- terior was originally two rooms on	41. Distance from and Frontage on Road
Further Description of dernacular I-housentrance on prima classic cornice weach floor, dividingle molding on	Important Features e has one-story ry facade. 2 ope ith returns. In ed by central ha bannister and be	enings on secondary facades. Neo- terior was originally two rooms on llway. L-shaped staircase has alustrades. Wide plank flooring	41. Distance from and Frontage on Road  Photo
Further Description of dernacular I-house intrance on prima classic cornice weach floor, dividingle molding on remains in upper	important Features e has one-story ry facade. 2 ope ith returns. In ed by central ha bannister and be rooms. Woodwork	enings on secondary facades. Neo- terior was originally two rooms on llway. L-shaped staircase has alustrades. Wide plank flooring is heavy and plain with bull'seye	41. Distance from and Frontage on Road  Photo
Further Description of Vernacular I-housentrance on prima classic cornice weach floor, divides imple molding on remains in upper decoration above	Important Features e has one-story ry facade. 2 ope ith returns. In ed by central ha bannister and be rooms. Woodwork	enings on secondary facades. Neo- terior was originally two rooms on llway. L-shaped staircase has alustrades. Wide plank flooring	41. Distance from and Frontage on Road  Photo
Further Description of Vernacular I-housentrance on prima classic cornice weach floor, divides imple molding on remains in upper decoration above	Important Features e has one-story ry facade. 2 ope ith returns. In ed by central ha bannister and be rooms. Woodwork	enings on secondary facades. Neo- terior was originally two rooms on llway. L-shaped staircase has alustrades. Wide plank flooring is heavy and plain with bull'seye	41. Distance from and Frontage on Road  Photo
Further Description of ernacular I-house ntrance on prima lassic cornice weach floor, dividingle molding on emains in upper ecoration above	Important Features e has one-story ry facade. 2 ope ith returns. In ed by central ha bannister and be rooms. Woodwork	enings on secondary facades. Neo- terior was originally two rooms on llway. L-shaped staircase has alustrades. Wide plank flooring is heavy and plain with bull'seye	41. Distance from and Frontage on Road  Photo
Further Description of ernacular I-house ntrance on prima lassic cornice weach floor, dividingle molding on emains in upper ecoration above	Important Features e has one-story ry facade. 2 ope ith returns. In ed by central ha bannister and be rooms. Woodwork	enings on secondary facades. Neo- terior was originally two rooms on llway. L-shaped staircase has alustrades. Wide plank flooring is heavy and plain with bull'seye	41. Distance from and Frontage on Road  Photo
Further Description of Pernacular I-housentrance on prima classic cornice we each floor, dividing on remains in upper decoration above History and Significance	Important Features e has one-story ry facade. 2 ope ith returns. In ed by central ha bannister and be rooms. Woodwork doors. #36: Muc	enings on secondary facades. Neo- terior was originally two rooms on llway. L-shaped staircase has alustrades. Wide plank flooring is heavy and plain with bull'seye	41. Distance from and Frontage on Road  Photo
Further Description of ernacular I-housentrance on prima lassic cornice weach floor, dividing on remains in upper lecoration above History and Significance	Important Features e has one-story ry facade. 2 ope ith returns. In ed by central ha bannister and be rooms. Woodwork doors. #36: Muc	enings on secondary facades. Neo- terior was originally two rooms on llway. L-shaped staircase has alustrades. Wide plank flooring is heavy and plain with bull'seye	41. Distance from and Frontage on Road  Photo
Further Description of Vernacular I-housentrance on prima classic cornice weach floor, divides imple molding on remains in upper decoration above. History and Significance on large lot on tentropy, to	Important Features e has one-story ry facade. 2 ope ith returns. In ed by central ha bannister and be rooms. Woodwork doors. #36: Muc	enings on secondary facades. Neo- terior was originally two rooms on llway. L-shaped staircase has alustrades. Wide plank flooring is heavy and plain with bull'seye h remodelling has been done to (con	41. Distance from and Frontage on Road  Photo
Further Description of Vernacular I-housentrance on prima classic cornice weach floor, divid simple molding on remains in upper decoration above History and Significance	Important Features e has one-story ry facade. 2 ope ith returns. In ed by central ha bannister and be rooms. Woodwork doors. #36: Muc	enings on secondary facades. Neo- terior was originally two rooms on llway. L-shaped staircase has alustrades. Wide plank flooring is heavy and plain with bull'seye h remodelling has been done to (con	The stance from and Frontage on Road  Photo  moutbuildings, not
Further Description of Vernacular I-housentrance on prima classic cornice weach floor, divid simple molding on remains in upper decoration above. History and Significance on large lot on tentemporary, to	important Features e has one-story ry facade. 2 opi ith returns. In ed by central ha bannister and bannister and bannister rooms. Woodwork doors. #36: Muc	enings on secondary facades. Neo- terior was originally two rooms on llway. L-shaped staircase has alustrades. Wide plank flooring is heavy and plain with bull'seye h remodelling has been done to (con	41. Distance from and Frontage on Road  Photo



FLOORPLANS

NOT TO SCALE




**PHOTOGRAPH** 

42. Cont. the interior of the house. Central hallway downstairs was enclosed, wall to room on left torn down and posts inserted to enlarge living room. All was panelled and carpeted, but closet under stairs remains as constructed. New fireplace in center of north wall of this room. Original probably had interior end chimneys. An addition of kitchen and workroom added to the north of house. Exterior remains basically unaltered.



## Office of Historic Preservation, P.O. Box 176, Jefferson City, Missouri 65101 HISTORIC INVENTORY

1 No	A Pres	sent Namo(s)	
53	]		
County	4 00	Shotwell House	
3 Location of Negatives	3 0111	Namo(s)	
RCHS & M			
Specific Lucation 1 mile west of Ric	chmond on Hywy 10	16 Thernatic Calegory	28 No of Stories two
	on mora on my 10		29. Basement? Yes 🕅
SRID		17 Date(s) or Period	No 1
7 City or Town II Rura	al. Township & Vicinity	18 Style or Design 40 49	30. Foundation Material ashlar stone 90
Richmond vic. Richmond	chmond twp.	vernacular/Italianate derivativ	
8 Carlin with North Ari	(T)	19. Architect or Engineer	brick . 4B
W	_ \	unknown 20. Contractor or Builder	32. Roof Type & Material HP hip-asphalt shingles
	7 / /·	William M. Shotwell	33. No. of Bays
	THE P.	21. Original Use, if apparent	Front 2 Side 2
	7 4	residence OIA	34. Wall Treatment
	(,)	residence	common bond 0
^^	. 0	23 Ownership Public ! !	36. Changes Addition
(4)	.3	Private by	(Explain Altered 1X In #42) Moved I
	w	24. Owner's Name & Address, if known	37 Condition
V Coordinates	UTM	William Shotwell	Interior good.
Lat Sale TSa	128m	Route 1, Washington, Mo.	Exterior good
		25 Open to Yes i i	38. Preservation Yes
Site Li Building og	Structure 1 i	26 Local Contact Person or Organization	Underway? No X
11 On National Yes II	12 is ii Yes Di	20 Local Contact Person or Organization	39 Endangered? Yes II By What? No IX
Ringister? No IX	Eligible? No 11	27. Other Surveys in Which Included	
Hist Dist.? No M	14. District Yes i i		40. Visible from Yes X Public Road?
15 Name of Established Di	istrict		41. Distance from and
			Frontage on Road
42. Further Description of I	moortant Fastures		
Primary facade has	s lateral primary	entrance balanced by a window to	
		tory. All fenestration is seg- ehung sash. Primary facade has	
jack arches above	windows which ar	re projected and carried on corbel	Photo
shoulders. Iron	tie bars on all f	acades. Brick water table belt	
		en mostly replaced. Curved stair-	
		eads. Some original woodwork(cont	
First family home	was across the r	coad(Route 10). Present house cons	tructed 1870. Brick was
fired on property	along present dr	riveway. Jabez Shotwell, a native	of Mason County.
Kentucky, a survey	yor, a farmer and	later a judge in Richmond, settl	ed on this site in 1835.
A well here was no	oted for its fine	water and many travellers would	stop there. After the
44 Description of Environm	in 1052, Jabez g	ave the farm to one of his sons,	William M. Shotwell, (cont
On a 156 acre farm	m, and a wooded 1	ot, on the outskirts of the city	of Richmond.
45 Sources of Information			46. Prepared by
Present Occupants		•	Cameron and Pease
On-site inspection Ray County History			47 Organization
may country mistory	, 1001.		RCHS & M
			8/79 49 Revision Date(s)



FLOORPLANS

NOT TO SCALE



PHOTOGRAPH


"42. Cont. remains below stairway. Also some original wide plank flooring. #36: House was vacant for a few years and interior virtually destroyed by vandals. Has been repaired and renovated but not restored. Original walls were plastered which was destroyed when electricity added, and plumbing ca. 1975. New ceiling, panelling in most rooms. Dining room changed to kitchen (which was originally in rear) bedroom, new living room. Two fireplaces, one closed. Has plain molded mantlepieces. Basement was added. Original porch was removed.

#43. Cont. who built the present house. It is owned by a descendent.



L NO. 4. PRESENT LOCAL NAME(S) OR DESIGNATION(S)		-
Don Garner Residence		, No.
o. orner hamely		
NEGATIVES RCHS		
6. SPECIFIC LEGAL LOCATION SECTION 34 16. THEMATIC CATEGORY	28. NO. OF STORIES TWO 2.1	2. C
Take 10 from Richmond west (c ca. 1900)	partial NO()	COUNTY
7. CITY OR TOWN IF RURAL, VICINITY 18. STYLE OR DESIGN	ashiar Stone 40	
vic Richmond Richmond Twp. Neoclassic/vernacular  Description of Location  Neoclassic/vernacular  Page 19. ARCHITECT OR ENGINEER	frame WW	
unknown	32 ROOF TYPE AND MATERIAL	GBR
20. CONTRACTOR OR BUILDER UNKNOWN	gable-asphalt shingles	43
21. ORIGINAL USE, IF APPARENT YEST dence	FRONT 3 SIDE 1	-
22. PRESENT USE	weatherboard 2/	PRESENT LOCAL
residence	35. PLAN SHAPE rectangular 36. CHANGES ADDITION(X)	. 5
23. OWNERSHIP PUBLIC ( ) PRIVATE ( X )	(EXPLAIN IN ALTERED (X )	CAL
24. OWNER'S NAME AND ADDRESS  IF KNOWN	MOVED ( )	NA NA
9. COORDINATES UTM Don Garner	INTERIOR excellent excellent	(3)
LAT Richmond, Missouri LONG 25. OPEN TO PUBLIC? YES()	EXTERIOR CACCITOTIC	ON
IO. SITE() STRUCTURE() NO()	UNDERWAY ? NO (X )	06.31
BUILDING ( X ) OBJECT ( ) 26. LOCAL CONTACT PERSON OR ORGANIZATION  10 14 NATIONAL YES ( ) 12. IS IT YES (X )  CISTER ? HO ( X ) ELIGIBLE? NO ( ) 27. OTHER SURVEYS IN WHICH INCLUDED	BY WHAT? NO (X )	NAME(S) OR DESIGNATION(S)
13. PART OF ESTAB. YES ( ) 14. DISTRICT YES ( ) HIST. DISTRICT? NO ( X )	40. VISIBLE FROM YES (X ) PUBLIC ROAD ? NO( )	3
IS. NAME OF ESTABLISHED DISTRICT	41. DISTANCE FROM AND FRONTAGE ON ROAD	
42. FURTHER DESCRIPTION OF IMPORTANT FEATURES		a
I-house dating from about the turn of the century has undergone a good deal of remodelling. New windows cut on primary elevation and on south facade. Single story addition to rear of kitchen and dining room. Construction of new front porch caused central window on primary facade to be shortened; cast-iron posts with brackets have replaced wood piers on this porch. Interior also completely (cont)	PHOTO MUST BE PROVIDED	OTHER NAME(S)
43. HISTORY AND SIGNIFICANCE		
Lane was owned by Margaret Finley in 1877 at which time there was no h	nouse on this site.	
		o. TOWNSHIP
		1
44. DESCRIPTION OF ENVIRONMENT AND OUTBUILDINGS		
Bural.		
45. SOURCES OF INFORMATION	46. PREPARED BY	-
D 0 1 A17 2077	Ogg and Brown	1 :
Ray County Atlas, 1877.	47. ORGANIZATION	
Ray County Atlas, 1877.  Don Garner On-site inspection.	47. ORGANIZATION RCHS & M 48. DATE   49. REVISION DATE(S)	

- #6. Cont. to County Route EE; 1/2 mile south to unmarked gravel road; 1/2 mile southeast.
- #42. Cont. remodelled; wall partition removed in north front room to combine it with hallway as well as partition between this room and adjoining kitchen of the addition. Wall-to-wall carpeting installed; new stairrail.



FLOORPLANS NOT TO SCALE




PHOTOGRAPH



Office of Historic Preservation, P.O. Box 176, Jefferson City, Missouri 65101

HISTORIC INVENTORY

No 102 110 4 Pro	Lester Property	
Nay	Richardson House	
Location of Negatives RCHS	The same of the sa	28 No of Stories TWO
Specific Location	16 Thematic Calegory	29. Basement? Yes I
1 mile south of Henrietta	17 Date(s) or Period	No I
on Hywy 13.	ca. 1880	30. Foundation Material Brick 33
City or Town II Rural, Township & Vicinit	y 18 Style or Design	Brick 30
Henrietta vic. Richmond twp.	VETHACUTAL	frame, wa
Site Plan with North Arrow	19. Architect or Engineer	32. Roof Type & Material GB
	20. Contractor or Builder Smith	gable-asphalt shing
	unknown CB	33. No. of Bays Front 5 Side 2
	21. Original Use, if apparent residence 0/1	34. Wall Treatment
	22 Present Use	weatherboard 2
	vacant	35. Plan Shape rectangula
	23 Ownership Public I ! Private L!	36. Changes Addition
1	24. Owner's Name & Address.	in #42) Moved
out 2	il known	37 Condition fair
	Jerry Lester Richmond, Missouri	Interior Tair  Exterior fair
Coordinates UTM		38. Preservation Yes
Long	Public? No KK	Underway? No
Site 1 Structure Building of Object		39 Endangered? Yes
On National Yes II 12 Is II Yes	Ty .	By What? neglect
Ringister? No X: Eligible? No		40. Visible from Yes
Part of Estab Yes I 14. District Yes		Public Road? No
HIST DIST.	<u>^</u>	41. Distance from and Frontage on Road
5 Name of Established District		Frontage on road
2. Further Description of Important Features	I-house atop a brick foundation. It	is /
FI	c a contral cililleteal billially circle	
and two over two windows al	I crowned with lillers. Collies are	Photo
marked by boaded nilaster co	rnerhoards and a poxed cornice and	
frieze surround the structur	re. Small willdows pierce the active	
level on each secondary face	ade. #36: One brick stove chimney had in the southwest facade. New porch ac	det to primary elevation
43 History and Significance	THE SOCIETY OF THE STATE OF THE	
	owning this property in 1877. The	re is no house indicated
1 7 three unbout tho	COUNTY, INTITION DIDDOLLIONS WIN	d Silidii de
on the secondary facades we	re common latolis illucti eatitet til tile	century.
44 Description of Environment and Outbuildi	ngs	dawa outhuildings
A few trees probably date f	rom the same period as the house; mo	detal output latings
are of much later construct	10n.	
45 Sources of Information		46. Prepared by
On-site inspection. R	ay County Atlas 1877	Cameron
on or so mapers.		47. Organization
		RCHS & M 48. Date 49 Revision Date
		6/80
		0,00



FLOORPLANS

NOT TO SCALE




PHOTOGRAPH



48. Date 6/80

49 Revision Date(s)

120 127	Present Name(s)  Cambelll House		
3 Location of Negatives	Other Namo(s)		
RCHS 6 Specific Location	16. Thematic Category	28. No. of Stories two 2-/	
On Community Link between Ro 10 and Route EE, Sec. 3, Ran 28, Twp. 51.		29. Basement? Yes ! 1 No IX	
7 City or Town II Rural, Township & Vicin Vic. Richmond Richmond Twp	18 Style or Design	ashlar/cement 40 65	
wic. Richmond Richmond Twp	19. Architect or Engineer	frame Wu	
w	unknown  20. Contractor or Builder  John W. Campbell	32. Roof Type & Material (5) gable/comp shingles	G.P.
SULLA	21. Original Use, if apparent	33. No. of Bays Front 5 Side 2	• :
	residence O/A 22 Present Use residence	34. Wall Treatment weatherboard	
	23 Ownership Public ! !	35. Plan Shape rectangular  36. Changes Addition x (Explain Altered K	
9 Goordinates UTM	24. Owner's Name & Address.  If known  Frank Campbell  Richmond, Missouri	37. Condition Interior good  Exterior good	
Comp	25. Open to Yes 11 Public? No XX	38. Preservation Yes Underway? NoX	
Building x i Object	26. Local Contact Person or Organization	39. Endangered? Yes II By What? No K	
Megister? No x Eligible? No	27. Other Surveys in Which Included		
J Part of Estab Yes 1.1 Hist Dist? No XI Potent'l? No		40. Visible from Yes (X Public Road? No ):	
5 Name of Established District		41. Distance from and Frontage on Road	
window heads, pilaster corne by 2 wall gables. Interior concrete porch with hipped ' remodelled with addition of and realignment of original	ssic details: boxed cornice, molded r boards. Primary facade highlighted brick chimney. #36: Addition of roof and cast-iron posts. House several windows to primary facade centralized primary entrance.	Photo	- Names
by John W. Campbell. James 1, 1901, James' son Thomas A He was the presiding judge of	r the land in 1829 and was owner to at e present owner of the property. Hous M. Campbell Jr. was the present owner' ndrew Campbell moved into the house an f Ray County from 1930 to 1934.	se was built in 1884	
In a rural setting, with ori	3	(	
5 Biography of Clay, Ray, etc.		46. Prepared by Pauline Brown	
Ray County History, 1883.		47. Organization RCHS & M	
Frank Campbell. On-s	ite inspection.	ACAD & M	



FLOORPLANS

NOT TO SCALE



PHOTOGRAPH



49 Revision Date(s)

48. Date


5/80

Office of Historic Preservation, P.O. Box 176, Jefferson City, Missouri 65101
HISTORIC INVENTORY

	4 Present Name(s)	
No 57	Royce Carter Residence	
County	5 Other Namo(s)	
Location of Negatives RCHS	Seek House	
	16 Thematic Category	28 No of Stories two 2-2
Specific Lucation /2 mile northwest of Richmo		29. Basement? Yes I
nmarked gravel road,	17 Data(s) of Vertoc	No (C)
52 R28 S24 CE	Ca. 1030	ashlar stone 40
City or Town If Rural, Township	Twp. Vernacular; Greek Revival	31. Wall Construction
ichmond vic. Richmond Site Plan with North Arrow	19. Architect or Engineer	frame .WW
Sile Flat with the	unknown 20. Contractor or Builder Post	32. Roof Type & Material G G gable-comp. shingles
0	unknown	33. No. of Bays 63
h ////	21. Original Use, if apparent	Front 5 Side 1
// held	residence OLA	34. Wall Treatment weatherboard
(D) *	// Present Use residence	35. Plan Shape L-shaped
1 2 2	23 Ownership Public ! !	36. Changes Addition (Explain Altered)
6 5	Private 1 y	in #42) Moved
	24. Owner's Name & Address.	37 Condition
Covalinates UTM	Royce Carter	Interior excellent Exterior excellent
Coordinates UTM	Richmond, Missouri	38. Preservation Yes
Long	No.11	30. 110001101101
Site 1 ( St Building ) X	Object   26 Local Contact Person or Organization	39 Endangered? Yes By What? No
On National Yes II 12 Is It	Yes I IX	By what:
Angister? No 1 X Eligible		40. Visible from Yes
Part of Estab Yes   14. District Hist Dist.? No   X Potent		Public Road? No
5 Name of Established District		41. Distance from and Frontage on Road
	•	
way on both stories of prisidelights. Dominating prediment supported by Dori frieze continue around buistory el to rear of buildistory veranda; entrance to History and Significance	k Revival styling including central entry mary elevation with 6 light transom and rimary facade is two story portico with ic freestanding piers. Boxed cornice and ilding and portico's pediment. Large two ing is fronted on the east facade by a two house from veranda at each story. Stone 1877. Building said to have been constramily home, an identical building one mile of the Dale family.	e(Copt)
and who may have been a m	ember of the Dale family.	
On large farm with origin	al plantings surrounding house; later far	m buildings to the
east and rear.		
45 Sources of Information		46. Prepared by Cameron
On-site inspection.		47 Organization
Dick Dale.		RCHS & M

Ray County Atlas, 1877.

42. Cont. interior end chimneys. Modernization of interior includes cutting of new triple window on west facade of el.



FLOORPLANS

NOT TO SCALE






PHOTOGRAPH





L NO. 121	PRESENT LOCAL NAME(S) OR DESIGNATION(S)		I. NO
2. PUNTY DAY	Swofford House		Ģ
3. LOCATION OF	OTHER NAME(S)		
NEGATIVES RCHS	E. Turney	EZE NO OF STORIES 1%	N
6. SPECIFIC LEGAL LOCATION 28 SECTION 3	IG. THEMATIC CATEGORY	29. BASEMENT ? YES ( )	CO
3/5 mile east from Richmond (cont)	ca. 1890 C. 1930	NO (X )	COUNTY
7. CITY OR TOWN IF RURAL, VICINITY VIC. Richmond, Richmond Twp.		SI. WALL CONSTRUCTION	
. DESCRIPTION OF LOCATION WASHHOUSE	The Annual of The Control of the Con	32 ROOF TYPE AND MATERIAL	GB
SHED	20. CONTRACTOR OR BUILDER unknown	gable-comp. shingles	63
	21. ORIGINAL USE, IF APPARENT	FRONT n/a SIDE 1	. PRI
	residence TIA 22. PRESENT USE	shake shingles 25	PRESENT LOCAL NAME(S)
zeret	residence 23. OWNERSHIP PUBLIC(	35. PLAN SHAPE nectangular ) 36. CHANGES ADDITION ( X)	Loc
* Way Max	PRIVATE ( V	(EXPLAIN IN ALTERED ( X) MOVED ( )	A F
	IF KNOWN	37. CONDITION	AME(
9. COORDINATES UTM	Chet Swofford Richmond, Missouri	EXTERIOR good	
LONG	25. OPEN TO PUBLIC? YES	) 38. PRESERVATION YES ( )	R O
10. SITE ( ) STRUCTURE BUILDING (XX) OBJECT		HOT XI	OR DESIGNATION(S)
II NATIONAL YES ( ) 12. IS IT YES		BY WHAT? NO ( X)	ATIO
13. PART OF ESTAB. YES ( ) 14. DISTRICT YES POTENTIAL? NO		40. VISIBLE FROM YES ( χ) PUBLIC ROAD? NO ( )	(S)
IS. NAME OF ESTABLISHED DISTRICT		41. DISTANCE FROM AND FRONTAGE ON ROAD	
42. FURTHER DESCRIPTION OF IMPORTANT FE	THEF		· co
	with addition of wood siding. The	РНОТО	OTHER
original house probably had a seco		MUST	
	g it a double pen vernacular style sed and a larger window cut in the	BE	NAME (S)
	gutted and remodelled. Ca. 1930, the enclosed back porch, removed stairs		(8)
43. HISTORY AND SIGNIFICANCE	encloses back porch, removed scales		
Present owners have lived here sin	ce 1952. Earlier owners planted the		
	recorded in the county atlas as the the cedar trees in the front yard, o		
family; most remain.	the ceast stees in the from you, o	ne for each chaca an ane	704
			6. TOWNSHIP
Cadar trees front the house. Behi	nd the house was said to be a Negro	graveyard. A log house	RANGE
w demolished a few years ago in	the same location. Behind the house		-
and a root cellar, ca. 1911.  45. SOURCES OF INFORMATION		46. PREPARED BY	-
Mr. and Mrs. Swofford.		Brown and Ogg	88 M
Ray County Atlases, 1877; 1897; 19 Pauline Brown On-site inspect	ion.	RCHS & M	SECTION
		48. DATE 49. REVISION DATE(S)	•

SECTION



NOT TO SCALE **FLOORPLANS** 



